




T20240627052651





BLK: 3,SNR1: 0.14295 ,SNR2: 0.59034




Frequency (Hz)

F20240627052653




BLK: 3,SNR1: 0.46261 ,SNR2: 4.7656





Frequency (Hz)


2356+437 2024/06/26 20.48UT TOYOKAWA-FUJI



T20240627052651





BLK: 4,SNR1: 0.37144 ,SNR2: 6.3056




Frequency (Hz)

K20240627052648




BLK: 4,SNR1: 0.11814 ,SNR2: 2.2282





Frequency (Hz)

2356+437 2024/06/26 20.48UT TOYOKAWA-KISO






F20240627052653





BLK: 4,SNR1: 0.14879 ,SNR2: 2.3216




Frequency (Hz)

K20240627052648




BLK: 4,SNR1: 0.19328 ,SNR2: 0.67262





Frequency (Hz)


2356+437 2024/06/26 20.48UT FUJI -KISO



T20240627060908





BLK:15,SNR1: 1.3959 ,SNR2: 4.1281




Frequency (Hz)

F20240627060910




BLK:15,SNR1: 2.8935 ,SNR2: 5.5977





Frequency (Hz)


0038+328 2024/06/26 21.18UT TOYOKAWA-FUJI





T20240627060908




BLK:18,SNR1: 0.64086 ,SNR2: 2.7912




K20240627060906





BLK:18,SNR1: 1.7332 ,SNR2: 4.3762




0038+328 2024/06/26 21.18UT TOYOKAWA-KISO



F20240627060910





BLK:25,SNR1: 1.8035 ,SNR2: 6.6858




Frequency (Hz)

K20240627060906




BLK:25,SNR1: 4.0508 ,SNR2: 16.979





Frequency (Hz)


0038+328 2024/06/26 21.18UT FUJI -KISO



T20240627063057





BLK:16,SNR1: 1.8272 ,SNR2: 4.6815




Frequency (Hz)

F20240627063059




BLK:16,SNR1: 2.8828 ,SNR2: 13.456





Frequency (Hz)


0100+146 2024/06/26 21.54UT TOYOKAWA-FUJI



T20240627063057





BLK:18,SNR1: 1.6481 ,SNR2: 4.2221




Frequency (Hz)

K20240627063054




BLK:18,SNR1: 2.8178 ,SNR2: 13.426





Frequency (Hz)


0100+146 2024/06/26 21.54UT TOYOKAWA-KISO



F20240627063059





BLK:22,SNR1: 9.7102 ,SNR2: 23.975




Frequency (Hz)

K20240627063054




BLK:22,SNR1: 2.5168 ,SNR2: 12.240





Frequency (Hz)


0100+146 2024/06/26 21.54UT FUJI -KISO



T20240627064617




BLK:10,SNR1: 0.91099 ,SNR2: 7.1910




Frequency (Hz)

F20240627064619




BLK:10,SNR1:-0.98235E-01,SNR2: 1.6120





Frequency (Hz)

0115-01 2024/06/26 21.80UT TOYOKAWA-FUJI






T20240627064617





BLK:10,SNR1: 0.39404 ,SNR2: 1.7441




Frequency (Hz)

K20240627064614




BLK:10,SNR1: 5.0086 ,SNR2: 9.8275




Frequency (Hz)


0115-01 2024/06/26 21.80UT TOYOKAWA-KISO



F20240627064619





BLK: 7,SNR1:-0.84529E-01,SNR2: 0.85673




Frequency (Hz)

K20240627064614




BLK: 7,SNR1: 6.0427 ,SNR2: 11.772





Frequency (Hz)


0115-01 2024/06/26 21.80UT FUJI -KISO



T20240627065917





BLK:16,SNR1: 0.88207 ,SNR2: 3.0019




Frequency (Hz)

F20240627065919




BLK:16,SNR1: 0.15483 ,SNR2: 2.5325





Frequency (Hz)


0128+03 2024/06/26 22.02UT TOYOKAWA-FUJI



T20240627065917





BLK:11,SNR1: 0.77182 ,SNR2: 3.2897




Frequency (Hz)

K20240627065914




BLK:11,SNR1: 0.67848 ,SNR2: 2.7126




Frequency (Hz)


0128+03 2024/06/26 22.02UT TOYOKAWA-KISO





F20240627065919




BLK: 8,SNR1: 0.13541 ,SNR2: 2.9731




K20240627065914




BLK: 8,SNR1: 2.1953 ,SNR2: 8.9447




0128+03 2024/06/26 22.02UT FUJI -KISO



T20240627070550



BLK:21,SNR1: 3.6278 ,SNR2: 9.0686





Frequency (Hz)


3C48

2024/06/26 22.13UT TOYOKAWA-FUJI


F20240627070552




BLK:21,SNR1: 2.3466 ,SNR2: 6.9549




Frequency (Hz)



T20240627070550




BLK:24,SNR1: 3.5777 ,SNR2: 9.2481




Frequency (Hz)

3C48 2024/06/26 22.13UT TOYOKAWA-KISO


K20240627070547





BLK:24,SNR1: 31.463 ,SNR2: 40.433




Frequency (Hz)





F20240627070552




BLK:28,SNR1: 3.1737 ,SNR2: 8.5425




K20240627070547



BLK:28,SNR1: 24.120 ,SNR2: 31.394





3C48 2024/06/26 22.13UT FUJI -KISO






T20240627072535





BLK:22,SNR1: 7.5406 ,SNR2: 18.893




Frequency (Hz)

F20240627072537




BLK:22,SNR1: 6.7822 ,SNR2: 17.577





Frequency (Hz)


0155-109 2024/06/26 22.45UT TOYOKAWA-FUJI



T20240627072535





BLK:32,SNR1: 7.6683 ,SNR2: 19.184




Frequency (Hz)

K20240627072532




BLK:32,SNR1: 8.1618 ,SNR2: 20.262




Frequency (Hz)


0155-109 2024/06/26 22.45UT TOYOKAWA-KISO





F20240627072537




BLK:23,SNR1: 3.6970 ,SNR2: 10.395




K20240627072532





BLK:23,SNR1: 8.0962 ,SNR2: 20.067




0155-109 2024/06/26 22.45UT FUJI -KISO



T20240627073242




BLK: 7,SNR1: 0.40471E-02,SNR2: 0.33945




Frequency (Hz)

F20240627073244




BLK: 7,SNR1:-0.65010E-01,SNR2: 1.2938




Frequency (Hz)


0202+15 2024/06/26 22.57UT TOYOKAWA-FUJI



T20240627073242





BLK: 6,SNR1:-0.39025E-01,SNR2: 0.36396




Frequency (Hz)

K20240627073239




BLK: 6,SNR1: 17.954 ,SNR2: 33.764





Frequency (Hz)


0202+15 2024/06/26 22.57UT TOYOKAWA-KISO



F20240627073244





BLK:10,SNR1:-0.36495E-01,SNR2: 1.3492




Frequency (Hz)

K20240627073239




BLK:10,SNR1: 13.677 ,SNR2: 25.933





Frequency (Hz)


0202+15 2024/06/26 22.57UT FUJI -KISO



T20240627074433




BLK: 2,SNR1: 0.25638E-01,SNR2: 0.80841




Frequency (Hz)

F20240627074435




BLK: 2,SNR1: 0.18429 ,SNR2: 4.4872





Frequency (Hz)


0213+178 2024/06/26 22.77UT TOYOKAWA-FUJI



T20240627074433





BLK:11,SNR1: 0.13447 ,SNR2: 0.60133




Frequency (Hz)

K20240627074430




BLK:11,SNR1: 20.863 ,SNR2: 29.813





Frequency (Hz)

0213+178 2024/06/26 22.77UT TOYOKAWA-KISO






F20240627074435




BLK: 1,SNR1: 0.92159E-01,SNR2: 0.57703




Frequency (Hz)

K20240627074430




BLK: 1,SNR1: 22.267 ,SNR2: 32.327





Frequency (Hz)


0213+178 2024/06/26 22.77UT FUJI -KISO



T20240627075215



BLK: 8,SNR1: 0.18137 ,SNR2: 0.96858




Frequency (Hz)


3C67

2024/06/26 22.90UT TOYOKAWA-FUJI


F20240627075217




BLK: 8,SNR1: 2.0852 ,SNR2: 6.7416




Frequency (Hz)



T20240627075215



BLK: 7,SNR1: 0.68131E-01,SNR2: 0.55849





Frequency (Hz)


3C67

2024/06/26 22.90UT TOYOKAWA-KISO


K20240627075212




BLK: 7,SNR1: 7.0313 ,SNR2: 13.862




Frequency (Hz)



F20240627075217



BLK:13,SNR1: 1.7858 ,SNR2: 5.9508




Frequency (Hz)


3C67

2024/06/26 22.90UT FUJI -KISO


K20240627075212





BLK:13,SNR1: 1.5280 ,SNR2: 6.1453




Frequency (Hz)



T20240627081030



BLK:13,SNR1: 0.30609 ,SNR2: 1.7946





Frequency (Hz)


3C71

2024/06/26 23.20UT TOYOKAWA-FUJI


F20240627081032





BLK:13,SNR1: 0.59935 ,SNR2: 3.8639




Frequency (Hz)



T20240627081030




BLK:19,SNR1: 0.33378 ,SNR2: 1.5894





3C71 2024/06/26 23.20UT TOYOKAWA-KISO



K20240627081027




BLK:19,SNR1: 3.2560 ,SNR2: 4.2701



F20240627081032



BLK:12,SNR1: 0.12383 ,SNR2: 2.3265





Frequency (Hz)


3C71

2024/06/26 23.20UT FUJI -KISO


K20240627081027





BLK:12,SNR1: 3.7714 ,SNR2: 13.287




Frequency (Hz)



T20240627082945





BLK:34,SNR1: 10.480 ,SNR2: 18.169




Frequency (Hz)

F20240627082947




BLK:34,SNR1: 1.0591 ,SNR2: 2.7262




Frequency (Hz)

0258+350 2024/06/26 23.52UT TOYOKAWA-FUJI






T20240627082945




BLK:34,SNR1: 8.5399 ,SNR2: 15.951




Frequency (Hz)

K20240627082942




BLK:34,SNR1: 12.889 ,SNR2: 22.201




Frequency (Hz)


0258+350 2024/06/26 23.52UT TOYOKAWA-KISO



F20240627082947




BLK:35,SNR1: 0.94968 ,SNR2: 2.4395




Frequency (Hz)

K20240627082942




BLK:35,SNR1: 12.000 ,SNR2: 20.312





Frequency (Hz)


0258+350 2024/06/26 23.52UT FUJI -KISO



T20240627083934





BLK:17,SNR1: 0.16103 ,SNR2: 1.0869




Frequency (Hz)

F20240627083936




BLK:17,SNR1: 2.7145 ,SNR2: 13.669





Frequency (Hz)


0308+305 2024/06/26 23.69UT TOYOKAWA-FUJI



T20240627083934





BLK:15,SNR1: 0.14420 ,SNR2: 1.2106




Frequency (Hz)

K20240627083931




BLK:15,SNR1: 3.7378 ,SNR2: 14.499





Frequency (Hz)


0308+305 2024/06/26 23.69UT TOYOKAWA-KISO



F20240627083936





BLK:35,SNR1: 2.1952 ,SNR2: 10.621




Frequency (Hz)

K20240627083931




BLK:35,SNR1: 3.0867 ,SNR2: 12.161




Frequency (Hz)


0308+305 2024/06/26 23.69UT FUJI -KISO



T20240627084754




BLK: 4,SNR1: 0.30139 ,SNR2: 1.0679





3C84 2024/06/26 23.83UT TOYOKAWA-FUJI



F20240627084756




BLK: 4,SNR1: 0.58369 ,SNR2: 0.96275



T20240627084754




BLK:10,SNR1: 0.16146 ,SNR2: 0.95184





3C84 2024/06/26 23.83UT TOYOKAWA-KISO


K20240627084752




BLK:10,SNR1: 3.0044 ,SNR2: 14.007



F20240627084756



BLK: 9,SNR1: 0.48237 ,SNR2: 4.0310





Frequency (Hz)


3C84

2024/06/26 23.83UT FUJI -KISO


K20240627084752



BLK: 9,SNR1: 1.5386 ,SNR2: 7.2358




Frequency (Hz)






T20240627090427




BLK:20,SNR1: 0.22185 ,SNR2: 0.81162





0333+32 2024/06/27 0.10UT TOYOKAWA-FUJI



F20240627090429




BLK:20,SNR1: 4.2494 ,SNR2: 16.913



T20240627090427





BLK:20,SNR1: 0.21486 ,SNR2: 0.65330




Frequency (Hz)

K20240627090424




BLK:20,SNR1: 19.991 ,SNR2: 40.399




Frequency (Hz)


0333+32 2024/06/27 0.10UT TOYOKAWA-KISO





F20240627090429




BLK:35,SNR1: 3.4390 ,SNR2: 11.581




K20240627090424





BLK:35,SNR1: 26.631 ,SNR2: 36.546




0333+32 2024/06/27 0.10UT FUJI -KISO



T20240627091729





BLK:19,SNR1: 0.13591 ,SNR2: 1.7512





0347+05 2024/06/27 0.32UT TOYOKAWA-FUJI



F20240627091731




BLK:19,SNR1: 1.6562 ,SNR2: 4.2641



T20240627091729





BLK:16,SNR1: 0.17158 ,SNR2: 2.0836




Frequency (Hz)

K20240627091727




BLK:16,SNR1: 20.825 ,SNR2: 34.100





Frequency (Hz)


0347+05 2024/06/27 0.32UT TOYOKAWA-KISO





F20240627091731




BLK:24,SNR1: 2.2452 ,SNR2: 5.9753




K20240627091727




BLK:24,SNR1: 6.1249 ,SNR2: 24.572




0347+05 2024/06/27 0.32UT FUJI -KISO



T20240627093303




BLK:11,SNR1: 2.0715 ,SNR2: 12.440




Frequency (Hz)

F20240627093305




BLK:11,SNR1: 2.0491 ,SNR2: 8.6614




Frequency (Hz)


0403-132 2024/06/27 0.58UT TOYOKAWA-FUJI



T20240627093303




BLK:17,SNR1: 5.8580 ,SNR2: 29.759





0403-132 2024/06/27 0.58UT TOYOKAWA-KISO

K20240627093300





BLK:17,SNR1: 0.30378 ,SNR2: 1.5302








F20240627093305




BLK: 7,SNR1: 0.44288E-01,SNR2: 1.2110




K20240627093300




BLK: 7,SNR1: 0.13464 ,SNR2: 0.85670




0403-132 2024/06/27 0.58UT FUJI -KISO



T20240627094214




BLK:14,SNR1: 0.38803 ,SNR2: 3.3966




Frequency (Hz)

F20240627094216




BLK:14,SNR1: 2.9456 ,SNR2: 13.254




Frequency (Hz)


0411+05 2024/06/27 0.73UT TOYOKAWA-FUJI



T20240627094214




BLK:14,SNR1: 0.34381 ,SNR2: 1.5140





0411+05 2024/06/27 0.73UT TOYOKAWA-KISO



K20240627094211




BLK:14,SNR1: 1.4481 ,SNR2: 6.2896



F20240627094216





BLK:17,SNR1: 2.9414 ,SNR2: 13.220




Frequency (Hz)

K20240627094211




BLK:17,SNR1: 1.2536 ,SNR2: 5.5893





Frequency (Hz)


0411+05 2024/06/27 0.73UT FUJI -KISO



T20240627094908





BLK:31,SNR1: 0.32471 ,SNR2: 2.1071




Frequency (Hz)

F20240627094910




BLK:31,SNR1: 20.074 ,SNR2: 32.691





Frequency (Hz)


0418+236 2024/06/27 0.85UT TOYOKAWA-FUJI





T20240627094908




BLK:32,SNR1: 0.64494 ,SNR2: 3.8731




K20240627094906




BLK:32,SNR1: 1.4109 ,SNR2: 5.3903




0418+236 2024/06/27 0.85UT TOYOKAWA-KISO



F20240627094910





BLK:37,SNR1: 18.405 ,SNR2: 29.076




Frequency (Hz)

K20240627094906




BLK:37,SNR1: 1.3261 ,SNR2: 5.0089




Frequency (Hz)


0418+236 2024/06/27 0.85UT FUJI -KISO



T20240627100035




BLK:24,SNR1: 2.6650 ,SNR2: 17.203




Frequency (Hz)

3C119 2024/06/27 1.04UT TOYOKAWA-FUJI


F20240627100037



BLK:24,SNR1: 0.52651 ,SNR2: 3.5782




Frequency (Hz)






T20240627100035





BLK:17,SNR1: 2.7548 ,SNR2: 18.357





3C119 2024/06/27 1.04UT TOYOKAWA-KISO


K20240627100032




BLK:17,SNR1: 0.51148 ,SNR2: 1.8041



F20240627100037





BLK:17,SNR1: 0.54396 ,SNR2: 3.7590





3C119 2024/06/27 1.04UT FUJI -KISO



K20240627100032




BLK:17,SNR1: 6.6578 ,SNR2: 22.477



T20240627104843




BLK:33,SNR1: 6.8086 ,SNR2: 55.181





3C138 2024/06/27 1.84UT TOYOKAWA-FUJI



F20240627104845




BLK:33,SNR1: 0.64524 ,SNR2: 3.1495



T20240627104843





BLK:29,SNR1: 6.8935 ,SNR2: 38.708





3C138 2024/06/27 1.84UT TOYOKAWA-KISO


K20240627104841




BLK:29,SNR1: 18.965 ,SNR2: 29.375



F20240627104845





BLK:24,SNR1: 0.63742 ,SNR2: 2.8633




Frequency (Hz)

3C138 2024/06/27 1.84UT FUJI -KISO


K20240627104841




BLK:24,SNR1: 6.4349 ,SNR2: 25.260




Frequency (Hz)



T20240627110216





BLK:24,SNR1: 14.223 ,SNR2: 27.637





0531+194 2024/06/27 2.07UT TOYOKAWA-FUJI



F20240627110218




BLK:24,SNR1: 4.1625 ,SNR2: 11.493



T20240627110216




BLK:28,SNR1: 13.337 ,SNR2: 25.917





0531+194 2024/06/27 2.07UT TOYOKAWA-KISO



K20240627110214




BLK:28,SNR1: 26.779 ,SNR2: 26.810




F20240627110218




BLK:21,SNR1: 10.272 ,SNR2: 20.844




K20240627110214



BLK:21,SNR1: 4.9318 ,SNR2: 13.408





0531+194 2024/06/27 2.07UT FUJI -KISO







T20240627111035




BLK:19,SNR1: 28.804 ,SNR2: 100.74




F20240627111037





BLK:19,SNR1: 0.64148 ,SNR2: 3.2560




3C147 2024/06/27 2.20UT TOYOKAWA-FUJI



T20240627111035




BLK:27,SNR1: 25.046 ,SNR2: 78.085





3C147 2024/06/27 2.20UT TOYOKAWA-KISO


K20240627111033




BLK:27,SNR1: 3.7601 ,SNR2: 13.181




F20240627111037




BLK:22,SNR1:-0.77436E-01,SNR2: 1.4594




K20240627111033




BLK:22,SNR1: 4.1931 ,SNR2: 14.774




3C147 2024/06/27 2.20UT FUJI -KISO



T20240627111847




BLK:17,SNR1: 3.8460 ,SNR2: 16.829




Frequency (Hz)

0548+16 2024/06/27 2.34UT TOYOKAWA-FUJI


F20240627111849




BLK:17,SNR1:-0.27888 ,SNR2: 0.61305




Frequency (Hz)



T20240627111847





BLK:23,SNR1: 3.1354 ,SNR2: 13.150





0548+16 2024/06/27 2.34UT TOYOKAWA-KISO


K20240627111845




BLK:23,SNR1: 1.6542 ,SNR2: 6.8347



F20240627111849





BLK:13,SNR1:-0.25183 ,SNR2: 0.75537





0548+16 2024/06/27 2.34UT FUJI -KISO


K20240627111845




BLK:13,SNR1: 2.5602 ,SNR2: 10.712



T20240627112258





BLK:15,SNR1: 89.979 ,SNR2: 115.60





0552+12 2024/06/27 2.41UT TOYOKAWA-FUJI



F20240627112300




BLK:15,SNR1: 0.19870E-01,SNR2: 4.6437



T20240627112258





BLK:19,SNR1: 61.193 ,SNR2: 79.118




Frequency (Hz)

0552+12 2024/06/27 2.41UT TOYOKAWA-KISO


K20240627112256



BLK:19,SNR1: 1.6124 ,SNR2: 6.5801





Frequency (Hz)







F20240627112300




BLK:23,SNR1:-0.68865E-01,SNR2: 3.8812




K20240627112256





BLK:23,SNR1: 1.7924 ,SNR2: 7.3234




0552+12 2024/06/27 2.41UT FUJI -KISO



T20240627112724




BLK:14,SNR1: 6.7903 ,SNR2: 19.209





0556+191 2024/06/27 2.48UT TOYOKAWA-FUJI



F20240627112726




BLK:14,SNR1: 0.14017 ,SNR2: 1.4896



T20240627112724





BLK:18,SNR1: 22.800 ,SNR2: 75.384




0556+191 2024/06/27 2.48UT TOYOKAWA-KISO


K20240627112722




BLK:18,SNR1: 3.9611 ,SNR2: 16.661




Frequency (Hz)





F20240627112726




BLK:19,SNR1: 2.3989 ,SNR2: 6.8906




K20240627112722





BLK:19,SNR1: 3.9671 ,SNR2: 16.686




0556+191 2024/06/27 2.48UT FUJI -KISO



T20240627113511





BLK:13,SNR1: 43.524 ,SNR2: 145.76




Frequency (Hz)

F20240627113513




BLK:13,SNR1: 2.8098 ,SNR2: 12.631





Frequency (Hz)


0605-08 2024/06/27 2.61UT TOYOKAWA-FUJI



T20240627113511





BLK:20,SNR1: 82.329 ,SNR2: 125.62




Frequency (Hz)

0605-08 2024/06/27 2.61UT TOYOKAWA-KISO


K20240627113508




BLK:20,SNR1: 1.4448 ,SNR2: 5.6422




Frequency (Hz)



F20240627113513





BLK:16,SNR1: 2.6897 ,SNR2: 12.113





0605-08 2024/06/27 2.61UT FUJI -KISO


K20240627113508




BLK:16,SNR1: 1.4681 ,SNR2: 5.7698




T20240627115418




BLK:39,SNR1: 326.54 ,SNR2: 422.22




F20240627115420



BLK:39,SNR1: 21.622 ,SNR2: 41.042




3C161 2024/06/27 2.93UT TOYOKAWA-FUJI








T20240627115418




BLK:23,SNR1: 371.91 ,SNR2: 490.25




K20240627115416




BLK:23,SNR1: 4.2038 ,SNR2: 19.017




3C161 2024/06/27 2.93UT TOYOKAWA-KISO





F20240627115420




BLK:27,SNR1: 21.566 ,SNR2: 40.948




K20240627115416




BLK:27,SNR1: 4.1382 ,SNR2: 18.720




3C161 2024/06/27 2.93UT FUJI -KISO




T20240627122151




BLK:16,SNR1: 0.96471 ,SNR2: 2.2489




F20240627122153




BLK:16,SNR1: 1.1864 ,SNR2: 3.3457




0652-130 2024/06/27 3.39UT TOYOKAWA-FUJI



T20240627122151





BLK:20,SNR1: 0.58023 ,SNR2: 3.7630





0652-130 2024/06/27 3.39UT TOYOKAWA-KISO


K20240627122149




BLK:20,SNR1: 1.3828 ,SNR2: 5.5736



F20240627122153





BLK:15,SNR1: 0.34161 ,SNR2: 1.3107




Frequency (Hz)

K20240627122149




BLK:15,SNR1: 0.94345 ,SNR2: 4.0512




Frequency (Hz)


0652-130 2024/06/27 3.39UT FUJI -KISO





T20240627123328




BLK:25,SNR1: 0.44308 ,SNR2: 1.9159




F20240627123330




BLK:25,SNR1: 3.5202 ,SNR2: 8.3283




0703+138 2024/06/27 3.59UT TOYOKAWA-FUJI



T20240627123328





BLK:17,SNR1: 0.50400 ,SNR2: 2.2380





0703+138 2024/06/27 3.59UT TOYOKAWA-KISO


K20240627123325




BLK:17,SNR1: 2.7564 ,SNR2: 5.4673




F20240627123330




BLK:23,SNR1: 3.0528 ,SNR2: 7.3432




K20240627123325



BLK:23,SNR1: 1.4875 ,SNR2: 5.8949




0703+138 2024/06/27 3.59UT FUJI -KISO







T20240627124250




BLK:26,SNR1: 1.9868 ,SNR2: 5.0493




F20240627124252




BLK:26,SNR1: 1.8048 ,SNR2: 6.0890




0713-024 2024/06/27 3.74UT TOYOKAWA-FUJI





T20240627124250




BLK:29,SNR1: 1.5157 ,SNR2: 5.3998




K20240627124248




BLK:29,SNR1: 4.3373 ,SNR2: 8.5658




0713-024 2024/06/27 3.74UT TOYOKAWA-KISO





F20240627124252




BLK:27,SNR1: 2.0714 ,SNR2: 7.3522




K20240627124248





BLK:27,SNR1: 4.2733 ,SNR2: 8.4403




0713-024 2024/06/27 3.74UT FUJI -KISO




T20240627125302




BLK:26,SNR1: 1.6106 ,SNR2: 6.8318




F20240627125304





BLK:26,SNR1: 4.5843 ,SNR2: 11.210




0723+10 2024/06/27 3.91UT TOYOKAWA-FUJI




T20240627125302




BLK:22,SNR1: 1.6993 ,SNR2: 7.3589




K20240627125259




BLK:22,SNR1: 2.5401 ,SNR2: 11.787




0723+10 2024/06/27 3.91UT TOYOKAWA-KISO




F20240627125304




BLK:29,SNR1: 4.6526 ,SNR2: 11.342




K20240627125259





BLK:29,SNR1: 6.1859 ,SNR2: 15.745




0723+10 2024/06/27 3.91UT FUJI -KISO




T20240627130317




BLK:15,SNR1: 4.8305 ,SNR2: 11.486




F20240627130319





BLK:15,SNR1: 0.74055 ,SNR2: 2.9762




0732+33 2024/06/27 4.0BUT TOYOKAWA-FUJI



T20240627130317





BLK:16,SNR1: 4.5900 ,SNR2: 11.063





0732+33 2024/06/27 4.08UT TOYOKAWA-KISO

K20240627130314





BLK:16,SNR1: 15.572 ,SNR2: 20.935








F20240627130319




BLK:28,SNR1: 0.25035 ,SNR2: 2.7991




K20240627130314





BLK:28,SNR1: 5.5235 ,SNR2: 10.859




0732+33 2024/06/27 4.08UT FUJI -KISO




T20240627131119




BLK:21,SNR1: 1.2981 ,SNR2: 9.8802




F20240627131121





BLK:21,SNR1: 0.20086 ,SNR2: 2.2681




0741-06 2024/06/27 4.22UT TOYOKAWA-FUJI



T20240627131119





BLK:28,SNR1: 1.2830 ,SNR2: 8.6889





0741-06 2024/06/27 4.22UT TOYOKAWA-KISO


K20240627131116




BLK:28,SNR1: 0.39237 ,SNR2: 1.4882




F20240627131121




BLK:14,SNR1: 0.74080E-01,SNR2: 2.3374




K20240627131116





BLK:14,SNR1: 0.27047 ,SNR2: 1.5984




0741-06 2024/06/27 4.22UT FUJI -KISO





T20240627132103




BLK:12,SNR1: 1.2638 ,SNR2: 6.0062




F20240627132105





BLK:12,SNR1: 0.23075 ,SNR2: 2.6583




0752-200 2024/06/27 4.38UT TOYOKAWA-FUJI



T20240627132103





BLK:10,SNR1: 0.77847 ,SNR2: 4.7588





0752-200 2024/06/27 4.38UT TOYOKAWA-KISO



K20240627132101




BLK:10,SNR1: 0.32184 ,SNR2: 1.6461





F20240627132105




BLK: 6,SNR1: 0.86798E-01,SNR2: 2.0582




K20240627132101





BLK: 6,SNR1: 0.15767 ,SNR2: 0.92820




0752-200 2024/06/27 4.38UT FUJI -KISO



T20240627132838





BLK:33,SNR1: 8.4812 ,SNR2: 21.268





3C190 2024/06/27 4.51UT TOYOKAWA-FUJI

F20240627132840





BLK:33,SNR1: 6.9257 ,SNR2: 19.837






T20240627132838





BLK:35,SNR1: 8.4577 ,SNR2: 21.209





3C190 2024/06/27 4.51UT TOYOKAWA-KISO



K20240627132836




BLK:35,SNR1: 8.7581 ,SNR2: 21.928



F20240627132840





BLK:35,SNR1: 7.4124 ,SNR2: 21.220





3C190 2024/06/27 4.51UT FUJI -KISO



K20240627132836




BLK:35,SNR1: 8.6400 ,SNR2: 21.641




T20240627134102




BLK:27,SNR1: 6.2304 ,SNR2: 15.414




F20240627134104





BLK:27,SNR1: 3.4168 ,SNR2: 15.526




3C196 2024/06/27 4.71UT TOYOKAWA-FUJI



T20240627134102





BLK:31,SNR1: 6.0627 ,SNR2: 14.989





3C196 2024/06/27 4.71UT TOYOKAWA-KISO



K20240627134100




BLK:31,SNR1: 9.5552 ,SNR2: 23.760



F20240627134104




BLK:31,SNR1: 3.3838 ,SNR2: 15.397





3C196 2024/06/27 4.71UT FUJI -KISO



K20240627134100




BLK:31,SNR1: 8.5938 ,SNR2: 21.434





T20240627135212




BLK:24,SNR1: 8.3293 ,SNR2: 20.933




F20240627135214





BLK:24,SNR1: 9.8220 ,SNR2: 24.531




0821+394 2024/06/27 4.90UT TOYOKAWA-FUJI



T20240627135212





BLK:18,SNR1: 8.3046 ,SNR2: 20.876





0821+394 2024/06/27 4.90UT TOYOKAWA-KISO



K20240627135209




BLK:18,SNR1: 2.6418 ,SNR2: 12.734



F20240627135214





BLK:26,SNR1: 9.7384 ,SNR2: 24.329





0821+394 2024/06/27 4.90UT FUJI -KISO

K20240627135209





BLK:26,SNR1: 2.6311 ,SNR2: 12.694








T20240627140352




BLK:26,SNR1: 2.7785 ,SNR2: 13.286




F20240627140354





BLK:26,SNR1: 8.5623 ,SNR2: 22.417




0834-19 2024/06/27 5.09UT TOYOKAWA-FUJI





T20240627140352




BLK:31,SNR1: 2.7788 ,SNR2: 13.287




K20240627140350





BLK:31,SNR1: 8.5208 ,SNR2: 21.014




0834-19 2024/06/27 5.09UT TOYOKAWA-KISO





F20240627140354




BLK:29,SNR1: 8.0036 ,SNR2: 24.031




K20240627140350





BLK:29,SNR1: 8.5443 ,SNR2: 15.285




0834-19 2024/06/27 5.09UT FUJI -KISO




T20240627140858




BLK: 5,SNR1: 8.3289 ,SNR2: 33.584




F20240627140900





BLK: 5,SNR1:-0.16584E-01,SNR2: 0.99748




0839-071 2024/06/27 5.18UT TOYOKAWA-FUJI



T20240627140858





BLK:15,SNR1: 5.4811 ,SNR2: 21.718





0839-071 2024/06/27 5.18UT TOYOKAWA-KISO


K20240627140856




BLK:15,SNR1: 0.58336 ,SNR2: 2.9491





F20240627140900




BLK:10,SNR1: 0.49442 ,SNR2: 2.9899




K20240627140856




BLK:10,SNR1: 0.57850 ,SNR2: 4.8922




0839-071 2024/06/27 5.18UT FUJI -KISO




T20240627141959




BLK:10,SNR1: 0.23223 ,SNR2: 1.7224




F20240627142001




BLK:10,SNR1: 0.43972 ,SNR2: 3.9089




3C208 2024/06/27 5.36UT TOYOKAWA-FUJI




T20240627141959




BLK:12,SNR1: 0.28381 ,SNR2: 2.2579




K20240627141957



BLK:12,SNR1: 0.49553 ,SNR2: 2.8651




3C208 2024/06/27 5.36UT TOYOKAWA-KISO






F20240627142001





BLK:14,SNR1: 0.31007 ,SNR2: 3.1914





3C208 2024/06/27 5.36UT FUJI -KISO



K20240627141957




BLK:14,SNR1: 0.36250 ,SNR2: 1.9511





T20240627143640




BLK:23,SNR1: 2.3877 ,SNR2: 5.7102




F20240627143642





BLK:23,SNR1: 1.0469 ,SNR2: 9.0000




3C216 2024/06/27 5.64UT TOYOKAWA-FUJI



T20240627143640




BLK:24,SNR1: 3.5969 ,SNR2: 8.9680





3C216 2024/06/27 5.64UT TOYOKAWA-KISO



K20240627143638




BLK:24,SNR1: 8.1393 ,SNR2: 20.152



F20240627143642





BLK:21,SNR1: 1.2458 ,SNR2: 3.6971





3C216 2024/06/27 5.64UT FUJI -KISO



K20240627143638




BLK:21,SNR1: 8.6023 ,SNR2: 21.264




T20240627144851




BLK:27,SNR1: 2.8859 ,SNR2: 12.654




F20240627144853




BLK:27,SNR1: 2.7166 ,SNR2: 9.4026





0919-142 2024/06/27 5.84UT TOYOKAWA-FUJI







BLK:25,SNR1: 7.7974 ,SNR2: 18.739




BLK:25,SNR1: 4.7663 ,SNR2: 12.014




0919-142 2024/06/27 5.84UT TOYOKAWA-KISO



F20240627144853





BLK:25,SNR1: 2.5850 ,SNR2: 6.5006




Frequency (Hz)

K20240627144849




BLK:25,SNR1: 2.2511 ,SNR2: 10.185




Frequency (Hz)


0919-142 2024/06/27 5.84UT FUJI -KISO




T20240627145530




BLK:22,SNR1: 3.9490 ,SNR2: 9.8199




F20240627145532



BLK:22,SNR1: 7.4738 ,SNR2: 17.183




0926+117 2024/06/27 5.95UT TOYOKAWA-FUJI







T20240627145530




BLK:26,SNR1: 7.1240 ,SNR2: 17.852




K20240627145528




BLK:26,SNR1: 3.4595 ,SNR2: 11.865




0926+117 2024/06/27 5.95UT TOYOKAWA-KISO




F20240627145532




BLK:21,SNR1: 6.5890 ,SNR2: 15.308




K20240627145528





BLK:21,SNR1: 3.7909 ,SNR2: 12.988




0926+117 2024/06/27 5.95UT FUJI -KISO





T20240627150315




BLK: 6,SNR1: 0.11393 ,SNR2: 1.9648




F20240627150317





BLK: 6,SNR1:-0.72017E-01,SNR2: 0.54988




3C222 2024/06/27 6.08UT TOYOKAWA-FUJI





T20240627150315




BLK:11,SNR1: 0.28052 ,SNR2: 0.81408




K20240627150312





BLK:11,SNR1: 0.54203 ,SNR2: 4.1942




3C222 2024/06/27 6.08UT TOYOKAWA-KISO





F20240627150317




BLK: 6,SNR1: 0.98315E-02,SNR2: 0.57349




K20240627150312





BLK: 6,SNR1: 0.21638 ,SNR2: 0.67759




3C222 2024/06/27 6.08UT FUJI -KISO





T20240627151015




BLK:36,SNR1: 8.3467 ,SNR2: 15.599




F20240627151017





BLK:36,SNR1: 7.8014 ,SNR2: 19.797




0941-08 2024/06/27 6.20UT TOYOKAWA-FUJI





T20240627151015




BLK:35,SNR1: 8.3539 ,SNR2: 15.613




K20240627151012





BLK:35,SNR1: 7.7143 ,SNR2: 24.273




0941-08 2024/06/27 6.20UT TOYOKAWA-KISO





F20240627151017




BLK:37,SNR1: 8.0590 ,SNR2: 20.438




K20240627151012



BLK:37,SNR1: 7.7131 ,SNR2: 24.269





0941-08 2024/06/27 6.20UT FUJI -KISO








T20240627151837




BLK:21,SNR1: 8.4268 ,SNR2: 21.363




F20240627151839





BLK:21,SNR1: 8.1206 ,SNR2: 15.184




3C230 2024/06/27 6.34UT TOYOKAWA-FUJI





T20240627151837




BLK:33,SNR1: 8.3322 ,SNR2: 15.567




K20240627151834





BLK:33,SNR1: 8.4074 ,SNR2: 22.148




3C230 2024/06/27 6.34UT TOYOKAWA-KISO





F20240627151839




BLK:24,SNR1: 8.1294 ,SNR2: 15.200




K20240627151834




BLK:24,SNR1: 8.4104 ,SNR2: 22.156




3C230 2024/06/27 6.34UT FUJI -KISO





T20240627153438




BLK:17,SNR1: 1.8318 ,SNR2: 11.387




F20240627153440




BLK:17,SNR1: 0.98465 ,SNR2: 4.4692




3C237 2024/06/27 6.61UT TOYOKAWA-FUJI





T20240627153438




BLK:20,SNR1: 1.3015 ,SNR2: 8.5765




K20240627153435





BLK:20,SNR1: 0.68019 ,SNR2: 3.4827




3C237 2024/06/27 6.61UT TOYOKAWA-KISO





F20240627153440




BLK:20,SNR1: 0.61016 ,SNR2: 3.0945




K20240627153435





BLK:20,SNR1: 0.69961 ,SNR2: 3.4989




3C237 2024/06/27 6.61UT FUJI -KISO





T20240627154054




BLK:33,SNR1: 2.7482 ,SNR2: 13.151




F20240627154056





BLK:33,SNR1: 13.602 ,SNR2: 31.455




1011+110 2024/06/27 6.71UT TOYOKAWA-FUJI




T20240627154054




BLK:33,SNR1: 6.8971 ,SNR2: 18.489




K20240627154051



BLK:33,SNR1: 16.251 ,SNR2: 28.625





1011+110 2024/06/27 6.71UT TOYOKAWA-KISO







F20240627154056




BLK:36,SNR1: 6.7849 ,SNR2: 19.178




K20240627154051





BLK:36,SNR1: 8.3288 ,SNR2: 20.917




1011+110 2024/06/27 6.71UT FUJI -KISO





T20240627154835




BLK:13,SNR1: 1.3766 ,SNR2: 5.9754




F20240627154837





BLK:13,SNR1: 114.51 ,SNR2: 121.07




3C241 2024/06/27 6.84UT TOYOKAWA-FUJI





T20240627154835




BLK:14,SNR1: 0.89184 ,SNR2: 4.5606




K20240627154832




BLK:14,SNR1: 9.0469 ,SNR2: 22.324





3C241 2024/06/27 6.84UT TOYOKAWA-KISO







BLK:10,SNR1: 112.12 ,SNR2: 119.17





BLK:10,SNR1: 7.6248 ,SNR2: 11.306




3C241 2024/06/27 6.84UT FUJI -KISO





T20240627160004




BLK: 9,SNR1: 0.48895 ,SNR2: 2.6829




F20240627160006





BLK: 9,SNR1: 1.2238 ,SNR2: 4.7550




1031-11 2024/06/27 7.03UT TOYOKAWA-FUJI



T20240627160004





BLK:15,SNR1: 0.37380 ,SNR2: 2.0473




Frequency (Hz)

K20240627160001




BLK:15,SNR1: 2.4973 ,SNR2: 8.9035





Frequency (Hz)


1031-11 2024/06/27 7.03UT TOYOKAWA-KISO



F20240627160006





BLK:13,SNR1: 0.92338 ,SNR2: 3.6273




Frequency (Hz)

K20240627160001




BLK:13,SNR1: 2.2063 ,SNR2: 8.4051





Frequency (Hz)


1031-11 2024/06/27 7.03UT FUJI -KISO



T20240627160438




BLK:28,SNR1: 7.6648 ,SNR2: 26.607




Frequency (Hz)

F20240627160440




BLK:28,SNR1: 15.565 ,SNR2: 37.410





Frequency (Hz)

1035-058 2024/06/27 7.11UT TOYOKAWA-FUJI






T20240627160438





BLK:28,SNR1: 7.6797 ,SNR2: 26.656




Frequency (Hz)

K20240627160435




BLK:28,SNR1: 10.834 ,SNR2: 20.149




Frequency (Hz)


1035-058 2024/06/27 7.11UT TOYOKAWA-KISO





F20240627160440




BLK:31,SNR1: 15.482 ,SNR2: 37.212




K20240627160435





BLK:31,SNR1: 10.636 ,SNR2: 19.790




1035-058 2024/06/27 7.11UT FUJI -KISO



T20240627161350




BLK:13,SNR1: 13.234 ,SNR2: 31.487




Frequency (Hz)

F20240627161352




BLK:13,SNR1: 0.54794 ,SNR2: 6.5663




Frequency (Hz)


1044-008 2024/06/27 7.26UT TOYOKAWA-FUJI




T20240627161350




BLK:20,SNR1: 12.358 ,SNR2: 29.402




K20240627161347




BLK:20,SNR1: 3.8099 ,SNR2: 13.418




1044-008 2024/06/27 7.26UT TOYOKAWA-KISO



F20240627161352




BLK:18,SNR1: 2.5431 ,SNR2: 8.8252




Frequency (Hz)

K20240627161347




BLK:18,SNR1: 8.0750 ,SNR2: 15.666





Frequency (Hz)


1044-008 2024/06/27 7.26UT FUJI -KISO





T20240627162455




BLK:12,SNR1: 4.2382 ,SNR2: 13.474




F20240627162457





BLK:12,SNR1: 0.73832E-01,SNR2: 1.7939




1055+01 2024/06/27 7.44UT TOYOKAWA-FUJI



T20240627162455





BLK:22,SNR1: 7.2789 ,SNR2: 26.918




Frequency (Hz)

K20240627162452




BLK:22,SNR1: 3.5814 ,SNR2: 7.0519





Frequency (Hz)


1055+01 2024/06/27 7.44UT TOYOKAWA-KISO



F20240627162457





BLK:11,SNR1: 0.86851E-01,SNR2: 2.1051




Frequency (Hz)

K20240627162452




BLK:11,SNR1: 8.4945 ,SNR2: 14.863





Frequency (Hz)

1055+01 2024/06/27 7.44UT FUJI -KISO








T20240627163612




BLK:14,SNR1: 1.5166 ,SNR2: 3.8246




F20240627163614





BLK:14,SNR1: 2.4771 ,SNR2: 6.3416




1107+109 2024/06/27 7.63UT TOYOKAWA-FUJI



T20240627163612





BLK:14,SNR1: 2.8766 ,SNR2: 6.9889




Frequency (Hz)

K20240627163609




BLK:14,SNR1: 6.1148 ,SNR2: 11.957





Frequency (Hz)


1107+109 2024/06/27 7.63UT TOYOKAWA-KISO



F20240627163614





BLK:10,SNR1: 2.8460 ,SNR2: 7.1645




Frequency (Hz)

K20240627163609




BLK:10,SNR1: 7.5862 ,SNR2: 13.624





Frequency (Hz)


1107+109 2024/06/27 7.63UT FUJI -KISO



T20240627164550




BLK: 6,SNR1: 88.864 ,SNR2: 117.17




Frequency (Hz)

F20240627164552




BLK: 6,SNR1: 2.1530 ,SNR2: 4.2619





Frequency (Hz)


3C255 2024/06/27 7.79UT TOYOKAWA-FUJI





T20240627164550




BLK:21,SNR1: 88.796 ,SNR2: 117.08




K20240627164547





BLK:21,SNR1: 87.544 ,SNR2: 88.416




3C255 2024/06/27 7.79UT TOYOKAWA-KISO



F20240627164552





BLK: 7,SNR1: 0.45945 ,SNR2: 2.9282




Frequency (Hz)

K20240627164547




BLK: 7,SNR1: 90.157 ,SNR2: 91.055





Frequency (Hz)


3C255 2024/06/27 7.79UT FUJI -KISO



T20240627170948




BLK: 4,SNR1: 0.29589 ,SNR2: 2.8819




Frequency (Hz)

F20240627170950




BLK: 4,SNR1:-0.42835E-01,SNR2: 3.4092





Frequency (Hz)


3C263.1 2024/06/27 8.19UT TOYOKAWA-FUJI



T20240627170948





BLK:11,SNR1: 0.21186 ,SNR2: 0.85024




Frequency (Hz)

K20240627170945




BLK:11,SNR1: 1.4270 ,SNR2: 5.0133





Frequency (Hz)

3C263.1 2024/06/27 8.19UT TOYOKAWA-KISO






F20240627170950




BLK: 2,SNR1: 0.14538 ,SNR2: 3.9764




Frequency (Hz)

K20240627170945




BLK: 2,SNR1: 4.0345 ,SNR2: 13.271





Frequency (Hz)


3C263.1 2024/06/27 8.19UT FUJI -KISO





T20240627171615




BLK: 7,SNR1: 0.33474 ,SNR2: 1.9044




F20240627171617





BLK: 7,SNR1:-0.12271E-01,SNR2: 2.5928




3C267 2024/06/27 8.30UT TOYOKAWA-FUJI



T20240627171615





BLK: 8,SNR1: 0.35736 ,SNR2: 2.1891




Frequency (Hz)

K20240627171613




BLK: 8,SNR1: 0.52803 ,SNR2: 2.8835





Frequency (Hz)


3C267 2024/06/27 8.30UT TOYOKAWA-KISO



F20240627171617





BLK: 8,SNR1: 0.37485 ,SNR2: 1.5806




Frequency (Hz)

K20240627171613




BLK: 8,SNR1: 0.60749 ,SNR2: 4.9985





Frequency (Hz)


3C267 2024/06/27 8.30UT FUJI -KISO



T20240627173529





BLK:19,SNR1: 0.79721 ,SNR2: 2.5732




Frequency (Hz)

F20240627173531




BLK:19,SNR1: 6.8159 ,SNR2: 16.232





Frequency (Hz)


1206+439 2024/06/27 8.62UT TOYOKAWA-FUJI



T20240627173529





BLK:15,SNR1: 1.1411 ,SNR2: 5.0653




Frequency (Hz)

K20240627173526




BLK:15,SNR1: 2.1702 ,SNR2: 7.9798





Frequency (Hz)


1206+439 2024/06/27 8.62UT TOYOKAWA-KISO



F20240627173531




BLK:17,SNR1: 7.0822 ,SNR2: 16.854




Frequency (Hz)

K20240627173526



BLK:17,SNR1: 1.9657 ,SNR2: 7.4550



Frequency (Hz)

1206+439 2024/06/27 8.62UT FUJI -KISO

