



T20240629054837





BLK: 3,SNR1:-0.54883E-01,SNR2: 0.46084




Frequency (Hz)

F20240629054839




BLK: 3,SNR1: 0.11035E-01,SNR2: 0.93017




Frequency (Hz)


0025+373 2024/06/28 20.84UT TOYOKAWA-FUJI



T20240629054837





BLK: 2,SNR1: 0.77740 ,SNR2: 1.1931




Frequency (Hz)

K20240629054834




BLK: 2,SNR1: 1.8379 ,SNR2: 6.7960





Frequency (Hz)

0025+373 2024/06/28 20.84UT TOYOKAWA-KISO






F20240629054839





BLK: 7,SNR1: 11.044 ,SNR2: 14.460




Frequency (Hz)

K20240629054834




BLK: 7,SNR1: 0.35221 ,SNR2: 2.2765





Frequency (Hz)


0025+373 2024/06/28 20.84UT FUJI -KISO



T20240629060117





BLK: 9,SNR1: 0.53314 ,SNR2: 2.8819




Frequency (Hz)

F20240629060119




BLK: 9,SNR1:-0.69162E-01,SNR2: 2.2823





Frequency (Hz)


0038+328 2024/06/28 21.05UT TOYOKAWA-FUJI



T20240629060117





BLK: 3,SNR1: 1.0727 ,SNR2: 3.7675




Frequency (Hz)

K20240629060114





BLK: 3,SNR1: 0.17341 ,SNR2: 1.1659





Frequency (Hz)

0038+328 2024/06/28 21.05UT TOYOKAWA-KISO







BLK: 5, SNR1: 0.70069 ,SNR2: 2.3321





BLK: 5, SNR1: 0.40058 ,SNR2: 1.8161




0038+328 2024/06/28 21.05UT FUJI -KISO



T20240629062305





BLK: 8,SNR1: 3.1221 ,SNR2: 13.643




Frequency (Hz)

0100+146 2024/06/28 21.41UT TOYOKAWA-FUJI


F20240629062307





BLK: 8,SNR1: 2.6831 ,SNR2: 4.1447




Frequency (Hz)



T20240629062305




BLK:12,SNR1: 3.0434 ,SNR2: 13.374




Frequency (Hz)

K20240629062302




BLK:12,SNR1: 0.39049 ,SNR2: 2.0821





Frequency (Hz)


0100+146 2024/06/28 21.41UT TOYOKAWA-KISO





F20240629062307




BLK: 9,SNR1: 2.0632 ,SNR2: 5.8869




K20240629062302





BLK: 9,SNR1: 0.58409 ,SNR2: 2.2641




0100+146 2024/06/28 21.41UT FUJI -KISO



T20240629063242





BLK: 8,SNR1: 0.61066 ,SNR2: 10.896




Frequency (Hz)

F20240629063244




BLK: 8,SNR1: 1.5795 ,SNR2: 11.520




Frequency (Hz)

0109+416 2024/06/28 21.57UT TOYOKAWA-FUJI






T20240629063242




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0109+416 2024/06/28 21.57UT TOYOKAWA-KISO




F20240629063244




No.Good Data




KISO




No.Good Data




0109+416 2024/06/28 21.57UT FUJI -KISO



T20240629064347





BLK: 5,SNR1:-0.40490E-01,SNR2: 0.66910




Frequency (Hz)

F20240629064349




BLK: 5,SNR1: 0.33949 ,SNR2: 4.3361





Frequency (Hz)


0120+405 2024/06/28 21.76UT TOYOKAWA-FUJI





T20240629064347




No.Good Data




KISO




No.Good Data




0120+405 2024/06/28 21.76UT TOYOKAWA-KISO




F20240629064349




No.Good Data




KISO





No.Good Data




0120+405 2024/06/28 21.76UT FUJI -KISO



T20240629065125





BLK:22,SNR1: 2.7987 ,SNR2: 13.343




Frequency (Hz)

F20240629065127




BLK:22,SNR1: 3.5358 ,SNR2: 15.302




Frequency (Hz)


0128+03 2024/06/28 21.89UT TOYOKAWA-FUJI





T20240629065125




No.Good Data




KISO





No.Good Data




0128+03 2024/06/28 21.89UT TOYOKAWA-KISO




F20240629065127




No.Good Data




KISO



No.Good Data




0128+03 2024/06/28 21.89UT FUJI -KISO






T20240629065759



BLK:19,SNR1: 2.2087 ,SNR2: 5.5490





Frequency (Hz)


3C48

2024/06/28 21.99UT TOYOKAWA-FUJI


F20240629065801




BLK:19,SNR1: 0.58656E-01,SNR2: 1.7114




Frequency (Hz)



T20240629065759





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C48 2024/06/28 21.99UT TOYOKAWA-KISO





F20240629065801




No.Good Data




KISO





No.Good Data




3C48 2024/06/28 21.99UT FUJI -KISO



T20240629071744





BLK: 7,SNR1:-0.35165E-01,SNR2: 0.41531




Frequency (Hz)

F20240629071746




BLK: 7,SNR1: 1.7486 ,SNR2: 5.9254





Frequency (Hz)


0155-109 2024/06/28 22.32UT TOYOKAWA-FUJI



T20240629071744





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0155-109 2024/06/28 22.32UT TOYOKAWA-KISO



F20240629071746





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0155-109 2024/06/28 22.32UT FUJI -KISO



T20240629072451





BLK: 7,SNR1: 0.23903 ,SNR2: 1.8696




Frequency (Hz)

F20240629072453




BLK: 7,SNR1: 0.85238 ,SNR2: 3.7011





Frequency (Hz)


0202+15 2024/06/28 22.44UT TOYOKAWA-FUJI



T20240629072451





BLK:11,SNR1: 0.17975 ,SNR2: 2.0387




Frequency (Hz)

K20240629072448




BLK:11,SNR1: 7.0372 ,SNR2: 13.480





Frequency (Hz)

0202+15 2024/06/28 22.44UT TOYOKAWA-KISO






F20240629072453





BLK:20,SNR1: 2.0119 ,SNR2: 3.9751




Frequency (Hz)

K20240629072448




BLK:20,SNR1: 6.4863 ,SNR2: 16.494




Frequency (Hz)


0202+15 2024/06/28 22.44UT FUJI -KISO




T20240629073641




BLK: 4,SNR1: 0.13220 ,SNR2: 2.0016




F20240629073643




BLK: 4,SNR1: 3.6501 ,SNR2: 9.1357




0213+178 2024/06/28 22.64UT TOYOKAWA-FUJI



T20240629073641




BLK: 9,SNR1: 0.60235E-01,SNR2: 1.0755




Frequency (Hz)

K20240629073638




BLK: 9,SNR1: 3.0683 ,SNR2: 11.592





Frequency (Hz)


0213+178 2024/06/28 22.64UT TOYOKAWA-KISO



F20240629073643





BLK:18,SNR1: 3.0296 ,SNR2: 8.4104




Frequency (Hz)

K20240629073638




BLK:18,SNR1: 3.2679 ,SNR2: 6.4589





Frequency (Hz)


0213+178 2024/06/28 22.64UT FUJI -KISO



T20240629074423





BLK: 7,SNR1: 0.11667 ,SNR2: 0.69007




Frequency (Hz)

F20240629074425




BLK: 7,SNR1: 1.0874 ,SNR2: 3.0223




Frequency (Hz)


3C67 2024/06/28 22.77UT TOYOKAWA-FUJI



T20240629074423



BLK: 8,SNR1: 0.18315 ,SNR2: 0.51725




Frequency (Hz)


3C67

2024/06/28 22.77UT TOYOKAWA-KISO


K20240629074420




BLK: 8,SNR1: 2.5377 ,SNR2: 9.9085




Frequency (Hz)




F20240629074425




BLK: 6,SNR1: 0.19725E-02,SNR2: 0.54847




K20240629074420





BLK: 6,SNR1: 3.7791 ,SNR2: 14.301




3C67 2024/06/28 22.77UT FUJI -KISO



T20240629080238




BLK: 2,SNR1: 0.39745E-01,SNR2: 0.80759




Frequency (Hz)

3C71 2024/06/28 23.07UT TOYOKAWA-FUJI


F20240629080240



BLK: 2,SNR1: 1.8902 ,SNR2: 7.6971





Frequency (Hz)






T20240629080238



BLK: 4, SNR1: 0.11146 , SNR2: 0.49219





Frequency (Hz)


3C71

2024/06/28 23.07UT TOYOKAWA-KISO


K20240629080235





BLK: 4, SNR1: 0.10327 , SNR2: 0.75937




Frequency (Hz)



F20240629080240



BLK: 8,SNR1: 0.64835 ,SNR2: 4.7530




Frequency (Hz)


3C71

2024/06/28 23.07UT FUJI -KISO


K20240629080235




BLK: 8,SNR1: 0.37009 ,SNR2: 1.7343




Frequency (Hz)



T20240629082153




BLK:21,SNR1: 22.589 ,SNR2: 70.612




Frequency (Hz)

F20240629082155




BLK:21,SNR1: 4.6581 ,SNR2: 11.816





Frequency (Hz)


0258+350 2024/06/28 23.39UT TOYOKAWA-FUJI



T20240629082153





BLK:20,SNR1: 22.445 ,SNR2: 70.169




Frequency (Hz)

K20240629082150




BLK:20,SNR1: 14.940 ,SNR2: 60.959





Frequency (Hz)


0258+350 2024/06/28 23.39UT TOYOKAWA-KISO





F20240629082155




BLK:26,SNR1: 4.3492 ,SNR2: 11.008




K20240629082150





BLK:26,SNR1: 3.6191 ,SNR2: 15.478




0258+350 2024/06/28 23.39UT FUJI -KISO



T20240629083142





BLK: 8,SNR1: 0.38162E-01,SNR2: 1.0881




Frequency (Hz)

F20240629083144




BLK: 8,SNR1: 4.5832 ,SNR2: 8.1709





Frequency (Hz)


0308+305 2024/06/28 23.56UT TOYOKAWA-FUJI





T20240629083142




BLK:10,SNR1: 0.87541E-01,SNR2: 0.47784




K20240629083139





BLK:10,SNR1: 2.7695 ,SNR2: 12.423




0308+305 2024/06/28 23.56UT TOYOKAWA-KISO





F20240629083144




BLK:10,SNR1: 4.0146 ,SNR2: 11.098




K20240629083139



BLK:10,SNR1: 6.9719 ,SNR2: 13.554





0308+305 2024/06/28 23.56UT FUJI -KISO






T20240629084314





BLK: 7,SNR1: 0.37237 ,SNR2: 1.9447




Frequency (Hz)

F20240629084316




BLK: 7,SNR1: 0.33334 ,SNR2: 1.7586





Frequency (Hz)


0320+05 2024/06/28 23.75UT TOYOKAWA-FUJI



T20240629084314





BLK: 6,SNR1: 0.43564 ,SNR2: 1.8648




Frequency (Hz)

K20240629084311




BLK: 6,SNR1: 2.3010 ,SNR2: 8.8092





Frequency (Hz)


0320+05 2024/06/28 23.75UT TOYOKAWA-KISO



F20240629084316





BLK:10,SNR1: 5.0141 ,SNR2: 11.105




Frequency (Hz)

K20240629084311




BLK:10,SNR1: 1.3136 ,SNR2: 5.1200





Frequency (Hz)


0320+05 2024/06/28 23.75UT FUJI -KISO




T20240629085404




BLK: 6,SNR1: 0.85418E-01,SNR2: 0.27899




F20240629085406





BLK: 6,SNR1: 1.4224 ,SNR2: 3.3554




0331-013 2024/06/28 23.93UT TOYOKAWA-FUJI





T20240629085404




BLK: 9,SNR1: 0.34510E-01,SNR2: 0.38778




K20240629085401





BLK: 9,SNR1: 1.0360 ,SNR2: 4.4612




0331-013 2024/06/28 23.93UT TOYOKAWA-KISO



F20240629085406





BLK:13,SNR1: 0.58198 ,SNR2: 2.7973




Frequency (Hz)

K20240629085401




BLK:13,SNR1: 0.94320 ,SNR2: 4.0776





Frequency (Hz)


0331-013 2024/06/28 23.93UT FUJI -KISO





T20240629090937




BLK: 3,SNR1: 0.18390 ,SNR2: 0.55805




F20240629090939





BLK: 3,SNR1:-0.83222E-01,SNR2: 0.24310




0347+05 2024/06/29 0.19UT TOYOKAWA-FUJI





T20240629090937




BLK: 3,SNR1:-0.37950E-01,SNR2: 1.2072




K20240629090935



BLK: 3,SNR1: 0.93840E-01,SNR2: 1.3755




0347+05 2024/06/29 0.19UT TOYOKAWA-KISO







F20240629090939




BLK: 1,SNR1: 0.75585 ,SNR2: 2.9381




K20240629090935




BLK: 1,SNR1: 0.19461E-01,SNR2: 0.0000




0347+05 2024/06/29 0.19UT FUJI -KISO



T20240629092511




BLK: 6,SNR1: 1.1461 ,SNR2: 11.638




Frequency (Hz)

F20240629092513




BLK: 6,SNR1: 0.30851 ,SNR2: 1.5825




Frequency (Hz)


0403-132 2024/06/29 0.45UT TOYOKAWA-FUJI



T20240629092511





BLK:13,SNR1: 1.4008 ,SNR2: 14.736





0403-132 2024/06/29 0.45UT TOYOKAWA-KISO



K20240629092508




BLK:13,SNR1: 0.60991 ,SNR2: 2.1790





F20240629092513




BLK: 3, SNR1: 0.10496 , SNR2: 1.6989




K20240629092508





BLK: 3, SNR1: 1.7766 , SNR2: 6.8836




0403-132 2024/06/29 0.45UT FUJI -KISO



T20240629093422





BLK: 3,SNR1: 0.96450E-01,SNR2: 0.76796





0411+05 2024/06/29 0.60UT TOYOKAWA-FUJI



F20240629093424




BLK: 3,SNR1:-0.18008 ,SNR2: 0.85205E-02



T20240629093422





BLK: 6,SNR1: 0.94651E-01,SNR2: 1.1611





0411+05 2024/06/29 0.60UT TOYOKAWA-KISO


K20240629093419




BLK: 6,SNR1: 1.3925 ,SNR2: 7.3553





F20240629093424




BLK: 5,SNR1: 0.69147 ,SNR2: 6.5744




K20240629093419




BLK: 5,SNR1: 1.2018 ,SNR2: 7.0506




0411+05 2024/06/29 0.60UT FUJI -KISO



T20240629094116




BLK:12,SNR1: 0.42687E-01,SNR2: 0.19893




Frequency (Hz)

F20240629094118




BLK:12,SNR1: 1.1757 ,SNR2: 3.8866





Frequency (Hz)

0418+236 2024/06/29 0.72UT TOYOKAWA-FUJI






T20240629094116





BLK: 3,SNR1: 0.49105E-01,SNR2: 0.41809




Frequency (Hz)

K20240629094114




BLK: 3,SNR1: 0.19207 ,SNR2: 0.83341





Frequency (Hz)


0418+236 2024/06/29 0.72UT TOYOKAWA-KISO





F20240629094118




BLK:13,SNR1: 1.0596 ,SNR2: 8.3488




K20240629094114




BLK:13,SNR1: 0.81740 ,SNR2: 4.1547




0418+236 2024/06/29 0.72UT FUJI -KISO





T20240629095243




BLK:17,SNR1: 1.5190 ,SNR2: 14.718




F20240629095245




BLK:17,SNR1: 0.24670 ,SNR2: 2.1919




3C119 2024/06/29 0.91UT TOYOKAWA-FUJI



T20240629095243





BLK:20,SNR1: 1.7477 ,SNR2: 6.5546





3C119 2024/06/29 0.91UT TOYOKAWA-KISO


K20240629095241




BLK:20,SNR1: 2.7018 ,SNR2: 10.536




F20240629095245




BLK:18,SNR1: 0.16299 ,SNR2: 1.3011




K20240629095241





BLK:18,SNR1: 0.42861 ,SNR2: 2.1544




3C119 2024/06/29 0.91UT FUJI -KISO



T20240629104051





BLK:31,SNR1: 4.0626 ,SNR2: 17.047





3C138 2024/06/29 1.71UT TOYOKAWA-FUJI



F20240629104053




BLK:31,SNR1: 16.375 ,SNR2: 21.345



T20240629104051




BLK:22,SNR1: 10.786 ,SNR2: 21.181





3C138 2024/06/29 1.71UT TOYOKAWA-KISO



K20240629104048




BLK:22,SNR1: 4.1021 ,SNR2: 11.311



F20240629104053




BLK:25,SNR1: 17.742 ,SNR2: 22.980





3C138 2024/06/29 1.71UT FUJI -KISO

K20240629104048





BLK:25,SNR1: 3.8631 ,SNR2: 10.698






T20240629105424




BLK:34,SNR1: 3.7698 ,SNR2: 12.172




Frequency (Hz)

F20240629105426




BLK:34,SNR1: 0.25236 ,SNR2: 2.9098




Frequency (Hz)


0531+194 2024/06/29 1.93UT TOYOKAWA-FUJI




T20240629105424




BLK:37,SNR1: 3.7885 ,SNR2: 12.227




K20240629105421





BLK:37,SNR1: 3.8367 ,SNR2: 12.375




0531+194 2024/06/29 1.93UT TOYOKAWA-KISO



F20240629105426





BLK:23,SNR1: 0.32943 ,SNR2: 3.0591




Frequency (Hz)

K20240629105421




BLK:23,SNR1: 3.8152 ,SNR2: 12.313




Frequency (Hz)


0531+194 2024/06/29 1.93UT FUJI -KISO




T20240629110243




BLK:29,SNR1: 11.070 ,SNR2: 51.066




F20240629110245




BLK:29,SNR1: 0.61838 ,SNR2: 4.2472




3C147 2024/06/29 2.07UT TOYOKAWA-FUJI



T20240629110243




BLK:32,SNR1: 10.821 ,SNR2: 52.320





3C147 2024/06/29 2.07UT TOYOKAWA-KISO


K20240629110241




BLK:32,SNR1: 3.8694 ,SNR2: 14.283



F20240629110245




BLK:23,SNR1: 0.84878 ,SNR2: 4.4172





3C147 2024/06/29 2.07UT FUJI -KISO


K20240629110241




BLK:23,SNR1: 2.2544 ,SNR2: 8.8973



T20240629111055





BLK:24,SNR1: 1.9665 ,SNR2: 9.4438





0548+16 2024/06/29 2.21UT TOYOKAWA-FUJI


F20240629111057




BLK:24,SNR1: 0.23902 ,SNR2: 2.3295



T20240629111055




BLK:15,SNR1: 1.9782 ,SNR2: 8.8764




0548+16 2024/06/29 2.21UT TOYOKAWA-KISO


K20240629111053



BLK:15,SNR1: 0.28722 ,SNR2: 3.0752




Frequency (Hz)








F20240629111057




BLK:15,SNR1: 0.33940 ,SNR2: 3.2749




K20240629111053




BLK:15,SNR1: 0.42333 ,SNR2: 2.0645




0548+16 2024/06/29 2.21UT FUJI -KISO



T20240629111506





BLK: 7,SNR1: 6.2427 ,SNR2: 50.568




0552+12 2024/06/29 2.28UT TOYOKAWA-FUJI


F20240629111508




BLK: 7,SNR1: 0.18194 ,SNR2: 0.79893




Frequency (Hz)



T20240629111506





BLK:15,SNR1: 14.292 ,SNR2: 103.47





0552+12 2024/06/29 2.28UT TOYOKAWA-KISO


K20240629111503




BLK:15,SNR1: 0.30123 ,SNR2: 2.5914





F20240629111508




BLK:12,SNR1: 0.56976 ,SNR2: 2.0239




K20240629111503





BLK:12,SNR1: 0.43693 ,SNR2: 1.7895




0552+12 2024/06/29 2.28UT FUJI -KISO




T20240629111933




BLK:14,SNR1: 0.97222 ,SNR2: 4.6797




F20240629111935





BLK:14,SNR1: 0.70492E-01,SNR2: 1.3757




0556+191 2024/06/29 2.35UT TOYOKAWA-FUJI



T20240629111933





BLK:11,SNR1: 1.0068 ,SNR2: 5.2824





0556+191 2024/06/29 2.35UT TOYOKAWA-KISO


K20240629111930




BLK:11,SNR1: 0.72974 ,SNR2: 4.4379





F20240629111935




BLK: 8,SNR1:-0.41463E-01,SNR2: 1.5205




K20240629111930




BLK: 8,SNR1: 0.82138 ,SNR2: 4.1564




0556+191 2024/06/29 2.35UT FUJI -KISO




T20240629112719




BLK: 3,SNR1: 0.89574 ,SNR2: 7.3468




F20240629112721



BLK: 3,SNR1:-0.41385E-01,SNR2: 2.0038




0605-08 2024/06/29 2.48UT TOYOKAWA-FUJI








T20240629112719




BLK: 4,SNR1: 0.28217 ,SNR2: 0.57434




K20240629112716




BLK: 4,SNR1:-0.12066E-01,SNR2: 1.5980




0605-08 2024/06/29 2.48UT TOYOKAWA-KISO



F20240629112721





BLK: 2,SNR1:-0.11434 ,SNR2: 0.39100





0605-08 2024/06/29 2.48UT FUJI -KISO



K20240629112716




BLK: 2,SNR1: 3.5070 ,SNR2: 14.452




T20240629114626




BLK:15,SNR1: 3.0575 ,SNR2: 10.836




F20240629114628




BLK:15,SNR1: 2.3030 ,SNR2: 8.0718




3C161 2024/06/29 2.80UT TOYOKAWA-FUJI




T20240629114626




BLK:28,SNR1: 2.6544 ,SNR2: 5.4314




K20240629114623





BLK:28,SNR1: 5.2106 ,SNR2: 10.169




3C161 2024/06/29 2.80UT TOYOKAWA-KISO



F20240629114628





BLK:28,SNR1: 1.9055 ,SNR2: 6.8084




Frequency (Hz)

3C161 2024/06/29 2.80UT FUJI -KISO


K20240629114623





BLK:28,SNR1: 5.1908 ,SNR2: 10.231




Frequency (Hz)




T20240629121400




BLK: 5,SNR1: 54.324 ,SNR2: 84.162




F20240629121402





BLK: 5,SNR1: 1.3846 ,SNR2: 5.8944




0652-130 2024/06/29 3.26UT TOYOKAWA-FUJI



T20240629121400




BLK: 7,SNR1: 42.541 ,SNR2: 56.449





0652-130 2024/06/29 3.26UT TOYOKAWA-KISO


K20240629121357




BLK: 7,SNR1: 1.0604 ,SNR2: 6.6006





F20240629121402




BLK:10,SNR1: 0.31454 ,SNR2: 2.2094




K20240629121357



BLK:10,SNR1: 0.36598 ,SNR2: 1.5542





0652-130 2024/06/29 3.26UT FUJI -KISO








T20240629122536




BLK: 3,SNR1:-0.10350 ,SNR2: 0.35241




F20240629122538





BLK: 3,SNR1: 0.30272 ,SNR2: 1.2717




0703+138 2024/06/29 3.45UT TOYOKAWA-FUJI





T20240629122536




BLK: 6,SNR1: 0.79744E-01,SNR2: 2.0121




K20240629122533





BLK: 6,SNR1: 0.66619 ,SNR2: 2.8319




0703+138 2024/06/29 3.45UT TOYOKAWA-KISO



F20240629122538





BLK: 3,SNR1:-0.30217E-01,SNR2: 2.1500




Frequency (Hz)

K20240629122533




BLK: 3,SNR1: 2.9132 ,SNR2: 14.302





Frequency (Hz)


0703+138 2024/06/29 3.45UT FUJI -KISO





T20240629123459




BLK: 7,SNR1: 0.20538E-01,SNR2: 0.72038




F20240629123501




BLK: 7,SNR1: 0.53198 ,SNR2: 2.4522




0713-024 2024/06/29 3.61UT TOYOKAWA-FUJI





T20240629123459




BLK: 6,SNR1: 0.20548 ,SNR2: 0.85247




K20240629123456




BLK: 6,SNR1: 1.1537 ,SNR2: 5.1394




0713-024 2024/06/29 3.61UT TOYOKAWA-KISO





F20240629123501




BLK:11,SNR1: 0.51164 ,SNR2: 1.8895




K20240629123456




BLK:11,SNR1: 0.87212 ,SNR2: 3.4738




0713-024 2024/06/29 3.61UT FUJI -KISO




T20240629124510




BLK:12,SNR1: 0.68679 ,SNR2: 3.1865




F20240629124512





BLK:12,SNR1: 2.6004 ,SNR2: 11.938




0723+10 2024/06/29 3.78UT TOYOKAWA-FUJI





T20240629124510




BLK:19,SNR1: 0.71320 ,SNR2: 3.0870




K20240629124507



BLK:19,SNR1: 0.82353 ,SNR2: 3.3708





0723+10 2024/06/29 3.78UT TOYOKAWA-KISO






F20240629124512





BLK:16,SNR1: 7.4913 ,SNR2: 18.073





0723+10 2024/06/29 3.78UT FUJI -KISO


K20240629124507




BLK:16,SNR1: 2.7164 ,SNR2: 5.7306



T20240629125525





BLK:28,SNR1: 6.6221 ,SNR2: 18.497





0732+33 2024/06/29 3.95UT TOYOKAWA-FUJI


F20240629125527




BLK:28,SNR1: 7.3956 ,SNR2: 21.380



T20240629125525





BLK:29,SNR1: 6.5884 ,SNR2: 18.416





0732+33 2024/06/29 3.95UT TOYOKAWA-KISO



K20240629125522




BLK:29,SNR1: 6.2521 ,SNR2: 16.082



F20240629125527





BLK:23,SNR1: 7.3737 ,SNR2: 21.318





0732+33 2024/06/29 3.95UT FUJI -KISO



K20240629125522




BLK:23,SNR1: 8.3643 ,SNR2: 20.965





T20240629130327




BLK:30,SNR1: 8.2842 ,SNR2: 21.027




F20240629130329





BLK:30,SNR1: 7.0279 ,SNR2: 20.453




0741-06 2024/06/29 4.09UT TOYOKAWA-FUJI



T20240629130327




BLK:32,SNR1: 8.2978 ,SNR2: 21.061





0741-06 2024/06/29 4.09UT TOYOKAWA-KISO



K20240629130324




BLK:32,SNR1: 7.5405 ,SNR2: 18.972



F20240629130329




BLK:32,SNR1: 11.047 ,SNR2: 19.519





0741-06 2024/06/29 4.09UT FUJI -KISO



K20240629130324




BLK:32,SNR1: 7.5765 ,SNR2: 19.060



T20240629131311




BLK:21,SNR1: 9.9577 ,SNR2: 17.633





0752-200 2024/06/29 4.25UT TOYOKAWA-FUJI

F20240629131313




BLK:21,SNR1: 5.2257 ,SNR2: 12.941







T20240629131311




BLK:19,SNR1: 10.225 ,SNR2: 18.112




K20240629131308




BLK:19,SNR1: 6.8579 ,SNR2: 13.463




0752-200 2024/06/29 4.25UT TOYOKAWA-KISO



F20240629131313




BLK:22,SNR1: 3.7541 ,SNR2: 9.3281





0752-200 2024/06/29 4.25UT FUJI -KISO



K20240629131308




BLK:22,SNR1: 3.7049 ,SNR2: 13.685





T20240629132046




BLK:19,SNR1: 0.18882 ,SNR2: 1.8478




F20240629132048





BLK:19,SNR1: 0.42567 ,SNR2: 2.1867




3C190 2024/06/29 4.37UT TOYOKAWA-FUJI





T20240629132046




BLK:17,SNR1: 0.11527 ,SNR2: 1.7880




K20240629132043





BLK:17,SNR1: 0.78774 ,SNR2: 2.3193




3C190 2024/06/29 4.37UT TOYOKAWA-KISO





F20240629132048




BLK:24,SNR1: 0.41104 ,SNR2: 2.2183




K20240629132043





BLK:24,SNR1: 0.55235 ,SNR2: 3.7487




3C190 2024/06/29 4.37UT FUJI -KISO





T20240629133310




BLK:24,SNR1: 0.38883 ,SNR2: 4.2032




F20240629133312





BLK:24,SNR1: 1.0442 ,SNR2: 7.7706




3C196 2024/06/29 4.58UT TOYOKAWA-FUJI





T20240629133310




BLK:21,SNR1: 0.40821 ,SNR2: 5.5773




K20240629133307




BLK:21,SNR1: 0.85494 ,SNR2: 3.5491




3C196 2024/06/29 4.58UT TOYOKAWA-KISO



F20240629133312





BLK:27,SNR1: 1.2284 ,SNR2: 5.8449





3C196 2024/06/29 4.58UT FUJI -KISO

K20240629133307





BLK:27,SNR1: 0.61316 ,SNR2: 2.5351







T20240629134420




BLK:14,SNR1: 0.24413 ,SNR2: 2.0293




F20240629134422





BLK:14,SNR1:-0.33984E-01,SNR2: 0.83864




0821+394 2024/06/29 4.77UT TOYOKAWA-FUJI





T20240629134420




BLK:26,SNR1: 0.21480 ,SNR2: 2.0211




K20240629134417




BLK:26,SNR1: 1.0280 ,SNR2: 4.8786




0821+394 2024/06/29 4.77UT TOYOKAWA-KISO





F20240629134422




BLK:19,SNR1: 0.53761E-01,SNR2: 1.1270




K20240629134417





BLK:19,SNR1: 0.99393 ,SNR2: 5.2509




0821+394 2024/06/29 4.77UT FUJI -KISO





T20240629135601




BLK:16,SNR1: 0.14081 ,SNR2: 1.5777




F20240629135603





BLK:16,SNR1: 0.26557 ,SNR2: 1.4296




0834-19 2024/06/29 4.96UT TOYOKAWA-FUJI





T20240629135601




BLK:20,SNR1: 0.12477 ,SNR2: 1.4925




K20240629135558





BLK:20,SNR1: 0.81260 ,SNR2: 4.5267




0834-19 2024/06/29 4.96UT TOYOKAWA-KISO





F20240629135603




BLK:14,SNR1: 0.40645 ,SNR2: 1.4442




K20240629135558





BLK:14,SNR1: 0.50702 ,SNR2: 4.4290




0834-19 2024/06/29 4.96UT FUJI -KISO





T20240629140106




BLK:31,SNR1: 2.7951 ,SNR2: 13.081




F20240629140108





BLK:31,SNR1: 7.8954 ,SNR2: 19.535




0839-071 2024/06/29 5.05UT TOYOKAWA-FUJI





T20240629140106




BLK:29,SNR1: 2.7333 ,SNR2: 12.841




K20240629140103



BLK:29,SNR1: 8.8876 ,SNR2: 21.707





0839-071 2024/06/29 5.05UT TOYOKAWA-KISO








F20240629140108




BLK:35,SNR1: 7.8599 ,SNR2: 19.445




K20240629140103





BLK:35,SNR1: 8.7401 ,SNR2: 21.338




0839-071 2024/06/29 5.05UT FUJI -KISO




T20240629141207




BLK:11,SNR1: 0.34595 ,SNR2: 1.5549




F20240629141209





BLK:11,SNR1: 0.53622E-01,SNR2: 1.7588




3C208 2024/06/29 5.23UT TOYOKAWA-FUJI




T20240629141207




BLK:18,SNR1: 1.3518 ,SNR2: 3.4572




K20240629141204





BLK:18,SNR1: 1.0996 ,SNR2: 4.4464




3C208 2024/06/29 5.23UT TOYOKAWA-KISO





F20240629141209




BLK:16,SNR1: 0.25869 ,SNR2: 1.7108




K20240629141204





BLK:16,SNR1: 0.90715 ,SNR2: 3.7446




3C208 2024/06/29 5.23UT FUJI -KISO




T20240629142848




BLK:29,SNR1: 0.20348 ,SNR2: 1.2010




F20240629142850







BLK:29,SNR1: 0.89283 ,SNR2: 6.3322




3C216 2024/06/29 5.51UT TOYOKAWA-FUJI








3C216 2024/06/29 5.51UT TOYOKAWA-KISO



F20240629142850





BLK:29,SNR1: 1.0682 ,SNR2: 5.9231




Frequency (Hz)

K20240629142845




BLK:29,SNR1: 1.7251 ,SNR2: 9.0688





Frequency (Hz)


3C216 2024/06/29 5.51UT FUJI -KISO





T20240629144100




BLK:23,SNR1: 0.45087 ,SNR2: 3.2280




F20240629144102



BLK:23,SNR1: 1.6170 ,SNR2: 5.2913





0919-142 2024/06/29 5.71UT TOYOKAWA-FUJI








T20240629144100




BLK:28,SNR1: 2.9054 ,SNR2: 7.0465




K20240629144057





BLK:28,SNR1: 1.5167 ,SNR2: 5.8015




0919-142 2024/06/29 5.71UT TOYOKAWA-KISO



F20240629144102





BLK:29,SNR1: 1.3498 ,SNR2: 6.4770




Frequency (Hz)

K20240629144057




BLK:29,SNR1: 3.4236 ,SNR2: 11.821





Frequency (Hz)


0919-142 2024/06/29 5.71UT FUJI -KISO





T20240629144739




BLK:28,SNR1: 2.0643 ,SNR2: 6.9674




F20240629144741





BLK:28,SNR1: 12.486 ,SNR2: 22.772




0926+117 2024/06/29 5.82UT TOYOKAWA-FUJI





T20240629144739




BLK:27,SNR1: 1.7479 ,SNR2: 6.0922




K20240629144736





BLK:27,SNR1: 2.3308 ,SNR2: 10.751




0926+117 2024/06/29 5.82UT TOYOKAWA-KISO



F20240629144741





BLK:30,SNR1: 10.224 ,SNR2: 18.490




Frequency (Hz)

K20240629144736




BLK:30,SNR1: 2.2996 ,SNR2: 10.572





Frequency (Hz)


0926+117 2024/06/29 5.82UT FUJI -KISO





T20240629145523




BLK:34,SNR1: 8.9834 ,SNR2: 22.492




F20240629145525





BLK:34,SNR1: 13.777 ,SNR2: 33.570




3C222 2024/06/29 5.95UT TOYOKAWA-FUJI





T20240629145523




BLK:34,SNR1: 8.9233 ,SNR2: 22.346




K20240629145520





BLK:34,SNR1: 13.147 ,SNR2: 32.082




3C222 2024/06/29 5.95UT TOYOKAWA-KISO




F20240629145525




BLK:34,SNR1: 9.5200 ,SNR2: 23.825




K20240629145520



BLK:34,SNR1: 12.733 ,SNR2: 31.100





3C222 2024/06/29 5.95UT FUJI -KISO








T20240629150223




BLK:19,SNR1: 1.7397 ,SNR2: 6.1255




F20240629150225




BLK:19,SNR1: 0.59679 ,SNR2: 2.4494




0941-08 2024/06/29 6.07UT TOYOKAWA-FUJI





T20240629150223




BLK:21,SNR1: 1.5573 ,SNR2: 5.3578




K20240629150220





BLK:21,SNR1: 0.36470 ,SNR2: 1.0278




0941-08 2024/06/29 6.07UT TOYOKAWA-KISO



F20240629150225





BLK:24,SNR1: 0.67768 ,SNR2: 1.9626




Frequency (Hz)

K20240629150220




BLK:24,SNR1: 0.67124 ,SNR2: 1.8843





Frequency (Hz)


0941-08 2024/06/29 6.07UT FUJI -KISO





T20240629151045




BLK:22,SNR1: 0.93319 ,SNR2: 4.2712




F20240629151047





BLK:22,SNR1: 5.2521 ,SNR2: 13.049




3C230 2024/06/29 6.21UT TOYOKAWA-FUJI





T20240629151045




BLK:20,SNR1: 0.85644 ,SNR2: 3.5789




K20240629151042





BLK:20,SNR1: 1.2315 ,SNR2: 4.3591




3C230 2024/06/29 6.21UT TOYOKAWA-KISO





F20240629151047




BLK:27,SNR1: 4.8110 ,SNR2: 12.118




K20240629151042





BLK:27,SNR1: 1.2512 ,SNR2: 4.4061




3C230 2024/06/29 6.21UT FUJI -KISO





T20240629152646




BLK:21,SNR1: 0.56759 ,SNR2: 4.2699




F20240629152648





BLK:21,SNR1: 0.95637 ,SNR2: 2.3317




3C237 2024/06/29 6.47UT TOYOKAWA-FUJI





T20240629152646




BLK:24,SNR1: 0.59564 ,SNR2: 4.4836




K20240629152643



BLK:24,SNR1: 0.67243 ,SNR2: 2.5833





3C237 2024/06/29 6.47UT TOYOKAWA-KISO








F20240629152648




BLK:27,SNR1: 1.6681 ,SNR2: 4.1656




K20240629152643





BLK:27,SNR1: 0.55163 ,SNR2: 2.4229




3C237 2024/06/29 6.47UT FUJI -KISO





T20240629153302




BLK:30,SNR1: 7.4307 ,SNR2: 18.575




F20240629153304




BLK:30,SNR1: 7.7382 ,SNR2: 19.479




1011+110 2024/06/29 6.58UT TOYOKAWA-FUJI




T20240629153302




BLK:25,SNR1: 7.7283 ,SNR2: 19.312




K20240629153259





BLK:25,SNR1: 9.1548 ,SNR2: 17.066




1011+110 2024/06/29 6.58UT TOYOKAWA-KISO





F20240629153304




BLK:31,SNR1: 7.1823 ,SNR2: 18.462




K20240629153259





BLK:31,SNR1: 12.715 ,SNR2: 22.543




1011+110 2024/06/29 6.58UT FUJI -KISO



T20240629154043





BLK:21,SNR1: 5.0550 ,SNR2: 12.829




Frequency (Hz)

F20240629154045




BLK:21,SNR1: 3.4217 ,SNR2: 11.352





Frequency (Hz)


3C241 2024/06/29 6.71UT TOYOKAWA-FUJI





T20240629154043




BLK:23,SNR1: 4.8739 ,SNR2: 12.211




K20240629154040




BLK:23,SNR1: 12.974 ,SNR2: 22.933




3C241 2024/06/29 6.71UT TOYOKAWA-KISO





F20240629154045




BLK:26,SNR1: 3.0118 ,SNR2: 10.134




K20240629154040





BLK:26,SNR1: 12.677 ,SNR2: 22.409




3C241 2024/06/29 6.71UT FUJI -KISO




T20240629155212




BLK: 6,SNR1: 0.88361E-01,SNR2: 1.3762




F20240629155214



BLK: 6,SNR1: 0.13958 ,SNR2: 2.0852





1031-11 2024/06/29 6.90UT TOYOKAWA-FUJI








T20240629155212




BLK: 1,SNR1: 0.36822 ,SNR2: 1.8028




K20240629155209




BLK: 1,SNR1: 5.6866 ,SNR2: 16.191




1031-11 2024/06/29 6.90UT TOYOKAWA-KISO




F20240629155214




BLK: 2,SNR1: 0.11658 ,SNR2: 0.78049




K20240629155209





BLK: 2,SNR1: 0.81492 ,SNR2: 2.5230




1031-11 2024/06/29 6.90UT FUJI -KISO




T20240629155646




BLK: 3,SNR1:-0.42577E-01,SNR2: 2.2320




F20240629155648





BLK: 3,SNR1: 0.68818 ,SNR2: 3.2192




1035-058 2024/06/29 6.97UT TOYOKAWA-FUJI



T20240629155646




BLK: 3,SNR1: 0.16729 ,SNR2: 1.4419




Frequency (Hz)

K20240629155643




BLK: 3,SNR1: 1.7460 ,SNR2: 10.195





Frequency (Hz)


1035-058 2024/06/29 6.97UT TOYOKAWA-KISO





F20240629155648




BLK: 4,SNR1: 0.93401E-01,SNR2: 0.99711




K20240629155643





BLK: 4,SNR1: 0.24238E-01,SNR2: 1.6224




1035-058 2024/06/29 6.97UT FUJI -KISO



T20240629160558





BLK:11,SNR1: 5.5229 ,SNR2: 13.499




Frequency (Hz)

F20240629160600




BLK:11,SNR1: 1.4298 ,SNR2: 4.9195





Frequency (Hz)


1044-008 2024/06/29 7.13UT TOYOKAWA-FUJI



T20240629160558





BLK:12,SNR1: 5.4251 ,SNR2: 13.123




Frequency (Hz)

K20240629160556




BLK:12,SNR1: 3.3521 ,SNR2: 11.734





Frequency (Hz)


1044-008 2024/06/29 7.13UT TOYOKAWA-KISO





F20240629160600




BLK:17,SNR1: 4.1648 ,SNR2: 11.499




K20240629160556



BLK:17,SNR1: 1.0891 ,SNR2: 4.2232





1044-008 2024/06/29 7.13UT FUJI -KISO






T20240629161703




BLK:10,SNR1: 1.6649 ,SNR2: 7.5450




Frequency (Hz)

F20240629161705




BLK:10,SNR1: 4.3075 ,SNR2: 10.475





Frequency (Hz)


1055+01 2024/06/29 7.31UT TOYOKAWA-FUJI



T20240629161703





BLK:15,SNR1: 1.1752 ,SNR2: 5.4132




Frequency (Hz)

K20240629161700




BLK:15,SNR1: 1.2765 ,SNR2: 4.8785




Frequency (Hz)


1055+01 2024/06/29 7.31UT TOYOKAWA-KISO



F20240629161705





BLK:21,SNR1: 4.1282 ,SNR2: 9.4081




Frequency (Hz)

K20240629161700




BLK:21,SNR1: 1.0599 ,SNR2: 4.2816





Frequency (Hz)


1055+01 2024/06/29 7.31UT FUJI -KISO



T20240629162821





BLK:16,SNR1: 0.79110 ,SNR2: 3.1450




Frequency (Hz)

F20240629162823




BLK:16,SNR1: 12.260 ,SNR2: 21.792





Frequency (Hz)


1107+109 2024/06/29 7.50UT TOYOKAWA-FUJI





T20240629162821




BLK: 7,SNR1: 1.2318 ,SNR2: 4.4876




K20240629162818





BLK: 7,SNR1: 1.9345 ,SNR2: 7.3405




1107+109 2024/06/29 7.50UT TOYOKAWA-KISO





F20240629162823




BLK:19,SNR1: 9.5625 ,SNR2: 17.313




K20240629162818





BLK:19,SNR1: 1.1180 ,SNR2: 4.3640




1107+109 2024/06/29 7.50UT FUJI -KISO



T20240629163758





BLK:20,SNR1: 0.47525 ,SNR2: 1.6494




Frequency (Hz)

F20240629163800




BLK:20,SNR1: 2.4126 ,SNR2: 5.4067





Frequency (Hz)


3C255 2024/06/29 7.66UT TOYOKAWA-FUJI



T20240629163758





BLK:19,SNR1: 0.39032 ,SNR2: 3.6347




Frequency (Hz)

K20240629163756




BLK:19,SNR1: 5.1558 ,SNR2: 8.0072





Frequency (Hz)

3C255 2024/06/29 7.66UT TOYOKAWA-KISO






F20240629163800





BLK:28,SNR1: 12.339 ,SNR2: 28.715




Frequency (Hz)

3C255 2024/06/29 7.66UT FUJI -KISO


K20240629163756





BLK:28,SNR1: 2.1661 ,SNR2: 7.9814




Frequency (Hz)



T20240629170156





BLK: 5,SNR1: 0.15611 ,SNR2: 0.78245




Frequency (Hz)

F20240629170158




BLK: 5,SNR1: 1.9756 ,SNR2: 7.1729





Frequency (Hz)


3C263.1 2024/06/29 8.06UT TOYOKAWA-FUJI



T20240629170156





BLK: 9,SNR1: 0.19125 ,SNR2: 1.0193




Frequency (Hz)

K20240629170154




BLK: 9,SNR1: 1.7710 ,SNR2: 7.9534





Frequency (Hz)


3C263.1 2024/06/29 8.06UT TOYOKAWA-KISO



F20240629170158





BLK:20,SNR1: 0.97798 ,SNR2: 4.1386




Frequency (Hz)

K20240629170154




BLK:20,SNR1: 1.2135 ,SNR2: 5.7478





Frequency (Hz)


3C263.1 2024/06/29 8.06UT FUJI -KISO



T20240629170823





BLK: 2,SNR1: 1.6236 ,SNR2: 16.332




Frequency (Hz)

F20240629170825




BLK: 2,SNR1:-0.64849E-02,SNR2: 1.1302





Frequency (Hz)


3C267 2024/06/29 8.17UT TOYOKAWA-FUJI



T20240629170823





BLK: 2,SNR1: 0.44464 ,SNR2: 4.3022




Frequency (Hz)

K20240629170821




BLK: 2,SNR1: 0.62155 ,SNR2: 5.7000





Frequency (Hz)


3C267 2024/06/29 8.17UT TOYOKAWA-KISO



F20240629170825





BLK: 4,SNR1: 0.60660 ,SNR2: 3.9956




Frequency (Hz)

K20240629170821




BLK: 4,SNR1: 0.92495 ,SNR2: 3.4712





Frequency (Hz)


3C267 2024/06/29 8.17UT FUJI -KISO



T20240629172737




BLK: 5,SNR1: 0.15091 ,SNR2: 0.37079




Frequency (Hz)

F20240629172739




BLK: 5,SNR1: 0.25279 ,SNR2: 1.5293





Frequency (Hz)

1206+439 2024/06/29 8.49UT TOYOKAWA-FUJI






T20240629172737





BLK: 2,SNR1: 0.94367E-01,SNR2: 0.47298




Frequency (Hz)

K20240629172735




BLK: 2,SNR1: 7.1848 ,SNR2: 28.227




Frequency (Hz)


1206+439 2024/06/29 8.49UT TOYOKAWA-KISO



F20240629172739




BLK: 9,SNR1: 0.49925 ,SNR2: 1.3563




Frequency (Hz)

K20240629172735



BLK: 9,SNR1: 1.6577 ,SNR2: 7.0595



Frequency (Hz)

1206+439 2024/06/29 8.49UT FUJI -KISO

