




T20240702054929





BLK:10,SNR1: 0.35562 ,SNR2: 2.1298




Frequency (Hz)

F20240702054931




BLK:10,SNR1: 0.19679 ,SNR2: 1.0778





Frequency (Hz)


0038+328 2024/07/01 20.85UT TOYOKAWA-FUJI



T20240702054929





BLK:10,SNR1: 0.29026 ,SNR2: 2.3402




Frequency (Hz)

K20240702054926




BLK:10,SNR1: 0.53470 ,SNR2: 2.7991





Frequency (Hz)

0038+328 2024/07/01 20.85UT TOYOKAWA-KISO






F20240702054931





BLK:10,SNR1: 0.29740 ,SNR2: 2.2452




Frequency (Hz)

K20240702054926




BLK:10,SNR1: 0.52053 ,SNR2: 2.6199




Frequency (Hz)


0038+328 2024/07/01 20.85UT FUJI -KISO



T20240702060422





BLK:12,SNR1: 2.2964 ,SNR2: 5.8807




Frequency (Hz)

F20240702060424




BLK:12,SNR1: 2.1505 ,SNR2: 9.6217




Frequency (Hz)


0053+261 2024/07/01 21.10UT TOYOKAWA-FUJI



T20240702060422





BLK:18,SNR1: 2.7034 ,SNR2: 6.9567




Frequency (Hz)

K20240702060419




BLK:18,SNR1: 6.7460 ,SNR2: 19.023





Frequency (Hz)


0053+261 2024/07/01 21.10UT TOYOKAWA-KISO



F20240702060424





BLK:24,SNR1: 3.3523 ,SNR2: 8.2199




Frequency (Hz)

K20240702060419




BLK:24,SNR1: 5.7338 ,SNR2: 13.206




Frequency (Hz)


0053+261 2024/07/01 21.10UT FUJI -KISO



T20240702062054





BLK: 1,SNR1: 0.15831 ,SNR2: 2.8195




Frequency (Hz)

F20240702062056




BLK: 1,SNR1:-0.25771 ,SNR2: 0.71543





Frequency (Hz)


0109+416 2024/07/01 21.38UT TOYOKAWA-FUJI



T20240702062054





BLK: 1,SNR1: 0.48214 ,SNR2: 1.7727




Frequency (Hz)

K20240702062051




BLK: 1,SNR1:-0.71138E-02,SNR2: 0.44320E-01




Frequency (Hz)

0109+416 2024/07/01 21.38UT TOYOKAWA-KISO




F20240702062056



Time (sec)




BLK: 6,SNR1: 0.43794 ,SNR2: 2.1376




Frequency (Hz)


K20240702062051



Time (sec)




BLK: 6,SNR1: 0.24860 ,SNR2: 0.69346





Frequency (Hz)


0109+416 2024/07/01 21.38UT FUJI -KISO



T20240702063159





BLK: 6,SNR1: 0.19938 ,SNR2: 0.59541




Frequency (Hz)

F20240702063201




BLK: 6,SNR1: 0.70235 ,SNR2: 2.7838




Frequency (Hz)

0120+405 2024/07/01 21.56UT TOYOKAWA-FUJI






T20240702063159





BLK: 1,SNR1: 0.67510 ,SNR2: 1.4552




Frequency (Hz)

K20240702063156




BLK: 1,SNR1: 0.27656 ,SNR2: 2.6734





Frequency (Hz)


0120+405 2024/07/01 21.56UT TOYOKAWA-KISO



F20240702063201





BLK: 3,SNR1: 0.64176 ,SNR2: 5.4334




Frequency (Hz)

K20240702063156




BLK: 3,SNR1: 0.85528E-01,SNR2: 1.1540





Frequency (Hz)


0120+405 2024/07/01 21.56UT FUJI -KISO



T20240702063937




BLK: 8,SNR1: 0.40547E-01,SNR2: 0.77564




Frequency (Hz)

F20240702063939




BLK: 8,SNR1: 1.3060 ,SNR2: 5.5662





Frequency (Hz)


0128+03 2024/07/01 21.69UT TOYOKAWA-FUJI



T20240702063937




BLK: 6,SNR1:-0.81280E-01,SNR2: 0.46047




Frequency (Hz)

K20240702063934




BLK: 6,SNR1: 1.2947 ,SNR2: 5.3481




Frequency (Hz)


0128+03 2024/07/01 21.69UT TOYOKAWA-KISO



F20240702063939





BLK:12,SNR1: 2.0673 ,SNR2: 9.5207




Frequency (Hz)

K20240702063934




BLK:12,SNR1: 1.5712 ,SNR2: 3.0987





Frequency (Hz)


0128+03 2024/07/01 21.69UT FUJI -KISO



T20240702064611




BLK:19,SNR1: 1.0142 ,SNR2: 7.3224




Frequency (Hz)

3C48 2024/07/01 21.80UT TOYOKAWA-FUJI


F20240702064613





BLK:19,SNR1: 1.2667 ,SNR2: 3.4561




Frequency (Hz)



T20240702064611





BLK:30,SNR1: 0.93938 ,SNR2: 3.1450




Frequency (Hz)

3C48 2024/07/01 21.80UT TOYOKAWA-KISO


K20240702064608





BLK:30,SNR1: 0.59625 ,SNR2: 2.4465




Frequency (Hz)



F20240702064613





BLK:16,SNR1: 1.2460 ,SNR2: 3.8639




Frequency (Hz)

3C48 2024/07/01 21.80UT FUJI -KISO


K20240702064608



BLK:16,SNR1: 0.78678 ,SNR2: 2.8393





Frequency (Hz)






T20240702070556





BLK: 2,SNR1:-0.62840E-01,SNR2: 0.26002




Frequency (Hz)

F20240702070558




BLK: 2,SNR1: 2.5390 ,SNR2: 9.7729





Frequency (Hz)


0155-109 2024/07/01 22.13UT TOYOKAWA-FUJI



T20240702070556





BLK: 1,SNR1: 0.58304E-01,SNR2: 1.0210




Frequency (Hz)

K20240702070553




BLK: 1,SNR1: 0.20260 ,SNR2: 0.84834





Frequency (Hz)


0155-109 2024/07/01 22.13UT TOYOKAWA-KISO



F20240702070558




BLK: 1,SNR1: 0.21622E-01,SNR2: 1.9227




Frequency (Hz)

K20240702070553




BLK: 1,SNR1: 0.14309 ,SNR2: 0.98618





Frequency (Hz)


0155-109 2024/07/01 22.13UT FUJI -KISO



T20240702071303





BLK: 1,SNR1: 0.10810 ,SNR2: 0.27032




Frequency (Hz)

F20240702071305




BLK: 1,SNR1: 1.0068 ,SNR2: 6.8049





Frequency (Hz)


0202+15 2024/07/01 22.25UT TOYOKAWA-FUJI




T20240702071303




BLK: 5,SNR1:-0.64053E-01,SNR2: 0.88877




K20240702071300





BLK: 5,SNR1: 2.2691 ,SNR2: 6.8555




0202+15 2024/07/01 22.25UT TOYOKAWA-KISO



F20240702071305




BLK:12,SNR1: 3.1375 ,SNR2: 13.571




Frequency (Hz)

0202+15 2024/07/01 22.25UT FUJI -KISO


K20240702071300





BLK:12,SNR1: 3.6886 ,SNR2: 15.571




Frequency (Hz)



T20240702072453




BLK: 2,SNR1:-0.66031E-01,SNR2: 0.75675




Frequency (Hz)

F20240702072455




BLK: 2,SNR1: 2.7850 ,SNR2: 9.7068





Frequency (Hz)


0213+178 2024/07/01 22.44UT TOYOKAWA-FUJI





T20240702072453




BLK: 2,SNR1: 0.14308 ,SNR2: 1.6292




K20240702072451



BLK: 2,SNR1: 1.6733 ,SNR2: 9.3816




0213+178 2024/07/01 22.44UT TOYOKAWA-KISO






F20240702072455




BLK: 7,SNR1: 0.80843 ,SNR2: 3.2021




Frequency (Hz)

K20240702072451




BLK: 7,SNR1: 0.69922 ,SNR2: 2.5569





Frequency (Hz)


0213+178 2024/07/01 22.44UT FUJI -KISO



T20240702073235



BLK: 4,SNR1: 0.30171 ,SNR2: 3.7796




Frequency (Hz)


3C67

2024/07/01 22.57UT TOYOKAWA-FUJI


F20240702073237




BLK: 4,SNR1: 0.43108 ,SNR2: 3.6748




Frequency (Hz)



T20240702073235



BLK: 2,SNR1: 0.99013E-01,SNR2: 5.2890




Frequency (Hz)


3C67

2024/07/01 22.57UT TOYOKAWA-KISO


K20240702073233




BLK: 2,SNR1: 0.54897 ,SNR2: 7.4757




Frequency (Hz)



F20240702073237



BLK:11,SNR1: 0.35376E-01,SNR2: 1.0634




Frequency (Hz)


3C67

2024/07/01 22.57UT FUJI -KISO


K20240702073233





BLK:11,SNR1: 0.69931 ,SNR2: 2.8540




Frequency (Hz)



T20240702075051




BLK: 3,SNR1:-0.70686E-01,SNR2: 0.29908





3C71 2024/07/01 22.88UT TOYOKAWA-FUJI



F20240702075053




BLK: 3,SNR1: 0.88993 ,SNR2: 6.0412



T20240702075051



BLK: 1,SNR1: 0.13596 ,SNR2: 0.0000





Frequency (Hz)


3C71

2024/07/01 22.88UT TOYOKAWA-KISO


K20240702075048




BLK: 1,SNR1: 1.8876 ,SNR2: 7.4703




Frequency (Hz)



F20240702075053





BLK: 2,SNR1:-0.17056 ,SNR2: 0.43517




Frequency (Hz)

3C71 2024/07/01 22.88UT FUJI -KISO


K20240702075048





BLK: 2,SNR1: 0.62393 ,SNR2: 6.6970




Frequency (Hz)



T20240702081005





BLK: 8,SNR1: 0.29658 ,SNR2: 3.5221





0258+350 2024/07/01 23.20UT TOYOKAWA-FUJI

F20240702081007





BLK: 8,SNR1: 5.5668 ,SNR2: 14.065






T20240702081005





BLK:10,SNR1: 0.20194 ,SNR2: 2.9145





0258+350 2024/07/01 23.20UT TOYOKAWA-KISO



K20240702081002




BLK:10,SNR1: 1.0249 ,SNR2: 4.4260





F20240702081007




BLK:17,SNR1: 3.1751 ,SNR2: 8.2823




K20240702081002





BLK:17,SNR1: 0.54730 ,SNR2: 2.5584




0258+350 2024/07/01 23.20UT FUJI -KISO



T20240702081955





BLK: 7,SNR1: 0.10925 ,SNR2: 0.89899




Frequency (Hz)

F20240702081957




BLK: 7,SNR1: 1.3808 ,SNR2: 3.7249





Frequency (Hz)


0308+305 2024/07/01 23.36UT TOYOKAWA-FUJI



T20240702081955





BLK: 7,SNR1: 0.11484 ,SNR2: 0.55236




Frequency (Hz)

K20240702081953




BLK: 7,SNR1: 1.1692 ,SNR2: 5.2676





Frequency (Hz)


0308+305 2024/07/01 23.36UT TOYOKAWA-KISO



F20240702081957





BLK:16,SNR1: 3.3123 ,SNR2: 8.7019




Frequency (Hz)

K20240702081953




BLK:16,SNR1: 1.3022 ,SNR2: 5.9955




Frequency (Hz)


0308+305 2024/07/01 23.36UT FUJI -KISO



T20240702083126




BLK: 6,SNR1: 0.14273 ,SNR2: 2.3606





0320+05 2024/07/01 23.55UT TOYOKAWA-FUJI



F20240702083128




BLK: 6,SNR1: 0.36646 ,SNR2: 2.8403





T20240702083126




BLK: 7,SNR1: 0.12953 ,SNR2: 1.2144




K20240702083124





BLK: 7,SNR1: 1.4570 ,SNR2: 9.5627




0320+05 2024/07/01 23.55UT TOYOKAWA-KISO



F20240702083128





BLK:11,SNR1: 0.32780 ,SNR2: 1.5863




Frequency (Hz)

K20240702083124




BLK:11,SNR1: 0.47663 ,SNR2: 2.0369





Frequency (Hz)

0320+05 2024/07/01 23.55UT FUJI -KISO






T20240702084447





BLK: 4,SNR1: 0.94797E-01,SNR2: 0.63029




Frequency (Hz)

F20240702084449




BLK: 4,SNR1: 3.7582 ,SNR2: 10.937





Frequency (Hz)


0333+32 2024/07/01 23.77UT TOYOKAWA-FUJI



T20240702084447





BLK:18,SNR1: 0.19280 ,SNR2: 1.1636




Frequency (Hz)

K20240702084445




BLK:18,SNR1: 6.2332 ,SNR2: 11.742




Frequency (Hz)


0333+32 2024/07/01 23.77UT TOYOKAWA-KISO



F20240702084449





BLK:12,SNR1: 1.8703 ,SNR2: 4.5702




Frequency (Hz)

K20240702084445




BLK:12,SNR1: 8.4884 ,SNR2: 16.361




Frequency (Hz)


0333+32 2024/07/01 23.77UT FUJI -KISO




T20240702085312




BLK: 8,SNR1: 0.49609E-01,SNR2: 0.94195




F20240702085314





BLK: 8,SNR1: 0.15663 ,SNR2: 0.62333




0342-111 2024/07/01 23.91UT TOYOKAWA-FUJI



T20240702085312





BLK: 7,SNR1: 0.91639E-01,SNR2: 0.40992




Frequency (Hz)

K20240702085310




BLK: 7,SNR1: 2.3090 ,SNR2: 10.337




Frequency (Hz)


0342-111 2024/07/01 23.91UT TOYOKAWA-KISO



F20240702085314





BLK:10,SNR1: 0.54455 ,SNR2: 2.4156




Frequency (Hz)

K20240702085310




BLK:10,SNR1: 1.7910 ,SNR2: 8.0999





Frequency (Hz)


0342-111 2024/07/01 23.91UT FUJI -KISO



T20240702091324





BLK: 4,SNR1: 0.26217 ,SNR2: 2.1651




Frequency (Hz)

F20240702091326




BLK: 4,SNR1: 0.22652 ,SNR2: 2.6679




Frequency (Hz)


0403-132 2024/07/02 0.25UT TOYOKAWA-FUJI





T20240702091324




BLK: 5,SNR1: 0.15973E-01,SNR2: 0.61092




K20240702091321



BLK: 5,SNR1: 0.79333 ,SNR2: 4.0018





0403-132 2024/07/02 0.25UT TOYOKAWA-KISO








F20240702091326




BLK: 8,SNR1: 0.19408 ,SNR2: 2.5147




K20240702091321





BLK: 8,SNR1: 0.65820 ,SNR2: 2.1967




0403-132 2024/07/02 0.25UT FUJI -KISO





T20240702092234




BLK: 6,SNR1: 0.12937 ,SNR2: 1.3556




F20240702092236





BLK: 6,SNR1: 1.1473 ,SNR2: 9.2399




0411+05 2024/07/02 0.40UT TOYOKAWA-FUJI



T20240702092234





BLK: 5,SNR1: 0.93285E-01,SNR2: 0.55273





0411+05 2024/07/02 0.40UT TOYOKAWA-KISO


K20240702092231




BLK: 5,SNR1: 0.41584 ,SNR2: 2.0017




F20240702092236




BLK: 3,SNR1: 1.1136 ,SNR2: 8.0956




K20240702092231





BLK: 3,SNR1: 0.25576 ,SNR2: 0.64944




0411+05 2024/07/02 0.40UT FUJI -KISO



T20240702092928





BLK: 7,SNR1: 4.0305 ,SNR2: 16.876





0418+236 2024/07/02 0.52UT TOYOKAWA-FUJI



F20240702092930




BLK: 7,SNR1: 1.1079 ,SNR2: 5.7512



T20240702092928





BLK:15,SNR1: 4.0635 ,SNR2: 17.001




Frequency (Hz)

K20240702092925




BLK:15,SNR1: 4.0797 ,SNR2: 17.129




Frequency (Hz)


0418+236 2024/07/02 0.52UT TOYOKAWA-KISO





F20240702092930




BLK:21,SNR1: 1.1167 ,SNR2: 5.6623




K20240702092925




BLK:21,SNR1: 4.0522 ,SNR2: 17.020




0418+236 2024/07/02 0.52UT FUJI -KISO





T20240702094056




BLK:19,SNR1: 0.94901 ,SNR2: 11.252




F20240702094058



BLK:19,SNR1: 0.35358 ,SNR2: 1.4475





3C119 2024/07/02 0.71UT TOYOKAWA-FUJI






T20240702094056




BLK:26,SNR1: 0.87120 ,SNR2: 4.9353





3C119 2024/07/02 0.71UT TOYOKAWA-KISO



K20240702094053




BLK:26,SNR1: 0.51728 ,SNR2: 2.6573





F20240702094058




BLK:13,SNR1: 0.27839 ,SNR2: 1.7153




K20240702094053





BLK:13,SNR1: 0.78122 ,SNR2: 4.8014




3C119 2024/07/02 0.71UT FUJI -KISO



T20240702102903





BLK:38,SNR1: 7.0466 ,SNR2: 43.428




Frequency (Hz)

3C138 2024/07/02 1.51UT TOYOKAWA-FUJI


F20240702102905





BLK:38,SNR1: 0.21641 ,SNR2: 3.0640




Frequency (Hz)



T20240702102903





BLK:33,SNR1: 8.3264 ,SNR2: 28.592





3C138 2024/07/02 1.51UT TOYOKAWA-KISO



K20240702102900




BLK:33,SNR1: 1.4869 ,SNR2: 5.0724





F20240702102905




BLK:27,SNR1: 0.24561 ,SNR2: 3.4248




K20240702102900




BLK:27,SNR1: 1.7471 ,SNR2: 6.4498




3C138 2024/07/02 1.51UT FUJI -KISO



T20240702104236




BLK:22,SNR1: 4.4929 ,SNR2: 20.742





0531+194 2024/07/02 1.74UT TOYOKAWA-FUJI



F20240702104238




BLK:22,SNR1: 0.15928 ,SNR2: 2.4108



T20240702104236





BLK:33,SNR1: 3.6343 ,SNR2: 14.848





0531+194 2024/07/02 1.74UT TOYOKAWA-KISO


K20240702104233




BLK:33,SNR1: 1.0978 ,SNR2: 4.6958




F20240702104238




BLK:26,SNR1: 0.14379 ,SNR2: 2.3561




K20240702104233



BLK:26,SNR1: 0.97854 ,SNR2: 3.9991





0531+194 2024/07/02 1.74UT FUJI -KISO






T20240702105056





BLK:27,SNR1: 15.638 ,SNR2: 27.444




Frequency (Hz)

3C147 2024/07/02 1.88UT TOYOKAWA-FUJI


F20240702105058




BLK:27,SNR1: 0.50473 ,SNR2: 4.5439




Frequency (Hz)



T20240702105056




BLK:29,SNR1: 15.348 ,SNR2: 26.946





3C147 2024/07/02 1.88UT TOYOKAWA-KISO


K20240702105053




BLK:29,SNR1: 1.5934 ,SNR2: 6.6707




F20240702105058




BLK:28,SNR1: 0.69847 ,SNR2: 5.5141




K20240702105053




BLK:28,SNR1: 1.5171 ,SNR2: 9.4823




3C147 2024/07/02 1.88UT FUJI -KISO



T20240702105907





BLK:17,SNR1: 0.72290 ,SNR2: 3.2040





0548+16 2024/07/02 2.01UT TOYOKAWA-FUJI


F20240702105909




BLK:17,SNR1: 3.8355 ,SNR2: 9.4669



T20240702105907




BLK:22,SNR1: 1.2706 ,SNR2: 2.4075





0548+16 2024/07/02 2.01UT TOYOKAWA-KISO


K20240702105904




BLK:22,SNR1: 5.0909 ,SNR2: 14.098



F20240702105909




BLK:22,SNR1: 3.3120 ,SNR2: 8.1895





0548+16 2024/07/02 2.01UT FUJI -KISO


K20240702105904




BLK:22,SNR1: 5.4642 ,SNR2: 14.945



T20240702110318





BLK:15,SNR1: 4.2440 ,SNR2: 15.766




Frequency (Hz)

0552+12 2024/07/02 2.08UT TOYOKAWA-FUJI


F20240702110320





BLK:15,SNR1: 0.24608 ,SNR2: 0.87830




Frequency (Hz)



T20240702110318




BLK:17,SNR1: 4.0089 ,SNR2: 13.530





0552+12 2024/07/02 2.08UT TOYOKAWA-KISO

K20240702110315




BLK:17,SNR1: 0.50526 ,SNR2: 4.1339






F20240702110320




BLK: 5,SNR1: 0.19962 ,SNR2: 2.4744





0552+12 2024/07/02 2.08UT FUJI -KISO


K20240702110315




BLK: 5,SNR1: 1.9170 ,SNR2: 13.052



T20240702110745




BLK:11,SNR1: 0.53477 ,SNR2: 3.9884





0556+191 2024/07/02 2.16UT TOYOKAWA-FUJI


F20240702110747




BLK:11,SNR1: 1.3525 ,SNR2: 6.5821



T20240702110745




BLK:14,SNR1: 6.4616 ,SNR2: 15.641





0556+191 2024/07/02 2.16UT TOYOKAWA-KISO



K20240702110742




BLK:14,SNR1: 7.7708 ,SNR2: 19.458





F20240702110747




BLK:14,SNR1: 2.8653 ,SNR2: 6.9966




K20240702110742




BLK:14,SNR1: 5.2045 ,SNR2: 15.093




0556+191 2024/07/02 2.16UT FUJI -KISO



T20240702111531




BLK: 5,SNR1: 0.38885 ,SNR2: 2.4809





0605-08 2024/07/02 2.29UT TOYOKAWA-FUJI



F20240702111533




BLK: 5,SNR1: 0.45399E-01,SNR2: 0.68664



T20240702111531





BLK: 4,SNR1: 0.43445 ,SNR2: 1.8596




Frequency (Hz)

K20240702111528




BLK: 4,SNR1: 0.37700 ,SNR2: 1.7011





Frequency (Hz)


0605-08 2024/07/02 2.29UT TOYOKAWA-KISO





F20240702111533




BLK: 3,SNR1: 0.31020 ,SNR2: 4.8362




K20240702111528




BLK: 3,SNR1: 0.35023 ,SNR2: 1.7413




0605-08 2024/07/02 2.29UT FUJI -KISO



T20240702113439




BLK:26,SNR1: 2.4551 ,SNR2: 6.2900




3C161 2024/07/02 2.61UT TOYOKAWA-FUJI


F20240702113441







BLK:26,SNR1: 3.4153 ,SNR2: 7.9807




Frequency (Hz)









3C161 2024/07/02 2.61UT TOYOKAWA-KISO




F20240702113441




BLK:27,SNR1: 3.7445 ,SNR2: 8.5719




K20240702113436





BLK:27,SNR1: 2.7620 ,SNR2: 5.4685




3C161 2024/07/02 2.61UT FUJI -KISO



T20240702120212




BLK:11,SNR1: 24.828 ,SNR2: 36.039




0652-130 2024/07/02 3.06UT TOYOKAWA-FUJI


F20240702120214





BLK:11,SNR1: 1.4368 ,SNR2: 2.5279




Frequency (Hz)





T20240702120212




BLK: 9,SNR1: 29.092 ,SNR2: 42.504




K20240702120209




BLK: 9,SNR1: 4.1245 ,SNR2: 15.741




0652-130 2024/07/02 3.06UT TOYOKAWA-KISO




F20240702120214




BLK:14,SNR1: 1.2174 ,SNR2: 3.5063




K20240702120209




BLK:14,SNR1: 3.8265 ,SNR2: 13.949




0652-130 2024/07/02 3.06UT FUJI -KISO



T20240702121348




BLK:10,SNR1: 0.71390 ,SNR2: 2.4713




Frequency (Hz)

F20240702121350




BLK:10,SNR1: 1.0161 ,SNR2: 2.8318





Frequency (Hz)


0703+138 2024/07/02 3.26UT TOYOKAWA-FUJI





T20240702121348




BLK:12,SNR1: 0.69432 ,SNR2: 1.7223




K20240702121345





BLK:12,SNR1: 0.62759 ,SNR2: 3.0614




0703+138 2024/07/02 3.26UT TOYOKAWA-KISO



F20240702121350





BLK:17,SNR1: 0.77280 ,SNR2: 2.0964




Frequency (Hz)

K20240702121345




BLK:17,SNR1: 0.47282 ,SNR2: 2.1311





Frequency (Hz)

0703+138 2024/07/02 3.26UT FUJI -KISO






T20240702122311





BLK: 8,SNR1: 0.21929 ,SNR2: 1.7340




Frequency (Hz)

F20240702122313




BLK: 8,SNR1: 0.84651 ,SNR2: 2.7880





Frequency (Hz)


0713-024 2024/07/02 3.41UT TOYOKAWA-FUJI





T20240702122311




BLK:13,SNR1: 0.21875 ,SNR2: 3.5957




K20240702122308




BLK:13,SNR1: 0.22451 ,SNR2: 2.0621




0713-024 2024/07/02 3.41UT TOYOKAWA-KISO



F20240702122313





BLK: 7,SNR1: 0.59502 ,SNR2: 1.9158





0713-024 2024/07/02 3.41UT FUJI -KISO


K20240702122308




BLK: 7,SNR1: 0.15222 ,SNR2: 0.90710





T20240702123323




BLK: 7,SNR1: 0.78102 ,SNR2: 7.7342




F20240702123325





BLK: 7,SNR1: 0.26936 ,SNR2: 2.0689




0723+10 2024/07/02 3.58UT TOYOKAWA-FUJI



T20240702123323





BLK:11,SNR1: 0.60871 ,SNR2: 2.6645





0723+10 2024/07/02 3.58UT TOYOKAWA-KISO


K20240702123320




BLK:11,SNR1: 44.505 ,SNR2: 71.859





F20240702123325




BLK: 9,SNR1: 0.17517 ,SNR2: 1.0600




K20240702123320





BLK: 9,SNR1: 30.470 ,SNR2: 70.711




0723+10 2024/07/02 3.58UT FUJI -KISO




T20240702124337




BLK:23,SNR1: 1.2929 ,SNR2: 2.5145




F20240702124339





BLK:23,SNR1: 0.16607 ,SNR2: 1.3993




0732+33 2024/07/02 3.76UT TOYOKAWA-FUJI



T20240702124337




BLK:22,SNR1: 1.0720 ,SNR2: 3.6121





0732+33 2024/07/02 3.76UT TOYOKAWA-KISO

K20240702124334




BLK:22,SNR1: 0.50800 ,SNR2: 2.1198








F20240702124339




BLK:19,SNR1: 0.63599E-02,SNR2: 2.0576




K20240702124334




BLK:19,SNR1: 0.78304 ,SNR2: 3.3041




0732+33 2024/07/02 3.76UT FUJI -KISO





T20240702125139




BLK:28,SNR1: 6.3760 ,SNR2: 15.283




F20240702125141




BLK:28,SNR1: 2.5864 ,SNR2: 11.755




0741-06 2024/07/02 3.89UT TOYOKAWA-FUJI





T20240702125139




BLK:32,SNR1: 6.3805 ,SNR2: 15.311




K20240702125136





BLK:32,SNR1: 7.1004 ,SNR2: 17.443




0741-06 2024/07/02 3.89UT TOYOKAWA-KISO




F20240702125141




BLK:29,SNR1: 9.0898 ,SNR2: 21.387




K20240702125136





BLK:29,SNR1: 8.6222 ,SNR2: 20.915




0741-06 2024/07/02 3.89UT FUJI -KISO



T20240702130124





BLK:14,SNR1: 3.3160 ,SNR2: 8.3627





0752-200 2024/07/02 4.05UT TOYOKAWA-FUJI



F20240702130126




BLK:14,SNR1: 2.8143 ,SNR2: 12.629





T20240702130124




BLK:13,SNR1: 3.3924 ,SNR2: 8.5276




K20240702130121







BLK:13,SNR1: 2.6067 ,SNR2: 12.584




0752-200 2024/07/02 4.05UT TOYOKAWA-KISO







0752-200 2024/07/02 4.05UT FUJI -KISO





T20240702130858




BLK:18,SNR1: 0.51623 ,SNR2: 3.8021




F20240702130900



BLK:18,SNR1: 0.36223 ,SNR2: 1.6448





3C190 2024/07/02 4.18UT TOYOKAWA-FUJI








T20240702130858




BLK:18,SNR1: 0.43544 ,SNR2: 3.3178




K20240702130855





BLK:18,SNR1: 0.60239 ,SNR2: 5.0094




3C190 2024/07/02 4.18UT TOYOKAWA-KISO





F20240702130900




BLK:13,SNR1: 0.28035 ,SNR2: 1.3166




K20240702130855





BLK:13,SNR1: 0.63166 ,SNR2: 4.7615




3C190 2024/07/02 4.18UT FUJI -KISO




T20240702132123




BLK:19,SNR1: 1.4614 ,SNR2: 6.7286




F20240702132125





BLK:19,SNR1: 3.1973 ,SNR2: 7.1312




3C196 2024/07/02 4.38UT TOYOKAWA-FUJI



T20240702132123




BLK:25,SNR1: 2.5959 ,SNR2: 5.9204





3C196 2024/07/02 4.38UT TOYOKAWA-KISO


K20240702132120




BLK:25,SNR1: 1.0763 ,SNR2: 4.1952



F20240702132125





BLK:14,SNR1: 3.5556 ,SNR2: 7.7970





3C196 2024/07/02 4.38UT FUJI -KISO



K20240702132120




BLK:14,SNR1: 1.2128 ,SNR2: 5.6739




T20240702133233




BLK:17,SNR1: 2.2056 ,SNR2: 5.4878




F20240702133235





BLK:17,SNR1: 0.51701 ,SNR2: 3.2301




0821+394 2024/07/02 4.57UT TOYOKAWA-FUJI





T20240702133233




BLK:16,SNR1: 1.7857 ,SNR2: 6.2402




K20240702133230




BLK:16,SNR1: 3.6972 ,SNR2: 13.085




0821+394 2024/07/02 4.57UT TOYOKAWA-KISO




F20240702133235




BLK:19,SNR1: 0.58475 ,SNR2: 5.0415




K20240702133230



BLK:19,SNR1: 3.4695 ,SNR2: 12.265




0821+394 2024/07/02 4.57UT FUJI -KISO








T20240702134413




BLK:23,SNR1: 8.3065 ,SNR2: 20.831




F20240702134415




BLK:23,SNR1: 8.6559 ,SNR2: 20.351




0834-19 2024/07/02 4.77UT TOYOKAWA-FUJI





T20240702134413




BLK:26,SNR1: 8.0794 ,SNR2: 20.273




K20240702134410





BLK:26,SNR1: 8.5761 ,SNR2: 21.678




0834-19 2024/07/02 4.77UT TOYOKAWA-KISO





F20240702134415




BLK:28,SNR1: 8.4327 ,SNR2: 20.046




K20240702134410





BLK:28,SNR1: 8.4002 ,SNR2: 22.248




0834-19 2024/07/02 4.77UT FUJI -KISO





T20240702134918




BLK:24,SNR1: 3.7470 ,SNR2: 9.3735




F20240702134920





BLK:24,SNR1: 2.8776 ,SNR2: 13.349




0839-071 2024/07/02 4.85UT TOYOKAWA-FUJI




T20240702134918




BLK:22,SNR1: 2.8675 ,SNR2: 7.2434




K20240702134915





BLK:22,SNR1: 5.2478 ,SNR2: 13.080




0839-071 2024/07/02 4.85UT TOYOKAWA-KISO




F20240702134920




BLK:25,SNR1: 8.7683 ,SNR2: 21.917




K20240702134915





BLK:25,SNR1: 5.7969 ,SNR2: 14.868




0839-071 2024/07/02 4.85UT FUJI -KISO





T20240702140019




BLK:28,SNR1: 13.984 ,SNR2: 25.546




F20240702140021





BLK:28,SNR1: 14.063 ,SNR2: 25.968




3C208 2024/07/02 5.03UT TOYOKAWA-FUJI





T20240702140019




BLK:27,SNR1: 14.125 ,SNR2: 25.809




K20240702140016



BLK:27,SNR1: 16.250 ,SNR2: 30.837





3C208 2024/07/02 5.03UT TOYOKAWA-KISO






F20240702140021





BLK:35,SNR1: 13.062 ,SNR2: 24.123





3C208 2024/07/02 5.03UT FUJI -KISO



K20240702140016




BLK:35,SNR1: 15.850 ,SNR2: 30.083




T20240702141700




BLK: 4,SNR1: 0.90901 ,SNR2: 1.7581




F20240702141702





BLK: 4,SNR1:-0.11643 ,SNR2: 1.0141




3C216 2024/07/02 5.31UT TOYOKAWA-FUJI





T20240702141700




BLK: 8,SNR1: 0.38939 ,SNR2: 1.5679




K20240702141657




BLK: 8,SNR1: 1.5653 ,SNR2: 6.5543




3C216 2024/07/02 5.31UT TOYOKAWA-KISO




F20240702141702




BLK: 8,SNR1: 0.31311 ,SNR2: 1.1172




K20240702141657





BLK: 8,SNR1: 0.13302 ,SNR2: 0.51950




3C216 2024/07/02 5.31UT FUJI -KISO




T20240702142912




BLK:10,SNR1: 10.523 ,SNR2: 20.478




F20240702142914





BLK:10,SNR1: 0.40126 ,SNR2: 2.7021




0919-142 2024/07/02 5.51UT TOYOKAWA-FUJI





T20240702142912




BLK: 9,SNR1: 10.646 ,SNR2: 20.715




K20240702142909




BLK: 9,SNR1: 1.4230 ,SNR2: 5.5401




0919-142 2024/07/02 5.51UT TOYOKAWA-KISO





F20240702142914




BLK:15,SNR1: 0.95826 ,SNR2: 3.1284




K20240702142909




BLK:15,SNR1: 9.2410 ,SNR2: 33.230




0919-142 2024/07/02 5.51UT FUJI -KISO





T20240702143551




BLK:14,SNR1: 1.4849 ,SNR2: 5.0729




F20240702143553



BLK:14,SNR1: 2.6850 ,SNR2: 12.273





0926+117 2024/07/02 5.63UT TOYOKAWA-FUJI








T20240702143551




BLK: 6,SNR1: 1.6466 ,SNR2: 5.7408




K20240702143549





BLK: 6,SNR1: 1.4141 ,SNR2: 2.9366




0926+117 2024/07/02 5.63UT TOYOKAWA-KISO



F20240702143553





BLK:14,SNR1: 2.5473 ,SNR2: 11.701




Frequency (Hz)

K20240702143549




BLK:14,SNR1: 0.67491 ,SNR2: 2.8110





Frequency (Hz)


0926+117 2024/07/02 5.63UT FUJI -KISO





T20240702144336




BLK: 7,SNR1: 0.13950 ,SNR2: 3.3072




F20240702144338





BLK: 7,SNR1:-0.23564E-01,SNR2: 0.78413




3C222 2024/07/02 5.75UT TOYOKAWA-FUJI





T20240702144336




BLK:11,SNR1: 0.20987 ,SNR2: 4.0085




K20240702144334





BLK:11,SNR1: 0.17176 ,SNR2: 2.4548




3C222 2024/07/02 5.75UT TOYOKAWA-KISO



F20240702144338





BLK: 6,SNR1: 0.22283 ,SNR2: 1.4977




Frequency (Hz)

K20240702144334




BLK: 6,SNR1: 0.17083 ,SNR2: 0.49860





Frequency (Hz)


3C222 2024/07/02 5.75UT FUJI -KISO




T20240702145036




BLK: 7,SNR1: 0.79096E-01,SNR2: 1.3536




F20240702145038





BLK: 7,SNR1: 0.78341 ,SNR2: 2.0385




0941-08 2024/07/02 5.87UT TOYOKAWA-FUJI





T20240702145036




BLK: 5,SNR1: 0.23134 ,SNR2: 4.2850




K20240702145034




BLK: 5,SNR1: 1.1628 ,SNR2: 4.7876




0941-08 2024/07/02 5.87UT TOYOKAWA-KISO





F20240702145038




BLK: 5,SNR1:-0.13423 ,SNR2: 0.50661




K20240702145034



BLK: 5,SNR1: 0.93684 ,SNR2: 2.9352




0941-08 2024/07/02 5.87UT FUJI -KISO






T20240702145857





BLK: 3,SNR1: 0.10740 ,SNR2: 1.0475




Frequency (Hz)

F20240702145859




BLK: 3,SNR1: 0.59411 ,SNR2: 1.4215





Frequency (Hz)


3C230 2024/07/02 6.01UT TOYOKAWA-FUJI





T20240702145857




BLK: 6,SNR1: 0.10604 ,SNR2: 2.0121




K20240702145854





BLK: 6,SNR1: 0.56399 ,SNR2: 1.4734




3C230 2024/07/02 6.01UT TOYOKAWA-KISO



F20240702145859





BLK: 5,SNR1:-0.41501E-01,SNR2: 1.5857




Frequency (Hz)

K20240702145854




BLK: 5,SNR1: 0.39961 ,SNR2: 2.5250





Frequency (Hz)


3C230 2024/07/02 6.01UT FUJI -KISO



T20240702151458





BLK:14,SNR1: 1.5907 ,SNR2: 3.5774




Frequency (Hz)

F20240702151500




BLK:14,SNR1: 0.66119 ,SNR2: 3.6881





Frequency (Hz)


3C237 2024/07/02 6.28UT TOYOKAWA-FUJI





T20240702151458




BLK:22,SNR1: 1.2359 ,SNR2: 2.7181




K20240702151456





BLK:22,SNR1: 0.53909 ,SNR2: 3.1770




3C237 2024/07/02 6.28UT TOYOKAWA-KISO





F20240702151500




BLK:11,SNR1: 1.4552 ,SNR2: 6.8847




K20240702151456





BLK:11,SNR1: 2.0839 ,SNR2: 7.1629




3C237 2024/07/02 6.28UT FUJI -KISO



T20240702152114





BLK: 3,SNR1: 0.15548 ,SNR2: 0.73266




Frequency (Hz)

F20240702152116




BLK: 3,SNR1: 1.9663 ,SNR2: 7.6089





Frequency (Hz)


1011+110 2024/07/02 6.38UT TOYOKAWA-FUJI





T20240702152114




BLK: 3,SNR1: 0.15807 ,SNR2: 0.30644




K20240702152112



BLK: 3,SNR1: 0.37894 ,SNR2: 2.0495





1011+110 2024/07/02 6.38UT TOYOKAWA-KISO






F20240702152116





BLK:11,SNR1: 0.93059 ,SNR2: 3.2186




Frequency (Hz)

K20240702152112




BLK:11,SNR1: 0.41571 ,SNR2: 2.6788





Frequency (Hz)


1011+110 2024/07/02 6.38UT FUJI -KISO




T20240702152855




BLK:18,SNR1: 0.22283 ,SNR2: 2.0251




F20240702152857





BLK:18,SNR1: 3.8335 ,SNR2: 6.8518




3C241 2024/07/02 6.51UT TOYOKAWA-FUJI





T20240702152855




BLK:15,SNR1: 0.25977 ,SNR2: 1.6184




K20240702152853




BLK:15,SNR1: 3.9925 ,SNR2: 11.087




3C241 2024/07/02 6.51UT TOYOKAWA-KISO





F20240702152857




BLK:23,SNR1: 2.9046 ,SNR2: 7.4725




K20240702152853





BLK:23,SNR1: 3.9812 ,SNR2: 11.057




3C241 2024/07/02 6.51UT FUJI -KISO



T20240702154025





BLK:15,SNR1: 0.24686 ,SNR2: 1.2870




Frequency (Hz)

F20240702154027




BLK:15,SNR1: 1.1715 ,SNR2: 4.0465





Frequency (Hz)


1031-11 2024/07/02 6.70UT TOYOKAWA-FUJI




T20240702154025




BLK:12,SNR1: 0.22181 ,SNR2: 1.4006




K20240702154023





BLK:12,SNR1: 5.8274 ,SNR2: 10.272




1031-11 2024/07/02 6.70UT TOYOKAWA-KISO



F20240702154027





BLK:25,SNR1: 0.80595 ,SNR2: 2.9818




Frequency (Hz)

K20240702154023




BLK:25,SNR1: 2.2028 ,SNR2: 7.8470




Frequency (Hz)


1031-11 2024/07/02 6.70UT FUJI -KISO



T20240702154458




BLK:10,SNR1: 7.7627 ,SNR2: 64.076




Frequency (Hz)

F20240702154500




BLK:10,SNR1: 0.35974 ,SNR2: 1.6815




Frequency (Hz)

1035-058 2024/07/02 6.78UT TOYOKAWA-FUJI







T20240702154458




BLK: 3,SNR1: 10.482 ,SNR2: 106.02




K20240702154456




BLK: 3,SNR1: 0.19229 ,SNR2: 4.8879




1035-058 2024/07/02 6.78UT TOYOKAWA-KISO



F20240702154500





BLK: 7,SNR1:-0.24014 ,SNR2: 0.56353




Frequency (Hz)

K20240702154456




BLK: 7,SNR1: 0.22756 ,SNR2: 3.9968





Frequency (Hz)


1035-058 2024/07/02 6.78UT FUJI -KISO



T20240702155411





BLK: 3,SNR1: 0.40200E-01,SNR2: 0.27904




Frequency (Hz)

F20240702155413




BLK: 3,SNR1:-0.39986E-01,SNR2: 0.62746





Frequency (Hz)


1044-008 2024/07/02 6.93UT TOYOKAWA-FUJI



T20240702155411




BLK: 5,SNR1: 0.19912 ,SNR2: 0.59540




Frequency (Hz)

K20240702155408




BLK: 5,SNR1: 0.20910 ,SNR2: 1.0912





Frequency (Hz)


1044-008 2024/07/02 6.93UT TOYOKAWA-KISO



F20240702155413





BLK: 6,SNR1:-0.33186E-01,SNR2: 1.3969




Frequency (Hz)

K20240702155408




BLK: 6,SNR1: 0.45783 ,SNR2: 2.9058




Frequency (Hz)


1044-008 2024/07/02 6.93UT FUJI -KISO



T20240702160515





BLK: 3,SNR1: 0.18441 ,SNR2: 1.2476




Frequency (Hz)

F20240702160517




BLK: 3,SNR1: 0.14275 ,SNR2: 2.3442





Frequency (Hz)


1055+01 2024/07/02 7.12UT TOYOKAWA-FUJI



T20240702160515





BLK: 9,SNR1: 0.95496E-01,SNR2: 0.75132




Frequency (Hz)

K20240702160513




BLK: 9,SNR1: 0.52022 ,SNR2: 2.3841





Frequency (Hz)


1055+01 2024/07/02 7.12UT TOYOKAWA-KISO



F20240702160517





BLK:14,SNR1: 0.15949 ,SNR2: 2.6763




Frequency (Hz)

K20240702160513




BLK:14,SNR1: 0.24625 ,SNR2: 1.2323





Frequency (Hz)

1055+01 2024/07/02 7.12UT FUJI -KISO






T20240702161633





BLK: 8,SNR1: 0.38461 ,SNR2: 3.0876




Frequency (Hz)

F20240702161635




BLK: 8,SNR1: 1.4625 ,SNR2: 3.7715





Frequency (Hz)


1107+109 2024/07/02 7.30UT TOYOKAWA-FUJI



T20240702161633





BLK: 7,SNR1: 0.40278 ,SNR2: 3.1750




Frequency (Hz)

K20240702161631




BLK: 7,SNR1: 0.90540 ,SNR2: 5.3633





Frequency (Hz)


1107+109 2024/07/02 7.30UT TOYOKAWA-KISO





F20240702161635




BLK:15,SNR1: 0.72818 ,SNR2: 1.8182




K20240702161631





BLK:15,SNR1: 0.70286 ,SNR2: 3.5457




1107+109 2024/07/02 7.30UT FUJI -KISO



T20240702162610




BLK: 3,SNR1: 0.73991E-01,SNR2: 1.1179




Frequency (Hz)

F20240702162612




BLK: 3,SNR1: 0.33389 ,SNR2: 1.4530





Frequency (Hz)


3C255 2024/07/02 7.46UT TOYOKAWA-FUJI





T20240702162610




BLK: 3,SNR1: 0.19589 ,SNR2: 1.6382




K20240702162608




BLK: 3,SNR1: 1.1856 ,SNR2: 4.2482




3C255 2024/07/02 7.46UT TOYOKAWA-KISO



F20240702162612





BLK: 2,SNR1: 0.94247E-01,SNR2: 0.89538




Frequency (Hz)

K20240702162608




BLK: 2,SNR1:-0.34067E-01,SNR2: 0.43470





Frequency (Hz)


3C255 2024/07/02 7.46UT FUJI -KISO



T20240702165008





BLK: 6,SNR1: 0.49665 ,SNR2: 2.0704




Frequency (Hz)

F20240702165010




BLK: 6,SNR1: 0.78675 ,SNR2: 4.0179





Frequency (Hz)


3C263.1 2024/07/02 7.86UT TOYOKAWA-FUJI



T20240702165008





BLK: 5,SNR1: 0.60949 ,SNR2: 3.9198




Frequency (Hz)

K20240702165006




BLK: 5,SNR1: 0.30797 ,SNR2: 2.6602




Frequency (Hz)

3C263.1 2024/07/02 7.86UT TOYOKAWA-KISO






F20240702165010




BLK: 9,SNR1: 1.6705 ,SNR2: 4.9320




Frequency (Hz)

K20240702165006




BLK: 9,SNR1: 0.19440 ,SNR2: 1.4524





Frequency (Hz)


3C263.1 2024/07/02 7.86UT FUJI -KISO



T20240702165635





BLK: 3,SNR1: 0.72535E-01,SNR2: 0.95082




Frequency (Hz)

F20240702165637




BLK: 3,SNR1: 0.51664E-01,SNR2: 3.4897





Frequency (Hz)


3C267 2024/07/02 7.97UT TOYOKAWA-FUJI



T20240702165635





BLK: 4, SNR1: 0.66039 , SNR2: 3.7253




Frequency (Hz)

K20240702165632




BLK: 4, SNR1: 0.93050 , SNR2: 3.9860





Frequency (Hz)


3C267 2024/07/02 7.97UT TOYOKAWA-KISO



F20240702165637





BLK: 7,SNR1: 0.70240E-01,SNR2: 1.2647




Frequency (Hz)

K20240702165632




BLK: 7,SNR1: 0.44455 ,SNR2: 2.1299





Frequency (Hz)


3C267 2024/07/02 7.97UT FUJI -KISO



T20240702171549





BLK: 1,SNR1:-0.14715 ,SNR2: 0.0000




Frequency (Hz)

F20240702171551




BLK: 1,SNR1: 0.63207 ,SNR2: 7.8959





Frequency (Hz)


1206+439 2024/07/02 8.29UT TOYOKAWA-FUJI



T20240702171549





BLK: 3,SNR1:-0.38398E-01,SNR2: 1.4093




Frequency (Hz)

K20240702171546




BLK: 3,SNR1:-0.55229E-01,SNR2: 0.33102





Frequency (Hz)


1206+439 2024/07/02 8.29UT TOYOKAWA-KISO



F20240702171551





BLK: 1,SNR1: 0.29270 ,SNR2: 2.1299




Frequency (Hz)

K20240702171546




BLK: 1,SNR1: 0.14635 ,SNR2: 1.3634





Frequency (Hz)


1206+439 2024/07/02 8.29UT FUJI -KISO



T20240702174537




BLK: 5,SNR1:-0.38578E-01,SNR2: 0.22888




Frequency (Hz)

F20240702174539




BLK: 5,SNR1: 2.9928 ,SNR2: 13.241





Frequency (Hz)

1236+327 2024/07/02 8.79UT TOYOKAWA-FUJI






T20240702174537





BLK: 5,SNR1: 0.15594 ,SNR2: 0.41792




Frequency (Hz)

K20240702174534




BLK: 5,SNR1: 0.36502 ,SNR2: 2.3800





Frequency (Hz)


1236+327 2024/07/02 8.79UT TOYOKAWA-KISO



F20240702174539





BLK:14,SNR1: 3.0175 ,SNR2: 13.318




Frequency (Hz)

K20240702174534



BLK:14,SNR1: 1.4855 ,SNR2: 6.6932



Frequency (Hz)

1236+327 2024/07/02 8.79UT FUJI -KISO

