





T20240706054508




No.Good Data




F20240706054510




No.Good Data




0049+379 2024/07/05 20.78UT TOYOKAWA-FUJI



T20240706054508




BLK: 4,SNR1: 0.15552E-01,SNR2: 0.26120




Frequency (Hz)

K20240706054505




BLK: 4,SNR1: 0.50420 ,SNR2: 1.5442




Frequency (Hz)

0049+379 2024/07/05 20.78UT TOYOKAWA-KISO






F20240706054510





BLK: 1,SNR1: 1.0771 ,SNR2: 4.2780




Frequency (Hz)

K20240706054505




BLK: 1,SNR1: 0.13380 ,SNR2: 0.45201





Frequency (Hz)


0049+379 2024/07/05 20.78UT FUJI -KISO




T20240706055934




BLK: 5,SNR1: 0.70554E-01,SNR2: 0.56200




F20240706055936





BLK: 5,SNR1:-0.42177E-01,SNR2: 1.4720




0103+422 2024/07/05 21.02UT TOYOKAWA-FUJI



T20240706055934





BLK: 4,SNR1: 0.40332E-01,SNR2: 0.22575




Frequency (Hz)

K20240706055932




BLK: 4,SNR1: 0.49525 ,SNR2: 4.8564




Frequency (Hz)


0103+422 2024/07/05 21.02UT TOYOKAWA-KISO





F20240706055936




BLK:13,SNR1: 0.30004 ,SNR2: 3.9678




K20240706055932





BLK:13,SNR1: 0.40590 ,SNR2: 1.9477




0103+422 2024/07/05 21.02UT FUJI -KISO




T20240706061221




BLK: 3,SNR1:-0.14120E-01,SNR2: 0.14271




F20240706061223





BLK: 3,SNR1: 0.29031 ,SNR2: 1.2974




0116+31 2024/07/05 21.23UT TOYOKAWA-FUJI



T20240706061221




BLK: 5,SNR1: 0.73436E-02,SNR2: 0.26730




Frequency (Hz)

K20240706061218




BLK: 5,SNR1: 1.5554 ,SNR2: 7.2371




Frequency (Hz)


0116+31 2024/07/05 21.23UT TOYOKAWA-KISO



F20240706061223




BLK:11,SNR1: 0.16011 ,SNR2: 1.7173




Frequency (Hz)

K20240706061218




BLK:11,SNR1: 1.1030 ,SNR2: 5.3996





Frequency (Hz)


0116+31 2024/07/05 21.23UT FUJI -KISO



T20240706063027



BLK:10,SNR1: 0.30659 ,SNR2: 1.2083





Frequency (Hz)


3C48

2024/07/05 21.54UT TOYOKAWA-FUJI


F20240706063029



BLK:10,SNR1: 0.33444 ,SNR2: 2.9594





Frequency (Hz)






T20240706063027



BLK:10,SNR1: 0.31151 ,SNR2: 2.5479





Frequency (Hz)


3C48

2024/07/05 21.54UT TOYOKAWA-KISO


K20240706063025




BLK:10,SNR1: 2.8604 ,SNR2: 12.336




Frequency (Hz)



F20240706063029




BLK: 3,SNR1: 0.19223 ,SNR2: 1.8475




Frequency (Hz)

3C48 2024/07/05 21.54UT FUJI -KISO


K20240706063025




BLK: 3,SNR1: 3.6846 ,SNR2: 15.866




Frequency (Hz)



T20240706064411





BLK: 2,SNR1: 0.14750 ,SNR2: 0.44598




Frequency (Hz)

F20240706064413




BLK: 2,SNR1:-0.24596 ,SNR2: 2.7424




Frequency (Hz)


0148+274 2024/07/05 21.76UT TOYOKAWA-FUJI



T20240706064411





BLK: 5,SNR1: 0.45061E-01,SNR2: 0.76507




Frequency (Hz)

K20240706064408




BLK: 5,SNR1: 0.13728 ,SNR2: 2.9787




Frequency (Hz)


0148+274 2024/07/05 21.76UT TOYOKAWA-KISO



F20240706064413




BLK: 2,SNR1:-0.33323 ,SNR2: 2.7511




Frequency (Hz)

K20240706064408




BLK: 2,SNR1: 0.32279 ,SNR2: 0.26447




Frequency (Hz)


0148+274 2024/07/05 21.76UT FUJI -KISO



T20240706065719




BLK: 5,SNR1: 0.82399E-01,SNR2: 0.72760




Frequency (Hz)

F20240706065721




BLK: 5,SNR1: 1.0626 ,SNR2: 3.2293





Frequency (Hz)


0202+15 2024/07/05 21.98UT TOYOKAWA-FUJI



T20240706065719





BLK: 2,SNR1: 0.16934E-01,SNR2: 0.29624




Frequency (Hz)

K20240706065716




BLK: 2,SNR1: 0.20327 ,SNR2: 0.39927




Frequency (Hz)


0202+15 2024/07/05 21.98UT TOYOKAWA-KISO



F20240706065721





BLK:12,SNR1: 0.72273 ,SNR2: 2.0212




Frequency (Hz)

K20240706065716




BLK:12,SNR1: 3.7266 ,SNR2: 17.082





Frequency (Hz)

0202+15 2024/07/05 21.98UT FUJI -KISO






T20240706070910




BLK: 3,SNR1: 0.21111 ,SNR2: 0.62176




Frequency (Hz)

F20240706070912




BLK: 3,SNR1: 0.41569 ,SNR2: 3.7799





Frequency (Hz)


0213+178 2024/07/05 22.18UT TOYOKAWA-FUJI



T20240706070910





BLK: 1,SNR1: 0.31285 ,SNR2: 1.5001




Frequency (Hz)

K20240706070907




BLK: 1,SNR1: 0.13080 ,SNR2: 0.67355





Frequency (Hz)


0213+178 2024/07/05 22.18UT TOYOKAWA-KISO





F20240706070912




BLK: 5,SNR1: 0.30967 ,SNR2: 1.7577




K20240706070907





BLK: 5,SNR1: 0.98080 ,SNR2: 5.1414




0213+178 2024/07/05 22.18UT FUJI -KISO



T20240706071652



BLK: 4,SNR1: 0.19330 ,SNR2: 0.52803





Frequency (Hz)


3C67

2024/07/05 22.31UT TOYOKAWA-FUJI


F20240706071654





BLK: 4,SNR1: 0.39622 ,SNR2: 2.4257




Frequency (Hz)



T20240706071652





BLK: 1,SNR1: 0.22173 ,SNR2: 1.1168




Frequency (Hz)

3C67 2024/07/05 22.31UT TOYOKAWA-KISO


K20240706071649




BLK: 1,SNR1: 0.51487 ,SNR2: 0.95521




Frequency (Hz)



F20240706071654



BLK: 1,SNR1: 0.69803 ,SNR2: 0.83539




Frequency (Hz)


3C67

2024/07/05 22.31UT FUJI -KISO


K20240706071649




BLK: 1,SNR1:-0.65151E-02,SNR2: 0.0000




Frequency (Hz)



T20240706073507



BLK: 3,SNR1: 0.20250 ,SNR2: 0.30052





Frequency (Hz)


3C71

2024/07/05 22.61UT TOYOKAWA-FUJI


F20240706073509





BLK: 3,SNR1: 1.7076 ,SNR2: 4.0844




Frequency (Hz)





T20240706073507




BLK: 5,SNR1: 0.23487E-01,SNR2: 0.33640




K20240706073504



BLK: 5,SNR1: 1.3957 ,SNR2: 7.5214





3C71 2024/07/05 22.61UT TOYOKAWA-KISO






F20240706073509



BLK: 4,SNR1:-0.63465E-02,SNR2: 1.3251





Frequency (Hz)


3C71

2024/07/05 22.61UT FUJI -KISO


K20240706073504





BLK: 4,SNR1: 1.0569 ,SNR2: 6.6168




Frequency (Hz)



T20240706075422





BLK:10,SNR1: 3.9531 ,SNR2: 10.954




Frequency (Hz)

F20240706075424




BLK:10,SNR1: 4.1173 ,SNR2: 17.294





Frequency (Hz)


0258+350 2024/07/05 22.93UT TOYOKAWA-FUJI



T20240706075422





BLK:17,SNR1: 3.7789 ,SNR2: 10.474





0258+350 2024/07/05 22.93UT TOYOKAWA-KISO



K20240706075419




BLK:17,SNR1: 4.0706 ,SNR2: 17.093



F20240706075424





BLK:23,SNR1: 4.1421 ,SNR2: 17.391




Frequency (Hz)

K20240706075419




BLK:23,SNR1: 4.0705 ,SNR2: 17.092





Frequency (Hz)


0258+350 2024/07/05 22.93UT FUJI -KISO





T20240706080411




No.Good Data




F20240706080413





No.Good Data




0308+305 2024/07/05 23.10UT TOYOKAWA-FUJI





T20240706080411




BLK: 4,SNR1:-0.65009E-01,SNR2: 0.64057




K20240706080408




BLK: 4,SNR1: 1.8256 ,SNR2: 7.1625




0308+305 2024/07/05 23.10UT TOYOKAWA-KISO



F20240706080413




BLK: 7,SNR1: 2.9354 ,SNR2: 12.698




Frequency (Hz)

K20240706080408




BLK: 7,SNR1: 2.2435 ,SNR2: 8.5132





Frequency (Hz)


0308+305 2024/07/05 23.10UT FUJI -KISO



T20240706081543





BLK: 7,SNR1: 0.18753 ,SNR2: 1.7626




Frequency (Hz)

F20240706081545




BLK: 7,SNR1: 0.30114 ,SNR2: 1.8601




Frequency (Hz)

0320+05 2024/07/05 23.29UT TOYOKAWA-FUJI







T20240706081543




BLK: 9,SNR1: 0.87253E-01,SNR2: 1.5566




K20240706081541




BLK: 9,SNR1: 1.4811 ,SNR2: 6.1902




0320+05 2024/07/05 23.29UT TOYOKAWA-KISO



F20240706081545




BLK:11,SNR1: 0.50366 ,SNR2: 2.0484




Frequency (Hz)

K20240706081541




BLK:11,SNR1: 0.91025 ,SNR2: 3.7870





Frequency (Hz)


0320+05 2024/07/05 23.29UT FUJI -KISO



T20240706082904




BLK: 1,SNR1:-0.12979 ,SNR2: 0.34362




Frequency (Hz)

F20240706082906




BLK: 1,SNR1: 0.55719E-02,SNR2: 0.52523E-01





Frequency (Hz)


0333+32 2024/07/05 23.51UT TOYOKAWA-FUJI



T20240706082904





BLK: 2,SNR1: 0.42079E-01,SNR2: 0.28050





0333+32 2024/07/05 23.51UT TOYOKAWA-KISO



K20240706082901




BLK: 2,SNR1: 0.25576 ,SNR2: 2.5583



F20240706082906




BLK: 9,SNR1: 1.1329 ,SNR2: 3.4411




Frequency (Hz)

K20240706082901




BLK: 9,SNR1: 0.35806 ,SNR2: 1.7059




Frequency (Hz)


0333+32 2024/07/05 23.51UT FUJI -KISO




T20240706084206




BLK: 8,SNR1: 0.16130 ,SNR2: 0.63495




F20240706084208





BLK: 8,SNR1: 1.7792 ,SNR2: 4.6963




0347+05 2024/07/05 23.73UT TOYOKAWA-FUJI





T20240706084206




BLK: 6,SNR1: 0.36491E-01,SNR2: 1.1928




K20240706084204





BLK: 6,SNR1: 1.3650 ,SNR2: 5.4996




0347+05 2024/07/05 23.73UT TOYOKAWA-KISO





F20240706084208




BLK:12,SNR1: 2.5457 ,SNR2: 6.4903




K20240706084204



BLK:12,SNR1: 0.84996 ,SNR2: 3.5199





0347+05 2024/07/05 23.73UT FUJI -KISO








T20240706090651




BLK: 5,SNR1:-0.12509E-01,SNR2: 1.1909




F20240706090653





BLK: 5,SNR1: 0.39147 ,SNR2: 1.5123




0411+05 2024/07/06 0.14UT TOYOKAWA-FUJI



T20240706090651





BLK: 4,SNR1: 0.15680 ,SNR2: 1.9961





0411+05 2024/07/06 0.14UT TOYOKAWA-KISO



K20240706090648




BLK: 4,SNR1: 0.62442 ,SNR2: 5.1896





F20240706090653




BLK: 8,SNR1: 0.44376 ,SNR2: 1.7283




K20240706090648





BLK: 8,SNR1: 0.48879 ,SNR2: 2.1882




0411+05 2024/07/06 0.14UT FUJI -KISO





T20240706091345




BLK:12,SNR1: 3.1320 ,SNR2: 7.6798




F20240706091347





BLK:12,SNR1: 2.7619 ,SNR2: 6.7317




0418+236 2024/07/06 0.26UT TOYOKAWA-FUJI





T20240706091345




BLK:18,SNR1: 2.6425 ,SNR2: 6.3941




K20240706091342





BLK:18,SNR1: 9.7571 ,SNR2: 24.220




0418+236 2024/07/06 0.26UT TOYOKAWA-KISO



F20240706091347




BLK:22,SNR1: 2.2082 ,SNR2: 5.3990




Frequency (Hz)

K20240706091342




BLK:22,SNR1: 7.5386 ,SNR2: 19.468





Frequency (Hz)


0418+236 2024/07/06 0.26UT FUJI -KISO



T20240706092512





BLK:18,SNR1: 1.2462 ,SNR2: 3.3768




Frequency (Hz)

F20240706092514




BLK:18,SNR1: 4.9445 ,SNR2: 12.467




Frequency (Hz)


3C119 2024/07/06 0.45UT TOYOKAWA-FUJI




T20240706092512




BLK:22,SNR1: 1.0551 ,SNR2: 5.1347




K20240706092510



BLK:22,SNR1: 5.3341 ,SNR2: 7.6672




3C119 2024/07/06 0.45UT TOYOKAWA-KISO






F20240706092514




BLK:21,SNR1: 4.7073 ,SNR2: 11.761





3C119 2024/07/06 0.45UT FUJI -KISO



K20240706092510




BLK:21,SNR1: 2.5662 ,SNR2: 8.8381



T20240706101319





BLK:29,SNR1: 4.2319 ,SNR2: 10.280




Frequency (Hz)

F20240706101321




BLK:29,SNR1: 5.4553 ,SNR2: 15.705





Frequency (Hz)


3C138 2024/07/06 1.25UT TOYOKAWA-FUJI



T20240706101319





BLK:34,SNR1: 2.9667 ,SNR2: 13.159




Frequency (Hz)

3C138 2024/07/06 1.25UT TOYOKAWA-KISO


K20240706101316





BLK:34,SNR1: 2.7482 ,SNR2: 13.092




Frequency (Hz)



F20240706101321





BLK:28,SNR1: 5.6590 ,SNR2: 16.485




Frequency (Hz)

3C138 2024/07/06 1.25UT FUJI -KISO


K20240706101316




BLK:28,SNR1: 2.7706 ,SNR2: 13.201




Frequency (Hz)



T20240706102653





BLK:21,SNR1: 2.2673 ,SNR2: 29.097





0531+194 2024/07/06 1.48UT TOYOKAWA-FUJI


F20240706102655




BLK:21,SNR1: 0.11336 ,SNR2: 2.8189



T20240706102653





BLK:26,SNR1: 2.1573 ,SNR2: 25.926





0531+194 2024/07/06 1.48UT TOYOKAWA-KISO



K20240706102650




BLK:26,SNR1: 0.59036 ,SNR2: 2.9346





F20240706102655




BLK:14,SNR1: 0.21809 ,SNR2: 0.92298




K20240706102650




BLK:14,SNR1: 0.83911 ,SNR2: 3.5305




0531+194 2024/07/06 1.48UT FUJI -KISO



T20240706103512





BLK:24,SNR1: 8.0181 ,SNR2: 19.336




Frequency (Hz)

3C147 2024/07/06 1.61UT TOYOKAWA-FUJI


F20240706103514



BLK:24,SNR1: 3.9571 ,SNR2: 10.694





Frequency (Hz)






T20240706103512





BLK:25,SNR1: 8.3430 ,SNR2: 20.104




Frequency (Hz)

3C147 2024/07/06 1.61UT TOYOKAWA-KISO


K20240706103509




BLK:25,SNR1: 6.6443 ,SNR2: 12.981




Frequency (Hz)





F20240706103514




BLK:32,SNR1: 3.2933 ,SNR2: 9.5321




K20240706103509





BLK:32,SNR1: 18.821 ,SNR2: 24.524




3C147 2024/07/06 1.61UT FUJI -KISO



T20240706104324





BLK:25,SNR1: 14.578 ,SNR2: 25.810





0548+16 2024/07/06 1.75UT TOYOKAWA-FUJI



F20240706104326




BLK:25,SNR1: 6.3239 ,SNR2: 16.071



T20240706104324





BLK:24,SNR1: 14.330 ,SNR2: 34.460





0548+16 2024/07/06 1.75UT TOYOKAWA-KISO


K20240706104321




BLK:24,SNR1: 2.9239 ,SNR2: 13.838





F20240706104326




BLK:31,SNR1: 6.1234 ,SNR2: 15.559




K20240706104321





BLK:31,SNR1: 2.9181 ,SNR2: 13.816




0548+16 2024/07/06 1.75UT FUJI -KISO



T20240706104735





BLK:24,SNR1: 2.6330 ,SNR2: 11.632




Frequency (Hz)

0552+12 2024/07/06 1.82UT TOYOKAWA-FUJI


F20240706104737




BLK:24,SNR1: 2.5576 ,SNR2: 5.3515




Frequency (Hz)



T20240706104735




BLK:23,SNR1: 2.6657 ,SNR2: 11.761





0552+12 2024/07/06 1.82UT TOYOKAWA-KISO



K20240706104732




BLK:23,SNR1: 9.0845 ,SNR2: 17.607





F20240706104737




BLK:23,SNR1: 2.1401 ,SNR2: 5.1671




K20240706104732



BLK:23,SNR1: 9.2558 ,SNR2: 17.935





0552+12 2024/07/06 1.82UT FUJI -KISO






T20240706105201





BLK: 7,SNR1: 0.32457 ,SNR2: 0.78332




Frequency (Hz)

F20240706105203




BLK: 7,SNR1: 2.9318 ,SNR2: 14.592





Frequency (Hz)


0556+191 2024/07/06 1.90UT TOYOKAWA-FUJI





T20240706105201




BLK:17,SNR1: 0.53285 ,SNR2: 1.9688




K20240706105158




BLK:17,SNR1: 0.74792 ,SNR2: 3.1514




0556+191 2024/07/06 1.90UT TOYOKAWA-KISO





F20240706105203




BLK: 8,SNR1: 7.1674 ,SNR2: 11.503




K20240706105158





BLK: 8,SNR1: 0.37235 ,SNR2: 1.5305




0556+191 2024/07/06 1.90UT FUJI -KISO



T20240706105947





BLK:11,SNR1: 0.78457E-01,SNR2: 0.63129




Frequency (Hz)

F20240706105949




BLK:11,SNR1: 0.17670E-01,SNR2: 1.0870





Frequency (Hz)


0605-08 2024/07/06 2.02UT TOYOKAWA-FUJI



T20240706105947





BLK:10,SNR1: 0.13559 ,SNR2: 0.85650




Frequency (Hz)

0605-08 2024/07/06 2.02UT TOYOKAWA-KISO


K20240706105944




BLK:10,SNR1: 1.1057 ,SNR2: 4.5887




Frequency (Hz)




F20240706105949




BLK:13,SNR1: 0.79627E-01,SNR2: 1.3510




K20240706105944




BLK:13,SNR1: 0.82857 ,SNR2: 3.3632




0605-08 2024/07/06 2.02UT FUJI -KISO





T20240706111855




BLK:31,SNR1: 21.985 ,SNR2: 40.197




F20240706111857




BLK:31,SNR1: 8.4958 ,SNR2: 21.025




3C161 2024/07/06 2.34UT TOYOKAWA-FUJI




T20240706111855




BLK:32,SNR1: 22.954 ,SNR2: 41.950




K20240706111852



BLK:32,SNR1: 7.5010 ,SNR2: 22.171





3C161 2024/07/06 2.34UT TOYOKAWA-KISO






F20240706111857




BLK:34,SNR1: 8.4302 ,SNR2: 20.865





3C161 2024/07/06 2.34UT FUJI -KISO



K20240706111852




BLK:34,SNR1: 7.6447 ,SNR2: 22.985





T20240706114628




BLK: 9,SNR1: 0.25037 ,SNR2: 1.4657




F20240706114630





BLK: 9,SNR1:-0.78170E-01,SNR2: 1.1078




0652-130 2024/07/06 2.80UT TOYOKAWA-FUJI



T20240706114628





BLK:10,SNR1: 0.18555 ,SNR2: 1.7223





0652-130 2024/07/06 2.80UT TOYOKAWA-KISO


K20240706114625




BLK:10,SNR1: 0.63199 ,SNR2: 3.1131




F20240706114630




BLK: 8,SNR1: 0.96476E-01,SNR2: 1.1777




K20240706114625





BLK: 8,SNR1: 0.63397 ,SNR2: 2.4429




0652-130 2024/07/06 2.80UT FUJI -KISO





T20240706115804




BLK: 5,SNR1:-0.17761E-01,SNR2: 0.31125




F20240706115806





BLK: 5,SNR1: 2.3601 ,SNR2: 4.4823




0703+138 2024/07/06 3.00UT TOYOKAWA-FUJI





T20240706115804




BLK: 3,SNR1: 0.45314E-01,SNR2: 0.48739




K20240706115801





BLK: 3,SNR1: 0.82536 ,SNR2: 4.5908




0703+138 2024/07/06 3.00UT TOYOKAWA-KISO




F20240706115806




BLK: 2,SNR1: 2.8619 ,SNR2: 9.4021




K20240706115801




BLK: 2,SNR1: 0.92984 ,SNR2: 6.0409




0703+138 2024/07/06 3.00UT FUJI -KISO



T20240706120727




BLK: 3,SNR1: 0.35385 ,SNR2: 1.1895




0713-024 2024/07/06 3.15UT TOYOKAWA-FUJI


F20240706120729



BLK: 3,SNR1: 0.77631 ,SNR2: 2.3729





Frequency (Hz)






T20240706120727





BLK:14,SNR1: 0.22000 ,SNR2: 3.0939





0713-024 2024/07/06 3.15UT TOYOKAWA-KISO


K20240706120724




BLK:14,SNR1: 0.38526 ,SNR2: 1.9397





F20240706120729




BLK: 4,SNR1:-0.17820 ,SNR2: 0.70820




K20240706120724




BLK: 4,SNR1:-0.29527E-01,SNR2: 0.57004




0713-024 2024/07/06 3.15UT FUJI -KISO




T20240706121739




BLK:18,SNR1: 1.0836 ,SNR2: 4.2156




F20240706121741





BLK:18,SNR1: 5.2768 ,SNR2: 14.599




0723+10 2024/07/06 3.32UT TOYOKAWA-FUJI




T20240706121739




BLK:25,SNR1: 0.96363 ,SNR2: 3.3257




K20240706121736




BLK:25,SNR1: 1.0341 ,SNR2: 4.3435




0723+10 2024/07/06 3.32UT TOYOKAWA-KISO



F20240706121741




BLK:24,SNR1: 4.8735 ,SNR2: 13.864





0723+10 2024/07/06 3.32UT FUJI -KISO


K20240706121736




BLK:24,SNR1: 5.5749 ,SNR2: 13.948



T20240706122753





BLK:32,SNR1: 6.2292 ,SNR2: 15.707





0732+33 2024/07/06 3.49UT TOYOKAWA-FUJI


F20240706122755




BLK:32,SNR1: 6.0036 ,SNR2: 16.622



T20240706122753




BLK:24,SNR1: 6.5666 ,SNR2: 16.569





0732+33 2024/07/06 3.49UT TOYOKAWA-KISO



K20240706122750




BLK:24,SNR1: 8.2675 ,SNR2: 20.473



F20240706122755




BLK:30,SNR1: 6.0660 ,SNR2: 16.792





0732+33 2024/07/06 3.49UT FUJI -KISO

K20240706122750





BLK:30,SNR1: 8.0101 ,SNR2: 20.068






T20240706123556




BLK:23,SNR1: 2.8729 ,SNR2: 13.666





0741-06 2024/07/06 3.63UT TOYOKAWA-FUJI



F20240706123558




BLK:23,SNR1: 8.5467 ,SNR2: 21.148



T20240706123556





BLK:25,SNR1: 2.8641 ,SNR2: 13.630




0741-06 2024/07/06 3.63UT TOYOKAWA-KISO


K20240706123553




BLK:25,SNR1: 8.5141 ,SNR2: 21.097




Frequency (Hz)





F20240706123558




BLK:28,SNR1: 7.9822 ,SNR2: 19.772




K20240706123553





BLK:28,SNR1: 8.0041 ,SNR2: 19.888




0741-06 2024/07/06 3.63UT FUJI -KISO




T20240706124540




BLK:16,SNR1: 0.68281 ,SNR2: 2.0392




F20240706124542





BLK:16,SNR1: 1.3214 ,SNR2: 3.3342




0752-200 2024/07/06 3.79UT TOYOKAWA-FUJI



T20240706124540




BLK:16,SNR1: 0.63124 ,SNR2: 1.9062





0752-200 2024/07/06 3.79UT TOYOKAWA-KISO



K20240706124537




BLK:16,SNR1: 3.7113 ,SNR2: 9.6900



F20240706124542





BLK:19,SNR1: 1.6807 ,SNR2: 4.0214





0752-200 2024/07/06 3.79UT FUJI -KISO


K20240706124537




BLK:19,SNR1: 4.8748 ,SNR2: 12.200




T20240706125315




BLK:15,SNR1: 0.73213 ,SNR2: 5.5237




F20240706125317




BLK:15,SNR1: 0.28982 ,SNR2: 2.5513




3C190 2024/07/06 3.92UT TOYOKAWA-FUJI



T20240706125315





BLK:20,SNR1: 0.74024 ,SNR2: 3.1404





3C190 2024/07/06 3.92UT TOYOKAWA-KISO

K20240706125313




BLK:20,SNR1: 1.0366 ,SNR2: 3.8159






F20240706125317





BLK:18,SNR1: 0.32954 ,SNR2: 2.2738





3C190 2024/07/06 3.92UT FUJI -KISO



K20240706125313




BLK:18,SNR1:-0.98996E-01,SNR2: 2.1327



T20240706130539





BLK:17,SNR1: 0.61862 ,SNR2: 8.0322





3C196 2024/07/06 4.12UT TOYOKAWA-FUJI



F20240706130541




BLK:17,SNR1: 0.76164 ,SNR2: 9.3895





T20240706130539




BLK:31,SNR1: 0.57910 ,SNR2: 6.7291




K20240706130536




BLK:31,SNR1: 0.24052 ,SNR2: 1.3865




3C196 2024/07/06 4.12UT TOYOKAWA-KISO





F20240706130541




BLK: 9,SNR1: 0.79447E-01,SNR2: 3.8547




K20240706130536




BLK: 9,SNR1: 0.38521 ,SNR2: 1.7346




3C196 2024/07/06 4.12UT FUJI -KISO




T20240706131649




BLK: 6,SNR1: 0.26243 ,SNR2: 2.9274




F20240706131651




BLK: 6,SNR1: 0.40857 ,SNR2: 3.9694




0821+394 2024/07/06 4.31UT TOYOKAWA-FUJI





T20240706131649




BLK:13,SNR1: 0.12596 ,SNR2: 3.4574




K20240706131646




BLK:13,SNR1: 0.11133 ,SNR2: 1.6387




0821+394 2024/07/06 4.31UT TOYOKAWA-KISO




F20240706131651




BLK: 6,SNR1: 0.47753 ,SNR2: 5.1482




K20240706131646




BLK: 6,SNR1: 0.34127 ,SNR2: 1.3069




0821+394 2024/07/06 4.31UT FUJI -KISO




T20240706132829




BLK: 4,SNR1:-0.34418E-01,SNR2: 0.96222




F20240706132831



BLK: 4,SNR1: 0.80213E-02,SNR2: 1.7200




0834-19 2024/07/06 4.50UT TOYOKAWA-FUJI








T20240706132829




BLK: 9,SNR1: 0.35167E-01,SNR2: 1.1212




K20240706132826




BLK: 9,SNR1: 0.20409 ,SNR2: 2.0772




0834-19 2024/07/06 4.50UT TOYOKAWA-KISO





F20240706132831




BLK: 6,SNR1: 0.98684E-01,SNR2: 3.3346




K20240706132826





BLK: 6,SNR1: 0.28148 ,SNR2: 2.3758




0834-19 2024/07/06 4.50UT FUJI -KISO




T20240706133335




BLK:17,SNR1: 1.6566 ,SNR2: 7.3729




F20240706133337





BLK:17,SNR1: 1.1005 ,SNR2: 6.4017




0839-071 2024/07/06 4.59UT TOYOKAWA-FUJI





T20240706133335




BLK:19,SNR1: 1.5140 ,SNR2: 6.8993




K20240706133332




BLK:19,SNR1: 2.0924 ,SNR2: 4.1467




0839-071 2024/07/06 4.59UT TOYOKAWA-KISO





F20240706133337




BLK:17,SNR1: 0.80056 ,SNR2: 4.6476




K20240706133332





BLK:17,SNR1: 3.5062 ,SNR2: 6.9103




0839-071 2024/07/06 4.59UT FUJI -KISO





T20240706134435




BLK: 2,SNR1: 0.10307 ,SNR2: 1.7849




F20240706134437





BLK: 2,SNR1:-0.32432 ,SNR2: 0.43836




3C208 2024/07/06 4.77UT TOYOKAWA-FUJI





T20240706134435




BLK:10,SNR1: 0.21961 ,SNR2: 0.72734




K20240706134432




BLK:10,SNR1: 2.9632 ,SNR2: 5.1673




3C208 2024/07/06 4.77UT TOYOKAWA-KISO



F20240706134437





BLK: 3,SNR1:-0.49461 ,SNR2: 0.0000





3C208 2024/07/06 4.77UT FUJI -KISO

K20240706134432





BLK: 3,SNR1: 0.53949 ,SNR2: 2.1623








T20240706140117




BLK: 8,SNR1: 0.22126 ,SNR2: 0.65461




F20240706140119





BLK: 8,SNR1: 0.22234E-01,SNR2: 1.0029




3C216 2024/07/06 5.05UT TOYOKAWA-FUJI





T20240706140117




BLK: 8,SNR1: 0.21099 ,SNR2: 0.71930




K20240706140115




BLK: 8,SNR1: 1.5705 ,SNR2: 4.5145




3C216 2024/07/06 5.05UT TOYOKAWA-KISO





F20240706140119




BLK: 9,SNR1: 0.21678 ,SNR2: 2.4698




K20240706140115




BLK: 9,SNR1: 1.5524 ,SNR2: 5.0890




3C216 2024/07/06 5.05UT FUJI -KISO




T20240706141328




BLK: 3,SNR1: 0.36283E-01,SNR2: 0.48027




F20240706141330




BLK: 3,SNR1:-0.26360,SNR2: 1.0078




0919-142 2024/07/06 5.25UT TOYOKAWA-FUJI





T20240706141328




BLK: 5,SNR1: 0.10829 ,SNR2: 0.81607




K20240706141325




BLK: 5,SNR1: 0.24630 ,SNR2: 1.2464




0919-142 2024/07/06 5.25UT TOYOKAWA-KISO





F20240706141330




BLK: 2,SNR1: 0.10389E-01,SNR2: 1.9709




K20240706141325





BLK: 2,SNR1: 0.20144E-01,SNR2: 0.22402




0919-142 2024/07/06 5.25UT FUJI -KISO





T20240706142007




BLK: 7,SNR1: 0.20187 ,SNR2: 1.1226




F20240706142009





BLK: 7,SNR1: 1.1408 ,SNR2: 2.8551




0926+117 2024/07/06 5.36UT TOYOKAWA-FUJI





T20240706142007




BLK: 4,SNR1: 0.16344 ,SNR2: 1.5219




K20240706142004



BLK: 4,SNR1: 3.2102 ,SNR2: 9.3955





0926+117 2024/07/06 5.36UT TOYOKAWA-KISO








F20240706142009




BLK:20,SNR1: 1.2871 ,SNR2: 3.0718




K20240706142004





BLK:20,SNR1: 0.82733 ,SNR2: 3.3900




0926+117 2024/07/06 5.36UT FUJI -KISO




T20240706142752




BLK:10,SNR1: 0.94942E-01,SNR2: 1.7546




F20240706142754





BLK:10,SNR1:-0.11474E-01,SNR2: 1.3407




3C222 2024/07/06 5.49UT TOYOKAWA-FUJI





T20240706142752




BLK:11,SNR1: 0.13372 ,SNR2: 0.87881




K20240706142749




BLK:11,SNR1: 1.3411 ,SNR2: 5.1611




3C222 2024/07/06 5.49UT TOYOKAWA-KISO





F20240706142754




BLK: 6,SNR1:-0.43857E-01,SNR2: 1.3992




K20240706142749





BLK: 6,SNR1: 1.0836 ,SNR2: 4.9230




3C222 2024/07/06 5.49UT FUJI -KISO




T20240706143452




BLK: 4,SNR1: 0.18612 ,SNR2: 1.4152




F20240706143454





BLK: 4,SNR1: 5.0391 ,SNR2: 17.300




0941-08 2024/07/06 5.61UT TOYOKAWA-FUJI





T20240706143452




BLK: 2,SNR1: 0.13676 ,SNR2: 0.89380




K20240706143450





BLK: 2,SNR1:-0.13462 ,SNR2: 0.46637




0941-08 2024/07/06 5.61UT TOYOKAWA-KISO



F20240706143454





BLK: 4,SNR1: 6.1905 ,SNR2: 12.494




Frequency (Hz)

K20240706143450




BLK: 4,SNR1: 0.58144E-01,SNR2: 0.29541





Frequency (Hz)


0941-08 2024/07/06 5.61UT FUJI -KISO



T20240706144314





BLK:10,SNR1: 0.20508 ,SNR2: 1.1239




Frequency (Hz)

F20240706144316




BLK:10,SNR1:-0.87107E-01,SNR2: 2.2095





Frequency (Hz)

3C230 2024/07/06 5.75UT TOYOKAWA-FUJI






T20240706144314





BLK:10,SNR1: 0.26582 ,SNR2: 1.2896




Frequency (Hz)

K20240706144311




BLK:10,SNR1: 6.2803 ,SNR2: 15.063





Frequency (Hz)


3C230 2024/07/06 5.75UT TOYOKAWA-KISO



F20240706144316





BLK: 9,SNR1: 0.17438 ,SNR2: 3.2735




Frequency (Hz)

K20240706144311




BLK: 9,SNR1: 7.0847 ,SNR2: 17.109





Frequency (Hz)


3C230 2024/07/06 5.75UT FUJI -KISO





T20240706145914




BLK: 8,SNR1: 0.27640 ,SNR2: 3.2842




F20240706145916





BLK: 8,SNR1: 0.20591 ,SNR2: 1.2218




3C237 2024/07/06 6.02UT TOYOKAWA-FUJI





T20240706145914




BLK: 8,SNR1: 0.11752 ,SNR2: 3.0451




K20240706145911




BLK: 8,SNR1: 0.42405 ,SNR2: 5.1037




3C237 2024/07/06 6.02UT TOYOKAWA-KISO





F20240706145916




BLK: 4,SNR1: 0.15210 ,SNR2: 2.6416




K20240706145911





BLK: 4,SNR1: 0.29316 ,SNR2: 1.0996




3C237 2024/07/06 6.02UT FUJI -KISO





T20240706150531




BLK: 4,SNR1: 0.10763 ,SNR2: 0.50557




F20240706150533





BLK: 4,SNR1: 1.6365 ,SNR2: 6.1010




1011+110 2024/07/06 6.12UT TOYOKAWA-FUJI





T20240706150531




BLK: 3,SNR1: 0.31617E-01,SNR2: 0.70715




K20240706150528





BLK: 3,SNR1: 0.58787E-01,SNR2: 1.0776




1011+110 2024/07/06 6.12UT TOYOKAWA-KISO





F20240706150533




BLK:14,SNR1: 1.3485 ,SNR2: 5.0093




K20240706150528



BLK:14,SNR1: 0.45184 ,SNR2: 1.9038





1011+110 2024/07/06 6.12UT FUJI -KISO






T20240706151312





BLK: 6,SNR1: 0.84044E-01,SNR2: 0.51640




Frequency (Hz)

F20240706151314




BLK: 6,SNR1: 1.9148 ,SNR2: 4.6076





Frequency (Hz)


3C241 2024/07/06 6.25UT TOYOKAWA-FUJI





T20240706151312




BLK: 7,SNR1: 0.11159 ,SNR2: 0.65703




K20240706151309





BLK: 7,SNR1: 0.90004 ,SNR2: 3.8031




3C241 2024/07/06 6.25UT TOYOKAWA-KISO





F20240706151314




BLK: 8,SNR1: 0.51371E-01,SNR2: 1.3922




K20240706151309





BLK: 8,SNR1: 0.80656 ,SNR2: 3.6400




3C241 2024/07/06 6.25UT FUJI -KISO





T20240706152441




BLK: 4,SNR1: 0.10422E-01,SNR2: 0.36304




F20240706152443




BLK: 4,SNR1:-0.74499E-01,SNR2: 1.2352




1031-11 2024/07/06 6.44UT TOYOKAWA-FUJI



T20240706152441





BLK: 1,SNR1:-0.11490 ,SNR2: 0.25097




Frequency (Hz)

K20240706152439




BLK: 1,SNR1: 0.37366 ,SNR2: 11.044




Frequency (Hz)


1031-11 2024/07/06 6.44UT TOYOKAWA-KISO





F20240706152443




BLK: 1,SNR1:-0.13436 ,SNR2: 0.88669




K20240706152439





BLK: 1,SNR1: 0.53093 ,SNR2: 3.1966




1031-11 2024/07/06 6.44UT FUJI -KISO



T20240706152915





BLK: 4,SNR1:-0.23575E-01,SNR2: 1.7042




Frequency (Hz)

F20240706152917




BLK: 4,SNR1:-0.18537,SNR2: 2.0304





Frequency (Hz)


1035-058 2024/07/06 6.52UT TOYOKAWA-FUJI



T20240706152915





BLK: 2,SNR1:-0.10608 ,SNR2: 0.43761E-02




Frequency (Hz)

K20240706152913




BLK: 2,SNR1: 0.89809 ,SNR2: 3.5014




Frequency (Hz)

1035-058 2024/07/06 6.52UT TOYOKAWA-KISO






F20240706152917





BLK: 3,SNR1: 5.6837 ,SNR2: 5.5067




Frequency (Hz)

K20240706152913




BLK: 3,SNR1: 0.19624 ,SNR2: 1.0421





Frequency (Hz)


1035-058 2024/07/06 6.52UT FUJI -KISO




T20240706153827




BLK: 5,SNR1: 0.16594 ,SNR2: 1.0893




F20240706153829





BLK: 5,SNR1:-0.28234E-01,SNR2: 1.5304




1044-008 2024/07/06 6.67UT TOYOKAWA-FUJI





T20240706153827




BLK: 4,SNR1: 0.58421E-01,SNR2: 0.58275




K20240706153825




BLK: 4,SNR1: 0.28251 ,SNR2: 1.2130




1044-008 2024/07/06 6.67UT TOYOKAWA-KISO





F20240706153829




BLK:10,SNR1: 2.1456 ,SNR2: 9.8303




K20240706153825





BLK:10,SNR1: 0.57728 ,SNR2: 2.5936




1044-008 2024/07/06 6.67UT FUJI -KISO





T20240706154932




BLK: 5,SNR1: 0.79309E-03,SNR2: 0.29874




F20240706154934





BLK: 5,SNR1: 2.3112 ,SNR2: 2.3000




1055+01 2024/07/06 6.85UT TOYOKAWA-FUJI





T20240706154932




BLK: 2,SNR1: 0.11429 ,SNR2: 0.49880




K20240706154930





BLK: 2,SNR1: 1.4278 ,SNR2: 11.663




1055+01 2024/07/06 6.85UT TOYOKAWA-KISO



F20240706154934





BLK: 9,SNR1: 7.1413 ,SNR2: 7.3956




Frequency (Hz)

K20240706154930




BLK: 9,SNR1: 0.68076 ,SNR2: 3.5594





Frequency (Hz)


1055+01 2024/07/06 6.85UT FUJI -KISO



T20240706160049





BLK:10,SNR1: 0.30783 ,SNR2: 1.0426




Frequency (Hz)

F20240706160051




BLK:10,SNR1: 0.60996 ,SNR2: 1.8466





Frequency (Hz)

1107+109 2024/07/06 7.04UT TOYOKAWA-FUJI






T20240706160049





BLK: 4,SNR1: 0.47708 ,SNR2: 3.1841




Frequency (Hz)

K20240706160046




BLK: 4,SNR1: 0.24673 ,SNR2: 0.99025




Frequency (Hz)





1107+109 2024/07/06 7.04UT TOYOKAWA-KISO





F20240706160051




K20240706160046



T20240706161027




BLK: 5,SNR1: 0.16903 ,SNR2: 0.77367




Frequency (Hz)

F20240706161029




BLK: 5,SNR1: 1.1228 ,SNR2: 3.1476




Frequency (Hz)


3C255 2024/07/06 7.20UT TOYOKAWA-FUJI





T20240706161027




BLK: 7,SNR1: 0.99054E-01,SNR2: 0.63384




K20240706161024




BLK: 7,SNR1: 0.23746 ,SNR2: 1.8169




3C255 2024/07/06 7.20UT TOYOKAWA-KISO



F20240706161029





BLK:10,SNR1: 0.52413 ,SNR2: 2.8615




Frequency (Hz)

K20240706161024




BLK:10,SNR1: 0.24735 ,SNR2: 1.1597





Frequency (Hz)


3C255 2024/07/06 7.20UT FUJI -KISO



T20240706162104





BLK: 4,SNR1: 0.72037E-01,SNR2: 0.41395




Frequency (Hz)

F20240706162106




BLK: 4,SNR1: 1.0883 ,SNR2: 4.7996





Frequency (Hz)


1127-14 2024/07/06 7.38UT TOYOKAWA-FUJI



T20240706162104





BLK: 4,SNR1: 0.18961E-01,SNR2: 0.88407




Frequency (Hz)

K20240706162102




BLK: 4,SNR1: 0.50297 ,SNR2: 2.8483





Frequency (Hz)


1127-14 2024/07/06 7.38UT TOYOKAWA-KISO



F20240706162106





BLK: 4,SNR1: 0.61420E-01,SNR2: 3.4886




Frequency (Hz)

K20240706162102




BLK: 4,SNR1: 0.49858 ,SNR2: 1.4657





Frequency (Hz)

1127-14 2024/07/06 7.38UT FUJI -KISO






T20240706163425




BLK: 7,SNR1: 0.99811E-02,SNR2: 0.99954




Frequency (Hz)

F20240706163427




BLK: 7,SNR1:-0.26399E-01,SNR2: 2.4165




Frequency (Hz)


3C263.1 2024/07/06 7.60UT TOYOKAWA-FUJI



T20240706163425





BLK: 4,SNR1: 0.15355 ,SNR2: 0.95103




Frequency (Hz)

K20240706163422




BLK: 4,SNR1: 0.34081 ,SNR2: 1.7649




Frequency (Hz)


3C263.1 2024/07/06 7.60UT TOYOKAWA-KISO



F20240706163427





BLK: 3,SNR1: 8.9256 ,SNR2: 21.059




Frequency (Hz)

K20240706163422




BLK: 3,SNR1: 0.17063 ,SNR2: 1.4071





Frequency (Hz)


3C263.1 2024/07/06 7.60UT FUJI -KISO




T20240706164052




BLK: 5,SNR1: 0.93066E-01,SNR2: 0.32583




F20240706164054





BLK: 5,SNR1: 0.22588 ,SNR2: 2.2983




3C267 2024/07/06 7.71UT TOYOKAWA-FUJI



T20240706164052





BLK: 9,SNR1:-0.13537E-01,SNR2: 0.38259




Frequency (Hz)

K20240706164050




BLK: 9,SNR1: 0.64833 ,SNR2: 4.6438





Frequency (Hz)


3C267 2024/07/06 7.71UT TOYOKAWA-KISO



F20240706164054




BLK: 4,SNR1: 0.16564 ,SNR2: 1.2210




Frequency (Hz)

K20240706164050




BLK: 4,SNR1: 0.31417 ,SNR2: 1.4137




Frequency (Hz)


3C267 2024/07/06 7.71UT FUJI -KISO



T20240706170006




BLK:15,SNR1: 4.2494 ,SNR2: 4.5230




Frequency (Hz)

F20240706170008




BLK:15,SNR1: 0.20370 ,SNR2: 1.5598





Frequency (Hz)


1206+439 2024/07/06 8.03UT TOYOKAWA-FUJI



T20240706170006





BLK:13,SNR1: 6.0661 ,SNR2: 6.5262




Frequency (Hz)

K20240706170003




BLK:13,SNR1: 0.62227 ,SNR2: 2.7954





Frequency (Hz)

1206+439 2024/07/06 8.03UT TOYOKAWA-KISO






F20240706170008





BLK:10,SNR1: 0.55575 ,SNR2: 2.7197




Frequency (Hz)

K20240706170003




BLK:10,SNR1: 0.30303 ,SNR2: 1.9245





Frequency (Hz)


1206+439 2024/07/06 8.03UT FUJI -KISO



T20240706180644





BLK:23,SNR1: 3.6094 ,SNR2: 6.2851




Frequency (Hz)

F20240706180646




BLK:23,SNR1: 2.7127 ,SNR2: 6.2368





Frequency (Hz)


1313+453 2024/07/06 9.14UT TOYOKAWA-FUJI



T20240706180644





BLK:27,SNR1: 3.2079 ,SNR2: 6.9115




Frequency (Hz)

K20240706180641




BLK:27,SNR1: 0.90124 ,SNR2: 3.1991




Frequency (Hz)


1313+453 2024/07/06 9.14UT TOYOKAWA-KISO



F20240706180646





BLK:22,SNR1: 1.4845 ,SNR2: 5.6906




Frequency (Hz)

K20240706180641



BLK:22,SNR1: 1.0534 ,SNR2: 3.7675



Frequency (Hz)

1313+453 2024/07/06 9.14UT FUJI -KISO

