




T20240707055538





BLK: 3,SNR1: 0.63026 ,SNR2: 6.6235




Frequency (Hz)

F20240707055540




BLK: 3,SNR1:-0.13722 ,SNR2: 1.5191





Frequency (Hz)


0103+422 2024/07/06 20.96UT TOYOKAWA-FUJI



T20240707055538





BLK: 3,SNR1: 1.6034 ,SNR2: 6.8391




Frequency (Hz)

K20240707055535




BLK: 3,SNR1: 0.98859E-01,SNR2: 0.54427




Frequency (Hz)

0103+422 2024/07/06 20.96UT TOYOKAWA-KISO






F20240707055540




BLK: 3,SNR1:-0.20758 ,SNR2: 0.55426




Frequency (Hz)

K20240707055535




BLK: 3,SNR1: 0.29464 ,SNR2: 5.6451





Frequency (Hz)


0103+422 2024/07/06 20.96UT FUJI -KISO



T20240707060825





BLK: 1,SNR1: 0.35563 ,SNR2: 1.1261




Frequency (Hz)

F20240707060827




BLK: 1,SNR1: 0.83855 ,SNR2: 4.4097





Frequency (Hz)


0116+31 2024/07/06 21.17UT TOYOKAWA-FUJI



T20240707060825





BLK: 6,SNR1: 0.39017E-01,SNR2: 0.41070




Frequency (Hz)

K20240707060822




BLK: 6,SNR1: 1.6941 ,SNR2: 7.8476





Frequency (Hz)


0116+31 2024/07/06 21.17UT TOYOKAWA-KISO



F20240707060827




BLK:14,SNR1: 0.21983 ,SNR2: 1.7763




Frequency (Hz)

K20240707060822




BLK:14,SNR1: 0.49385 ,SNR2: 1.9475





Frequency (Hz)


0116+31 2024/07/06 21.17UT FUJI -KISO



T20240707062631



BLK:15,SNR1: 1.1245 ,SNR2: 14.522





Frequency (Hz)


3C48

2024/07/06 21.47UT TOYOKAWA-FUJI


F20240707062633





BLK:15,SNR1: 0.21892 ,SNR2: 2.7576




Frequency (Hz)



T20240707062631



BLK:11,SNR1: 0.63337 ,SNR2: 7.7546





Frequency (Hz)


3C48

2024/07/06 21.47UT TOYOKAWA-KISO


K20240707062628




BLK:11,SNR1: 0.33598 ,SNR2: 1.6227




Frequency (Hz)



F20240707062633





BLK:10,SNR1: 0.26543 ,SNR2: 3.8364




Frequency (Hz)

3C48 2024/07/06 21.47UT FUJI -KISO


K20240707062628





BLK:10,SNR1: 0.45843 ,SNR2: 2.6614




Frequency (Hz)



T20240707064015





BLK: 2,SNR1: 0.16879 ,SNR2: 0.56040




Frequency (Hz)

F20240707064017




BLK: 2,SNR1: 0.40292 ,SNR2: 3.5665





Frequency (Hz)

0148+274 2024/07/06 21.70UT TOYOKAWA-FUJI






T20240707064015





BLK: 2,SNR1:-0.65158E-01,SNR2: 0.0000




Frequency (Hz)

K20240707064012




BLK: 2,SNR1: 2.1980 ,SNR2: 7.7634




Frequency (Hz)


0148+274 2024/07/06 21.70UT TOYOKAWA-KISO



F20240707064017




BLK: 1,SNR1: 1.2309 ,SNR2: 2.3460




Frequency (Hz)

K20240707064012




BLK: 1,SNR1: 3.9904 ,SNR2: 13.791





Frequency (Hz)


0148+274 2024/07/06 21.70UT FUJI -KISO



T20240707065323





BLK: 7,SNR1: 0.26557E-01,SNR2: 0.91721




Frequency (Hz)

F20240707065325




BLK: 7,SNR1: 0.29294 ,SNR2: 1.1994





Frequency (Hz)


0202+15 2024/07/06 21.92UT TOYOKAWA-FUJI





T20240707065323




No.Good Data




K20240707065320





No.Good Data




0202+15 2024/07/06 21.92UT TOYOKAWA-KISO



F20240707065325





BLK: 1,SNR1: 0.13872E-01,SNR2: 0.93514




Frequency (Hz)

K20240707065320




BLK: 1,SNR1:-0.80656E-01,SNR2: 0.22239





Frequency (Hz)


0202+15 2024/07/06 21.92UT FUJI -KISO





T202407070514




BLK: 8,SNR1: 0.29582 ,SNR2: 0.38882




F202407070516




BLK: 8,SNR1: 0.40629 ,SNR2: 3.4603




0213+178 2024/07/06 22.12UT TOYOKAWA-FUJI



T202407070514





BLK: 9,SNR1:-0.56489E-01,SNR2: 0.21640




Frequency (Hz)

K202407070511




BLK: 9,SNR1: 2.3922 ,SNR2: 7.6393




Frequency (Hz)


0213+178 2024/07/06 22.12UT TOYOKAWA-KISO




F202407070516




BLK:17,SNR1: 0.76776 ,SNR2: 2.3625




K202407070511



BLK:17,SNR1: 2.0085 ,SNR2: 6.0414





0213+178 2024/07/06 22.12UT FUJI -KISO






T20240707071256



BLK: 2,SNR1: 0.71381E-02,SNR2: 0.0000





Frequency (Hz)


3C67

2024/07/06 22.24UT TOYOKAWA-FUJI


F20240707071258





BLK: 2,SNR1:-0.75380E-01,SNR2: 2.2725




Frequency (Hz)



T20240707071256



BLK: 4,SNR1: 0.13654 ,SNR2: 0.79096





Frequency (Hz)


3C67

2024/07/06 22.24UT TOYOKAWA-KISO


K20240707071253




BLK: 4,SNR1: 0.76913 ,SNR2: 3.7721




Frequency (Hz)





F20240707071258




No.Good Data




K20240707071253




No.Good Data




3C67 2024/07/06 22.24UT FUJI -KISO



T20240707073111



BLK:16,SNR1: 3.3317 ,SNR2: 13.651




Frequency (Hz)


3C71

2024/07/06 22.55UT TOYOKAWA-FUJI


F20240707073113





BLK:16,SNR1: 4.1231 ,SNR2: 7.8823




Frequency (Hz)



T20240707073111



BLK:21,SNR1: 3.0525 ,SNR2: 12.519




Frequency (Hz)


3C71

2024/07/06 22.55UT TOYOKAWA-KISO


K20240707073108





BLK:21,SNR1: 3.9473 ,SNR2: 16.937




Frequency (Hz)



F20240707073113





BLK:22,SNR1: 1.6429 ,SNR2: 7.3649




Frequency (Hz)

3C71 2024/07/06 22.55UT FUJI -KISO


K20240707073108





BLK:22,SNR1: 3.9851 ,SNR2: 16.761




Frequency (Hz)



T20240707075026





BLK: 6,SNR1: 0.31581 ,SNR2: 1.4813




Frequency (Hz)

F20240707075028




BLK: 6,SNR1: 0.54849 ,SNR2: 5.2477





Frequency (Hz)


0258+350 2024/07/06 22.87UT TOYOKAWA-FUJI





T20240707075026




BLK: 6,SNR1: 0.34089 ,SNR2: 1.5028




K20240707075023



BLK: 6,SNR1: 0.56004 ,SNR2: 2.0197




0258+350 2024/07/06 22.87UT TOYOKAWA-KISO







F20240707075028




BLK:10,SNR1: 0.28799 ,SNR2: 3.0544




K20240707075023





BLK:10,SNR1: 0.83014 ,SNR2: 4.9272




0258+350 2024/07/06 22.87UT FUJI -KISO



T20240707080015




BLK: 1,SNR1: 0.42408E-01,SNR2: 0.75179




Frequency (Hz)

F20240707080017




BLK: 1,SNR1: 0.36849 ,SNR2: 2.1612





Frequency (Hz)


0308+305 2024/07/06 23.03UT TOYOKAWA-FUJI



T20240707080015




BLK: 6,SNR1: 0.11014E-01,SNR2: 0.86427




Frequency (Hz)

K20240707080012




BLK: 6,SNR1: 1.8350 ,SNR2: 13.643




Frequency (Hz)


0308+305 2024/07/06 23.03UT TOYOKAWA-KISO



F20240707080017




BLK: 6,SNR1:-0.24736E-01,SNR2: 0.86610




Frequency (Hz)

K20240707080012




BLK: 6,SNR1: 1.8241 ,SNR2: 7.7765





Frequency (Hz)


0308+305 2024/07/06 23.03UT FUJI -KISO



T20240707081147





BLK: 8,SNR1: 0.18791 ,SNR2: 0.65991




Frequency (Hz)

F20240707081149




BLK: 8,SNR1: 0.44136E-01,SNR2: 2.7575





Frequency (Hz)


0320+05 2024/07/06 23.22UT TOYOKAWA-FUJI



T20240707081147




BLK:11,SNR1: 0.17742 ,SNR2: 0.83276




Frequency (Hz)

K20240707081144




BLK:11,SNR1: 0.18366 ,SNR2: 0.90244




Frequency (Hz)


0320+05 2024/07/06 23.22UT TOYOKAWA-KISO



F20240707081149





BLK: 5,SNR1: 0.86131 ,SNR2: 6.4426




Frequency (Hz)

K20240707081144




BLK: 5,SNR1: 0.23963 ,SNR2: 0.50648





Frequency (Hz)


0320+05 2024/07/06 23.22UT FWJ -KISO



T20240707082508





BLK: 8,SNR1: 5.1728 ,SNR2: 9.6860




Frequency (Hz)

F20240707082510




BLK: 8,SNR1:-0.35406 ,SNR2: 0.42687





Frequency (Hz)

0333+32 2024/07/06 23.45UT TOYOKAWA-FUJI






T20240707082508




BLK:16,SNR1: 7.9507 ,SNR2: 13.920




Frequency (Hz)

K20240707082505




BLK:16,SNR1: 2.9352 ,SNR2: 13.012





Frequency (Hz)


0333+32 2024/07/06 23.45UT TOYOKAWA-KISO




F20240707082510




BLK:17,SNR1:-0.20587 ,SNR2: 2.4638




K20240707082505




BLK:17,SNR1: 2.8406 ,SNR2: 12.180




0333+32 2024/07/06 23.45UT FUJI -KISO



T20240707083810




BLK:15,SNR1: 0.46904 ,SNR2: 2.2869




Frequency (Hz)

F20240707083812




BLK:15,SNR1: 1.1797 ,SNR2: 4.4293





Frequency (Hz)


0347+05 2024/07/06 23.66UT TOYOKAWA-FUJI



T20240707083810





BLK:16,SNR1: 0.72753 ,SNR2: 2.5036




Frequency (Hz)

K20240707083807




BLK:16,SNR1: 6.1861 ,SNR2: 17.755





Frequency (Hz)


0347+05 2024/07/06 23.66UT TOYOKAWA-KISO



F20240707083812





BLK:18,SNR1: 0.94589 ,SNR2: 3.6833




Frequency (Hz)

K20240707083807




BLK:18,SNR1: 0.73413 ,SNR2: 3.9350





Frequency (Hz)


0347+05 2024/07/06 23.66UT FUJI -KISO




T20240707085344




BLK: 8,SNR1: 0.43196E-01,SNR2: 0.96946




F20240707085346




BLK: 8,SNR1:-0.15651 ,SNR2: 1.1902




0403-132 2024/07/06 23.92UT TOYOKAWA-FUJI



T20240707085344





BLK:12,SNR1: 0.17652 ,SNR2: 0.90683




Frequency (Hz)

K20240707085341




BLK:12,SNR1: 1.5089 ,SNR2: 7.2072




Frequency (Hz)


0403-132 2024/07/06 23.92UT TOYOKAWA-KISO



F20240707085346




BLK:13,SNR1: 0.53214E-01,SNR2: 0.95458




Frequency (Hz)

K20240707085341




BLK:13,SNR1: 4.1293 ,SNR2: 17.301





Frequency (Hz)

0403-132 2024/07/06 23.92UT FUJI -KISO






T20240707090255





BLK:19,SNR1: 0.31050 ,SNR2: 2.5502




Frequency (Hz)

F20240707090257




BLK:19,SNR1: 2.7007 ,SNR2: 6.7047





Frequency (Hz)


0411+05 2024/07/07 0.08UT TOYOKAWA-FUJI



T20240707090255





BLK:14,SNR1: 0.27355 ,SNR2: 2.3564




Frequency (Hz)

K20240707090252




BLK:14,SNR1: 5.5360 ,SNR2: 13.918




Frequency (Hz)


0411+05 2024/07/07 0.08UT TOYOKAWA-KISO





F20240707090257




BLK:24,SNR1: 3.7864 ,SNR2: 8.9449




K20240707090252





BLK:24,SNR1: 4.2837 ,SNR2: 11.155




0411+05 2024/07/07 0.08UT FUJI -KISO



T20240707090949





BLK: 2,SNR1: 2.1732 ,SNR2: 27.457




Frequency (Hz)

F20240707090951




BLK: 2,SNR1: 0.74597 ,SNR2: 4.6619




Frequency (Hz)


0418+236 2024/07/07 0.19UT TOYOKAWA-FUJI



T20240707090949





BLK: 2,SNR1: 0.21854 ,SNR2: 1.2416




Frequency (Hz)

K20240707090946




BLK: 2,SNR1: 0.64728 ,SNR2: 1.8835





Frequency (Hz)


0418+236 2024/07/07 0.19UT TOYOKAWA-KISO



F20240707090951




BLK: 2,SNR1: 0.50766 ,SNR2: 3.6046




Frequency (Hz)

K20240707090946




BLK: 2,SNR1: 0.43484 ,SNR2: 2.5939




Frequency (Hz)


0418+236 2024/07/07 0.19UT FUJI -KISO





T20240707092116




BLK:12,SNR1: 0.44438 ,SNR2: 4.5884




F20240707092118





BLK:12,SNR1:-0.92904E-01,SNR2: 2.1423




3C119 2024/07/07 0.38UT TOYOKAWA-FUJI



T20240707092116





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C119 2024/07/07 0.38UT TOYOKAWA-KISO








F20240707092118




No.Good Data




KISO





No.Good Data




3C119 2024/07/07 0.38UT FUJI -KISO



T20240707100924





BLK:33,SNR1: 2.9447 ,SNR2: 13.707




Frequency (Hz)

3C138 2024/07/07 1.18UT TOYOKAWA-FUJI


F20240707100926





BLK:33,SNR1: 18.535 ,SNR2: 25.519




Frequency (Hz)



T20240707100924





BLK:32,SNR1: 2.9856 ,SNR2: 13.865




Frequency (Hz)

3C138 2024/07/07 1.18UT TOYOKAWA-KISO


K20240707100921





BLK:32,SNR1: 2.7955 ,SNR2: 13.338




Frequency (Hz)



F20240707100926





BLK:34,SNR1: 18.516 ,SNR2: 25.493





3C138 2024/07/07 1.18UT FUJI -KISO



K20240707100921




BLK:34,SNR1: 2.6155 ,SNR2: 12.627



T20240707102257





BLK:19,SNR1: 9.7578 ,SNR2: 24.379





0531+194 2024/07/07 1.41UT TOYOKAWA-FUJI



F20240707102259




BLK:19,SNR1: 2.2313 ,SNR2: 7.8139



T20240707102257





BLK:29,SNR1: 9.7312 ,SNR2: 24.314





0531+194 2024/07/07 1.41UT TOYOKAWA-KISO


K20240707102254




BLK:29,SNR1: 7.1306 ,SNR2: 20.892



F20240707102259





BLK:26,SNR1: 5.9788 ,SNR2: 10.707





0531+194 2024/07/07 1.41UT FUJI -KISO



K20240707102254




BLK:26,SNR1: 5.3876 ,SNR2: 14.952



T20240707103116




BLK:23,SNR1: 8.4319 ,SNR2: 21.065





3C147 2024/07/07 1.55UT TOYOKAWA-FUJI

F20240707103118





BLK:23,SNR1: 3.2057 ,SNR2: 11.446






T20240707103116




BLK:32,SNR1: 7.6262 ,SNR2: 19.546





3C147 2024/07/07 1.55UT TOYOKAWA-KISO


K20240707103113




BLK:32,SNR1: 7.8220 ,SNR2: 19.834




F20240707103118




BLK:27,SNR1: 0.82902 ,SNR2: 5.1813




K20240707103113




BLK:27,SNR1: 8.1364 ,SNR2: 20.429




3C147 2024/07/07 1.55UT FUJI -KISO





T20240707103928




BLK:17,SNR1: 0.30038 ,SNR2: 1.3181




F20240707103930





BLK:17,SNR1: 0.19190 ,SNR2: 1.5026




0548+16 2024/07/07 1.69UT TOYOKAWA-FUJI



T20240707103928




BLK:15,SNR1: 0.28300 ,SNR2: 1.1939





0548+16 2024/07/07 1.69UT TOYOKAWA-KISO



K20240707103925




BLK:15,SNR1: 0.48896 ,SNR2: 1.6147





F20240707103930




BLK:13,SNR1: 0.79053 ,SNR2: 1.8101




K20240707103925





BLK:13,SNR1: 0.69028 ,SNR2: 2.4635




0548+16 2024/07/07 1.69UT FUJI -KISO



T20240707104339





BLK:28,SNR1: 8.5908 ,SNR2: 21.548





0552+12 2024/07/07 1.76UT TOYOKAWA-FUJI



F20240707104341




BLK:28,SNR1: 2.9701 ,SNR2: 13.798



T20240707104339





BLK:34,SNR1: 8.5760 ,SNR2: 21.510





0552+12 2024/07/07 1.76UT TOYOKAWA-KISO



K20240707104336




BLK:34,SNR1: 8.0458 ,SNR2: 15.060



F20240707104341





BLK:31,SNR1: 2.9659 ,SNR2: 13.780





0552+12 2024/07/07 1.76UT FUJI -KISO

K20240707104336




BLK:31,SNR1: 7.5668 ,SNR2: 19.814







T20240707104805




BLK: 3,SNR1: 0.14998 ,SNR2: 1.7886




F20240707104807




BLK: 3,SNR1:-0.39922E-01,SNR2: 2.2334




0556+191 2024/07/07 1.83UT TOYOKAWA-FUJI





T20240707104805




BLK: 8,SNR1: 0.65254E-01,SNR2: 0.48436




K20240707104802





BLK: 8,SNR1: 0.26674 ,SNR2: 0.83056




0556+191 2024/07/07 1.83UT TOYOKAWA-KISO



F20240707104807





BLK: 6,SNR1: 0.12607 ,SNR2: 0.95223




Frequency (Hz)

K20240707104802




BLK: 6,SNR1: 0.38249 ,SNR2: 0.80645






Frequency (Hz)





0556+191 2024/07/07 1.83UT FUJI -KISO





T20240707105552




F20240707105554



T20240707105552





BLK:36,SNR1: 2.9856 ,SNR2: 13.230





0605-08 2024/07/07 1.96UT TOYOKAWA-KISO



K20240707105549




BLK:36,SNR1: 8.3786 ,SNR2: 20.970





F20240707105554




BLK:33,SNR1: 2.9659 ,SNR2: 13.128




K20240707105549




BLK:33,SNR1: 10.511 ,SNR2: 19.542




0605-08 2024/07/07 1.96UT FUJI -KISO





T20240707111459




BLK:21,SNR1: 10.838 ,SNR2: 19.006




F20240707111501





BLK:21,SNR1: 0.58167 ,SNR2: 2.7676




3C161 2024/07/07 2.28UT TOYOKAWA-FUJI



T20240707111459





BLK:35,SNR1: 9.5737 ,SNR2: 16.834





3C161 2024/07/07 2.28UT TOYOKAWA-KISO

K20240707111456





BLK:35,SNR1: 2.5627 ,SNR2: 12.420








F20240707111501




BLK:21,SNR1: 0.78397 ,SNR2: 3.1905




K20240707111456







BLK:21,SNR1: 5.0407 ,SNR2: 16.227






3C161 2024/07/07 2.28UT FUJI -KISO






0652-130 2024/07/07 2.74UT TOYOKAWA-FUJI









BLK:21,SNR1: 6.3549 ,SNR2: 15.494




0652-130 2024/07/07 2.74UT TOYOKAWA-KISO




BLK:21,SNR1: 2.7437 ,SNR2: 13.056





F20240707114234




BLK:21,SNR1: 4.7648 ,SNR2: 12.167




K20240707114229




BLK:21,SNR1: 2.7508 ,SNR2: 13.079




0652-130 2024/07/07 2.74UT FUJI -KISO



T20240707115409




BLK:33,SNR1: 10.692 ,SNR2: 25.780





0703+138 2024/07/07 2.93UT TOYOKAWA-FUJI


F20240707115411




BLK:33,SNR1: 16.988 ,SNR2: 29.939



T20240707115409





BLK:30,SNR1: 9.3639 ,SNR2: 17.073





0703+138 2024/07/07 2.93UT TOYOKAWA-KISO


K20240707115406




BLK:30,SNR1: 13.035 ,SNR2: 32.275




F20240707115411




BLK:33,SNR1: 16.968 ,SNR2: 29.911




K20240707115406





BLK:33,SNR1: 12.631 ,SNR2: 31.299




0703+138 2024/07/07 2.93UT FUJI -KISO



T20240707120331





BLK:32,SNR1: 8.8907 ,SNR2: 22.281




Frequency (Hz)

F20240707120333




BLK:32,SNR1: 9.7670 ,SNR2: 17.403





Frequency (Hz)

0713-024 2024/07/07 3.09UT TOYOKAWA-FUJI






T20240707120331





BLK:34,SNR1: 8.8909 ,SNR2: 22.282




Frequency (Hz)

0713-024 2024/07/07 3.09UT TOYOKAWA-KISO


K20240707120328




BLK:34,SNR1: 9.0112 ,SNR2: 22.566




Frequency (Hz)




F20240707120333




BLK:34,SNR1: 9.8647 ,SNR2: 17.570




K20240707120328




BLK:34,SNR1: 8.9705 ,SNR2: 22.454




0713-024 2024/07/07 3.09UT FUJI -KISO




T20240707121343




BLK:17,SNR1: 1.7188 ,SNR2: 8.8751




F20240707121345




BLK:17,SNR1: 0.39616E-01,SNR2: 2.7951




0723+10 2024/07/07 3.26UT TOYOKAWA-FUJI




T20240707121343




BLK:23,SNR1: 1.5325 ,SNR2: 7.8927




K20240707121340





BLK:23,SNR1: 0.41815 ,SNR2: 2.2083




0723+10 2024/07/07 3.26UT TOYOKAWA-KISO




F20240707121345




BLK: 6,SNR1: 0.28346 ,SNR2: 1.7433




K20240707121340





BLK: 6,SNR1: 1.6942 ,SNR2: 9.6708




0723+10 2024/07/07 3.26UT FUJI -KISO



T20240707122358





BLK:30,SNR1: 14.959 ,SNR2: 26.365





0732+33 2024/07/07 3.43UT TOYOKAWA-FUJI



F20240707122400




BLK:30,SNR1: 5.8600 ,SNR2: 14.737



T20240707122358





BLK:33,SNR1: 14.855 ,SNR2: 26.175




0732+33 2024/07/07 3.43UT TOYOKAWA-KISO


K20240707122355




BLK:33,SNR1: 3.0804 ,SNR2: 14.427




Frequency (Hz)



F20240707122400





BLK:32,SNR1: 8.2994 ,SNR2: 14.712




Frequency (Hz)

K20240707122355




BLK:32,SNR1: 11.867 ,SNR2: 27.077




Frequency (Hz)

0732+33 2024/07/07 3.43UT FUJI -KISO







T20240707123200




BLK:14,SNR1: 1.1831 ,SNR2: 2.8082




F20240707123202




BLK:14,SNR1: 1.2178 ,SNR2: 4.3667




0741-06 2024/07/07 3.56UT TOYOKAWA-FUJI





T20240707123200




BLK:24,SNR1: 0.76621 ,SNR2: 1.5538




K20240707123157




BLK:24,SNR1: 0.43057 ,SNR2: 1.8406




0741-06 2024/07/07 3.56UT TOYOKAWA-KISO





F20240707123202




BLK:10,SNR1: 1.9276 ,SNR2: 6.2823




K20240707123157





BLK:10,SNR1: 1.3700 ,SNR2: 5.6053




0741-06 2024/07/07 3.56UT FUJI -KISO




T20240707124144




BLK: 6,SNR1: 0.20212E-02,SNR2: 1.1162




F20240707124146





BLK: 6,SNR1: 0.54314E-01,SNR2: 1.4630




0752-200 2024/07/07 3.72UT TOYOKAWA-FUJI



T20240707124144





BLK: 2,SNR1: 0.39343 ,SNR2: 1.7185





0752-200 2024/07/07 3.72UT TOYOKAWA-KISO


K20240707124141




BLK: 2,SNR1: 0.83473 ,SNR2: 2.3288



F20240707124146





BLK: 2,SNR1: 0.30429 ,SNR2: 3.0858





0752-200 2024/07/07 3.72UT FUJI -KISO


K20240707124141




BLK: 2,SNR1: 0.38926 ,SNR2: 1.8497




T20240707124919




BLK:30,SNR1: 4.8573 ,SNR2: 12.393




F20240707124921




BLK:30,SNR1: 7.8831 ,SNR2: 19.220




3C190 2024/07/07 3.85UT TOYOKAWA-FUJI




T20240707124919




BLK:23,SNR1: 5.4320 ,SNR2: 13.862




K20240707124916



BLK:23,SNR1: 5.7456 ,SNR2: 11.244




3C190 2024/07/07 3.85UT TOYOKAWA-KISO








F20240707124921




BLK:26,SNR1: 8.1896 ,SNR2: 20.193




K20240707124916




BLK:26,SNR1: 6.8575 ,SNR2: 16.537




3C190 2024/07/07 3.85UT FUJI -KISO



T20240707130143




BLK:19,SNR1: 7.4248 ,SNR2: 20.935





3C196 2024/07/07 4.06UT TOYOKAWA-FUJI



F20240707130145




BLK:19,SNR1: 4.1679 ,SNR2: 9.3292



T20240707130143





BLK:23,SNR1: 7.0862 ,SNR2: 19.971





3C196 2024/07/07 4.06UT TOYOKAWA-KISO


K20240707130140




BLK:23,SNR1: 4.6946 ,SNR2: 18.488





F20240707130145




BLK:14,SNR1: 4.2604 ,SNR2: 9.5621




K20240707130140




BLK:14,SNR1: 7.0757 ,SNR2: 27.201




3C196 2024/07/07 4.06UT FUJI -KISO





T20240707131253




BLK:17,SNR1: 9.6857 ,SNR2: 17.933




F20240707131255





BLK:17,SNR1: 3.1100 ,SNR2: 7.2587




0821+394 2024/07/07 4.24UT TOYOKAWA-FUJI




T20240707131253




BLK:25,SNR1: 8.1349 ,SNR2: 14.930




K20240707131250




BLK:25,SNR1: 0.82780 ,SNR2: 2.4807




0821+394 2024/07/07 4.24UT TOYOKAWA-KISO





F20240707131255




BLK:15,SNR1: 2.1273 ,SNR2: 7.5092




K20240707131250





BLK:15,SNR1: 1.4731 ,SNR2: 4.7402




0821+394 2024/07/07 4.24UT FUJI -KISO




T20240707132433




BLK: 7,SNR1: 0.85703 ,SNR2: 4.1262




F20240707132435



BLK: 7,SNR1: 0.63289 ,SNR2: 1.7814




0834-19 2024/07/07 4.44UT TOYOKAWA-FUJI








T20240707132433




BLK:13,SNR1: 0.40171 ,SNR2: 2.2620




K20240707132430




BLK:13,SNR1: 1.5137 ,SNR2: 6.1840




0834-19 2024/07/07 4.44UT TOYOKAWA-KISO





F20240707132435




BLK:14,SNR1: 0.71245 ,SNR2: 2.0132




K20240707132430





BLK:14,SNR1: 1.2730 ,SNR2: 5.2482




0834-19 2024/07/07 4.44UT FUJI -KISO




T20240707132939




BLK: 3,SNR1: 0.14504 ,SNR2: 1.1977




F20240707132941





BLK: 3,SNR1:-0.18596 ,SNR2: 0.19261




0839-071 2024/07/07 4.52UT TOYOKAWA-FUJI





T20240707132939




BLK: 4,SNR1: 0.18193E-01,SNR2: 0.55103




K20240707132936





BLK: 4,SNR1: 1.5297 ,SNR2: 5.3728




0839-071 2024/07/07 4.52UT TOYOKAWA-KISO





F20240707132941




BLK: 1,SNR1: 1.9785 ,SNR2: 6.6898




K20240707132936





BLK: 1,SNR1:-0.37969E-01,SNR2: 0.60795




0839-071 2024/07/07 4.52UT FUJI -KISO





T20240707134040




BLK: 4,SNR1: 0.29296 ,SNR2: 1.4432




F20240707134042





BLK: 4,SNR1: 0.45250 ,SNR2: 1.5787




3C208 2024/07/07 4.71UT TOYOKAWA-FUJI





T20240707134040




BLK: 8,SNR1: 0.92196E-01,SNR2: 1.9829




K20240707134037




BLK: 8,SNR1: 1.0406 ,SNR2: 4.1935




3C208 2024/07/07 4.71UT TOYOKAWA-KISO



F20240707134042





BLK: 3,SNR1: 0.25237 ,SNR2: 1.2302





3C208 2024/07/07 4.71UT FUJI -KISO

K20240707134037





BLK: 3,SNR1: 0.32411 ,SNR2: 0.65775







T20240707135721




BLK: 2,SNR1: 0.97547E-01,SNR2: 2.3183




F20240707135723





BLK: 2,SNR1:-0.11111 ,SNR2: 0.55086




3C216 2024/07/07 4.98UT TOYOKAWA-FUJI





T20240707135721




BLK: 7,SNR1: 0.52487E-01,SNR2: 0.57585




K20240707135718




BLK: 7,SNR1: 0.77854 ,SNR2: 3.0283




3C216 2024/07/07 4.98UT TOYOKAWA-KISO




F20240707135723




BLK: 5,SNR1:-0.80520E-01,SNR2: 1.7056




K20240707135718





BLK: 5,SNR1: 0.21662 ,SNR2: 1.1013




3C216 2024/07/07 4.98UT FUJI -KISO





T20240707140932




BLK:15,SNR1: 132.26 ,SNR2: 134.91




F20240707140934





BLK:15,SNR1: 35.180 ,SNR2: 34.840




0919-142 2024/07/07 5.19UT TOYOKAWA-FUJI





T20240707140932




BLK:18,SNR1: 130.44 ,SNR2: 132.39




K20240707140929





BLK:18,SNR1: 131.87 ,SNR2: 129.33




0919-142 2024/07/07 5.19UT TOYOKAWA-KISO





F20240707140934




BLK:10,SNR1: 12.677 ,SNR2: 21.168




K20240707140929





BLK:10,SNR1: 113.52 ,SNR2: 100.64




0919-142 2024/07/07 5.19UT FUJI -KISO





T20240707141611




BLK:19,SNR1: 23.389 ,SNR2: 43.671




F20240707141613





BLK:19,SNR1: 99.313 ,SNR2: 119.29




0926+117 2024/07/07 5.30UT TOYOKAWA-FUJI





T20240707141611




BLK:13,SNR1: 28.374 ,SNR2: 53.500




K20240707141608



BLK:13,SNR1: 0.14200 ,SNR2: 1.2030





0926+117 2024/07/07 5.30UT TOYOKAWA-KISO








F20240707141613




BLK:19,SNR1: 92.296 ,SNR2: 110.87




K20240707141608





BLK:19,SNR1: 0.26268 ,SNR2: 1.9851




0926+117 2024/07/07 5.30UT FUJI -KISO




T20240707142356




BLK: 7,SNR1: 0.24914 ,SNR2: 0.85778




F20240707142358





BLK: 7,SNR1: 6.4905 ,SNR2: 25.932




3C222 2024/07/07 5.43UT TOYOKAWA-FUJI




T20240707142356




BLK: 6,SNR1: 0.18875 ,SNR2: 0.85346




K20240707142353





BLK: 6,SNR1: 0.28342 ,SNR2: 0.92854




3C222 2024/07/07 5.43UT TOYOKAWA-KISO





F20240707142358




BLK: 4,SNR1: 8.7651 ,SNR2: 34.652




K20240707142353





BLK: 4,SNR1: 0.15766 ,SNR2: 2.2225




3C222 2024/07/07 5.43UT FUJI -KISO





T20240707143056




BLK: 8,SNR1: 0.10195 ,SNR2: 0.45659




F20240707143058





BLK: 8,SNR1: 0.34676 ,SNR2: 1.9760




0941-08 2024/07/07 5.54UT TOYOKAWA-FUJI





T20240707143056




BLK: 8,SNR1: 0.14070 ,SNR2: 0.49667




K20240707143053





BLK: 8,SNR1: 1.1455 ,SNR2: 6.3519




0941-08 2024/07/07 5.54UT TOYOKAWA-KISO



F20240707143058





BLK: 5,SNR1: 0.16989 ,SNR2: 1.8694




Frequency (Hz)

K20240707143053




BLK: 5,SNR1: 1.0382 ,SNR2: 4.5203





Frequency (Hz)


0941-08 2024/07/07 5.54UT FUJI -KISO




T20240707143918




BLK: 5,SNR1: 1.1229 ,SNR2: 8.3464




F20240707143920



BLK: 5,SNR1:-0.57161E-01,SNR2: 1.4245




3C230 2024/07/07 5.68UT TOYOKAWA-FUJI








T20240707143918




BLK: 6,SNR1: 0.88854 ,SNR2: 5.2091




K20240707143915





BLK: 6,SNR1: 0.50715 ,SNR2: 2.2347




3C230 2024/07/07 5.68UT TOYOKAWA-KISO



F20240707143920





BLK:10,SNR1: 0.53491 ,SNR2: 2.8209




Frequency (Hz)

K20240707143915




BLK:10,SNR1: 1.0481 ,SNR2: 4.3344





Frequency (Hz)


3C230 2024/07/07 5.68UT FUJI -KISO





T20240707145519




BLK:11,SNR1: 0.30804 ,SNR2: 0.77240




F20240707145521





BLK:11,SNR1:-0.21449 ,SNR2: 0.58880




3C237 2024/07/07 5.95UT TOYOKAWA-FUJI





T20240707145519




BLK: 9,SNR1: 0.24956 ,SNR2: 1.2219




K20240707145516





BLK: 9,SNR1: 0.57934 ,SNR2: 4.6927




3C237 2024/07/07 5.95UT TOYOKAWA-KISO





F20240707145521




BLK: 7,SNR1: 0.11807 ,SNR2: 3.6014




K20240707145516





BLK: 7,SNR1: 0.71552 ,SNR2: 5.7736




3C237 2024/07/07 5.95UT FUJI -KISO




T20240707150135




BLK: 5,SNR1: 0.16458 ,SNR2: 1.2414




F20240707150137





BLK: 5,SNR1: 0.20079 ,SNR2: 4.9215




1011+110 2024/07/07 6.05UT TOYOKAWA-FUJI





T20240707150135




BLK: 4,SNR1: 0.28120 ,SNR2: 2.8218




K20240707150132




BLK: 4,SNR1: 0.44580 ,SNR2: 2.1135




1011+110 2024/07/07 6.05UT TOYOKAWA-KISO




F20240707150137




BLK: 4,SNR1: 0.28461E-01,SNR2: 2.6715




K20240707150132



BLK: 4,SNR1: 0.80991 ,SNR2: 5.8385





1011+110 2024/07/07 6.05UT FUJI -KISO






T20240707150916





BLK: 7,SNR1: 0.21824 ,SNR2: 3.1489




Frequency (Hz)

F20240707150918




BLK: 7,SNR1: 0.10429E-01,SNR2: 1.3554




Frequency (Hz)


3C241 2024/07/07 6.18UT TOYOKAWA-FUJI



T20240707150916





BLK: 6,SNR1: 0.23924 ,SNR2: 3.8855




Frequency (Hz)

K20240707150913




BLK: 6,SNR1: 0.27257 ,SNR2: 0.71121





Frequency (Hz)


3C241 2024/07/07 6.18UT TOYOKAWA-KISO



F20240707150918





BLK: 4,SNR1: 0.39959 ,SNR2: 2.6598




Frequency (Hz)

K20240707150913




BLK: 4,SNR1: 0.12493 ,SNR2: 2.2140





Frequency (Hz)


3C241 2024/07/07 6.18UT FUJI -KISO



T20240707152045





BLK: 2,SNR1: 0.12140 ,SNR2: 1.6091




Frequency (Hz)

F20240707152047




BLK: 2,SNR1:-0.14583 ,SNR2: 0.55921





Frequency (Hz)


1031-11 2024/07/07 6.37UT TOYOKAWA-FUJI



T20240707152045





BLK: 2,SNR1: 0.55367E-01,SNR2: 2.6804




Frequency (Hz)

K20240707152042




BLK: 2,SNR1: 0.81810 ,SNR2: 7.1342




Frequency (Hz)


1031-11 2024/07/07 6.37UT TOYOKAWA-KISO





F20240707152047




BLK: 2,SNR1:-0.33214 ,SNR2: 0.11393E-01




K20240707152042





BLK: 2,SNR1: 2.6163 ,SNR2: 17.382




1031-11 2024/07/07 6.37UT FUJI -KISO



T20240707152519





BLK: 5,SNR1: 0.15639 ,SNR2: 0.61409




Frequency (Hz)

F20240707152521




BLK: 5,SNR1:-0.10700 ,SNR2: 1.8030





Frequency (Hz)


1035-058 2024/07/07 6.45UT TOYOKAWA-FUJI



T20240707152519





BLK: 3,SNR1: 0.95980E-01,SNR2: 1.3921




Frequency (Hz)

K20240707152516




BLK: 3,SNR1: 1.3564 ,SNR2: 8.4821




Frequency (Hz)

1035-058 2024/07/07 6.45UT TOYOKAWA-KISO






F20240707152521





BLK: 2,SNR1:-0.14120 ,SNR2: 1.7783




Frequency (Hz)

K20240707152516




BLK: 2,SNR1: 0.28672 ,SNR2: 0.71425





Frequency (Hz)


1035-058 2024/07/07 6.45UT FUJI -KISO




T20240707153431




BLK: 3,SNR1: 0.67952E-01,SNR2: 0.28201




F20240707153433





BLK: 3,SNR1:-0.65524E-01,SNR2: 0.75644




1044-008 2024/07/07 6.60UT TOYOKAWA-FUJI





T20240707153431




BLK: 5,SNR1: 0.72432E-01,SNR2: 0.25506




K20240707153429




BLK: 5,SNR1: 1.1726 ,SNR2: 5.6414




1044-008 2024/07/07 6.60UT TOYOKAWA-KISO





F20240707153433




BLK: 4,SNR1:-0.17056 ,SNR2: 1.1610




K20240707153429





BLK: 4,SNR1: 0.17795 ,SNR2: 0.68941




1044-008 2024/07/07 6.60UT FUJI -KISO



T20240707154536





BLK: 1,SNR1: 0.32313 ,SNR2: 1.7411




Frequency (Hz)

F20240707154538




BLK: 1,SNR1:-0.45214 ,SNR2: 0.33150





Frequency (Hz)


1055+01 2024/07/07 6.79UT TOYOKAWA-FUJI





T20240707154536




BLK: 5,SNR1: 1.7141 ,SNR2: 7.6052




K20240707154533




BLK: 5,SNR1: 0.55662 ,SNR2: 2.5634




1055+01 2024/07/07 6.79UT TOYOKAWA-KISO





F20240707154538




BLK: 4,SNR1:-0.23640 ,SNR2: 0.0000




K20240707154533





BLK: 4,SNR1: 0.50937 ,SNR2: 1.7586




1055+01 2024/07/07 6.79UT FUJI -KISO



T20240707155653




BLK: 4,SNR1: 0.16578E-01,SNR2: 0.90206




Frequency (Hz)

F20240707155655




BLK: 4,SNR1: 0.29591 ,SNR2: 1.5528





Frequency (Hz)

1107+109 2024/07/07 6.98UT TOYOKAWA-FUJI






T20240707155653





BLK: 2,SNR1: 0.91897E-01,SNR2: 0.56616




Frequency (Hz)

K20240707155650




BLK: 2,SNR1: 2.5717 ,SNR2: 10.461




Frequency (Hz)


1107+109 2024/07/07 6.98UT TOYOKAWA-KISO



F20240707155655





BLK: 5,SNR1: 0.87604E-01,SNR2: 2.5748




Frequency (Hz)

K20240707155650




BLK: 5,SNR1: 0.21152 ,SNR2: 0.82455





Frequency (Hz)


1107+109 2024/07/07 6.98UT FUJI -KISO




T20240707160631




BLK: 4,SNR1: 0.69374E-01,SNR2: 0.55431




F20240707160633





BLK: 4,SNR1:-0.22045 ,SNR2: 0.0000




3C255 2024/07/07 7.14UT TOYOKAWA-FUJI





T20240707160631




BLK: 2,SNR1: 0.18126 ,SNR2: 0.72629




K20240707160628




BLK: 2,SNR1: 0.63482 ,SNR2: 5.4040




3C255 2024/07/07 7.14UT TOYOKAWA-KISO



F20240707160633




BLK: 4,SNR1:-0.29782E-02,SNR2: 1.3407




Frequency (Hz)

K20240707160628




BLK: 4,SNR1: 1.3564 ,SNR2: 7.7182





Frequency (Hz)


3C255 2024/07/07 7.14UT FUJI -KISO




T20240707161708




BLK: 4,SNR1:-0.69645E-01,SNR2: 1.5260




F20240707161710




BLK: 4,SNR1: 5.3518 ,SNR2: 21.753




1127-14 2024/07/07 7.31UT TOYOKAWA-FUJI





T20240707161708




BLK: 2,SNR1:-0.54861E-01,SNR2: 0.54473




K20240707161705





BLK: 2,SNR1: 0.52545 ,SNR2: 4.9386




1127-14 2024/07/07 7.31UT TOYOKAWA-KISO



F20240707161710





BLK: 8,SNR1: 18.881 ,SNR2: 35.934




Frequency (Hz)

K20240707161705




BLK: 8,SNR1: 11.713 ,SNR2: 33.989





Frequency (Hz)

1127-14 2024/07/07 7.31UT FUJI -KISO






T20240707163029




BLK: 1,SNR1: 0.43951 ,SNR2: 0.79220




Frequency (Hz)

F20240707163031




BLK: 1,SNR1: 0.27075 ,SNR2: 2.9103





Frequency (Hz)


3C263.1 2024/07/07 7.54UT TOYOKAWA-FUJI





T20240707163029




BLK: 5,SNR1: 0.86481E-01,SNR2: 0.99478




K20240707163026





BLK: 5,SNR1: 0.32338 ,SNR2: 1.4605




3C263.1 2024/07/07 7.54UT TOYOKAWA-KISO



F20240707163031





BLK: 3,SNR1:-0.23480 ,SNR2: 0.0000




Frequency (Hz)

K20240707163026




BLK: 3,SNR1: 1.4039 ,SNR2: 7.2829





Frequency (Hz)


3C263.1 2024/07/07 7.54UT FUJI -KISO



T20240707163656




BLK: 3,SNR1: 0.82721E-02,SNR2: 1.4008




Frequency (Hz)

F20240707163658




BLK: 3,SNR1: 0.83103 ,SNR2: 5.8753





Frequency (Hz)


3C267 2024/07/07 7.64UT TOYOKAWA-FUJI





T20240707163656




BLK: 4,SNR1: 0.32960 ,SNR2: 0.85305




K20240707163653





BLK: 4,SNR1: 0.40284 ,SNR2: 1.3840




3C267 2024/07/07 7.64UT TOYOKAWA-KISO



F20240707163658





BLK: 7,SNR1: 1.1102 ,SNR2: 5.1670




Frequency (Hz)

K20240707163653




BLK: 7,SNR1: 0.49614 ,SNR2: 3.5600





Frequency (Hz)


3C267 2024/07/07 7.64UT FUJI -KISO



T20240707165610




BLK: 7,SNR1: 0.44976E-01,SNR2: 0.71705




Frequency (Hz)

F20240707165612




BLK: 7,SNR1: 0.13084 ,SNR2: 1.3417





Frequency (Hz)


1206+439 2024/07/07 7.96UT TOYOKAWA-FUJI



T20240707165610





BLK: 8,SNR1: 0.14725 ,SNR2: 0.52517




Frequency (Hz)

K20240707165607




BLK: 8,SNR1: 1.5811 ,SNR2: 6.5504




Frequency (Hz)

1206+439 2024/07/07 7.96UT TOYOKAWA-KISO






F20240707165612





BLK: 8,SNR1: 0.98614E-01,SNR2: 1.1602




Frequency (Hz)

K20240707165607




BLK: 8,SNR1: 5.1880 ,SNR2: 13.462





Frequency (Hz)


1206+439 2024/07/07 7.96UT FUJI -KISO



T20240707180248





BLK:13,SNR1: 0.25959 ,SNR2: 1.3716




Frequency (Hz)

F20240707180250




BLK:13,SNR1: 1.9352 ,SNR2: 5.0742





Frequency (Hz)


1313+453 2024/07/07 9.07UT TOYOKAWA-FUJI



T20240707180248





BLK: 7,SNR1: 0.16428 ,SNR2: 1.0232




Frequency (Hz)

K20240707180245




BLK: 7,SNR1: 1.7902 ,SNR2: 9.7714





Frequency (Hz)


1313+453 2024/07/07 9.07UT TOYOKAWA-KISO



F20240707180250





BLK:15,SNR1: 1.4462 ,SNR2: 5.0306




Frequency (Hz)

K20240707180245



BLK:15,SNR1: 2.9054 ,SNR2: 11.482



Frequency (Hz)

1313+453 2024/07/07 9.07UT FUJI -KISO

