




T20240708055142





BLK: 3,SNR1:-0.45384E-01,SNR2: 0.30254




Frequency (Hz)

F20240708055144




BLK: 3,SNR1: 0.30670 ,SNR2: 1.7882





Frequency (Hz)


0103+422 2024/07/07 20.89UT TOYOKAWA-FUJI



T20240708055142





BLK: 3,SNR1: 0.81157E-01,SNR2: 2.4907




Frequency (Hz)

K20240708055139




BLK: 3,SNR1: 0.63168 ,SNR2: 3.9161




Frequency (Hz)

0103+422 2024/07/07 20.89UT TOYOKAWA-KISO






F20240708055144




BLK: 5,SNR1: 0.32951E-01,SNR2: 1.3802




Frequency (Hz)

K20240708055139




BLK: 5,SNR1: 0.15379 ,SNR2: 0.80257




Frequency (Hz)


0103+422 2024/07/07 20.89UT FUJI -KISO



T20240708060429





BLK: 3,SNR1:-0.31315E-01,SNR2: 0.43874




Frequency (Hz)

F20240708060431




BLK: 3,SNR1: 0.16527 ,SNR2: 1.7392





Frequency (Hz)


0116+31 2024/07/07 21.10UT TOYOKAWA-FUJI





T20240708060429




No.Good Data




K20240708060426





No.Good Data




0116+31 2024/07/07 21.10UT TOYOKAWA-KISO



F20240708060431





BLK: 6,SNR1: 0.43044 ,SNR2: 2.8558




Frequency (Hz)

K20240708060426




BLK: 6,SNR1: 0.48339 ,SNR2: 2.1976




Frequency (Hz)


0116+31 2024/07/07 21.10UT FUJI -KISO



T20240708062236





BLK:16,SNR1: 0.65957 ,SNR2: 4.7483




Frequency (Hz)

3C48 2024/07/07 21.40UT TOYOKAWA-FUJI


F20240708062238





BLK:16,SNR1: 0.23796 ,SNR2: 1.9505




Frequency (Hz)



T20240708062236





BLK:14,SNR1: 0.84456 ,SNR2: 5.6570




Frequency (Hz)

K20240708062233




BLK:14,SNR1: 0.62846 ,SNR2: 2.5209





Frequency (Hz)


3C48 2024/07/07 21.40UT TOYOKAWA-KISO



F20240708062238




BLK:19,SNR1: 2.4802 ,SNR2: 3.6959




Frequency (Hz)

3C48 2024/07/07 21.40UT FUJI -KISO


K20240708062233





BLK:19,SNR1: 2.4069 ,SNR2: 11.065




Frequency (Hz)



T20240708063619





BLK: 6,SNR1: 0.26199E-01,SNR2: 0.70854




Frequency (Hz)

F20240708063621




BLK: 6,SNR1: 2.1173 ,SNR2: 6.4367




Frequency (Hz)

0148+274 2024/07/07 21.63UT TOYOKAWA-FUJI






T20240708063619





BLK: 7,SNR1: 0.19066E-01,SNR2: 0.29200




Frequency (Hz)

K20240708063616




BLK: 7,SNR1: 0.69143 ,SNR2: 3.8687





Frequency (Hz)


0148+274 2024/07/07 21.63UT TOYOKAWA-KISO



F20240708063621




BLK: 7,SNR1: 0.64646 ,SNR2: 5.5680




Frequency (Hz)

K20240708063616




BLK: 7,SNR1: 0.57158 ,SNR2: 2.6949





Frequency (Hz)


0148+274 2024/07/07 21.63UT FUJI -KISO



T20240708064927





BLK: 3,SNR1: 0.68382 ,SNR2: 13.859




Frequency (Hz)

F20240708064929




BLK: 3,SNR1:-0.35079 ,SNR2: 0.21459




Frequency (Hz)


0202+15 2024/07/07 21.85UT TOYOKAWA-FUJI



T20240708064927





BLK: 5,SNR1: 0.21647 ,SNR2: 0.66920




Frequency (Hz)

K20240708064924




BLK: 5,SNR1: 9.5336 ,SNR2: 49.820




Frequency (Hz)


0202+15 2024/07/07 21.85UT TOYOKAWA-KISO



F20240708064929





BLK: 1,SNR1:-0.26763 ,SNR2: 0.47604




Frequency (Hz)

K20240708064924




BLK: 1,SNR1: 0.43297 ,SNR2: 0.58112





Frequency (Hz)


0202+15 2024/07/07 21.85UT FUJI -KISO



T20240708070118





BLK: 4,SNR1: 0.55992E-01,SNR2: 2.5408




Frequency (Hz)

F20240708070120




BLK: 4,SNR1:-0.59879E-01,SNR2: 1.1950





Frequency (Hz)


0213+178 2024/07/07 22.05UT TOYOKAWA-FUJI



T20240708070118





BLK: 2,SNR1: 0.76903E-01,SNR2: 0.0000




Frequency (Hz)

K20240708070115




BLK: 2,SNR1: 2.9481 ,SNR2: 8.9117




Frequency (Hz)


0213+178 2024/07/07 22.05UT TOYOKAWA-KISO



F20240708070120





BLK: 9,SNR1:-0.37248E-01,SNR2: 0.84581




Frequency (Hz)

K20240708070115




BLK: 9,SNR1: 0.70281 ,SNR2: 3.6866





Frequency (Hz)

0213+178 2024/07/07 22.05UT FUJI -KISO






T20240708070900



BLK:16,SNR1: 3.4227 ,SNR2: 15.006





Frequency (Hz)


3C67

2024/07/07 22.18UT TOYOKAWA-FUJI


F20240708070902





BLK:16,SNR1: 2.9023 ,SNR2: 7.9288




Frequency (Hz)



T20240708070900





BLK:15,SNR1: 3.5056 ,SNR2: 15.359




Frequency (Hz)

3C67 2024/07/07 22.18UT TOYOKAWA-KISO


K20240708070857





BLK:15,SNR1: 3.0205 ,SNR2: 13.481




Frequency (Hz)



F20240708070902





BLK:20,SNR1: 3.3235 ,SNR2: 14.403




Frequency (Hz)

3C67 2024/07/07 22.18UT FUJI -KISO


K20240708070857





BLK:20,SNR1: 3.0039 ,SNR2: 13.413




Frequency (Hz)



T20240708072715



BLK: 5,SNR1: 0.26407 ,SNR2: 2.9980




Frequency (Hz)


3C71

2024/07/07 22.48UT TOYOKAWA-FUJI


F20240708072717





BLK: 5,SNR1:-0.24147 ,SNR2: 0.81932




Frequency (Hz)



T20240708072715



BLK: 4,SNR1: 49.964 ,SNR2: 287.02





Frequency (Hz)


3C71

2024/07/07 22.48UT TOYOKAWA-KISO


K20240708072712




BLK: 4,SNR1: 0.16784 ,SNR2: 1.3532




Frequency (Hz)




F20240708072717




BLK: 5,SNR1: 0.28752 ,SNR2: 2.5816




K20240708072712





BLK: 5,SNR1: 0.37633 ,SNR2: 2.0544




3C71 2024/07/07 22.48UT FUJI -KISO



T20240708074630




BLK: 2,SNR1:-0.74288E-01,SNR2: 0.13083




Frequency (Hz)

F20240708074632




BLK: 2,SNR1: 0.36958E-01,SNR2: 0.95913





Frequency (Hz)


0258+350 2024/07/07 22.80UT TOYOKAWA-FUJI



T20240708074630




BLK: 2,SNR1:-0.25609E-01,SNR2: 0.18685




Frequency (Hz)

K20240708074627




BLK: 2,SNR1: 1.3698 ,SNR2: 13.182




Frequency (Hz)

0258+350 2024/07/07 22.80UT TOYOKAWA-KISO






F20240708074632




BLK: 7,SNR1: 1.0691 ,SNR2: 1.7846




Frequency (Hz)

K20240708074627




BLK: 7,SNR1: 0.38816 ,SNR2: 1.3816





Frequency (Hz)


0258+350 2024/07/07 22.80UT FUJI -KISO




T20240708075619




BLK: 5,SNR1: 0.13622 ,SNR2: 0.94227




F20240708075621





BLK: 5,SNR1: 0.77179 ,SNR2: 3.4810




0308+305 2024/07/07 22.97UT TOYOKAWA-FUJI





T20240708075619




BLK: 9,SNR1: 0.68432E-01,SNR2: 0.51205




K20240708075616




BLK: 9,SNR1: 0.65577 ,SNR2: 3.1090




0308+305 2024/07/07 22.97UT TOYOKAWA-KISO



F20240708075621





BLK:14,SNR1: 1.2733 ,SNR2: 4.8860




Frequency (Hz)

K20240708075616




BLK:14,SNR1: 1.3920 ,SNR2: 6.5802





Frequency (Hz)


0308+305 2024/07/07 22.97UT FUJI -KISO



T20240708080751





BLK:10,SNR1: 0.72018E-01,SNR2: 1.2452




Frequency (Hz)

F20240708080753




BLK:10,SNR1: 0.71591 ,SNR2: 2.3652




Frequency (Hz)


0320+05 2024/07/07 23.16UT TOYOKAWA-FUJI





T20240708080751




BLK: 7,SNR1: 0.95827E-01,SNR2: 1.7621




K20240708080748





BLK: 7,SNR1: 0.73262 ,SNR2: 3.2491




0320+05 2024/07/07 23.16UT TOYOKAWA-KISO



F20240708080753





BLK: 9,SNR1: 0.42089 ,SNR2: 2.4321




Frequency (Hz)

K20240708080748




BLK: 9,SNR1: 0.70189 ,SNR2: 3.0950





Frequency (Hz)


0320+05 2024/07/07 23.16UT FUJI -KISO





T20240708082112




BLK:11,SNR1: 0.21602 ,SNR2: 1.5115




F20240708082114



BLK:11,SNR1: 25.027 ,SNR2: 74.807





0333+32 2024/07/07 23.38UT TOYOKAWA-FUJI






T20240708082112





BLK: 4,SNR1: 0.50008 ,SNR2: 3.6771





0333+32 2024/07/07 23.38UT TOYOKAWA-KISO


K20240708082109




BLK: 4,SNR1: 0.78546 ,SNR2: 8.6691





F20240708082114




BLK:10,SNR1: 7.4124 ,SNR2: 33.857




K20240708082109





BLK:10,SNR1: 0.30296 ,SNR2: 2.3764




0333+32 2024/07/07 23.38UT FUJI -KISO



T20240708083414





BLK: 5,SNR1: 6.3820 ,SNR2: 17.130




Frequency (Hz)

F20240708083416




BLK: 5,SNR1: 3.0473 ,SNR2: 10.615




Frequency (Hz)


0347+05 2024/07/07 23.60UT TOYOKAWA-FUJI



T20240708083414





BLK: 4,SNR1: 7.2802 ,SNR2: 19.720





0347+05 2024/07/07 23.60UT TOYOKAWA-KISO


K20240708083411




BLK: 4,SNR1: 0.65632 ,SNR2: 2.2879



F20240708083416





BLK: 4,SNR1: 0.78287 ,SNR2: 6.3398




Frequency (Hz)

K20240708083411




BLK: 4,SNR1: 0.39701 ,SNR2: 3.2388





Frequency (Hz)


0347+05 2024/07/07 23.60UT FUJI -KISO



T20240708084948





BLK:19,SNR1: 3.0700 ,SNR2: 7.6145




Frequency (Hz)

F20240708084950




BLK:19,SNR1: 4.4536 ,SNR2: 10.096





Frequency (Hz)


0403-132 2024/07/07 23.86UT TOYOKAWA-FUJI



T20240708084948





BLK:20,SNR1: 6.1333 ,SNR2: 14.911




Frequency (Hz)

K20240708084945




BLK:20,SNR1: 6.6427 ,SNR2: 13.065




Frequency (Hz)


0403-132 2024/07/07 23.86UT TOYOKAWA-KISO



F20240708084950




BLK:25,SNR1: 4.9349 ,SNR2: 12.409




Frequency (Hz)

K20240708084945




BLK:25,SNR1: 3.9464 ,SNR2: 7.8388




Frequency (Hz)

0403-132 2024/07/07 23.86UT FUJI -KISO






T20240708090553





BLK: 1,SNR1:-0.15075 ,SNR2: 1.9355




Frequency (Hz)

F20240708090555




BLK: 1,SNR1: 0.68062 ,SNR2: 3.3488




Frequency (Hz)


0418+236 2024/07/08 0.13UT TOYOKAWA-FUJI



T20240708090553





BLK: 4,SNR1: 0.67572 ,SNR2: 1.9898




Frequency (Hz)

K20240708090550




BLK: 4,SNR1: 0.47112 ,SNR2: 5.0546




Frequency (Hz)


0418+236 2024/07/08 0.13UT TOYOKAWA-KISO





F20240708090555




No.Good Data




K20240708090550





No.Good Data




0418+236 2024/07/08 0.13UT FUJI -KISO



T20240708091720





BLK:10,SNR1: 0.43719 ,SNR2: 5.7716





3C119 2024/07/08 0.32UT TOYOKAWA-FUJI



F20240708091722




BLK:10,SNR1: 58.466 ,SNR2: 132.20



T20240708091720





BLK:21,SNR1: 0.53937 ,SNR2: 2.4449





3C119 2024/07/08 0.32UT TOYOKAWA-KISO



K20240708091717




BLK:21,SNR1: 1.9357 ,SNR2: 7.6443



F20240708091722





BLK: 5,SNR1: 0.18756 ,SNR2: 0.90495




Frequency (Hz)

3C119 2024/07/08 0.32UT FUJI -KISO


K20240708091717




BLK: 5,SNR1: 2.7474 ,SNR2: 10.990




Frequency (Hz)





T20240708100528




BLK:21,SNR1: 1.8614 ,SNR2: 4.4880




F20240708100530




BLK:21,SNR1: 0.31028E-01,SNR2: 1.3319




3C138 2024/07/08 1.12UT TOYOKAWA-FUJI





T20240708100528




BLK:27,SNR1: 1.6253 ,SNR2: 4.9679




K20240708100525



BLK:27,SNR1: 0.76847 ,SNR2: 3.4232





3C138 2024/07/08 1.12UT TOYOKAWA-KISO






F20240708100530





BLK:14,SNR1: 1.2857 ,SNR2: 4.8795




Frequency (Hz)

3C138 2024/07/08 1.12UT FUJI -KISO


K20240708100525




BLK:14,SNR1: 2.3442 ,SNR2: 9.0777




Frequency (Hz)



T20240708101901





BLK:21,SNR1: 2.1124 ,SNR2: 5.1743




Frequency (Hz)

F20240708101903




BLK:21,SNR1: 1.0569 ,SNR2: 4.5134




Frequency (Hz)


0531+194 2024/07/08 1.35UT TOYOKAWA-FUJI



T20240708101901




BLK:31,SNR1: 2.2866 ,SNR2: 5.8132




Frequency (Hz)

K20240708101858




BLK:31,SNR1: 6.9785 ,SNR2: 17.658





Frequency (Hz)


0531+194 2024/07/08 1.35UT TOYOKAWA-KISO





F20240708101903




BLK:24,SNR1: 2.5199 ,SNR2: 8.9104




K20240708101858




BLK:24,SNR1: 7.0392 ,SNR2: 17.809




0531+194 2024/07/08 1.35UT FUJI -KISO



T20240708102720




BLK:27,SNR1: 11.743 ,SNR2: 45.752





3C147 2024/07/08 1.48UT TOYOKAWA-FUJI


F20240708102722




BLK:27,SNR1: 0.59889 ,SNR2: 7.2608



T20240708102720





BLK:36,SNR1: 12.568 ,SNR2: 48.739





3C147 2024/07/08 1.48UT TOYOKAWA-KISO


K20240708102717




BLK:36,SNR1: 3.4626 ,SNR2: 14.346



F20240708102722





BLK:32,SNR1: 1.0709 ,SNR2: 3.8076




Frequency (Hz)

3C147 2024/07/08 1.48UT FUJI -KISO


K20240708102717





BLK:32,SNR1: 4.0324 ,SNR2: 16.703




Frequency (Hz)



T20240708103532




BLK:15,SNR1: 2.0447 ,SNR2: 5.2826





0548+16 2024/07/08 1.62UT TOYOKAWA-FUJI

F20240708103534





BLK:15,SNR1: 1.9467 ,SNR2: 8.7938






T20240708103532





BLK:24,SNR1: 2.6900 ,SNR2: 12.084





0548+16 2024/07/08 1.62UT TOYOKAWA-KISO


K20240708103529




BLK:24,SNR1: 0.95676 ,SNR2: 3.6568





F20240708103534




BLK:14,SNR1: 10.153 ,SNR2: 16.145




K20240708103529





BLK:14,SNR1: 1.0346 ,SNR2: 4.0011




0548+16 2024/07/08 1.62UT FUJI -KISO



T20240708103943





BLK:16,SNR1: 0.66528 ,SNR2: 2.6256





0552+12 2024/07/08 1.69UT TOYOKAWA-FUJI



F20240708103945




BLK:16,SNR1: 3.3817 ,SNR2: 14.290



T20240708103943





BLK:19,SNR1: 0.66699 ,SNR2: 2.8089





0552+12 2024/07/08 1.69UT TOYOKAWA-KISO


K20240708103940




BLK:19,SNR1: 0.68856 ,SNR2: 2.9029





F20240708103945




BLK:15,SNR1: 6.5382 ,SNR2: 14.406




K20240708103940





BLK:15,SNR1: 0.77024 ,SNR2: 3.2255




0552+12 2024/07/08 1.69UT FUJI -KISO



T20240708104410





BLK:10,SNR1: 4.2692 ,SNR2: 11.772




Frequency (Hz)

F20240708104412




BLK:10,SNR1: 0.20329 ,SNR2: 2.3160





Frequency (Hz)


0556+191 2024/07/08 1.76UT TOYOKAWA-FUJI



T20240708104410





BLK:23,SNR1: 4.3062 ,SNR2: 11.842





0556+191 2024/07/08 1.76UT TOYOKAWA-KISO


K20240708104407




BLK:23,SNR1: 2.4296 ,SNR2: 9.6348




F20240708104412




BLK:10,SNR1: 0.14815 ,SNR2: 1.7069




K20240708104407



BLK:10,SNR1: 6.5301 ,SNR2: 12.742





0556+191 2024/07/08 1.76UT FUJI -KISO






T20240708105156




BLK:17,SNR1: 6.7163 ,SNR2: 16.136





0605-08 2024/07/08 1.89UT TOYOKAWA-FUJI


F20240708105158




BLK:17,SNR1: 1.2811 ,SNR2: 6.1791





T20240708105156




BLK:22,SNR1: 6.3626 ,SNR2: 15.306




K20240708105153




BLK:22,SNR1: 9.0309 ,SNR2: 21.194




0605-08 2024/07/08 1.89UT TOYOKAWA-KISO





F20240708105158




BLK:19,SNR1: 1.1487 ,SNR2: 5.6629




K20240708105153





BLK:19,SNR1: 7.8086 ,SNR2: 15.015




0605-08 2024/07/08 1.89UT FUJI -KISO



T20240708111103





BLK: 9,SNR1: 97.666 ,SNR2: 127.11




Frequency (Hz)

3C161 2024/07/08 2.21UT TOYOKAWA-FUJI


F20240708111105





BLK: 9,SNR1: 0.86682E-01,SNR2: 1.1824




Frequency (Hz)



T20240708111103





BLK:17,SNR1: 141.59 ,SNR2: 142.29




Frequency (Hz)

3C161 2024/07/08 2.21UT TOYOKAWA-KISO


K20240708111100





BLK:17,SNR1: 148.34 ,SNR2: 158.49




Frequency (Hz)



F20240708111105





BLK:12,SNR1:-0.26945E-01,SNR2: 2.1837




Frequency (Hz)

K20240708111100




BLK:12,SNR1: 135.06 ,SNR2: 151.46





Frequency (Hz)


3C161 2024/07/08 2.21UT FUJI -KISO



T20240708113836




BLK:23,SNR1: 84.809 ,SNR2: 82.382





0652-130 2024/07/08 2.67UT TOYOKAWA-FUJI



F20240708113838




BLK:23,SNR1: 6.0488 ,SNR2: 15.186



T20240708113836




BLK:30,SNR1: 75.224 ,SNR2: 73.775





0652-130 2024/07/08 2.67UT TOYOKAWA-KISO

K20240708113834





BLK:30,SNR1: 20.927 ,SNR2: 37.243







F20240708113838




BLK:27,SNR1: 5.6950 ,SNR2: 14.335




K20240708113834





BLK:27,SNR1: 20.766 ,SNR2: 36.645




0652-130 2024/07/08 2.67UT FUJI -KISO



T20240708115013





BLK:32,SNR1: 2.8846 ,SNR2: 13.691





0703+138 2024/07/08 2.87UT TOYOKAWA-FUJI


F20240708115015




BLK:32,SNR1: 14.022 ,SNR2: 24.707



T20240708115013





BLK:33,SNR1: 2.8437 ,SNR2: 13.528





0703+138 2024/07/08 2.87UT TOYOKAWA-KISO


K20240708115010




BLK:33,SNR1: 13.682 ,SNR2: 31.534



F20240708115015





BLK:27,SNR1: 14.240 ,SNR2: 25.036





0703+138 2024/07/08 2.87UT FUJI -KISO



K20240708115010




BLK:27,SNR1: 2.6132 ,SNR2: 12.630



T20240708115935




BLK:12,SNR1: 1.6283 ,SNR2: 5.8476




Frequency (Hz)

F20240708115937




BLK:12,SNR1: 2.2171 ,SNR2: 7.2339





Frequency (Hz)


0713-024 2024/07/08 3.02UT TOYOKAWA-FUJI



T20240708115935





BLK:15,SNR1: 41.618 ,SNR2: 95.422




Frequency (Hz)

K20240708115932




BLK:15,SNR1: 1.4812 ,SNR2: 5.8122




Frequency (Hz)


0713-024 2024/07/08 3.02UT TOYOKAWA-KISO





F20240708115937




BLK:16,SNR1: 1.7761 ,SNR2: 6.0047




K20240708115932





BLK:16,SNR1: 1.5499 ,SNR2: 6.1316




0713-024 2024/07/08 3.02UT FUJI -KISO




T20240708120947




BLK:23,SNR1: 68.851 ,SNR2: 75.970




F20240708120949



BLK:23,SNR1: 1.7128 ,SNR2: 4.1688





0723+10 2024/07/08 3.19UT TOYOKAWA-FUJI







T20240708120947




BLK:21,SNR1: 78.791 ,SNR2: 75.812




K20240708120944





BLK:21,SNR1: 0.85946 ,SNR2: 3.0282




0723+10 2024/07/08 3.19UT TOYOKAWA-KISO





F20240708120949




BLK:12,SNR1: 2.4850 ,SNR2: 4.7831




K20240708120944




BLK:12,SNR1: 0.70455 ,SNR2: 2.4529




0723+10 2024/07/08 3.19UT FUJI -KISO




T20240708122002




BLK:18,SNR1: 74.062 ,SNR2: 200.60




F20240708122004




BLK:18,SNR1: 0.99200E-01,SNR2: 2.4726




0732+33 2024/07/08 3.36UT TOYOKAWA-FUJI



T20240708122002




BLK:26,SNR1: 29.794 ,SNR2: 52.310





0732+33 2024/07/08 3.36UT TOYOKAWA-KISO


K20240708122000




BLK:26,SNR1: 0.32140 ,SNR2: 1.9242





F20240708122004




BLK:15,SNR1: 0.27247 ,SNR2: 1.6690




K20240708122000




BLK:15,SNR1: 0.56696 ,SNR2: 3.8464




0732+33 2024/07/08 3.36UT FUJI -KISO



T20240708122804




BLK:14,SNR1: 0.62456 ,SNR2: 6.7550





0741-06 2024/07/08 3.50UT TOYOKAWA-FUJI


F20240708122806




BLK:14,SNR1:-0.22817 ,SNR2: 0.47238




T20240708122804




BLK:24,SNR1: 0.78942 ,SNR2: 5.8014




K20240708122801




BLK:24,SNR1: 0.49928 ,SNR2: 3.0636




0741-06 2024/07/08 3.50UT TOYOKAWA-KISO



F20240708122806





BLK:11,SNR1:-0.17926 ,SNR2: 0.57033E-01





0741-06 2024/07/08 3.50UT FUJI -KISO

K20240708122801





BLK:11,SNR1: 0.72375 ,SNR2: 2.4796







T20240708123748




BLK:16,SNR1: 7.7306 ,SNR2: 18.898




F20240708123750





BLK:16,SNR1: 6.4545 ,SNR2: 15.954




0752-200 2024/07/08 3.66UT TOYOKAWA-FUJI



T20240708123748





BLK:16,SNR1: 7.4793 ,SNR2: 18.300





0752-200 2024/07/08 3.66UT TOYOKAWA-KISO


K20240708123745




BLK:16,SNR1: 2.7616 ,SNR2: 12.961



F20240708123750





BLK:23,SNR1: 5.3656 ,SNR2: 13.254





0752-200 2024/07/08 3.66UT FUJI -KISO



K20240708123745




BLK:23,SNR1: 2.8720 ,SNR2: 13.372





T20240708124523




BLK:12,SNR1: 1.1369 ,SNR2: 4.6713




F20240708124525





BLK:12,SNR1: 1.2052 ,SNR2: 6.0415




3C190 2024/07/08 3.78UT TOYOKAWA-FUJI





T20240708124523




BLK:23,SNR1: 1.0187 ,SNR2: 4.0159




K20240708124520




BLK:23,SNR1: 1.7386 ,SNR2: 6.7656




3C190 2024/07/08 3.78UT TOYOKAWA-KISO





F20240708124525




BLK:13,SNR1: 2.7994 ,SNR2: 7.2843




K20240708124520




BLK:13,SNR1: 2.2691 ,SNR2: 9.0548




3C190 2024/07/08 3.78UT FUJI -KISO




T20240708125747




BLK:14,SNR1: 0.59555 ,SNR2: 2.7450




F20240708125749





BLK:14,SNR1: 0.44759E-01,SNR2: 1.2222




3C196 2024/07/08 3.99UT TOYOKAWA-FUJI



T20240708125747





BLK:18,SNR1: 0.49916 ,SNR2: 2.3956





3C196 2024/07/08 3.99UT TOYOKAWA-KISO

K20240708125744




BLK:18,SNR1: 0.65861 ,SNR2: 2.3714






F20240708125749




BLK:17,SNR1: 0.31542 ,SNR2: 1.3961





3C196 2024/07/08 3.99UT FUJI -KISO


K20240708125744




BLK:17,SNR1: 1.1715 ,SNR2: 5.0923




T20240708130857




BLK:10,SNR1: 0.61305 ,SNR2: 1.5700




F20240708130859




BLK:10,SNR1: 0.44486 ,SNR2: 2.4362




0821+394 2024/07/08 4.18UT TOYOKAWA-FUJI





T20240708130857




BLK:21,SNR1: 0.30545 ,SNR2: 2.6576




K20240708130854




BLK:21,SNR1: 1.0407 ,SNR2: 4.0071




0821+394 2024/07/08 4.18UT TOYOKAWA-KISO





F20240708130859




BLK:12,SNR1: 0.39203 ,SNR2: 1.9664




K20240708130854




BLK:12,SNR1: 1.5877 ,SNR2: 6.0782




0821+394 2024/07/08 4.18UT FUJI -KISO




T20240708132037




BLK:15,SNR1: 2.3852 ,SNR2: 17.597




F20240708132039





BLK:15,SNR1: 1.2373 ,SNR2: 2.3493




0834-19 2024/07/08 4.37UT TOYOKAWA-FUJI





T20240708132037




BLK:11,SNR1: 0.45816 ,SNR2: 4.1995




K20240708132034




BLK:11,SNR1: 1.8392 ,SNR2: 7.1924




0834-19 2024/07/08 4.37UT TOYOKAWA-KISO





F20240708132039




BLK:17,SNR1: 0.87318 ,SNR2: 3.2561




K20240708132034





BLK:17,SNR1: 1.5419 ,SNR2: 6.1646




0834-19 2024/07/08 4.37UT FUJI -KISO





T20240708132543




BLK: 2,SNR1:-0.20772E-01,SNR2: 0.75277




F20240708132545



BLK: 2,SNR1: 0.99056 ,SNR2: 2.6749





0839-071 2024/07/08 4.46UT TOYOKAWA-FUJI








T20240708132543




BLK: 3,SNR1:-0.12395 ,SNR2: 0.40309




K20240708132540




BLK: 3,SNR1: 0.61502 ,SNR2: 4.2669




0839-071 2024/07/08 4.46UT TOYOKAWA-KISO





F20240708132545




BLK: 5,SNR1:-0.17640 ,SNR2: 0.56735




K20240708132540





BLK: 5,SNR1: 0.27517 ,SNR2: 1.0852




0839-071 2024/07/08 4.46UT FUJI -KISO




T20240708133644




BLK: 8,SNR1: 0.22117 ,SNR2: 0.80741




F20240708133646





BLK: 8,SNR1: 0.89578 ,SNR2: 3.6510




3C208 2024/07/08 4.64UT TOYOKAWA-FUJI





T20240708133644




BLK: 9,SNR1: 0.15758 ,SNR2: 1.8038




K20240708133641




BLK: 9,SNR1: 1.0133 ,SNR2: 4.5566




3C208 2024/07/08 4.64UT TOYOKAWA-KISO





F20240708133646




BLK: 4,SNR1: 0.42087 ,SNR2: 3.3627




K20240708133641





BLK: 4,SNR1: 0.54861 ,SNR2: 3.1852




3C208 2024/07/08 4.64UT FUJI -KISO




T20240708135325




BLK: 8,SNR1: 0.16776 ,SNR2: 1.4693




F20240708135327





BLK: 8,SNR1:-0.92843E-01,SNR2: 2.9275




3C216 2024/07/08 4.92UT TOYOKAWA-FUJI





T20240708135325




BLK: 9,SNR1: 0.17280 ,SNR2: 0.68692




K20240708135322





BLK: 9,SNR1: 1.1532 ,SNR2: 8.7077




3C216 2024/07/08 4.92UT TOYOKAWA-KISO



F20240708135327





BLK:11,SNR1:-0.20977 ,SNR2: 1.6910





3C216 2024/07/08 4.92UT FUJI -KISO

K20240708135322





BLK:11,SNR1: 0.49733 ,SNR2: 3.2414








T20240708140537




BLK: 7,SNR1: 0.16688 ,SNR2: 1.9674




F20240708140539





BLK: 7,SNR1: 0.62522 ,SNR2: 8.1576




0919-142 2024/07/08 5.12UT TOYOKAWA-FUJI





T20240708140537




BLK: 2,SNR1: 0.33404 ,SNR2: 2.8720




K20240708140534




BLK: 2,SNR1: 0.90746 ,SNR2: 5.0412




0919-142 2024/07/08 5.12UT TOYOKAWA-KISO





F20240708140539




BLK: 4,SNR1: 3.5298 ,SNR2: 11.552




K20240708140534





BLK: 4,SNR1: 0.63117 ,SNR2: 3.9768




0919-142 2024/07/08 5.12UT FUJI -KISO




T20240708141215




BLK: 3,SNR1: 0.15737 ,SNR2: 1.1826




F20240708141217





BLK: 3,SNR1: 0.13348 ,SNR2: 2.2247




0926+117 2024/07/08 5.23UT TOYOKAWA-FUJI





T20240708141215




BLK: 1,SNR1: 0.50041 ,SNR2: 1.4864




K20240708141212




BLK: 1,SNR1: 0.53641 ,SNR2: 4.5387




0926+117 2024/07/08 5.23UT TOYOKAWA-KISO




F20240708141217




BLK: 2,SNR1: 0.24411 ,SNR2: 2.6552




K20240708141212





BLK: 2,SNR1: 0.23659 ,SNR2: 0.81267E-02




0926+117 2024/07/08 5.23UT FUJI -KISO




T20240708142000




BLK: 7,SNR1: 0.20176 ,SNR2: 2.5921




F20240708142002





BLK: 7,SNR1:-0.23428E-01,SNR2: 1.7853




3C222 2024/07/08 5.36UT TOYOKAWA-FUJI





T20240708142000




BLK: 9,SNR1: 0.12501 ,SNR2: 2.3740




K20240708141957



BLK: 9,SNR1: 0.24227 ,SNR2: 0.66350




3C222 2024/07/08 5.36UT TOYOKAWA-KISO








F20240708142002




BLK:10,SNR1: 4.0731 ,SNR2: 10.046




K20240708141957





BLK:10,SNR1: 0.31680 ,SNR2: 1.7851




3C222 2024/07/08 5.36UT FUJI -KISO



T20240708142700





BLK: 6,SNR1: 0.93908E-01,SNR2: 0.54256




Frequency (Hz)

F20240708142702




BLK: 6,SNR1:-0.65815E-01,SNR2: 2.6142





Frequency (Hz)


0941-08 2024/07/08 5.48UT TOYOKAWA-FUJI





T20240708142700




BLK: 7,SNR1: 0.61044E-01,SNR2: 0.40285




K20240708142657





BLK: 7,SNR1: 1.2675 ,SNR2: 4.3644




0941-08 2024/07/08 5.48UT TOYOKAWA-KISO





F20240708142702




BLK: 6,SNR1:-0.80476E-01,SNR2: 1.1474




K20240708142657





BLK: 6,SNR1: 0.25870 ,SNR2: 1.0792




0941-08 2024/07/08 5.48UT FUJI -KISO





T20240708143522




BLK: 4,SNR1: 0.18895 ,SNR2: 0.74922




F20240708143524





BLK: 4,SNR1: 2.4400 ,SNR2: 16.711




3C230 2024/07/08 5.62UT TOYOKAWA-FUJI





T20240708143522




BLK: 9,SNR1: 0.12509 ,SNR2: 2.4764




K20240708143519





BLK: 9,SNR1: 0.76465 ,SNR2: 3.7866




3C230 2024/07/08 5.62UT TOYOKAWA-KISO





F20240708143524




BLK: 7,SNR1: 2.7366 ,SNR2: 19.660




K20240708143519





BLK: 7,SNR1: 0.30301 ,SNR2: 0.81318




3C230 2024/07/08 5.62UT FUJI -KISO





T20240708145123




BLK: 6,SNR1: 0.26970 ,SNR2: 3.2027




F20240708145125



BLK: 6,SNR1: 0.33584 ,SNR2: 1.0588





3C237 2024/07/08 5.88UT TOYOKAWA-FUJI








T20240708145123




BLK:13,SNR1: 0.23167 ,SNR2: 1.7629




K20240708145120





BLK:13,SNR1: 0.67492 ,SNR2: 2.7080




3C237 2024/07/08 5.88UT TOYOKAWA-KISO





F20240708145125




BLK:11,SNR1: 0.53033 ,SNR2: 2.0982




K20240708145120





BLK:11,SNR1: 0.78835 ,SNR2: 4.8826




3C237 2024/07/08 5.88UT FUJI -KISO




T20240708145739




BLK: 4,SNR1: 0.50639E-01,SNR2: 0.35291




F20240708145741





BLK: 4,SNR1: 0.30251 ,SNR2: 2.0056




1011+110 2024/07/08 5.99UT TOYOKAWA-FUJI





T20240708145739




BLK: 1,SNR1: 0.19444 ,SNR2: 0.22566E-01




K20240708145736




BLK: 1,SNR1: 1.6227 ,SNR2: 4.3482




1011+110 2024/07/08 5.99UT TOYOKAWA-KISO





F20240708145741




BLK: 2,SNR1: 0.69438 ,SNR2: 3.6379




K20240708145736





BLK: 2,SNR1: 0.20854 ,SNR2: 1.0867




1011+110 2024/07/08 5.99UT FUJI -KISO





T20240708150520




BLK: 4,SNR1: 0.80260E-01,SNR2: 0.99970




F20240708150522





BLK: 4,SNR1: 0.11238 ,SNR2: 3.0489




3C241 2024/07/08 6.12UT TOYOKAWA-FUJI





T20240708150520




BLK: 6,SNR1: 0.34454E-01,SNR2: 0.35918




K20240708150517





BLK: 6,SNR1: 0.42161 ,SNR2: 2.8884




3C241 2024/07/08 6.12UT TOYOKAWA-KISO





F20240708150522




BLK: 7,SNR1: 0.38846 ,SNR2: 5.2062




K20240708150517



BLK: 7,SNR1: 1.0497 ,SNR2: 6.1167





3C241 2024/07/08 6.12UT FUJI -KISO






T20240708151649





BLK: 2,SNR1: 0.17993E-01,SNR2: 1.8792




Frequency (Hz)

F20240708151651




BLK: 2,SNR1:-0.22467,SNR2: 0.52829





Frequency (Hz)


1031-11 2024/07/08 6.31UT TOYOKAWA-FUJI





T20240708151649




BLK: 6,SNR1:-0.29673E-01,SNR2: 0.48401




K20240708151646




BLK: 6,SNR1: 0.55602 ,SNR2: 1.8680




1031-11 2024/07/08 6.31UT TOYOKAWA-KISO



F20240708151651





BLK: 2,SNR1: 0.30228 ,SNR2: 1.4404




Frequency (Hz)

K20240708151646




BLK: 2,SNR1: 0.11852 ,SNR2: 1.0993





Frequency (Hz)


1031-11 2024/07/08 6.31UT FUJI -KISO



T20240708152123





BLK: 2,SNR1:-0.11556 ,SNR2: 0.44311




Frequency (Hz)

F20240708152125




BLK: 2,SNR1: 1.0463 ,SNR2: 4.1065





Frequency (Hz)


1035-058 2024/07/08 6.38UT TOYOKAWA-FUJI



T20240708152123





BLK: 2,SNR1: 0.78996E-01,SNR2: 0.41661




Frequency (Hz)

K20240708152120




BLK: 2,SNR1: 1.0401 ,SNR2: 7.2799





Frequency (Hz)


1035-058 2024/07/08 6.38UT TOYOKAWA-KISO



F20240708152125




BLK: 1,SNR1:-0.50857E-01,SNR2: 0.64434




Frequency (Hz)

K20240708152120




BLK: 1,SNR1: 4.4727 ,SNR2: 19.938





Frequency (Hz)


1035-058 2024/07/08 6.38UT FUJI -KISO



T20240708153035





BLK: 1,SNR1: 0.30504 ,SNR2: 1.0954




Frequency (Hz)

F20240708153037




BLK: 1,SNR1: 1.4884 ,SNR2: 7.2886





Frequency (Hz)


1044-008 2024/07/08 6.54UT TOYOKAWA-FUJI





T20240708153035




BLK: 2,SNR1: 0.12142 ,SNR2: 0.62484




K20240708153032







BLK: 2,SNR1: 3.1552 ,SNR2: 13.868




1044-008 2024/07/08 6.54UT TOYOKAWA-KISO










1044-008 2024/07/08 6.54UT FUJI -KISO



T20240708154140





BLK: 3,SNR1: 0.14613 ,SNR2: 1.5459




Frequency (Hz)

F20240708154142




BLK: 3,SNR1: 0.42911E-01,SNR2: 1.0827





Frequency (Hz)


1055+01 2024/07/08 6.72UT TOYOKAWA-FUJI





T20240708154140




BLK: 6,SNR1: 0.15491 ,SNR2: 0.54103




K20240708154137





BLK: 6,SNR1: 16.907 ,SNR2: 33.286




1055+01 2024/07/08 6.72UT TOYOKAWA-KISO



F20240708154142





BLK: 5,SNR1:-0.77562E-01,SNR2: 1.4915




Frequency (Hz)

K20240708154137




BLK: 5,SNR1: 10.003 ,SNR2: 32.379





Frequency (Hz)


1055+01 2024/07/08 6.72UT FUJI -KISO





T20240708155257




BLK: 2,SNR1: 1.0862 ,SNR2: 5.6406




F20240708155259




BLK: 2,SNR1: 0.84138 ,SNR2: 4.7139




1107+109 2024/07/08 6.91UT TOYOKAWA-FUJI





T20240708155257




BLK: 5,SNR1: 9.6731 ,SNR2: 29.293




K20240708155254





BLK: 5,SNR1: 0.60224 ,SNR2: 2.6060




1107+109 2024/07/08 6.91UT TOYOKAWA-KISO





F20240708155259




BLK: 5,SNR1: 0.26235 ,SNR2: 3.5978




K20240708155254





BLK: 5,SNR1: 0.10220 ,SNR2: 0.32090




1107+109 2024/07/08 6.91UT FUJI -KISO




T20240708160235




BLK: 3,SNR1: 0.88223E-01,SNR2: 1.3324




F20240708160237



BLK: 3,SNR1:-0.44124E-01,SNR2: 2.1774





3C255 2024/07/08 7.07UT TOYOKAWA-FUJI







T20240708160235




BLK: 6,SNR1: 0.20027 ,SNR2: 0.89443




K20240708160232




BLK: 6,SNR1: 28.285 ,SNR2: 42.294





3C255 2024/07/08 7.07UT TOYOKAWA-KISO







BLK: 8,SNR1:-0.74556E-01,SNR2: 1.0850





BLK: 8,SNR1: 7.2217 ,SNR2: 25.828




3C255 2024/07/08 7.07UT FUJI -KISO




T20240708161312




BLK: 6,SNR1: 0.12062 ,SNR2: 1.9204




F20240708161314





BLK: 6,SNR1: 58.757 ,SNR2: 67.369




1127-14 2024/07/08 7.25UT TOYOKAWA-FUJI





T20240708161312




BLK:12,SNR1: 0.63028E-01,SNR2: 0.94849




K20240708161309




BLK:12,SNR1: 0.84317 ,SNR2: 4.8253




1127-14 2024/07/08 7.25UT TOYOKAWA-KISO



F20240708161314





BLK: 6,SNR1: 20.822 ,SNR2: 39.344




Frequency (Hz)

K20240708161309




BLK: 6,SNR1: 1.0945 ,SNR2: 7.2481





Frequency (Hz)


1127-14 2024/07/08 7.25UT FUJI -KISO



T20240708162633





BLK: 4,SNR1:-0.13517E-01,SNR2: 1.0093




Frequency (Hz)

F20240708162635




BLK: 4,SNR1: 0.75179 ,SNR2: 2.4345




Frequency (Hz)


3C263.1 2024/07/08 7.47UT TOYOKAWA-FUJI





T20240708162633




BLK: 3,SNR1: 0.54222E-01,SNR2: 0.28138




K20240708162630





BLK: 3,SNR1: 2.0951 ,SNR2: 13.144




3C263.1 2024/07/08 7.47UT TOYOKAWA-KISO



F20240708162635





BLK: 3,SNR1: 2.8425 ,SNR2: 7.0575




Frequency (Hz)

K20240708162630




BLK: 3,SNR1: 0.71709E-01,SNR2: 1.9849





Frequency (Hz)

3C263.1 2024/07/08 7.47UT FUJI -KISO






T20240708163300





BLK: 3,SNR1: 0.18932 ,SNR2: 0.51348




Frequency (Hz)

F20240708163302




BLK: 3,SNR1:-0.24776 ,SNR2: 0.52910





Frequency (Hz)


3C267 2024/07/08 7.58UT TOYOKAWA-FUJI



T20240708163300





BLK: 3,SNR1: 0.24619 ,SNR2: 0.54683




Frequency (Hz)

K20240708163257




BLK: 3,SNR1: 0.33215 ,SNR2: 1.5093





Frequency (Hz)


3C267 2024/07/08 7.58UT TOYOKAWA-KISO



F20240708163302





BLK: 6,SNR1:-0.26351 ,SNR2: 1.7955




Frequency (Hz)

K20240708163257




BLK: 6,SNR1: 0.81821 ,SNR2: 4.0090





Frequency (Hz)


3C267 2024/07/08 7.58UT FUJI -KISO



T20240708165214





BLK: 3,SNR1: 0.88185 ,SNR2: 6.2463




Frequency (Hz)

F20240708165216




BLK: 3,SNR1:-0.44441 ,SNR2: 0.89826





Frequency (Hz)


1206+439 2024/07/08 7.90UT TOYOKAWA-FUJI



T20240708165214





BLK: 4,SNR1: 0.49557 ,SNR2: 2.8547




Frequency (Hz)

K20240708165212




BLK: 4,SNR1: 0.53803 ,SNR2: 6.5558




Frequency (Hz)


1206+439 2024/07/08 7.90UT TOYOKAWA-KISO





F20240708165216




BLK: 2,SNR1: 1.6024 ,SNR2: 4.3646




K20240708165212





BLK: 2,SNR1: 0.17542E-01,SNR2: 0.81793




1206+439 2024/07/08 7.90UT FUJI -KISO



T20240708175852





BLK: 4,SNR1: 0.15337 ,SNR2: 0.55521




Frequency (Hz)

F20240708175854




BLK: 4,SNR1: 0.23092E-01,SNR2: 0.68675





Frequency (Hz)


1313+453 2024/07/08 9.01UT TOYOKAWA-FUJI



T20240708175852





BLK: 5,SNR1:-0.46530E-02,SNR2: 0.15730




Frequency (Hz)

K20240708175849




BLK: 5,SNR1: 1.8049 ,SNR2: 5.6921




Frequency (Hz)

1313+453 2024/07/08 9.01UT TOYOKAWA-KISO








F20240708175854




BLK: 5,SNR1: 0.10173E-01,SNR2: 0.73875




K20240708175849





BLK: 5,SNR1: 0.51597 ,SNR2: 5.2557




1313+453 2024/07/08 9.01UT FUJI -KISO



T20240708182011




BLK: 4,SNR1: 0.60076 ,SNR2: 2.9381




Frequency (Hz)

F20240708182013




BLK: 4,SNR1: 1.3610 ,SNR2: 11.371





Frequency (Hz)


1335+479 2024/07/08 9.36UT TOYOKAWA-FUJI



T20240708182011




BLK: 5,SNR1: 0.37177 ,SNR2: 3.6447




Frequency (Hz)

K20240708182009




BLK: 5,SNR1: 1.6423 ,SNR2: 5.8184




Frequency (Hz)


1335+479 2024/07/08 9.36UT TOYOKAWA-KISO



F20240708182013





BLK: 6,SNR1: 0.72410 ,SNR2: 6.8883




Frequency (Hz)

K20240708182009



BLK: 6,SNR1: 0.22385 ,SNR2: 2.8278



Frequency (Hz)

1335+479 2024/07/08 9.36UT FUJI -KISO

