




T20240709054746





BLK: 9,SNR1: 2.3601 ,SNR2: 30.458




Frequency (Hz)

F20240709054748




BLK: 9,SNR1: 2.7977 ,SNR2: 6.7194





Frequency (Hz)


0103+422 2024/07/08 20.82UT TOYOKAWA-FUJI



T20240709054746





BLK: 9,SNR1: 2.2249 ,SNR2: 9.4967




Frequency (Hz)

K20240709054743




BLK: 9,SNR1: 3.0582 ,SNR2: 7.5906




Frequency (Hz)

0103+422 2024/07/08 20.82UT TOYOKAWA-KISO






F20240709054748





BLK:15,SNR1: 0.83378 ,SNR2: 4.4336




Frequency (Hz)

K20240709054743




BLK:15,SNR1: 4.6816 ,SNR2: 11.462





Frequency (Hz)


0103+422 2024/07/08 20.82UT FUJI -KISO



T20240709060033





BLK: 5,SNR1: 0.21232E-01,SNR2: 0.74890




Frequency (Hz)

F20240709060035




BLK: 5,SNR1: 19.419 ,SNR2: 42.278





Frequency (Hz)


0116+31 2024/07/08 21.04UT TOYOKAWA-FUJI



T20240709060033





BLK: 4,SNR1: 0.10114 ,SNR2: 0.79167




Frequency (Hz)

K20240709060030




BLK: 4,SNR1: 5.1682 ,SNR2: 11.929





Frequency (Hz)


0116+31 2024/07/08 21.04UT TOYOKAWA-KISO



F20240709060035





BLK: 8,SNR1: 66.138 ,SNR2: 92.563




Frequency (Hz)

0116+31 2024/07/08 21.04UT FUJI -KISO


K20240709060030





BLK: 8,SNR1: 0.54022 ,SNR2: 2.4846




Frequency (Hz)



T20240709061840





BLK:14,SNR1: 10.824 ,SNR2: 17.692




Frequency (Hz)

3C48 2024/07/08 21.34UT TOYOKAWA-FUJI


F20240709061842





BLK:14,SNR1: 0.18172 ,SNR2: 1.0154




Frequency (Hz)



T20240709061840





BLK:14,SNR1: 10.899 ,SNR2: 17.813




Frequency (Hz)

3C48 2024/07/08 21.34UT TOYOKAWA-KISO


K20240709061838




BLK:14,SNR1: 2.1154 ,SNR2: 6.6596




Frequency (Hz)



F20240709061842





BLK:16,SNR1: 0.41912 ,SNR2: 2.1047




Frequency (Hz)

3C48 2024/07/08 21.34UT FUJI -KISO


K20240709061838





BLK:16,SNR1: 2.3790 ,SNR2: 7.2552




Frequency (Hz)



T20240709063223





BLK: 7,SNR1: 0.85126E-01,SNR2: 0.50199




Frequency (Hz)

F20240709063225




BLK: 7,SNR1: 1.4542 ,SNR2: 4.4027




Frequency (Hz)

0148+274 2024/07/08 21.57UT TOYOKAWA-FUJI






T20240709063223





BLK: 5,SNR1: 0.53054E-01,SNR2: 0.63744




Frequency (Hz)

K20240709063221




BLK: 5,SNR1: 4.6803 ,SNR2: 12.342




Frequency (Hz)


0148+274 2024/07/08 21.57UT TOYOKAWA-KISO





F20240709063225




BLK: 7,SNR1: 3.0868 ,SNR2: 8.0980




K20240709063221









BLK: 7,SNR1: 8.2734 ,SNR2: 19.887




0148+274 2024/07/08 21.57UT FUJI -KISO








0202+15 2024/07/08 21.79UT TOYOKAWA-FUJI



T20240709064532





BLK:11,SNR1: 2.7707 ,SNR2: 11.842




Frequency (Hz)

K20240709064529




BLK:11,SNR1: 3.6086 ,SNR2: 9.8993





Frequency (Hz)


0202+15 2024/07/08 21.79UT TOYOKAWA-KISO



F20240709064534





BLK:24,SNR1: 3.7257 ,SNR2: 9.4130




Frequency (Hz)

K20240709064529




BLK:24,SNR1: 4.0481 ,SNR2: 17.001





Frequency (Hz)


0202+15 2024/07/08 21.79UT FUJI -KISO




T20240709065722




BLK: 4,SNR1: 0.27678E-02,SNR2: 0.13020




F20240709065724





BLK: 4,SNR1: 0.22270 ,SNR2: 2.7752




0213+178 2024/07/08 21.98UT TOYOKAWA-FUJI



T20240709065722





BLK: 2,SNR1:-0.96074E-02,SNR2: 1.1627




Frequency (Hz)

K20240709065720




BLK: 2,SNR1: 0.66093 ,SNR2: 2.5361





Frequency (Hz)


0213+178 2024/07/08 21.98UT TOYOKAWA-KISO



F20240709065724





BLK: 7,SNR1: 0.12100 ,SNR2: 2.3643




Frequency (Hz)

K20240709065720




BLK: 7,SNR1: 0.25530 ,SNR2: 0.97699





Frequency (Hz)

0213+178 2024/07/08 21.98UT FUJI -KISO






T20240709070504



BLK: 3,SNR1:-0.41890E-01,SNR2: 0.98370





Frequency (Hz)


3C67

2024/07/08 22.11UT TOYOKAWA-FUJI


F20240709070506





BLK: 3,SNR1: 1.5171 ,SNR2: 9.5398




Frequency (Hz)



T20240709070504





BLK: 5,SNR1: 0.29923 ,SNR2: 0.74788




Frequency (Hz)

3C67 2024/07/08 22.11UT TOYOKAWA-KISO


K20240709070501





BLK: 5,SNR1: 10.217 ,SNR2: 24.050




Frequency (Hz)



F20240709070506





BLK: 9,SNR1: 2.3858 ,SNR2: 10.665




Frequency (Hz)

3C67 2024/07/08 22.11UT FUJI -KISO


K20240709070501





BLK: 9,SNR1: 3.6961 ,SNR2: 9.5062




Frequency (Hz)



T20240709072319



BLK: 3,SNR1:-0.35166E-01,SNR2: 0.45058




Frequency (Hz)


3C71

2024/07/08 22.42UT TOYOKAWA-FUJI


F20240709072321





BLK: 3,SNR1:-0.19851E-01,SNR2: 1.2342




Frequency (Hz)



T20240709072319



BLK: 3,SNR1: 0.18859 ,SNR2: 0.92747





Frequency (Hz)


3C71

2024/07/08 22.42UT TOYOKAWA-KISO


K20240709072317




BLK: 3,SNR1: 0.17365 ,SNR2: 1.7063




Frequency (Hz)



F20240709072321



BLK: 4,SNR1: 0.82101E-01,SNR2: 0.96665




Frequency (Hz)


3C71

2024/07/08 22.42UT FUJI -KISO


K20240709072317




BLK: 4,SNR1: 0.13474 ,SNR2: 0.89135




Frequency (Hz)



T20240709074234




BLK: 5,SNR1: 0.12609 ,SNR2: 0.69375




Frequency (Hz)

F20240709074236




BLK: 5,SNR1: 0.78787 ,SNR2: 1.6734





Frequency (Hz)


0258+350 2024/07/08 22.74UT TOYOKAWA-FUJI



T20240709074234




BLK: 4,SNR1: 0.44907E-01,SNR2: 0.43172





0258+350 2024/07/08 22.74UT TOYOKAWA-KISO

K20240709074231




BLK: 4,SNR1: 0.25127 ,SNR2: 1.4516








F20240709074236




BLK:13,SNR1: 0.31759 ,SNR2: 1.6621




K20240709074231




BLK:13,SNR1: 7.4045 ,SNR2: 15.302




0258+350 2024/07/08 22.74UT FUJI -KISO



T20240709075223





BLK: 4,SNR1: 0.22552 ,SNR2: 1.4695




Frequency (Hz)

F20240709075225




BLK: 4,SNR1: 2.6751 ,SNR2: 6.4872





Frequency (Hz)


0308+305 2024/07/08 22.90UT TOYOKAWA-FUJI



T20240709075223




BLK:10,SNR1: 0.28736 ,SNR2: 0.76171




Frequency (Hz)

K20240709075221




BLK:10,SNR1: 11.087 ,SNR2: 19.025




Frequency (Hz)


0308+305 2024/07/08 22.90UT TOYOKAWA-KISO



F20240709075225




BLK:16,SNR1: 1.2116 ,SNR2: 4.5872




Frequency (Hz)

K20240709075221




BLK:16,SNR1: 7.7150 ,SNR2: 13.314





Frequency (Hz)


0308+305 2024/07/08 22.90UT FUJI -KISO



T20240709080355





BLK:11,SNR1: 0.23456 ,SNR2: 0.79844




Frequency (Hz)

F20240709080357




BLK:11,SNR1: 2.5416 ,SNR2: 5.8690





Frequency (Hz)


0320+05 2024/07/08 23.09UT TOYOKAWA-FUJI



T20240709080355





BLK:21,SNR1: 0.22870 ,SNR2: 1.6309




Frequency (Hz)

K20240709080352




BLK:21,SNR1: 3.2625 ,SNR2: 9.3393





Frequency (Hz)


0320+05 2024/07/08 23.09UT TOYOKAWA-KISO



F20240709080357





BLK:19,SNR1: 3.4731 ,SNR2: 7.8838




Frequency (Hz)

K20240709080352




BLK:19,SNR1: 2.0377 ,SNR2: 5.9210





Frequency (Hz)


0320+05 2024/07/08 23.09UT FUJI -KISO



T20240709081716




BLK:14,SNR1: 0.30012 ,SNR2: 1.1964




Frequency (Hz)

F20240709081718




BLK:14,SNR1: 0.61324 ,SNR2: 3.3666





Frequency (Hz)

0333+32 2024/07/08 23.32UT TOYOKAWA-FUJI








T20240709081716




BLK:12,SNR1: 0.39287 ,SNR2: 1.1517




K20240709081713




BLK:12,SNR1: 1.6798 ,SNR2: 3.4394




0333+32 2024/07/08 23.32UT TOYOKAWA-KISO



F20240709081718




BLK:16,SNR1: 0.64684 ,SNR2: 3.5556




Frequency (Hz)

K20240709081713




BLK:16,SNR1: 1.1435 ,SNR2: 4.6300




Frequency (Hz)


0333+32 2024/07/08 23.32UT FUJI -KISO



T20240709083018




BLK: 6,SNR1: 0.60592 ,SNR2: 1.6412




Frequency (Hz)

F20240709083020




BLK: 6,SNR1: 1.2369 ,SNR2: 2.7990





Frequency (Hz)


0347+05 2024/07/08 23.53UT TOYOKAWA-FUJI



T20240709083018




BLK:10,SNR1: 4.4514 ,SNR2: 15.324




Frequency (Hz)

0347+05 2024/07/08 23.53UT TOYOKAWA-KISO


K20240709083015





BLK:10,SNR1: 1.1183 ,SNR2: 4.4596




Frequency (Hz)



F20240709083020





BLK:10,SNR1: 0.99746 ,SNR2: 2.3825




Frequency (Hz)

K20240709083015




BLK:10,SNR1: 0.94628 ,SNR2: 3.7730





Frequency (Hz)


0347+05 2024/07/08 23.53UT FUJI -KISO




T20240709084552




BLK: 7,SNR1: 0.23477 ,SNR2: 1.3595




F20240709084554





BLK: 7,SNR1: 1.5351 ,SNR2: 2.5381




0403-132 2024/07/08 23.79UT TOYOKAWA-FUJI



T20240709084552




BLK:11,SNR1: 0.24671 ,SNR2: 2.4859




Frequency (Hz)

K20240709084550




BLK:11,SNR1: 2.6554 ,SNR2: 11.904




Frequency (Hz)


0403-132 2024/07/08 23.79UT TOYOKAWA-KISO





F20240709084554




BLK:12,SNR1: 1.6305 ,SNR2: 3.3709




K20240709084550



BLK:12,SNR1: 2.3567 ,SNR2: 10.479




0403-132 2024/07/08 23.79UT FUJI -KISO








T20240709085412




BLK:12,SNR1: 0.14087 ,SNR2: 1.6742




F20240709085414





BLK:12,SNR1: 1.9584 ,SNR2: 9.1129




0411-171 2024/07/08 23.93UT TOYOKAWA-FUJI



T20240709085412





BLK: 5,SNR1: 0.37527 ,SNR2: 1.1122





0411-171 2024/07/08 23.93UT TOYOKAWA-KISO



K20240709085409




BLK: 5,SNR1: 0.91529 ,SNR2: 7.6549





F20240709085414




BLK:12,SNR1: 2.8785 ,SNR2: 7.4063




K20240709085409





BLK:12,SNR1: 0.42283 ,SNR2: 1.7456




0411-171 2024/07/08 23.93UT FUJI -KISO



T202407090157





BLK:30,SNR1: 8.1965 ,SNR2: 23.061




Frequency (Hz)

F202407090159




BLK:30,SNR1: 8.6117 ,SNR2: 21.267





Frequency (Hz)


0418+236 2024/07/09 0.06UT TOYOKAWA-FUJI



T20240709090157





BLK:32,SNR1: 8.2257 ,SNR2: 23.167




Frequency (Hz)

K20240709090154




BLK:32,SNR1: 7.9445 ,SNR2: 20.150




Frequency (Hz)


0418+236 2024/07/09 0.06UT TOYOKAWA-KISO





F202407090159




BLK:28,SNR1: 8.7453 ,SNR2: 21.593




K202407090154





BLK:28,SNR1: 7.9626 ,SNR2: 20.198




0418+236 2024/07/09 0.06UT FUJI -KISO



T20240709091324





BLK:27,SNR1: 10.805 ,SNR2: 26.885




Frequency (Hz)

F20240709091326




BLK:27,SNR1: 7.7858 ,SNR2: 19.909





Frequency (Hz)


3C119 2024/07/09 0.25UT TOYOKAWA-FUJI



T20240709091324





BLK:24,SNR1: 3.5739 ,SNR2: 16.391




Frequency (Hz)

3C119 2024/07/09 0.25UT TOYOKAWA-KISO


K20240709091321



BLK:24,SNR1: 8.9154 ,SNR2: 22.335





Frequency (Hz)






F20240709091326





BLK:25,SNR1: 7.7893 ,SNR2: 19.919





3C119 2024/07/09 0.25UT FUJI -KISO



K20240709091321




BLK:25,SNR1: 8.7848 ,SNR2: 22.007



T20240709100132





BLK:27,SNR1: 1.8689 ,SNR2: 13.379




Frequency (Hz)

F20240709100134




BLK:27,SNR1:-0.79561E-02,SNR2: 1.0584




Frequency (Hz)


3C138 2024/07/09 1.05UT TOYOKAWA-FUJI



T20240709100132




BLK:31,SNR1: 2.1196 ,SNR2: 6.2561





3C138 2024/07/09 1.05UT TOYOKAWA-KISO



K20240709100129




BLK:31,SNR1: 2.0179 ,SNR2: 8.5229




F20240709100134




BLK:18,SNR1:-0.42537E-01,SNR2: 1.2193




K20240709100129




BLK:18,SNR1: 1.4247 ,SNR2: 4.5634




3C138 2024/07/09 1.05UT FUJI -KISO




T20240709101505




BLK:18,SNR1: 1.5429 ,SNR2: 5.7604




F20240709101507





BLK:18,SNR1: 0.12248 ,SNR2: 1.6616




0531+194 2024/07/09 1.28UT TOYOKAWA-FUJI



T20240709101505




BLK:27,SNR1: 1.3663 ,SNR2: 4.5175





0531+194 2024/07/09 1.28UT TOYOKAWA-KISO



K20240709101502




BLK:27,SNR1: 3.1157 ,SNR2: 12.168





F20240709101507




BLK:12,SNR1: 0.47362 ,SNR2: 4.8538




K20240709101502





BLK:12,SNR1: 3.2082 ,SNR2: 14.136




0531+194 2024/07/09 1.28UT FUJI -KISO



T20240709102324





BLK:26,SNR1: 11.143 ,SNR2: 44.239





3C147 2024/07/09 1.42UT TOYOKAWA-FUJI

F20240709102326





BLK:26,SNR1: 1.6358 ,SNR2: 8.0845






T20240709102324





BLK:32,SNR1: 11.908 ,SNR2: 47.096





3C147 2024/07/09 1.42UT TOYOKAWA-KISO


K20240709102321




BLK:32,SNR1: 3.4199 ,SNR2: 13.162



F20240709102326





BLK:30,SNR1: 1.3607 ,SNR2: 6.8915





3C147 2024/07/09 1.42UT FUJI -KISO


K20240709102321




BLK:30,SNR1: 3.2142 ,SNR2: 12.618



T20240709103136





BLK:30,SNR1: 2.7716 ,SNR2: 12.580





0548+16 2024/07/09 1.55UT TOYOKAWA-FUJI


F20240709103138




BLK:30,SNR1: 6.9490 ,SNR2: 17.277



T20240709103136





BLK:33,SNR1: 3.0724 ,SNR2: 13.696





0548+16 2024/07/09 1.55UT TOYOKAWA-KISO


K20240709103133




BLK:33,SNR1: 2.9208 ,SNR2: 13.002



F20240709103138





BLK:26,SNR1: 7.3960 ,SNR2: 18.355





0548+16 2024/07/09 1.55UT FUJI -KISO


K20240709103133




BLK:26,SNR1: 2.8791 ,SNR2: 12.851



T20240709103547




BLK:19,SNR1: 1.7211 ,SNR2: 6.2761





0552+12 2024/07/09 1.62UT TOYOKAWA-FUJI


F20240709103549




BLK:19,SNR1: 3.4144 ,SNR2: 3.8338



T20240709103547





BLK:21,SNR1: 1.6489 ,SNR2: 5.6123





0552+12 2024/07/09 1.62UT TOYOKAWA-KISO



K20240709103544




BLK:21,SNR1: 1.4944 ,SNR2: 5.7296





F20240709103549




BLK:18,SNR1: 2.2656 ,SNR2: 3.9846




K20240709103544



BLK:18,SNR1: 1.2593 ,SNR2: 5.0938




0552+12 2024/07/09 1.62UT FUJI -KISO






T20240709104014




BLK:17,SNR1: 2.6399 ,SNR2: 11.692





0556+191 2024/07/09 1.70UT TOYOKAWA-FUJI


F20240709104016




BLK:17,SNR1: 0.25502E-01,SNR2: 2.1758



T20240709104014





BLK:18,SNR1: 0.48665 ,SNR2: 2.2431





0556+191 2024/07/09 1.70UT TOYOKAWA-KISO


K20240709104011




BLK:18,SNR1: 1.6318 ,SNR2: 6.2760





F20240709104016




BLK:13,SNR1:-0.35122E-01,SNR2: 1.6903




K20240709104011





BLK:13,SNR1: 1.9913 ,SNR2: 7.4250




0556+191 2024/07/09 1.70UT FUJI -KISO




T20240709104800




BLK: 7,SNR1: 0.10984 ,SNR2: 1.0464




F20240709104802





BLK: 7,SNR1: 0.62139 ,SNR2: 1.6429




0605-08 2024/07/09 1.83UT TOYOKAWA-FUJI



T20240709104800





BLK: 7,SNR1: 0.55093E-01,SNR2: 1.1438





0605-08 2024/07/09 1.83UT TOYOKAWA-KISO


K20240709104757




BLK: 7,SNR1: 0.84688E-02,SNR2: 0.33983



F20240709104802





BLK: 2,SNR1:-0.31464 ,SNR2: 0.87340




Frequency (Hz)

K20240709104757




BLK: 2,SNR1: 0.64931 ,SNR2: 2.6742




Frequency (Hz)


0605-08 2024/07/09 1.83UT FUJI -KISO



T20240709110707




BLK:28,SNR1: 2.4808 ,SNR2: 11.816





3C161 2024/07/09 2.15UT TOYOKAWA-FUJI


F20240709110709




BLK:28,SNR1: 8.8142 ,SNR2: 15.502




T20240709110707




BLK:34,SNR1: 1.3355 ,SNR2: 6.1822




K20240709110704



BLK:34,SNR1: 7.9494 ,SNR2: 19.928




3C161 2024/07/09 2.15UT TOYOKAWA-KISO






F20240709110709




BLK:30,SNR1: 8.3798 ,SNR2: 14.755





3C161 2024/07/09 2.15UT FUJI -KISO


K20240709110704




BLK:30,SNR1: 7.9727 ,SNR2: 19.995




T20240709113441




BLK: 7,SNR1: 0.15558 ,SNR2: 1.8412




F20240709113443




BLK: 7,SNR1: 1.7083 ,SNR2: 4.6563




0652-130 2024/07/09 2.61UT TOYOKAWA-FUJI





T20240709113441




BLK:13,SNR1: 0.43994 ,SNR2: 2.3404




K20240709113438




BLK:13,SNR1: 49.828 ,SNR2: 65.251




0652-130 2024/07/09 2.61UT TOYOKAWA-KISO





F20240709113443




BLK: 8,SNR1: 3.9452 ,SNR2: 13.659




K20240709113438





BLK: 8,SNR1: 7.5500 ,SNR2: 13.288




0652-130 2024/07/09 2.61UT FUJI -KISO



T20240709114617




BLK:12,SNR1:-0.99140E-02,SNR2: 0.28686E-01





0703+138 2024/07/09 2.80UT TOYOKAWA-FUJI


F20240709114619




BLK:12,SNR1: 0.40573 ,SNR2: 4.0553




T20240709114617




BLK:14,SNR1:-0.78204E-02,SNR2: 0.32162E-01




K20240709114614





BLK:14,SNR1: 0.24188 ,SNR2: 3.4273




0703+138 2024/07/09 2.80UT TOYOKAWA-KISO



F20240709114619





BLK: 8,SNR1: 0.83161 ,SNR2: 3.8298





0703+138 2024/07/09 2.80UT FUJI -KISO



K20240709114614




BLK: 8,SNR1: 0.86012 ,SNR2: 3.9537




T20240709115540




BLK:18,SNR1: 0.29756 ,SNR2: 2.6967




F20240709115542



BLK:18,SNR1: 1.1617 ,SNR2: 5.0515





0713-024 2024/07/09 2.96UT TOYOKAWA-FUJI






T20240709115540





BLK:17,SNR1: 0.38347 ,SNR2: 3.2291





0713-024 2024/07/09 2.96UT TOYOKAWA-KISO


K20240709115537




BLK:17,SNR1: 3.0117 ,SNR2: 12.238



F20240709115542





BLK:21,SNR1: 0.77009 ,SNR2: 6.4100





0713-024 2024/07/09 2.96UT FUJI -KISO


K20240709115537




BLK:21,SNR1: 1.6314 ,SNR2: 5.1488



T20240709120551




BLK:13,SNR1: 0.52281 ,SNR2: 1.6877





0723+10 2024/07/09 3.13UT TOYOKAWA-FUJI



F20240709120553




BLK:13,SNR1: 2.1689 ,SNR2: 6.6246





T20240709120551




BLK:19,SNR1: 0.57418 ,SNR2: 4.2134




K20240709120548





BLK:19,SNR1: 0.87461 ,SNR2: 3.9194




0723+10 2024/07/09 3.13UT TOYOKAWA-KISO



F20240709120553





BLK: 6,SNR1: 2.2683 ,SNR2: 8.2118




Frequency (Hz)

K20240709120548




BLK: 6,SNR1: 0.37120 ,SNR2: 2.9551





Frequency (Hz)


0723+10 2024/07/09 3.13UT FUJI -KISO



T20240709121606





BLK:22,SNR1: 4.2208 ,SNR2: 10.039





0732+33 2024/07/09 3.30UT TOYOKAWA-FUJI


F20240709121608




BLK:22,SNR1: 7.0896 ,SNR2: 16.792



T20240709121606




BLK:28,SNR1: 3.7641 ,SNR2: 6.6486





0732+33 2024/07/09 3.30UT TOYOKAWA-KISO



K20240709121603




BLK:28,SNR1: 5.6322 ,SNR2: 10.981





F20240709121608




BLK:24,SNR1: 6.9484 ,SNR2: 16.483




K20240709121603



BLK:24,SNR1: 5.6239 ,SNR2: 10.955




0732+33 2024/07/09 3.30UT FUJI -KISO







T20240709122408




BLK:17,SNR1: 2.2130 ,SNR2: 4.5324




F20240709122410




BLK:17,SNR1: 0.92470 ,SNR2: 5.1393




0741-06 2024/07/09 3.43UT TOYOKAWA-FUJI




T20240709122408




BLK:26,SNR1: 1.1787 ,SNR2: 5.1885




K20240709122405




BLK:26,SNR1: 2.2996 ,SNR2: 10.371




0741-06 2024/07/09 3.43UT TOYOKAWA-KISO




F20240709122410




BLK:25,SNR1: 0.43155 ,SNR2: 5.2415




K20240709122405




BLK:25,SNR1: 4.7772 ,SNR2: 11.902




0741-06 2024/07/09 3.43UT FUJI -KISO




T20240709123352




BLK: 5,SNR1: 0.19375 ,SNR2: 1.8201




F20240709123354





BLK: 5,SNR1: 0.23858 ,SNR2: 1.1659




0752-200 2024/07/09 3.59UT TOYOKAWA-FUJI





T20240709123352




BLK: 9,SNR1: 1.9352 ,SNR2: 4.1375




K20240709123349




BLK: 9,SNR1: 1.2597 ,SNR2: 5.0373




0752-200 2024/07/09 3.59UT TOYOKAWA-KISO




F20240709123354




BLK: 1,SNR1: 0.29615 ,SNR2: 0.62764




K20240709123349





BLK: 1,SNR1: 2.9664 ,SNR2: 10.786




0752-200 2024/07/09 3.59UT FUJI -KISO




T20240709124127




BLK: 9,SNR1: 0.67376 ,SNR2: 3.0655




F20240709124129





BLK: 9,SNR1: 0.81630E-01,SNR2: 0.95893




3C190 2024/07/09 3.72UT TOYOKAWA-FUJI




T20240709124127




BLK:22,SNR1: 0.69131 ,SNR2: 4.2457




K20240709124124



BLK:22,SNR1: 0.49896 ,SNR2: 5.1964




3C190 2024/07/09 3.72UT TOYOKAWA-KISO







F20240709124129




BLK: 5,SNR1: 0.97726E-01,SNR2: 0.60450




K20240709124124




BLK: 5,SNR1: 0.16410E-01,SNR2: 1.0891




3C190 2024/07/09 3.72UT FUJI -KISO




T20240709125352




BLK:14,SNR1: 0.93798 ,SNR2: 6.7907




F20240709125354





BLK:14,SNR1: 0.18906 ,SNR2: 0.92217




3C196 2024/07/09 3.93UT TOYOKAWA-FUJI




T20240709125352




BLK:29,SNR1: 0.96218 ,SNR2: 3.9476




K20240709125349




BLK:29,SNR1: 3.8204 ,SNR2: 5.3288




3C196 2024/07/09 3.93UT TOYOKAWA-KISO



F20240709125354




BLK: 5,SNR1: 0.76676E-01,SNR2: 1.3321





3C196 2024/07/09 3.93UT FUJI -KISO


K20240709125349




BLK: 5,SNR1: 8.9911 ,SNR2: 13.149




T20240709130501




BLK:11,SNR1: 0.99460 ,SNR2: 2.4113




F20240709130503





BLK:11,SNR1: 4.9290 ,SNR2: 19.328




0821+394 2024/07/09 4.11UT TOYOKAWA-FUJI




T20240709130501




BLK:20,SNR1: 1.5737 ,SNR2: 3.6197




K20240709130458




BLK:20,SNR1: 1.4435 ,SNR2: 7.9450




0821+394 2024/07/09 4.11UT TOYOKAWA-KISO





F20240709130503




BLK: 9,SNR1: 3.1543 ,SNR2: 18.458




K20240709130458





BLK: 9,SNR1: 1.8235 ,SNR2: 9.1621




0821+394 2024/07/09 4.11UT FUJI -KISO




T20240709131642




BLK:11,SNR1: 0.12389 ,SNR2: 1.6900




F20240709131644



BLK:11,SNR1: 0.23788E-01,SNR2: 0.76818





0834-19 2024/07/09 4.31UT TOYOKAWA-FUJI








T20240709131642




BLK: 5,SNR1: 0.22559 ,SNR2: 2.6883




K20240709131639





BLK: 5,SNR1: 1.2766 ,SNR2: 7.3242




0834-19 2024/07/09 4.31UT TOYOKAWA-KISO





F20240709131644




BLK: 1,SNR1:-0.86055E-01,SNR2: 0.63665




K20240709131639




BLK: 1,SNR1: 0.15651 ,SNR2: 0.89456




0834-19 2024/07/09 4.31UT FUJI -KISO




T20240709132147




BLK: 3,SNR1:-0.90813E-01,SNR2: 0.47487




F20240709132149




BLK: 3,SNR1:-0.92552E-01,SNR2: 0.93458




0839-071 2024/07/09 4.39UT TOYOKAWA-FUJI




T20240709132147




BLK: 9,SNR1: 0.19829 ,SNR2: 0.96659




K20240709132145




BLK: 9,SNR1: 5.0483 ,SNR2: 13.116




0839-071 2024/07/09 4.39UT TOYOKAWA-KISO




F20240709132149




BLK: 7,SNR1: 2.3577 ,SNR2: 10.676




K20240709132145





BLK: 7,SNR1: 0.51440 ,SNR2: 2.2520




0839-071 2024/07/09 4.39UT FUJI -KISO




T20240709133248




BLK:10,SNR1: 0.20572 ,SNR2: 3.4247




F20240709133250





BLK:10,SNR1: 0.30596 ,SNR2: 2.1545




3C208 2024/07/09 4.57UT TOYOKAWA-FUJI





T20240709133248




BLK:13,SNR1: 0.14588 ,SNR2: 2.8160




K20240709133245





BLK:13,SNR1: 4.9751 ,SNR2: 17.139




3C208 2024/07/09 4.57UT TOYOKAWA-KISO



F20240709133250





BLK:12,SNR1: 0.23590 ,SNR2: 3.3992




Frequency (Hz)

K20240709133245




BLK:12,SNR1: 0.77163 ,SNR2: 3.5925





Frequency (Hz)

3C208 2024/07/09 4.57UT FUJI -KISO







T20240709134929




BLK: 4,SNR1: 0.24261 ,SNR2: 1.3233




F20240709134931





BLK: 4,SNR1:-0.33451E-02,SNR2: 2.2816




3C216 2024/07/09 4.85UT TOYOKAWA-FUJI





T20240709134929




BLK:12,SNR1: 0.15175 ,SNR2: 1.1522




K20240709134926




BLK:12,SNR1: 6.2195 ,SNR2: 21.732




3C216 2024/07/09 4.85UT TOYOKAWA-KISO



F20240709134931




BLK: 6,SNR1:-0.23785E-01,SNR2: 1.8138





3C216 2024/07/09 4.85UT FUJI -KISO


K20240709134926




BLK: 6,SNR1: 1.3813 ,SNR2: 5.2223




T20240709140141




BLK: 5,SNR1: 0.27698 ,SNR2: 1.6666




F20240709140143




BLK: 5,SNR1: 0.82201 ,SNR2: 2.7495




0919-142 2024/07/09 5.06UT TOYOKAWA-FUJI





T20240709140141




BLK: 1,SNR1: 0.83066 ,SNR2: 3.3288




K20240709140139





BLK: 1,SNR1: 0.62680 ,SNR2: 0.84685




0919-142 2024/07/09 5.06UT TOYOKAWA-KISO



F20240709140143





BLK: 1,SNR1: 0.66152E-01,SNR2: 2.1568




Frequency (Hz)

K20240709140139




BLK: 1,SNR1: 0.34906E-01,SNR2: 0.42957





Frequency (Hz)


0919-142 2024/07/09 5.06UT FUJI -KISO





T20240709140820




BLK: 4,SNR1: 0.13173 ,SNR2: 0.91149




F20240709140822





BLK: 4,SNR1: 0.93214 ,SNR2: 3.9654




0926+117 2024/07/09 5.17UT TOYOKAWA-FUJI





T20240709140820




BLK: 1,SNR1:-0.13161E-01,SNR2: 0.41092




K20240709140817



BLK: 1,SNR1: 0.29868 ,SNR2: 3.8415





0926+117 2024/07/09 5.17UT TOYOKAWA-KISO








F20240709140822




BLK: 9,SNR1: 0.47463 ,SNR2: 1.4075




K20240709140817





BLK: 9,SNR1: 0.63693 ,SNR2: 2.2760




0926+117 2024/07/09 5.17UT FUJI -KISO



T20240709141604





BLK: 4,SNR1: 0.15035 ,SNR2: 0.64598




Frequency (Hz)

F20240709141606




BLK: 4,SNR1:-0.60368E-01,SNR2: 2.4958





Frequency (Hz)


3C222 2024/07/09 5.30UT TOYOKAWA-FUJI





T20240709141604




BLK: 1,SNR1: 0.37976 ,SNR2: 1.0121




K20240709141601





BLK: 1,SNR1: 0.29986 ,SNR2: 1.6394




3C222 2024/07/09 5.30UT TOYOKAWA-KISO



F20240709141606





BLK: 2,SNR1:-0.39551E-01,SNR2: 2.2923




Frequency (Hz)

K20240709141601




BLK: 2,SNR1: 0.16981 ,SNR2: 0.80312





Frequency (Hz)


3C222 2024/07/09 5.30UT FUJI -KISO




T20240709142304




BLK: 5,SNR1: 0.50289E-01,SNR2: 1.0978




F20240709142306





BLK: 5,SNR1: 0.83576E-01,SNR2: 2.1315




0941-08 2024/07/09 5.41UT TOYOKAWA-FUJI





T20240709142304




BLK: 3,SNR1: 0.25244 ,SNR2: 0.76438




K20240709142301




BLK: 3,SNR1: 2.0334 ,SNR2: 9.1746




0941-08 2024/07/09 5.41UT TOYOKAWA-KISO





F20240709142306




BLK: 1,SNR1:-0.93195E-01,SNR2: 0.78591




K20240709142301





BLK: 1,SNR1: 0.27443 ,SNR2: 1.8541




0941-08 2024/07/09 5.41UT FUJI -KISO



T20240709143126





BLK: 4,SNR1: 0.18534 ,SNR2: 0.49870




Frequency (Hz)

F20240709143128




BLK: 4,SNR1: 1.6502 ,SNR2: 2.5127





Frequency (Hz)

3C230 2024/07/09 5.55UT TOYOKAWA-FUJI








T20240709143126




BLK: 9,SNR1: 0.27276 ,SNR2: 1.2000




K20240709143124





BLK: 9,SNR1: 0.60570 ,SNR2: 2.4263




3C230 2024/07/09 5.55UT TOYOKAWA-KISO



F20240709143128





BLK: 5,SNR1: 0.27264E-01,SNR2: 2.2724




Frequency (Hz)

K20240709143124




BLK: 5,SNR1: 0.20270 ,SNR2: 0.72629





Frequency (Hz)


3C230 2024/07/09 5.55UT FUJI -KISO





T20240709144727




BLK:17,SNR1: 0.64538 ,SNR2: 2.5901




F20240709144729





BLK:17,SNR1: 0.11196 ,SNR2: 1.2829




3C237 2024/07/09 5.82UT TOYOKAWA-FUJI





T20240709144727




BLK:21,SNR1: 0.52840 ,SNR2: 3.3484




K20240709144724





BLK:21,SNR1: 0.83037E-01,SNR2: 0.58699




3C237 2024/07/09 5.82UT TOYOKAWA-KISO





F20240709144729




BLK: 5,SNR1:-0.10017 ,SNR2: 0.63264




K20240709144724





BLK: 5,SNR1: 0.27505 ,SNR2: 0.86425




3C237 2024/07/09 5.82UT FUJI -KISO





T20240709145343




BLK: 6,SNR1: 63.154 ,SNR2: 95.814




F20240709145345





BLK: 6,SNR1: 0.34695 ,SNR2: 1.5166




1011+110 2024/07/09 5.92UT TOYOKAWA-FUJI





T20240709145343




BLK: 4,SNR1: 85.377 ,SNR2: 103.18




K20240709145340





BLK: 4,SNR1: 0.13308 ,SNR2: 0.21893




1011+110 2024/07/09 5.92UT TOYOKAWA-KISO





F20240709145345




BLK: 7,SNR1: 0.30006 ,SNR2: 1.7125




K20240709145340



BLK: 7,SNR1: 1.0370 ,SNR2: 3.5502





1011+110 2024/07/09 5.92UT FUJI -KISO








T20240709150124




BLK:10,SNR1: 0.20302 ,SNR2: 0.77719




F20240709150126





BLK:10,SNR1: 0.32317 ,SNR2: 2.0775




3C241 2024/07/09 6.05UT TOYOKAWA-FUJI



T20240709150124





BLK: 7,SNR1: 60.581 ,SNR2: 90.411




Frequency (Hz)

K20240709150121




BLK: 7,SNR1: 0.33014 ,SNR2: 3.3562





Frequency (Hz)


3C241 2024/07/09 6.05UT TOYOKAWA-KISO





F20240709150126




BLK: 4,SNR1: 0.99861 ,SNR2: 1.7969




K20240709150121





BLK: 4,SNR1: 0.24168 ,SNR2: 0.87372




3C241 2024/07/09 6.05UT FUJI -KISO





T20240709151253




BLK: 4,SNR1: 3.9188 ,SNR2: 16.912




F20240709151255





BLK: 4,SNR1: 1.6453 ,SNR2: 8.3083




1031-11 2024/07/09 6.24UT TOYOKAWA-FUJI





T20240709151253




BLK:18,SNR1: 12.677 ,SNR2: 24.435




K20240709151250




BLK:18,SNR1: 4.1210 ,SNR2: 17.294




1031-11 2024/07/09 6.24UT TOYOKAWA-KISO





F20240709151255




BLK: 9,SNR1: 3.8909 ,SNR2: 16.071




K20240709151250





BLK: 9,SNR1: 4.1307 ,SNR2: 17.302




1031-11 2024/07/09 6.24UT FUJI -KISO



T20240709151727




BLK: 3,SNR1: 0.29571 ,SNR2: 1.3842




Frequency (Hz)

F20240709151729




BLK: 3,SNR1: 0.37145 ,SNR2: 1.7053





Frequency (Hz)


1035-058 2024/07/09 6.32UT TOYOKAWA-FUJI




T20240709151727




BLK: 4,SNR1: 0.24890 ,SNR2: 2.8818




K20240709151724



BLK: 4,SNR1: 0.20799 ,SNR2: 1.1639





1035-058 2024/07/09 6.32UT TOYOKAWA-KISO






F20240709151729





BLK:10,SNR1:-0.14690E-01,SNR2: 2.5287




Frequency (Hz)

K20240709151724




BLK:10,SNR1: 0.16696 ,SNR2: 0.43819





Frequency (Hz)


1035-058 2024/07/09 6.32UT FUJI -KISO



T20240709152639





BLK: 5,SNR1: 0.35794E-01,SNR2: 0.47659




Frequency (Hz)

F20240709152641




BLK: 5,SNR1: 0.32439 ,SNR2: 2.1714





Frequency (Hz)


1044-008 2024/07/09 6.47UT TOYOKAWA-FUJI





T20240709152639




BLK: 4,SNR1: 0.40205E-01,SNR2: 1.2480




K20240709152636





BLK: 4,SNR1: 0.57308 ,SNR2: 6.4282




1044-008 2024/07/09 6.47UT TOYOKAWA-KISO





F20240709152641




BLK: 8,SNR1: 0.29108 ,SNR2: 1.7328




K20240709152636





BLK: 8,SNR1: 1.1503 ,SNR2: 4.6905




1044-008 2024/07/09 6.47UT FUJI -KISO




T20240709153744




BLK: 6,SNR1: 0.50835 ,SNR2: 2.1523




F20240709153746





BLK: 6,SNR1:-0.84588E-01,SNR2: 2.2208




1055+01 2024/07/09 6.66UT TOYOKAWA-FUJI





T20240709153744




BLK: 7,SNR1: 0.50991 ,SNR2: 1.9378




K20240709153741




BLK: 7,SNR1: 2.8947 ,SNR2: 10.222




1055+01 2024/07/09 6.66UT TOYOKAWA-KISO



F20240709153746




BLK:11,SNR1: 0.65308E-03,SNR2: 1.9809




Frequency (Hz)

K20240709153741




BLK:11,SNR1: 0.84588 ,SNR2: 2.8388





Frequency (Hz)


1055+01 2024/07/09 6.66UT FUJI -KISO



T20240709154902




BLK:11,SNR1: 0.19044 ,SNR2: 0.82825




Frequency (Hz)

F20240709154904




BLK:11,SNR1: 0.88068 ,SNR2: 2.9540





Frequency (Hz)

1107+109 2024/07/09 6.85UT TOYOKAWA-FUJI






T20240709154902





BLK: 9,SNR1: 0.25448E-01,SNR2: 1.3672




Frequency (Hz)

K20240709154859




BLK: 9,SNR1: 0.46914 ,SNR2: 2.1682




Frequency (Hz)


1107+109 2024/07/09 6.85UT TOYOKAWA-KISO



F20240709154904





BLK:11,SNR1: 1.7138 ,SNR2: 5.2514




Frequency (Hz)

K20240709154859




BLK:11,SNR1: 0.45925 ,SNR2: 2.9198




Frequency (Hz)


1107+109 2024/07/09 6.85UT FUJI -KISO



T20240709155839





BLK: 5,SNR1: 0.11603 ,SNR2: 1.3932




Frequency (Hz)

F20240709155841




BLK: 5,SNR1:-0.38687E-01,SNR2: 0.70693





Frequency (Hz)


3C255 2024/07/09 7.01UT TOYOKAWA-FUJI





T20240709155839




BLK: 5, SNR1: 0.84232E-01, SNR2: 1.1665




K20240709155836





BLK: 5, SNR1: 0.93198, SNR2: 5.3624




3C255 2024/07/09 7.01UT TOYOKAWA-KISO



F20240709155841





BLK: 4,SNR1:-0.17970 ,SNR2: 0.74019E-01




Frequency (Hz)

K20240709155836




BLK: 4,SNR1: 0.10372 ,SNR2: 2.8372





Frequency (Hz)


3C255 2024/07/09 7.01UT FUJI -KISO



T20240709160917





BLK: 2,SNR1: 0.19895 ,SNR2: 1.0829




Frequency (Hz)

F20240709160919




BLK: 2,SNR1:-0.37679 ,SNR2: 0.0000





Frequency (Hz)


1127-14 2024/07/09 7.18UT TOYOKAWA-FUJI



T20240709160917




BLK: 4,SNR1: 1.0315 ,SNR2: 4.0627




Frequency (Hz)

K20240709160914




BLK: 4,SNR1: 1.0633 ,SNR2: 7.1208





Frequency (Hz)


1127-14 2024/07/09 7.18UT TOYOKAWA-KISO



F20240709160919





BLK: 2,SNR1: 2.0688 ,SNR2: 9.6990




Frequency (Hz)

K20240709160914




BLK: 2,SNR1: 0.32964 ,SNR2: 2.1207





Frequency (Hz)

1127-14 2024/07/09 7.18UT FUJI -KISO






T20240709162237




BLK: 2,SNR1: 6.9172 ,SNR2: 28.939




Frequency (Hz)

F20240709162239




BLK: 2,SNR1:-0.18714 ,SNR2: 0.48588





Frequency (Hz)


3C263.1 2024/07/09 7.41UT TOYOKAWA-FUJI



T20240709162237





BLK: 9,SNR1: 1.3392 ,SNR2: 5.7934




Frequency (Hz)

K20240709162234




BLK: 9,SNR1: 1.3949 ,SNR2: 7.4686




Frequency (Hz)


3C263.1 2024/07/09 7.41UT TOYOKAWA-KISO



F20240709162239





BLK:13,SNR1: 1.1363 ,SNR2: 5.9735




Frequency (Hz)

K20240709162234




BLK:13,SNR1: 0.30450 ,SNR2: 1.3381





Frequency (Hz)


3C263.1 2024/07/09 7.41UT FUJI -KISO




T20240709162904




BLK: 3,SNR1: 0.66669E-01,SNR2: 0.12526




F20240709162906





BLK: 3,SNR1: 0.11904E-02,SNR2: 0.62872




3C267 2024/07/09 7.51UT TOYOKAWA-FUJI





T20240709162904




BLK: 1,SNR1:-0.16680E-01,SNR2: 0.32526




K20240709162901




BLK: 1,SNR1: 1.3121 ,SNR2: 7.6996




3C267 2024/07/09 7.51UT TOYOKAWA-KISO



F20240709162906





BLK: 1,SNR1:-0.68852E-01,SNR2: 1.0500




Frequency (Hz)

K20240709162901




BLK: 1,SNR1: 5.8468 ,SNR2: 37.515





Frequency (Hz)


3C267 2024/07/09 7.51UT FUJI -KISO




T20240709164818




BLK: 4,SNR1: 3.3486 ,SNR2: 5.8824




F20240709164820





BLK: 4,SNR1:-0.15276 ,SNR2: 1.4134




1206+439 2024/07/09 7.83UT TOYOKAWA-FUJI



T20240709164818





BLK: 5, SNR1: 3.3267 , SNR2: 5.8454




Frequency (Hz)

K20240709164815




BLK: 5, SNR1: 3.4763 , SNR2: 11.989




Frequency (Hz)

1206+439 2024/07/09 7.83UT TOYOKAWA-KISO






F20240709164820





BLK: 6,SNR1: 0.93816 ,SNR2: 7.7904




Frequency (Hz)

K20240709164815




BLK: 6,SNR1: 2.3860 ,SNR2: 9.0553




Frequency (Hz)


1206+439 2024/07/09 7.83UT FUJI -KISO



T20240709175456





BLK:18,SNR1: 6.4311 ,SNR2: 17.394




Frequency (Hz)

F20240709175458




BLK:18,SNR1: 7.6788 ,SNR2: 19.347





Frequency (Hz)


1313+453 2024/07/09 8.94UT TOYOKAWA-FUJI



T20240709175456





BLK:17,SNR1: 6.4376 ,SNR2: 17.399




Frequency (Hz)

K20240709175453




BLK:17,SNR1: 7.7014 ,SNR2: 20.407





Frequency (Hz)


1313+453 2024/07/09 8.94UT TOYOKAWA-KISO



F20240709175458




BLK:15,SNR1: 7.6190 ,SNR2: 19.202




Frequency (Hz)

K20240709175453




BLK:15,SNR1: 7.6861 ,SNR2: 20.367





Frequency (Hz)


1313+453 2024/07/09 8.94UT FUJI -KISO



T20240709181615




BLK:36,SNR1: 15.077 ,SNR2: 26.765




Frequency (Hz)

F20240709181617




BLK:36,SNR1: 5.6854 ,SNR2: 14.577





Frequency (Hz)


1335+479 2024/07/09 9.30UT TOYOKAWA-FUJI



T20240709181615




BLK:34,SNR1: 14.403 ,SNR2: 26.397




Frequency (Hz)

K20240709181613




BLK:34,SNR1: 16.060 ,SNR2: 28.309




Frequency (Hz)


1335+479 2024/07/09 9.30UT TOYOKAWA-KISO



F20240709181617





BLK:36,SNR1: 5.7006 ,SNR2: 14.614




Frequency (Hz)

K20240709181613




BLK:36,SNR1: 16.919 ,SNR2: 29.833




Frequency (Hz)


1335+479 2024/07/09 9.30UT FUJI -KISO



T20240709182021





BLK: 4,SNR1: 0.35858 ,SNR2: 3.8319




Frequency (Hz)

F20240709182023




BLK: 4,SNR1: 0.53567E-01,SNR2: 2.8568





Frequency (Hz)

1339+472 2024/07/09 9.37UT TOYOKAWA-FUJI






T20240709182021





BLK: 6,SNR1: 0.62718E-01,SNR2: 0.98073




Frequency (Hz)

K20240709182019




BLK: 6,SNR1: 7.8024 ,SNR2: 11.992




Frequency (Hz)


1339+472 2024/07/09 9.37UT TOYOKAWA-KISO



F20240709182023




BLK: 8,SNR1:-0.28162E-01,SNR2: 1.4057




Frequency (Hz)

K20240709182019



BLK: 8,SNR1: 2.8913 ,SNR2: 11.433



Frequency (Hz)

1339+472 2024/07/09 9.37UT FUJI -KISO

