



T20240710054350





BLK: 5,SNR1: 2.2083 ,SNR2: 34.775




Frequency (Hz)

F20240710054352




BLK: 5,SNR1: 0.24685 ,SNR2: 1.9669




Frequency (Hz)


0103+422 2024/07/09 20.76UT TOYOKAWA-FUJI



T20240710054350





BLK: 6,SNR1: 5.8014 ,SNR2: 65.255




Frequency (Hz)

K20240710054347




BLK: 6,SNR1: 6.8161 ,SNR2: 21.187




Frequency (Hz)

0103+422 2024/07/09 20.76UT TOYOKAWA-KISO






F20240710054352





BLK: 4,SNR1: 0.16172 ,SNR2: 0.94879




Frequency (Hz)

K20240710054347




BLK: 4,SNR1: 0.66219 ,SNR2: 4.0689





Frequency (Hz)


0103+422 2024/07/09 20.76UT FUJI -KISO





T20240710055637




No.Good Data




F20240710055639





No.Good Data




0116+31 2024/07/09 20.97UT TOYOKAWA-FUJI



T20240710055637




BLK: 3,SNR1: 3.8472 ,SNR2: 16.520




Frequency (Hz)

0116+31 2024/07/09 20.97UT TOYOKAWA-KISO


K20240710055634




BLK: 3,SNR1: 1.8988 ,SNR2: 10.010




Frequency (Hz)



F20240710055639




BLK:12,SNR1: 0.18852 ,SNR2: 1.5220




Frequency (Hz)

K20240710055634




BLK:12,SNR1: 1.5553 ,SNR2: 6.1844





Frequency (Hz)


0116+31 2024/07/09 20.97UT FUJI -KISO



T20240710061444





BLK:14,SNR1: 0.12156 ,SNR2: 1.8989




Frequency (Hz)

3C48 2024/07/09 21.27UT TOYOKAWA-FUJI


F20240710061446





BLK:14,SNR1:-0.77611E-01,SNR2: 1.5125




Frequency (Hz)



T20240710061444



BLK:10,SNR1: 0.27561 ,SNR2: 2.3172





Frequency (Hz)


3C48

2024/07/09 21.27UT TOYOKAWA-KISO


K20240710061441




BLK:10,SNR1: 2.0020 ,SNR2: 8.0801




Frequency (Hz)



F20240710061446




BLK:11,SNR1:-0.10434E-01,SNR2: 1.3464




Frequency (Hz)

3C48 2024/07/09 21.27UT FUJI -KISO


K20240710061441





BLK:11,SNR1: 1.9029 ,SNR2: 7.6890




Frequency (Hz)



T20240710062827





BLK: 1,SNR1: 0.56448 ,SNR2: 1.3670




Frequency (Hz)

F20240710062829




BLK: 1,SNR1: 0.61188E-01,SNR2: 1.6337





Frequency (Hz)

0148+274 2024/07/09 21.50UT TOYOKAWA-FUJI






T20240710062827




BLK: 2,SNR1: 0.14620E-01,SNR2: 0.32431




Frequency (Hz)

K20240710062824




BLK: 2,SNR1: 1.3236 ,SNR2: 9.5650




Frequency (Hz)


0148+274 2024/07/09 21.50UT TOYOKAWA-KISO



F20240710062829




BLK: 3,SNR1: 0.63830E-01,SNR2: 1.0847




Frequency (Hz)

K20240710062824




BLK: 3,SNR1: 7.4847 ,SNR2: 14.775




Frequency (Hz)


0148+274 2024/07/09 21.50UT FUJI -KISO



T20240710064136




BLK: 3,SNR1: 0.11882 ,SNR2: 1.4796




Frequency (Hz)

F20240710064138




BLK: 3,SNR1: 0.56360 ,SNR2: 1.6158




Frequency (Hz)


0202+15 2024/07/09 21.72UT TOYOKAWA-FUJI



T20240710064136





BLK: 7,SNR1: 0.74958E-01,SNR2: 0.75836




Frequency (Hz)

K20240710064133




BLK: 7,SNR1: 10.790 ,SNR2: 14.750




Frequency (Hz)


0202+15 2024/07/09 21.72UT TOYOKAWA-KISO



F20240710064138





BLK: 8,SNR1: 0.51443 ,SNR2: 1.6100




Frequency (Hz)

K20240710064133




BLK: 8,SNR1: 1.8724 ,SNR2: 8.2599




Frequency (Hz)


0202+15 2024/07/09 21.72UT FUJI -KISO



T20240710065326





BLK: 9,SNR1: 0.10893 ,SNR2: 1.2726




Frequency (Hz)

F20240710065328




BLK: 9,SNR1: 0.92163 ,SNR2: 1.8231





Frequency (Hz)


0213+178 2024/07/09 21.92UT TOYOKAWA-FUJI



T20240710065326





BLK: 7,SNR1: 0.22437 ,SNR2: 1.6996




Frequency (Hz)

K20240710065323




BLK: 7,SNR1: 3.2155 ,SNR2: 10.899





Frequency (Hz)


0213+178 2024/07/09 21.92UT TOYOKAWA-KISO



F20240710065328





BLK: 9,SNR1: 0.27030 ,SNR2: 1.8783




Frequency (Hz)

K20240710065323




BLK: 9,SNR1: 1.0864 ,SNR2: 4.0881





Frequency (Hz)

0213+178 2024/07/09 21.92UT FUJI -KISO






T20240710070108



BLK: 7,SNR1: 0.57480 ,SNR2: 1.9531





Frequency (Hz)


3C67

2024/07/09 22.05UT TOYOKAWA-FUJI


F20240710070110





BLK: 7,SNR1: 0.25985E-01,SNR2: 0.81695




Frequency (Hz)



T20240710070108



BLK: 4,SNR1:-0.20034E-01,SNR2: 0.27854





Frequency (Hz)


3C67

2024/07/09 22.05UT TOYOKAWA-KISO


K20240710070105




BLK: 4,SNR1: 4.9051 ,SNR2: 9.3918




Frequency (Hz)



F20240710070110



BLK: 5,SNR1:-0.13660 ,SNR2: 1.2851




Frequency (Hz)


3C67

2024/07/09 22.05UT FUJI -KISO


K20240710070105





BLK: 5,SNR1: 0.11520 ,SNR2: 2.5740




Frequency (Hz)




T20240710071923




BLK: 4,SNR1: 0.15328 ,SNR2: 0.51612




F20240710071925




BLK: 4,SNR1:-0.65240E-01,SNR2: 0.81496




3C71 2024/07/09 22.35UT TOYOKAWA-FUJI



T20240710071923



BLK: 8,SNR1: 0.95716E-01,SNR2: 0.95360





Frequency (Hz)


3C71

2024/07/09 22.35UT TOYOKAWA-KISO


K20240710071920




BLK: 8,SNR1: 0.89157 ,SNR2: 5.8219




Frequency (Hz)



F20240710071925



BLK:13,SNR1: 0.75019E-01,SNR2: 2.1622





Frequency (Hz)


3C71

2024/07/09 22.35UT FUJI -KISO


K20240710071920




BLK:13,SNR1: 1.0461 ,SNR2: 6.7316




Frequency (Hz)



T20240710073838





BLK: 9,SNR1: 0.25931 ,SNR2: 1.6183




Frequency (Hz)

F20240710073840




BLK: 9,SNR1: 0.34960 ,SNR2: 2.1974




Frequency (Hz)


0258+350 2024/07/09 22.67UT TOYOKAWA-FUJI



T20240710073838





BLK: 9,SNR1: 0.27816 ,SNR2: 0.75425




Frequency (Hz)

K20240710073835




BLK: 9,SNR1: 20.789 ,SNR2: 31.722




Frequency (Hz)

0258+350 2024/07/09 22.67UT TOYOKAWA-KISO






F20240710073840




BLK:19,SNR1: 0.35439 ,SNR2: 1.8963




Frequency (Hz)

K20240710073835




BLK:19,SNR1: 8.0733 ,SNR2: 15.795





Frequency (Hz)


0258+350 2024/07/09 22.67UT FUJI -KISO



T20240710074827




BLK: 3,SNR1: 0.64661E-01,SNR2: 1.0098




Frequency (Hz)

F20240710074829




BLK: 3,SNR1: 0.37582 ,SNR2: 3.4959





Frequency (Hz)


0308+305 2024/07/09 22.84UT TOYOKAWA-FUJI



T20240710074827




BLK: 3,SNR1: 0.26221 ,SNR2: 1.0924





0308+305 2024/07/09 22.84UT TOYOKAWA-KISO



K20240710074824




BLK: 3,SNR1: 0.92058 ,SNR2: 4.8898



F20240710074829





BLK: 7,SNR1: 0.40190E-01,SNR2: 1.3028




Frequency (Hz)

K20240710074824




BLK: 7,SNR1: 7.2188 ,SNR2: 28.128





Frequency (Hz)


0308+305 2024/07/09 22.84UT FUJI -KISO



T20240710075959




BLK: 5,SNR1: 0.28157 ,SNR2: 0.78469




Frequency (Hz)

F20240710080001




BLK: 5,SNR1: 0.42700E-01,SNR2: 2.7384




Frequency (Hz)


0320+05 2024/07/09 23.03UT TOYOKAWA-FUJI




T20240710075959




BLK: 8,SNR1: 0.62580E-01,SNR2: 0.81040




K20240710075956




BLK: 8,SNR1: 35.841 ,SNR2: 46.932




0320+05 2024/07/09 23.03UT TOYOKAWA-KISO



F20240710080001





BLK: 5,SNR1:-0.13042 ,SNR2: 0.53150




Frequency (Hz)

K20240710075956




BLK: 5,SNR1: 1.8008 ,SNR2: 13.019





Frequency (Hz)


0320+05 2024/07/09 23.03UT FUJI -KISO



T20240710081320




BLK:13,SNR1: 2.1713 ,SNR2: 9.7858




Frequency (Hz)

F20240710081322




BLK:13,SNR1: 4.7180 ,SNR2: 9.5471





Frequency (Hz)

0333+32 2024/07/09 23.25UT TOYOKAWA-FUJI






T20240710081320





BLK: 9,SNR1: 2.3284 ,SNR2: 10.540




Frequency (Hz)

K20240710081317




BLK: 9,SNR1: 10.595 ,SNR2: 18.399





Frequency (Hz)


0333+32 2024/07/09 23.25UT TOYOKAWA-KISO



F20240710081322





BLK:23,SNR1: 3.7823 ,SNR2: 7.3859




Frequency (Hz)

K20240710081317




BLK:23,SNR1: 8.7627 ,SNR2: 15.209





Frequency (Hz)


0333+32 2024/07/09 23.25UT FUJI -KISO



T20240710082622





BLK:24,SNR1: 5.5537 ,SNR2: 14.003





0347+05 2024/07/09 23.47UT TOYOKAWA-FUJI


F20240710082624




BLK:24,SNR1: 3.0559 ,SNR2: 14.124



T20240710082622




BLK:26,SNR1: 7.1392 ,SNR2: 18.956




Frequency (Hz)

0347+05 2024/07/09 23.47UT TOYOKAWA-KISO


K20240710082620




BLK:26,SNR1: 8.0755 ,SNR2: 20.107




Frequency (Hz)



F20240710082624




BLK:29,SNR1: 3.0594 ,SNR2: 14.135




Frequency (Hz)

0347+05 2024/07/09 23.47UT FUJI -KISO


K20240710082620





BLK:29,SNR1: 9.4389 ,SNR2: 16.798




Frequency (Hz)



T20240710084157





BLK: 5,SNR1: 0.25816 ,SNR2: 1.5623




Frequency (Hz)

F20240710084159




BLK: 5,SNR1: 3.5089 ,SNR2: 5.0869





Frequency (Hz)


0403-132 2024/07/09 23.73UT TOYOKAWA-FUJI





T20240710084157




BLK: 5,SNR1: 0.12363 ,SNR2: 1.3701




K20240710084154





BLK: 5,SNR1: 0.56909 ,SNR2: 4.3555




0403-132 2024/07/09 23.73UT TOYOKAWA-KISO





F20240710084159




BLK: 9,SNR1: 2.6421 ,SNR2: 4.3005




K20240710084154



BLK: 9,SNR1: 0.40419 ,SNR2: 1.5420




0403-132 2024/07/09 23.73UT FUJI -KISO







T20240710085107




BLK:16,SNR1: 1.2284 ,SNR2: 6.1048




F20240710085109





BLK:16,SNR1: 3.7136 ,SNR2: 9.1338




0411+05 2024/07/09 23.88UT TOYOKAWA-FUJI



T20240710085107





BLK:13,SNR1: 1.4416 ,SNR2: 7.0657




Frequency (Hz)

K20240710085105




BLK:13,SNR1: 2.7701 ,SNR2: 12.996





Frequency (Hz)


0411+05 2024/07/09 23.88UT TOYOKAWA-KISO



F20240710085109





BLK:18,SNR1: 3.6835 ,SNR2: 9.1731




Frequency (Hz)

K20240710085105




BLK:18,SNR1: 2.8013 ,SNR2: 13.085




Frequency (Hz)


0411+05 2024/07/09 23.88UT FUJI -KISO





T20240710090200




BLK:20,SNR1: 4.7245 ,SNR2: 12.172




F20240710090200





BLK:20,SNR1: 2.9751 ,SNR2: 13.802




0422+178 2024/07/10 0.06UT TOYOKAWA-FUJI





T20240710090200




BLK:21,SNR1: 4.6619 ,SNR2: 11.864




K20240710090157





BLK:21,SNR1: 9.0921 ,SNR2: 22.736




0422+178 2024/07/10 0.06UT TOYOKAWA-KISO



F20240710090202





BLK:23,SNR1: 2.9637 ,SNR2: 13.757




Frequency (Hz)

K20240710090157




BLK:23,SNR1: 9.0488 ,SNR2: 22.628





Frequency (Hz)


0422+178 2024/07/10 0.06UT FUJI -KISO



T20240710090928





BLK:26,SNR1: 8.6968 ,SNR2: 21.812





3C119 2024/07/10 0.19UT TOYOKAWA-FUJI



F20240710090930




BLK:26,SNR1: 6.6249 ,SNR2: 18.576



T20240710090928





BLK:25,SNR1: 8.7742 ,SNR2: 22.000





3C119 2024/07/10 0.19UT TOYOKAWA-KISO

K20240710090925





BLK:25,SNR1: 1.6821 ,SNR2: 8.5728








F20240710090930




BLK:27,SNR1: 7.3388 ,SNR2: 20.309




K20240710090925





BLK:27,SNR1: 1.7967 ,SNR2: 9.1343




3C119 2024/07/10 0.19UT FUJI -KISO



T20240710095736





BLK:32,SNR1: 7.7377 ,SNR2: 18.287





3C138 2024/07/10 0.99UT TOYOKAWA-FUJI



F20240710095738




BLK:32,SNR1: 4.7925 ,SNR2: 11.796



T20240710095736




BLK:33,SNR1: 7.7300 ,SNR2: 18.269





3C138 2024/07/10 0.99UT TOYOKAWA-KISO


K20240710095734




BLK:33,SNR1: 6.0014 ,SNR2: 14.453



F20240710095738




BLK:32,SNR1: 4.9942 ,SNR2: 12.144





3C138 2024/07/10 0.99UT FUJI -KISO



K20240710095734




BLK:32,SNR1: 6.1809 ,SNR2: 14.883





T20240710101109




BLK:20,SNR1: 4.7352 ,SNR2: 15.013




F20240710101111




BLK:20,SNR1: 2.1058 ,SNR2: 7.2122




0531+194 2024/07/10 1.21UT TOYOKAWA-FUJI



T20240710101109




BLK:31,SNR1: 3.7846 ,SNR2: 10.015





0531+194 2024/07/10 1.21UT TOYOKAWA-KISO


K20240710101106




BLK:31,SNR1: 7.0516 ,SNR2: 8.9364





F20240710101111




BLK:21,SNR1: 2.2290 ,SNR2: 7.3852




K20240710101106




BLK:21,SNR1: 7.5916 ,SNR2: 9.7684




0531+194 2024/07/10 1.21UT FUJI -KISO



T20240710101929





BLK:28,SNR1: 18.931 ,SNR2: 34.881




Frequency (Hz)

3C147 2024/07/10 1.35UT TOYOKAWA-FUJI


F20240710101931



BLK:28,SNR1: 12.603 ,SNR2: 19.474




Frequency (Hz)






T20240710101929





BLK:31,SNR1: 18.859 ,SNR2: 34.747





3C147 2024/07/10 1.35UT TOYOKAWA-KISO


K20240710101926




BLK:31,SNR1: 17.630 ,SNR2: 33.396



F20240710101931





BLK:29,SNR1: 12.463 ,SNR2: 23.296





3C147 2024/07/10 1.35UT FUJI -KISO



K20240710101926




BLK:29,SNR1: 16.859 ,SNR2: 31.658



T20240710102740





BLK:18,SNR1: 1.1870 ,SNR2: 5.1564





0548+16 2024/07/10 1.49UT TOYOKAWA-FUJI



F20240710102742




BLK:18,SNR1: 2.2148 ,SNR2: 18.293



T20240710102740




BLK:20,SNR1: 1.2400 ,SNR2: 3.2930





0548+16 2024/07/10 1.49UT TOYOKAWA-KISO


K20240710102738




BLK:20,SNR1: 13.795 ,SNR2: 21.708



F20240710102742




BLK:14,SNR1: 3.1608 ,SNR2: 26.612





0548+16 2024/07/10 1.49UT FUJI -KISO



K20240710102738




BLK:14,SNR1: 14.077 ,SNR2: 19.698



T20240710103151





BLK:29,SNR1: 9.0762 ,SNR2: 16.206





0552+12 2024/07/10 1.56UT TOYOKAWA-FUJI



F20240710103153




BLK:29,SNR1: 8.1966 ,SNR2: 20.522



T20240710103151





BLK:32,SNR1: 9.0877 ,SNR2: 16.226




0552+12 2024/07/10 1.56UT TOYOKAWA-KISO


K20240710103148





BLK:32,SNR1: 8.7920 ,SNR2: 15.699




Frequency (Hz)



F20240710103153





BLK:35,SNR1: 3.0182 ,SNR2: 13.966




Frequency (Hz)

K20240710103148




BLK:35,SNR1: 9.3536 ,SNR2: 23.095





Frequency (Hz)

0552+12 2024/07/10 1.56UT FUJI -KISO






T20240710103618





BLK:19,SNR1: 4.1440 ,SNR2: 17.012




Frequency (Hz)

F20240710103620




BLK:19,SNR1: 3.5800 ,SNR2: 7.8245





Frequency (Hz)


0556+191 2024/07/10 1.63UT TOYOKAWA-FUJI



T20240710103618





BLK:26,SNR1: 4.1746 ,SNR2: 17.140




Frequency (Hz)

0556+191 2024/07/10 1.63UT TOYOKAWA-KISO


K20240710103616




BLK:26,SNR1: 4.3352 ,SNR2: 18.950




Frequency (Hz)




F20240710103620




BLK:25,SNR1: 7.1356 ,SNR2: 13.451




K20240710103616





BLK:25,SNR1: 4.3339 ,SNR2: 18.944




0556+191 2024/07/10 1.63UT FUJI -KISO



T20240710104404




BLK:29,SNR1: 7.7750 ,SNR2: 19.875





0605-08 2024/07/10 1.76UT TOYOKAWA-FUJI



F20240710104406




BLK:29,SNR1: 11.340 ,SNR2: 26.139



T20240710104404




BLK:29,SNR1: 7.9170 ,SNR2: 20.045





0605-08 2024/07/10 1.76UT TOYOKAWA-KISO


K20240710104401




BLK:29,SNR1: 12.499 ,SNR2: 22.085



F20240710104406





BLK:28,SNR1: 12.645 ,SNR2: 28.561





0605-08 2024/07/10 1.76UT FUJI -KISO


K20240710104401




BLK:28,SNR1: 11.455 ,SNR2: 20.237



T20240710110312




BLK:18,SNR1: 1.3412 ,SNR2: 6.9318





3C161 2024/07/10 2.08UT TOYOKAWA-FUJI


F20240710110314




BLK:18,SNR1:-0.39689E-01,SNR2: 1.2835



T20240710110312





BLK:29,SNR1: 1.1410 ,SNR2: 6.0766





3C161 2024/07/10 2.08UT TOYOKAWA-KISO

K20240710110309





BLK:29,SNR1: 2.5990 ,SNR2: 10.691






F20240710110314





BLK:12,SNR1:-0.12077 ,SNR2: 1.1550




Frequency (Hz)

K20240710110309




BLK:12,SNR1: 0.31922 ,SNR2: 1.3788




Frequency (Hz)


3C161 2024/07/10 2.08UT FUJI -KISO




T20240710113045




BLK: 7,SNR1: 4.6851 ,SNR2: 11.401




F20240710113047




BLK: 7,SNR1: 0.57785E-01,SNR2: 2.1923




0652-130 2024/07/10 2.54UT TOYOKAWA-FUJI





T20240710113045




BLK:14,SNR1: 3.0415 ,SNR2: 7.4398




K20240710113042




BLK:14,SNR1: 1.8577 ,SNR2: 6.5630




0652-130 2024/07/10 2.54UT TOYOKAWA-KISO





F20240710113047




BLK:12,SNR1: 0.13565 ,SNR2: 2.7029




K20240710113042





BLK:12,SNR1: 1.7710 ,SNR2: 6.6557




0652-130 2024/07/10 2.54UT FUJI -KISO




T20240710114221




BLK:19,SNR1: 2.2367 ,SNR2: 13.677




F20240710114223




BLK:19,SNR1: 0.58565 ,SNR2: 5.1699




0703+138 2024/07/10 2.73UT TOYOKAWA-FUJI




T20240710114221




BLK:16,SNR1: 2.5345 ,SNR2: 11.143




K20240710114219





BLK:16,SNR1: 0.43394 ,SNR2: 2.1606




0703+138 2024/07/10 2.73UT TOYOKAWA-KISO





F20240710114223




BLK: 8,SNR1: 1.1589 ,SNR2: 8.8417




K20240710114219




BLK: 8,SNR1: 0.42400 ,SNR2: 3.4901




0703+138 2024/07/10 2.73UT FUJI -KISO



T20240710115144





BLK:22,SNR1: 13.182 ,SNR2: 48.670





0713-024 2024/07/10 2.89UT TOYOKAWA-FUJI

F20240710115146




BLK:22,SNR1: 12.583 ,SNR2: 30.700






T20240710115144





BLK:29,SNR1: 13.613 ,SNR2: 23.997





0713-024 2024/07/10 2.89UT TOYOKAWA-KISO



K20240710115142




BLK:29,SNR1: 7.3478 ,SNR2: 18.944





F20240710115146




BLK:28,SNR1: 11.990 ,SNR2: 29.288




K20240710115142





BLK:28,SNR1: 4.3019 ,SNR2: 11.383




0713-024 2024/07/10 2.89UT FUJI -KISO




T20240710120155




BLK:18,SNR1: 2.1432 ,SNR2: 5.0206




F20240710120157





BLK:18,SNR1: 8.0458 ,SNR2: 12.452




0723+10 2024/07/10 3.06UT TOYOKAWA-FUJI



T20240710120155




BLK:25,SNR1: 126.51 ,SNR2: 164.67





0723+10 2024/07/10 3.06UT TOYOKAWA-KISO


K20240710120152




BLK:25,SNR1: 3.5751 ,SNR2: 12.685




F20240710120157




BLK:29,SNR1: 6.4289 ,SNR2: 11.481




K20240710120152




BLK:29,SNR1: 10.636 ,SNR2: 11.746




0723+10 2024/07/10 3.06UT FUJI -KISO




T20240710121210




BLK:20,SNR1: 1.0128 ,SNR2: 2.7195




F20240710121212




BLK:20,SNR1: 5.4157 ,SNR2: 13.205




0732+33 2024/07/10 3.23UT TOYOKAWA-FUJI



T20240710121210




BLK:26,SNR1: 0.86711 ,SNR2: 2.4049





0732+33 2024/07/10 3.23UT TOYOKAWA-KISO


K20240710121208




BLK:26,SNR1: 2.2296 ,SNR2: 8.5068




F20240710121212




BLK:22,SNR1: 5.3117 ,SNR2: 12.951




K20240710121208



BLK:22,SNR1: 3.8822 ,SNR2: 13.999




0732+33 2024/07/10 3.23UT FUJI -KISO







T20240710122012




BLK: 6,SNR1: 1.1740 ,SNR2: 11.584




F20240710122014




BLK: 6,SNR1:-0.57151E-02,SNR2: 1.2595




0741-06 2024/07/10 3.36UT TOYOKAWA-FUJI





T20240710122012




BLK:21,SNR1: 1.2164 ,SNR2: 8.8353




K20240710122010




BLK:21,SNR1: 0.60437 ,SNR2: 3.5722




0741-06 2024/07/10 3.36UT TOYOKAWA-KISO





F20240710122014




BLK:10,SNR1:-0.16086 ,SNR2: 0.72048




K20240710122010





BLK:10,SNR1: 0.21502 ,SNR2: 1.3897




0741-06 2024/07/10 3.36UT FUJI -KISO



T20240710122956




BLK: 7,SNR1: 59.885 ,SNR2: 122.89





0752-200 2024/07/10 3.53UT TOYOKAWA-FUJI



F20240710122958




BLK: 7,SNR1:-0.97899E-01,SNR2: 0.32252



T20240710122956




BLK: 7,SNR1: 52.273 ,SNR2: 105.18




0752-200 2024/07/10 3.53UT TOYOKAWA-KISO


K20240710122953





BLK: 7,SNR1: 0.48744 ,SNR2: 2.2989




Frequency (Hz)





F20240710122958




No.Good Data




K20240710122953




No.Good Data




0752-200 2024/07/10 3.53UT FUJI -KISO



T20240710123731





BLK: 8,SNR1: 1.0629 ,SNR2: 8.4087





3C190 2024/07/10 3.65UT TOYOKAWA-FUJI



F20240710123733




BLK: 8,SNR1: 0.48031 ,SNR2: 3.2351





T20240710123731




BLK:15,SNR1: 0.93488 ,SNR2: 3.5809




K20240710123728



BLK:15,SNR1: 1.0888 ,SNR2: 4.2100





3C190 2024/07/10 3.65UT TOYOKAWA-KISO






F20240710123733





BLK:14,SNR1: 0.42368 ,SNR2: 2.4105





3C190 2024/07/10 3.65UT FUJI -KISO



K20240710123728




BLK:14,SNR1: 1.2659 ,SNR2: 4.9528





T20240710124956




BLK: 7,SNR1: 0.39899 ,SNR2: 4.9331




F20240710124958




BLK: 7,SNR1: 0.10857E-01,SNR2: 0.91048




3C196 2024/07/10 3.86UT TOYOKAWA-FUJI




T20240710124956




BLK:21,SNR1: 0.46543 ,SNR2: 5.3623




K20240710124953




BLK:21,SNR1: 0.71839 ,SNR2: 2.9627




3C196 2024/07/10 3.86UT TOYOKAWA-KISO




F20240710124958




No.Good Data




K20240710124953




No.Good Data




3C196 2024/07/10 3.86UT FUJI -KISO




T20240710130105




BLK:10,SNR1: 0.30756 ,SNR2: 2.9117




F20240710130107





BLK:10,SNR1: 0.18013 ,SNR2: 1.3857




0821+394 2024/07/10 4.05UT TOYOKAWA-FUJI





T20240710130105




BLK:19,SNR1: 0.32818 ,SNR2: 2.2029




K20240710130102




BLK:19,SNR1: 1.4682 ,SNR2: 4.3108




0821+394 2024/07/10 4.05UT TOYOKAWA-KISO





F20240710130107




BLK:12,SNR1: 0.11261 ,SNR2: 2.0408




K20240710130102





BLK:12,SNR1: 1.4035 ,SNR2: 6.2086




0821+394 2024/07/10 4.05UT FUJI -KISO





T20240710131246




BLK: 5,SNR1: 0.14791 ,SNR2: 2.8165




F20240710131248



BLK: 5,SNR1: 0.20035 ,SNR2: 1.8651





0834-19 2024/07/10 4.24UT TOYOKAWA-FUJI








T20240710131246




BLK: 5,SNR1:-0.55408E-01,SNR2: 1.1351




K20240710131243




BLK: 5,SNR1: 1.7993 ,SNR2: 9.5442




0834-19 2024/07/10 4.24UT TOYOKAWA-KISO





F20240710131248




BLK: 8,SNR1: 0.15271 ,SNR2: 1.2222




K20240710131243





BLK: 8,SNR1: 0.15960 ,SNR2: 1.0968




0834-19 2024/07/10 4.24UT FUJI -KISO



T20240710131751





BLK: 6,SNR1: 3.9064 ,SNR2: 18.272




Frequency (Hz)

F20240710131753




BLK: 6,SNR1:-0.12785 ,SNR2: 1.9817





Frequency (Hz)


0839-071 2024/07/10 4.33UT TOYOKAWA-FUJI



T20240710131751





BLK: 4,SNR1: 1.3008 ,SNR2: 11.317




Frequency (Hz)

K20240710131748




BLK: 4,SNR1: 0.74500 ,SNR2: 3.6812





Frequency (Hz)


0839-071 2024/07/10 4.33UT TOYOKAWA-KISO





F20240710131753




BLK: 4,SNR1: 0.15592 ,SNR2: 1.2530




K20240710131748





BLK: 4,SNR1: 0.31148 ,SNR2: 1.6239




0839-071 2024/07/10 4.33UT FUJI -KISO




T20240710132852




BLK:10,SNR1: 0.27952 ,SNR2: 2.1351




F20240710132854





BLK:10,SNR1: 0.63262 ,SNR2: 2.1771




3C208 2024/07/10 4.51UT TOYOKAWA-FUJI





T20240710132852




BLK: 8,SNR1: 0.29864 ,SNR2: 2.6840




K20240710132849




BLK: 8,SNR1: 1.0745 ,SNR2: 6.5723




3C208 2024/07/10 4.51UT TOYOKAWA-KISO



F20240710132854





BLK: 4,SNR1: 0.98992 ,SNR2: 7.4467





3C208 2024/07/10 4.51UT FUJI -KISO

K20240710132849





BLK: 4,SNR1: 0.24491 ,SNR2: 1.0685








T20240710134533




BLK: 9,SNR1: 0.34804 ,SNR2: 5.8616




F20240710134535





BLK: 9,SNR1: 0.54609 ,SNR2: 5.1500




3C216 2024/07/10 4.79UT TOYOKAWA-FUJI





T20240710134533




BLK:13,SNR1: 0.48046 ,SNR2: 2.1654




K20240710134530




BLK:13,SNR1: 1.4064 ,SNR2: 6.8083




3C216 2024/07/10 4.79UT TOYOKAWA-KISO




F20240710134535




BLK: 6,SNR1: 1.4618 ,SNR2: 5.2346




K20240710134530




BLK: 6,SNR1: 0.60794 ,SNR2: 4.5868




3C216 2024/07/10 4.79UT FUJI -KISO




T20240710135745




BLK: 6,SNR1: 0.16142 ,SNR2: 1.5228




F20240710135747





BLK: 6,SNR1:-0.19839 ,SNR2: 0.62353




0919-142 2024/07/10 4.99UT TOYOKAWA-FUJI





T20240710135745




BLK: 6,SNR1: 0.11673 ,SNR2: 0.59482




K20240710135742





BLK: 6,SNR1: 0.98707 ,SNR2: 4.8683




0919-142 2024/07/10 4.99UT TOYOKAWA-KISO





F20240710135747




BLK: 2,SNR1:-0.44378E-01,SNR2: 0.62417




K20240710135742





BLK: 2,SNR1: 0.68843 ,SNR2: 2.5530




0919-142 2024/07/10 4.99UT FUJI -KISO





T20240710140424




BLK: 7,SNR1: 0.61001 ,SNR2: 3.2342




F20240710140426





BLK: 7,SNR1: 0.33917 ,SNR2: 3.3041




0926+117 2024/07/10 5.10UT TOYOKAWA-FUJI





T20240710140424




BLK:12,SNR1: 1.5959 ,SNR2: 7.4277




K20240710140421





BLK:12,SNR1: 0.90292 ,SNR2: 4.1710






0926+117 2024/07/10 5.10UT TOYOKAWA-KISO









BLK:12,SNR1: 1.1263 ,SNR2: 8.2313




BLK:12,SNR1: 0.25920 ,SNR2: 0.75016






0926+117 2024/07/10 5.10UT FUJI -KISO




T20240710141208





F20240710141210




3C222 2024/07/10 5.23UT TOYOKAWA-FUJI





T20240710141208




BLK:13,SNR1: 4.9407 ,SNR2: 9.6289




K20240710141205





BLK:13,SNR1: 0.54421 ,SNR2: 2.0068




3C222 2024/07/10 5.23UT TOYOKAWA-KISO



F20240710141210





BLK: 4,SNR1: 0.84552 ,SNR2: 2.1655




Frequency (Hz)

K20240710141205




BLK: 4,SNR1: 1.2393 ,SNR2: 5.5732





Frequency (Hz)


3C222 2024/07/10 5.23UT FUJI -KISO




T20240710141908




BLK:15,SNR1: 0.22436 ,SNR2: 1.6437




F20240710141910





BLK:15,SNR1: 0.26205 ,SNR2: 3.2284




0941-08 2024/07/10 5.35UT TOYOKAWA-FUJI





T20240710141908




BLK: 9,SNR1: 0.26896 ,SNR2: 1.1215




K20240710141905




BLK: 9,SNR1: 0.22522 ,SNR2: 1.1806




0941-08 2024/07/10 5.35UT TOYOKAWA-KISO





F20240710141910




BLK: 6,SNR1: 0.20787 ,SNR2: 3.1254




K20240710141905





BLK: 6,SNR1: 0.36279 ,SNR2: 1.7246




0941-08 2024/07/10 5.35UT FUJI -KISO




T20240710142730




BLK:11,SNR1: 0.74142E-01,SNR2: 1.3943




F20240710142732



BLK:11,SNR1:-0.89079E-01,SNR2: 0.95412





3C230 2024/07/10 5.49UT TOYOKAWA-FUJI








T20240710142730




BLK:12,SNR1: 0.17054 ,SNR2: 1.3623




K20240710142727




BLK:12,SNR1: 0.44108 ,SNR2: 2.5458




3C230 2024/07/10 5.49UT TOYOKAWA-KISO




F20240710142732




BLK: 8,SNR1:-0.23594 ,SNR2: 0.53134




K20240710142727





BLK: 8,SNR1: 0.20340 ,SNR2: 0.66832




3C230 2024/07/10 5.49UT FUJI -KISO





T20240710144331




BLK:17,SNR1: 0.35560 ,SNR2: 2.1599




F20240710144333





BLK:17,SNR1: 34.458 ,SNR2: 43.706




3C237 2024/07/10 5.75UT TOYOKAWA-FUJI





T20240710144331




BLK:13,SNR1: 0.35461 ,SNR2: 1.4672




K20240710144328




BLK:13,SNR1: 0.48465 ,SNR2: 2.5210




3C237 2024/07/10 5.75UT TOYOKAWA-KISO





F20240710144333




BLK:13,SNR1: 11.953 ,SNR2: 18.377




K20240710144328





BLK:13,SNR1: 0.36901 ,SNR2: 1.9878




3C237 2024/07/10 5.75UT FUJI -KISO



T20240710144947





BLK:11,SNR1: 0.98062E-01,SNR2: 0.86271




Frequency (Hz)

F20240710144949




BLK:11,SNR1: 0.25016 ,SNR2: 3.3284





Frequency (Hz)


1011+110 2024/07/10 5.86UT TOYOKAWA-FUJI



T20240710144947





BLK:10,SNR1: 0.10683 ,SNR2: 1.5766




Frequency (Hz)

K20240710144944




BLK:10,SNR1: 0.30192 ,SNR2: 2.4290




Frequency (Hz)


1011+110 2024/07/10 5.86UT TOYOKAWA-KISO





F20240710144949




BLK:16,SNR1: 0.23463 ,SNR2: 3.1024




K20240710144944



BLK:16,SNR1: 0.24914 ,SNR2: 1.8679





1011+110 2024/07/10 5.86UT FUJI -KISO








T20240710145728




BLK:13,SNR1: 0.87213E-01,SNR2: 1.3918




F20240710145730





BLK:13,SNR1: 0.65206 ,SNR2: 1.6566




3C241 2024/07/10 5.99UT TOYOKAWA-FUJI




T20240710145728




BLK:18,SNR1: 0.17200 ,SNR2: 0.99834




K20240710145725





BLK:18,SNR1: 1.3508 ,SNR2: 5.9858




3C241 2024/07/10 5.99UT TOYOKAWA-KISO



F20240710145730





BLK:14,SNR1: 0.43669 ,SNR2: 2.6438




Frequency (Hz)

K20240710145725




BLK:14,SNR1: 2.3335 ,SNR2: 10.726





Frequency (Hz)


3C241 2024/07/10 5.99UT FUJI -KISO





T20240710150857




BLK: 6,SNR1: 0.20141E-01,SNR2: 0.61385




F20240710150859





BLK: 6,SNR1:-0.24080,SNR2: 0.67439




1031-11 2024/07/10 6.18UT TOYOKAWA-FUJI





T20240710150857




BLK:12,SNR1: 0.10387 ,SNR2: 0.64705




K20240710150854





BLK:12,SNR1: 1.8369 ,SNR2: 10.086




1031-11 2024/07/10 6.18UT TOYOKAWA-KISO





F20240710150859




BLK: 5,SNR1:-0.27873 ,SNR2: 1.1319




K20240710150854





BLK: 5,SNR1: 0.20149 ,SNR2: 1.6892




1031-11 2024/07/10 6.18UT FUJI -KISO



T20240710151331





BLK:10,SNR1: 1.2495 ,SNR2: 10.131




Frequency (Hz)

F20240710151333




BLK:10,SNR1: 0.21859E-02,SNR2: 1.2487





Frequency (Hz)


1035-058 2024/07/10 6.25UT TOYOKAWA-FUJI



T20240710151331





BLK: 7,SNR1: 0.50083 ,SNR2: 4.4833




Frequency (Hz)

K20240710151328




BLK: 7,SNR1: 0.81928 ,SNR2: 3.1031




Frequency (Hz)

1035-058 2024/07/10 6.25UT TOYOKAWA-KISO






F20240710151333





BLK:11,SNR1: 0.10214 ,SNR2: 2.4830




Frequency (Hz)

K20240710151328




BLK:11,SNR1: 0.55373 ,SNR2: 2.5591




Frequency (Hz)


1035-058 2024/07/10 6.25UT FUJI -KISO



T20240710152244





BLK: 9,SNR1: 0.23803 ,SNR2: 0.83660




Frequency (Hz)

F20240710152246




BLK: 9,SNR1:-0.37036E-01,SNR2: 1.6810





Frequency (Hz)


1044-008 2024/07/10 6.41UT TOYOKAWA-FUJI





T20240710152244




BLK:11,SNR1: 0.14517 ,SNR2: 0.96018




K20240710152241




BLK:11,SNR1: 2.7294 ,SNR2: 5.9257




1044-008 2024/07/10 6.41UT TOYOKAWA-KISO




F20240710152246




BLK: 5,SNR1: 0.22752 ,SNR2: 1.7564




K20240710152241





BLK: 5,SNR1: 0.57249 ,SNR2: 6.3441




1044-008 2024/07/10 6.41UT FUJI -KISO





T20240710153348




BLK:10,SNR1: 0.11687 ,SNR2: 1.6488




F20240710153350





BLK:10,SNR1: 0.67782 ,SNR2: 2.1418




1055+01 2024/07/10 6.59UT TOYOKAWA-FUJI





T20240710153348




BLK: 8,SNR1: 0.77357E-01,SNR2: 1.5023




K20240710153346




BLK: 8,SNR1: 17.740 ,SNR2: 33.318




1055+01 2024/07/10 6.59UT TOYOKAWA-KISO



F20240710153350





BLK: 7,SNR1: 0.85284 ,SNR2: 2.0524




Frequency (Hz)

K20240710153346




BLK: 7,SNR1: 0.15468 ,SNR2: 0.98703





Frequency (Hz)


1055+01 2024/07/10 6.59UT FUJI -KISO



T20240710154506




BLK: 3,SNR1: 0.27615 ,SNR2: 0.85234




Frequency (Hz)

F20240710154508




BLK: 3,SNR1: 0.68968 ,SNR2: 2.5177





Frequency (Hz)

1107+109 2024/07/10 6.78UT TOYOKAWA-FUJI






T20240710154506





BLK: 4,SNR1: 0.13674 ,SNR2: 0.41228




Frequency (Hz)

K20240710154504




BLK: 4,SNR1: 2.3021 ,SNR2: 7.0346




Frequency (Hz)




1107+109 2024/07/10 6.78UT TOYOKAWA-KISO




F20240710154508





K20240710154504




1107+109 2024/07/10 6.78UT FUJI -KISO



T20240710155443





BLK: 1,SNR1:-0.19804 ,SNR2: 0.41199




Frequency (Hz)

F20240710155445




BLK: 1,SNR1: 0.35671 ,SNR2: 2.1264





Frequency (Hz)


3C255 2024/07/10 6.94UT TOYOKAWA-FUJI





T20240710155443




BLK:11,SNR1: 0.98069E-01,SNR2: 0.91809




K20240710155440





BLK:11,SNR1: 0.34817 ,SNR2: 1.5661




3C255 2024/07/10 6.94UT TOYOKAWA-KISO



F20240710155445





BLK: 8,SNR1: 0.33317 ,SNR2: 4.1937




Frequency (Hz)

K20240710155440




BLK: 8,SNR1: 3.4906 ,SNR2: 13.487





Frequency (Hz)


3C255 2024/07/10 6.94UT FUJI -KISO





T20240710160521




BLK: 5,SNR1: 0.40656E-02,SNR2: 0.59637




F20240710160523





BLK: 5,SNR1: 0.27708E-01,SNR2: 4.6190




1127-14 2024/07/10 7.12UT TOYOKAWA-FUJI





T20240710160521




BLK: 7,SNR1: 0.76653E-02,SNR2: 0.72646




K20240710160518





BLK: 7,SNR1: 0.48729 ,SNR2: 1.9098




1127-14 2024/07/10 7.12UT TOYOKAWA-KISO





F20240710160523




BLK: 3,SNR1: 0.90318E-01,SNR2: 5.2194




K20240710160518



BLK: 3,SNR1: 0.29949 ,SNR2: 5.9549




1127-14 2024/07/10 7.12UT FUJI -KISO







T20240710161841




BLK:15,SNR1: 3.8076 ,SNR2: 22.294




F20240710161843




BLK:15,SNR1: 0.28145 ,SNR2: 3.1780




3C263.1 2024/07/10 7.34UT TOYOKAWA-FUJI



T20240710161841





BLK:23,SNR1: 3.1013 ,SNR2: 18.534




Frequency (Hz)

K20240710161838








BLK:23,SNR1: 0.54563 ,SNR2: 2.4713




Frequency (Hz)

3C263.1 2024/07/10 7.34UT TOYOKAWA-KISO








3C263.1 2024/07/10 7.34UT FUJI -KISO



T20240710162508





BLK:13,SNR1: 2.5175 ,SNR2: 6.4469




Frequency (Hz)

F20240710162510




BLK:13,SNR1: 0.92431 ,SNR2: 2.3660





Frequency (Hz)


3C267 2024/07/10 7.45UT TOYOKAWA-FUJI



T20240710162508





BLK:11,SNR1: 1.3646 ,SNR2: 9.8607




Frequency (Hz)

K20240710162506




BLK:11,SNR1: 0.12082 ,SNR2: 1.7592





Frequency (Hz)


3C267 2024/07/10 7.45UT TOYOKAWA-KISO





F20240710162510




BLK:11,SNR1: 0.40454 ,SNR2: 2.3433




K20240710162506





BLK:11,SNR1: 3.7585 ,SNR2: 5.4639




3C267 2024/07/10 7.45UT FUJI -KISO



T20240710164422





BLK:18,SNR1: 72.507 ,SNR2: 147.22




Frequency (Hz)

F20240710164424




BLK:18,SNR1: 0.82451 ,SNR2: 3.3781





Frequency (Hz)


1206+439 2024/07/10 7.77UT TOYOKAWA-FUJI



T20240710164422





BLK:18,SNR1: 82.677 ,SNR2: 236.40




Frequency (Hz)

K20240710164419




BLK:18,SNR1: 6.0596 ,SNR2: 8.0666





Frequency (Hz)

1206+439 2024/07/10 7.77UT TOYOKAWA-KISO






F20240710164424





BLK:20,SNR1: 5.7418 ,SNR2: 7.6111




Frequency (Hz)

K20240710164419




BLK:20,SNR1: 6.2841 ,SNR2: 8.1547





Frequency (Hz)


1206+439 2024/07/10 7.77UT FUJI -KISO



T20240710170413





BLK:11,SNR1: 0.25847 ,SNR2: 1.3677




Frequency (Hz)

F20240710170415




BLK:11,SNR1: 1.3987 ,SNR2: 4.8890





Frequency (Hz)


3C273 2024/07/10 8.10UT TOYOKAWA-FUJI



T20240710170413





BLK:12,SNR1: 0.16230 ,SNR2: 0.97510




Frequency (Hz)

K20240710170410




BLK:12,SNR1: 0.67014 ,SNR2: 3.5542





Frequency (Hz)


3C273 2024/07/10 8.10UT TOYOKAWA-KISO



F20240710170415





BLK:11,SNR1: 4.2405 ,SNR2: 10.749




Frequency (Hz)

K20240710170410




BLK:11,SNR1: 1.2514 ,SNR2: 3.8712





Frequency (Hz)


3C273 2024/07/10 8.10UT FUJI -KISO



T20240710175100




BLK: 2,SNR1: 0.64995E-01,SNR2: 0.0000




Frequency (Hz)

F20240710175102




BLK: 2,SNR1: 0.62484 ,SNR2: 4.0637





Frequency (Hz)


1313+453 2024/07/10 8.88UT TOYOKAWA-FUJI



T20240710175100





BLK: 3,SNR1:-0.26772E-01,SNR2: 0.55673




Frequency (Hz)

K20240710175057




BLK: 3,SNR1: 0.42078 ,SNR2: 4.2508





Frequency (Hz)


1313+453 2024/07/10 8.88UT TOYOKAWA-KISO



F20240710175102




BLK: 6,SNR1: 0.54120 ,SNR2: 4.6340




Frequency (Hz)

K20240710175057




BLK: 6,SNR1: 0.15829 ,SNR2: 3.9800





Frequency (Hz)


1313+453 2024/07/10 8.88UT FUJI -KISO



T20240710181219





BLK:20,SNR1: 7.8375 ,SNR2: 13.934




Frequency (Hz)

F20240710181221




BLK:20,SNR1: 2.4939 ,SNR2: 12.128





Frequency (Hz)

1335+479 2024/07/10 9.23UT TOYOKAWA-FUJI






T20240710181219





BLK:16,SNR1: 9.1242 ,SNR2: 16.078




Frequency (Hz)

K20240710181216




BLK:16,SNR1: 11.096 ,SNR2: 25.745




Frequency (Hz)


1335+479 2024/07/10 9.23UT TOYOKAWA-KISO



F20240710181221





BLK:20,SNR1: 2.4962 ,SNR2: 12.138




Frequency (Hz)

K20240710181216




BLK:20,SNR1: 11.065 ,SNR2: 25.674





Frequency (Hz)


1335+479 2024/07/10 9.23UT FUJI -KISO



T20240710181625




BLK:24,SNR1: 3.0196 ,SNR2: 14.226




Frequency (Hz)

F20240710181627




BLK:24,SNR1: 6.1825 ,SNR2: 15.563





Frequency (Hz)


1339+472 2024/07/10 9.30UT TOYOKAWA-FUJI



T20240710181625





BLK:31,SNR1: 3.0268 ,SNR2: 14.255




Frequency (Hz)

K20240710181622




BLK:31,SNR1: 8.2980 ,SNR2: 21.633




Frequency (Hz)


1339+472 2024/07/10 9.30UT TOYOKAWA-KISO



F20240710181627





BLK:27,SNR1: 6.0553 ,SNR2: 15.062




Frequency (Hz)

K20240710181622



BLK:27,SNR1: 8.3390 ,SNR2: 21.740



Frequency (Hz)

1339+472 2024/07/10 9.30UT FUJI -KISO

