





T20240720055317




BLK:17,SNR1: 7.5497 ,SNR2: 21.610




F20240720055319





BLK:17,SNR1: 6.4834 ,SNR2: 16.263




0152+435 2024/07/19 20.92UT TOYOKAWA-FUJI



T20240720055317





BLK:12,SNR1: 7.5287 ,SNR2: 21.541




Frequency (Hz)

K20240720055314




BLK:12,SNR1: 14.084 ,SNR2: 28.357




Frequency (Hz)

0152+435 2024/07/19 20.92UT TOYOKAWA-KISO






F20240720055319




BLK:10,SNR1: 0.93425 ,SNR2: 3.2523




Frequency (Hz)

K20240720055314




BLK:10,SNR1: 13.575 ,SNR2: 31.525





Frequency (Hz)


0152+435 2024/07/19 20.92UT FUJI -KISO



T20240720062149



BLK:10,SNR1: 0.24723 ,SNR2: 1.4534





Frequency (Hz)


3C67

2024/07/19 21.39UT TOYOKAWA-FUJI


F20240720062151





BLK:10,SNR1: 0.75579 ,SNR2: 2.7612




Frequency (Hz)



T20240720062149





BLK:13,SNR1: 0.19958 ,SNR2: 1.5526




Frequency (Hz)

3C67 2024/07/19 21.39UT TOYOKAWA-KISO


K20240720062146





BLK:13,SNR1: 81.370 ,SNR2: 80.187




Frequency (Hz)



F20240720062151



BLK:15,SNR1: 0.81089 ,SNR2: 2.9753





Frequency (Hz)


3C67

2024/07/19 21.39UT FUJI -KISO


K20240720062146





BLK:15,SNR1: 4.9743 ,SNR2: 23.033




Frequency (Hz)



T20240720065919





BLK:36,SNR1: 21.712 ,SNR2: 39.978




Frequency (Hz)

F20240720065921




BLK:36,SNR1: 30.039 ,SNR2: 46.650





Frequency (Hz)


0258+350 2024/07/19 22.02UT TOYOKAWA-FUJI



T20240720065919





BLK:34,SNR1: 21.716 ,SNR2: 39.984




Frequency (Hz)

K20240720065916




BLK:34,SNR1: 12.409 ,SNR2: 30.319





Frequency (Hz)


0258+350 2024/07/19 22.02UT TOYOKAWA-KISO



F20240720065921





BLK:33,SNR1: 30.054 ,SNR2: 46.674




Frequency (Hz)

K20240720065916




BLK:33,SNR1: 12.338 ,SNR2: 30.150





Frequency (Hz)


0258+350 2024/07/19 22.02UT FUJI -KISO



T20240720070908





BLK:12,SNR1: 6.1415 ,SNR2: 15.106




Frequency (Hz)

F20240720070910




BLK:12,SNR1: 1.2415 ,SNR2: 6.6070





Frequency (Hz)

0308+305 2024/07/19 22.18UT TOYOKAWA-FUJI






T20240720070908





BLK:21,SNR1: 4.7049 ,SNR2: 11.678




Frequency (Hz)

K20240720070905




BLK:21,SNR1: 5.2053 ,SNR2: 12.782





Frequency (Hz)


0308+305 2024/07/19 22.18UT TOYOKAWA-KISO



F20240720070910




BLK:28,SNR1: 4.3338 ,SNR2: 7.3892




Frequency (Hz)

K20240720070905




BLK:28,SNR1: 5.6539 ,SNR2: 13.762




Frequency (Hz)


0308+305 2024/07/19 22.18UT FUJI -KISO



T20240720072040




BLK:23,SNR1: 5.5714 ,SNR2: 14.133




Frequency (Hz)

F20240720072042




BLK:23,SNR1: 4.8040 ,SNR2: 12.495





Frequency (Hz)


0320+05 2024/07/19 22.37UT TOYOKAWA-FUJI



T20240720072040





BLK:26,SNR1: 5.1719 ,SNR2: 13.141




Frequency (Hz)

K20240720072037




BLK:26,SNR1: 8.2024 ,SNR2: 20.568





Frequency (Hz)


0320+05 2024/07/19 22.37UT TOYOKAWA-KISO



F20240720072042





BLK:23,SNR1: 5.3286 ,SNR2: 13.990




Frequency (Hz)

K20240720072037




BLK:23,SNR1: 8.7466 ,SNR2: 22.166





Frequency (Hz)


0320+05 2024/07/19 22.37UT FUJI -KISO



T20240720073401





BLK:32,SNR1: 2.8429 ,SNR2: 13.541




Frequency (Hz)

F20240720073403




BLK:32,SNR1: 7.6689 ,SNR2: 19.111





Frequency (Hz)


0333+32 2024/07/19 22.60UT TOYOKAWA-FUJI



T20240720073401





BLK:34,SNR1: 2.8424 ,SNR2: 13.539




Frequency (Hz)

K20240720073358




BLK:34,SNR1: 6.0600 ,SNR2: 10.921





Frequency (Hz)


0333+32 2024/07/19 22.60UT TOYOKAWA-KISO



F20240720073403





BLK:36,SNR1: 7.6984 ,SNR2: 19.175




Frequency (Hz)

K20240720073358




BLK:36,SNR1: 6.1542 ,SNR2: 11.085





Frequency (Hz)

0333+32 2024/07/19 22.60UT FUJI -KISO






T20240720074703




BLK: 3,SNR1:-0.45759E-01,SNR2: 0.45361




Frequency (Hz)

F20240720074705




BLK: 3,SNR1: 0.11291 ,SNR2: 3.1812




Frequency (Hz)


0347+05 2024/07/19 22.81UT TOYOKAWA-FUJI



T20240720074703




BLK: 2,SNR1: 0.13367 ,SNR2: 0.99797




Frequency (Hz)

K20240720074700




BLK: 2,SNR1: 0.36815 ,SNR2: 3.8727




Frequency (Hz)


0347+05 2024/07/19 22.81UT TOYOKAWA-KISO





F20240720074705




BLK: 4,SNR1: 0.26001E-01,SNR2: 1.2226




K20240720074700





BLK: 4,SNR1: 0.36299 ,SNR2: 1.7348




0347+05 2024/07/19 22.81UT FUJI -KISO



T20240720080238





BLK: 6,SNR1: 0.24980 ,SNR2: 2.4153




Frequency (Hz)

F20240720080240




BLK: 6,SNR1:-0.22544 ,SNR2: 0.60932





Frequency (Hz)


0403-132 2024/07/19 23.07UT TOYOKAWA-FUJI



T20240720080238





BLK: 4,SNR1: 0.35522 ,SNR2: 1.8768




Frequency (Hz)

K20240720080235




BLK: 4,SNR1: 4.7493 ,SNR2: 7.3589





Frequency (Hz)


0403-132 2024/07/19 23.07UT TOYOKAWA-KISO



F20240720080240





BLK: 3,SNR1: 0.60524 ,SNR2: 1.4506




Frequency (Hz)

K20240720080235




BLK: 3,SNR1: 0.98249E-01,SNR2: 1.5091





Frequency (Hz)


0403-132 2024/07/19 23.07UT FUJI -KISO



T20240720081148





BLK: 8,SNR1: 0.17304 ,SNR2: 0.82173




Frequency (Hz)

F20240720081150




BLK: 8,SNR1: 0.27407 ,SNR2: 3.3291





Frequency (Hz)


0411+05 2024/07/19 23.22UT TOYOKAWA-FUJI



T20240720081148





BLK: 7,SNR1: 0.14582 ,SNR2: 1.8447




Frequency (Hz)

K20240720081145




BLK: 7,SNR1: 2.7782 ,SNR2: 5.1284





Frequency (Hz)

0411+05 2024/07/19 23.22UT TOYOKAWA-KISO






F20240720081150





BLK: 8,SNR1: 0.40436 ,SNR2: 3.3756




Frequency (Hz)

K20240720081145




BLK: 8,SNR1: 0.17177 ,SNR2: 0.77842





Frequency (Hz)


0411+05 2024/07/19 23.22UT FUJI -KISO



T20240720081842




BLK:22,SNR1: 1.5912 ,SNR2: 4.9194




Frequency (Hz)

F20240720081844




BLK:22,SNR1: 2.3953 ,SNR2: 8.2117




Frequency (Hz)


0418+236 2024/07/19 23.34UT TOYOKAWA-FUJI



T20240720081842




BLK:21,SNR1: 1.6148 ,SNR2: 5.0671




Frequency (Hz)

K20240720081839




BLK:21,SNR1: 5.4150 ,SNR2: 13.032





Frequency (Hz)


0418+236 2024/07/19 23.34UT TOYOKAWA-KISO



F20240720081844





BLK:21,SNR1: 2.6291 ,SNR2: 9.0108




Frequency (Hz)

K20240720081839




BLK:21,SNR1: 1.3408 ,SNR2: 4.1425




Frequency (Hz)


0418+236 2024/07/19 23.34UT FUJI -KISO





T20240720083009




BLK:15,SNR1: 2.5719 ,SNR2: 8.5174




F20240720083011




BLK:15,SNR1: 0.95339 ,SNR2: 3.0469




3C119 2024/07/19 23.53UT TOYOKAWA-FUJI




T20240720083009




BLK:19,SNR1: 2.0276 ,SNR2: 6.6898




K20240720083006





BLK:19,SNR1: 8.0912 ,SNR2: 7.1850




3C119 2024/07/19 23.53UT TOYOKAWA-KISO




F20240720083011




BLK:20,SNR1: 8.5099 ,SNR2: 19.742




K20240720083006




BLK:20,SNR1: 21.736 ,SNR2: 23.470




3C119 2024/07/19 23.53UT FUJI -KISO



T20240720085358





BLK:11,SNR1: 0.22090 ,SNR2: 2.2444




Frequency (Hz)

F20240720085400




BLK:11,SNR1: 1.0614 ,SNR2: 8.5824





Frequency (Hz)

0453+227 2024/07/19 23.93UT TOYOKAWA-FUJI






T20240720085358





BLK:16,SNR1: 0.11119 ,SNR2: 1.3948




Frequency (Hz)

K20240720085355




BLK:16,SNR1: 3.3013 ,SNR2: 11.479




Frequency (Hz)


0453+227 2024/07/19 23.93UT TOYOKAWA-KISO



F20240720085400




BLK:20,SNR1: 2.5867 ,SNR2: 8.9150




Frequency (Hz)

K20240720085355




BLK:20,SNR1: 0.32027 ,SNR2: 1.1045




Frequency (Hz)


0453+227 2024/07/19 23.93UT FUJI -KISO



T20240720091817





BLK:23,SNR1: 1.0704 ,SNR2: 4.6697





3C138 2024/07/20 0.33UT TOYOKAWA-FUJI


F20240720091819




BLK:23,SNR1: 0.24068 ,SNR2: 3.3188



T20240720091817




BLK:28,SNR1: 1.1073 ,SNR2: 5.6309




Frequency (Hz)

3C138 2024/07/20 0.33UT TOYOKAWA-KISO


K20240720091814




BLK:28,SNR1: 2.5779 ,SNR2: 10.480




Frequency (Hz)



F20240720091819




BLK:15,SNR1: 8.8294 ,SNR2: 20.728





3C138 2024/07/20 0.33UT FUJI -KISO


K20240720091814




BLK:15,SNR1: 2.2518 ,SNR2: 9.2789



T20240720093150




BLK:12,SNR1: 0.65858 ,SNR2: 3.6828





0531+194 2024/07/20 0.56UT TOYOKAWA-FUJI


F20240720093152




BLK:12,SNR1: 0.10283 ,SNR2: 1.1634



T20240720093150




BLK:22,SNR1: 0.62742 ,SNR2: 3.3209





0531+194 2024/07/20 0.56UT TOYOKAWA-KISO


K20240720093147




BLK:22,SNR1: 0.11938 ,SNR2: 0.78490




F20240720093152




BLK:12,SNR1:-0.83195E-01,SNR2: 1.2465




K20240720093147



BLK:12,SNR1: 2.6460 ,SNR2: 11.043





0531+194 2024/07/20 0.56UT FUJI -KISO








T20240720094010




BLK:20,SNR1: 19.238 ,SNR2: 77.991




F20240720094012





BLK:20,SNR1: 0.12775 ,SNR2: 2.8461




3C147 2024/07/20 0.70UT TOYOKAWA-FUJI





T20240720094010




BLK:18,SNR1: 16.945 ,SNR2: 49.757




K20240720094008





BLK:18,SNR1: 52.188 ,SNR2: 64.604




3C147 2024/07/20 0.70UT TOYOKAWA-KISO





F20240720094012




BLK:14,SNR1: 0.95326E-01,SNR2: 2.7136




K20240720094008





BLK:14,SNR1: 69.575 ,SNR2: 65.393




3C147 2024/07/20 0.70UT FUJI -KISO



T20240720094821




BLK: 9,SNR1: 0.31537 ,SNR2: 3.3946





0548+16 2024/07/20 0.83UT TOYOKAWA-FUJI



F20240720094823




BLK: 9,SNR1:-0.25462 ,SNR2: 0.94396



T20240720094821





BLK:14,SNR1: 0.39168 ,SNR2: 1.8021




Frequency (Hz)

K20240720094818




BLK:14,SNR1: 2.1455 ,SNR2: 8.6667





Frequency (Hz)


0548+16 2024/07/20 0.83UT TOYOKAWA-KISO





F20240720094823




BLK: 7,SNR1: 0.79872E-01,SNR2: 1.3249




K20240720094818




BLK: 7,SNR1: 0.38535 ,SNR2: 2.2177




0548+16 2024/07/20 0.83UT FUJI -KISO



T20240720095232




BLK: 6,SNR1: 0.16883 ,SNR2: 4.4618




Frequency (Hz)

F20240720095234




BLK: 6,SNR1: 0.18152 ,SNR2: 3.6090





Frequency (Hz)


0552+12 2024/07/20 0.90UT TOYOKAWA-FUJI



T20240720095232




BLK: 9,SNR1: 0.20953 ,SNR2: 2.4432




Frequency (Hz)

K20240720095230




BLK: 9,SNR1: 0.49190 ,SNR2: 1.9621




Frequency (Hz)

0552+12 2024/07/20 0.90UT TOYOKAWA-KISO







F20240720095234




BLK:10,SNR1: 0.55539 ,SNR2: 5.1298




K20240720095230




BLK:10,SNR1: 0.34617 ,SNR2: 1.6127




0552+12 2024/07/20 0.90UT FUJI -KISO



T20240720095659




BLK: 6,SNR1: 0.16328 ,SNR2: 1.3109




Frequency (Hz)

F20240720095701




BLK: 6,SNR1:-0.10843 ,SNR2: 1.2859





Frequency (Hz)


0556+191 2024/07/20 0.98UT TOYOKAWA-FUJI



T20240720095659





BLK:10,SNR1: 0.12101 ,SNR2: 1.0495





0556+191 2024/07/20 0.98UT TOYOKAWA-KISO


K20240720095657




BLK:10,SNR1: 1.1339 ,SNR2: 8.2958



F20240720095701





BLK: 7,SNR1:-0.17924 ,SNR2: 0.67125




Frequency (Hz)

K20240720095657




BLK: 7,SNR1: 15.203 ,SNR2: 28.605




Frequency (Hz)


0556+191 2024/07/20 0.98UT FUJI -KISO




T20240720100445




BLK: 3,SNR1: 0.86968E-01,SNR2: 0.47830




F20240720100447




BLK: 3,SNR1:-0.16820 ,SNR2: 0.0000




0605-08 2024/07/20 1.11UT TOYOKAWA-FUJI



T20240720100445





BLK: 6,SNR1:-0.21160E-01,SNR2: 0.24899





0605-08 2024/07/20 1.11UT TOYOKAWA-KISO


K20240720100442




BLK: 6,SNR1: 21.806 ,SNR2: 24.469





F20240720100447




BLK: 7,SNR1: 0.19226 ,SNR2: 3.5383




K20240720100442




BLK: 7,SNR1: 20.398 ,SNR2: 23.413




0605-08 2024/07/20 1.11UT FUJI -KISO



T20240720102353




BLK:20,SNR1: 1.5781 ,SNR2: 18.387




Frequency (Hz)

3C161 2024/07/20 1.43UT TOYOKAWA-FUJI


F20240720102355



BLK:20,SNR1: 0.14632E-01,SNR2: 1.9701




Frequency (Hz)






T20240720102353




BLK:30,SNR1: 1.8246 ,SNR2: 20.069





3C161 2024/07/20 1.43UT TOYOKAWA-KISO


K20240720102351




BLK:30,SNR1: 0.53333 ,SNR2: 4.8997





F20240720102355




BLK:15,SNR1:-0.66270E-01,SNR2: 1.9790




K20240720102351





BLK:15,SNR1: 0.65055 ,SNR2: 6.9813




3C161 2024/07/20 1.43UT FUJI -KISO





T20240720105126




BLK: 5,SNR1: 0.39394 ,SNR2: 1.4874




F20240720105128





BLK: 5,SNR1:-0.21867 ,SNR2: 0.10407




0652-130 2024/07/20 1.89UT TOYOKAWA-FUJI



T20240720105126





BLK: 4, SNR1: 0.16801 , SNR2: 1.7569




Frequency (Hz)

K20240720105123




BLK: 4, SNR1: 0.12832 , SNR2: 0.31963





Frequency (Hz)


0652-130 2024/07/20 1.89UT TOYOKAWA-KISO





F20240720105128




BLK: 9,SNR1: 0.98271 ,SNR2: 5.0518




K20240720105123





BLK: 9,SNR1: 8.6427 ,SNR2: 30.776




0652-130 2024/07/20 1.89UT FUJI -KISO





T20240720110302




BLK: 7,SNR1: 0.10085 ,SNR2: 0.70101




F20240720110304





BLK: 7,SNR1: 0.43223E-01,SNR2: 1.4294




0703+138 2024/07/20 2.08UT TOYOKAWA-FUJI



T20240720110302





BLK: 9,SNR1: 0.46548E-02,SNR2: 0.47877




Frequency (Hz)

K20240720110259




BLK: 9,SNR1: 0.29763 ,SNR2: 2.4718




Frequency (Hz)


0703+138 2024/07/20 2.08UT TOYOKAWA-KISO





F20240720110304




BLK: 6,SNR1: 0.41536E-01,SNR2: 1.8210




K20240720110259



BLK: 6,SNR1: 0.28576 ,SNR2: 1.7597





0703+138 2024/07/20 2.08UT FUJI -KISO







T20240720111225




BLK: 8,SNR1: 0.23875 ,SNR2: 2.9282




F20240720111227





BLK: 8,SNR1: 0.55988E-01,SNR2: 1.2770




0713-024 2024/07/20 2.24UT TOYOKAWA-FUJI



T20240720111225




BLK:15,SNR1: 0.27034 ,SNR2: 3.4690





0713-024 2024/07/20 2.24UT TOYOKAWA-KISO


K20240720111222




BLK:15,SNR1: 0.49061 ,SNR2: 4.5750




F20240720111227




BLK: 5,SNR1: 0.14259 ,SNR2: 1.2039




K20240720111227




BLK: 5,SNR1: 0.17930 ,SNR2: 1.8836




0713-024 2024/07/20 2.24UT FUJI -KISO




T20240720112236




BLK:14,SNR1: 0.59146 ,SNR2: 3.1335




F20240720112238




BLK:14,SNR1: 0.28618 ,SNR2: 1.3082




0723+10 2024/07/20 2.40UT TOYOKAWA-FUJI





T20240720112236




BLK:23,SNR1: 0.76408 ,SNR2: 3.5284




K20240720112233




BLK:23,SNR1: 0.29007 ,SNR2: 0.85892




0723+10 2024/07/20 2.40UT TOYOKAWA-KISO




F20240720112238




BLK:12,SNR1: 0.27558 ,SNR2: 1.6964




K20240720112233





BLK:12,SNR1: 0.24412 ,SNR2: 2.0880




0723+10 2024/07/20 2.40UT FUJI -KISO



T20240720113251





BLK:10,SNR1: 0.41224 ,SNR2: 3.3280




Frequency (Hz)

F20240720113253




BLK:10,SNR1:-0.62466E-01,SNR2: 1.4239





Frequency (Hz)


0732+33 2024/07/20 2.58UT TOYOKAWA-FUJI



T20240720113251





BLK:20,SNR1: 0.51457 ,SNR2: 3.5812




Frequency (Hz)

0732+33 2024/07/20 2.58UT TOYOKAWA-KISO


K20240720113248



BLK:20,SNR1: 0.47466 ,SNR2: 2.7713





Frequency (Hz)







F20240720113253




BLK:15,SNR1: 3.5127 ,SNR2: 9.6937




K20240720113248




BLK:15,SNR1: 0.66962 ,SNR2: 3.9484




0732+33 2024/07/20 2.58UT FUJI -KISO



T20240720114053




BLK:18,SNR1: 2.1413 ,SNR2: 12.563




0741-06 2024/07/20 2.71UT TOYOKAWA-FUJI


F20240720114055




BLK:18,SNR1: 0.24017 ,SNR2: 1.4885




Frequency (Hz)




T20240720114053




BLK:29,SNR1: 2.0688 ,SNR2: 12.620




K20240720114050




BLK:29,SNR1: 0.67035 ,SNR2: 1.9444




0741-06 2024/07/20 2.71UT TOYOKAWA-KISO




F20240720114055




BLK:19,SNR1: 0.94268E-01,SNR2: 1.8619




K20240720114050





BLK:19,SNR1: 0.78705 ,SNR2: 2.2824




0741-06 2024/07/20 2.71UT FUJI -KISO



T20240720115037




BLK:26,SNR1: 275.09 ,SNR2: 324.67





0752-200 2024/07/20 2.87UT TOYOKAWA-FUJI


F20240720115039




BLK:26,SNR1: 0.76622 ,SNR2: 4.1909





T20240720115037




BLK:17,SNR1: 327.03 ,SNR2: 499.20




K20240720115034




BLK:17,SNR1: 0.45766 ,SNR2: 2.6265




0752-200 2024/07/20 2.87UT TOYOKAWA-KISO





F20240720115039




BLK: 8,SNR1: 2.0801 ,SNR2: 11.361




K20240720115034




BLK: 8,SNR1: 0.76015 ,SNR2: 3.1383




0752-200 2024/07/20 2.87UT FUJI -KISO





T20240720115812




BLK:30,SNR1: 40.460 ,SNR2: 78.249




F20240720115814



BLK:30,SNR1: 7.4138 ,SNR2: 24.768




3C190 2024/07/20 3.00UT TOYOKAWA-FUJI








T20240720115812




BLK:26,SNR1: 47.977 ,SNR2: 91.020




K20240720115810




BLK:26,SNR1: 5.4564 ,SNR2: 22.294




3C190 2024/07/20 3.00UT TOYOKAWA-KISO




F20240720115814




BLK:27,SNR1: 8.6299 ,SNR2: 28.740




K20240720115810





BLK:27,SNR1: 5.2522 ,SNR2: 20.584




3C190 2024/07/20 3.00UT FUJI -KISO



T20240720121037




BLK:11,SNR1: 3.1157 ,SNR2: 6.2341




Frequency (Hz)

F20240720121039




BLK:11,SNR1:-0.52945E-01,SNR2: 1.0630





Frequency (Hz)


3C196 2024/07/20 3.21UT TOYOKAWA-FUJI



T20240720121037





BLK:15,SNR1: 6.3705 ,SNR2: 18.707




Frequency (Hz)

K20240720121034




BLK:15,SNR1: 0.42591 ,SNR2: 1.3092




Frequency (Hz)


3C196 2024/07/20 3.21UT TOYOKAWA-KISO





F20240720121039




BLK: 9,SNR1:-0.11956 ,SNR2: 1.7269




K20240720121034




BLK: 9,SNR1: 0.25990 ,SNR2: 0.62883




3C196 2024/07/20 3.21UT FUJI -KISO




T20240720122146




BLK:10,SNR1: 0.42360 ,SNR2: 4.3182




F20240720122148




BLK:10,SNR1: 0.38878 ,SNR2: 1.2848




0821+394 2024/07/20 3.39UT TOYOKAWA-FUJI




T20240720122146




BLK:18,SNR1: 0.45599 ,SNR2: 3.1566




K20240720122143




BLK:18,SNR1: 1.0224 ,SNR2: 4.1007




0821+394 2024/07/20 3.39UT TOYOKAWA-KISO





F20240720122148




BLK:11,SNR1: 0.24417 ,SNR2: 1.1948




K20240720122143



BLK:11,SNR1: 1.0465 ,SNR2: 4.1489




0821+394 2024/07/20 3.39UT FUJI -KISO







T20240720123327




BLK:13,SNR1: 0.58472 ,SNR2: 3.7834




F20240720123329





BLK:13,SNR1: 0.20109 ,SNR2: 1.2574




0834-19 2024/07/20 3.59UT TOYOKAWA-FUJI





T20240720123327




BLK:15,SNR1: 0.30275 ,SNR2: 2.9834




K20240720123324




BLK:15,SNR1: 0.62207 ,SNR2: 1.9200




0834-19 2024/07/20 3.59UT TOYOKAWA-KISO





F20240720123329




BLK: 3,SNR1: 0.14983 ,SNR2: 0.77080




K20240720123324




BLK: 3,SNR1: 1.8635 ,SNR2: 6.6835




0834-19 2024/07/20 3.59UT FUJI -KISO




T20240720123832




BLK:11,SNR1: 0.65397 ,SNR2: 2.8064




F20240720123834




BLK:11,SNR1: 0.49396 ,SNR2: 5.3628




0839-071 2024/07/20 3.67UT TOYOKAWA-FUJI




T20240720123832




BLK:19,SNR1: 0.37668 ,SNR2: 1.7803




K20240720123829




BLK:19,SNR1: 1.9712 ,SNR2: 7.7280




0839-071 2024/07/20 3.67UT TOYOKAWA-KISO





F20240720123834




BLK:14,SNR1: 0.46132 ,SNR2: 4.9532




K20240720123829





BLK:14,SNR1: 2.5853 ,SNR2: 9.9153




0839-071 2024/07/20 3.67UT FUJI -KISO




T20240720124933




BLK: 9,SNR1: 0.20457 ,SNR2: 1.1198




F20240720124935





BLK: 9,SNR1: 0.11403 ,SNR2: 0.61166




3C208 2024/07/20 3.85UT TOYOKAWA-FUJI



T20240720124933





BLK:19,SNR1: 0.32081 ,SNR2: 1.3789





3C208 2024/07/20 3.85UT TOYOKAWA-KISO

K20240720124930




BLK:19,SNR1: 0.38658 ,SNR2: 1.4648






F20240720124935





BLK:10,SNR1: 0.31759E-01,SNR2: 0.98235





3C208 2024/07/20 3.85UT FUJI -KISO



K20240720124930




BLK:10,SNR1: 0.29300 ,SNR2: 0.73886



T20240720130614




BLK: 4,SNR1: 1.2562 ,SNR2: 4.4021





3C216 2024/07/20 4.13UT TOYOKAWA-FUJI



F20240720130616




BLK: 4,SNR1: 10.132 ,SNR2: 52.749



T20240720130614





BLK: 7,SNR1: 0.64704 ,SNR2: 4.0172





3C216 2024/07/20 4.13UT TOYOKAWA-KISO


K20240720130611




BLK: 7,SNR1: 117.11 ,SNR2: 113.21



F20240720130616





BLK:10,SNR1: 3.5488 ,SNR2: 15.194





3C216 2024/07/20 4.13UT FUJI -KISO



K20240720130611




BLK:10,SNR1: 114.85 ,SNR2: 111.03




T20240720131826




BLK: 7,SNR1: 0.29086 ,SNR2: 2.0221




F20240720131828





BLK: 7,SNR1:-0.13983 ,SNR2: 2.2402




0919-142 2024/07/20 4.34UT TOYOKAWA-FUJI





T20240720131826




BLK:11,SNR1: 0.21413 ,SNR2: 1.8831




K20240720131823





BLK:11,SNR1: 0.74649 ,SNR2: 3.2075




0919-142 2024/07/20 4.34UT TOYOKAWA-KISO





F20240720131828




BLK: 5,SNR1:-0.14468 ,SNR2: 2.3194




K20240720131823





BLK: 5,SNR1: 0.36364 ,SNR2: 1.2273




0919-142 2024/07/20 4.34UT FUJI -KISO




T20240720132505




BLK:34,SNR1: 4.3940 ,SNR2: 10.773




F20240720132507



BLK:34,SNR1: 1.3627 ,SNR2: 7.3365





0926+117 2024/07/20 4.45UT TOYOKAWA-FUJI






T20240720132505





BLK:30,SNR1: 4.4756 ,SNR2: 11.050





0926+117 2024/07/20 4.45UT TOYOKAWA-KISO


K20240720132502




BLK:30,SNR1: 6.9275 ,SNR2: 20.278





F20240720132507




BLK:31,SNR1: 14.119 ,SNR2: 17.479




K20240720132502




BLK:31,SNR1: 6.9260 ,SNR2: 20.273




0926+117 2024/07/20 4.45UT FUJI -KISO




T20240720133249




BLK: 9,SNR1: 0.53444 ,SNR2: 4.1590




F20240720133251





BLK: 9,SNR1: 0.67116 ,SNR2: 3.2503




3C222 2024/07/20 4.58UT TOYOKAWA-FUJI



T20240720133249





BLK:21,SNR1: 0.47078 ,SNR2: 4.0405





3C222 2024/07/20 4.58UT TOYOKAWA-KISO


K20240720133246




BLK:21,SNR1: 1.1407 ,SNR2: 4.4952





F20240720133251




BLK:12,SNR1: 0.31130 ,SNR2: 2.1663




K20240720133246





BLK:12,SNR1: 0.66463 ,SNR2: 2.8040




3C222 2024/07/20 4.58UT FUJI -KISO




T20240720133949




BLK:16,SNR1: 0.48381 ,SNR2: 1.8670




F20240720133951





BLK:16,SNR1: 1.9381 ,SNR2: 5.0689




0941-08 2024/07/20 4.69UT TOYOKAWA-FUJI





T20240720133949




BLK:19,SNR1: 0.39636 ,SNR2: 1.5807




K20240720133946




BLK:19,SNR1: 1.2233 ,SNR2: 5.0207




0941-08 2024/07/20 4.69UT TOYOKAWA-KISO





F20240720133951




BLK:17,SNR1: 2.1718 ,SNR2: 7.4243




K20240720133946



BLK:17,SNR1: 1.5927 ,SNR2: 6.4673





0941-08 2024/07/20 4.69UT FUJI -KISO






T20240720134811





BLK:33,SNR1: 3.0546 ,SNR2: 14.308





3C230 2024/07/20 4.83UT TOYOKAWA-FUJI



F20240720134813




BLK:33,SNR1: 10.263 ,SNR2: 25.280



T20240720134811





BLK:32,SNR1: 3.0057 ,SNR2: 14.115





3C230 2024/07/20 4.83UT TOYOKAWA-KISO



K20240720134808




BLK:32,SNR1: 29.807 ,SNR2: 30.104



F20240720134813





BLK:30,SNR1: 9.1898 ,SNR2: 22.580





3C230 2024/07/20 4.83UT FUJI -KISO



K20240720134808




BLK:30,SNR1: 29.843 ,SNR2: 30.140




T20240720140218




BLK:12,SNR1: 1.2379 ,SNR2: 3.0755




F20240720140220





BLK:12,SNR1: 3.4859 ,SNR2: 12.091




3C236 2024/07/20 5.07UT TOYOKAWA-FUJI




T20240720140218




BLK:19,SNR1: 2.5695 ,SNR2: 4.8671




K20240720140215




BLK:19,SNR1: 0.69312 ,SNR2: 4.4761




3C236 2024/07/20 5.07UT TOYOKAWA-KISO




F20240720140220




BLK:12,SNR1: 1.4539 ,SNR2: 7.1285




K20240720140215





BLK:12,SNR1: 9.0402 ,SNR2: 16.051




3C236 2024/07/20 5.07UT FUJI -KISO



T20240720141028





BLK:30,SNR1: 27.646 ,SNR2: 30.017




Frequency (Hz)

F20240720141030




BLK:30,SNR1: 7.1909 ,SNR2: 20.165





Frequency (Hz)


1011+110 2024/07/20 5.20UT TOYOKAWA-FUJI





T20240720141028




BLK:36,SNR1: 28.372 ,SNR2: 30.971




K20240720141025



BLK:36,SNR1: 10.593 ,SNR2: 18.735




1011+110 2024/07/20 5.20UT TOYOKAWA-KISO






F20240720141030





BLK:33,SNR1: 7.4928 ,SNR2: 18.886





1011+110 2024/07/20 5.20UT FUJI -KISO



K20240720141025




BLK:33,SNR1: 11.273 ,SNR2: 19.899




T20240720141809




BLK:15,SNR1: 0.61527 ,SNR2: 2.0760




F20240720141811





BLK:15,SNR1: 1.9765 ,SNR2: 7.5415




3C241 2024/07/20 5.33UT TOYOKAWA-FUJI




T20240720141809




BLK:17,SNR1: 0.53078 ,SNR2: 1.5417




K20240720141806




BLK:17,SNR1: 0.19406 ,SNR2: 3.7550




3C241 2024/07/20 5.33UT TOYOKAWA-KISO




F20240720141811




BLK:19,SNR1: 2.1276 ,SNR2: 6.3335




K20240720141806





BLK:19,SNR1: 0.16944 ,SNR2: 3.3472




3C241 2024/07/20 5.33UT FUJI -KISO




T20240720142938




BLK: 9,SNR1: 0.19153 ,SNR2: 1.2839




F20240720142940





BLK: 9,SNR1:-0.18751E-01,SNR2: 1.3111




1031-11 2024/07/20 5.52UT TOYOKAWA-FUJI





T20240720142938




BLK:13,SNR1: 0.11647 ,SNR2: 1.0706




K20240720142935





BLK:13,SNR1:-0.15294E-01,SNR2: 1.9428




1031-11 2024/07/20 5.52UT TOYOKAWA-KISO





F20240720142940




BLK:12,SNR1: 0.54328E-01,SNR2: 1.8186




K20240720142935




BLK:12,SNR1:-0.85360E-01,SNR2: 1.0033




1031-11 2024/07/20 5.52UT FUJI -KISO




T20240720143412




BLK: 8,SNR1: 0.57679E-01,SNR2: 1.4028




F20240720143414



BLK: 8,SNR1: 0.53094 ,SNR2: 6.2515





1035-058 2024/07/20 5.60UT TOYOKAWA-FUJI







T20240720143412




BLK:14,SNR1: 0.10688 ,SNR2: 1.4641




K20240720143409




BLK:14,SNR1:-0.56422E-01,SNR2: 2.4671




1035-058 2024/07/20 5.60UT TOYOKAWA-KISO



F20240720143414





BLK:14,SNR1: 0.17355 ,SNR2: 3.6880




Frequency (Hz)

K20240720143409




BLK:14,SNR1: 1.1069 ,SNR2: 5.7106





Frequency (Hz)


1035-058 2024/07/20 5.60UT FUJI -KISO





T20240720144325




BLK:24,SNR1: 2.7752 ,SNR2: 13.266




F20240720144327





BLK:24,SNR1: 7.8014 ,SNR2: 19.337




1044-008 2024/07/20 5.75UT TOYOKAWA-FUJI





T20240720144325




BLK:31,SNR1: 13.054 ,SNR2: 30.016




K20240720144322





BLK:31,SNR1: 2.7905 ,SNR2: 13.307




1044-008 2024/07/20 5.75UT TOYOKAWA-KISO





F20240720144327




BLK:30,SNR1: 14.869 ,SNR2: 26.320




K20240720144322





BLK:30,SNR1: 2.7060 ,SNR2: 12.968




1044-008 2024/07/20 5.75UT FUJI -KISO




T20240720145429




BLK:27,SNR1: 7.8925 ,SNR2: 19.885




F20240720145431





BLK:27,SNR1: 5.3790 ,SNR2: 14.770




1055+01 2024/07/20 5.94UT TOYOKAWA-FUJI





T20240720145429




BLK:34,SNR1: 7.8792 ,SNR2: 19.852




K20240720145426




BLK:34,SNR1: 10.251 ,SNR2: 24.502




1055+01 2024/07/20 5.94UT TOYOKAWA-KISO





F20240720145431




BLK:34,SNR1: 4.7454 ,SNR2: 13.248




K20240720145426



BLK:34,SNR1: 8.4516 ,SNR2: 20.799





1055+01 2024/07/20 5.94UT FUJI -KISO






T20240720150547





BLK:22,SNR1: 4.0706 ,SNR2: 10.896




Frequency (Hz)

F20240720150549




BLK:22,SNR1: 4.4736 ,SNR2: 11.940





Frequency (Hz)


1107+109 2024/07/20 6.12UT TOYOKAWA-FUJI



T20240720150547





BLK:26,SNR1: 3.0757 ,SNR2: 8.8222




Frequency (Hz)

K20240720150544




BLK:26,SNR1: 2.8573 ,SNR2: 10.163





Frequency (Hz)


1107+109 2024/07/20 6.12UT TOYOKAWA-KISO





F20240720150549




BLK:17,SNR1: 6.4608 ,SNR2: 16.013




K20240720150544





BLK:17,SNR1: 3.5906 ,SNR2: 12.484




1107+109 2024/07/20 6.12UT FUJI -KISO




T20240720151524




BLK:10,SNR1: 0.60269 ,SNR2: 1.7547




F20240720151526





BLK:10,SNR1: 0.83525 ,SNR2: 7.9513




3C255 2024/07/20 6.28UT TOYOKAWA-FUJI





T20240720151524




BLK:14,SNR1: 1.3689 ,SNR2: 4.8916




K20240720151521





BLK:14,SNR1: 0.19045 ,SNR2: 2.1225




3C255 2024/07/20 6.28UT TOYOKAWA-KISO



F20240720151526





BLK:11,SNR1: 0.12458E-01,SNR2: 1.0036




Frequency (Hz)

K20240720151521




BLK:11,SNR1: 0.51424 ,SNR2: 2.1213





Frequency (Hz)


3C255 2024/07/20 6.28UT FUJI -KISO




T20240720152602




BLK: 7,SNR1: 1.0376 ,SNR2: 5.5465




F20240720152604





BLK: 7,SNR1: 0.20561 ,SNR2: 2.6611




1127-14 2024/07/20 6.46UT TOYOKAWA-FUJI





T20240720152602




BLK:21,SNR1: 0.33873 ,SNR2: 1.8770




K20240720152559



BLK:21,SNR1: 0.98972E-01,SNR2: 1.0119




1127-14 2024/07/20 6.46UT TOYOKAWA-KISO






F20240720152604





BLK:13,SNR1: 0.15006 ,SNR2: 2.3382




Frequency (Hz)

K20240720152559




BLK:13,SNR1: 0.64989 ,SNR2: 4.4549





Frequency (Hz)


1127-14 2024/07/20 6.46UT FUJI -KISO




T20240720153922




BLK: 7,SNR1: 0.64420E-02,SNR2: 0.54678




F20240720153924





BLK: 7,SNR1:-0.26596 ,SNR2: 0.71554




3C263.1 2024/07/20 6.68UT TOYOKAWA-FUJI





T20240720153922




BLK:16,SNR1: 1.0949 ,SNR2: 3.0646




K20240720153919





BLK:16,SNR1: 0.95920E-01,SNR2: 0.77355




3C263.1 2024/07/20 6.68UT TOYOKAWA-KISO



F20240720153924





BLK: 3,SNR1: 0.21543 ,SNR2: 1.8826




Frequency (Hz)

K20240720153919




BLK: 3,SNR1:-0.13230 ,SNR2: 0.35634





Frequency (Hz)


3C263.1 2024/07/20 6.68UT FUJI -KISO



T20240720154549




BLK: 6,SNR1: 0.87816 ,SNR2: 1.6559




Frequency (Hz)

F20240720154551




BLK: 6,SNR1: 0.65154 ,SNR2: 3.6159





Frequency (Hz)


3C267 2024/07/20 6.79UT TOYOKAWA-FUJI





T20240720154549




BLK:15,SNR1: 0.25576 ,SNR2: 1.0859




K20240720154546




BLK:15,SNR1: 0.43333 ,SNR2: 2.2668




3C267 2024/07/20 6.79UT TOYOKAWA-KISO




F20240720154551




BLK: 7,SNR1: 0.53253 ,SNR2: 2.7339




K20240720154546





BLK: 7,SNR1: 0.38131 ,SNR2: 2.1142




3C267 2024/07/20 6.79UT FUJI -KISO



T20240720161137




BLK: 7,SNR1: 0.50293 ,SNR2: 4.1485




Frequency (Hz)

F20240720161139




BLK: 7,SNR1: 0.51724 ,SNR2: 2.9644





Frequency (Hz)

1213-17 2024/07/20 7.22UT TOYOKAWA-FUJI






T20240720161137





BLK: 2,SNR1:-0.14352 ,SNR2: 2.9627




Frequency (Hz)

K20240720161134




BLK: 2,SNR1: 0.55392 ,SNR2: 0.76738





Frequency (Hz)


1213-17 2024/07/20 7.22UT TOYOKAWA-KISO



F20240720161139





BLK: 3,SNR1: 3.1425 ,SNR2: 7.2071




Frequency (Hz)

K20240720161134




BLK: 3,SNR1: 1.0435 ,SNR2: 6.4840




Frequency (Hz)


1213-17 2024/07/20 7.22UT FUJI -KISO



T20240720162454




BLK:14,SNR1: 0.45292 ,SNR2: 5.6068




Frequency (Hz)

F20240720162456




BLK:14,SNR1:-0.42409E-01,SNR2: 0.99589





Frequency (Hz)


3C273 2024/07/20 7.44UT TOYOKAWA-FUJI





T20240720162454




BLK:18,SNR1: 0.64318 ,SNR2: 5.5277




K20240720162451





BLK:18,SNR1: 0.11315 ,SNR2: 0.80369




3C273 2024/07/20 7.44UT TOYOKAWA-KISO



F20240720162456





BLK: 7,SNR1: 0.61977 ,SNR2: 1.5937




Frequency (Hz)

K20240720162451




BLK: 7,SNR1: 0.93157E-01,SNR2: 0.38958





Frequency (Hz)


3C273 2024/07/20 7.44UT FUJI -KISO




T20240720163805




BLK: 6,SNR1: 0.90857E-01,SNR2: 0.90368




F20240720163807





BLK: 6,SNR1: 0.61299 ,SNR2: 1.4712




3C275 2024/07/20 7.66UT TOYOKAWA-FUJI





T20240720163805




BLK: 1,SNR1: 0.17050 ,SNR2: 0.57343




K20240720163802





BLK: 1,SNR1: 0.26696E-01,SNR2: 0.38968




3C275 2024/07/20 7.66UT TOYOKAWA-KISO



F20240720163807





BLK: 2,SNR1: 0.24640 ,SNR2: 2.6869




Frequency (Hz)

K20240720163802




BLK: 2,SNR1: 0.12308 ,SNR2: 0.74370





Frequency (Hz)

3C275 2024/07/20 7.66UT FUJI -KISO






T20240720165153




BLK: 4,SNR1: 0.20391 ,SNR2: 2.1316




Frequency (Hz)

F20240720165155




BLK: 4,SNR1: 0.33905 ,SNR2: 1.9286





Frequency (Hz)


3C279 2024/07/20 7.89UT TOYOKAWA-FUJI



T20240720165153





BLK: 3,SNR1: 0.20061E-01,SNR2: 1.5055




Frequency (Hz)

K20240720165150




BLK: 3,SNR1: 1.7851 ,SNR2: 5.7845




Frequency (Hz)


3C279 2024/07/20 7.89UT TOYOKAWA-KISO



F20240720165155





BLK: 4,SNR1: 0.20102 ,SNR2: 1.3620




Frequency (Hz)

K20240720165150




BLK: 4,SNR1: 1.6809 ,SNR2: 5.4225





Frequency (Hz)


3C279 2024/07/20 7.89UT FUJI -KISO



T20240720171141




BLK: 6,SNR1: 6.2817 ,SNR2: 12.468




Frequency (Hz)

F20240720171143




BLK: 6,SNR1: 1.3692 ,SNR2: 7.0610




Frequency (Hz)


1313+453 2024/07/20 8.22UT TOYOKAWA-FUJI




T20240720171141




BLK:11,SNR1: 3.5128 ,SNR2: 6.9633




K20240720171138




BLK:11,SNR1: 18.172 ,SNR2: 27.236




1313+453 2024/07/20 8.22UT TOYOKAWA-KISO



F20240720171143




BLK: 6,SNR1: 3.5326 ,SNR2: 9.6908




Frequency (Hz)

K20240720171138




BLK: 6,SNR1: 7.1860 ,SNR2: 20.405





Frequency (Hz)


1313+453 2024/07/20 8.22UT FUJI -KISO



T20240720172147





BLK: 1,SNR1: 0.77028E-01,SNR2: 0.65683




Frequency (Hz)

F20240720172149




BLK: 1,SNR1:-0.19835 ,SNR2: 0.95677





Frequency (Hz)


1323+32 2024/07/20 8.39UT TOYOKAWA-FUJI



T20240720172147





BLK: 5,SNR1: 0.92213E-02,SNR2: 0.51234




Frequency (Hz)

K20240720172144




BLK: 5,SNR1: 7.5279 ,SNR2: 15.654





Frequency (Hz)

1323+32 2024/07/20 8.39UT TOYOKAWA-KISO






F20240720172149





BLK: 5,SNR1: 0.93044E-02,SNR2: 2.9543




Frequency (Hz)

K20240720172144




BLK: 5,SNR1: 5.5263 ,SNR2: 14.602





Frequency (Hz)


1323+32 2024/07/20 8.39UT FUJI -KISO



T20240720172638





BLK: 3,SNR1: 0.45060E-01,SNR2: 1.2567




Frequency (Hz)

F20240720172640




BLK: 3,SNR1: 0.46769E-01,SNR2: 0.79673





Frequency (Hz)


3C286 2024/07/20 8.47UT TOYOKAWA-FUJI



T20240720172638





BLK: 4,SNR1: 0.17900 ,SNR2: 1.8608




Frequency (Hz)

K20240720172635




BLK: 4,SNR1: 1.2193 ,SNR2: 4.9556





Frequency (Hz)


3C286 2024/07/20 8.47UT TOYOKAWA-KISO



F20240720172640




BLK: 4,SNR1: 0.18309 ,SNR2: 1.2277




Frequency (Hz)

K20240720172635



BLK: 4,SNR1: 0.34815 ,SNR2: 1.5298



Frequency (Hz)

3C286 2024/07/20 8.47UT FUJI -KISO

