





T20240731060157




BLK: 5,SNR1: 0.27353E-01,SNR2: 0.73518




F20240731060157




BLK: 5,SNR1: 1.5075 ,SNR2: 7.2317




0244+377 2024/07/30 21.06UT TOYOKAWA-FUJI



T20240731060157





BLK: 7,SNR1:-0.19970E-01,SNR2: 0.24249




Frequency (Hz)

K20240731060155




BLK: 7,SNR1: 1.0615 ,SNR2: 4.4158





Frequency (Hz)


0244+377 2024/07/30 21.06UT TOYOKAWA-KISO



F20240731060157





BLK:11,SNR1: 1.0794 ,SNR2: 5.3644




Frequency (Hz)

K20240731060155




BLK:11,SNR1: 0.80056 ,SNR2: 3.6222





Frequency (Hz)


0244+377 2024/07/30 21.06UT FUJI -KISO



T20240731061604





BLK: 2,SNR1: 0.98226E-01,SNR2: 0.36101




Frequency (Hz)

F20240731061605




BLK: 2,SNR1: 0.79971 ,SNR2: 8.9939




Frequency (Hz)


0258+350 2024/07/30 21.30UT TOYOKAWA-FUJI



T20240731061604





BLK: 5,SNR1:-0.51018E-01,SNR2: 0.25813




Frequency (Hz)

K20240731061602




BLK: 5,SNR1: 0.76360 ,SNR2: 2.6321





Frequency (Hz)


0258+350 2024/07/30 21.30UT TOYOKAWA-KISO



F20240731061605





BLK: 5,SNR1:-0.53631E-02,SNR2: 2.3594




Frequency (Hz)

K20240731061602




BLK: 5,SNR1: 0.48431 ,SNR2: 3.0049





Frequency (Hz)


0258+350 2024/07/30 21.30UT FUJI -KISO




T20240731062000




No.Good Data




F20240731062001





No.Good Data




0302+341 2024/07/30 21.36UT TOYOKAWA-FUJI



T20240731062000





BLK: 2,SNR1: 0.45375E-01,SNR2: 0.91378




Frequency (Hz)

K20240731061958




BLK: 2,SNR1: 0.86839 ,SNR2: 2.7205





Frequency (Hz)

0302+341 2024/07/30 21.36UT TOYOKAWA-KISO








F20240731062001




BLK: 3,SNR1:-0.93442E-01,SNR2: 1.9854




K20240731061958





BLK: 3,SNR1: 0.52879 ,SNR2: 1.8906




0302+341 2024/07/30 21.36UT FUJI -KISO



T20240731062554





BLK: 4,SNR1: 0.22455 ,SNR2: 0.62895




Frequency (Hz)

F20240731062554




BLK: 4,SNR1: 0.48677 ,SNR2: 2.5642




Frequency (Hz)


0308+305 2024/07/30 21.46UT TOYOKAWA-FUJI





T20240731062554




BLK: 3,SNR1:-0.22887E-01,SNR2: 0.34253




K20240731062552





BLK: 3,SNR1:-0.19989 ,SNR2: 0.89597




0308+305 2024/07/30 21.46UT TOYOKAWA-KISO



F20240731062554





BLK: 8,SNR1: 0.33448 ,SNR2: 7.5158




Frequency (Hz)

K20240731062552




BLK: 8,SNR1: 1.0520 ,SNR2: 1.9845





Frequency (Hz)


0308+305 2024/07/30 21.46UT FUJI -KISO



T20240731063725





BLK:11,SNR1: 0.86553 ,SNR2: 4.3033




Frequency (Hz)

F20240731063726




BLK:11,SNR1: 0.65522 ,SNR2: 2.6329




Frequency (Hz)


0320+05 2024/07/30 21.65UT TOYOKAWA-FUJI



T20240731063725




BLK:13,SNR1: 0.77987 ,SNR2: 4.0166




Frequency (Hz)

K20240731063723




BLK:13,SNR1: 1.7277 ,SNR2: 8.7964





Frequency (Hz)


0320+05 2024/07/30 21.65UT TOYOKAWA-KISO




F20240731063726




BLK: 9,SNR1: 0.53076 ,SNR2: 3.9865




K20240731063723





BLK: 9,SNR1: 0.34284 ,SNR2: 2.4019




0320+05 2024/07/30 21.65UT FUJI -KISO



T20240731065046




BLK: 4,SNR1: 0.16310 ,SNR2: 2.6969




Frequency (Hz)

F20240731065046




BLK: 4,SNR1: 2.1310 ,SNR2: 6.9587




Frequency (Hz)

0333+32 2024/07/30 21.87UT TOYOKAWA-FUJI






T20240731065046





BLK: 2,SNR1: 0.22895 ,SNR2: 4.7250




Frequency (Hz)

K20240731065043




BLK: 2,SNR1: 28.725 ,SNR2: 35.861




Frequency (Hz)


0333+32 2024/07/30 21.87UT TOYOKAWA-KISO



F20240731065046





BLK: 9,SNR1: 1.3644 ,SNR2: 4.7449




Frequency (Hz)

K20240731065043




BLK: 9,SNR1: 8.6324 ,SNR2: 16.324





Frequency (Hz)


0333+32 2024/07/30 21.87UT FUJI -KISO



T20240731070348





BLK: 5,SNR1: 0.80214E-01,SNR2: 0.88835




Frequency (Hz)

0347+05 2024/07/30 22.09UT TOYOKAWA-FUJI


F20240731070348





BLK: 5,SNR1: 1.8128 ,SNR2: 10.140




Frequency (Hz)



T20240731070348





BLK: 4,SNR1: 0.35791E-01,SNR2: 0.71089




Frequency (Hz)

K20240731070345




BLK: 4,SNR1: 1.6275 ,SNR2: 2.9340




Frequency (Hz)


0347+05 2024/07/30 22.09UT TOYOKAWA-KISO



F20240731070348




BLK: 3,SNR1: 0.15291 ,SNR2: 1.6304




Frequency (Hz)

K20240731070345




BLK: 3,SNR1: 0.42956 ,SNR2: 1.6845





Frequency (Hz)


0347+05 2024/07/30 22.09UT FUJI -KISO



T20240731071923





BLK: 2,SNR1: 0.62283E-01,SNR2: 1.1182




Frequency (Hz)

F20240731071923




BLK: 2,SNR1:-0.17465 ,SNR2: 0.58522





Frequency (Hz)


0403-132 2024/07/30 22.35UT TOYOKAWA-FUJI



T20240731071923





BLK: 5, SNR1: 0.11212 , SNR2: 0.64434




Frequency (Hz)

K20240731071920




BLK: 5, SNR1: 0.80384 , SNR2: 3.7833





Frequency (Hz)


0403-132 2024/07/30 22.35UT TOYOKAWA-KISO



F20240731071923





BLK: 2,SNR1:-0.28560 ,SNR2: 0.0000




Frequency (Hz)

K20240731071920




BLK: 2,SNR1: 0.59216 ,SNR2: 4.0959





Frequency (Hz)

0403-132 2024/07/30 22.35UT FUJI -KISO






T20240731072833





BLK: 3,SNR1: 0.24167E-01,SNR2: 1.2401




Frequency (Hz)

F20240731072833




BLK: 3,SNR1: 0.52588 ,SNR2: 2.2587





Frequency (Hz)


0411+05 2024/07/30 22.50UT TOYOKAWA-FUJI



T20240731072833





BLK: 3,SNR1:-0.68291E-02,SNR2: 1.0908




Frequency (Hz)

0411+05 2024/07/30 22.50UT TOYOKAWA-KISO


K20240731072830




BLK: 3,SNR1: 0.13316 ,SNR2: 0.53496




Frequency (Hz)



F20240731072833




BLK: 5,SNR1: 0.99461 ,SNR2: 3.6802




Frequency (Hz)

K20240731072830




BLK: 5,SNR1: 0.14295 ,SNR2: 0.42635





Frequency (Hz)


0411+05 2024/07/30 22.50UT FUJI -KISO



T20240731073527





BLK: 5,SNR1: 0.25615 ,SNR2: 0.72109




Frequency (Hz)

F20240731073527




BLK: 5,SNR1: 0.81816 ,SNR2: 6.1757





Frequency (Hz)


0418+236 2024/07/30 22.62UT TOYOKAWA-FUJI



T20240731073527





BLK: 6,SNR1: 0.59653 ,SNR2: 5.4066




Frequency (Hz)

K20240731073524




BLK: 6,SNR1: 5.5446 ,SNR2: 11.286





Frequency (Hz)


0418+236 2024/07/30 22.62UT TOYOKAWA-KISO





F20240731073527




BLK: 7,SNR1: 0.24432 ,SNR2: 3.6467




K20240731073524





BLK: 7,SNR1: 0.72242 ,SNR2: 2.7535




0418+236 2024/07/30 22.62UT FUJI -KISO



T20240731074655





BLK:11,SNR1: 1.3558 ,SNR2: 6.7030




Frequency (Hz)

3C119 2024/07/30 22.81UT TOYOKAWA-FUJI


F20240731074655




BLK:11,SNR1: 1.0312 ,SNR2: 7.4988




Frequency (Hz)




T20240731074655




BLK:18,SNR1: 1.2403 ,SNR2: 5.7704




K20240731074652



BLK:18,SNR1: 15.226 ,SNR2: 24.378




3C119 2024/07/30 22.81UT TOYOKAWA-KISO






F20240731074655





BLK:14,SNR1: 0.96129 ,SNR2: 3.5785




Frequency (Hz)

3C119 2024/07/30 22.81UT FUJI -KISO


K20240731074652





BLK:14,SNR1: 14.921 ,SNR2: 23.472




Frequency (Hz)



T20240731083502




BLK:14,SNR1: 0.93926 ,SNR2: 7.8444




Frequency (Hz)

3C138 2024/07/30 23.61UT TOYOKAWA-FUJI


F20240731083502




BLK:14,SNR1: 0.37510 ,SNR2: 2.0109




Frequency (Hz)



T20240731083502




BLK:15,SNR1: 0.96654 ,SNR2: 5.7904




Frequency (Hz)

3C138 2024/07/30 23.61UT TOYOKAWA-KISO


K20240731083459




BLK:15,SNR1: 43.800 ,SNR2: 48.336




Frequency (Hz)



F20240731083502




BLK: 6,SNR1: 0.30883 ,SNR2: 2.0119




Frequency (Hz)

3C138 2024/07/30 23.61UT FUJI -KISO


K20240731083459




BLK: 6,SNR1:-0.13312E-01,SNR2: 3.6708




Frequency (Hz)



T20240731084835




BLK:12,SNR1: 0.55290 ,SNR2: 2.6085





0531+194 2024/07/30 23.84UT TOYOKAWA-FUJI


F20240731084835




BLK:12,SNR1: 0.70300 ,SNR2: 1.8886





T20240731084835




BLK:14,SNR1: 0.81591 ,SNR2: 1.6615




K20240731084832




BLK:14,SNR1: 87.071 ,SNR2: 81.834




0531+194 2024/07/30 23.84UT TOYOKAWA-KISO



F20240731084835





BLK:11,SNR1: 0.89431E-01,SNR2: 2.2626




Frequency (Hz)

K20240731084832




BLK:11,SNR1: 1.3301 ,SNR2: 5.6756




Frequency (Hz)


0531+194 2024/07/30 23.84UT FUJI -KISO



T20240731090506




BLK:23,SNR1: 1.7542 ,SNR2: 3.0673




Frequency (Hz)

0548+16 2024/07/31 0.11UT TOYOKAWA-FUJI


F20240731090506



BLK:23,SNR1: 3.9307 ,SNR2: 5.7146




Frequency (Hz)






T20240731090506





BLK:17,SNR1: 2.7863 ,SNR2: 4.8873




Frequency (Hz)

0548+16 2024/07/31 0.11UT TOYOKAWA-KISO


K20240731090503




BLK:17,SNR1: 2.0996 ,SNR2: 4.1119




Frequency (Hz)





F20240731090506




BLK:18,SNR1: 5.0482 ,SNR2: 10.823




K20240731090503




BLK:18,SNR1: 80.839 ,SNR2: 82.049




0548+16 2024/07/31 0.11UT FUJI -KISO



T20240731090917




BLK: 3,SNR1: 2.1617 ,SNR2: 10.863




Frequency (Hz)

0552+12 2024/07/31 0.18UT TOYOKAWA-FUJI


F20240731090917




BLK: 3,SNR1: 0.35430 ,SNR2: 1.2590




Frequency (Hz)



T20240731090917





BLK:12,SNR1: 9.2874 ,SNR2: 65.216




Frequency (Hz)

K20240731090914




BLK:12,SNR1: 30.910 ,SNR2: 62.769





Frequency (Hz)


0552+12 2024/07/31 0.18UT TOYOKAWA-KISO





F20240731090917




BLK: 7,SNR1: 0.44198E-01,SNR2: 0.76801




K20240731090914





BLK: 7,SNR1: 0.51719 ,SNR2: 4.4712




0552+12 2024/07/31 0.18UT FUJI -KISO



T20240731091344





BLK:17,SNR1: 1.9264 ,SNR2: 3.2090




Frequency (Hz)

F20240731091344




BLK:17,SNR1: 14.977 ,SNR2: 23.163




Frequency (Hz)


0556+191 2024/07/31 0.26UT TOYOKAWA-FUJI



T20240731091344




BLK:17,SNR1: 2.4364 ,SNR2: 4.0081




Frequency (Hz)

K20240731091342




BLK:17,SNR1: 71.996 ,SNR2: 68.954





Frequency (Hz)


0556+191 2024/07/31 0.26UT TOYOKAWA-KISO





F20240731091344




BLK:22,SNR1: 12.322 ,SNR2: 19.080




K20240731091342



BLK:22,SNR1: 6.9986 ,SNR2: 19.986




0556+191 2024/07/31 0.26UT FUJI -KISO






T20240731091816




BLK:19,SNR1: 0.68358 ,SNR2: 2.6065




Frequency (Hz)

F20240731091816




BLK:19,SNR1: 0.81410 ,SNR2: 6.4421




Frequency (Hz)


3C152 2024/07/31 0.33UT TOYOKAWA-FUJI





T20240731091816




BLK:10,SNR1: 0.52892 ,SNR2: 3.5540




K20240731091814




BLK:10,SNR1: 84.188 ,SNR2: 78.399




3C152 2024/07/31 0.33UT TOYOKAWA-KISO



F20240731091816





BLK:11,SNR1: 0.27534 ,SNR2: 2.8457




Frequency (Hz)

3C152 2024/07/31 0.33UT FUJI -KISO


K20240731091814




BLK:11,SNR1: 6.8539 ,SNR2: 32.466




Frequency (Hz)



T20240731094038





BLK:22,SNR1: 4.8699 ,SNR2: 33.998




Frequency (Hz)

3C161 2024/07/31 0.71UT TOYOKAWA-FUJI


F20240731094038





BLK:22,SNR1: 0.15052 ,SNR2: 2.7928




Frequency (Hz)



T20240731094038





BLK:29,SNR1: 3.8808 ,SNR2: 28.178




Frequency (Hz)

3C161 2024/07/31 0.71UT TOYOKAWA-KISO


K20240731094035




BLK:29,SNR1: 1.3486 ,SNR2: 6.1222




Frequency (Hz)



F20240731094038





BLK:17,SNR1: 0.31790 ,SNR2: 3.8170




Frequency (Hz)

3C161 2024/07/31 0.71UT FUJI -KISO


K20240731094035





BLK:17,SNR1: 1.8368 ,SNR2: 8.7162




Frequency (Hz)



T20240731100811





BLK:22,SNR1: 9.4767 ,SNR2: 26.449




0652-130 2024/07/31 1.16UT TOYOKAWA-FUJI


F20240731100811





BLK:22,SNR1: 7.6355 ,SNR2: 21.504




Frequency (Hz)





T20240731100811




BLK:21,SNR1: 9.7204 ,SNR2: 27.109




K20240731100808



BLK:21,SNR1: 25.538 ,SNR2: 39.466





0652-130 2024/07/31 1.16UT TOYOKAWA-KISO






F20240731100811





BLK:20,SNR1: 8.4669 ,SNR2: 23.729





0652-130 2024/07/31 1.16UT FUJI -KISO


K20240731100808




BLK:20,SNR1: 7.5244 ,SNR2: 21.462



T20240731101947




BLK:17,SNR1: 10.774 ,SNR2: 17.718





0703+138 2024/07/31 1.36UT TOYOKAWA-FUJI



F20240731101947




BLK:17,SNR1: 8.2875 ,SNR2: 13.033



T20240731101947





BLK:20,SNR1: 9.9086 ,SNR2: 16.431




Frequency (Hz)

K20240731101944




BLK:20,SNR1: 14.959 ,SNR2: 25.926




Frequency (Hz)


0703+138 2024/07/31 1.36UT TOYOKAWA-KISO



F20240731101947





BLK:24,SNR1: 11.057 ,SNR2: 18.115





0703+138 2024/07/31 1.36UT FUJI -KISO


K20240731101944




BLK:24,SNR1: 15.437 ,SNR2: 25.547




T20240731102910




BLK:11,SNR1: 0.33190 ,SNR2: 2.5040




F20240731102910




BLK:11,SNR1: 0.19282 ,SNR2: 2.8494




0713-024 2024/07/31 1.51UT TOYOKAWA-FUJI



T20240731102910





BLK:16,SNR1: 0.22220 ,SNR2: 2.4014





0713-024 2024/07/31 1.51UT TOYOKAWA-KISO


K20240731102907




BLK:16,SNR1: 0.36018 ,SNR2: 2.8255



F20240731102910





BLK: 4,SNR1:-0.29673 ,SNR2: 1.1994





0713-024 2024/07/31 1.51UT FUJI -KISO


K20240731102907




BLK: 4,SNR1: 0.80908 ,SNR2: 5.9887



T20240731103921




BLK:15,SNR1: 0.46303 ,SNR2: 3.6332





0723+10 2024/07/31 1.68UT TOYOKAWA-FUJI

F20240731103922




BLK:15,SNR1: 2.8688 ,SNR2: 12.479






T20240731103921





BLK:18,SNR1: 0.76983 ,SNR2: 3.7491





0723+10 2024/07/31 1.68UT TOYOKAWA-KISO


K20240731103918




BLK:18,SNR1: 0.47685 ,SNR2: 1.2277



F20240731103922





BLK:12,SNR1: 3.5290 ,SNR2: 17.330





0723+10 2024/07/31 1.68UT FUJI -KISO



K20240731103918




BLK:12,SNR1: 0.47005 ,SNR2: 1.8479



T20240731104936





BLK:11,SNR1: 0.42378 ,SNR2: 2.8947




Frequency (Hz)

0732+33 2024/07/31 1.85UT TOYOKAWA-FUJI


F20240731104936




BLK:11,SNR1: 6.5358 ,SNR2: 60.789




Frequency (Hz)





T20240731104936




BLK:16,SNR1: 0.42743 ,SNR2: 1.2328




K20240731104933




BLK:16,SNR1: 40.523 ,SNR2: 101.76




0732+33 2024/07/31 1.85UT TOYOKAWA-KISO



F20240731104936




BLK:11,SNR1: 4.6405 ,SNR2: 33.193





0732+33 2024/07/31 1.85UT FUJI -KISO



K20240731104933




BLK:11,SNR1: 39.624 ,SNR2: 58.580



T20240731105738





BLK:23,SNR1: 12.472 ,SNR2: 21.717




Frequency (Hz)

0741-06 2024/07/31 1.99UT TOYOKAWA-FUJI


F20240731105738




BLK:23,SNR1: 0.48948 ,SNR2: 4.7555




Frequency (Hz)



T20240731105738




BLK:26,SNR1: 7.3358 ,SNR2: 11.388





0741-06 2024/07/31 1.99UT TOYOKAWA-KISO


K20240731105735




BLK:26,SNR1: 1.7905 ,SNR2: 7.9850



F20240731105738




BLK:21,SNR1: 5.6636 ,SNR2: 8.5033





0741-06 2024/07/31 1.99UT FUJI -KISO

K20240731105735





BLK:21,SNR1: 1.8496 ,SNR2: 8.2015






T20240731110723





BLK:18,SNR1: 17.800 ,SNR2: 32.049





0752-200 2024/07/31 2.15UT TOYOKAWA-FUJI



F20240731110724




BLK:18,SNR1: 13.762 ,SNR2: 23.045



T20240731110723





BLK:22,SNR1: 17.693 ,SNR2: 31.861




0752-200 2024/07/31 2.15UT TOYOKAWA-KISO


K20240731110720





BLK:22,SNR1: 17.104 ,SNR2: 29.383




Frequency (Hz)





F20240731110724




BLK:18,SNR1: 19.920 ,SNR2: 22.274




K20240731110720





BLK:18,SNR1: 11.755 ,SNR2: 19.118




0752-200 2024/07/31 2.15UT FUJI -KISO




T20240731111457




BLK:12,SNR1: 0.53058 ,SNR2: 4.3806




F20240731111457




BLK:12,SNR1: 0.12124 ,SNR2: 1.8183




3C190 2024/07/31 2.28UT TOYOKAWA-FUJI





T20240731111457




BLK:10,SNR1: 0.46588 ,SNR2: 3.0118




K20240731111454




BLK:10,SNR1: 70.509 ,SNR2: 119.30




3C190 2024/07/31 2.28UT TOYOKAWA-KISO





F20240731111457




BLK: 7, SNR1: 0.14708 , SNR2: 4.0438




K20240731111454




BLK: 7, SNR1: 0.92631 , SNR2: 6.0523




3C190 2024/07/31 2.28UT FUJI -KISO




T20240731112722




BLK:10,SNR1: 1.6696 ,SNR2: 6.7265




F20240731112722




BLK:10,SNR1: 0.92313E-01,SNR2: 2.0343




3C196 2024/07/31 2.48UT TOYOKAWA-FUJI



T20240731112722




BLK:21,SNR1: 1.3232 ,SNR2: 3.7963





3C196 2024/07/31 2.48UT TOYOKAWA-KISO

K20240731112719




BLK:21,SNR1: 6.0791 ,SNR2: 17.487






F20240731112722




BLK:11,SNR1: 0.23766 ,SNR2: 3.1397





3C196 2024/07/31 2.48UT FUJI -KISO



K20240731112719




BLK:11,SNR1: 3.5216 ,SNR2: 14.120



T20240731113831




BLK:13,SNR1: 0.84038 ,SNR2: 2.5511





0821+394 2024/07/31 2.67UT TOYOKAWA-FUJI


F20240731113831




BLK:13,SNR1:-0.28498E-01,SNR2: 1.2988



T20240731113831




BLK:23,SNR1: 0.77723 ,SNR2: 2.1579





0821+394 2024/07/31 2.67UT TOYOKAWA-KISO



K20240731113828




BLK:23,SNR1: 3.9110 ,SNR2: 16.839



F20240731113831





BLK: 3,SNR1:-0.56282E-01,SNR2: 0.99831




Frequency (Hz)

K20240731113828




BLK: 3,SNR1: 7.1454 ,SNR2: 23.009




Frequency (Hz)


0821+394 2024/07/31 2.67UT FUJI -KISO



T20240731115012




BLK:12,SNR1: 0.91972 ,SNR2: 8.8813





0834-19 2024/07/31 2.86UT TOYOKAWA-FUJI


F20240731115012




BLK:12,SNR1: 0.23842E-01,SNR2: 1.7685



T20240731115012





BLK:19,SNR1: 0.90479 ,SNR2: 1.9585





0834-19 2024/07/31 2.86UT TOYOKAWA-KISO


K20240731115009




BLK:19,SNR1: 0.34498 ,SNR2: 1.1259



F20240731115012





BLK: 9,SNR1: 0.45656E-01,SNR2: 1.8871





0834-19 2024/07/31 2.86UT FUJI -KISO



K20240731115009




BLK: 9,SNR1: 0.28157 ,SNR2: 1.2988





T20240731115517




BLK:27,SNR1: 133.83 ,SNR2: 554.62




F20240731115517



BLK:27,SNR1: 21.321 ,SNR2: 117.92





0839-071 2024/07/31 2.95UT TOYOKAWA-FUJI






T20240731115517





BLK:23,SNR1: 154.37 ,SNR2: 639.79





0839-071 2024/07/31 2.95UT TOYOKAWA-KISO



K20240731115514




BLK:23,SNR1: 23.636 ,SNR2: 103.85





F20240731115517




BLK:24,SNR1: 24.430 ,SNR2: 134.93




K20240731115514




BLK:24,SNR1: 22.050 ,SNR2: 90.916




0839-071 2024/07/31 2.95UT FUJI -KISO



T20240731120618




BLK:15,SNR1: 0.62450 ,SNR2: 3.8201





3C208 2024/07/31 3.13UT TOYOKAWA-FUJI



F20240731120618




BLK:15,SNR1: 3.0839 ,SNR2: 6.7173




T20240731120618




BLK:10,SNR1: 0.74413 ,SNR2: 4.0877




K20240731120615





BLK:10,SNR1: 0.52016 ,SNR2: 1.5671




3C208 2024/07/31 3.13UT TOYOKAWA-KISO





F20240731120618




BLK:15,SNR1: 2.6007 ,SNR2: 10.412




K20240731120615





BLK:15,SNR1: 0.37870 ,SNR2: 1.4067




3C208 2024/07/31 3.13UT FUJI -KISO



T20240731122259





BLK:11,SNR1: 0.41288 ,SNR2: 5.0997





3C216 2024/07/31 3.41UT TOYOKAWA-FUJI



F20240731122259




BLK:11,SNR1: 0.88721 ,SNR2: 3.2086



T20240731122259





BLK:19,SNR1: 0.37448 ,SNR2: 2.4540





3C216 2024/07/31 3.41UT TOYOKAWA-KISO


K20240731122256




BLK:19,SNR1: 0.50816 ,SNR2: 1.7382



F20240731122259





BLK: 7,SNR1: 0.73434 ,SNR2: 3.3061





3C216 2024/07/31 3.41UT FUJI -KISO

K20240731122256





BLK: 7,SNR1: 1.6752 ,SNR2: 6.5555







T20240731123511




BLK: 4,SNR1: 0.13959 ,SNR2: 1.0363




F20240731123511





BLK: 4,SNR1: 5.2966 ,SNR2: 9.2284




0919-142 2024/07/31 3.61UT TOYOKAWA-FUJI



T20240731123511





BLK: 2,SNR1: 0.21752 ,SNR2: 0.75823





0919-142 2024/07/31 3.61UT TOYOKAWA-KISO


K20240731123508




BLK: 2,SNR1: 2.4525 ,SNR2: 14.969



F20240731123511





BLK: 3,SNR1:-0.93979E-01,SNR2: 1.5355





0919-142 2024/07/31 3.61UT FUJI -KISO



K20240731123508




BLK: 3,SNR1: 0.10607 ,SNR2: 0.54591



T20240731124150





BLK: 8,SNR1: 0.11585 ,SNR2: 0.96040




Frequency (Hz)

F20240731124150




BLK: 8,SNR1: 0.68399 ,SNR2: 2.0090





Frequency (Hz)


0926+117 2024/07/31 3.73UT TOYOKAWA-FUJI





T20240731124150




BLK: 4,SNR1: 0.21476 ,SNR2: 1.8119




K20240731124147





BLK: 4,SNR1: 0.60606 ,SNR2: 1.9706




0926+117 2024/07/31 3.73UT TOYOKAWA-KISO



F20240731124150





BLK: 2,SNR1: 0.77922 ,SNR2: 4.0743





0926+117 2024/07/31 3.73UT FUJI -KISO



K20240731124147




BLK: 2,SNR1:-0.17172E-02,SNR2: 1.5840




T20240731124934




BLK:15,SNR1: 1.0081 ,SNR2: 6.1414




F20240731124934





BLK:15,SNR1:-0.16386 ,SNR2: 0.64184




3C222 2024/07/31 3.85UT TOYOKAWA-FUJI





T20240731124934




BLK:20,SNR1: 0.85578 ,SNR2: 3.3215




K20240731124931



BLK:20,SNR1: 85.651 ,SNR2: 138.00





3C222 2024/07/31 3.85UT TOYOKAWA-KISO








F20240731124934




BLK:13,SNR1:-0.84403E-01,SNR2: 1.7529




K20240731124931





BLK:13,SNR1: 106.41 ,SNR2: 137.59




3C222 2024/07/31 3.85UT FUJI -KISO




T20240731125635




BLK:12,SNR1: 0.35992 ,SNR2: 2.1348




F20240731125635





BLK:12,SNR1:-0.10498 ,SNR2: 2.2725




0941-08 2024/07/31 3.97UT TOYOKAWA-FUJI



T20240731125635





BLK:14,SNR1: 0.49304 ,SNR2: 2.2372





0941-08 2024/07/31 3.97UT TOYOKAWA-KISO


K20240731125632




BLK:14,SNR1: 0.65459 ,SNR2: 4.1893





F20240731125635




BLK: 4,SNR1: 0.99994 ,SNR2: 2.5456




K20240731125632





BLK: 4,SNR1: 0.16831 ,SNR2: 2.3936




0941-08 2024/07/31 3.97UT FUJI -KISO



T20240731130456




BLK:17,SNR1: 1.2109 ,SNR2: 5.4020





3C230 2024/07/31 4.11UT TOYOKAWA-FUJI



F20240731130456




BLK:17,SNR1: 0.93843 ,SNR2: 4.0408



T20240731130456





BLK:28,SNR1: 1.3752 ,SNR2: 6.0038





3C230 2024/07/31 4.11UT TOYOKAWA-KISO


K20240731130453




BLK:28,SNR1: 0.25082 ,SNR2: 0.99473



F20240731130456





BLK: 8,SNR1: 0.49078 ,SNR2: 5.1316





3C230 2024/07/31 4.11UT FUJI -KISO


K20240731130453




BLK: 8,SNR1: 0.38004 ,SNR2: 1.2374



T20240731131903




BLK:12,SNR1: 0.71771 ,SNR2: 7.0273





3C236 2024/07/31 4.35UT TOYOKAWA-FUJI

F20240731131903





BLK:12,SNR1:-0.15935E-01,SNR2: 1.4734








T20240731131903




BLK:17,SNR1: 0.78871 ,SNR2: 3.9105




K20240731131901





BLK:17,SNR1: 1.5609 ,SNR2: 6.4672




3C236 2024/07/31 4.35UT TOYOKAWA-KISO



F20240731131903





BLK:12,SNR1: 0.38302 ,SNR2: 2.3217




Frequency (Hz)

3C236 2024/07/31 4.35UT FUJI -KISO


K20240731131901





BLK:12,SNR1: 2.0467 ,SNR2: 8.5677




Frequency (Hz)





T20240731132713




BLK: 3,SNR1:-0.68574E-01,SNR2: 1.1081




F20240731132713





BLK: 3,SNR1: 0.95036 ,SNR2: 10.642




1011+110 2024/07/31 4.48UT TOYOKAWA-FUJI





T20240731132713




BLK: 3,SNR1:-0.11642 ,SNR2: 0.42527




K20240731132711




BLK: 3,SNR1: 3.1740 ,SNR2: 17.533




1011+110 2024/07/31 4.48UT TOYOKAWA-KISO





F20240731132713




BLK: 3,SNR1: 0.87868 ,SNR2: 3.9898




K20240731132711




BLK: 3,SNR1: 0.21625 ,SNR2: 0.43672




1011+110 2024/07/31 4.48UT FUJI -KISO



T20240731133454




BLK:14,SNR1: 6.1805 ,SNR2: 27.242





3C241 2024/07/31 4.61UT TOYOKAWA-FUJI


F20240731133454




BLK:14,SNR1: 0.48677 ,SNR2: 5.1979



T20240731133454




BLK:18,SNR1: 5.1169 ,SNR2: 21.516





3C241 2024/07/31 4.61UT TOYOKAWA-KISO


K20240731133451




BLK:18,SNR1: 1.3802 ,SNR2: 5.8753



F20240731133454





BLK:16,SNR1: 1.0434 ,SNR2: 7.6010





3C241 2024/07/31 4.61UT FUJI -KISO

K20240731133451




BLK:16,SNR1: 0.84919 ,SNR2: 12.160







T20240731134624




BLK: 3,SNR1: 0.40896 ,SNR2: 2.4408




F20240731134624





BLK: 3,SNR1: 0.22070 ,SNR2: 1.8518




1031-11 2024/07/31 4.80UT TOYOKAWA-FUJI





T20240731134624




BLK:16,SNR1: 0.63350 ,SNR2: 2.1160




K20240731134621




BLK:16,SNR1: 1.4549 ,SNR2: 5.9993




1031-11 2024/07/31 4.80UT TOYOKAWA-KISO





F20240731134624




BLK:10,SNR1: 0.83098E-01,SNR2: 1.8332




K20240731134621




BLK:10,SNR1: 3.8258 ,SNR2: 15.190




1031-11 2024/07/31 4.80UT FUJI -KISO




T20240731135057




BLK: 4,SNR1: 0.76071E-02,SNR2: 0.61380




F20240731135057





BLK: 4,SNR1: 0.12633 ,SNR2: 1.6372




1035-058 2024/07/31 4.88UT TOYOKAWA-FUJI





T20240731135057




BLK: 3,SNR1: 0.37925E-01,SNR2: 0.96640




K20240731135055




BLK: 3,SNR1: 2.4566 ,SNR2: 10.694




1035-058 2024/07/31 4.88UT TOYOKAWA-KISO




F20240731135057




BLK: 4,SNR1: 0.83359E-02,SNR2: 1.1217




K20240731135055





BLK: 4,SNR1: 0.82026 ,SNR2: 3.5250




1035-058 2024/07/31 4.88UT FUJI -KISO




T20240731140010




BLK: 4,SNR1: 0.17324E-01,SNR2: 0.73924




F20240731140010





BLK: 4,SNR1:-0.26485E-01,SNR2: 4.5488




1044-008 2024/07/31 5.03UT TOYOKAWA-FUJI





T20240731140010




BLK: 4,SNR1:-0.21556E-01,SNR2: 0.25911




K20240731140008



BLK: 4,SNR1: 0.60752 ,SNR2: 5.7156




1044-008 2024/07/31 5.03UT TOYOKAWA-KISO






F20240731140010





BLK: 2,SNR1: 0.18693 ,SNR2: 7.4157




Frequency (Hz)

K20240731140008




BLK: 2,SNR1: 0.32603 ,SNR2: 0.91953




Frequency (Hz)


1044-008 2024/07/31 5.03UT FUJI -KISO





T20240731141114




BLK: 7,SNR1: 0.62660 ,SNR2: 3.9895




F20240731141114





BLK: 7,SNR1: 0.40424 ,SNR2: 1.3772




1055+01 2024/07/31 5.22UT TOYOKAWA-FUJI





T20240731141114




BLK:15,SNR1: 0.39856 ,SNR2: 1.3119




K20240731141111





BLK:15,SNR1: 1.0995 ,SNR2: 4.6573




1055+01 2024/07/31 5.22UT TOYOKAWA-KISO





F20240731141114




BLK: 6,SNR1:-0.17086 ,SNR2: 1.2456




K20240731141111





BLK: 6,SNR1: 0.62010 ,SNR2: 1.9105




1055+01 2024/07/31 5.22UT FUJI -KISO





T20240731142232




BLK:11,SNR1: 74.184 ,SNR2: 105.25




F20240731142232





BLK:11,SNR1: 0.29896E-01,SNR2: 1.4717




1107+109 2024/07/31 5.40UT TOYOKAWA-FUJI





T20240731142232




BLK: 8,SNR1: 31.361 ,SNR2: 75.917




K20240731142229





BLK: 8,SNR1: 0.40370 ,SNR2: 3.4846




1107+109 2024/07/31 5.40UT TOYOKAWA-KISO



F20240731142232





BLK: 7,SNR1: 0.12580 ,SNR2: 1.5744




Frequency (Hz)

K20240731142229




BLK: 7,SNR1: 0.48902 ,SNR2: 2.4901





Frequency (Hz)


1107+109 2024/07/31 5.40UT FUJI -KISO




T20240731143209




BLK: 5,SNR1: 111.82 ,SNR2: 160.95




F20240731143209



BLK: 5,SNR1:-0.31048 ,SNR2: 0.61328





3C255 2024/07/31 5.56UT TOYOKAWA-FUJI






T20240731143209





BLK: 9,SNR1: 42.396 ,SNR2: 155.30




Frequency (Hz)

K20240731143206




BLK: 9,SNR1: 0.27783 ,SNR2: 1.1076





Frequency (Hz)


3C255 2024/07/31 5.56UT TOYOKAWA-KISO





F20240731143209




BLK: 4,SNR1: 0.75417 ,SNR2: 1.7068




K20240731143206





BLK: 4,SNR1: 0.25326 ,SNR2: 3.2504




3C255 2024/07/31 5.56UT FUJI -KISO



T20240731144247





BLK: 7,SNR1: 107.75 ,SNR2: 160.83




Frequency (Hz)

F20240731144247




BLK: 7,SNR1:-0.23023 ,SNR2: 0.86128





Frequency (Hz)


1127-14 2024/07/31 5.74UT TOYOKAWA-FUJI





T20240731144247




BLK:12,SNR1: 77.196 ,SNR2: 116.94




K20240731144244





BLK:12,SNR1: 2.7982 ,SNR2: 11.117




1127-14 2024/07/31 5.74UT TOYOKAWA-KISO



F20240731144247





BLK: 9,SNR1: 0.13009 ,SNR2: 2.6266




Frequency (Hz)

K20240731144244




BLK: 9,SNR1: 3.1354 ,SNR2: 12.384





Frequency (Hz)


1127-14 2024/07/31 5.74UT FUJI -KISO



T20240731145607





BLK: 5,SNR1: 1.1891 ,SNR2: 5.3403




Frequency (Hz)

F20240731145607




BLK: 5,SNR1:-0.90698E-02,SNR2: 1.4695





Frequency (Hz)


3C263.1 2024/07/31 5.96UT TOYOKAWA-FUJI





T20240731145607




BLK: 6,SNR1: 2.6112 ,SNR2: 11.320




K20240731145604





BLK: 6,SNR1: 0.51128 ,SNR2: 2.2881




3C263.1 2024/07/31 5.96UT TOYOKAWA-KISO



F20240731145607





BLK: 1,SNR1: 0.31743 ,SNR2: 0.91243




Frequency (Hz)

K20240731145604




BLK: 1,SNR1: 0.23133E-02,SNR2: 0.16243





Frequency (Hz)

3C263.1 2024/07/31 5.96UT FUJI -KISO






T20240731150234





BLK: 7,SNR1: 0.11621 ,SNR2: 1.1696




Frequency (Hz)

F20240731150234




BLK: 7,SNR1: 0.22591 ,SNR2: 3.4417





Frequency (Hz)


3C267 2024/07/31 6.07UT TOYOKAWA-FUJI





T20240731150234




BLK:10,SNR1: 0.15746 ,SNR2: 1.1984




K20240731150231




BLK:10,SNR1: 1.3945 ,SNR2: 5.1307




3C267 2024/07/31 6.07UT TOYOKAWA-KISO





F20240731150234




BLK: 5,SNR1: 0.16621 ,SNR2: 1.5374




K20240731150231





BLK: 5,SNR1: 0.37862 ,SNR2: 1.0773




3C267 2024/07/31 6.07UT FUJI -KISO



T20240731152822




BLK: 2,SNR1: 0.15576 ,SNR2: 1.6738




Frequency (Hz)

F20240731152822




BLK: 2,SNR1:-0.18496 ,SNR2: 0.0000





Frequency (Hz)


1213-17 2024/07/31 6.50UT TOYOKAWA-FUJI





T20240731152822




BLK: 8,SNR1: 0.13290 ,SNR2: 1.2169




K20240731152819




BLK: 8,SNR1: 54.587 ,SNR2: 67.194




1213-17 2024/07/31 6.50UT TOYOKAWA-KISO





F20240731152822




BLK: 3,SNR1:-0.19334 ,SNR2: 0.0000




K20240731152819





BLK: 3,SNR1: 60.453 ,SNR2: 74.392




1213-17 2024/07/31 6.50UT FUJI -KISO





T20240731154139




BLK: 8,SNR1: 1.3073 ,SNR2: 6.3490




F20240731154139





BLK: 8,SNR1:-0.76652E-02,SNR2: 1.3663




3C273 2024/07/31 6.72UT TOYOKAWA-FUJI





T20240731154139




BLK:25,SNR1: 1.2093 ,SNR2: 5.2890




K20240731154136



BLK:25,SNR1: 0.34264 ,SNR2: 3.1221





3C273 2024/07/31 6.72UT TOYOKAWA-KISO








F20240731154139




BLK:11,SNR1:-0.37019E-01,SNR2: 1.2227




K20240731154136





BLK:11,SNR1: 0.37508 ,SNR2: 3.1732




3C273 2024/07/31 6.72UT FUJI -KISO




T20240731155450




BLK: 3,SNR1: 0.43642 ,SNR2: 3.8282




F20240731155450





BLK: 3,SNR1:-0.67863E-01,SNR2: 0.85005




3C275 2024/07/31 6.94UT TOYOKAWA-FUJI



T20240731155450





BLK: 6,SNR1: 0.22568 ,SNR2: 2.1770




Frequency (Hz)

K20240731155448




BLK: 6,SNR1: 0.14806 ,SNR2: 1.5592





Frequency (Hz)


3C275 2024/07/31 6.94UT TOYOKAWA-KISO



F20240731155450





BLK: 6,SNR1: 0.17445 ,SNR2: 1.7403




Frequency (Hz)

K20240731155448




BLK: 6,SNR1: 1.2446 ,SNR2: 5.6003




Frequency (Hz)


3C275 2024/07/31 6.94UT FUJI -KISO





T20240731160055




BLK: 9,SNR1: 0.21180 ,SNR2: 3.0109




F20240731160055




BLK: 9,SNR1: 71.352 ,SNR2: 65.874




1245-19 2024/07/31 7.04UT TOYOKAWA-FUJI





T20240731160055




BLK:15,SNR1: 0.20552 ,SNR2: 2.9808




K20240731160053





BLK:15,SNR1: 5.0472 ,SNR2: 14.789




1245-19 2024/07/31 7.04UT TOYOKAWA-KISO



F20240731160055





BLK:15,SNR1: 58.819 ,SNR2: 54.301




Frequency (Hz)

K20240731160053




BLK:15,SNR1: 12.757 ,SNR2: 23.586





Frequency (Hz)


1245-19 2024/07/31 7.04UT FUJI -KISO



T20240731160838




BLK: 4,SNR1: 2.4310 ,SNR2: 11.066




Frequency (Hz)

F20240731160838




BLK: 4,SNR1: 0.68291E-01,SNR2: 2.0677





Frequency (Hz)

3C279 2024/07/31 7.17UT TOYOKAWA-FUJI






T20240731160838





BLK: 7,SNR1: 2.3373 ,SNR2: 10.469




Frequency (Hz)

K20240731160836




BLK: 7,SNR1: 0.58004 ,SNR2: 2.6680





Frequency (Hz)


3C279 2024/07/31 7.17UT TOYOKAWA-KISO



F20240731160838




BLK: 6,SNR1:-0.92675E-02,SNR2: 1.9194




Frequency (Hz)

K20240731160836




BLK: 6,SNR1: 0.30719 ,SNR2: 1.4352





Frequency (Hz)


3C279 2024/07/31 7.17UT FUJI -KISO




T20240731162408




BLK: 6,SNR1: 3.0975 ,SNR2: 19.375




F20240731162408





BLK: 6,SNR1:-0.12218 ,SNR2: 0.66456




3C283 2024/07/31 7.43UT TOYOKAWA-FUJI





T20240731162408




BLK:11,SNR1: 1.7579 ,SNR2: 10.798




K20240731162405




BLK:11,SNR1: 4.9504 ,SNR2: 12.606




3C283 2024/07/31 7.43UT TOYOKAWA-KISO



F20240731162408





BLK: 9,SNR1: 0.47074 ,SNR2: 3.5757




Frequency (Hz)

K20240731162405




BLK: 9,SNR1: 5.7489 ,SNR2: 14.262





Frequency (Hz)


3C283 2024/07/31 7.43UT FUJI -KISO



T20240731163832




BLK: 9,SNR1: 1.1663 ,SNR2: 5.6159




Frequency (Hz)

F20240731163832




BLK: 9,SNR1: 0.65705 ,SNR2: 3.4604





Frequency (Hz)


1323+32 2024/07/31 7.67UT TOYOKAWA-FUJI



T20240731163832





BLK:19,SNR1: 0.71766 ,SNR2: 3.5866




Frequency (Hz)

K20240731163829




BLK:19,SNR1: 7.8622 ,SNR2: 15.812




Frequency (Hz)


1323+32 2024/07/31 7.67UT TOYOKAWA-KISO



F20240731163832




BLK:25,SNR1: 0.77095 ,SNR2: 3.4725




Frequency (Hz)

K20240731163829




BLK:25,SNR1: 2.8553 ,SNR2: 12.617





Frequency (Hz)

1323+32 2024/07/31 7.67UT FUJI -KISO







T20240731164323




BLK:20,SNR1: 9.5271 ,SNR2: 22.623




F20240731164323





BLK:20,SNR1: 0.20258 ,SNR2: 1.5535




3C286 2024/07/31 7.75UT TOYOKAWA-FUJI




T20240731164323




BLK:25,SNR1: 9.3679 ,SNR2: 22.006




K20240731164320




BLK:25,SNR1: 0.65333 ,SNR2: 2.9873




3C286 2024/07/31 7.75UT TOYOKAWA-KISO



F20240731164323




BLK:15,SNR1: 0.21580 ,SNR2: 1.7517




Frequency (Hz)

K20240731164320




BLK:15,SNR1: 0.85020 ,SNR2: 4.0094





Frequency (Hz)


3C286 2024/07/31 7.75UT FUJI -KISO



T20240731165950





BLK:12,SNR1: 7.8600 ,SNR2: 21.508




Frequency (Hz)

F20240731165951




BLK:12,SNR1: 8.1403 ,SNR2: 19.436





Frequency (Hz)


1345+12 2024/07/31 8.03UT TOYOKAWA-FUJI



T20240731165950





BLK:15,SNR1: 7.4159 ,SNR2: 20.310




Frequency (Hz)

K20240731165947




BLK:15,SNR1: 8.9912 ,SNR2: 22.122





Frequency (Hz)


1345+12 2024/07/31 8.03UT TOYOKAWA-KISO



F20240731165951





BLK:22,SNR1: 12.292 ,SNR2: 13.207




Frequency (Hz)

K20240731165947




BLK:22,SNR1: 15.845 ,SNR2: 28.844





Frequency (Hz)


1345+12 2024/07/31 8.03UT FUJI -KISO



T20240731180550





BLK: 2,SNR1: 0.42382 ,SNR2: 1.1941




Frequency (Hz)

F20240731180550




BLK: 2,SNR1: 0.17890 ,SNR2: 4.5690





Frequency (Hz)


1452+502 2024/07/31 9.13UT TOYOKAWA-FUJI



T20240731180550





BLK: 5,SNR1: 0.39645E-01,SNR2: 0.54380




Frequency (Hz)

K20240731180548




BLK: 5,SNR1: 1.0048 ,SNR2: 4.3071





Frequency (Hz)

1452+502 2024/07/31 9.13UT TOYOKAWA-KISO






F20240731180550





BLK: 3,SNR1: 0.13778 ,SNR2: 2.9420




Frequency (Hz)

K20240731180548



BLK: 3,SNR1: 0.62065 ,SNR2: 3.4014



Frequency (Hz)

1452+502 2024/07/31 9.13UT FUJI -KISO

