



T20240801055801





BLK: 4,SNR1: 0.24239 ,SNR2: 0.77340




Frequency (Hz)

F20240801055802






BLK: 4,SNR1: 0.42574 ,SNR2: 2.8274






Frequency (Hz)

0244+377 2024/07/31 21.00UT TOYOKAWA-FUJI







BLK: 3,SNR1:-0.40554E-01,SNR2: 0.61033





BLK: 3,SNR1: 0.85675 ,SNR2: 3.0945




0244+377 2024/07/31 21.00UT TOYOKAWA-KISO



F20240801055802





BLK: 5,SNR1: 0.13638 ,SNR2: 1.3643




Frequency (Hz)

K20240801055759




BLK: 5,SNR1: 0.85865 ,SNR2: 3.0411





Frequency (Hz)


0244+377 2024/07/31 21.00UT FUJI -KISO



T20240801061208




BLK: 4,SNR1: 0.16238 ,SNR2: 0.49173




Frequency (Hz)

F20240801061208




BLK: 4,SNR1: 0.26446 ,SNR2: 1.9073





Frequency (Hz)


0258+350 2024/07/31 21.23UT TOYOKAWA-FUJI





T20240801061208




BLK: 8,SNR1: 0.17687E-02,SNR2: 0.65560




K20240801061206





BLK: 8,SNR1: 3.0863 ,SNR2: 13.610




0258+350 2024/07/31 21.23UT TOYOKAWA-KISO



F20240801061208





BLK:11,SNR1: 0.43109 ,SNR2: 2.7281




Frequency (Hz)

K20240801061206




BLK:11,SNR1: 3.0457 ,SNR2: 13.449





Frequency (Hz)


0258+350 2024/07/31 21.23UT FUJI -KISO





T20240801061604




No.Good Data




F20240801061605





No.Good Data




0302+341 2024/07/31 21.30UT TOYOKAWA-FUJI



T20240801061604





BLK: 3,SNR1: 0.27270 ,SNR2: 0.56126




Frequency (Hz)

K20240801061601




BLK: 3,SNR1: 1.3913 ,SNR2: 6.7245




Frequency (Hz)

0302+341 2024/07/31 21.30UT TOYOKAWA-KISO








F20240801061605




No.Good Data




K20240801061601




No.Good Data




0302+341 2024/07/31 21.30UT FUJI -KISO



T20240801062158




BLK: 2,SNR1: 0.39230E-01,SNR2: 0.33506




Frequency (Hz)

F20240801062158




BLK: 2,SNR1: 0.68374 ,SNR2: 2.6273




Frequency (Hz)


0308+305 2024/07/31 21.39UT TOYOKAWA-FUJI



T20240801062158





BLK: 4,SNR1: 0.72050E-01,SNR2: 0.52530




Frequency (Hz)

K20240801062155




BLK: 4,SNR1: 2.1407 ,SNR2: 13.617





Frequency (Hz)


0308+305 2024/07/31 21.39UT TOYOKAWA-KISO



F20240801062158





BLK: 4,SNR1: 0.49631E-01,SNR2: 2.7079




Frequency (Hz)

K20240801062155




BLK: 4,SNR1: 1.6366 ,SNR2: 7.4153





Frequency (Hz)


0308+305 2024/07/31 21.39UT FUJI -KISO



T20240801063734




BLK: 7,SNR1: 4.5241 ,SNR2: 54.730




Frequency (Hz)

F20240801063735




BLK: 7,SNR1: 1.0815 ,SNR2: 4.3360





Frequency (Hz)


0324+119 2024/07/31 21.65UT TOYOKAWA-FUJI



T20240801063734





BLK: 3,SNR1: 24.455 ,SNR2: 112.99




Frequency (Hz)

K20240801063731




BLK: 3,SNR1: 2.9542 ,SNR2: 17.093




Frequency (Hz)


0324+119 2024/07/31 21.65UT TOYOKAWA-KISO




F20240801063735




BLK: 4,SNR1:-0.15792E-01,SNR2: 1.5580




K20240801063731





BLK: 4,SNR1: 0.25733E-01,SNR2: 0.51526




0324+119 2024/07/31 21.65UT FUJI -KISO



T20240801064650





BLK: 8,SNR1: 0.17584 ,SNR2: 2.5563




Frequency (Hz)

F20240801064650




BLK: 8,SNR1: 0.29477 ,SNR2: 2.4508




Frequency (Hz)

0333+32 2024/07/31 21.81UT TOYOKAWA-FUJI






T20240801064650





BLK: 6,SNR1: 0.28637 ,SNR2: 2.6541




Frequency (Hz)

K20240801064647




BLK: 6,SNR1:-0.26386 ,SNR2: 0.80197E-01





Frequency (Hz)


0333+32 2024/07/31 21.81UT TOYOKAWA-KISO





F20240801064650




BLK:15,SNR1: 0.18208 ,SNR2: 1.6942




K20240801064647





BLK:15,SNR1: 1.6287 ,SNR2: 2.8998




0333+32 2024/07/31 21.81UT FUJI -KISO



T20240801065952





BLK: 5,SNR1: 0.17758 ,SNR2: 0.79008




Frequency (Hz)

F20240801065953




BLK: 5,SNR1: 0.29538 ,SNR2: 4.5456





Frequency (Hz)


0347+05 2024/07/31 22.03UT TOYOKAWA-FUJI



T20240801065952





BLK: 5,SNR1: 0.38893E-01,SNR2: 1.0889




Frequency (Hz)

K20240801065950




BLK: 5,SNR1: 1.9669 ,SNR2: 6.5965




Frequency (Hz)


0347+05 2024/07/31 22.03UT TOYOKAWA-KISO



F20240801065953




BLK:12,SNR1: 0.89373 ,SNR2: 3.5836




Frequency (Hz)

K20240801065950




BLK:12,SNR1: 0.75725E-01,SNR2: 1.0679





Frequency (Hz)


0347+05 2024/07/31 22.03UT FUJI -KISO



T20240801071527





BLK: 4,SNR1: 0.11535 ,SNR2: 0.93288




Frequency (Hz)

F20240801071528




BLK: 4,SNR1: 0.28767 ,SNR2: 1.6841





Frequency (Hz)


0403-132 2024/07/31 22.29UT TOYOKAWA-FUJI



T20240801071527





BLK: 5,SNR1: 0.37052 ,SNR2: 2.0498




Frequency (Hz)

K20240801071524




BLK: 5,SNR1: 0.65002 ,SNR2: 1.6927





Frequency (Hz)


0403-132 2024/07/31 22.29UT TOYOKAWA-KISO





F20240801071528




BLK: 1,SNR1: 0.11353E-01,SNR2: 2.5430




K20240801071524



BLK: 1,SNR1: 0.36013 ,SNR2: 1.3064




0403-132 2024/07/31 22.29UT FUJI -KISO






T20240801072437




BLK: 3,SNR1: 0.22155 ,SNR2: 1.4073




Frequency (Hz)

F20240801072438




BLK: 3,SNR1: 0.92496E-01,SNR2: 2.0976




Frequency (Hz)


0411+05 2024/07/31 22.44UT TOYOKAWA-FUJI



T20240801072437




BLK: 2,SNR1: 0.20512 ,SNR2: 1.6108




Frequency (Hz)

K20240801072434




BLK: 2,SNR1: 1.4425 ,SNR2: 11.752





Frequency (Hz)


0411+05 2024/07/31 22.44UT TOYOKAWA-KISO





F20240801072438




BLK: 3,SNR1: 0.18692 ,SNR2: 2.2268




K20240801072434





BLK: 3,SNR1: 0.10566 ,SNR2: 3.6682




0411+05 2024/07/31 22.44UT FUJI -KISO



T20240801073131




BLK: 5,SNR1: 0.97746E-01,SNR2: 0.87417




Frequency (Hz)

F20240801073131




BLK: 5,SNR1: 0.52167 ,SNR2: 2.0161





Frequency (Hz)


0418+236 2024/07/31 22.55UT TOYOKAWA-FUJI



T20240801073131





BLK: 3,SNR1: 0.12256 ,SNR2: 0.65893




Frequency (Hz)

K20240801073129




BLK: 3,SNR1: 0.33252 ,SNR2: 1.5129




Frequency (Hz)


0418+236 2024/07/31 22.55UT TOYOKAWA-KISO



F20240801073131




BLK:15,SNR1: 1.4413 ,SNR2: 7.2192




Frequency (Hz)

K20240801073129




BLK:15,SNR1: 15.913 ,SNR2: 27.172




Frequency (Hz)


0418+236 2024/07/31 22.55UT FUJI -KISO



T20240801074259





BLK:20,SNR1: 4.8967 ,SNR2: 19.505




Frequency (Hz)

F20240801074259




BLK:20,SNR1: 0.93243 ,SNR2: 4.2357





Frequency (Hz)


3C119 2024/07/31 22.74UT TOYOKAWA-FUJI



T20240801074259





BLK:22,SNR1: 4.5123 ,SNR2: 16.966




Frequency (Hz)

3C119 2024/07/31 22.74UT TOYOKAWA-KISO


K20240801074257



BLK:22,SNR1: 20.775 ,SNR2: 32.936





Frequency (Hz)






F20240801074259





BLK:20,SNR1: 1.1694 ,SNR2: 5.1611




Frequency (Hz)

3C119 2024/07/31 22.74UT FUJI -KISO


K20240801074257





BLK:20,SNR1: 2.7505 ,SNR2: 7.4212




Frequency (Hz)



T20240801083106




BLK:15,SNR1: 0.91062 ,SNR2: 2.3976




Frequency (Hz)

F20240801083106




BLK:15,SNR1:-0.12835 ,SNR2: 0.94539





Frequency (Hz)


3C138 2024/07/31 23.55UT TOYOKAWA-FUJI




T20240801083106




BLK:17,SNR1: 0.83674 ,SNR2: 4.2287




K20240801083104




BLK:17,SNR1: 42.387 ,SNR2: 57.368




3C138 2024/07/31 23.55UT TOYOKAWA-KISO



F20240801083106





BLK: 7,SNR1:-0.19663 ,SNR2: 0.42336





3C138 2024/07/31 23.55UT FUJI -KISO



K20240801083104




BLK: 7,SNR1: 2.0547 ,SNR2: 6.9593



T20240801084439




BLK:11,SNR1: 0.42833 ,SNR2: 4.9434




Frequency (Hz)

F20240801084439




BLK:11,SNR1: 0.65195E-01,SNR2: 2.2361





Frequency (Hz)


0531+194 2024/07/31 23.77UT TOYOKAWA-FUJI



T20240801084439





BLK:21,SNR1: 0.46828 ,SNR2: 3.9600




Frequency (Hz)

K20240801084437




BLK:21,SNR1: 2.5407 ,SNR2: 9.8037





Frequency (Hz)


0531+194 2024/07/31 23.77UT TOYOKAWA-KISO



F20240801084439





BLK: 6,SNR1:-0.11976 ,SNR2: 0.85150




Frequency (Hz)

K20240801084437




BLK: 6,SNR1: 0.14909 ,SNR2: 1.1626





Frequency (Hz)


0531+194 2024/07/31 23.77UT FUJI -KISO



T20240801085259





BLK:20,SNR1: 3.4481 ,SNR2: 14.649




Frequency (Hz)

3C147 2024/07/31 23.91UT TOYOKAWA-FUJI


F20240801085259



BLK:20,SNR1: 2.2784 ,SNR2: 8.7393





Frequency (Hz)








T20240801085259




BLK:21,SNR1: 3.4521 ,SNR2: 14.663




K20240801085256




BLK:21,SNR1: 6.1842 ,SNR2: 15.023




3C147 2024/07/31 23.91UT TOYOKAWA-KISO




F20240801085259




BLK:25,SNR1: 1.1659 ,SNR2: 5.7795




K20240801085256





BLK:25,SNR1: 6.1524 ,SNR2: 14.902




3C147 2024/07/31 23.91UT FUJI -KISO



T20240801090110





BLK:24,SNR1: 1.9992 ,SNR2: 9.4260




Frequency (Hz)

F20240801090110




BLK:24,SNR1: 7.1673 ,SNR2: 18.074




Frequency (Hz)


0548+16 2024/08/01 0.05UT TOYOKAWA-FUJI



T20240801090110





BLK:24,SNR1: 2.0259 ,SNR2: 9.5141





0548+16 2024/08/01 0.05UT TOYOKAWA-KISO



K20240801090107




BLK:24,SNR1: 2.6619 ,SNR2: 12.810



F20240801090110





BLK:25,SNR1: 7.1186 ,SNR2: 17.955





0548+16 2024/08/01 0.05UT FUJI -KISO



K20240801090107




BLK:25,SNR1: 2.6381 ,SNR2: 12.717



T20240801090521





BLK:14,SNR1: 0.84283 ,SNR2: 4.4855





0552+12 2024/08/01 0.12UT TOYOKAWA-FUJI



F20240801090521




BLK:14,SNR1: 3.1889 ,SNR2: 7.8798





T20240801090521




BLK:13,SNR1: 0.96724 ,SNR2: 4.8889




K20240801090518





BLK:13,SNR1: 32.281 ,SNR2: 35.627




0552+12 2024/08/01 0.12UT TOYOKAWA-KISO




F20240801090521




BLK:18,SNR1: 2.6000 ,SNR2: 9.0885




K20240801090518



BLK:18,SNR1: 30.238 ,SNR2: 33.371





0552+12 2024/08/01 0.12UT FUJI -KISO








T20240801090948




BLK: 6,SNR1: 0.94146E-01,SNR2: 0.75891




F20240801090949





BLK: 6,SNR1: 0.27214 ,SNR2: 3.1177




0556+191 2024/08/01 0.19UT TOYOKAWA-FUJI





T20240801090948




BLK:12,SNR1: 0.98666E-01,SNR2: 0.49645




K20240801090945




BLK:12,SNR1: 3.7650 ,SNR2: 14.668




0556+191 2024/08/01 0.19UT TOYOKAWA-KISO





F20240801090949




BLK: 8,SNR1:-0.11390 ,SNR2: 1.7364




K20240801090945





BLK: 8,SNR1: 1.2278 ,SNR2: 5.6349




0556+191 2024/08/01 0.19UT FUJI -KISO



T20240801091421





BLK:27,SNR1: 7.0527 ,SNR2: 20.862





3C152 2024/08/01 0.27UT TOYOKAWA-FUJI



F20240801091421




BLK:27,SNR1: 4.5735 ,SNR2: 11.137



T20240801091421





BLK:33,SNR1: 6.9424 ,SNR2: 20.497





3C152 2024/08/01 0.27UT TOYOKAWA-KISO



K20240801091418




BLK:33,SNR1: 17.096 ,SNR2: 30.157



F20240801091421





BLK:28,SNR1: 5.6022 ,SNR2: 13.444





3C152 2024/08/01 0.27UT FUJI -KISO



K20240801091418




BLK:28,SNR1: 17.450 ,SNR2: 30.777



T20240801093642





BLK:28,SNR1: 2.6056 ,SNR2: 12.595





3C161 2024/08/01 0.64UT TOYOKAWA-FUJI



F20240801093642




BLK:28,SNR1: 7.3981 ,SNR2: 18.603



T20240801093642





BLK:32,SNR1: 2.6061 ,SNR2: 12.597





3C161 2024/08/01 0.64UT TOYOKAWA-KISO

K20240801093639




BLK:32,SNR1: 7.4376 ,SNR2: 21.559






F20240801093642





BLK:35,SNR1: 7.3791 ,SNR2: 18.553





3C161 2024/08/01 0.64UT FUJI -KISO



K20240801093639




BLK:35,SNR1: 7.5516 ,SNR2: 21.921



T20240801100415




BLK: 2,SNR1:-0.84779E-02,SNR2: 0.81360





0652-130 2024/08/01 1.10UT TOYOKAWA-FUJI



F20240801100415




BLK: 2,SNR1: 3.7570 ,SNR2: 11.300





T20240801100415




BLK: 6,SNR1: 0.10333 ,SNR2: 1.3559




K20240801100412




BLK: 6,SNR1: 1.2735 ,SNR2: 5.3067




0652-130 2024/08/01 1.10UT TOYOKAWA-KISO





F20240801100415




BLK: 5,SNR1:-0.31919 ,SNR2: 0.37945




K20240801100412




BLK: 5,SNR1: 1.4638 ,SNR2: 6.3462




0652-130 2024/08/01 1.10UT FUJI -KISO




T20240801101551




BLK:15,SNR1: 2.2959 ,SNR2: 9.2110




F20240801101551




BLK:15,SNR1:-0.58550E-02,SNR2: 2.0006




0703+138 2024/08/01 1.29UT TOYOKAWA-FUJI



T20240801101551





BLK:11,SNR1: 2.3334 ,SNR2: 9.7202





0703+138 2024/08/01 1.29UT TOYOKAWA-KISO



K20240801101548




BLK:11,SNR1: 0.33052 ,SNR2: 2.7044



F20240801101551




BLK:11,SNR1:-0.77684E-01,SNR2: 1.8122




Frequency (Hz)

K20240801101548




BLK:11,SNR1: 0.43967 ,SNR2: 1.3021





Frequency (Hz)


0703+138 2024/08/01 1.29UT FUJI -KISO



T20240801102514





BLK: 4,SNR1: 0.21706 ,SNR2: 2.0882




Frequency (Hz)

F20240801102514




BLK: 4,SNR1: 0.12115E-01,SNR2: 0.91021





Frequency (Hz)

0713-024 2024/08/01 1.45UT TOYOKAWA-FUJI






T20240801102514





BLK:10,SNR1: 0.15851 ,SNR2: 1.6166




Frequency (Hz)

K20240801102511




BLK:10,SNR1: 0.93052 ,SNR2: 2.4339





Frequency (Hz)


0713-024 2024/08/01 1.45UT TOYOKAWA-KISO



F20240801102514





BLK: 3,SNR1: 0.13910 ,SNR2: 2.1830




Frequency (Hz)

K20240801102511




BLK: 3,SNR1: 0.67758 ,SNR2: 4.0070





Frequency (Hz)


0713-024 2024/08/01 1.45UT FUJI -KISO



T20240801103526





BLK:21,SNR1: 3.4224 ,SNR2: 9.6489





0723+10 2024/08/01 1.62UT TOYOKAWA-FUJI



F20240801103526




BLK:21,SNR1: 6.4208 ,SNR2: 15.695



T20240801103526





BLK:25,SNR1: 6.7515 ,SNR2: 11.710





0723+10 2024/08/01 1.62UT TOYOKAWA-KISO



K20240801103523




BLK:25,SNR1: 8.4278 ,SNR2: 23.902





F20240801103526




BLK:23,SNR1: 9.1968 ,SNR2: 24.572




K20240801103523





BLK:23,SNR1: 8.5360 ,SNR2: 24.201




0723+10 2024/08/01 1.62UT FUJI -KISO



T20240801104540





BLK:21,SNR1: 251.49 ,SNR2: 600.81




Frequency (Hz)

F20240801104540




BLK:21,SNR1: 267.33 ,SNR2: 786.66





Frequency (Hz)


0732+33 2024/08/01 1.79UT TOYOKAWA-FUJI



T20240801104540





BLK:29,SNR1: 223.48 ,SNR2: 391.11




Frequency (Hz)

K20240801104537




BLK:29,SNR1: 580.89 ,SNR2: 1167.8




Frequency (Hz)


0732+33 2024/08/01 1.79UT TOYOKAWA-KISO



F20240801104540




BLK:26,SNR1: 232.24 ,SNR2: 683.35




Frequency (Hz)

K20240801104537




BLK:26,SNR1: 824.29 ,SNR2: 1549.4





Frequency (Hz)

0732+33 2024/08/01 1.79UT FUJI -KISO






T20240801105342




BLK:17,SNR1: 3.4754 ,SNR2: 14.945




0741-06 2024/08/01 1.92UT TOYOKAWA-FUJI


F20240801105342





BLK:17,SNR1:-0.15955 ,SNR2: 1.4729




Frequency (Hz)



T20240801105342




BLK:32,SNR1: 2.8939 ,SNR2: 12.861





0741-06 2024/08/01 1.92UT TOYOKAWA-KISO


K20240801105339




BLK:32,SNR1: 2.3617 ,SNR2: 9.0295




F20240801105342




BLK:17,SNR1: 0.33979 ,SNR2: 4.4475




K20240801105339





BLK:17,SNR1: 1.8828 ,SNR2: 7.0952




0741-06 2024/08/01 1.92UT FUJI -KISO





T20240801110327




BLK: 9,SNR1: 0.66074 ,SNR2: 4.1585




F20240801110327





BLK: 9,SNR1: 2.7004 ,SNR2: 10.528




0752-200 2024/08/01 2.09UT TOYOKAWA-FUJI



T20240801110327





BLK:14,SNR1: 0.86061 ,SNR2: 2.7576





0752-200 2024/08/01 2.09UT TOYOKAWA-KISO



K20240801110324




BLK:14,SNR1: 8.3288 ,SNR2: 23.599





F20240801110327




BLK:23,SNR1: 1.6123 ,SNR2: 6.7575




K20240801110324





BLK:23,SNR1: 8.0868 ,SNR2: 22.936




0752-200 2024/08/01 2.09UT FUJI -KISO




T202408011111101




BLK:13,SNR1: 0.46054 ,SNR2: 1.8722




F202408011111101





BLK:13,SNR1: 1.0125 ,SNR2: 5.1402




3C190 2024/08/01 2.21UT TOYOKAWA-FUJI





T202408011111101




BLK:17,SNR1: 0.46289 ,SNR2: 3.8458




K202408011111058



BLK:17,SNR1: 0.55107 ,SNR2: 4.6063





3C190 2024/08/01 2.21UT TOYOKAWA-KISO







F20240801111101




BLK: 8,SNR1: 1.4615 ,SNR2: 10.773




K202408011111058





BLK: 8,SNR1: 0.23138 ,SNR2: 1.5788




3C190 2024/08/01 2.21UT FUJI -KISO





T20240801112326




BLK:26,SNR1: 0.89099 ,SNR2: 3.9254




F20240801112326




BLK:26,SNR1: 0.47124 ,SNR2: 2.1916




3C196 2024/08/01 2.42UT TOYOKAWA-FUJI




T20240801112326




BLK:33,SNR1: 0.94879 ,SNR2: 9.3830




K20240801112323




BLK:33,SNR1: 0.25739 ,SNR2: 1.7455




3C196 2024/08/01 2.42UT TOYOKAWA-KISO




F20240801112326




BLK: 7,SNR1: 0.20665 ,SNR2: 1.3135




K20240801112323




BLK: 7,SNR1: 0.63557 ,SNR2: 4.0352




3C196 2024/08/01 2.42UT FUJI -KISO




T20240801113436




BLK:15,SNR1: 1.1126 ,SNR2: 6.9645




F20240801113436




BLK:15,SNR1: 0.28277E-01,SNR2: 2.3150




0821+394 2024/08/01 2.60UT TOYOKAWA-FUJI



T20240801113436





BLK:24,SNR1: 0.93730 ,SNR2: 6.3379





0821+394 2024/08/01 2.60UT TOYOKAWA-KISO


K20240801113433




BLK:24,SNR1: 1.5944 ,SNR2: 6.4337





F20240801113436




BLK:13,SNR1: 0.34615 ,SNR2: 2.0862




K20240801113433





BLK:13,SNR1: 2.3167 ,SNR2: 9.2966




0821+394 2024/08/01 2.60UT FUJI -KISO



T20240801114616





BLK: 9,SNR1: 4.7688 ,SNR2: 9.1351




0834-19 2024/08/01 2.80UT TOYOKAWA-FUJI


F20240801114616



BLK: 9,SNR1: 0.22889 ,SNR2: 3.8805




Frequency (Hz)






T20240801114616





BLK:20,SNR1: 4.2628 ,SNR2: 8.0394





0834-19 2024/08/01 2.80UT TOYOKAWA-KISO



K20240801114613




BLK:20,SNR1: 0.39485 ,SNR2: 1.0522




F20240801114616




BLK: 8,SNR1: 0.34359 ,SNR2: 3.7664




K20240801114613





BLK: 8,SNR1: 0.60988 ,SNR2: 5.3682




0834-19 2024/08/01 2.80UT FUJI -KISO



T20240801115121





BLK:10,SNR1: 10.660 ,SNR2: 20.708





0839-071 2024/08/01 2.88UT TOYOKAWA-FUJI



F20240801115121




BLK:10,SNR1:-0.24312 ,SNR2: 0.63475



T20240801115121





BLK:11,SNR1: 13.713 ,SNR2: 25.527





0839-071 2024/08/01 2.88UT TOYOKAWA-KISO


K20240801115118




BLK:11,SNR1: 0.37589 ,SNR2: 1.3430



F20240801115121





BLK: 2,SNR1:-0.24613 ,SNR2: 0.58204E-02





0839-071 2024/08/01 2.88UT FUJI -KISO


K20240801115118




BLK: 2,SNR1: 0.34990 ,SNR2: 1.7988




T20240801120222




BLK:24,SNR1: 29.371 ,SNR2: 175.34




F20240801120222




BLK:24,SNR1: 24.469 ,SNR2: 95.666




3C208 2024/08/01 3.07UT TOYOKAWA-FUJI





T20240801120222




BLK:10,SNR1: 69.666 ,SNR2: 188.66




K20240801120219




BLK:10,SNR1: 5.5120 ,SNR2: 25.873




3C208 2024/08/01 3.07UT TOYOKAWA-KISO



F20240801120222





BLK:14,SNR1: 34.315 ,SNR2: 183.72





3C208 2024/08/01 3.07UT FUJI -KISO

K20240801120219





BLK:14,SNR1: 3.8833 ,SNR2: 16.524







T20240801121903




BLK:10,SNR1: 0.47364 ,SNR2: 3.7207




F20240801121903





BLK:10,SNR1: 0.45000E-01,SNR2: 3.2106




3C216 2024/08/01 3.35UT TOYOKAWA-FUJI




T20240801121903




BLK:21,SNR1: 0.66176 ,SNR2: 2.3886




K20240801121900





BLK:21,SNR1: 0.38021 ,SNR2: 1.9301




3C216 2024/08/01 3.35UT TOYOKAWA-KISO



F20240801121903





BLK: 4,SNR1:-0.15353 ,SNR2: 2.2161




Frequency (Hz)

3C216 2024/08/01 3.35UT FUJI -KISO


K20240801121900





BLK: 4,SNR1: 0.31969 ,SNR2: 0.95758




Frequency (Hz)




T20240801123115




BLK: 6,SNR1:-0.82085E-01,SNR2: 0.54887




F20240801123115




BLK: 6,SNR1: 0.66805 ,SNR2: 1.3077




0919-142 2024/08/01 3.55UT TOYOKAWA-FUJI





T20240801123115




BLK: 8,SNR1: 0.29128E-01,SNR2: 0.35096




K20240801123112




BLK: 8,SNR1: 0.15487 ,SNR2: 1.3013




0919-142 2024/08/01 3.55UT TOYOKAWA-KISO




F20240801123115




BLK: 2,SNR1:-0.21259E-01,SNR2: 2.3733




K20240801123112





BLK: 2,SNR1: 0.23556 ,SNR2: 0.38688




0919-142 2024/08/01 3.55UT FUJI -KISO





T20240801123754




BLK: 3,SNR1: 0.19169 ,SNR2: 3.8229




F20240801123754





BLK: 3,SNR1:-0.76149E-01,SNR2: 1.5630




0926+117 2024/08/01 3.66UT TOYOKAWA-FUJI





T20240801123754




BLK: 5,SNR1: 0.10074 ,SNR2: 1.0581




K20240801123751



BLK: 5,SNR1: 0.66524 ,SNR2: 2.4609




0926+117 2024/08/01 3.66UT TOYOKAWA-KISO








F20240801123754




BLK: 1,SNR1: 0.80496E-01,SNR2: 0.40974




K20240801123751




BLK: 1,SNR1: 0.66156E-01,SNR2: 1.6102




0926+117 2024/08/01 3.66UT FUJI -KISO




T20240801124538




BLK: 9,SNR1: 1.2862 ,SNR2: 10.502




F20240801124538





BLK: 9,SNR1:-0.23216 ,SNR2: 0.69639




3C222 2024/08/01 3.79UT TOYOKAWA-FUJI



T20240801124538





BLK:20,SNR1: 1.3847 ,SNR2: 4.1678





3C222 2024/08/01 3.79UT TOYOKAWA-KISO


K20240801124536




BLK:20,SNR1: 0.61492 ,SNR2: 1.6875




F20240801124538




BLK: 4,SNR1:-0.15673 ,SNR2: 0.62978




K20240801124536





BLK: 4,SNR1: 0.65318 ,SNR2: 1.8054




3C222 2024/08/01 3.79UT FUJI -KISO




T20240801125239




BLK: 2,SNR1: 0.92391E-01,SNR2: 0.57976




F20240801125239





BLK: 2,SNR1: 0.16815 ,SNR2: 2.4602




0941-08 2024/08/01 3.91UT TOYOKAWA-FUJI





T20240801125239




BLK: 9,SNR1: 0.49370 ,SNR2: 1.6110




K20240801125236





BLK: 9,SNR1: 0.49282 ,SNR2: 1.6114




0941-08 2024/08/01 3.91UT TOYOKAWA-KISO





F20240801125239




BLK: 4,SNR1: 0.25710 ,SNR2: 2.7869




K20240801125236





BLK: 4,SNR1: 0.44487 ,SNR2: 2.5826




0941-08 2024/08/01 3.91UT FUJI -KISO



T20240801130100




BLK: 8,SNR1: 0.52533 ,SNR2: 4.9182





3C230 2024/08/01 4.04UT TOYOKAWA-FUJI

F20240801130100





BLK: 8,SNR1: 0.76104 ,SNR2: 4.7744






T20240801130100





BLK:16,SNR1: 0.71770 ,SNR2: 4.2805





3C230 2024/08/01 4.04UT TOYOKAWA-KISO


K20240801130057




BLK:16,SNR1: 0.38494 ,SNR2: 0.75653



F20240801130100





BLK: 4,SNR1: 0.68426 ,SNR2: 8.9296





3C230 2024/08/01 4.04UT FUJI -KISO


K20240801130057




BLK: 4,SNR1: 0.21181 ,SNR2: 1.1672





T20240801131508




BLK:12,SNR1: 0.69344 ,SNR2: 3.7815




F20240801131508




BLK:12,SNR1: 0.25730 ,SNR2: 4.1947




3C236 2024/08/01 4.28UT TOYOKAWA-FUJI





T20240801131508




BLK:22,SNR1: 0.88400 ,SNR2: 7.8420




K20240801131505





BLK:22,SNR1: 0.45018 ,SNR2: 4.5826




3C236 2024/08/01 4.28UT TOYOKAWA-KISO





F20240801131508




BLK: 9,SNR1: 0.91909E-01,SNR2: 2.2193




K20240801131505





BLK: 9,SNR1: 0.37255 ,SNR2: 1.3442




3C236 2024/08/01 4.28UT FUJI -KISO




T20240801132317




BLK: 4,SNR1: 1.4971 ,SNR2: 11.388




F20240801132317





BLK: 4,SNR1:-0.81939E-01,SNR2: 0.36921




1011+110 2024/08/01 4.42UT TOYOKAWA-FUJI





T20240801132317




BLK: 5,SNR1: 1.2904 ,SNR2: 9.8756




K20240801132314




BLK: 5,SNR1: 0.40923 ,SNR2: 1.6554




1011+110 2024/08/01 4.42UT TOYOKAWA-KISO




F20240801132317




BLK: 6,SNR1: 0.55875 ,SNR2: 4.6555




K20240801132314



BLK: 6,SNR1: 0.32193 ,SNR2: 0.75979




1011+110 2024/08/01 4.42UT FUJI -KISO






T20240801133058




BLK: 9,SNR1: 1.2203 ,SNR2: 7.2455





3C241 2024/08/01 4.54UT TOYOKAWA-FUJI


F20240801133058




BLK: 9,SNR1: 0.31869 ,SNR2: 1.5828





T20240801133058




BLK:10,SNR1: 1.4205 ,SNR2: 8.5334




K20240801133055




BLK:10,SNR1: 0.66615 ,SNR2: 1.8900




3C241 2024/08/01 4.54UT TOYOKAWA-KISO





F20240801133058




BLK: 6,SNR1: 0.53560 ,SNR2: 2.6161




K20240801133055





BLK: 6,SNR1: 0.30499 ,SNR2: 2.1906




3C241 2024/08/01 4.54UT FUJI -KISO




T20240801134228




BLK: 3,SNR1: 0.15029 ,SNR2: 0.68508




F20240801134228





BLK: 3,SNR1:-0.15634 ,SNR2: 1.1782




1031-11 2024/08/01 4.74UT TOYOKAWA-FUJI





T20240801134228




BLK: 7,SNR1: 0.72710E-01,SNR2: 0.80438




K20240801134225





BLK: 7,SNR1: 0.95685 ,SNR2: 4.9180




1031-11 2024/08/01 4.74UT TOYOKAWA-KISO



F20240801134228





BLK: 3,SNR1:-0.20297 ,SNR2: 1.4669




Frequency (Hz)

K20240801134225




BLK: 3,SNR1: 0.52594 ,SNR2: 3.9432





Frequency (Hz)


1031-11 2024/08/01 4.74UT FUJI -KISO





T20240801134701




BLK: 6,SNR1: 5.6619 ,SNR2: 14.722




F20240801134701





BLK: 6,SNR1: 0.58749 ,SNR2: 1.6191




1035-058 2024/08/01 4.81UT TOYOKAWA-FUJI





T20240801134701




BLK: 6,SNR1: 12.396 ,SNR2: 33.469




K20240801134658



BLK: 6,SNR1: 21.476 ,SNR2: 33.205




1035-058 2024/08/01 4.81UT TOYOKAWA-KISO








F20240801134701




BLK: 8,SNR1: 0.92596E-01,SNR2: 1.7808




K20240801134658





BLK: 8,SNR1: 18.744 ,SNR2: 28.987




1035-058 2024/08/01 4.81UT FUJI -KISO




T20240801135614




BLK: 1,SNR1: 0.83926E-02,SNR2: 0.84788




F20240801135614





BLK: 1,SNR1:-0.54642E-01,SNR2: 0.81674




1044-008 2024/08/01 4.97UT TOYOKAWA-FUJI





T20240801135614




BLK: 5,SNR1: 0.41824E-01,SNR2: 0.67853




K20240801135611





BLK: 5,SNR1: 0.45209 ,SNR2: 3.2853




1044-008 2024/08/01 4.97UT TOYOKAWA-KISO





F20240801135614




BLK: 4,SNR1: 0.59463E-01,SNR2: 3.1735




K20240801135611





BLK: 4,SNR1: 0.22111 ,SNR2: 0.53782




1044-008 2024/08/01 4.97UT FUJI -KISO




T20240801140718




BLK: 5,SNR1: 0.48912 ,SNR2: 2.1097




F20240801140718




BLK: 5,SNR1: 0.63244 ,SNR2: 2.2530




1055+01 2024/08/01 5.15UT TOYOKAWA-FUJI





T20240801140718




BLK: 9,SNR1: 0.24593 ,SNR2: 1.4327




K20240801140715





BLK: 9,SNR1: 0.89414E-01,SNR2: 0.84118




1055+01 2024/08/01 5.15UT TOYOKAWA-KISO



F20240801140718





BLK: 4,SNR1: 0.46775 ,SNR2: 1.5512




Frequency (Hz)

K20240801140715




BLK: 4,SNR1: 0.23233 ,SNR2: 1.3431





Frequency (Hz)


1055+01 2024/08/01 5.15UT FUJI -KISO



T20240801141836





BLK: 5,SNR1: 0.26725 ,SNR2: 0.64530




Frequency (Hz)

F20240801141836




BLK: 5,SNR1: 0.54167 ,SNR2: 2.4551





Frequency (Hz)

1107+109 2024/08/01 5.34UT TOYOKAWA-FUJI








T20240801141836




BLK: 8,SNR1: 0.13255 ,SNR2: 0.89956




K20240801141833





BLK: 8,SNR1: 1.0167 ,SNR2: 2.9748




1107+109 2024/08/01 5.34UT TOYOKAWA-KISO




F20240801141836




BLK: 3,SNR1: 0.22884 ,SNR2: 0.76266




K20240801141833





BLK: 3,SNR1: 0.85392 ,SNR2: 6.0177




1107+109 2024/08/01 5.34UT FUJI -KISO



T20240801142813





BLK: 4,SNR1: 0.47569 ,SNR2: 2.2530




Frequency (Hz)

F20240801142813




BLK: 4,SNR1: 0.14661 ,SNR2: 2.1323





Frequency (Hz)


3C255 2024/08/01 5.50UT TOYOKAWA-FUJI





T20240801142813




BLK:12,SNR1: 0.26732 ,SNR2: 2.0819




K20240801142810




BLK:12,SNR1: 0.40807 ,SNR2: 1.6404




3C255 2024/08/01 5.50UT TOYOKAWA-KISO



F20240801142813





BLK: 6,SNR1:-0.66481E-01,SNR2: 2.0893




Frequency (Hz)

K20240801142810




BLK: 6,SNR1: 0.51924 ,SNR2: 2.3862





Frequency (Hz)


3C255 2024/08/01 5.50UT FUJI -KISO



T20240801143851





BLK: 3,SNR1: 0.27247 ,SNR2: 2.6940




Frequency (Hz)

F20240801143851




BLK: 3,SNR1: 0.22579 ,SNR2: 2.6283





Frequency (Hz)


1127-14 2024/08/01 5.68UT TOYOKAWA-FUJI





T20240801143851




BLK: 5,SNR1: 0.25427 ,SNR2: 1.8235




K20240801143848





BLK: 5,SNR1: 0.99372 ,SNR2: 5.0979




1127-14 2024/08/01 5.68UT TOYOKAWA-KISO





F20240801143851




BLK: 8,SNR1:-0.36008E-02,SNR2: 1.6200




K20240801143848



BLK: 8,SNR1: 0.82576 ,SNR2: 3.8536





1127-14 2024/08/01 5.68UT FUJI -KISO






T20240801145211





BLK: 7,SNR1: 3.0985 ,SNR2: 13.312




Frequency (Hz)

F20240801145211




BLK: 7,SNR1: 79.972 ,SNR2: 368.51





Frequency (Hz)


3C263.1 2024/08/01 5.90UT TOYOKAWA-FUJI





T20240801145211




BLK: 8,SNR1: 2.8720 ,SNR2: 19.088




K20240801145208





BLK: 8,SNR1: 15.709 ,SNR2: 63.521




3C263.1 2024/08/01 5.90UT TOYOKAWA-KISO





F20240801145211




BLK: 8,SNR1: 71.056 ,SNR2: 320.01




K20240801145208





BLK: 8,SNR1: 15.196 ,SNR2: 88.013




3C263.1 2024/08/01 5.90UT FUJI -KISO





T20240801145838




BLK: 5,SNR1: 0.34574 ,SNR2: 1.0457




F20240801145838





BLK: 5,SNR1: 0.33183 ,SNR2: 1.6923




3C267 2024/08/01 6.01UT TOYOKAWA-FUJI





T20240801145838




BLK: 5,SNR1: 0.47251 ,SNR2: 1.6989




K20240801145835




BLK: 5,SNR1: 1.5073 ,SNR2: 6.6744




3C267 2024/08/01 6.01UT TOYOKAWA-KISO




F20240801145838




BLK: 9,SNR1: 0.76742 ,SNR2: 1.7007




K20240801145835





BLK: 9,SNR1: 4.0146 ,SNR2: 18.005




3C267 2024/08/01 6.01UT FUJI -KISO




T20240801152426




BLK:15,SNR1: 18.715 ,SNR2: 23.062




F20240801152426




BLK:15,SNR1: 1.1428 ,SNR2: 6.7646




1213-17 2024/08/01 6.44UT TOYOKAWA-FUJI





T20240801152426




BLK:20,SNR1: 17.002 ,SNR2: 21.466




K20240801152423



BLK:20,SNR1: 3.9360 ,SNR2: 10.923




1213-17 2024/08/01 6.44UT TOYOKAWA-KISO






F20240801152426





BLK:21,SNR1: 1.3999 ,SNR2: 7.0326




Frequency (Hz)

K20240801152423




BLK:21,SNR1: 3.0804 ,SNR2: 9.1174




Frequency (Hz)


1213-17 2024/08/01 6.44UT FUJI -KISO



T20240801153743




BLK: 6,SNR1: 2.3999 ,SNR2: 10.946




Frequency (Hz)

F20240801153743




BLK: 6,SNR1: 0.12064 ,SNR2: 1.1150





Frequency (Hz)


3C273 2024/08/01 6.66UT TOYOKAWA-FUJI





T20240801153743




BLK:23,SNR1: 2.5365 ,SNR2: 10.000




K20240801153741





BLK:23,SNR1: 1.4568 ,SNR2: 5.8255




3C273 2024/08/01 6.66UT TOYOKAWA-KISO





F20240801153743




BLK:14,SNR1:-0.68778E-01,SNR2: 1.2796




K20240801153741





BLK:14,SNR1: 2.1477 ,SNR2: 8.9232




3C273 2024/08/01 6.66UT FUJI -KISO



T20240801155054





BLK: 6,SNR1: 3.2458 ,SNR2: 15.043




Frequency (Hz)

F20240801155054




BLK: 6,SNR1:-0.11991 ,SNR2: 1.7188





Frequency (Hz)


3C275 2024/08/01 6.88UT TOYOKAWA-FUJI



T20240801155054





BLK:11,SNR1: 2.9438 ,SNR2: 13.603




Frequency (Hz)

3C275 2024/08/01 6.88UT TOYOKAWA-KISO


K20240801155051




BLK:11,SNR1: 3.6114 ,SNR2: 16.313




Frequency (Hz)



F20240801155054





BLK:18,SNR1: 0.52553 ,SNR2: 3.0225




Frequency (Hz)

K20240801155051




BLK:18,SNR1: 4.1637 ,SNR2: 10.736





Frequency (Hz)


3C275 2024/08/01 6.88UT FUJI -KISO



T20240801155659





BLK: 9,SNR1: 0.18244 ,SNR2: 1.1298




Frequency (Hz)

F20240801155659




BLK: 9,SNR1: 0.69094 ,SNR2: 2.4528




Frequency (Hz)

1245-19 2024/08/01 6.98UT TOYOKAWA-FUJI






T20240801155659





BLK: 5,SNR1: 0.13731 ,SNR2: 1.1802




Frequency (Hz)

K20240801155656




BLK: 5,SNR1: 1.0396 ,SNR2: 4.5623





Frequency (Hz)


1245-19 2024/08/01 6.98UT TOYOKAWA-KISO



F20240801155659





BLK: 9,SNR1: 0.63682 ,SNR2: 1.9874




Frequency (Hz)

K20240801155656




BLK: 9,SNR1: 0.22549 ,SNR2: 0.77390





Frequency (Hz)


1245-19 2024/08/01 6.98UT FUJI -KISO



T20240801160443




BLK: 6,SNR1: 2.5683 ,SNR2: 11.693




Frequency (Hz)

F20240801160443




BLK: 6,SNR1: 1.5479 ,SNR2: 12.894





Frequency (Hz)


3C279 2024/08/01 7.11UT TOYOKAWA-FUJI



T20240801160443





BLK:21,SNR1: 3.0398 ,SNR2: 13.407




Frequency (Hz)

K20240801160441




BLK:21,SNR1: 7.3785 ,SNR2: 20.639




Frequency (Hz)


3C279 2024/08/01 7.11UT TOYOKAWA-KISO



F20240801160443





BLK:19,SNR1: 0.40323 ,SNR2: 5.3967




Frequency (Hz)

K20240801160441




BLK:19,SNR1: 20.965 ,SNR2: 27.157





Frequency (Hz)


3C279 2024/08/01 7.11UT FUJI -KISO



T20240801162012





BLK: 9,SNR1: 0.15999 ,SNR2: 1.1849




Frequency (Hz)

F20240801162012




BLK: 9,SNR1: 0.61634 ,SNR2: 2.4684





Frequency (Hz)


3C283 2024/08/01 7.36UT TOYOKAWA-FUJI



T20240801162012





BLK: 5,SNR1: 0.37536 ,SNR2: 3.2088




Frequency (Hz)

3C283 2024/08/01 7.36UT TOYOKAWA-KISO


K20240801162010




BLK: 5,SNR1: 0.17771 ,SNR2: 0.44029




Frequency (Hz)



F20240801162012





BLK: 8,SNR1: 0.39774E-01,SNR2: 1.8623




Frequency (Hz)

K20240801162010




BLK: 8,SNR1: 1.4474 ,SNR2: 7.0365





Frequency (Hz)

3C283 2024/08/01 7.36UT FUJI -KISO






T20240801163437





BLK: 3,SNR1: 16.991 ,SNR2: 33.033




Frequency (Hz)

F20240801163437




BLK: 3,SNR1: 1.0074 ,SNR2: 3.4763





Frequency (Hz)


1323+32 2024/08/01 7.61UT TOYOKAWA-FUJI



T20240801163437





BLK: 7,SNR1: 12.753 ,SNR2: 24.807




Frequency (Hz)

K20240801163434




BLK: 7,SNR1: 1.8201 ,SNR2: 9.4078





Frequency (Hz)


1323+32 2024/08/01 7.61UT TOYOKAWA-KISO



F20240801163437





BLK:10,SNR1: 1.0139 ,SNR2: 3.7370




Frequency (Hz)

K20240801163434




BLK:10,SNR1: 2.7577 ,SNR2: 8.3341




Frequency (Hz)


1323+32 2024/08/01 7.61UT FUJI -KISO



T20240801163927





BLK:27,SNR1: 4.6793 ,SNR2: 9.1320




Frequency (Hz)

F20240801163927




BLK:27,SNR1: 36.816 ,SNR2: 77.299




Frequency (Hz)


3C286 2024/08/01 7.69UT TOYOKAWA-FUJI



T20240801163927




BLK:25,SNR1: 6.0887 ,SNR2: 14.821




Frequency (Hz)

K20240801163924




BLK:25,SNR1: 7.5233 ,SNR2: 17.967





Frequency (Hz)


3C286 2024/08/01 7.69UT TOYOKAWA-KISO



F20240801163927




BLK:22,SNR1: 31.917 ,SNR2: 65.033




Frequency (Hz)

K20240801163924




BLK:22,SNR1: 8.1595 ,SNR2: 19.479





Frequency (Hz)


3C286 2024/08/01 7.69UT FUJI -KISO



T20240801165554





BLK: 9,SNR1: 0.18600 ,SNR2: 0.84950




Frequency (Hz)

F20240801165554




BLK: 9,SNR1: 0.31673 ,SNR2: 3.4633





Frequency (Hz)


1345+12 2024/08/01 7.96UT TOYOKAWA-FUJI



T20240801165554





BLK:14,SNR1: 0.23919 ,SNR2: 0.91229




Frequency (Hz)

K20240801165551




BLK:14,SNR1: 4.3756 ,SNR2: 17.300





Frequency (Hz)

1345+12 2024/08/01 7.96UT TOYOKAWA-KISO






F20240801165554




BLK:18,SNR1: 0.36296 ,SNR2: 1.2615




Frequency (Hz)

K20240801165551




BLK:18,SNR1: 3.9983 ,SNR2: 15.842




Frequency (Hz)


1345+12 2024/08/01 7.96UT FUJI -KISO



T20240801170614




BLK:17,SNR1: 104.75 ,SNR2: 118.14




Frequency (Hz)

F20240801170614




BLK:17,SNR1: 115.63 ,SNR2: 111.78




Frequency (Hz)


1355+01 2024/08/01 8.13UT TOYOKAWA-FUJI



T20240801170614




BLK:14,SNR1: 106.43 ,SNR2: 120.02




Frequency (Hz)

K20240801170611





BLK:14,SNR1: 11.358 ,SNR2: 11.886





Frequency (Hz)

1355+01 2024/08/01 8.13UT TOYOKAWA-KISO







BLK:14,SNR1: 112.96 ,SNR2: 108.68





BLK:14,SNR1: 8.9689 ,SNR2: 9.4341




1355+01 2024/08/01 8.13UT FUJI -KISO



T20240801174903




BLK:17,SNR1: 3.0165 ,SNR2: 8.2117




Frequency (Hz)

F20240801174903




BLK:17,SNR1: 0.88034 ,SNR2: 5.2971





Frequency (Hz)


1438+357 2024/08/01 8.85UT TOYOKAWA-FUJI



T20240801174903




BLK:15,SNR1: 3.2915 ,SNR2: 9.2294




Frequency (Hz)

K20240801174900




BLK:15,SNR1: 4.0985 ,SNR2: 8.1254




Frequency (Hz)


1438+357 2024/08/01 8.85UT TOYOKAWA-KISO



F20240801174903




BLK:23,SNR1: 1.7480 ,SNR2: 6.3526




Frequency (Hz)

K20240801174900




BLK:23,SNR1: 3.9435 ,SNR2: 7.7575





Frequency (Hz)


1438+357 2024/08/01 8.85UT Fuji -KISO



T20240801180154





BLK: 4,SNR1: 0.23922 ,SNR2: 1.4077




Frequency (Hz)

F20240801180154




BLK: 4,SNR1: 0.46166E-01,SNR2: 0.75278





Frequency (Hz)

1452+502 2024/08/01 9.06UT TOYOKAWA-FUJI






T20240801180154





BLK: 7,SNR1: 0.32969E-01,SNR2: 0.97391




Frequency (Hz)

K20240801180152




BLK: 7,SNR1: 6.5176 ,SNR2: 16.306





Frequency (Hz)


1452+502 2024/08/01 9.06UT TOYOKAWA-KISO



F20240801180154





BLK: 2,SNR1: 0.27772E-01,SNR2: 2.8533




Frequency (Hz)

K20240801180152



BLK: 2,SNR1: 2.1008 ,SNR2: 9.8229



Frequency (Hz)

1452+502 2024/08/01 9.06UT FWJI -KISO

