




T20240805063107





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0333+32 2024/08/04 21.55UT TOYOKAWA-FUJI



T20240805063107





BLK: 8,SNR1: 0.89682E-01,SNR2: 1.1361




Frequency (Hz)

K20240805063104




BLK: 8,SNR1: 1.5938 ,SNR2: 6.5910





Frequency (Hz)


0333+32 2024/08/04 21.55UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805063104




No.Good Data





Frequency (Hz)


0333+32 2024/08/04 21.55UT FUJI -KISO



T20240805064409




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

0347+05 2024/08/04 21.76UT TOYOKAWA-FUJI






FUJI





No.Good Data




Frequency (Hz)

K20240805064407




No.Good Data





Frequency (Hz)


0347+05 2024/08/04 21.76UT FUJI -KISO




T20240805070854




No.Good Data




FUJI





No.Good Data




0411+05 2024/08/04 22.18UT TOYOKAWA-FUJI



T20240805070854





BLK: 5,SNR1: 0.75009E-01,SNR2: 1.7752




Frequency (Hz)

K20240805070851




BLK: 5,SNR1: 82.041 ,SNR2: 78.560





Frequency (Hz)

0411+05 2024/08/04 22.18UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240805070851




No.Good Data




Frequency (Hz)


0411+05 2024/08/04 22.18UT FUJI -KISO





T20240805071548




No.Good Data




FUJI





No.Good Data




0418+236 2024/08/04 22.29UT TOYOKAWA-FUJI



T20240805071548





BLK: 7,SNR1: 4.3341 ,SNR2: 14.914




Frequency (Hz)

K20240805071545




BLK: 7,SNR1: 2.8879 ,SNR2: 11.591





Frequency (Hz)


0418+236 2024/08/04 22.29UT TOYOKAWA-KISO





FUJI




No.Good Data




K20240805071545





No.Good Data




0418+236 2024/08/04 22.29UT FUJI -KISO





T20240805072715




No.Good Data




FUJI





No.Good Data




3C119 2024/08/04 22.48UT TOYOKAWA-FUJI



T20240805072715





BLK:13,SNR1: 6.0485 ,SNR2: 10.344




Frequency (Hz)

K20240805072713




BLK:13,SNR1: 74.804 ,SNR2: 87.259





Frequency (Hz)


3C119 2024/08/04 22.48UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805072713




No.Good Data




Frequency (Hz)


3C119 2024/08/04 22.48UT FUJI -KISO





T20240805081522




No.Good Data




FUJI



No.Good Data





3C138 2024/08/04 23.28UT TOYOKAWA-FUJI






T20240805081522





BLK:22,SNR1: 0.91865 ,SNR2: 3.2477




Frequency (Hz)

3C138 2024/08/04 23.28UT TOYOKAWA-KISO


K20240805081520





BLK:22,SNR1: 1.4537 ,SNR2: 3.0182




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20240805081520




No.Good Data





Frequency (Hz)


3C138 2024/08/04 23.28UT FUJI -KISO



T20240805082856




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0531+194 2024/08/04 23.51UT TOYOKAWA-FUJI



T20240805082856





BLK:19,SNR1: 5.5082 ,SNR2: 14.711




Frequency (Hz)

K20240805082853




BLK:19,SNR1: 10.561 ,SNR2: 19.692





Frequency (Hz)


0531+194 2024/08/04 23.51UT TOYOKAWA-KISO





FUJI




No.Good Data




K20240805082853





No.Good Data




0531+194 2024/08/04 23.51UT FUJI -KISO





T20240805083715




No.Good Data




FUJI




No.Good Data




3C147 2024/08/04 23.65UT TOYOKAWA-FUJI



T20240805083715




BLK:27,SNR1: 2.6933 ,SNR2: 7.3178




Frequency (Hz)

3C147 2024/08/04 23.65UT TOYOKAWA-KISO


K20240805083713





BLK:27,SNR1: 3.7879 ,SNR2: 13.956




Frequency (Hz)



FUJI




No.Good Data




Frequency (Hz)

K20240805083713




No.Good Data





Frequency (Hz)

3C147 2024/08/04 23.65UT FUJI -KISO








T20240805084527




No.Good Data




FUJI





No.Good Data




0548+16 2024/08/04 23.79UT TOYOKAWA-FUJI



T20240805084527





BLK: 3,SNR1: 0.91104E-01,SNR2: 0.41295




Frequency (Hz)

K20240805084524




BLK: 3,SNR1: 1.4420 ,SNR2: 6.1752





Frequency (Hz)


0548+16 2024/08/04 23.79UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805084524




No.Good Data





Frequency (Hz)


0548+16 2024/08/04 23.79UT FUJI -KISO



T20240805084938





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0552+12 2024/08/04 23.86UT TOYOKAWA-FUJI



T20240805084938





BLK: 6,SNR1: 0.78458 ,SNR2: 3.4579




Frequency (Hz)

K20240805084935




BLK: 6,SNR1: 1.2353 ,SNR2: 5.0487





Frequency (Hz)


0552+12 2024/08/04 23.86UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805084935




No.Good Data





Frequency (Hz)


0552+12 2024/08/04 23.86UT FUJI -KISO



T20240805085404





No.Good Data




Frequency (Hz)

FUJI





No.Good Data





Frequency (Hz)

0556+191 2024/08/04 23.93UT TOYOKAWA-FUJI







BLK:31,SNR1: 8.4656 ,SNR2: 22.961



BLK:31,SNR1: 62.911 ,SNR2: 59.156





0556+191 2024/08/04 23.93UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240805085401




No.Good Data





Frequency (Hz)


0556+191 2024/08/04 23.93UT FUJI -KISO





T20240805092058




No.Good Data




FUJI





No.Good Data




3C161 2024/08/05 0.38UT TOYOKAWA-FUJI



T20240805092058





BLK:26,SNR1: 10.738 ,SNR2: 18.343




Frequency (Hz)

3C161 2024/08/05 0.38UT TOYOKAWA-KISO


K20240805092055





BLK:26,SNR1: 8.8999 ,SNR2: 20.628




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20240805092055




No.Good Data





Frequency (Hz)


3C161 2024/08/05 0.38UT FUJI -KISO



T20240805094831





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0652-130 2024/08/05 0.84UT TOYOKAWA-FUJI



T20240805094831





BLK:14,SNR1: 2.5317 ,SNR2: 6.8532




Frequency (Hz)

K20240805094829




BLK:14,SNR1: 4.1974 ,SNR2: 16.883





Frequency (Hz)


0652-130 2024/08/05 0.84UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805094829




No.Good Data





Frequency (Hz)


0652-130 2024/08/05 0.84UT FUJI -KISO





T20240805100007




No.Good Data




FUJI



No.Good Data




0703+138 2024/08/05 1.03UT TOYOKAWA-FUJI






T20240805100007





BLK: 5,SNR1: 0.20906 ,SNR2: 1.8753




Frequency (Hz)

K20240805100005




BLK: 5,SNR1: 0.73913 ,SNR2: 3.0696





Frequency (Hz)


0703+138 2024/08/05 1.03UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805100005




No.Good Data





Frequency (Hz)


0703+138 2024/08/05 1.03UT FUJI -KISO





T20240805100930




No.Good Data




FUJI





No.Good Data




0713-024 2024/08/05 1.19UT TOYOKAWA-FUJI



T20240805100930





BLK: 6,SNR1: 0.11964 ,SNR2: 1.5419




Frequency (Hz)

K20240805100927




BLK: 6,SNR1: 0.37880 ,SNR2: 1.6901





Frequency (Hz)


0713-024 2024/08/05 1.19UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805100927




No.Good Data





Frequency (Hz)


0713-024 2024/08/05 1.19UT FUJI -KISO





T20240805101942




No.Good Data




FUJI





No.Good Data




0723+10 2024/08/05 1.36UT TOYOKAWA-FUJI



T20240805101942





BLK: 9,SNR1: 0.14864 ,SNR2: 1.8664





0723+10 2024/08/05 1.36UT TOYOKAWA-KISO



K20240805101939




BLK: 9,SNR1: 0.72777 ,SNR2: 3.6651



FUJI





No.Good Data




Frequency (Hz)

K20240805101939




No.Good Data





Frequency (Hz)

0723+10 2024/08/05 1.36UT FUJI -KISO








T20240805102957




No.Good Data




FUJI





No.Good Data




0732+33 2024/08/05 1.53UT TOYOKAWA-FUJI





T20240805102957




BLK:11,SNR1: 2.3640 ,SNR2: 9.0443




K20240805102955





BLK:11,SNR1: 0.28760 ,SNR2: 1.7072




0732+33 2024/08/05 1.53UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20240805102955




No. Good Data





Frequency (Hz)


0732+33 2024/08/05 1.53UT FUJI -KISO





T20240805103759




No. Good Data




FUJI




No. Good Data




0741-06 2024/08/05 1.66UT TOYOKAWA-FUJI



T20240805103759




BLK:22,SNR1: 0.73176 ,SNR2: 6.3163





0741-06 2024/08/05 1.66UT TOYOKAWA-KISO



K20240805103756




BLK:22,SNR1: 0.34995 ,SNR2: 0.53820



FUJI





No.Good Data




Frequency (Hz)

K20240805103756




No.Good Data





Frequency (Hz)


0741-06 2024/08/05 1.66UT FUJI -KISO





T20240805104743




No.Good Data




FUJI





No.Good Data




0752-200 2024/08/05 1.82UT TOYOKAWA-FUJI



T20240805104743





BLK: 3,SNR1: 0.53981 ,SNR2: 1.6725




Frequency (Hz)

K20240805104740




BLK: 3,SNR1: 0.24115 ,SNR2: 2.4519





Frequency (Hz)

0752-200 2024/08/05 1.82UT TOYOKAWA-KISO






FUJI





No. Good Data




Frequency (Hz)

K20240805104740




No. Good Data





Frequency (Hz)


0752-200 2024/08/05 1.82UT FUJI -KISO





T20240805105518




No.Good Data




FUJI





No.Good Data




3C190 2024/08/05 1.95UT TOYOKAWA-FUJI



T20240805105518





BLK:18,SNR1: 125.26 ,SNR2: 143.64





3C190 2024/08/05 1.95UT TOYOKAWA-KISO



K20240805105515




BLK:18,SNR1: 0.41571 ,SNR2: 1.9854



FUJI





No. Good Data




Frequency (Hz)

K20240805105515




No. Good Data





Frequency (Hz)


3C190 2024/08/05 1.95UT FUJI -KISO



T20240805110742





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C196 2024/08/05 2.16UT TOYOKAWA-FUJI




T20240805110742




BLK:15,SNR1: 0.30536 ,SNR2: 2.2146




K20240805110739





BLK:15,SNR1: 0.61342 ,SNR2: 2.5068




3C196 2024/08/05 2.16UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20240805110739




No. Good Data





Frequency (Hz)


3C196 2024/08/05 2.16UT FUJI -KISO



T20240805111852





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)

0821+394 2024/08/05 2.34UT TOYOKAWA-FUJI






T20240805111852





BLK:11,SNR1: 0.31807 ,SNR2: 2.2364




Frequency (Hz)

0821+394 2024/08/05 2.34UT TOYOKAWA-KISO


K20240805111849





BLK:11,SNR1: 0.43753 ,SNR2: 3.1233




Frequency (Hz)



FUJI





No. Good Data




Frequency (Hz)

K20240805111849




No. Good Data





Frequency (Hz)


0821+394 2024/08/05 2.34UT FUJI -KISO



T20240805113032





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0834-19 2024/08/05 2.54UT TOYOKAWA-FUJI



T20240805113032





BLK:18,SNR1: 0.61769 ,SNR2: 4.0523




0834-19 2024/08/05 2.54UT TOYOKAWA-KISO


K20240805113029





BLK:18,SNR1: 1.8117 ,SNR2: 8.9873




Frequency (Hz)



FUJI





No. Good Data




Frequency (Hz)

K20240805113029




No. Good Data





Frequency (Hz)


0834-19 2024/08/05 2.54UT FUJI -KISO



T20240805113538





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0839-071 2024/08/05 2.62UT TOYOKAWA-FUJI



T20240805113538




BLK: 5,SNR1: 1.0739 ,SNR2: 4.1791





0839-071 2024/08/05 2.62UT TOYOKAWA-KISO



K20240805113535




BLK: 5,SNR1: 1.1336 ,SNR2: 4.4731



FUJI





No.Good Data




Frequency (Hz)

K20240805113535




No.Good Data





Frequency (Hz)

0839-071 2024/08/05 2.62UT FUJI -KISO






T20240805114638





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C208 2024/08/05 2.81UT TOYOKAWA-FUJI





T20240805114638




BLK:13,SNR1: 1.1959 ,SNR2: 7.2622




K20240805114635





BLK:13,SNR1: 0.89123 ,SNR2: 2.3910




3C208 2024/08/05 2.81UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20240805114635




No. Good Data





Frequency (Hz)


3C208 2024/08/05 2.81UT FUJI -KISO



T20240805120320





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C216 2024/08/05 3.08UT TOYOKAWA-FUJI





T20240805120320




BLK:13,SNR1: 2.3568 ,SNR2: 8.7216




K20240805120317





BLK:13,SNR1: 0.41476 ,SNR2: 1.4113




3C216 2024/08/05 3.08UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805120317




No.Good Data





Frequency (Hz)


3C216 2024/08/05 3.08UT FUJI -KISO



T20240805121531





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0919-142 2024/08/05 3.29UT TOYOKAWA-FUJI





T20240805121531




BLK: 3,SNR1: 0.52159 ,SNR2: 2.0151




K20240805121528



BLK: 3,SNR1:-0.18563E-01,SNR2: 1.1494





0919-142 2024/08/05 3.29UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240805121528




No.Good Data





Frequency (Hz)


0919-142 2024/08/05 3.29UT FUJI -KISO





T20240805122210




No.Good Data




FUJI





No.Good Data




0926+117 2024/08/05 3.40UT TOYOKAWA-FUJI





T20240805122210




BLK: 4,SNR1: 0.90303 ,SNR2: 4.0613




K20240805122207





BLK: 4,SNR1: 1.6714 ,SNR2: 7.0315




0926+117 2024/08/05 3.40UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805122207




No.Good Data





Frequency (Hz)


0926+117 2024/08/05 3.40UT FUJI -KISO



T20240805122955





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C222 2024/08/05 3.53UT TOYOKAWA-FUJI




T20240805122955




BLK:23,SNR1: 81.304 ,SNR2: 95.977




K20240805122952





BLK:23,SNR1: 0.59940 ,SNR2: 2.0759




3C222 2024/08/05 3.53UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805122952




No.Good Data





Frequency (Hz)


3C222 2024/08/05 3.53UT FUJI -KISO



T20240805123655





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

0941-08 2024/08/05 3.64UT TOYOKAWA-FUJI







T20240805123655




BLK:13,SNR1: 73.093 ,SNR2: 115.97




K20240805123652





BLK:13,SNR1: 0.33310 ,SNR2: 0.67575




0941-08 2024/08/05 3.64UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805123652




No.Good Data





Frequency (Hz)


0941-08 2024/08/05 3.64UT FUJI -KISO



T20240805124517





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C230 2024/08/05 3.78UT TOYOKAWA-FUJI





T20240805124517




BLK:25,SNR1: 0.58316 ,SNR2: 3.2251




K20240805124514





BLK:25,SNR1: 0.24719 ,SNR2: 1.1436




3C230 2024/08/05 3.78UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20240805124514




No. Good Data





Frequency (Hz)


3C230 2024/08/05 3.78UT FUJI -KISO



T20240805125924





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C236 2024/08/05 4.02UT TOYOKAWA-FUJI




T20240805125924




BLK:21,SNR1: 0.72006 ,SNR2: 1.7891




K20240805125921





BLK:21,SNR1: 0.69700 ,SNR2: 2.9764




3C236 2024/08/05 4.02UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805125921




No.Good Data





Frequency (Hz)

3C236 2024/08/05 4.02UT FUJI -KISO






T20240805130734





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1011+110 2024/08/05 4.15UT TOYOKAWA-FUJI




T20240805130734




BLK:11,SNR1: 0.37294 ,SNR2: 1.7877




K20240805130731




BLK:11,SNR1: 0.52938 ,SNR2: 2.1702




1011+110 2024/08/05 4.15UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805130731




No.Good Data





Frequency (Hz)


1011+110 2024/08/05 4.15UT FUJI -KISO



T20240805131515





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C241 2024/08/05 4.28UT TOYOKAWA-FUJI





T20240805131515




BLK:25,SNR1: 4.5497 ,SNR2: 4.5712




K20240805131512





BLK:25,SNR1: 0.64799 ,SNR2: 2.7723




3C241 2024/08/05 4.28UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805131512




No.Good Data





Frequency (Hz)


3C241 2024/08/05 4.28UT FUJI -KISO



T20240805132644





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1031-11 2024/08/05 4.47UT TOYOKAWA-FUJI





T20240805132644




BLK:14,SNR1:-0.31153E-01,SNR2: 0.58813




K20240805132641



BLK:14,SNR1: 3.8416 ,SNR2: 15.900





1031-11 2024/08/05 4.47UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240805132641




No.Good Data





Frequency (Hz)


1031-11 2024/08/05 4.47UT FUJI -KISO



T20240805133118





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1035-058 2024/08/05 4.55UT TOYOKAWA-FUJI





T20240805133118




BLK:17,SNR1: 0.72667 ,SNR2: 4.7598




K20240805133115





BLK:17,SNR1: 0.28695 ,SNR2: 2.2836




1035-058 2024/08/05 4.55UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805133115




No.Good Data





Frequency (Hz)


1035-058 2024/08/05 4.55UT FUJI -KISO



T20240805134030





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1044-008 2024/08/05 4.70UT TOYOKAWA-FUJI




T20240805134030




BLK:15,SNR1: 0.19857 ,SNR2: 1.1886




K20240805134027





BLK:15,SNR1: 0.17790 ,SNR2: 0.61386




1044-008 2024/08/05 4.70UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805134027




No.Good Data





Frequency (Hz)


1044-008 2024/08/05 4.70UT FUJI -KISO



T20240805135135





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

1055+01 2024/08/05 4.89UT TOYOKAWA-FUJI








T20240805135135




BLK:16,SNR1: 0.66363 ,SNR2: 1.8187




K20240805135132





BLK:16,SNR1: 1.5485 ,SNR2: 7.3902




1055+01 2024/08/05 4.89UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805135132




No.Good Data





Frequency (Hz)


1055+01 2024/08/05 4.89UT FUJI -KISO



T20240805140252





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1107+109 2024/08/05 5.08UT TOYOKAWA-FUJI





T20240805140252




BLK:25,SNR1: 0.42443E-01,SNR2: 0.52131




K20240805140249




BLK:25,SNR1: 0.63635 ,SNR2: 2.5347




1107+109 2024/08/05 5.08UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20240805140249




No.Good Data





Frequency (Hz)


1107+109 2024/08/05 5.08UT FUJI -KISO



T20240805141230





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C255 2024/08/05 5.24UT TOYOKAWA-FUJI



T20240805141230





BLK:23,SNR1:-0.26479E-01,SNR2: 2.2948





3C255 2024/08/05 5.24UT TOYOKAWA-KISO



K20240805141227




BLK:23,SNR1: 0.61005 ,SNR2: 2.9343



FUJI




No.Good Data




Frequency (Hz)

K20240805141227




No.Good Data





Frequency (Hz)

3C255 2024/08/05 5.24UT FUJI -KISO






T20240805142307





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1127-14 2024/08/05 5.41UT TOYOKAWA-FUJI




T20240805142307




BLK:27,SNR1: 73.147 ,SNR2: 97.692




K20240805142304





BLK:27,SNR1: 0.20825 ,SNR2: 2.6140




1127-14 2024/08/05 5.41UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805142304




No.Good Data





Frequency (Hz)


1127-14 2024/08/05 5.41UT FUJI -KISO



T20240805143628





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C263.1 2024/08/05 5.64UT TOYOKAWA-FUJI





T20240805143628




BLK:20,SNR1: 0.10332 ,SNR2: 1.3514




K20240805143625





BLK:20,SNR1: 1.9633 ,SNR2: 6.1757




3C263.1 2024/08/05 5.64UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805143625




No.Good Data




Frequency (Hz)


3C263.1 2024/08/05 5.64UT FUJI -KISO



T20240805144255





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C267 2024/08/05 5.74UT TOYOKAWA-FUJI





T20240805144255




BLK:27,SNR1: 0.65891 ,SNR2: 2.0009




K20240805144252



BLK:27,SNR1: 3.8416 ,SNR2: 10.637





3C267 2024/08/05 5.74UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240805144252




No.Good Data






Frequency (Hz)




3C267 2024/08/05 5.74UT FUJI -KISO




T20240805150842




FUJI




1213-17 2024/08/05 6.17UT TOYOKAWA-FUJI





T20240805150842




BLK:11,SNR1: 5.6339 ,SNR2: 10.425




K20240805150839





BLK:11,SNR1: 0.88915 ,SNR2: 5.0571




1213-17 2024/08/05 6.17UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805150839




No.Good Data





Frequency (Hz)


1213-17 2024/08/05 6.17UT FUJI -KISO



T20240805152200





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C273 2024/08/05 6.39UT TOYOKAWA-FUJI





T20240805152200




BLK:22,SNR1: 16.358 ,SNR2: 33.328




K20240805152157





BLK:22,SNR1: 11.677 ,SNR2: 11.176




3C273 2024/08/05 6.39UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805152157




No.Good Data




Frequency (Hz)


3C273 2024/08/05 6.39UT FUJI -KISO



T20240805153510





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

3C275 2024/08/05 6.61UT TOYOKAWA-FUJI








T20240805153510




BLK: 9,SNR1: 5.1500 ,SNR2: 13.302




K20240805153507





BLK: 9,SNR1: 1.3807 ,SNR2: 1.3146




3C275 2024/08/05 6.61UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805153507




No.Good Data






Frequency (Hz)




3C275 2024/08/05 6.61UT FUJI -KISO




T20240805154115





FUJI




1245-19 2024/08/05 6.72UT TOYOKAWA-FUJI



T20240805154115





BLK:10,SNR1: 0.10639 ,SNR2: 2.1517




Frequency (Hz)

K20240805154112




BLK:10,SNR1: 1.3695 ,SNR2: 2.7629





Frequency (Hz)


1245-19 2024/08/05 6.72UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805154112




No.Good Data




Frequency (Hz)


1245-19 2024/08/05 6.72UT FUJI -KISO



T20240805154859





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C279 2024/08/05 6.84UT TOYOKAWA-FUJI





T20240805154859




BLK:22,SNR1: 8.2744 ,SNR2: 20.532




K20240805154856





BLK:22,SNR1: 1.9667 ,SNR2: 9.5247




3C279 2024/08/05 6.84UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805154856




No.Good Data






Frequency (Hz)

3C279 2024/08/05 6.84UT FUJI -KISO









T20240805160428





FUJI




3C283 2024/08/05 7.10UT TOYOKAWA-FUJI





T20240805160428




BLK:11,SNR1: 97.269 ,SNR2: 132.53




K20240805160425





BLK:11,SNR1: 1.0024 ,SNR2: 6.8581




3C283 2024/08/05 7.10UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805160425




No.Good Data






Frequency (Hz)




3C283 2024/08/05 7.10UT FUJI -KISO




T20240805161853





FUJI




1323+32 2024/08/05 7.34UT TOYOKAWA-FUJI



T20240805161853





BLK:10,SNR1: 0.12199 ,SNR2: 1.3318




Frequency (Hz)

K20240805161850




BLK:10,SNR1: 0.69197 ,SNR2: 2.9715





Frequency (Hz)


1323+32 2024/08/05 7.34UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805161850




No.Good Data






Frequency (Hz)




1323+32 2024/08/05 7.34UT FUJI -KISO




T20240805162343





FUJI




3C286 2024/08/05 7.42UT TOYOKAWA-FUJI



T20240805162343





BLK:33,SNR1: 2.7607 ,SNR2: 12.947




Frequency (Hz)

K20240805162341




BLK:33,SNR1: 7.0709 ,SNR2: 17.769






Frequency (Hz)

3C286 2024/08/05 7.42UT TOYOKAWA-KISO









FUJI





K20240805162341




3C286 2024/08/05 7.42UT FUJI -KISO



T20240805164010





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1345+12 2024/08/05 7.70UT TOYOKAWA-FUJI



T20240805164010





BLK:11,SNR1: 10.124 ,SNR2: 19.530




Frequency (Hz)

K20240805164007




BLK:11,SNR1: 0.24008 ,SNR2: 0.95978






Frequency (Hz)




1345+12 2024/08/05 7.70UT TOYOKAWA-KISO




FUJI





K20240805164007




1345+12 2024/08/05 7.70UT FUJI -KISO



T20240805165031





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1355+01 2024/08/05 7.87UT TOYOKAWA-FUJI





T20240805165031




BLK: 8,SNR1: 0.97496E-01,SNR2: 0.51938




K20240805165028






BLK: 8,SNR1: 0.23048 ,SNR2: 1.6961






1355+01 2024/08/05 7.87UT TOYOKAWA-KISO




FUJI






K20240805165028






1355+01 2024/08/05 7.87UT FUJI -KISO




T20240805171142



FUJI




3C298 2024/08/05 8.22UT TOYOKAWA-FUJI








T20240805171142




BLK:16,SNR1: 0.34057 ,SNR2: 3.0350




K20240805171139




BLK:16,SNR1: 0.66192 ,SNR2: 2.4651




3C298 2024/08/05 8.22UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240805171139



No.Good Data



Frequency (Hz)

3C298 2024/08/05 8.22UT FUJI -KISO

