




T20240807062315





BLK: 8,SNR1: 0.18890 ,SNR2: 1.6971




Frequency (Hz)

F20240807062315




BLK: 8,SNR1: 0.62130 ,SNR2: 3.7227





Frequency (Hz)


0333+32 2024/08/06 21.42UT TOYOKAWA-FUJI



T20240807062315





BLK:11,SNR1: 0.11736 ,SNR2: 1.7109




Frequency (Hz)

K20240807062312




BLK:11,SNR1: 0.54743 ,SNR2: 2.2770




Frequency (Hz)


0333+32 2024/08/06 21.42UT TOYOKAWA-KISO



F20240807062315





BLK:14,SNR1: 0.35080 ,SNR2: 2.6150




Frequency (Hz)

K20240807062312




BLK:14,SNR1: 0.88433 ,SNR2: 3.2613




Frequency (Hz)


0333+32 2024/08/06 21.42UT FUJI -KISO



T20240807063617





BLK:17,SNR1: 0.70033 ,SNR2: 4.5599




Frequency (Hz)

F20240807063617




BLK:17,SNR1: 3.8477 ,SNR2: 9.2929





Frequency (Hz)


0347+05 2024/08/06 21.63UT TOYOKAWA-FUJI



T20240807063617





BLK:13,SNR1: 1.2887 ,SNR2: 4.5165




Frequency (Hz)

K20240807063615




BLK:13,SNR1: 3.5503 ,SNR2: 11.777





Frequency (Hz)


0347+05 2024/08/06 21.63UT TOYOKAWA-KISO



F20240807063617





BLK:16,SNR1: 2.3984 ,SNR2: 7.9481




Frequency (Hz)

K20240807063615




BLK:16,SNR1: 5.2923 ,SNR2: 9.7571





Frequency (Hz)


0347+05 2024/08/06 21.63UT FUJI -KISO



T20240807070102





BLK:31,SNR1: 7.6201 ,SNR2: 19.036




Frequency (Hz)

F20240807070102




BLK:31,SNR1: 6.3328 ,SNR2: 15.898





Frequency (Hz)


0411+05 2024/08/06 22.05UT TOYOKAWA-FUJI



T20240807070102





BLK:21,SNR1: 6.2262 ,SNR2: 15.389




Frequency (Hz)

K20240807070100




BLK:21,SNR1: 10.774 ,SNR2: 24.926





Frequency (Hz)

0411+05 2024/08/06 22.05UT TOYOKAWA-KISO






F20240807070102





BLK:19,SNR1: 11.732 ,SNR2: 20.723




Frequency (Hz)

K20240807070100




BLK:19,SNR1: 9.5162 ,SNR2: 21.991





Frequency (Hz)


0411+05 2024/08/06 22.05UT FUJI -KISO



T20240807070756





BLK: 8,SNR1: 0.38150 ,SNR2: 2.4510




Frequency (Hz)

F20240807070756




BLK: 8,SNR1: 0.23022 ,SNR2: 3.4524





Frequency (Hz)


0418+236 2024/08/06 22.16UT TOYOKAWA-FUJI



T20240807070756





BLK:16,SNR1: 0.59517 ,SNR2: 3.7515




Frequency (Hz)

K20240807070754




BLK:16,SNR1: 77.390 ,SNR2: 88.757





Frequency (Hz)


0418+236 2024/08/06 22.16UT TOYOKAWA-KISO



F20240807070756





BLK:16,SNR1: 0.54004 ,SNR2: 2.4506




Frequency (Hz)

K20240807070754




BLK:16,SNR1: 79.148 ,SNR2: 76.150




Frequency (Hz)


0418+236 2024/08/06 22.16UT FUJI -KISO



T20240807071923




BLK: 5,SNR1: 0.12716 ,SNR2: 1.0791




Frequency (Hz)

F20240807071923




BLK: 5,SNR1: 0.41886E-01,SNR2: 0.72565





Frequency (Hz)


3C119 2024/08/06 22.35UT TOYOKAWA-FUJI



T20240807071923





BLK: 7,SNR1: 0.17680E-01,SNR2: 1.5775




Frequency (Hz)

K20240807071921




BLK: 7,SNR1: 77.081 ,SNR2: 72.445





Frequency (Hz)


3C119 2024/08/06 22.35UT TOYOKAWA-KISO





F20240807071923




BLK: 8,SNR1: 0.68492 ,SNR2: 2.5478




K20240807071921





BLK: 8,SNR1: 75.096 ,SNR2: 71.574




3C119 2024/08/06 22.35UT FUJI -KISO



T20240807080731





BLK:26,SNR1: 5.1926 ,SNR2: 12.446




Frequency (Hz)

3C138 2024/08/06 23.15UT TOYOKAWA-FUJI


F20240807080731



BLK:26,SNR1: 4.3511 ,SNR2: 10.839





Frequency (Hz)






T20240807080731





BLK:22,SNR1: 5.3089 ,SNR2: 12.840




Frequency (Hz)

K20240807080728




BLK:22,SNR1: 24.268 ,SNR2: 32.906





Frequency (Hz)


3C138 2024/08/06 23.15UT TOYOKAWA-KISO



F20240807080731





BLK:25,SNR1: 4.7681 ,SNR2: 11.984




Frequency (Hz)

3C138 2024/08/06 23.15UT FUJI -KISO


K20240807080728





BLK:25,SNR1: 24.129 ,SNR2: 32.717




Frequency (Hz)



T20240807082104





BLK:13,SNR1: 16.912 ,SNR2: 30.886




Frequency (Hz)

F20240807082104




BLK:13,SNR1: 3.5668 ,SNR2: 12.293





Frequency (Hz)


0531+194 2024/08/06 23.38UT TOYOKAWA-FUJI



T20240807082104





BLK:19,SNR1: 9.8881 ,SNR2: 23.338




Frequency (Hz)

K20240807082101




BLK:19,SNR1: 21.396 ,SNR2: 38.799





Frequency (Hz)


0531+194 2024/08/06 23.38UT TOYOKAWA-KISO





F20240807082104




BLK: 8,SNR1:-0.42733E-02,SNR2: 2.0402




K20240807082101





BLK: 8,SNR1: 5.7275 ,SNR2: 19.633




0531+194 2024/08/06 23.38UT FUJI -KISO



T20240807082923





BLK:24,SNR1: 4.7662 ,SNR2: 12.891




Frequency (Hz)

3C147 2024/08/06 23.52UT TOYOKAWA-FUJI


F20240807082923





BLK:24,SNR1: 5.5210 ,SNR2: 15.290




Frequency (Hz)



T20240807082923





BLK:31,SNR1: 4.1351 ,SNR2: 11.183




Frequency (Hz)

3C147 2024/08/06 23.52UT TOYOKAWA-KISO


K20240807082921





BLK:31,SNR1: 8.3701 ,SNR2: 23.372




Frequency (Hz)



F20240807082923





BLK:27,SNR1: 5.3144 ,SNR2: 14.724




Frequency (Hz)

3C147 2024/08/06 23.52UT FUJI -KISO


K20240807082921



BLK:27,SNR1: 8.4424 ,SNR2: 23.575





Frequency (Hz)








T20240807083735




BLK: 3,SNR1: 0.15690E-01,SNR2: 0.24143




F20240807083735




BLK: 3,SNR1: 0.29496E-01,SNR2: 0.59389




0548+16 2024/08/06 23.65UT TOYOKAWA-FUJI



T20240807083735




BLK: 5,SNR1: 0.10044 ,SNR2: 0.34137




Frequency (Hz)

K20240807083732




BLK: 5,SNR1: 6.4916 ,SNR2: 24.780





Frequency (Hz)


0548+16 2024/08/06 23.65UT TOYOKAWA-KISO



F20240807083735





BLK: 2,SNR1:-0.33288 ,SNR2: 0.29180




Frequency (Hz)

K20240807083732




BLK: 2,SNR1: 1.3379 ,SNR2: 7.5815





Frequency (Hz)


0548+16 2024/08/06 23.65UT FUJI -KISO



T20240807084146




BLK:12,SNR1: 3.0034 ,SNR2: 13.307




Frequency (Hz)

F20240807084146




BLK:12,SNR1:-0.63069E-01,SNR2: 1.2933





Frequency (Hz)


0552+12 2024/08/06 23.72UT TOYOKAWA-FUJI



T20240807084146




BLK:21,SNR1: 2.9967 ,SNR2: 13.277




Frequency (Hz)

K20240807084143




BLK:21,SNR1: 1.1413 ,SNR2: 4.7558




Frequency (Hz)


0552+12 2024/08/06 23.72UT TOYOKAWA-KISO



F20240807084146




BLK:13,SNR1:-0.71120E-01,SNR2: 1.6006




Frequency (Hz)

K20240807084143




BLK:13,SNR1: 1.0734 ,SNR2: 4.4321





Frequency (Hz)


0552+12 2024/08/06 23.72UT FUJI -KISO




T20240807084613




BLK: 4,SNR1:-0.78350E-01,SNR2: 0.93944




F20240807084613





BLK: 4,SNR1: 0.39925E-01,SNR2: 2.9844




0556+191 2024/08/06 23.80UT TOYOKAWA-FUJI



T20240807084613





BLK: 5,SNR1: 0.84514 ,SNR2: 2.7395




Frequency (Hz)

K20240807084610




BLK: 5,SNR1: 0.25230 ,SNR2: 1.9672




Frequency (Hz)

0556+191 2024/08/06 23.80UT TOYOKAWA-KISO







F20240807084613




BLK: 4,SNR1: 0.11130E-01,SNR2: 0.89083




K20240807084610





BLK: 4,SNR1: 4.9512 ,SNR2: 19.560




0556+191 2024/08/06 23.80UT FUJI -KISO



T20240807085045




BLK:11,SNR1: 5.0549 ,SNR2: 12.789





3C152 2024/08/06 23.87UT TOYOKAWA-FUJI



F20240807085045




BLK:11,SNR1: 0.10713 ,SNR2: 2.7120




T20240807085045




BLK:12,SNR1: 4.8526 ,SNR2: 12.319




K20240807085042





BLK:12,SNR1: 1.0149 ,SNR2: 4.2224




3C152 2024/08/06 23.87UT TOYOKAWA-KISO



F20240807085045





BLK:15,SNR1: 0.20958 ,SNR2: 3.1783




Frequency (Hz)

3C152 2024/08/06 23.87UT FUJI -KISO


K20240807085042





BLK:15,SNR1: 0.91138 ,SNR2: 3.9111




Frequency (Hz)



T20240807091306





BLK:15,SNR1: 0.34484 ,SNR2: 2.9289




Frequency (Hz)

3C161 2024/08/07 0.25UT TOYOKAWA-FUJI


F20240807091306




BLK:15,SNR1:-0.19530E-01,SNR2: 0.97534




Frequency (Hz)



T20240807091306





BLK:25,SNR1: 0.42551 ,SNR2: 3.2896





3C161 2024/08/07 0.25UT TOYOKAWA-KISO


K20240807091303




BLK:25,SNR1: 0.46886 ,SNR2: 1.7862



F20240807091306





BLK: 8,SNR1: 0.18712 ,SNR2: 1.7204




Frequency (Hz)

3C161 2024/08/07 0.25UT FUJI -KISO


K20240807091303





BLK: 8,SNR1: 0.45590 ,SNR2: 1.4491




Frequency (Hz)



T20240807094039




BLK: 7,SNR1: 3.0701 ,SNR2: 11.562




Frequency (Hz)

F20240807094039




BLK: 7,SNR1:-0.24773 ,SNR2: 0.0000





Frequency (Hz)

0652-130 2024/08/07 0.71UT TOYOKAWA-FUJI






T20240807094039





BLK: 7,SNR1: 4.0108 ,SNR2: 11.286




Frequency (Hz)

0652-130 2024/08/07 0.71UT TOYOKAWA-KISO


K20240807094037





BLK: 7,SNR1: 0.19431 ,SNR2: 0.66004




Frequency (Hz)



F20240807094039





BLK: 1,SNR1:-0.13835 ,SNR2: 0.0000




Frequency (Hz)

K20240807094037




BLK: 1,SNR1:-0.59749E-01,SNR2: 0.27432





Frequency (Hz)


0652-130 2024/08/07 0.71UT FWJI -KISO





T20240807095216




BLK:10,SNR1: 0.89768E-01,SNR2: 1.1042




F20240807095216




BLK:10,SNR1: 0.34845 ,SNR2: 1.7991




0703+138 2024/08/07 0.90UT TOYOKAWA-FUJI



T20240807095216





BLK:14,SNR1: 0.92908E-01,SNR2: 1.2677




Frequency (Hz)

K20240807095213




BLK:14,SNR1: 3.5452 ,SNR2: 14.485





Frequency (Hz)


0703+138 2024/08/07 0.90UT TOYOKAWA-KISO





F20240807095216




BLK:14,SNR1: 0.50392 ,SNR2: 1.5107




K20240807095213





BLK:14,SNR1: 3.8175 ,SNR2: 15.561




0703+138 2024/08/07 0.90UT FUJI -KISO





T20240807100138




BLK: 2,SNR1: 0.24102E-01,SNR2: 0.62740




F20240807100138





BLK: 2,SNR1: 0.16801 ,SNR2: 1.1432




0713-024 2024/08/07 1.06UT TOYOKAWA-FUJI



T20240807100138





BLK: 2,SNR1: 0.39331 ,SNR2: 2.0194





0713-024 2024/08/07 1.06UT TOYOKAWA-KISO


K20240807100135




BLK: 2,SNR1: 3.1729 ,SNR2: 19.232



F20240807100138





BLK: 2,SNR1: 3.4568 ,SNR2: 24.250




Frequency (Hz)

K20240807100135




BLK: 2,SNR1: 0.18132 ,SNR2: 2.8780




Frequency (Hz)

0713-024 2024/08/07 1.06UT FUJI -KISO







T20240807101150




BLK: 8,SNR1: 6.8755 ,SNR2: 31.921




F20240807101150





BLK: 8,SNR1:-0.31968E-01,SNR2: 1.3063




0723+10 2024/08/07 1.23UT TOYOKAWA-FUJI





T20240807101150




BLK:16,SNR1: 79.267 ,SNR2: 309.56




K20240807101148




BLK:16,SNR1: 0.41007 ,SNR2: 1.7570




0723+10 2024/08/07 1.23UT TOYOKAWA-KISO



F20240807101150




BLK:11,SNR1: 0.29813 ,SNR2: 2.1279




Frequency (Hz)

K20240807101148




BLK:11,SNR1: 1.8559 ,SNR2: 8.5343





Frequency (Hz)


0723+10 2024/08/07 1.23UT FUJI -KISO





T20240807102205




BLK:13,SNR1: 0.18321 ,SNR2: 0.90419




F20240807102205





BLK:13,SNR1: 0.88869E-01,SNR2: 0.85222




0732+33 2024/08/07 1.40UT TOYOKAWA-FUJI



T20240807102205





BLK:13,SNR1: 0.30293 ,SNR2: 1.9028





0732+33 2024/08/07 1.40UT TOYOKAWA-KISO


K20240807102202




BLK:13,SNR1: 0.57482 ,SNR2: 1.9954




F20240807102205




BLK:12,SNR1: 0.39066E-01,SNR2: 1.0793




K20240807102202





BLK:12,SNR1: 0.64905 ,SNR2: 2.3072




0732+33 2024/08/07 1.40UT FUJI -KISO





T20240807103007




BLK:13,SNR1: 77.422 ,SNR2: 133.25




F20240807103007





BLK:13,SNR1: 0.26401 ,SNR2: 3.4386




0741-06 2024/08/07 1.53UT TOYOKAWA-FUJI



T20240807103007





BLK:22,SNR1: 79.279 ,SNR2: 136.45





0741-06 2024/08/07 1.53UT TOYOKAWA-KISO

K20240807103004




BLK:22,SNR1: 0.57069 ,SNR2: 3.4463






F20240807103007





BLK: 4,SNR1: 0.63997 ,SNR2: 2.8559




Frequency (Hz)

K20240807103004




BLK: 4,SNR1: 0.21695 ,SNR2: 0.45618





Frequency (Hz)


0741-06 2024/08/07 1.53UT FUJI -KISO




T20240807103951




BLK: 8,SNR1: 71.347 ,SNR2: 81.840




F20240807103951





BLK: 8,SNR1: 0.21556 ,SNR2: 2.0776




0752-200 2024/08/07 1.69UT TOYOKAWA-FUJI



T20240807103951





BLK: 5,SNR1: 52.290 ,SNR2: 91.606




Frequency (Hz)

K20240807103948




BLK: 5,SNR1: 0.44201 ,SNR2: 4.0268




Frequency (Hz)


0752-200 2024/08/07 1.69UT TOYOKAWA-KISO





F20240807103951




BLK: 1,SNR1: 2.4902 ,SNR2: 6.7675




K20240807103948





BLK: 1,SNR1: 0.10063E-01,SNR2: 0.30055




0752-200 2024/08/07 1.69UT FUJI -KISO





T20240807104726




BLK:23,SNR1: 0.46765 ,SNR2: 4.7960




F20240807104726




BLK:23,SNR1: 4.4517 ,SNR2: 9.9074




3C190 2024/08/07 1.82UT TOYOKAWA-FUJI





T20240807104726




BLK:18,SNR1: 0.56734 ,SNR2: 2.5417




K20240807104723




BLK:18,SNR1: 0.38928E-01,SNR2: 0.96734




3C190 2024/08/07 1.82UT TOYOKAWA-KISO



F20240807104726





BLK:10,SNR1: 12.550 ,SNR2: 23.709





3C190 2024/08/07 1.82UT FUJI -KISO



K20240807104723




BLK:10,SNR1: 0.39408 ,SNR2: 3.6239



T20240807105950




BLK: 6,SNR1: 0.58649 ,SNR2: 7.9707




Frequency (Hz)

3C196 2024/08/07 2.03UT TOYOKAWA-FUJI


F20240807105950



BLK: 6,SNR1: 0.51758E-02,SNR2: 0.80990





Frequency (Hz)






T20240807105950





BLK:14,SNR1: 0.53221 ,SNR2: 8.4275




Frequency (Hz)

3C196 2024/08/07 2.03UT TOYOKAWA-KISO


K20240807105947




BLK:14,SNR1: 2.2079 ,SNR2: 10.820




Frequency (Hz)




F20240807105950




BLK: 6,SNR1: 0.67074 ,SNR2: 1.7464




K20240807105947





BLK: 6,SNR1: 2.1653 ,SNR2: 10.327




3C196 2024/08/07 2.03UT FUJI -KISO



T20240807111100





BLK: 7,SNR1: 0.21093 ,SNR2: 1.3194




Frequency (Hz)

F20240807111100




BLK: 7,SNR1:-0.51294E-01,SNR2: 0.71735





Frequency (Hz)


0821+394 2024/08/07 2.21UT TOYOKAWA-FUJI



T20240807111100





BLK:16,SNR1: 0.16592 ,SNR2: 1.2436




Frequency (Hz)

0821+394 2024/08/07 2.21UT TOYOKAWA-KISO


K20240807111057





BLK:16,SNR1: 1.4170 ,SNR2: 6.1359




Frequency (Hz)





F20240807111100




BLK:10,SNR1:-0.16821 ,SNR2: 0.98053




K20240807111057





BLK:10,SNR1: 0.95494 ,SNR2: 4.4045




0821+394 2024/08/07 2.21UT FUJI -KISO



T20240807112240





BLK:36,SNR1: 149.48 ,SNR2: 187.33




Frequency (Hz)

F20240807112240




BLK:36,SNR1: 9.7697 ,SNR2: 20.706




Frequency (Hz)


0834-19 2024/08/07 2.41UT TOYOKAWA-FUJI



T20240807112240





BLK:37,SNR1: 147.59 ,SNR2: 183.84




0834-19 2024/08/07 2.41UT TOYOKAWA-KISO


K20240807112237




BLK:37,SNR1: 6.6345 ,SNR2: 25.443




Frequency (Hz)



F20240807112240





BLK:35,SNR1: 9.8602 ,SNR2: 21.351





0834-19 2024/08/07 2.41UT FUJI -KISO

K20240807112237





BLK:35,SNR1: 6.6045 ,SNR2: 25.370






T20240807112746




BLK:12,SNR1: 0.28703 ,SNR2: 1.5733




0839-071 2024/08/07 2.49UT TOYOKAWA-FUJI


F20240807112746





BLK:12,SNR1:-0.15238 ,SNR2: 1.7487




Frequency (Hz)



T20240807112746





BLK:16,SNR1: 0.30925 ,SNR2: 1.3538




Frequency (Hz)

0839-071 2024/08/07 2.49UT TOYOKAWA-KISO


K20240807112743




BLK:16,SNR1: 1.1077 ,SNR2: 3.0260




Frequency (Hz)



F20240807112746





BLK:12,SNR1:-0.86148E-03,SNR2: 1.5519





0839-071 2024/08/07 2.49UT FUJI -KISO


K20240807112743




BLK:12,SNR1: 1.1880 ,SNR2: 3.1353




T20240807113847




BLK:39,SNR1: 2256.0 ,SNR2: 2775.6




F20240807113847




BLK:39,SNR1: 1227.6 ,SNR2: 1203.9




3C208 2024/08/07 2.67UT TOYOKAWA-FUJI





T20240807113847




BLK:34,SNR1: 2434.1 ,SNR2: 2976.7




K20240807113844




BLK:34,SNR1: 145.95 ,SNR2: 169.30




3C208 2024/08/07 2.67UT TOYOKAWA-KISO





F20240807113847




BLK:33,SNR1: 1334.8 ,SNR2: 1315.4




K20240807113844




BLK:33,SNR1: 19.319 ,SNR2: 44.302




3C208 2024/08/07 2.67UT FUJI -KISO




T20240807115528




BLK:23,SNR1: 10.178 ,SNR2: 22.481




F20240807115528





BLK:23,SNR1: 8.5012 ,SNR2: 19.251




3C216 2024/08/07 2.95UT TOYOKAWA-FUJI





T20240807115528




BLK:33,SNR1: 10.449 ,SNR2: 23.342




K20240807115525



BLK:33,SNR1: 20.997 ,SNR2: 33.075




3C216 2024/08/07 2.95UT TOYOKAWA-KISO







F20240807115528




BLK:27,SNR1: 7.9746 ,SNR2: 21.068




K20240807115525




BLK:27,SNR1: 19.028 ,SNR2: 35.785




3C216 2024/08/07 2.95UT FUJI -KISO




T20240807120740




BLK:12,SNR1: 6.7946 ,SNR2: 13.369




F20240807120740




BLK:12,SNR1:-0.68988E-01,SNR2: 3.6746




0919-142 2024/08/07 3.16UT TOYOKAWA-FUJI



T20240807120740




BLK:19,SNR1: 7.3567 ,SNR2: 13.964




Frequency (Hz)

K20240807120737




BLK:19,SNR1: 2.8203 ,SNR2: 11.626




Frequency (Hz)


0919-142 2024/08/07 3.16UT TOYOKAWA-KISO




F20240807120740




BLK: 6,SNR1: 33.850 ,SNR2: 32.443




K20240807120737





BLK: 6,SNR1: 0.68747 ,SNR2: 2.5999




0919-142 2024/08/07 3.16UT FUJI -KISO





T20240807121418




BLK:19,SNR1: 4.8998 ,SNR2: 9.7657




F20240807121418





BLK:19,SNR1: 1.1480 ,SNR2: 4.1461




0926+117 2024/08/07 3.27UT TOYOKAWA-FUJI



T20240807121418





BLK:21,SNR1: 4.5696 ,SNR2: 8.9609




Frequency (Hz)

0926+117 2024/08/07 3.27UT TOYOKAWA-KISO


K20240807121415




BLK:21,SNR1: 0.23736 ,SNR2: 1.4712




Frequency (Hz)





F20240807121418




BLK:11,SNR1: 1.0758 ,SNR2: 4.5773




K20240807121415





BLK:11,SNR1: 0.25529 ,SNR2: 1.3187




0926+117 2024/08/07 3.27UT FUJI -KISO





T20240807122203




BLK: 9,SNR1: 1.8299 ,SNR2: 7.1871




F20240807122203



BLK: 9,SNR1: 0.33148 ,SNR2: 1.5037





3C222 2024/08/07 3.40UT TOYOKAWA-FUJI








T20240807122203




BLK:23,SNR1: 13.507 ,SNR2: 20.129




K20240807122200




BLK:23,SNR1: 0.54880 ,SNR2: 1.8702




3C222 2024/08/07 3.40UT TOYOKAWA-KISO





F20240807122203




BLK: 5,SNR1:-0.33342E-01,SNR2: 1.4238




K20240807122200





BLK: 5,SNR1: 1.1603 ,SNR2: 3.1359




3C222 2024/08/07 3.40UT FUJI -KISO




T20240807122903




BLK:12,SNR1: 0.49518 ,SNR2: 2.6568




F20240807122903





BLK:12,SNR1:-0.17736 ,SNR2: 1.8459




0941-08 2024/08/07 3.51UT TOYOKAWA-FUJI




T20240807122903




BLK:16,SNR1: 0.49687 ,SNR2: 2.7242




K20240807122900




BLK:16,SNR1: 0.85358 ,SNR2: 3.7984




0941-08 2024/08/07 3.51UT TOYOKAWA-KISO





F20240807122903




BLK: 9,SNR1:-0.23602 ,SNR2: 1.5703




K20240807122900





BLK: 9,SNR1: 0.12988 ,SNR2: 0.84192




0941-08 2024/08/07 3.51UT FUJI -KISO




T20240807123725




BLK:10,SNR1: 0.79075 ,SNR2: 3.6316




F20240807123725





BLK:10,SNR1: 0.12093 ,SNR2: 1.1930




3C230 2024/08/07 3.65UT TOYOKAWA-FUJI



T20240807123725





BLK:20,SNR1: 1.0063 ,SNR2: 4.3310





3C230 2024/08/07 3.65UT TOYOKAWA-KISO


K20240807123722




BLK:20,SNR1: 0.35609 ,SNR2: 2.7142





F20240807123725




BLK:13,SNR1:-0.71398E-01,SNR2: 1.3766




K20240807123722



BLK:13,SNR1: 0.29698 ,SNR2: 0.88795





3C230 2024/08/07 3.65UT FUJI -KISO







T20240807125132




BLK:11,SNR1: 1.3166 ,SNR2: 4.7614




F20240807125132





BLK:11,SNR1: 0.11969 ,SNR2: 2.6005




3C236 2024/08/07 3.89UT TOYOKAWA-FUJI



T20240807125132




BLK:19,SNR1: 0.85526 ,SNR2: 1.4344





3C236 2024/08/07 3.89UT TOYOKAWA-KISO


K20240807125129




BLK:19,SNR1: 0.42537 ,SNR2: 1.2927



F20240807125132




BLK: 7,SNR1: 0.80551 ,SNR2: 2.5534





3C236 2024/08/07 3.89UT FUJI -KISO


K20240807125129




BLK: 7,SNR1: 0.38213 ,SNR2: 1.6463




T20240807125942




BLK:13,SNR1: 4.4575 ,SNR2: 7.2337




F20240807125942




BLK:13,SNR1: 0.54344 ,SNR2: 2.7593




1011+110 2024/08/07 4.02UT TOYOKAWA-FUJI





T20240807125942




BLK:15,SNR1: 6.4528 ,SNR2: 10.285




K20240807125940




BLK:15,SNR1: 3.9867 ,SNR2: 11.794




1011+110 2024/08/07 4.02UT TOYOKAWA-KISO





F20240807125942




BLK:14,SNR1: 0.66131 ,SNR2: 3.4180




K20240807125940





BLK:14,SNR1: 18.398 ,SNR2: 21.239




1011+110 2024/08/07 4.02UT FUJI -KISO



T20240807130723




BLK:12,SNR1: 0.91662 ,SNR2: 3.5594





3C241 2024/08/07 4.15UT TOYOKAWA-FUJI



F20240807130723




BLK:12,SNR1: 0.63663 ,SNR2: 6.8676





T20240807130723




BLK:23,SNR1: 0.67489 ,SNR2: 1.3568




K20240807130720



BLK:23,SNR1: 0.58811 ,SNR2: 2.4819




3C241 2024/08/07 4.15UT TOYOKAWA-KISO






F20240807130723





BLK:10,SNR1: 0.56179 ,SNR2: 6.5819





3C241 2024/08/07 4.15UT FUJI -KISO



K20240807130720




BLK:10,SNR1: 0.32337 ,SNR2: 1.1407




T20240807131852




BLK: 3,SNR1: 6.8815 ,SNR2: 6.6053




F20240807131853





BLK: 3,SNR1: 0.33883E-01,SNR2: 1.4780




1031-11 2024/08/07 4.34UT TOYOKAWA-FUJI





T20240807131852




BLK: 6,SNR1: 0.23460 ,SNR2: 1.1579




K20240807131849





BLK: 6,SNR1: 1.8391 ,SNR2: 6.3305




1031-11 2024/08/07 4.34UT TOYOKAWA-KISO





F20240807131853




BLK: 6,SNR1: 0.12917E-01,SNR2: 1.2934




K20240807131849





BLK: 6,SNR1: 1.6736 ,SNR2: 6.0059




1031-11 2024/08/07 4.34UT FUJI -KISO



T20240807132326





BLK: 3,SNR1: 0.76471 ,SNR2: 8.1594




Frequency (Hz)

F20240807132326




BLK: 3,SNR1: 0.14202E-01,SNR2: 1.3273





Frequency (Hz)


1035-058 2024/08/07 4.42UT TOYOKAWA-FUJI





T20240807132326




BLK: 8,SNR1: 0.58385 ,SNR2: 4.5627




K20240807132323





BLK: 8,SNR1: 0.59738 ,SNR2: 1.9433




1035-058 2024/08/07 4.42UT TOYOKAWA-KISO



F20240807132326





BLK: 5,SNR1: 0.25966 ,SNR2: 2.6219




Frequency (Hz)

K20240807132323




BLK: 5,SNR1: 0.38066 ,SNR2: 2.0817





Frequency (Hz)


1035-058 2024/08/07 4.42UT FUJI -KISO




T20240807133238




BLK: 5,SNR1: 0.76747 ,SNR2: 6.6699




F20240807133238



BLK: 5,SNR1:-0.10163 ,SNR2: 1.1810





1044-008 2024/08/07 4.57UT TOYOKAWA-FUJI







T20240807133238




BLK:11,SNR1: 0.69365 ,SNR2: 4.1070




K20240807133235




BLK:11,SNR1: 0.88664 ,SNR2: 3.3902




1044-008 2024/08/07 4.57UT TOYOKAWA-KISO




F20240807133238




BLK: 7,SNR1:-0.55752E-01,SNR2: 1.2101




K20240807133235





BLK: 7,SNR1: 1.1156 ,SNR2: 4.4082




1044-008 2024/08/07 4.57UT FUJI -KISO





T20240807134343




BLK: 6,SNR1: 0.35950 ,SNR2: 2.4338




F20240807134343





BLK: 6,SNR1:-0.13049 ,SNR2: 1.5350




1055+01 2024/08/07 4.76UT TOYOKAWA-FUJI





T20240807134343




BLK:13,SNR1: 3.9302 ,SNR2: 16.405




K20240807134341




BLK:13,SNR1: 0.37765 ,SNR2: 1.4764




1055+01 2024/08/07 4.76UT TOYOKAWA-KISO



F20240807134343





BLK: 5,SNR1:-0.21188 ,SNR2: 0.37204E-01





1055+01 2024/08/07 4.76UT FUJI -KISO



K20240807134341




BLK: 5,SNR1: 0.70473 ,SNR2: 2.9043




T20240807135500




BLK:23,SNR1: 4.3450 ,SNR2: 11.893




F20240807135500





BLK:23,SNR1: 0.90647 ,SNR2: 2.1946




1107+109 2024/08/07 4.94UT TOYOKAWA-FUJI





T20240807135500




BLK:30,SNR1: 4.2218 ,SNR2: 11.553




K20240807135457




BLK:30,SNR1: 7.0951 ,SNR2: 20.234




1107+109 2024/08/07 4.94UT TOYOKAWA-KISO





F20240807135500




BLK:25,SNR1: 0.85877 ,SNR2: 2.0683




K20240807135457



BLK:25,SNR1: 7.9106 ,SNR2: 22.477





1107+109 2024/08/07 4.94UT FUJI -KISO






T20240807140438




BLK:14,SNR1: 2.2535 ,SNR2: 10.500





3C255 2024/08/07 5.11UT TOYOKAWA-FUJI



F20240807140438




BLK:14,SNR1: 4.2803 ,SNR2: 11.196



T20240807140438





BLK:16,SNR1: 2.2395 ,SNR2: 10.449





3C255 2024/08/07 5.11UT TOYOKAWA-KISO


K20240807140435




BLK:16,SNR1: 0.63780 ,SNR2: 3.2164





F20240807140438




BLK:12,SNR1: 3.0832 ,SNR2: 7.3299




K20240807140435




BLK:12,SNR1: 0.73037 ,SNR2: 2.8872




3C255 2024/08/07 5.11UT FUJI -KISO




T20240807141515




BLK:13,SNR1: 2.7599 ,SNR2: 12.371




F20240807141515




BLK:13,SNR1: 0.23229 ,SNR2: 3.2922




1127-14 2024/08/07 5.28UT TOYOKAWA-FUJI




T20240807141515




BLK:25,SNR1: 2.7034 ,SNR2: 12.098




K20240807141512




BLK:25,SNR1: 4.5471 ,SNR2: 9.0677




1127-14 2024/08/07 5.28UT TOYOKAWA-KISO



F20240807141515





BLK:17,SNR1: 0.86014 ,SNR2: 3.2082




Frequency (Hz)

K20240807141512




BLK:17,SNR1: 6.0919 ,SNR2: 12.065





Frequency (Hz)


1127-14 2024/08/07 5.28UT FUJI -KISO



T20240807142836





BLK:22,SNR1: 9.1802 ,SNR2: 23.003





3C263.1 2024/08/07 5.50UT TOYOKAWA-FUJI



F20240807142836




BLK:22,SNR1: 7.9728 ,SNR2: 18.724




T20240807142836




BLK:22,SNR1: 1.7899 ,SNR2: 8.0660




K20240807142833



BLK:22,SNR1: 5.3405 ,SNR2: 13.063




3C263.1 2024/08/07 5.50UT TOYOKAWA-KISO







F20240807142836




BLK:30,SNR1: 7.5955 ,SNR2: 18.031




K20240807142833





BLK:30,SNR1: 7.5686 ,SNR2: 14.663




3C263.1 2024/08/07 5.50UT FUJI -KISO





T20240807143503




BLK: 7,SNR1: 0.62757 ,SNR2: 4.8358




F20240807143503





BLK: 7,SNR1: 1.9654 ,SNR2: 1.8853




3C267 2024/08/07 5.61UT TOYOKAWA-FUJI





T20240807143503




BLK:13,SNR1: 0.26979 ,SNR2: 3.2037




K20240807143500





BLK:13,SNR1: 1.0055 ,SNR2: 3.4601




3C267 2024/08/07 5.61UT TOYOKAWA-KISO





F20240807143503




BLK: 7,SNR1: 1.1290 ,SNR2: 1.5240




K20240807143500





BLK: 7,SNR1: 0.42817 ,SNR2: 1.8839




3C267 2024/08/07 5.61UT FUJI -KISO





T20240807150050




BLK:23,SNR1: 8.5267 ,SNR2: 21.418




F20240807150050





BLK:23,SNR1: 9.7899 ,SNR2: 24.895




1213-17 2024/08/07 6.04UT TOYOKAWA-FUJI





T20240807150050




BLK:35,SNR1: 8.4993 ,SNR2: 21.350




K20240807150047





BLK:35,SNR1: 6.0576 ,SNR2: 14.931




1213-17 2024/08/07 6.04UT TOYOKAWA-KISO





F20240807150050




BLK:32,SNR1: 12.817 ,SNR2: 22.695




K20240807150047





BLK:32,SNR1: 10.006 ,SNR2: 22.776




1213-17 2024/08/07 6.04UT FUJI -KISO



T20240807151408





BLK:33,SNR1: 9.8355 ,SNR2: 24.545




Frequency (Hz)

F20240807151408




BLK:33,SNR1: 4.2936 ,SNR2: 13.582





Frequency (Hz)

3C273 2024/08/07 6.26UT TOYOKAWA-FUJI








T20240807151408




BLK:34,SNR1: 2.9435 ,SNR2: 13.951




K20240807151405




BLK:34,SNR1: 8.3192 ,SNR2: 21.022




3C273 2024/08/07 6.26UT TOYOKAWA-KISO





F20240807151408




BLK:35,SNR1: 4.8077 ,SNR2: 15.848




K20240807151405





BLK:35,SNR1: 8.4440 ,SNR2: 21.338




3C273 2024/08/07 6.26UT FUJI -KISO



T20240807152719





BLK:11,SNR1: 0.50418 ,SNR2: 2.5577




Frequency (Hz)

F20240807152719




BLK:11,SNR1: 8.5442 ,SNR2: 8.1922





Frequency (Hz)


3C275 2024/08/07 6.48UT TOYOKAWA-FUJI





T20240807152719




BLK:15,SNR1: 1.1586 ,SNR2: 3.0740




K20240807152716





BLK:15,SNR1: 5.4816 ,SNR2: 13.844




3C275 2024/08/07 6.48UT TOYOKAWA-KISO





F20240807152719




BLK:15,SNR1: 8.4183 ,SNR2: 8.0721




K20240807152716





BLK:15,SNR1: 6.0438 ,SNR2: 15.098




3C275 2024/08/07 6.48UT FUJI -KISO



T20240807153324





BLK:13,SNR1: 0.20052 ,SNR2: 2.0143




Frequency (Hz)

F20240807153324




BLK:13,SNR1: 0.58409 ,SNR2: 1.0546





Frequency (Hz)


1245-19 2024/08/07 6.58UT TOYOKAWA-FUJI




T20240807153324




BLK:12,SNR1: 0.64218 ,SNR2: 5.4086




K20240807153321





BLK:12,SNR1: 2.3805 ,SNR2: 8.3581




1245-19 2024/08/07 6.58UT TOYOKAWA-KISO




F20240807153324




BLK:13,SNR1: 0.74011 ,SNR2: 1.3860




K20240807153321



BLK:13,SNR1: 2.4052 ,SNR2: 8.2613





1245-19 2024/08/07 6.58UT FUJI -KISO






T20240807154107





BLK:11,SNR1: 0.15239 ,SNR2: 0.71023




Frequency (Hz)

F20240807154107






BLK:11,SNR1: 0.47699 ,SNR2: 1.0026




Frequency (Hz)


3C279 2024/08/07 6.71UT TOYOKAWA-FUJI







3C279 2024/08/07 6.71UT TOYOKAWA-KISO







BLK:15,SNR1: 0.69143 ,SNR2: 1.3219





BLK:15,SNR1: 0.79827 ,SNR2: 3.8057




3C279 2024/08/07 6.71UT FUJI -KISO



T20240807155637





BLK: 9,SNR1: 2.9196 ,SNR2: 7.3739




Frequency (Hz)

F20240807155637




BLK: 9,SNR1: 0.26651 ,SNR2: 3.1285




Frequency (Hz)

3C283 2024/08/07 6.97UT TOYOKAWA-FUJI






F20240807155637





BLK:11,SNR1: 2.1954 ,SNR2: 3.3024




Frequency (Hz)

K20240807155634




BLK:11,SNR1: 4.7798 ,SNR2: 12.627





Frequency (Hz)


3C283 2024/08/07 6.97UT FUJI -KISO



T20240807161101





BLK:17,SNR1: 7.6531 ,SNR2: 11.637




Frequency (Hz)

F20240807161102




BLK:17,SNR1: 0.38593E-01,SNR2: 0.92560





Frequency (Hz)


1323+32 2024/08/07 7.21UT TOYOKAWA-FUJI





T20240807161101




BLK:15,SNR1: 0.52322 ,SNR2: 1.8515




K20240807161058



BLK:15,SNR1: 24.269 ,SNR2: 42.963





1323+32 2024/08/07 7.21UT TOYOKAWA-KISO






F20240807161102




BLK:17,SNR1: 1.7778 ,SNR2: 5.2787




Frequency (Hz)

K20240807161058




BLK:17,SNR1: 65.579 ,SNR2: 73.556





Frequency (Hz)


1323+32 2024/08/07 7.21UT FUJI -KISO



T20240807161551





BLK:15,SNR1: 0.57266 ,SNR2: 4.2501




Frequency (Hz)

F20240807161552




BLK:15,SNR1: 0.57952 ,SNR2: 1.6675





Frequency (Hz)


3C286 2024/08/07 7.29UT TOYOKAWA-FUJI



T20240807161551





BLK:15,SNR1: 0.76484 ,SNR2: 5.4936




Frequency (Hz)

K20240807161548




BLK:15,SNR1: 78.607 ,SNR2: 72.867





Frequency (Hz)


3C286 2024/08/07 7.29UT TOYOKAWA-KISO



F20240807161552





BLK: 5,SNR1: 0.26578 ,SNR2: 2.4370




Frequency (Hz)

K20240807161548




BLK: 5,SNR1: 76.864 ,SNR2: 101.99




Frequency (Hz)


3C286 2024/08/07 7.29UT FUJI -KISO



T20240807163219





BLK:18,SNR1: 0.27297 ,SNR2: 1.7735




Frequency (Hz)

F20240807163219




BLK:18,SNR1:-0.30290 ,SNR2: 0.88126





Frequency (Hz)


1345+12 2024/08/07 7.57UT TOYOKAWA-FUJI



T20240807163219





BLK:12,SNR1: 1.5334 ,SNR2: 1.8535




Frequency (Hz)

K20240807163216




BLK:12,SNR1: 77.581 ,SNR2: 76.452




Frequency (Hz)


1345+12 2024/08/07 7.57UT TOYOKAWA-KISO



F20240807163219





BLK:15,SNR1: 0.70837 ,SNR2: 2.6351




Frequency (Hz)

K20240807163216




BLK:15,SNR1: 75.264 ,SNR2: 74.896





Frequency (Hz)


1345+12 2024/08/07 7.57UT FUJI -KISO




T20240807164239




BLK: 7,SNR1: 0.19192 ,SNR2: 0.50551




F20240807164239



BLK: 7,SNR1: 1.2543 ,SNR2: 2.4681





1355+01 2024/08/07 7.74UT TOYOKAWA-FUJI






T20240807164239




BLK:10,SNR1: 0.90912E-01,SNR2: 0.38027




Frequency (Hz)

K20240807164236




BLK:10,SNR1: 5.4472 ,SNR2: 10.572




Frequency (Hz)


1355+01 2024/08/07 7.74UT TOYOKAWA-KISO



F20240807164239




BLK:14,SNR1: 0.41619 ,SNR2: 1.5270




Frequency (Hz)

K20240807164236




BLK:14,SNR1: 5.9673 ,SNR2: 9.3905





Frequency (Hz)


1355+01 2024/08/07 7.74UT FUJI -KISO



T20240807170350





BLK:11,SNR1: 0.18822 ,SNR2: 1.5585




Frequency (Hz)

F20240807170350




BLK:11,SNR1: 0.44183 ,SNR2: 1.2689





Frequency (Hz)


3C298 2024/08/07 8.09UT TOYOKAWA-FUJI



T20240807170350





BLK:12,SNR1: 0.19715 ,SNR2: 0.68413




Frequency (Hz)

K20240807170347




BLK:12,SNR1: 3.1161 ,SNR2: 5.6406




Frequency (Hz)


3C298 2024/08/07 8.09UT TOYOKAWA-KISO



F20240807170350




BLK:17,SNR1: 2.8066 ,SNR2: 3.2778




Frequency (Hz)

K20240807170347



BLK:17,SNR1: 0.57490 ,SNR2: 2.5676



Frequency (Hz)

3C298 2024/08/07 8.09UT FUJI -KISO

