



T20240811060134





BLK:20,SNR1: 4.2760 ,SNR2: 6.0887




Frequency (Hz)

F20240811060134




BLK:20,SNR1: 3.5680 ,SNR2: 11.733




Frequency (Hz)


0326+455 2024/08/10 21.05UT TOYOKAWA-FUJI



T20240811060134





BLK:16,SNR1: 2.6368 ,SNR2: 9.3106




Frequency (Hz)

0326+455 2024/08/10 21.05UT TOYOKAWA-KISO


K20240811060131




BLK:16,SNR1: 7.0114 ,SNR2: 17.561




Frequency (Hz)



F20240811060134





BLK:22,SNR1: 3.2823 ,SNR2: 10.655




Frequency (Hz)

K20240811060131




BLK:22,SNR1: 8.6410 ,SNR2: 15.365





Frequency (Hz)


0326+455 2024/08/10 21.05UT FUJI -KISO





T20240811061110




BLK:29,SNR1: 2.6516 ,SNR2: 12.748




F20240811061110





BLK:29,SNR1: 21.661 ,SNR2: 40.602




0337+319 2024/08/10 21.21UT TOYOKAWA-FUJI



T20240811061110





BLK:32,SNR1: 2.7015 ,SNR2: 12.947





0337+319 2024/08/10 21.21UT TOYOKAWA-KISO



K20240811061107




BLK:32,SNR1: 26.436 ,SNR2: 47.745



F20240811061110





BLK:36,SNR1: 21.302 ,SNR2: 39.928




Frequency (Hz)

0337+319 2024/08/10 21.21UT FUJI -KISO


K20240811061107





BLK:36,SNR1: 26.120 ,SNR2: 47.178




Frequency (Hz)



T20240811062415





BLK: 7,SNR1: 0.14478 ,SNR2: 0.99538




Frequency (Hz)

F20240811062415




BLK: 7,SNR1:-0.14686E-01,SNR2: 2.7837





Frequency (Hz)


0349+382 2024/08/10 21.43UT TOYOKAWA-FUJI



T20240811062415





BLK: 4,SNR1: 0.12754 ,SNR2: 0.73861




Frequency (Hz)

K20240811062412




BLK: 4,SNR1: 0.89956 ,SNR2: 5.9104




Frequency (Hz)

0349+382 2024/08/10 21.43UT TOYOKAWA-KISO








F20240811062415




BLK: 3,SNR1: 0.40567E-01,SNR2: 0.34345




K20240811062412







BLK: 3,SNR1: 0.96090 ,SNR2: 3.9226




0349+382 2024/08/10 21.43UT FUJI -KISO








0411+05 2024/08/10 21.78UT TOYOKAWA-FUJI



T20240811064518





BLK:23,SNR1: 1.2516 ,SNR2: 6.7210




Frequency (Hz)

K20240811064515




BLK:23,SNR1: 3.7549 ,SNR2: 15.785





Frequency (Hz)


0411+05 2024/08/10 21.78UT TOYOKAWA-KISO



F20240811064518





BLK:26,SNR1: 6.0031 ,SNR2: 13.394




Frequency (Hz)

K20240811064515




BLK:26,SNR1: 3.5532 ,SNR2: 15.253





Frequency (Hz)


0411+05 2024/08/10 21.78UT FUJI -KISO



T20240811065212





BLK:11,SNR1: 0.55179 ,SNR2: 2.5315




Frequency (Hz)

F20240811065212




BLK:11,SNR1: 2.1062 ,SNR2: 7.3161




Frequency (Hz)


0418+236 2024/08/10 21.90UT TOYOKAWA-FUJI



T20240811065212




BLK: 9,SNR1: 2.1459 ,SNR2: 9.4082




Frequency (Hz)

K20240811065209




BLK: 9,SNR1: 32.382 ,SNR2: 41.886




Frequency (Hz)


0418+236 2024/08/10 21.90UT TOYOKAWA-KISO



F20240811065212





BLK:12,SNR1: 0.83443 ,SNR2: 4.2418




Frequency (Hz)

K20240811065209




BLK:12,SNR1: 8.8544 ,SNR2: 17.015





Frequency (Hz)


0418+236 2024/08/10 21.90UT FUJI -KISO



T20240811070340





BLK:11,SNR1: 0.45314 ,SNR2: 2.0632




Frequency (Hz)

F20240811070340




BLK:11,SNR1: 1.3555 ,SNR2: 4.1493





Frequency (Hz)

3C119 2024/08/10 22.09UT TOYOKAWA-FUJI






T20240811070340





BLK:13,SNR1: 0.68277 ,SNR2: 2.8120




Frequency (Hz)

K20240811070337




BLK:13,SNR1: 1.5165 ,SNR2: 3.0241




Frequency (Hz)


3C119 2024/08/10 22.09UT TOYOKAWA-KISO



F20240811070340





BLK:13,SNR1: 1.1066 ,SNR2: 2.7229




Frequency (Hz)

K20240811070337




BLK:13,SNR1: 1.8263 ,SNR2: 3.6010





Frequency (Hz)


3C119 2024/08/10 22.09UT FUJI -KISO



T20240811075147





BLK:12,SNR1: 0.57279 ,SNR2: 2.1591




Frequency (Hz)

3C138 2024/08/10 22.89UT TOYOKAWA-FUJI


F20240811075147





BLK:12,SNR1: 0.18804 ,SNR2: 1.3585




Frequency (Hz)



T20240811075147





BLK:16,SNR1: 0.30654 ,SNR2: 2.3360




Frequency (Hz)

K20240811075144




BLK:16,SNR1: 12.793 ,SNR2: 19.229





Frequency (Hz)


3C138 2024/08/10 22.89UT TOYOKAWA-KISO



F20240811075147





BLK: 3,SNR1: 0.99089E-01,SNR2: 1.2989




Frequency (Hz)

3C138 2024/08/10 22.89UT FUJI -KISO


K20240811075144





BLK: 3,SNR1: 148.22 ,SNR2: 204.73




Frequency (Hz)



T20240811080520





BLK:15,SNR1: 1.6458 ,SNR2: 5.6290




Frequency (Hz)

F20240811080520




BLK:15,SNR1: 0.65859 ,SNR2: 6.9668





Frequency (Hz)


0531+194 2024/08/10 23.12UT TOYOKAWA-FUJI



T20240811080520





BLK:22,SNR1: 1.2018 ,SNR2: 6.7501




Frequency (Hz)

K20240811080517




BLK:22,SNR1: 10.393 ,SNR2: 31.091





Frequency (Hz)


0531+194 2024/08/10 23.12UT TOYOKAWA-KISO



F20240811080520





BLK:22,SNR1: 0.38191 ,SNR2: 4.8488




Frequency (Hz)

K20240811080517




BLK:22,SNR1: 9.1770 ,SNR2: 27.386





Frequency (Hz)

0531+194 2024/08/10 23.12UT FUJI -KISO






T20240811081340





BLK:16,SNR1: 9.5124 ,SNR2: 32.039




Frequency (Hz)

3C147 2024/08/10 23.26UT TOYOKAWA-FUJI


F20240811081340





BLK:16,SNR1:-0.10823 ,SNR2: 0.96508




Frequency (Hz)



T20240811081340





BLK:25,SNR1: 9.4039 ,SNR2: 32.340




Frequency (Hz)

K20240811081337




BLK:25,SNR1: 1.0373 ,SNR2: 3.7936





Frequency (Hz)


3C147 2024/08/10 23.26UT TOYOKAWA-KISO



F20240811081340





BLK:23,SNR1:-0.16249 ,SNR2: 1.1604




Frequency (Hz)

3C147 2024/08/10 23.26UT FUJI -KISO


K20240811081337





BLK:23,SNR1: 1.2359 ,SNR2: 7.0121




Frequency (Hz)



T20240811082151





BLK: 3,SNR1: 0.12933 ,SNR2: 1.3745




Frequency (Hz)

F20240811082151




BLK: 3,SNR1: 0.78953 ,SNR2: 2.3020





Frequency (Hz)


0548+16 2024/08/10 23.39UT TOYOKAWA-FUJI



T20240811082151





BLK: 1,SNR1: 0.53429 ,SNR2: 1.1662




Frequency (Hz)

K20240811082148




BLK: 1,SNR1: 7667.8 ,SNR2: 7377.1




Frequency (Hz)


0548+16 2024/08/10 23.39UT TOYOKAWA-KISO



F20240811082151





BLK: 2,SNR1:-0.11080 ,SNR2: 0.47315




Frequency (Hz)

K20240811082148




BLK: 2,SNR1: 9.7701 ,SNR2: 25.663





Frequency (Hz)


0548+16 2024/08/10 23.39UT FUJI -KISO



T20240811082602





BLK: 8,SNR1: 4.6691 ,SNR2: 12.219




Frequency (Hz)

0552+12 2024/08/10 23.46UT TOYOKAWA-FUJI


F20240811082602





BLK: 8,SNR1: 2.2321 ,SNR2: 8.3407




Frequency (Hz)



T20240811082602





BLK: 3,SNR1: 1.9240 ,SNR2: 12.383




Frequency (Hz)

0552+12 2024/08/10 23.46UT TOYOKAWA-KISO


K20240811082559



BLK: 3,SNR1: 4.7358 ,SNR2: 25.354




Frequency (Hz)






F20240811082602





BLK: 5, SNR1: 1.3212 , SNR2: 7.8955




Frequency (Hz)

K20240811082559




BLK: 5, SNR1: 47.737 , SNR2: 72.380





Frequency (Hz)


0552+12 2024/08/10 23.46UT FUJI -KISO



T20240811083029





BLK: 9,SNR1: 4.5338 ,SNR2: 7.6976




Frequency (Hz)

F20240811083029




BLK: 9,SNR1: 55.564 ,SNR2: 538.51





Frequency (Hz)


0556+191 2024/08/10 23.54UT TOYOKAWA-FUJI



T20240811083029




BLK: 8,SNR1: 3.8111 ,SNR2: 10.142





0556+191 2024/08/10 23.54UT TOYOKAWA-KISO


K20240811083026




BLK: 8,SNR1: 4.8018 ,SNR2: 19.828




F20240811083029




BLK: 9,SNR1: 45.163 ,SNR2: 460.50




K20240811083026





BLK: 9,SNR1: 34.809 ,SNR2: 41.094




0556+191 2024/08/10 23.54UT FUJI -KISO





T20240811083502




BLK: 4,SNR1: 0.76106 ,SNR2: 1.7109




F20240811083502





BLK: 4,SNR1: 5.2170 ,SNR2: 17.102




3C152 2024/08/10 23.61UT TOYOKAWA-FUJI



T20240811083502





BLK:12,SNR1: 0.38238 ,SNR2: 1.6952




Frequency (Hz)

K20240811083459




BLK:12,SNR1: 18.060 ,SNR2: 30.349





Frequency (Hz)


3C152 2024/08/10 23.61UT TOYOKAWA-KISO



F20240811083502





BLK: 7,SNR1: 1.2255 ,SNR2: 6.9826




Frequency (Hz)

3C152 2024/08/10 23.61UT FUJI -KISO


K20240811083459




BLK: 7,SNR1: 18.740 ,SNR2: 31.009




Frequency (Hz)




T20240811085208




BLK: 2,SNR1: 0.69923E-01,SNR2: 0.39002




F20240811085208



BLK: 2,SNR1: 0.47909 ,SNR2: 3.2843





3C158 2024/08/10 23.90UT TOYOKAWA-FUJI






T20240811085208





BLK: 1,SNR1:-0.73935E-01,SNR2: 0.79633E-01





3C158 2024/08/10 23.90UT TOYOKAWA-KISO



K20240811085205




BLK: 1,SNR1: 13.589 ,SNR2: 42.333



F20240811085208





BLK: 1,SNR1:-0.10039 ,SNR2: 0.62539




Frequency (Hz)

3C158 2024/08/10 23.90UT FUJI -KISO


K20240811085205





BLK: 1,SNR1: 22.207 ,SNR2: 38.044




Frequency (Hz)



T20240811092456





BLK: 1,SNR1: 0.24393 ,SNR2: 0.32632




Frequency (Hz)

F20240811092456




BLK: 1,SNR1: 1.3628 ,SNR2: 2.7886





Frequency (Hz)


0652-130 2024/08/11 0.44UT TOYOKAWA-FUJI




T20240811092456




BLK: 1,SNR1: 0.18635 ,SNR2: 0.66653




K20240811092453





BLK: 1,SNR1: 1.4862 ,SNR2: 7.1420




0652-130 2024/08/11 0.44UT TOYOKAWA-KISO



F20240811092456





BLK: 2,SNR1: 0.32498 ,SNR2: 1.9856




Frequency (Hz)

K20240811092453




BLK: 2,SNR1: 0.27955 ,SNR2: 2.0110





Frequency (Hz)


0652-130 2024/08/11 0.44UT FUJI -KISO





T20240811093632




BLK: 2, SNR1: 0.11579 , SNR2: 0.49454




F20240811093632





BLK: 2, SNR1: 0.22743 , SNR2: 0.86190




0703+138 2024/08/11 0.64UT TOYOKAWA-FUJI



T20240811093632





BLK: 2,SNR1:-0.20390 ,SNR2: 0.25156




Frequency (Hz)

K20240811093629




BLK: 2,SNR1: 0.97361 ,SNR2: 5.8824





Frequency (Hz)


0703+138 2024/08/11 0.64UT TOYOKAWA-KISO





F20240811093632




BLK: 8,SNR1: 0.27967 ,SNR2: 2.4888




K20240811093629



BLK: 8,SNR1: 0.21096 ,SNR2: 2.1285





0703+138 2024/08/11 0.64UT FUJI -KISO






T20240811094555




BLK: 6,SNR1: 0.38239E-01,SNR2: 1.6010




Frequency (Hz)

F20240811094555




BLK: 6,SNR1: 0.80026 ,SNR2: 1.9726




Frequency (Hz)


0713-024 2024/08/11 0.79UT TOYOKAWA-FUJI



T20240811094555





BLK: 4,SNR1: 0.62292E-01,SNR2: 0.86469




Frequency (Hz)

K20240811094552




BLK: 4,SNR1: 1.5345 ,SNR2: 6.0684




Frequency (Hz)


0713-024 2024/08/11 0.79UT TOYOKAWA-KISO





F20240811094555




BLK: 5,SNR1: 0.65077 ,SNR2: 2.4505




K20240811094552




BLK: 5,SNR1: 0.57563 ,SNR2: 2.7983




0713-024 2024/08/11 0.79UT FUJI -KISO




T20240811095607




BLK: 7,SNR1: 0.30319 ,SNR2: 2.5708




F20240811095607




BLK: 7,SNR1: 0.31270 ,SNR2: 1.9565




0723+10 2024/08/11 0.96UT TOYOKAWA-FUJI




T20240811095607




BLK:12,SNR1: 0.26505 ,SNR2: 0.79356




K20240811095604





BLK:12,SNR1: 1.8768 ,SNR2: 5.6207




0723+10 2024/08/11 0.96UT TOYOKAWA-KISO





F20240811095607




BLK:13,SNR1: 0.67761 ,SNR2: 3.4239




K20240811095604





BLK:13,SNR1: 1.8494 ,SNR2: 7.7476




0723+10 2024/08/11 0.96UT FUJI -KISO



T20240811100621




BLK:12,SNR1: 1.4741 ,SNR2: 10.259




Frequency (Hz)

0732+33 2024/08/11 1.13UT TOYOKAWA-FUJI


F20240811100621





BLK:12,SNR1: 2.3674 ,SNR2: 8.3106




Frequency (Hz)



T20240811100621





BLK:19,SNR1: 1.2205 ,SNR2: 8.5231





0732+33 2024/08/11 1.13UT TOYOKAWA-KISO

K20240811100618




BLK:19,SNR1: 2.2712 ,SNR2: 9.0194








F20240811100621




BLK:12,SNR1: 1.5603 ,SNR2: 5.1097




K20240811100618




BLK:12,SNR1: 2.9972 ,SNR2: 13.521




0732+33 2024/08/11 1.13UT FUJI -KISO



T20240811101423




BLK:10,SNR1: 0.81408 ,SNR2: 4.8770





0741-06 2024/08/11 1.27UT TOYOKAWA-FUJI


F20240811101423




BLK:10,SNR1:-0.18564 ,SNR2: 0.56620



T20240811101423





BLK:18,SNR1: 0.79777 ,SNR2: 5.0559





0741-06 2024/08/11 1.27UT TOYOKAWA-KISO



K20240811101420




BLK:18,SNR1: 0.39341 ,SNR2: 0.95364



F20240811101423





BLK: 9,SNR1: 0.63395 ,SNR2: 1.7402




Frequency (Hz)

K20240811101420




BLK: 9,SNR1: 0.34363 ,SNR2: 0.62349




Frequency (Hz)


0741-06 2024/08/11 1.27UT FUJI -KISO



T20240811102408




BLK: 5,SNR1:-0.11088E-01,SNR2: 0.72514





0752-200 2024/08/11 1.43UT TOYOKAWA-FUJI


F20240811102408




BLK: 5,SNR1: 11.995 ,SNR2: 25.253



T20240811102408





BLK: 9,SNR1: 0.10664E-02,SNR2: 1.4219





0752-200 2024/08/11 1.43UT TOYOKAWA-KISO


K20240811102405




BLK: 9,SNR1: 7.4930 ,SNR2: 24.131



F20240811102408





BLK: 9,SNR1: 21.990 ,SNR2: 20.051





0752-200 2024/08/11 1.43UT FUJI -KISO



K20240811102405




BLK: 9,SNR1: 0.34315 ,SNR2: 1.9206





T20240811103142




BLK:16,SNR1: 0.31570 ,SNR2: 1.3831




F20240811103142



BLK:16,SNR1: 0.99029 ,SNR2: 6.0269





3C190 2024/08/11 1.56UT TOYOKAWA-FUJI






T20240811103142





BLK:19,SNR1: 0.31504 ,SNR2: 1.4580




Frequency (Hz)

3C190 2024/08/11 1.56UT TOYOKAWA-KISO


K20240811103139





BLK:19,SNR1: 0.35839 ,SNR2: 1.4304




Frequency (Hz)



F20240811103142





BLK:17,SNR1: 1.5743 ,SNR2: 7.8201




Frequency (Hz)

K20240811103139




BLK:17,SNR1: 0.20459 ,SNR2: 1.1578




Frequency (Hz)


3C190 2024/08/11 1.56UT FUJI -KISO



T20240811104407




BLK:15,SNR1: 2.2014 ,SNR2: 6.7315





3C196 2024/08/11 1.76UT TOYOKAWA-FUJI


F20240811104407




BLK:15,SNR1: 0.42196E-02,SNR2: 1.6681



T20240811104407





BLK:28,SNR1: 1.9746 ,SNR2: 16.910





3C196 2024/08/11 1.76UT TOYOKAWA-KISO


K20240811104404




BLK:28,SNR1: 2.9062 ,SNR2: 13.024




F20240811104407




BLK:12,SNR1:-0.17804E-01,SNR2: 2.0603




K20240811104404





BLK:12,SNR1: 0.12927 ,SNR2: 3.2767




3C196 2024/08/11 1.76UT FUJI -KISO





T20240811105517




BLK:10,SNR1: 0.28043 ,SNR2: 3.6776




F20240811105517




BLK:10,SNR1: 0.56675E-01,SNR2: 3.4092




0821+394 2024/08/11 1.95UT TOYOKAWA-FUJI



T20240811105517





BLK:15,SNR1: 0.35859 ,SNR2: 3.7559





0821+394 2024/08/11 1.95UT TOYOKAWA-KISO


K20240811105514




BLK:15,SNR1: 1.2948 ,SNR2: 3.8412





F20240811105517




BLK: 5,SNR1: 0.44755 ,SNR2: 3.9838




K20240811105514



BLK: 5,SNR1: 0.25907 ,SNR2: 1.7577




0821+394 2024/08/11 1.95UT FUJI -KISO







T20240811110657




BLK: 5,SNR1:-0.50261E-01,SNR2: 0.45646




F20240811110657




BLK: 5,SNR1: 1.0680 ,SNR2: 4.4771




0834-19 2024/08/11 2.14UT TOYOKAWA-FUJI



T20240811110657





BLK: 8,SNR1: 0.22322 ,SNR2: 0.98336




0834-19 2024/08/11 2.14UT TOYOKAWA-KISO


K20240811110655




BLK: 8,SNR1: 0.32590 ,SNR2: 1.8573




Frequency (Hz)




F20240811110657




BLK: 4,SNR1: 0.12003 ,SNR2: 1.9730




K20240811110655





BLK: 4,SNR1: 0.15320 ,SNR2: 0.53058




0834-19 2024/08/11 2.14UT FUJI -KISO




T20240811111202




BLK: 3,SNR1: 0.17186 ,SNR2: 1.2407




F20240811111202





BLK: 3,SNR1: 1.0935 ,SNR2: 2.7254




0839-071 2024/08/11 2.23UT TOYOKAWA-FUJI



T20240811111202





BLK: 2,SNR1: 0.64759E-01,SNR2: 1.1019





0839-071 2024/08/11 2.23UT TOYOKAWA-KISO



K20240811111200




BLK: 2,SNR1: 3.3100 ,SNR2: 11.397





F20240811111202




BLK: 2,SNR1: 0.33120 ,SNR2: 1.3666




K20240811111200




BLK: 2,SNR1: 0.32349 ,SNR2: 1.9710




0839-071 2024/08/11 2.23UT FUJI -KISO



T20240811112303





BLK:13,SNR1: 0.23003 ,SNR2: 2.4990





3C208 2024/08/11 2.41UT TOYOKAWA-FUJI


F20240811112303




BLK:13,SNR1: 22.907 ,SNR2: 20.502





T20240811112303




BLK:14,SNR1: 0.18040 ,SNR2: 1.2882




K20240811112300



BLK:14,SNR1: 4.0812 ,SNR2: 14.144




3C208 2024/08/11 2.41UT TOYOKAWA-KISO






F20240811112303





BLK: 9,SNR1: 57.869 ,SNR2: 51.767





3C208 2024/08/11 2.41UT FUJI -KISO


K20240811112300




BLK: 9,SNR1: 3.3858 ,SNR2: 14.073



T20240811113944




BLK:11,SNR1: 0.43155 ,SNR2: 3.8528





3C216 2024/08/11 2.69UT TOYOKAWA-FUJI


F20240811113944




BLK:11,SNR1: 0.73377 ,SNR2: 3.8250




T20240811113944




BLK:21,SNR1: 0.43839 ,SNR2: 3.4176




K20240811113941




BLK:21,SNR1: 0.31023 ,SNR2: 0.88106




3C216 2024/08/11 2.69UT TOYOKAWA-KISO




F20240811113944




BLK: 9,SNR1: 0.16431 ,SNR2: 2.6347




K20240811113941




BLK: 9,SNR1: 0.51904 ,SNR2: 2.1155




3C216 2024/08/11 2.69UT FUJI -KISO



T20240811115156





BLK:20,SNR1: 4.1430 ,SNR2: 15.467




0919-142 2024/08/11 2.89UT TOYOKAWA-FUJI


F20240811115156




BLK:20,SNR1: 2.4156 ,SNR2: 10.088




Frequency (Hz)



T20240811115156





BLK:27,SNR1: 4.5272 ,SNR2: 16.828





0919-142 2024/08/11 2.89UT TOYOKAWA-KISO



K20240811115154




BLK:27,SNR1: 2.1317 ,SNR2: 9.8059



F20240811115156





BLK:24,SNR1: 6.0755 ,SNR2: 15.426





0919-142 2024/08/11 2.89UT FUJI -KISO



K20240811115154




BLK:24,SNR1: 2.6290 ,SNR2: 5.7266




T20240811115835




BLK:25,SNR1: 1.3796 ,SNR2: 7.1846




F20240811115835



BLK:25,SNR1: 3.6105 ,SNR2: 8.4441




0926+117 2024/08/11 3.00UT TOYOKAWA-FUJI






T20240811115835




BLK:10,SNR1: 3.2140 ,SNR2: 7.6178





0926+117 2024/08/11 3.00UT TOYOKAWA-KISO


K20240811115832




BLK:10,SNR1: 1.3157 ,SNR2: 4.9245



F20240811115835




BLK:14,SNR1: 1.8239 ,SNR2: 10.597





0926+117 2024/08/11 3.00UT FUJI -KISO


K20240811115832




BLK:14,SNR1: 2.4381 ,SNR2: 8.5184



T20240811120619




BLK:13,SNR1: 1.3030 ,SNR2: 4.4902





3C222 2024/08/11 3.13UT TOYOKAWA-FUJI


F20240811120619




BLK:13,SNR1: 3.2275 ,SNR2: 16.273





T20240811120619




BLK:23,SNR1: 1.3119 ,SNR2: 5.2758




K20240811120616





BLK:23,SNR1: 0.65792 ,SNR2: 2.5348




3C222 2024/08/11 3.13UT TOYOKAWA-KISO



F20240811120619





BLK:12,SNR1: 0.28751 ,SNR2: 4.8678




Frequency (Hz)

3C222 2024/08/11 3.13UT FUJI -KISO


K20240811120616





BLK:12,SNR1: 0.54754 ,SNR2: 1.7345




Frequency (Hz)




T20240811121320




BLK:12,SNR1: 0.93846 ,SNR2: 4.3674




F20240811121320





BLK:12,SNR1: 0.71997 ,SNR2: 3.0093




0941-08 2024/08/11 3.25UT TOYOKAWA-FUJI




T20240811121320




BLK:19,SNR1: 3.1674 ,SNR2: 9.9767




K20240811121317




BLK:19,SNR1: 3.0570 ,SNR2: 10.064




0941-08 2024/08/11 3.25UT TOYOKAWA-KISO




F20240811121320




BLK:16,SNR1: 9.6330 ,SNR2: 20.041




K20240811121317



BLK:16,SNR1: 5.0670 ,SNR2: 21.533





0941-08 2024/08/11 3.25UT FUJI -KISO






T20240811122141





BLK:17,SNR1: 3.6328 ,SNR2: 13.025





3C230 2024/08/11 3.39UT TOYOKAWA-FUJI



F20240811122141




BLK:17,SNR1: 0.56644E-01,SNR2: 1.5326



T20240811122141





BLK:24,SNR1: 3.7121 ,SNR2: 8.9321





3C230 2024/08/11 3.39UT TOYOKAWA-KISO


K20240811122138




BLK:24,SNR1: 4.4873 ,SNR2: 17.905




F20240811122141




BLK:18,SNR1: 0.51575E-01,SNR2: 1.4025




K20240811122138





BLK:18,SNR1: 5.5271 ,SNR2: 22.464




3C230 2024/08/11 3.39UT FUJI -KISO




T20240811123549




BLK:13,SNR1: 1.5684 ,SNR2: 12.417




F20240811123549




BLK:13,SNR1: 3.9530 ,SNR2: 8.7734




3C236 2024/08/11 3.63UT TOYOKAWA-FUJI





T20240811123549




BLK:17,SNR1: 0.71674 ,SNR2: 3.5658




K20240811123546




BLK:17,SNR1: 0.41508 ,SNR2: 1.0169




3C236 2024/08/11 3.63UT TOYOKAWA-KISO





F20240811123549




BLK:14,SNR1: 2.2491 ,SNR2: 5.7654




K20240811123546




BLK:14,SNR1: 1.0558 ,SNR2: 3.4636




3C236 2024/08/11 3.63UT FUJI -KISO




T20240811124358




BLK:17,SNR1: 2.5547 ,SNR2: 4.9584




F20240811124358




BLK:17,SNR1: 1.2933 ,SNR2: 4.7212




1011+110 2024/08/11 3.76UT TOYOKAWA-FUJI




T20240811124358




BLK:25,SNR1: 2.0951 ,SNR2: 3.8665




K20240811124355



BLK:25,SNR1: 3.9955 ,SNR2: 16.571




1011+110 2024/08/11 3.76UT TOYOKAWA-KISO








F20240811124358




BLK:27,SNR1: 0.72477 ,SNR2: 4.0181




K20240811124355





BLK:27,SNR1: 4.3328 ,SNR2: 17.714




1011+110 2024/08/11 3.76UT FUJI -KISO




T20240811125139




BLK:21,SNR1: 2.9467 ,SNR2: 7.6728




F20240811125139





BLK:21,SNR1: 0.70993 ,SNR2: 2.5415




3C241 2024/08/11 3.89UT TOYOKAWA-FUJI



T20240811125139





BLK:20,SNR1: 3.4324 ,SNR2: 9.0266




Frequency (Hz)

K20240811125136




BLK:20,SNR1: 0.77948 ,SNR2: 3.1579





Frequency (Hz)


3C241 2024/08/11 3.89UT TOYOKAWA-KISO





F20240811125139




BLK:16,SNR1: 1.0007 ,SNR2: 3.3665




K20240811125136





BLK:16,SNR1: 0.97648 ,SNR2: 3.8325




3C241 2024/08/11 3.89UT FUJI -KISO



T20240811130309





BLK:21,SNR1: 3.1046 ,SNR2: 13.677





1031-11 2024/08/11 4.08UT TOYOKAWA-FUJI



F20240811130309




BLK:21,SNR1: 6.5281 ,SNR2: 16.425



T20240811130309





BLK:26,SNR1: 3.1069 ,SNR2: 13.686





1031-11 2024/08/11 4.08UT TOYOKAWA-KISO


K20240811130306




BLK:26,SNR1: 8.4470 ,SNR2: 21.398





F20240811130309




BLK:25,SNR1: 6.6870 ,SNR2: 17.142




K20240811130306





BLK:25,SNR1: 7.5458 ,SNR2: 21.992




1031-11 2024/08/11 4.08UT FUJI -KISO




T20240811130742




BLK:12,SNR1: 28.161 ,SNR2: 33.318




F20240811130742



BLK:12,SNR1: 0.85489 ,SNR2: 8.5771





1035-058 2024/08/11 4.16UT TOYOKAWA-FUJI








T20240811130742




BLK:20,SNR1: 24.830 ,SNR2: 29.378




K20240811130739





BLK:20,SNR1: 14.781 ,SNR2: 32.531




1035-058 2024/08/11 4.16UT TOYOKAWA-KISO





F20240811130742




BLK:19,SNR1: 0.22747 ,SNR2: 4.1638




K20240811130739





BLK:19,SNR1: 14.633 ,SNR2: 32.215




1035-058 2024/08/11 4.16UT FUJI -KISO





T20240811131655




BLK:22,SNR1: 2.9049 ,SNR2: 13.771




F20240811131655





BLK:22,SNR1: 15.433 ,SNR2: 27.211




1044-008 2024/08/11 4.31UT TOYOKAWA-FUJI





T20240811131655




BLK:23,SNR1: 9.0436 ,SNR2: 22.645




K20240811131652





BLK:23,SNR1: 9.3983 ,SNR2: 23.519




1044-008 2024/08/11 4.31UT TOYOKAWA-KISO





F20240811131655




BLK:27,SNR1: 2.8446 ,SNR2: 13.531




K20240811131652





BLK:27,SNR1: 9.4473 ,SNR2: 23.635




1044-008 2024/08/11 4.31UT FUJI -KISO





T20240811132759




BLK:22,SNR1: 8.7712 ,SNR2: 22.016




F20240811132759





BLK:22,SNR1: 7.6849 ,SNR2: 19.345




1055+01 2024/08/11 4.49UT TOYOKAWA-FUJI





T20240811132759




BLK:28,SNR1: 9.0553 ,SNR2: 22.668




K20240811132756





BLK:28,SNR1: 8.4457 ,SNR2: 21.372




1055+01 2024/08/11 4.49UT TOYOKAWA-KISO



F20240811132759





BLK:29,SNR1: 7.3206 ,SNR2: 18.447





1055+01 2024/08/11 4.49UT FUJI -KISO

K20240811132756





BLK:29,SNR1: 8.4453 ,SNR2: 21.370








T20240811133917




BLK:28,SNR1: 9.3001 ,SNR2: 23.272




F20240811133917





BLK:28,SNR1: 8.4856 ,SNR2: 21.307




1107+109 2024/08/11 4.68UT TOYOKAWA-FUJI





T20240811133917




BLK:30,SNR1: 9.2792 ,SNR2: 23.221




K20240811133914





BLK:30,SNR1: 2.8489 ,SNR2: 13.537




1107+109 2024/08/11 4.68UT TOYOKAWA-KISO





F20240811133917




BLK:37,SNR1: 8.5718 ,SNR2: 21.514




K20240811133914





BLK:37,SNR1: 2.8970 ,SNR2: 13.727




1107+109 2024/08/11 4.68UT FUJI -KISO



T20240811134854




BLK:26,SNR1: 6.9482 ,SNR2: 17.766





3C255 2024/08/11 4.84UT TOYOKAWA-FUJI



F20240811134854




BLK:26,SNR1: 18.316 ,SNR2: 21.630





T20240811134854




BLK:29,SNR1: 6.9985 ,SNR2: 17.889




K20240811134851




BLK:29,SNR1: 8.0886 ,SNR2: 20.500




3C255 2024/08/11 4.84UT TOYOKAWA-KISO





F20240811134854




BLK:30,SNR1: 18.922 ,SNR2: 22.345




K20240811134851





BLK:30,SNR1: 8.5122 ,SNR2: 21.332




3C255 2024/08/11 4.84UT FUJI -KISO





T20240811135932




BLK:19,SNR1: 5.0538 ,SNR2: 12.377




F20240811135932





BLK:19,SNR1: 3.5100 ,SNR2: 12.433




1127-14 2024/08/11 5.02UT TOYOKAWA-FUJI





T20240811135932




BLK:28,SNR1: 3.4005 ,SNR2: 6.6843




K20240811135929



BLK:28,SNR1: 7.2231 ,SNR2: 19.044




1127-14 2024/08/11 5.02UT TOYOKAWA-KISO








F20240811135932




BLK:16,SNR1: 4.0270 ,SNR2: 14.156




K20240811135929





BLK:16,SNR1: 7.6061 ,SNR2: 19.996




1127-14 2024/08/11 5.02UT FUJI -KISO





T20240811141252




BLK:20,SNR1: 11.073 ,SNR2: 19.597




F20240811141252





BLK:20,SNR1: 2.2370 ,SNR2: 8.1145




3C263.1 2024/08/11 5.24UT TOYOKAWA-FUJI





T20240811141252




BLK:24,SNR1: 8.2160 ,SNR2: 20.616




K20240811141249




BLK:24,SNR1: 6.7069 ,SNR2: 17.249




3C263.1 2024/08/11 5.24UT TOYOKAWA-KISO




F20240811141252




BLK:22,SNR1: 2.1467 ,SNR2: 7.6088




K20240811141249




BLK:22,SNR1: 6.7919 ,SNR2: 17.327




3C263.1 2024/08/11 5.24UT FUJI -KISO




T20240811141919




BLK: 6,SNR1: 0.29084 ,SNR2: 2.1612




F20240811141920




BLK: 6,SNR1: 0.10480 ,SNR2: 1.2155




3C267 2024/08/11 5.35UT TOYOKAWA-FUJI





T20240811141919




BLK:11,SNR1: 716.12 ,SNR2: 4102.9




K20240811141916




BLK:11,SNR1: 0.91980 ,SNR2: 3.5501




3C267 2024/08/11 5.35UT TOYOKAWA-KISO





F20240811141920




BLK: 4,SNR1: 0.26590 ,SNR2: 2.6543




K20240811141916





BLK: 4,SNR1: 0.61862 ,SNR2: 2.7164




3C267 2024/08/11 5.35UT FUJI -KISO



T20240811144507





BLK:13,SNR1: 1.8393 ,SNR2: 3.6797




Frequency (Hz)

F20240811144507




BLK:13,SNR1: 0.11344 ,SNR2: 2.1220





Frequency (Hz)

1213-17 2024/08/11 5.78UT TOYOKAWA-FUJI






T20240811144507





BLK:21,SNR1: 1.6772 ,SNR2: 6.3944




Frequency (Hz)

K20240811144504




BLK:21,SNR1: 4.2173 ,SNR2: 8.3418





Frequency (Hz)


1213-17 2024/08/11 5.78UT TOYOKAWA-KISO



F20240811144507





BLK:24,SNR1: 0.17960 ,SNR2: 2.4465




Frequency (Hz)

K20240811144504




BLK:24,SNR1: 4.9745 ,SNR2: 9.7809





Frequency (Hz)


1213-17 2024/08/11 5.78UT FUJI -KISO





T20240811145824




BLK:16,SNR1: 6.0364 ,SNR2: 15.217




F20240811145824





BLK:16,SNR1:-0.13772 ,SNR2: 1.2392




3C273 2024/08/11 6.00UT TOYOKAWA-FUJI



T20240811145824




BLK:14,SNR1: 5.6376 ,SNR2: 14.141




Frequency (Hz)

K20240811145821




BLK:14,SNR1: 2.4964 ,SNR2: 9.0214




Frequency (Hz)


3C273 2024/08/11 6.00UT TOYOKAWA-KISO





F20240811145824




BLK:21,SNR1:-0.10073 ,SNR2: 1.3638




K20240811145821





BLK:21,SNR1: 3.3911 ,SNR2: 12.767




3C273 2024/08/11 6.00UT FUJI -KISO



T20240811151135





No.Good Data




Frequency (Hz)

F20240811151135




No.Good Data





Frequency (Hz)


3C275 2024/08/11 6.22UT TOYOKAWA-FUJI



T20240811151135





BLK: 7,SNR1: 0.15264 ,SNR2: 0.89563




Frequency (Hz)

K20240811151132




BLK: 7,SNR1: 1.4387 ,SNR2: 5.8963





Frequency (Hz)


3C275 2024/08/11 6.22UT TOYOKAWA-KISO





F20240811151135




BLK: 4,SNR1:-0.23633 ,SNR2: 2.3861




K20240811151132



BLK: 4,SNR1: 0.42731 ,SNR2: 1.3737





3C275 2024/08/11 6.22UT FUJI -KISO







T20240811151740




BLK: 7,SNR1: 3.1478 ,SNR2: 7.4045




F20240811151740





BLK: 7,SNR1: 0.32701 ,SNR2: 5.9160




1245-19 2024/08/11 6.32UT TOYOKAWA-FUJI




T20240811151740




BLK:11,SNR1: 2.1177 ,SNR2: 5.1846




K20240811151737




BLK:11,SNR1: 2.8104 ,SNR2: 10.123




1245-19 2024/08/11 6.32UT TOYOKAWA-KISO



F20240811151740





BLK:14,SNR1: 0.21735 ,SNR2: 3.1033




Frequency (Hz)

K20240811151737




BLK:14,SNR1: 2.9123 ,SNR2: 10.124




Frequency (Hz)


1245-19 2024/08/11 6.32UT FUJI -KISO



T20240811152524




BLK: 2,SNR1: 0.31619 ,SNR2: 2.3753




Frequency (Hz)

F20240811152524




BLK: 2,SNR1:-0.17321 ,SNR2: 2.0588





Frequency (Hz)


3C279 2024/08/11 6.45UT TOYOKAWA-FUJI



T20240811152524





BLK:13,SNR1: 0.28163 ,SNR2: 1.8189




Frequency (Hz)

K20240811152521




BLK:13,SNR1: 1.4849 ,SNR2: 6.3256




Frequency (Hz)


3C279 2024/08/11 6.45UT TOYOKAWA-KISO



F20240811152524





BLK:11,SNR1:-0.15343 ,SNR2: 0.89824




Frequency (Hz)

K20240811152521




BLK:11,SNR1: 1.2489 ,SNR2: 5.3886





Frequency (Hz)


3C279 2024/08/11 6.45UT FUJI -KISO



T20240811154053




BLK: 4,SNR1: 0.39859 ,SNR2: 3.0313




Frequency (Hz)

F20240811154053




BLK: 4,SNR1: 0.15400 ,SNR2: 1.2748





Frequency (Hz)


3C283 2024/08/11 6.71UT TOYOKAWA-FUJI




T20240811154053




BLK:16,SNR1: 0.18939 ,SNR2: 2.1638




K20240811154051



BLK:16,SNR1: 0.62586 ,SNR2: 2.3840




3C283 2024/08/11 6.71UT TOYOKAWA-KISO







F20240811154053




BLK:10,SNR1: 0.76502 ,SNR2: 1.9581




K20240811154051





BLK:10,SNR1: 1.2139 ,SNR2: 4.7188




3C283 2024/08/11 6.71UT FUJI -KISO





T20240811155518




BLK:11,SNR1: 1.3500 ,SNR2: 6.2652




F20240811155518





BLK:11,SNR1: 0.57331E-01,SNR2: 1.6292




1323+32 2024/08/11 6.95UT TOYOKAWA-FUJI



T20240811155518




BLK:16,SNR1: 0.55403 ,SNR2: 3.1370




Frequency (Hz)

K20240811155515





BLK:16,SNR1: 1.1193 ,SNR2: 5.7923





Frequency (Hz)

1323+32 2024/08/11 6.95UT TOYOKAWA-KISO







BLK:18,SNR1: 3.1098 ,SNR2: 13.657





BLK:18,SNR1: 2.0245 ,SNR2: 7.9424




1323+32 2024/08/11 6.95UT FUJI -KISO



T20240811160008





BLK:16,SNR1: 2.2641 ,SNR2: 6.9118




Frequency (Hz)

F20240811160008




BLK:16,SNR1: 0.26937 ,SNR2: 3.0425





Frequency (Hz)


3C286 2024/08/11 7.03UT TOYOKAWA-FUJI



T20240811160008





BLK:25,SNR1: 2.4986 ,SNR2: 6.9417




Frequency (Hz)

K20240811160005




BLK:25,SNR1: 0.51531 ,SNR2: 1.6797





Frequency (Hz)


3C286 2024/08/11 7.03UT TOYOKAWA-KISO



F20240811160008





BLK:22,SNR1: 0.28134 ,SNR2: 2.8319




Frequency (Hz)

K20240811160005




BLK:22,SNR1: 0.76181 ,SNR2: 3.0827





Frequency (Hz)


3C286 2024/08/11 7.03UT FUJI -KISO



T20240811161635





BLK: 3,SNR1: 0.17966 ,SNR2: 1.6183




Frequency (Hz)

F20240811161635




BLK: 3,SNR1: 0.20109 ,SNR2: 1.4962





Frequency (Hz)

1345+12 2024/08/11 7.30UT TOYOKAWA-FUJI






T20240811161635





BLK: 7,SNR1: 0.39706 ,SNR2: 1.1300




Frequency (Hz)

K20240811161632




BLK: 7,SNR1: 1.1410 ,SNR2: 4.9871





Frequency (Hz)


1345+12 2024/08/11 7.30UT TOYOKAWA-KISO



F20240811161635





BLK:12,SNR1: 0.27573E-01,SNR2: 1.0861




Frequency (Hz)

K20240811161632




BLK:12,SNR1: 0.42872 ,SNR2: 1.7064





Frequency (Hz)


1345+12 2024/08/11 7.30UT FUJI -KISO



T20240811162655





BLK: 6,SNR1: 0.35423 ,SNR2: 1.5781




Frequency (Hz)

F20240811162655




BLK: 6,SNR1: 0.18787 ,SNR2: 2.7475





Frequency (Hz)


1355+01 2024/08/11 7.48UT TOYOKAWA-FUJI



T20240811162655





BLK: 8,SNR1: 0.23072 ,SNR2: 1.2001




Frequency (Hz)

K20240811162652




BLK: 8,SNR1: 1.5681 ,SNR2: 7.0333




Frequency (Hz)


1355+01 2024/08/11 7.48UT TOYOKAWA-KISO



F20240811162655





BLK:10,SNR1: 0.35867 ,SNR2: 2.8851




Frequency (Hz)

K20240811162652




BLK:10,SNR1: 1.4564 ,SNR2: 6.5680




Frequency (Hz)


1355+01 2024/08/11 7.48UT FUJI -KISO



T20240811164806




BLK:13,SNR1: 0.53815 ,SNR2: 1.5231




Frequency (Hz)

F20240811164806




BLK:13,SNR1: 0.15499 ,SNR2: 1.4282




Frequency (Hz)


3C298 2024/08/11 7.83UT TOYOKAWA-FUJI





T20240811164806




BLK:15,SNR1: 0.65687 ,SNR2: 2.6502




K20240811164803




BLK:15,SNR1: 1.4282 ,SNR2: 4.4316




3C298 2024/08/11 7.83UT TOYOKAWA-KISO



F20240811164806





BLK: 8,SNR1: 2.0878 ,SNR2: 11.283




Frequency (Hz)

K20240811164803




BLK: 8,SNR1: 1.7918 ,SNR2: 5.7767





Frequency (Hz)

3C298 2024/08/11 7.83UT FUJI -KISO






T20240811165949





BLK: 1,SNR1: 0.12047 ,SNR2: 1.1895




Frequency (Hz)

F20240811165949




BLK: 1,SNR1: 0.49537 ,SNR2: 6.1085




Frequency (Hz)


1428-03 2024/08/11 8.03UT TOYOKAWA-FUJI





T20240811165949




BLK: 2,SNR1:-0.38430E-01,SNR2: 0.28124




K20240811165946




BLK: 2,SNR1: 0.22409E-01,SNR2: 3.0844




1428-03 2024/08/11 8.03UT TOYOKAWA-KISO



F20240811165949




BLK: 4, SNR1: 0.41884 , SNR2: 3.8445




Frequency (Hz)

K20240811165946




BLK: 4, SNR1: 0.12992 , SNR2: 1.0883





Frequency (Hz)


1428-03 2024/08/11 8.03UT FUJI -KISO



T20240811172308





BLK: 3,SNR1: 0.66022E-01,SNR2: 0.42919




Frequency (Hz)

F20240811172308




BLK: 3,SNR1: 0.23310 ,SNR2: 1.0094





Frequency (Hz)


1452+16 2024/08/11 8.41UT TOYOKAWA-FUJI



T20240811172308





BLK: 1,SNR1: 0.10556 ,SNR2: 0.72264




Frequency (Hz)

K20240811172305




BLK: 1,SNR1: 0.26444 ,SNR2: 4.0638





Frequency (Hz)


1452+16 2024/08/11 8.41UT TOYOKAWA-KISO



F20240811172308





BLK: 5,SNR1:-0.76748E-02,SNR2: 1.0471




Frequency (Hz)

K20240811172305



BLK: 5,SNR1: 14.030 ,SNR2: 35.498



Frequency (Hz)

1452+16 2024/08/11 8.41UT FUJI -KISO

