




T20240813061623




BLK:19,SNR1: 1.8596 ,SNR2: 7.9874




Frequency (Hz)

F20240813061623




BLK:19,SNR1: 0.66288 ,SNR2: 2.8543





Frequency (Hz)


0349+382 2024/08/12 21.30UT TOYOKAWA-FUJI




T20240813061623




BLK:25,SNR1: 1.6834 ,SNR2: 7.2708




K20240813061621





BLK:25,SNR1: 4.7943 ,SNR2: 9.3218




0349+382 2024/08/12 21.30UT TOYOKAWA-KISO



F20240813061623





BLK:23,SNR1: 0.57879 ,SNR2: 2.4468




Frequency (Hz)

K20240813061621








BLK:23,SNR1: 5.3703 ,SNR2: 10.400




Frequency (Hz)





0349+382 2024/08/12 21.30UT FUJI -KISO






0400+128 2024/08/12 21.47UT TOYOKAWA-FUJI








0400+128 2024/08/12 21.47UT TOYOKAWA-KISO



F20240813062636





BLK:11,SNR1: 0.58012 ,SNR2: 1.7950




Frequency (Hz)

K20240813062633




BLK:11,SNR1: 1.9043 ,SNR2: 7.1565





Frequency (Hz)


0400+128 2024/08/12 21.47UT FUJI -KISO



T20240813063726





BLK: 1,SNR1: 0.11644 ,SNR2: 0.88943




Frequency (Hz)

F20240813063726




BLK: 1,SNR1: 0.97941 ,SNR2: 2.3787





Frequency (Hz)


0411+05 2024/08/12 21.65UT TOYOKAWA-FUJI



T20240813063726




BLK: 2,SNR1: 0.13169 ,SNR2: 0.67451




Frequency (Hz)

K20240813063724




BLK: 2,SNR1: 76.053 ,SNR2: 117.83





Frequency (Hz)

0411+05 2024/08/12 21.65UT TOYOKAWA-KISO








F20240813063726




BLK: 2,SNR1: 0.17350 ,SNR2: 2.4280




K20240813063724





BLK: 2,SNR1: 0.44994 ,SNR2: 1.2769




0411+05 2024/08/12 21.65UT FUJI -KISO



T20240813064421





BLK: 3,SNR1: 2.7680 ,SNR2: 22.290




Frequency (Hz)

F20240813064421




BLK: 3,SNR1: 1.0791 ,SNR2: 2.0972





Frequency (Hz)


0418+236 2024/08/12 21.77UT TOYOKAWA-FUJI



T20240813064421





BLK: 6,SNR1: 2.2633 ,SNR2: 6.9935




Frequency (Hz)

K20240813064418




BLK: 6,SNR1: 58.820 ,SNR2: 82.905





Frequency (Hz)


0418+236 2024/08/12 21.77UT TOYOKAWA-KISO



F20240813064421





BLK: 5, SNR1: 0.23534 ,SNR2: 5.3152




Frequency (Hz)

K20240813064418




BLK: 5, SNR1: 18.971 ,SNR2: 30.176





Frequency (Hz)


0418+236 2024/08/12 21.77UT FUJI -KISO



T20240813065548





BLK: 6,SNR1: 0.90336 ,SNR2: 5.1299




Frequency (Hz)

3C119 2024/08/12 21.96UT TOYOKAWA-FUJI


F20240813065548




BLK: 6,SNR1: 0.28923 ,SNR2: 6.6999




Frequency (Hz)



T20240813065548





BLK:12,SNR1: 1.1460 ,SNR2: 5.3338




Frequency (Hz)

3C119 2024/08/12 21.96UT TOYOKAWA-KISO


K20240813065546




BLK:12,SNR1: 19.636 ,SNR2: 27.748




Frequency (Hz)



F20240813065548





BLK: 7,SNR1: 0.34248 ,SNR2: 3.3798




Frequency (Hz)

3C119 2024/08/12 21.96UT FUJI -KISO


K20240813065546





BLK: 7,SNR1: 3.7205 ,SNR2: 21.459




Frequency (Hz)



T20240813074355





BLK:16,SNR1: 1.9898 ,SNR2: 6.9409




Frequency (Hz)

F20240813074355




BLK:16,SNR1: 3.6755 ,SNR2: 13.033





Frequency (Hz)

3C138 2024/08/12 22.76UT TOYOKAWA-FUJI






T20240813074355




BLK:20,SNR1: 1.7915 ,SNR2: 6.4384




Frequency (Hz)

K20240813074353




BLK:20,SNR1: 47.802 ,SNR2: 46.226





Frequency (Hz)


3C138 2024/08/12 22.76UT TOYOKAWA-KISO



F20240813074355





BLK:17,SNR1: 0.55448 ,SNR2: 2.9988




Frequency (Hz)

3C138 2024/08/12 22.76UT FUJI -KISO


K20240813074353





BLK:17,SNR1: 12.602 ,SNR2: 24.256




Frequency (Hz)



T20240813075729





BLK: 9,SNR1: 0.56841 ,SNR2: 1.5941




Frequency (Hz)

F20240813075730




BLK: 9,SNR1:-0.53252E-02,SNR2: 2.8383





Frequency (Hz)


0531+194 2024/08/12 22.99UT TOYOKAWA-FUJI



T20240813075729





BLK:11,SNR1: 0.33413 ,SNR2: 1.6626




Frequency (Hz)

K20240813075726




BLK:11,SNR1: 8.7522 ,SNR2: 31.909




Frequency (Hz)


0531+194 2024/08/12 22.99UT TOYOKAWA-KISO




F20240813075730




BLK: 8,SNR1:-0.18184E-02,SNR2: 2.9494




K20240813075726





BLK: 8,SNR1: 8.6728 ,SNR2: 34.028




0531+194 2024/08/12 22.99UT FUJI -KISO



T20240813080548





BLK:18,SNR1: 5.5098 ,SNR2: 24.879




Frequency (Hz)

3C147 2024/08/12 23.12UT TOYOKAWA-FUJI


F20240813080548





BLK:18,SNR1: 0.56703E-01,SNR2: 1.9940




Frequency (Hz)



T20240813080548





BLK:25,SNR1: 4.9138 ,SNR2: 21.234




Frequency (Hz)

3C147 2024/08/12 23.12UT TOYOKAWA-KISO


K20240813080546





BLK:25,SNR1: 1.8451 ,SNR2: 7.9734




Frequency (Hz)



F20240813080548





BLK:19,SNR1: 0.47612E-01,SNR2: 2.1401




Frequency (Hz)

3C147 2024/08/12 23.12UT FUJI -KISO


K20240813080546



BLK:19,SNR1: 2.8906 ,SNR2: 12.599





Frequency (Hz)






T20240813081400





No.Good Data




Frequency (Hz)

F20240813081400




No.Good Data





Frequency (Hz)


0548+16 2024/08/12 23.26UT TOYOKAWA-FUJI



T20240813081400





BLK: 3,SNR1:-0.39449E-01,SNR2: 0.40721




Frequency (Hz)

K20240813081357




BLK: 3,SNR1: 3.1756 ,SNR2: 17.861





Frequency (Hz)


0548+16 2024/08/12 23.28UT TOYOKAWA-KISO



F20240813081400




BLK: 6,SNR1: 0.38219 ,SNR2: 2.2859




Frequency (Hz)

K20240813081357




BLK: 6,SNR1: 0.52676 ,SNR2: 2.2790




Frequency (Hz)


0548+16 2024/08/12 23.26UT FUJI -KISO



T20240813081810




BLK: 9,SNR1: 2.8028 ,SNR2: 21.358




Frequency (Hz)

F20240813081810











BLK: 9,SNR1: 0.36643 ,SNR2: 1.3257




Frequency (Hz)

0552+12 2024/08/12 23.33UT TOYOKAWA-FUJI






F20240813081810



Time (sec)




BLK: 3,SNR1: 0.67164 ,SNR2: 3.6498



Frequency (Hz)


K20240813081807



Time (sec)




BLK: 3,SNR1: 0.35124 ,SNR2: 1.0070





Frequency (Hz)


0552+12 2024/08/12 23.33UT FUJI -KISO



T20240813082237





BLK: 2,SNR1: 0.21737 ,SNR2: 0.47840




Frequency (Hz)

F20240813082237




BLK: 2,SNR1: 0.25572 ,SNR2: 3.9200





Frequency (Hz)


0556+191 2024/08/12 23.41UT TOYOKAWA-FUJI



T20240813082237





BLK: 4,SNR1: 0.40793E-01,SNR2: 0.26661





0556+191 2024/08/12 23.41UT TOYOKAWA-KISO

K20240813082234





BLK: 4,SNR1: 11.318 ,SNR2: 17.435






F20240813082237





BLK: 2,SNR1: 0.37338 ,SNR2: 4.4565




Frequency (Hz)

K20240813082234




BLK: 2,SNR1: 0.20168 ,SNR2: 0.52478





Frequency (Hz)


0556+191 2024/08/12 23.41UT FUJI -KISO



T20240813082710




BLK: 5,SNR1: 0.11672 ,SNR2: 0.95959




Frequency (Hz)

F20240813082710




BLK: 5,SNR1: 0.23984 ,SNR2: 3.8182





Frequency (Hz)


3C152 2024/08/12 23.48UT TOYOKAWA-FUJI



T20240813082710





BLK: 3,SNR1: 0.97700E-01,SNR2: 1.6620




Frequency (Hz)

K20240813082707




BLK: 3,SNR1: 0.12176 ,SNR2: 1.1828




Frequency (Hz)


3C152 2024/08/12 23.48UT TOYOKAWA-KISO



F20240813082710





BLK: 3,SNR1: 0.39468 ,SNR2: 2.6822




Frequency (Hz)

3C152 2024/08/12 23.48UT FUJI -KISO


K20240813082707




BLK: 3,SNR1: 0.34706 ,SNR2: 1.5487




Frequency (Hz)



T20240813084931





BLK: 4,SNR1: 0.57646 ,SNR2: 5.4355




Frequency (Hz)

3C161 2024/08/12 23.85UT TOYOKAWA-FUJI


F20240813084931




BLK: 4,SNR1:-0.26187 ,SNR2: 1.0492




Frequency (Hz)



T20240813084931





BLK:23,SNR1: 0.65001 ,SNR2: 3.9675




Frequency (Hz)

3C161 2024/08/12 23.85UT TOYOKAWA-KISO


K20240813084928





BLK:23,SNR1: 0.19982 ,SNR2: 2.4576




Frequency (Hz)



F20240813084931





BLK: 6,SNR1:-0.10746 ,SNR2: 0.79776




Frequency (Hz)

K20240813084928




BLK: 6,SNR1: 0.17880 ,SNR2: 1.7428





Frequency (Hz)


3C161 2024/08/12 23.85UT FUJI -KISO





T20240813091704




No.Good Data




F20240813091704



No.Good Data





0652-130 2024/08/13 0.31UT TOYOKAWA-FUJI







T20240813091704




BLK: 1,SNR1: 0.23814 ,SNR2: 1.7249




K20240813091701





BLK: 1,SNR1: 0.53414E-01,SNR2: 0.10010




0652-130 2024/08/13 03:1UT TOYOKAWA-KISO



F20240813091704





BLK: 1,SNR1:-0.16683 ,SNR2: 1.0642




Frequency (Hz)

K20240813091701




BLK: 1,SNR1: 0.32605E-01,SNR2: 0.32368




Frequency (Hz)


0652-130 2024/08/13 0.31UT FWJ -KISO




T20240813092840




BLK: 9,SNR1: 0.10272 ,SNR2: 0.17584




F20240813092840




BLK: 9,SNR1: 3.4716 ,SNR2: 10.006




0703+138 2024/08/13 0.51UT TOYOKAWA-FUJI





T20240813092840




BLK: 7,SNR1: 0.57639E-01,SNR2: 0.97291




K20240813092838





BLK: 7,SNR1: 1.4589 ,SNR2: 4.7453




0703+138 2024/08/13 0.51UT TOYOKAWA-KISO



F20240813092840





BLK:14,SNR1: 2.3020 ,SNR2: 7.2142




Frequency (Hz)

K20240813092838




BLK:14,SNR1: 1.4898 ,SNR2: 5.1825





Frequency (Hz)


0703+138 2024/08/13 0.51UT FUJI -KISO



T20240813093803





BLK: 4,SNR1:-0.16289 ,SNR2: 0.57666E-02




Frequency (Hz)

0713-024 2024/08/13 0.66UT TOYOKAWA-FUJI


F20240813093803





BLK: 4,SNR1:-0.93343E-01,SNR2: 2.9828




Frequency (Hz)



T20240813093803





BLK: 4,SNR1: 0.17431 ,SNR2: 1.1187





0713-024 2024/08/13 0.66UT TOYOKAWA-KISO


K20240813093800




BLK: 4,SNR1: 0.51685 ,SNR2: 6.5130





F20240813093803




BLK: 5,SNR1: 0.60811 ,SNR2: 5.7126




K20240813093800



BLK: 5,SNR1: 0.13484 ,SNR2: 1.8327





0713-024 2024/08/13 0.66UT FUJI -KISO








T20240813094815




BLK: 8,SNR1: 0.21214 ,SNR2: 0.65910




F20240813094815




BLK: 8,SNR1: 0.65645 ,SNR2: 4.5102




0723+10 2024/08/13 0.83UT TOYOKAWA-FUJI



T20240813094815





BLK: 7,SNR1: 0.10960 ,SNR2: 1.4116





0723+10 2024/08/13 0.83UT TOYOKAWA-KISO


K20240813094812




BLK: 7,SNR1: 0.70520 ,SNR2: 2.7343




F20240813094815




BLK: 4,SNR1: 0.14319 ,SNR2: 1.6082




K20240813094812





BLK: 4,SNR1: 0.60802 ,SNR2: 3.5956




0723+10 2024/08/13 0.83UT FUJI -KISO



T20240813095829




BLK: 3,SNR1: 0.29180 ,SNR2: 1.0934




Frequency (Hz)

F20240813095829




BLK: 3,SNR1: 0.73667 ,SNR2: 7.0257




Frequency (Hz)


0732+33 2024/08/13 1.00UT TOYOKAWA-FUJI



T20240813095829




BLK: 9,SNR1: 0.37425 ,SNR2: 1.5259




Frequency (Hz)

0732+33 2024/08/13 1.00UT TOYOKAWA-KISO


K20240813095826





BLK: 9,SNR1: 1.2010 ,SNR2: 5.3915




Frequency (Hz)





F20240813095829




BLK: 7,SNR1:-0.34233E-01,SNR2: 1.0532




K20240813095826





BLK: 7,SNR1: 2.0326 ,SNR2: 8.1008




0732+33 2024/08/13 1.00UT FUJI -KISO



T20240813100631





BLK: 5,SNR1: 0.48145 ,SNR2: 1.7357





0741-06 2024/08/13 1.14UT TOYOKAWA-FUJI



F20240813100631




BLK: 5,SNR1: 0.96119 ,SNR2: 8.8724





T20240813100631




BLK: 8,SNR1: 0.36463 ,SNR2: 2.2369




K20240813100628



BLK: 8,SNR1: 0.19107 ,SNR2: 0.55220




0741-06 2024/08/13 1.14UT TOYOKAWA-KISO








F20240813100631




BLK: 4,SNR1: 3.7515 ,SNR2: 15.388




K20240813100628





BLK: 4,SNR1: 0.22138 ,SNR2: 0.50147




0741-06 2024/08/13 1.14UT FUJI -KISO




T20240813101616




BLK: 5,SNR1:-0.19208E-02,SNR2: 0.94117




F20240813101616





BLK: 5,SNR1: 0.23509 ,SNR2: 2.2568




0752-200 2024/08/13 1.30UT TOYOKAWA-FUJI



T20240813101616




BLK: 7,SNR1: 0.20355E-01,SNR2: 1.5640





0752-200 2024/08/13 1.30UT TOYOKAWA-KISO


K20240813101613




BLK: 7,SNR1: 1.0467 ,SNR2: 10.093





F20240813101616




BLK: 3,SNR1: 0.90137 ,SNR2: 3.3167




K20240813101613





BLK: 3,SNR1: 0.12071 ,SNR2: 3.1745




0752-200 2024/08/13 1.30UT FUJI -KISO





T20240813102351




BLK:11,SNR1: 0.21978 ,SNR2: 1.5356




F20240813102351





BLK:11,SNR1: 0.39721 ,SNR2: 2.4593




3C190 2024/08/13 1.43UT TOYOKAWA-FUJI





T20240813102351




BLK:12,SNR1: 0.24405 ,SNR2: 1.9311




K20240813102348





BLK:12,SNR1: 0.76168 ,SNR2: 3.5180




3C190 2024/08/13 1.43UT TOYOKAWA-KISO



F20240813102351





BLK:14,SNR1: 0.51441 ,SNR2: 2.1670




Frequency (Hz)

K20240813102348




BLK:14,SNR1: 0.70311 ,SNR2: 3.1695




Frequency (Hz)


3C190 2024/08/13 1.43UT FUJI -KISO



T20240813103615




BLK:18,SNR1: 0.90884 ,SNR2: 8.5716





3C196 2024/08/13 1.63UT TOYOKAWA-FUJI

F20240813103615




BLK:18,SNR1: 3.3835 ,SNR2: 7.2632







T20240813103615




BLK:23,SNR1: 0.85015 ,SNR2: 2.9715




K20240813103612




BLK:23,SNR1: 4.4350 ,SNR2: 14.353




3C196 2024/08/13 1.63UT TOYOKAWA-KISO



F20240813103615





BLK:23,SNR1: 3.0380 ,SNR2: 6.6623





3C196 2024/08/13 1.63UT FUJI -KISO


K20240813103612




BLK:23,SNR1: 4.0757 ,SNR2: 12.456




T20240813104725




BLK:12,SNR1: 0.11258 ,SNR2: 0.81647




F20240813104725





BLK:12,SNR1: 4.4205 ,SNR2: 4.1599




0821+394 2024/08/13 1.82UT TOYOKAWA-FUJI



T20240813104725





BLK:15,SNR1: 0.11611 ,SNR2: 0.82621




Frequency (Hz)

0821+394 2024/08/13 1.82UT TOYOKAWA-KISO


K20240813104722




BLK:15,SNR1: 0.22965 ,SNR2: 1.6350




Frequency (Hz)





F20240813104725




BLK:16,SNR1: 2.1044 ,SNR2: 2.5401




K20240813104722




BLK:16,SNR1: 8.7531 ,SNR2: 18.010




0821+394 2024/08/13 1.82UT FUJI -KISO



T20240813105905




BLK: 8,SNR1: 0.71177E-01,SNR2: 1.5666





0834-19 2024/08/13 2.01UT TOYOKAWA-FUJI



F20240813105905




BLK: 8,SNR1: 0.33385 ,SNR2: 4.7659





T20240813105905




BLK: 6,SNR1: 0.44331E-01,SNR2: 1.7330




K20240813105902




BLK: 6,SNR1: 0.47394 ,SNR2: 1.7458




0834-19 2024/08/13 2.01UT TOYOKAWA-KISO





F20240813105905




BLK: 5, SNR1: 0.63362 , SNR2: 3.0209




K20240813105902



BLK: 5, SNR1: 0.33294 , SNR2: 1.8706





0834-19 2024/08/13 2.01UT FUJI -KISO






T20240813110410




BLK:11,SNR1: 8.3514 ,SNR2: 31.729





0839-071 2024/08/13 2.10UT TOYOKAWA-FUJI



F20240813110410




BLK:11,SNR1: 0.34343 ,SNR2: 9.7459



T20240813110410





BLK:21,SNR1: 8.4554 ,SNR2: 32.117





0839-071 2024/08/13 2.10UT TOYOKAWA-KISO


K20240813110407




BLK:21,SNR1: 6.4510 ,SNR2: 24.490





F20240813110410




BLK:15,SNR1: 0.56542 ,SNR2: 12.308




K20240813110407





BLK:15,SNR1: 6.4628 ,SNR2: 24.534




0839-071 2024/08/13 2.10UT FUJI -KISO



T20240813111511





BLK:24,SNR1: 0.26394 ,SNR2: 1.0643




Frequency (Hz)

F20240813111511




BLK:24,SNR1: 3.0492 ,SNR2: 9.7035





Frequency (Hz)


3C208 2024/08/13 2.28UT TOYOKAWA-FUJI





T20240813111511




BLK:23,SNR1: 0.27687 ,SNR2: 1.1062




K20240813111508





BLK:23,SNR1: 9.5222 ,SNR2: 18.340




3C208 2024/08/13 2.28UT TOYOKAWA-KISO




F20240813111511




BLK:26,SNR1: 2.9557 ,SNR2: 9.9793




K20240813111508




BLK:26,SNR1: 12.688 ,SNR2: 24.418




3C208 2024/08/13 2.28UT FUJI -KISO



T20240813113153




BLK:24,SNR1: 6.7243 ,SNR2: 25.948





3C216 2024/08/13 2.56UT TOYOKAWA-FUJI


F20240813113153




BLK:24,SNR1: 6.3853 ,SNR2: 24.783



T20240813113153





BLK:24,SNR1: 5.2287 ,SNR2: 20.512





3C216 2024/08/13 2.56UT TOYOKAWA-KISO

K20240813113150




BLK:24,SNR1: 7.0999 ,SNR2: 26.343






F20240813113153




BLK:27,SNR1: 9.7388 ,SNR2: 35.562





3C216 2024/08/13 2.56UT FUJI -KISO


K20240813113150




BLK:27,SNR1: 7.4792 ,SNR2: 28.108




T20240813114404




BLK:11,SNR1: 1.1625 ,SNR2: 3.0499




F20240813114404




BLK:11,SNR1: 0.98048E-01,SNR2: 2.7038




0919-142 2024/08/13 2.76UT TOYOKAWA-FUJI




T20240813114404




BLK:26,SNR1: 0.86613 ,SNR2: 2.9563




K20240813114401




BLK:26,SNR1: 5.1769 ,SNR2: 10.235




0919-142 2024/08/13 2.76UT TOYOKAWA-KISO




F20240813114404




BLK:23,SNR1:-0.15380 ,SNR2: 1.3403




K20240813114401





BLK:23,SNR1: 4.7003 ,SNR2: 17.079




0919-142 2024/08/13 2.76UT FUJI -KISO




T20240813115043




BLK:31,SNR1: 2.4119 ,SNR2: 8.4881




F20240813115044





BLK:31,SNR1: 6.0600 ,SNR2: 19.073




0926+117 2024/08/13 2.87UT TOYOKAWA-FUJI




T20240813115043




BLK:25,SNR1: 1.5645 ,SNR2: 6.0721




K20240813115040




BLK:25,SNR1: 1.6985 ,SNR2: 6.4928





0926+117 2024/08/13 2.87UT TOYOKAWA-KISO







BLK:18,SNR1: 4.1139 ,SNR2: 12.429




BLK:18,SNR1: 2.0970 ,SNR2: 7.5949




0926+117 2024/08/13 2.87UT FUJI -KISO



T20240813115828




BLK:23,SNR1: 5.6873 ,SNR2: 11.370





3C222 2024/08/13 3.00UT TOYOKAWA-FUJI

F20240813115828




BLK:23,SNR1: 0.21936 ,SNR2: 3.9179






T20240813115828




BLK:28,SNR1: 5.5363 ,SNR2: 11.007





3C222 2024/08/13 3.00UT TOYOKAWA-KISO


K20240813115825




BLK:28,SNR1: 10.756 ,SNR2: 40.059



F20240813115828




BLK:30,SNR1: 0.81383 ,SNR2: 3.5948





3C222 2024/08/13 3.00UT FUJI -KISO



K20240813115825




BLK:30,SNR1: 11.130 ,SNR2: 41.410



T20240813120528





BLK:10,SNR1: 9.5842 ,SNR2: 22.482





0941-08 2024/08/13 3.12UT TOYOKAWA-FUJI


F20240813120528




BLK:10,SNR1: 2.3916 ,SNR2: 11.504



T20240813120528





BLK:24,SNR1: 9.9003 ,SNR2: 23.457




0941-08 2024/08/13 3.12UT TOYOKAWA-KISO


K20240813120525





BLK:24,SNR1: 2.7131 ,SNR2: 13.020




Frequency (Hz)



F20240813120528





BLK:27,SNR1: 5.9620 ,SNR2: 15.079









0941-08 2024/08/13 3.12UT FUJI -KISO

K20240813120525








BLK:27,SNR1: 2.7715 ,SNR2: 13.247






3C230 2024/08/13 3.26UT TOYOKAWA-FUJI







3C230 2024/08/13 3.26UT TOYOKAWA-KISO




F20240813121350




BLK:14,SNR1:-0.49448E-01,SNR2: 1.8886




K20240813121347



BLK:14,SNR1: 6.6248 ,SNR2: 20.868





3C230 2024/08/13 3.26UT FUJI -KISO








T20240813122757




BLK:26,SNR1: 10.644 ,SNR2: 18.954




F20240813122757





BLK:26,SNR1: 7.3984 ,SNR2: 18.326




3C236 2024/08/13 3.49UT TOYOKAWA-FUJI




T20240813122757




BLK:25,SNR1: 8.4018 ,SNR2: 15.682




K20240813122754





BLK:25,SNR1: 19.564 ,SNR2: 24.995




3C236 2024/08/13 3.49UT TOYOKAWA-KISO



F20240813122757





BLK:31,SNR1: 6.9773 ,SNR2: 17.296





3C236 2024/08/13 3.49UT FUJI -KISO


K20240813122754




BLK:31,SNR1: 8.0517 ,SNR2: 22.562




T20240813123607




BLK: 9,SNR1: 1.4788 ,SNR2: 6.2646




F20240813123607




BLK: 9,SNR1: 2.4163 ,SNR2: 7.8557




1011+110 2024/08/13 3.63UT TOYOKAWA-FUJI





T20240813123607




BLK:12,SNR1: 1.2924 ,SNR2: 5.3272




K20240813123604





BLK:12,SNR1: 0.88913 ,SNR2: 2.9121




1011+110 2024/08/13 3.63UT TOYOKAWA-KISO





F20240813123607




BLK: 5,SNR1: 0.25214 ,SNR2: 2.0374




K20240813123604




BLK: 5,SNR1: 2.7123 ,SNR2: 10.814




1011+110 2024/08/13 3.63UT FUJI -KISO



T20240813124347





BLK:17,SNR1: 1.5648 ,SNR2: 11.283





3C241 2024/08/13 3.76UT TOYOKAWA-FUJI



F20240813124347




BLK:17,SNR1: 1.8452 ,SNR2: 7.2553



T20240813124347





BLK:16,SNR1: 10.001 ,SNR2: 202.70





3C241 2024/08/13 3.76UT TOYOKAWA-KISO





K20240813124344




BLK:16,SNR1: 9.4457 ,SNR2: 35.711










3C241 2024/08/13 3.76UT FUJI -KISO




T20240813125517




BLK: 9,SNR1: 1.3319 ,SNR2: 5.7085




F20240813125517





BLK: 9,SNR1: 2.2805 ,SNR2: 5.7887




1031-11 2024/08/13 3.95UT TOYOKAWA-FUJI



T20240813125517





BLK:16,SNR1: 1.1853 ,SNR2: 3.6912





1031-11 2024/08/13 3.95UT TOYOKAWA-KISO


K20240813125514




BLK:16,SNR1: 4.7436 ,SNR2: 19.595





F20240813125517




BLK: 9,SNR1: 2.1848 ,SNR2: 5.5605




K20240813125514





BLK: 9,SNR1: 1.6379 ,SNR2: 6.3467




1031-11 2024/08/13 3.95UT FUJI -KISO




T20240813125950




BLK:12,SNR1: 6.2309 ,SNR2: 11.096




F20240813125950





BLK:12,SNR1: 0.77343 ,SNR2: 7.0437




1035-058 2024/08/13 4.03UT TOYOKAWA-FUJI



T20240813125950





BLK:18,SNR1: 7.8141 ,SNR2: 13.885





1035-058 2024/08/13 4.03UT TOYOKAWA-KISO


K20240813125947




BLK:18,SNR1: 7.8927 ,SNR2: 20.024





F20240813125950




BLK:14,SNR1: 2.3800 ,SNR2: 8.4183




K20240813125947





BLK:14,SNR1: 7.2891 ,SNR2: 21.439




1035-058 2024/08/13 4.03UT FUJI -KISO





T20240813130903




BLK:13,SNR1: 23.882 ,SNR2: 30.420




F20240813130903



BLK:13,SNR1: 9.6448 ,SNR2: 18.165





1044-008 2024/08/13 4.18UT TOYOKAWA-FUJI








T20240813130903




BLK:10,SNR1: 2.4947 ,SNR2: 9.1105




K20240813130900




BLK:10,SNR1: 6.3805 ,SNR2: 23.443




1044-008 2024/08/13 4.18UT TOYOKAWA-KISO





F20240813130903




BLK:19,SNR1: 10.672 ,SNR2: 20.143




K20240813130900





BLK:19,SNR1: 10.144 ,SNR2: 37.120




1044-008 2024/08/13 4.18UT FUJI -KISO




T20240813132001




BLK: 8,SNR1: 0.12287 ,SNR2: 1.6563




F20240813132001





BLK: 8,SNR1:-0.22070 ,SNR2: 1.7742




1055+20 2024/08/13 4.36UT TOYOKAWA-FUJI





T20240813132001




BLK:10,SNR1: 0.12029 ,SNR2: 1.4190




K20240813131958




BLK:10,SNR1: 4.2467 ,SNR2: 13.475




1055+20 2024/08/13 4.36UT TOYOKAWA-KISO



F20240813132001





BLK: 9,SNR1:-0.17209 ,SNR2: 1.1252





1055+20 2024/08/13 4.36UT FUJI -KISO



K20240813131958




BLK: 9,SNR1: 2.5824 ,SNR2: 10.094




T20240813133125




BLK: 8,SNR1: 0.31480 ,SNR2: 1.8562




F20240813133125





BLK: 8,SNR1: 0.22369 ,SNR2: 1.3048




1107+109 2024/08/13 4.55UT TOYOKAWA-FUJI





T20240813133125




BLK:16,SNR1: 0.38642 ,SNR2: 1.6875




K20240813133123




BLK:16,SNR1: 0.61928 ,SNR2: 3.0542




1107+109 2024/08/13 4.55UT TOYOKAWA-KISO




F20240813133125




BLK: 7,SNR1: 0.42226 ,SNR2: 1.8592




K20240813133123



BLK: 7,SNR1: 0.75272 ,SNR2: 2.0269





1107+109 2024/08/13 4.55UT FUJI -KISO






T20240813134102




BLK:11,SNR1: 1.2278 ,SNR2: 5.6005





3C255 2024/08/13 4.71UT TOYOKAWA-FUJI


F20240813134102




BLK:11,SNR1:-0.24103 ,SNR2: 1.1780





T20240813134102




BLK:22,SNR1: 0.91969 ,SNR2: 9.2158




K20240813134059




BLK:22,SNR1: 0.26079 ,SNR2: 1.3084




3C255 2024/08/13 4.71UT TOYOKAWA-KISO



F20240813134102





BLK: 7,SNR1:-0.66389E-01,SNR2: 1.5998





3C255 2024/08/13 4.71UT FUJI -KISO



K20240813134059




BLK: 7,SNR1: 0.46998 ,SNR2: 1.4359



T20240813135140





BLK: 7,SNR1: 0.18966 ,SNR2: 2.0770




Frequency (Hz)

F20240813135140




BLK: 7,SNR1:-0.29767 ,SNR2: 0.72728





Frequency (Hz)


1127-14 2024/08/13 4.89UT TOYOKAWA-FUJI





T20240813135140




BLK:12,SNR1: 0.13771 ,SNR2: 0.94544




K20240813135137




BLK:12,SNR1: 0.61209 ,SNR2: 2.2181




1127-14 2024/08/13 4.89UT TOYOKAWA-KISO





F20240813135140




BLK: 4,SNR1:-0.23834 ,SNR2: 1.4970




K20240813135137





BLK: 4,SNR1: 1.1993 ,SNR2: 9.5635




1127-14 2024/08/13 4.89UT FUJI -KISO




T20240813140500




BLK: 7,SNR1: 0.19207 ,SNR2: 3.0697




F20240813140500





BLK: 7,SNR1: 0.44257E-01,SNR2: 2.2034




3C263.1 2024/08/13 5.11UT TOYOKAWA-FUJI





T20240813140500




BLK:12,SNR1: 0.22294 ,SNR2: 2.7189




K20240813140457



BLK:12,SNR1: 0.17415 ,SNR2: 0.55744





3C263.1 2024/08/13 5.11UT TOYOKAWA-KISO






F20240813140500





BLK: 3,SNR1: 3.2831 ,SNR2: 20.876





3C263.1 2024/08/13 5.11UT FUJI -KISO


K20240813140457




BLK: 3,SNR1: 0.15871 ,SNR2: 1.3841




T20240813141127




BLK:17,SNR1: 0.71935 ,SNR2: 2.9228




F20240813141127




BLK:17,SNR1: 0.85692 ,SNR2: 3.5085




3C267 2024/08/13 5.22UT TOYOKAWA-FUJI





T20240813141127




BLK:15,SNR1: 0.36106 ,SNR2: 1.2820




K20240813141124





BLK:15,SNR1: 0.96304 ,SNR2: 3.8737




3C267 2024/08/13 5.22UT TOYOKAWA-KISO



F20240813141127





BLK:23,SNR1: 0.98054 ,SNR2: 3.8855




Frequency (Hz)

K20240813141124




BLK:23,SNR1: 1.6316 ,SNR2: 6.8311





Frequency (Hz)


3C267 2024/08/13 5.22UT FUJI -KISO



T20240813143715





BLK: 3,SNR1: 0.40688E-01,SNR2: 0.35650




Frequency (Hz)

F20240813143715




BLK: 3,SNR1: 0.53591 ,SNR2: 6.3428





Frequency (Hz)


1213-17 2024/08/13 5.65UT TOYOKAWA-FUJI





T20240813143715




BLK: 6,SNR1: 0.96570E-01,SNR2: 0.58888




K20240813143712




BLK: 6,SNR1: 2.0505 ,SNR2: 9.1941




1213-17 2024/08/13 5.65UT TOYOKAWA-KISO





F20240813143715




BLK: 2,SNR1:-0.38003 ,SNR2: 0.0000




K20240813143712





BLK: 2,SNR1: 1.6514 ,SNR2: 10.423




1213-17 2024/08/13 5.65UT FUJI -KISO




T20240813145032




BLK:22,SNR1: 5.0653 ,SNR2: 22.187




F20240813145032



BLK:22,SNR1:-0.35614E-01,SNR2: 2.3238





3C273 2024/08/13 5.87UT TOYOKAWA-FUJI








T20240813145032




BLK:33,SNR1: 5.2436 ,SNR2: 24.096




K20240813145030




BLK:33,SNR1: 0.69439 ,SNR2: 2.4968




3C273 2024/08/13 5.87UT TOYOKAWA-KISO





F20240813145032




BLK:20,SNR1: 0.14986 ,SNR2: 3.0073




K20240813145030





BLK:20,SNR1: 0.83390 ,SNR2: 4.1625




3C273 2024/08/13 5.87UT FUJI -KISO



T20240813150343





BLK: 6,SNR1: 0.11217 ,SNR2: 0.42271




Frequency (Hz)

F20240813150343




BLK: 6,SNR1:-0.16834 ,SNR2: 1.8646





Frequency (Hz)


3C275 2024/08/13 6.09UT TOYOKAWA-FUJI



T20240813150343





BLK: 4,SNR1: 0.12739 ,SNR2: 1.0129




Frequency (Hz)

K20240813150341




BLK: 4,SNR1: 0.82833 ,SNR2: 4.6030




Frequency (Hz)


3C275 2024/08/13 6.09UT TOYOKAWA-KISO



F20240813150343





BLK: 7,SNR1: 1.6657 ,SNR2: 11.987




Frequency (Hz)

K20240813150341




BLK: 7,SNR1: 1.9803 ,SNR2: 7.9967





Frequency (Hz)


3C275 2024/08/13 6.09UT FUJI -KISO



T20240813150948





BLK: 8,SNR1: 0.30266E-01,SNR2: 0.83464




Frequency (Hz)

F20240813150948




BLK: 8,SNR1: 0.67639 ,SNR2: 1.7765





Frequency (Hz)


1245-19 2024/08/13 6.19UT TOYOKAWA-FUJI





T20240813150948




BLK: 6,SNR1: 0.81181E-01,SNR2: 3.1074




K20240813150946





BLK: 6,SNR1: 0.28342 ,SNR2: 0.37222




1245-19 2024/08/13 6.19UT TOYOKAWA-KISO



F20240813150948





BLK: 4,SNR1: 0.80576 ,SNR2: 3.0040




Frequency (Hz)

K20240813150946




BLK: 4,SNR1: 0.20715 ,SNR2: 0.56602





Frequency (Hz)

1245-19 2024/08/13 6.19UT FUJI -KISO






T20240813151732





BLK: 4,SNR1: 0.17895E-01,SNR2: 1.3916




Frequency (Hz)

F20240813151732




BLK: 4,SNR1:-0.27138 ,SNR2: 0.45206




Frequency (Hz)


3C279 2024/08/13 6.32UT TOYOKAWA-FUJI



T20240813151732





BLK: 4,SNR1:-0.85569E-02,SNR2: 0.92115




Frequency (Hz)

K20240813151730




BLK: 4,SNR1: 0.39275 ,SNR2: 3.8945




Frequency (Hz)


3C279 2024/08/13 6.32UT TOYOKAWA-KISO





F20240813151732




BLK: 5,SNR1: 0.12560E-01,SNR2: 2.3197




K20240813151730





BLK: 5,SNR1: 0.49261 ,SNR2: 1.7472




3C279 2024/08/13 6.32UT FUJI -KISO



T20240813153301





BLK:11,SNR1: 0.20179 ,SNR2: 1.7503




Frequency (Hz)

F20240813153301




BLK:11,SNR1: 0.62012 ,SNR2: 3.0810





Frequency (Hz)


3C283 2024/08/13 6.58UT TOYOKAWA-FUJI





T20240813153301




BLK: 8,SNR1: 0.27038 ,SNR2: 1.4128




K20240813153258




BLK: 8,SNR1: 0.21563 ,SNR2: 0.84326




3C283 2024/08/13 6.58UT TOYOKAWA-KISO





F20240813153301




BLK: 9,SNR1: 0.48038 ,SNR2: 2.6757




K20240813153258





BLK: 9,SNR1: 0.12612 ,SNR2: 0.85381




3C283 2024/08/13 6.58UT FUJI -KISO



T20240813154726




BLK:17,SNR1: 1.3484 ,SNR2: 6.7220




Frequency (Hz)

F20240813154726




BLK:17,SNR1: 0.25198 ,SNR2: 1.8533





Frequency (Hz)


1323+32 2024/08/13 6.82UT TOYOKAWA-FUJI





T20240813154726




BLK:15,SNR1: 1.3563 ,SNR2: 6.9886




K20240813154723



BLK:15,SNR1: 0.37166 ,SNR2: 1.7553




1323+32 2024/08/13 6.82UT TOYOKAWA-KISO






F20240813154726




BLK: 9,SNR1: 0.43533 ,SNR2: 3.0905




Frequency (Hz)

K20240813154723




BLK: 9,SNR1: 0.57596 ,SNR2: 2.6329




Frequency (Hz)


1323+32 2024/08/13 6.82UT FUJI -KISO



T20240813155216





BLK:18,SNR1: 5.1585 ,SNR2: 10.488




Frequency (Hz)

F20240813155216




BLK:18,SNR1: 0.28418 ,SNR2: 3.0710





Frequency (Hz)


3C286 2024/08/13 6.90UT TOYOKAWA-FUJI



T20240813155216





BLK:19,SNR1: 5.7950 ,SNR2: 15.752




Frequency (Hz)

K20240813155213




BLK:19,SNR1: 5.1979 ,SNR2: 13.009




Frequency (Hz)


3C286 2024/08/13 6.90UT TOYOKAWA-KISO





F20240813155216




BLK:12,SNR1: 2.7537 ,SNR2: 6.6120




K20240813155213





BLK:12,SNR1: 6.6653 ,SNR2: 16.427




3C286 2024/08/13 6.90UT FUJI -KISO



T20240813160843





BLK:10,SNR1: 0.25787 ,SNR2: 2.0519




Frequency (Hz)

F20240813160843




BLK:10,SNR1: 0.14606 ,SNR2: 0.90742





Frequency (Hz)


1345+12 2024/08/13 7.17UT TOYOKAWA-FUJI



T20240813160843





BLK:10,SNR1: 0.24263 ,SNR2: 2.3720




Frequency (Hz)

K20240813160841




BLK:10,SNR1: 1.2832 ,SNR2: 5.5493




Frequency (Hz)


1345+12 2024/08/13 7.17UT TOYOKAWA-KISO




F20240813160843




BLK: 8,SNR1: 0.48633E-01,SNR2: 1.2779




K20240813160841




BLK: 8,SNR1: 0.32690 ,SNR2: 1.5588




1345+12 2024/08/13 7.17UT FUJI -KISO



T20240813161904




BLK: 1,SNR1: 0.20121 ,SNR2: 2.6790




Frequency (Hz)

F20240813161904




BLK: 1,SNR1:-0.23921 ,SNR2: 0.0000





Frequency (Hz)

1355+01 2024/08/13 7.35UT TOYOKAWA-FUJI






T20240813161904





BLK: 4,SNR1: 0.25013 ,SNR2: 0.61441




Frequency (Hz)

K20240813161901




BLK: 4,SNR1: 1.8031 ,SNR2: 6.9115




Frequency (Hz)


1355+01 2024/08/13 7.35UT TOYOKAWA-KISO



F20240813161904





BLK: 7,SNR1: 0.54050E-01,SNR2: 0.99497




Frequency (Hz)

K20240813161901




BLK: 7,SNR1: 1.3832 ,SNR2: 3.4705





Frequency (Hz)


1355+01 2024/08/13 7.35UT FUJI -KISO



T20240813164014





BLK: 4,SNR1: 0.31166 ,SNR2: 1.2218




Frequency (Hz)

F20240813164014




BLK: 4,SNR1: 0.70092E-01,SNR2: 2.5222





Frequency (Hz)


3C298 2024/08/13 7.70UT TOYOKAWA-FUJI



T20240813164014





BLK: 9,SNR1: 0.12208 ,SNR2: 1.3040




Frequency (Hz)

K20240813164012




BLK: 9,SNR1: 1.0030 ,SNR2: 2.2263





Frequency (Hz)


3C298 2024/08/13 7.70UT TOYOKAWA-KISO



F20240813164014





BLK: 7,SNR1: 0.51170 ,SNR2: 1.3352




Frequency (Hz)

K20240813164012




BLK: 7,SNR1: 0.58830 ,SNR2: 1.8799





Frequency (Hz)


3C298 2024/08/13 7.70UT FUJI -KISO



T20240813165158





BLK: 6,SNR1: 0.23882 ,SNR2: 0.76036




Frequency (Hz)

F20240813165158




BLK: 6,SNR1: 2.9765 ,SNR2: 8.4781





Frequency (Hz)


1428-03 2024/08/13 7.89UT TOYOKAWA-FUJI



T20240813165158





BLK: 7,SNR1: 0.16897 ,SNR2: 1.5622




Frequency (Hz)

K20240813165155




BLK: 7,SNR1: 1.2341 ,SNR2: 4.4964




Frequency (Hz)


1428-03 2024/08/13 7.89UT TOYOKAWA-KISO



F20240813165158





BLK: 8,SNR1: 2.4178 ,SNR2: 7.1924




Frequency (Hz)

K20240813165155



BLK: 8,SNR1: 0.98230 ,SNR2: 2.2359



Frequency (Hz)

1428-03 2024/08/13 7.89UT FUJI -KISO

