




T20240824061233




BLK: 5,SNR1: 0.71156E-01,SNR2: 0.62455




Frequency (Hz)

F20240824061233




BLK: 5,SNR1: 0.88878 ,SNR2: 2.8388




Frequency (Hz)

3C119 2024/08/23 21.24UT TOYOKAWA-FUJI



T20240824061233



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C119 2024/08/23 21.24UT TOYOKAWA-KISO




F20240824061233



No.Good Data




KISO





No.Good Data




3C119 2024/08/23 21.24UT FUJI -KISO



T20240824070040





BLK:20,SNR1: 1.4443 ,SNR2: 2.7855




Frequency (Hz)

F20240824070040




BLK:20,SNR1: 0.73441 ,SNR2: 2.5955



Frequency (Hz)

3C138 2024/08/23 22.04UT TOYOKAWA-FUJI




T20240824070040



No.Good Data




KISO




No.Good Data



3C138 2024/08/23 22.04UT TOYOKAWA-KISO




F20240824070040



No.Good Data




KISO





No.Good Data




3C138 2024/08/23 22.04UT FUJI -KISO



T20240824071414





BLK:10,SNR1: 0.23908 ,SNR2: 1.6830




Frequency (Hz)

F20240824071414




BLK:10,SNR1: 0.61322E-01,SNR2: 1.0792



Frequency (Hz)


0531+194 2024/08/23 22.27UT TOYOKAWA-FUJI



T20240824071414



No.Good Data




KISO



No.Good Data



0531+194 2024/08/23 22.27UT TOYOKAWA-KISO






F20240824071414




No.Good Data



KISO





No.Good Data




0531+194 2024/08/23 22.27UT FUJI -KISO



T20240824072233





BLK:19,SNR1: 1.9780 ,SNR2: 2.4361




Frequency (Hz)

3C147 2024/08/23 22.40UT TOYOKAWA-FUJI


F20240824072233




BLK:19,SNR1:-0.18164E-01,SNR2: 1.2261




Frequency (Hz)





T20240824072233




No.Good Data




KISO



No.Good Data



3C147 2024/08/23 22.40UT TOYOKAWA-KISO



F20240824072233





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C147 2024/08/23 22.40UT FUJI -KISO



T20240824073045





BLK:25,SNR1: 7.7170 ,SNR2: 10.872




Frequency (Hz)

F20240824073045




BLK:25,SNR1: 1.3351 ,SNR2: 2.5665




Frequency (Hz)


0548+16 2024/08/23 22.54UT TOYOKAWA-FUJI



T20240824073045




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0548+16 2024/08/23 22.54UT TOYOKAWA-KISO




F20240824073045




No.Good Data



KISO





No.Good Data




0548+16 2024/08/23 22.54UT FUJI -KISO



T20240824073455





BLK:10,SNR1: 0.11518 ,SNR2: 1.9689




Frequency (Hz)

F20240824073455




BLK:10,SNR1: 0.18719 ,SNR2: 1.2463




Frequency (Hz)

0552+12 2024/08/23 22.61UT TOYOKAWA-FUJI






T20240824073455





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0552+12 2024/08/23 22.61UT TOYOKAWA-KISO



F20240824073455



No.Good Data



KISO





No.Good Data




0552+12 2024/08/23 22.61UT FUJI -KISO



T20240824073922





BLK:34,SNR1: 0.45744 ,SNR2: 1.8820




Frequency (Hz)

F20240824073922




BLK:34,SNR1: 4.1013 ,SNR2: 17.629





Frequency (Hz)


0556+191 2024/08/23 22.68UT TOYOKAWA-FUJI



T20240824073922





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0556+191 2024/08/23 22.68UT TOYOKAWA-KISO





F20240824073922




No.Good Data



KISO





No.Good Data




0556+191 2024/08/23 22.68UT FUJI -KISO



T20240824074355





BLK:16,SNR1: 0.17016 ,SNR2: 0.99064




Frequency (Hz)

F20240824074355




BLK:16,SNR1: 2.1158 ,SNR2: 5.7221





Frequency (Hz)


3C152 2024/08/23 22.76UT TOYOKAWA-FUJI



T20240824074355



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C152 2024/08/23 22.76UT TOYOKAWA-KISO



F20240824074355



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

3C152 2024/08/23 22.76UT FUJI -KISO






T20240824080616





BLK:17,SNR1: 0.46368 ,SNR2: 4.2588




Frequency (Hz)

3C161 2024/08/23 23.13UT TOYOKAWA-FUJI


F20240824080616





BLK:17,SNR1: 8.6983 ,SNR2: 21.540




Frequency (Hz)



T20240824080616



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C161 2024/08/23 23.13UT TOYOKAWA-KISO



F20240824080616





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C161 2024/08/23 23.13UT FUJI -KISO





T20240824083349




BLK: 4,SNR1: 0.23819 ,SNR2: 2.7687




F20240824083349



BLK: 4,SNR1: 0.24513 ,SNR2: 2.0835




0652-130 2024/08/23 23.59UT TOYOKAWA-FUJI



T20240824083349



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0652-130 2024/08/23 23.59UT TOYOKAWA-KISO



F20240824083349




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2024/08/23 23.59UT FUJI -KISO



T20240824084525





BLK:12,SNR1: 38.441 ,SNR2: 63.034




Frequency (Hz)

F20240824084525




BLK:12,SNR1: 55.562 ,SNR2: 75.185





Frequency (Hz)


0703+138 2024/08/23 23.79UT TOYOKAWA-FUJI



T20240824084525



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

0703+138 2024/08/23 23.79UT TOYOKAWA-KISO






F20240824084525





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0703+138 2024/08/23 23.79UT FUJI -KISO



T20240824090500





BLK:17,SNR1: 0.87808 ,SNR2: 7.6008




Frequency (Hz)

0723+10 2024/08/24 0.11UT TOYOKAWA-FUJI


F20240824090500



BLK:17,SNR1: 1.3136 ,SNR2: 3.8099



Frequency (Hz)



T20240824090500



No.Good Data




KISO



No.Good Data




0723+10 2024/08/24 0.11UT TOYOKAWA-KISO





F20240824090500




No.Good Data




KISO





No.Good Data




0723+10 2024/08/24 0.11UT FUJI -KISO





T20240824091514




BLK:20,SNR1: 10.024 ,SNR2: 9.7150




F20240824091514



BLK:20,SNR1: 1.9969 ,SNR2: 4.2204



0732+33 2024/08/24 0.28UT TOYOKAWA-FUJI



T20240824091514



No. Good Data




KISO





No. Good Data




0732+33 2024/08/24 0.28UT TOYOKAWA-KISO




F20240824091514




No.Good Data




KISO





No.Good Data




0732+33 2024/08/24 0.28UT FUJI -KISO



T20240824092316





BLK:29,SNR1: 6.0719 ,SNR2: 5.7238




Frequency (Hz)

F20240824092316




BLK:29,SNR1: 7.1335 ,SNR2: 12.614




Frequency (Hz)

0741-06 2024/08/24 0.42UT TOYOKAWA-FUJI








T20240824092316




No.Good Data




KISO



No.Good Data



0741-06 2024/08/24 0.42UT TOYOKAWA-KISO



F20240824092316



No.Good Data




KISO





No.Good Data




0741-06 2024/08/24 0.42UT FUJI -KISO



T20240824093301





BLK:21,SNR1: 2.3085 ,SNR2: 10.386




Frequency (Hz)

F20240824093301




BLK:21,SNR1: 3.3684 ,SNR2: 10.339



Frequency (Hz)

0752-200 2024/08/24 0.58UT TOYOKAWA-FUJI





T20240824093301




No.Good Data




KISO



No.Good Data



0752-200 2024/08/24 0.58UT TOYOKAWA-KISO



F20240824093301




No.Good Data




KISO





No.Good Data




0752-200 2024/08/24 0.58UT FUJI -KISO





T20240824094036




BLK:34,SNR1: 6.3671 ,SNR2: 16.256




F20240824094036



BLK:34,SNR1: 593.61 ,SNR2: 700.60




3C190 2024/08/24 0.70UT TOYOKAWA-FUJI



T20240824094036




No. Good Data



KISO




No. Good Data



3C190 2024/08/24 0.70UT TOYOKAWA-KISO




F20240824094036




No.Good Data



KISO



No.Good Data




3C190 2024/08/24 0.70UT FUJI -KISO








T20240824095300




BLK: 9,SNR1: 0.40866 ,SNR2: 1.9082




F20240824095300



BLK: 9,SNR1: 0.49899E-01,SNR2: 1.0461



3C196 2024/08/24 0.91UT TOYOKAWA-FUJI




T20240824095300




No.Good Data



KISO



No.Good Data



3C196 2024/08/24 0.91UT TOYOKAWA-KISO





F20240824095300




No.Good Data



KISO




No.Good Data




3C196 2024/08/24 0.91UT FUJI -KISO





T20240824100410




BLK: 5,SNR1: 0.43064 ,SNR2: 2.8917




F20240824100410



BLK: 5,SNR1: 0.17602 ,SNR2: 1.3760



0821+394 2024/08/24 1.10UT TOYOKAWA-FUJI



T20240824100410



No. Good Data




KISO




No. Good Data



0821+394 2024/08/24 1.10UT TOYOKAWA-KISO




F20240824100410




No. Good Data




KISO





No. Good Data




0821+394 2024/08/24 1.10UT FUJI -KISO




T20240824101550




BLK:10,SNR1: 0.31058 ,SNR2: 3.0585




F20240824101550



BLK:10,SNR1: 2.2306 ,SNR2: 4.8948



0834-19 2024/08/24 1.29UT TOYOKAWA-FUJI




T20240824101550



No. Good Data



KISO



No. Good Data



0834-19 2024/08/24 1.29UT TOYOKAWA-KISO





F20240824101550



No. Good Data



KISO





No. Good Data




0834-19 2024/08/24 1.29UT FUJI -KISO



T20240824102055





BLK:13,SNR1: 1.2740 ,SNR2: 5.7478




Frequency (Hz)

F20240824102055




BLK:13,SNR1: 0.45384 ,SNR2: 4.5212



Frequency (Hz)

0839-071 2024/08/24 1.38UT TOYOKAWA-FUJI



T20240824102055




No. Good Data



KISO



No. Good Data



0839-071 2024/08/24 1.38UT TOYOKAWA-KISO





F20240824102055




No. Good Data



KISO




No. Good Data




0839-071 2024/08/24 1.38UT FUJI -KISO




T20240824103156




BLK:17,SNR1: 0.43780 ,SNR2: 1.7747




F20240824103156



BLK:17,SNR1: 3.1736 ,SNR2: 7.6567




3C208 2024/08/24 1.56UT TOYOKAWA-FUJI



T20240824103156





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C208 2024/08/24 1.56UT TOYOKAWA-KISO




F20240824103156




No. Good Data




KISO





No. Good Data




3C208 2024/08/24 1.56UT FUJI -KISO



T20240824104838





BLK: 6,SNR1: 0.21047 ,SNR2: 0.84238





3C216 2024/08/24 1.84UT TOYOKAWA-FUJI

F20240824104838



BLK: 6,SNR1: 0.15158 ,SNR2: 4.4962





T20240824104838



No. Good Data



Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C216 2024/08/24 1.84UT TOYOKAWA-KISO





F20240824104838




No. Good Data




KISO





No. Good Data




3C216 2024/08/24 1.84UT FUJI -KISO



T20240824110049




BLK: 1,SNR1:-0.11782 ,SNR2: 2.7777




Frequency (Hz)

0919-142 2024/08/24 2.04UT TOYOKAWA-FUJI


F20240824110049



BLK: 1,SNR1:-0.35068 ,SNR2: 0.51365




Frequency (Hz)



T20240824110049





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0919-142 2024/08/24 2.04UT TOYOKAWA-KISO



F20240824110049





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0919-142 2024/08/24 2.04UT FUJI -KISO





T20240824110728




BLK:35,SNR1: 21.534 ,SNR2: 30.586




F20240824110728



BLK:35,SNR1: 24.824 ,SNR2: 43.078




0926+117 2024/08/24 2.15UT TOYOKAWA-FUJI





T20240824110728




No. Good Data




KISO



No. Good Data




0926+117 2024/08/24 2.15UT TOYOKAWA-KISO



F20240824110728



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0926+117 2024/08/24 2.15UT FUJI -KISO







T20240824111513




BLK:20,SNR1: 1.4176 ,SNR2: 5.7731




F20240824111513



BLK:20,SNR1: 0.47981E-01,SNR2: 2.3048



3C222 2024/08/24 2.28UT TOYOKAWA-FUJI



T20240824111513



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C222 2024/08/24 2.28UT TOYOKAWA-KISO



F20240824111513



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C222 2024/08/24 2.28UT FUJI -KISO



T20240824112213




BLK:17,SNR1: 0.87069 ,SNR2: 3.7656





0941-08 2024/08/24 2.40UT TOYOKAWA-FUJI

F20240824112213



BLK:17,SNR1:-0.96047E-03,SNR2: 1.6317



T20240824112213





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0941-08 2024/08/24 2.40UT TOYOKAWA-KISO





F20240824112213




No.Good Data




KISO




No.Good Data




0941-08 2024/08/24 2.40UT FUJI -KISO




T20240824113035




BLK:23,SNR1: 27.234 ,SNR2: 86.593




F20240824113035



BLK:23,SNR1: 0.53496 ,SNR2: 1.8612




3C230 2024/08/24 2.54UT TOYOKAWA-FUJI



T20240824113035





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C230 2024/08/24 2.54UT TOYOKAWA-KISO





F20240824113035



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


3C230 2024/08/24 2.54UT FUJI -KISO




T20240824114635




BLK:36,SNR1: 42.766 ,SNR2: 81.123




F20240824114636



BLK:36,SNR1: 111.23 ,SNR2: 111.78



3C237 2024/08/24 2.80UT TOYOKAWA-FUJI



T20240824114635



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C237 2024/08/24 2.80UT TOYOKAWA-KISO



F20240824114636





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C237 2024/08/24 2.80UT FUJI -KISO




T20240824120033




BLK:20,SNR1: 10.103 ,SNR2: 26.315




F20240824120033



BLK:20,SNR1: 0.26835 ,SNR2: 1.0521



3C241 2024/08/24 3.04UT TOYOKAWA-FUJI



T20240824120033



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C241 2024/08/24 3.04UT TOYOKAWA-KISO



F20240824120033





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C241 2024/08/24 3.04UT FUJI -KISO




T20240824121202




BLK:27,SNR1: 7.1892 ,SNR2: 27.174




F20240824121202



BLK:27,SNR1: 0.45915 ,SNR2: 2.1203



1031-11 2024/08/24 3.23UT TOYOKAWA-FUJI





T20240824121202




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1031-11 2024/08/24 3.23UT TOYOKAWA-KISO





F20240824121202




No.Good Data




KISO





No.Good Data




1031-11 2024/08/24 3.23UT FUJI -KISO



T20240824121635




BLK:13,SNR1: 1.4930 ,SNR2: 6.6660





1035-058 2024/08/24 3.30UT TOYOKAWA-FUJI


F20240824121635



BLK:13,SNR1: 0.13214 ,SNR2: 1.2835



T20240824121635




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1035-058 2024/08/24 3.30UT TOYOKAWA-KISO



F20240824121635





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2024/08/24 3.30UT FUJI -KISO




T20240824122548




BLK: 7,SNR1: 0.10981 ,SNR2: 0.44552




F20240824122548




BLK: 7,SNR1: 0.55807 ,SNR2: 1.8056



1044-008 2024/08/24 3.46UT TOYOKAWA-FUJI



T20240824122548




No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1044-008 2024/08/24 3.46UT TOYOKAWA-KISO



F20240824122548





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

1044-008 2024/08/24 3.46UT FUJI -KISO







T20240824123646




BLK: 9,SNR1: 0.83934E-01,SNR2: 1.4282




F20240824123646



BLK: 9,SNR1: 0.39241 ,SNR2: 2.0399



1055+20 2024/08/24 3.64UT TOYOKAWA-FUJI



T20240824123646



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1055+20 2024/08/24 3.64UT TOYOKAWA-KISO



F20240824123646



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1055+20 2024/08/24 3.64UT FUJI -KISO




T20240824124810




BLK:12,SNR1: 1.0782 ,SNR2: 6.4013




F20240824124810



BLK:12,SNR1: 2.1392 ,SNR2: 3.7317



1107+109 2024/08/24 3.83UT TOYOKAWA-FUJI



T20240824124810





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

1107+109 2024/08/24 3.83UT TOYOKAWA-KISO



F20240824124810



No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


1107+109 2024/08/24 3.83UT FUJI -KISO





T20240824125853




BLK:17,SNR1: 1.0205 ,SNR2: 3.3847




F20240824125853



BLK:17,SNR1: 0.80064 ,SNR2: 0.75399



1117+14 2024/08/24 4.01UT TOYOKAWA-FUJI



T20240824125853



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1117+14 2024/08/24 4.01UT TOYOKAWA-KISO





F20240824125853





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


1117+14 2024/08/24 4.01UT FUJI -KISO





T20240824130825




BLK:12,SNR1: 0.22095 ,SNR2: 1.1890




F20240824130825



BLK:12,SNR1: 0.91584E-01,SNR2: 0.31218



1127-14 2024/08/24 4.17UT TOYOKAWA-FUJI



T20240824130825



No. Good Data



Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1127-14 2024/08/24 4.17UT TOYOKAWA-KISO





F20240824130825




No.Good Data




KISO





No.Good Data




1127-14 2024/08/24 4.17UT FUJI -KISO





T20240824132145




BLK:17,SNR1: 0.25480 ,SNR2: 2.4756




F20240824132145





BLK:17,SNR1: 0.30178 ,SNR2: 1.9259



3C263.1 2024/08/24 4.39UT TOYOKAWA-FUJI



T20240824132145





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C263.1 2024/08/24 4.39UT TOYOKAWA-KISO



F20240824132145





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C263.1 2024/08/24 4.39UT FUJI -KISO





T20240824132812




BLK:16,SNR1: 0.47053 ,SNR2: 2.2160




F20240824132812



BLK:16,SNR1: 0.90176E-01,SNR2: 0.87595





3C267 2024/08/24 4.50UT TOYOKAWA-FUJI






T20240824132812





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

3C267 2024/08/24 4.50UT TOYOKAWA-KISO



F20240824132812





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2024/08/24 4.50UT FUJI -KISO





T20240824135400




BLK: 6,SNR1: 0.96921E-02,SNR2: 1.4951




F20240824135400



BLK: 6,SNR1: 47.389 ,SNR2: 71.016



1213-17 2024/08/24 4.93UT TOYOKAWA-FUJI



T20240824135400





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

1213-17 2024/08/24 4.93UT TOYOKAWA-KISO



F20240824135400





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1213-17 2024/08/24 4.93UT FUJI -KISO



T20240824140717





BLK:15,SNR1: 10.242 ,SNR2: 36.563





3C273 2024/08/24 5.15UT TOYOKAWA-FUJI


F20240824140717




BLK:15,SNR1: 1.7308 ,SNR2: 3.0293



T20240824140717





KISO






3C273 2024/08/24 5.15UT TOYOKAWA-KISO




F20240824140717



KISO





3C273 2024/08/24 5.15UT FUJI -KISO








T20240824142028




BLK:12,SNR1: 0.25829 ,SNR2: 1.6100




F20240824142028



BLK:12,SNR1: 0.11730 ,SNR2: 0.91581



3C275 2024/08/24 5.37UT TOYOKAWA-FUJI



T20240824142028





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C275 2024/08/24 5.37UT TOYOKAWA-KISO




F20240824142028





KISO




3C275 2024/08/24 5.37UT FUJI -KISO





T20240824142633




BLK:13,SNR1: 0.29153 ,SNR2: 2.6220




F20240824142633






BLK:13,SNR1: 1.9754 ,SNR2: 1.8977






1245-19 2024/08/24 5.47UT TOYOKAWA-FUJI




T20240824142633



KISO



1245-19 2024/08/24 5.47UT TOYOKAWA-KISO





F20240824142633




No.Good Data




KISO





No.Good Data




1245-19 2024/08/24 5.47UT FUJI -KISO



T20240824143417




BLK:17,SNR1: 0.24997 ,SNR2: 2.4407




Frequency (Hz)

F20240824143417




BLK:17,SNR1: 1.0672 ,SNR2: 3.4154




Frequency (Hz)

3C279 2024/08/24 5.60UT TOYOKAWA-FUJI





T20240824143417




No.Good Data




KISO



No.Good Data





3C279 2024/08/24 5.60UT TOYOKAWA-KISO





F20240824143417





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C279 2024/08/24 5.60UT FUJI -KISO





T20240824144946




BLK:19,SNR1: 0.58742 ,SNR2: 5.2362




F20240824144946





BLK:19,SNR1: 1.2055 ,SNR2: 2.2748



3C283 2024/08/24 5.86UT TOYOKAWA-FUJI



T20240824144946





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C283 2024/08/24 5.86UT TOYOKAWA-KISO



F20240824144946





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C283 2024/08/24 5.86UT FUJI -KISO





T20240824150411




BLK:11,SNR1: 1.7077 ,SNR2: 8.2279




F20240824150411




BLK:11,SNR1: 1.7324 ,SNR2: 1.8394



1323+32 2024/08/24 6.10UT TOYOKAWA-FUJI



T20240824150411




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1323+32 2024/08/24 6.10UT TOYOKAWA-KISO



F20240824150411





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2024/08/24 6.10UT FUJI -KISO




T20240824150901




BLK:13,SNR1: 2.2263 ,SNR2: 5.6767




F20240824150901



BLK:13,SNR1: 0.46366 ,SNR2: 1.6097






3C286 2024/08/24 6.18UT TOYOKAWA-FUJI








T20240824150901






KISO






3C286 2024/08/24 6.18UT TOYOKAWA-KISO



F20240824150901




KISO





3C286 2024/08/24 6.18UT FUJI -KISO







BLK:21,SNR1: 8.3075 ,SNR2: 22.019





BLK:21,SNR1: 1.9855 ,SNR2: 2.5809




1345+12 2024/08/24 6.45UT TOYOKAWA-FUJI



T20240824152528





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1345+12 2024/08/24 6.45UT TOYOKAWA-KISO



F20240824152528





KISO




1345+12 2024/08/24 6.45UT FUJI -KISO





T20240824153549




BLK:26,SNR1: 8.1940 ,SNR2: 23.213




F20240824153549




BLK:26,SNR1: 1.7160 ,SNR2: 2.4812



1355+01 2024/08/24 6.63UT TOYOKAWA-FUJI



T20240824153549




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

1355+01 2024/08/24 6.63UT TOYOKAWA-KISO



F20240824153549




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

1355+01 2024/08/24 6.63UT FUJI -KISO








T20240824155659




BLK:23,SNR1: 3.2651 ,SNR2: 5.8161




F20240824155659





BLK:23,SNR1: 0.15599 ,SNR2: 2.6084




3C298 2024/08/24 6.98UT TOYOKAWA-FUJI



T20240824155659




No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C298 2024/08/24 6.98UT TOYOKAWA-KISO




F20240824155659





KISO




3C298 2024/08/24 6.98UT FUJI -KISO





T20240824160843




BLK:19,SNR1: 1.0656 ,SNR2: 2.7231




F20240824160843






BLK:19,SNR1: 0.90121E-01,SNR2: 1.0720






1428-03 2024/08/24 7.17UT TOYOKAWA-FUJI




T20240824160843






KISO






1428-03 2024/08/24 7.17UT TOYOKAWA-KISO




F20240824160843





KISO




1428-03 2024/08/24 7.17UT FUJI -KISO



T20240824161724





BLK:16,SNR1: 0.23016 ,SNR2: 0.91674




Frequency (Hz)

F20240824161725




BLK:16,SNR1: 6.1898 ,SNR2: 6.4113






Frequency (Hz)




1436-16 2024/08/24 7.32UT TOYOKAWA-FUJI




T20240824161724



KISO






1436-16 2024/08/24 7.32UT TOYOKAWA-KISO









F20240824161725




KISO




1436-16 2024/08/24 7.32UT FUJI -KISO



T20240824163347





BLK:24,SNR1: 3.2854 ,SNR2: 3.0971




Frequency (Hz)

F20240824163347




BLK:24,SNR1: 0.21617 ,SNR2: 1.9365






Frequency (Hz)




1453-10 2024/08/24 7.59UT TOYOKAWA-FUJI



T20240824163347






KISO






1453-10 2024/08/24 7.59UT TOYOKAWA-KISO




F20240824163347





KISO




1453-10 2024/08/24 7.59UT FUJI -KISO



T20240824164840





BLK:21,SNR1: 2.8515 ,SNR2: 12.673




Frequency (Hz)

F20240824164840




BLK:21,SNR1: 4.5388 ,SNR2: 6.0999






Frequency (Hz)




1508-05 2024/08/24 7.84UT TOYOKAWA-FUJI




T20240824164840





KISO






1508-05 2024/08/24 7.84UT TOYOKAWA-KISO




F20240824164840





KISO




1508-05 2024/08/24 7.84UT FUJI -KISO



T20240824165740





BLK:22,SNR1: 4.7165 ,SNR2: 13.497




Frequency (Hz)

F20240824165740




BLK:22,SNR1: 1.4365 ,SNR2: 9.7732





Frequency (Hz)

3C318 2024/08/24 7.99UT TOYOKAWA-FUJI









T20240824165740






KISO






3C318 2024/08/24 7.99UT TOYOKAWA-KISO




F20240824165740





KISO




3C318 2024/08/24 7.99UT FUJI -KISO



T20240824170327





BLK:18,SNR1: 0.40160 ,SNR2: 2.7855




Frequency (Hz)

F20240824170327




BLK:18,SNR1: 4.4274 ,SNR2: 4.3106




Frequency (Hz)


1523+03 2024/08/24 8.09UT TOYOKAWA-FUJI



T20240824170327





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1523+03 2024/08/24 8.09UT TOYOKAWA-KISO





F20240824170327




No.Good Data




KISO





No.Good Data




1523+03 2024/08/24 8.09UT FUJI -KISO



T20240824171506





BLK:16,SNR1: 0.46912 ,SNR2: 1.3156




Frequency (Hz)

F20240824171506




BLK:16,SNR1: 1.1530 ,SNR2: 3.3550




Frequency (Hz)


1535+139 2024/08/24 8.28UT TOYOKAWA-FUJI



T20240824171506




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1535+139 2024/08/24 8.28UT TOYOKAWA-KISO



F20240824171506





No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1535+139 2024/08/24 8.28UT FUJI -KISO

