



T20240825065644





BLK:11,SNR1: 0.36335 ,SNR2: 3.1610




Frequency (Hz)

3C138 2024/08/24 21.97UT TOYOKAWA-FUJI


F20240825065644





BLK:11,SNR1: 0.57472E-01,SNR2: 0.62580




Frequency (Hz)



T20240825065644




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C138 2024/08/24 21.97UT TOYOKAWA-KISO




F20240825065644



No.Good Data




KISO





No.Good Data




3C138 2024/08/24 21.97UT FUJI -KISO



T20240825071018





BLK:11,SNR1: 0.11763 ,SNR2: 0.83510




Frequency (Hz)

F20240825071018




BLK:11,SNR1: 0.92965E-02,SNR2: 0.30869



Frequency (Hz)

0531+194 2024/08/24 22.20UT TOYOKAWA-FUJI




T20240825071018



No.Good Data




KISO




No.Good Data



0531+194 2024/08/24 22.20UT TOYOKAWA-KISO




F20240825071018



No.Good Data



KISO




No.Good Data




0531+194 2024/08/24 22.20UT FUJI -KISO



T20240825071837




BLK:23,SNR1: 3.5741 ,SNR2: 13.201




Frequency (Hz)

3C147 2024/08/24 22.34UT TOYOKAWA-FUJI


F20240825071838




BLK:23,SNR1: 0.83600E-01,SNR2: 2.4873




Frequency (Hz)





T20240825071837




No.Good Data




KISO



No.Good Data



3C147 2024/08/24 22.34UT TOYOKAWA-KISO






F20240825071838





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C147 2024/08/24 22.34UT FUJI -KISO



T20240825072649





BLK: 9,SNR1: 0.13485 ,SNR2: 0.84915




Frequency (Hz)

F20240825072649




BLK: 9,SNR1: 0.77322 ,SNR2: 3.6216



Frequency (Hz)


0548+16 2024/08/24 22.48UT TOYOKAWA-FUJI



T20240825072649



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0548+16 2024/08/24 22.48UT TOYOKAWA-KISO



F20240825072649




No.Good Data




KISO





No.Good Data




0548+16 2024/08/24 22.48UT FUJI -KISO



T20240825073100





BLK:17,SNR1: 2.9242 ,SNR2: 13.349




Frequency (Hz)

0552+12 2024/08/24 22.54UT TOYOKAWA-FUJI


F20240825073100



BLK:17,SNR1: 14.293 ,SNR2: 29.752




Frequency (Hz)



T20240825073100





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0552+12 2024/08/24 22.54UT TOYOKAWA-KISO



F20240825073100




No.Good Data



KISO





No.Good Data




0552+12 2024/08/24 22.54UT FUJI -KISO



T20240825073526





BLK:11,SNR1: 0.32287E-03,SNR2: 0.95914




Frequency (Hz)

F20240825073526




BLK:11,SNR1: 1.0776 ,SNR2: 8.4480




Frequency (Hz)

0556+191 2024/08/24 22.62UT TOYOKAWA-FUJI







T20240825073526




No.Good Data




KISO



No.Good Data



0556+191 2024/08/24 22.62UT TOYOKAWA-KISO



F20240825073526



No.Good Data




KISO





No.Good Data




0556+191 2024/08/24 22.62UT FUJI -KISO



T20240825073959





BLK:16,SNR1: 10.993 ,SNR2: 18.727




Frequency (Hz)

3C152 2024/08/24 22.69UT TOYOKAWA-FUJI


F20240825073959



BLK:16,SNR1: 6.9926 ,SNR2: 12.674



Frequency (Hz)



T20240825073959



No.Good Data



KISO




No.Good Data




3C152 2024/08/24 22.69UT TOYOKAWA-KISO




F20240825073959




No.Good Data



KISO





No.Good Data




3C152 2024/08/24 22.69UT FUJI -KISO



T20240825080220





BLK:23,SNR1: 8.1107 ,SNR2: 20.574




Frequency (Hz)

3C161 2024/08/24 23.07UT TOYOKAWA-FUJI


F20240825080221



BLK:23,SNR1: 7.4881 ,SNR2: 19.815



Frequency (Hz)



T20240825080220



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

3C161 2024/08/24 23.07UT TOYOKAWA-KISO





F20240825080221




No.Good Data



KISO



No.Good Data





3C161 2024/08/24 23.07UT FUJI -KISO






T20240825082953





BLK:11,SNR1: 0.28909 ,SNR2: 2.4975




Frequency (Hz)

F20240825082953




BLK:11,SNR1: 0.30965 ,SNR2: 3.7566



Frequency (Hz)


0652-130 2024/08/24 23.53UT TOYOKAWA-FUJI



T20240825082953




No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0652-130 2024/08/24 23.53UT TOYOKAWA-KISO



F20240825082953





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0652-130 2024/08/24 23.53UT FUJI -KISO



T20240825084129





BLK:11,SNR1: 13.289 ,SNR2: 23.654




Frequency (Hz)

F20240825084129




BLK:11,SNR1: 2.0226 ,SNR2: 8.9767



Frequency (Hz)

0703+138 2024/08/24 23.72UT TOYOKAWA-FUJI



T20240825084129



No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

0703+138 2024/08/24 23.72UT TOYOKAWA-KISO



F20240825084129





No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0703+138 2024/08/24 23.72UT FUJI -KISO



T20240825085052





BLK:19,SNR1: 0.21628 ,SNR2: 1.1644




Frequency (Hz)

F20240825085052




BLK:19,SNR1: 9.0791 ,SNR2: 22.396




Frequency (Hz)


0713-024 2024/08/24 23.88UT TOYOKAWA-FUJI



T20240825085052




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

0713-024 2024/08/24 23.88UT TOYOKAWA-KISO






F20240825085052





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0713-024 2024/08/24 23.88UT FUJI -KISO



T20240825090104





BLK:17,SNR1: 4.0456 ,SNR2: 13.035




Frequency (Hz)

F20240825090104




BLK:17,SNR1: 4.3725 ,SNR2: 11.735



Frequency (Hz)

0723+10 2024/08/25 0.05UT TOYOKAWA-FUJI



T20240825090104



No.Good Data




KISO



No.Good Data



0723+10 2024/08/25 0.05UT TOYOKAWA-KISO





F20240825090104




No.Good Data




KISO





No.Good Data




0723+10 2024/08/25 0.05UT FUJI -KISO



T20240825091119





BLK:26,SNR1: 2.5746 ,SNR2: 12.134




Frequency (Hz)

0732+33 2024/08/25 0.22UT TOYOKAWA-FUJI


F20240825091119



BLK:26,SNR1: 6.9097 ,SNR2: 17.228



Frequency (Hz)



T20240825091119



No. Good Data




KISO





No. Good Data




0732+33 2024/08/25 0.22UT TOYOKAWA-KISO




F20240825091119




No. Good Data




KISO




No. Good Data




0732+33 2024/08/25 0.22UT FUJI -KISO




T20240825091921




BLK:13,SNR1: 1.7935 ,SNR2: 5.0591




F20240825091921



BLK:13,SNR1: 2.7600 ,SNR2: 6.1861



0741-06 2024/08/25 0.35UT TOYOKAWA-FUJI






T20240825091921





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

0741-06 2024/08/25 0.35UT TOYOKAWA-KISO



F20240825091921



No.Good Data




KISO




No.Good Data




0741-06 2024/08/25 0.35UT FUJI -KISO



T20240825092905




BLK: 5,SNR1:-0.28762E-01,SNR2: 0.92772





0752-200 2024/08/25 0.51UT TOYOKAWA-FUJI


F20240825092905




BLK: 5,SNR1:-0.13212E-01,SNR2: 0.63172




T20240825092905




No.Good Data




KISO



No.Good Data



0752-200 2024/08/25 0.51UT TOYOKAWA-KISO





F20240825092905




No.Good Data




KISO





No.Good Data




0752-200 2024/08/25 0.51UT FUJI -KISO





T20240825093640




BLK:11,SNR1: 0.17019 ,SNR2: 2.4408




F20240825093640



BLK:11,SNR1: 0.52998 ,SNR2: 2.2810



3C190 2024/08/25 0.64UT TOYOKAWA-FUJI



T20240825093640



No.Good Data



KISO




No.Good Data



3C190 2024/08/25 0.64UT TOYOKAWA-KISO




F20240825093640




No.Good Data



KISO



No.Good Data





3C190 2024/08/25 0.64UT FUJI -KISO






T20240825094904




BLK: 9,SNR1: 0.18833 ,SNR2: 3.2314




Frequency (Hz)

3C196 2024/08/25 0.85UT TOYOKAWA-FUJI


F20240825094904



BLK: 9,SNR1: 0.54629 ,SNR2: 7.0086



Frequency (Hz)



T20240825094904



No.Good Data




Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

3C196 2024/08/25 0.85UT TOYOKAWA-KISO



F20240825094904





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C196 2024/08/25 0.85UT FUJI -KISO




T20240825100014




BLK: 4,SNR1: 0.16200 ,SNR2: 1.4914




F20240825100014



BLK: 4,SNR1: 0.73967 ,SNR2: 6.4197



0821+394 2024/08/25 1.03UT TOYOKAWA-FUJI





T20240825100014




No. Good Data




KISO




No. Good Data



0821+394 2024/08/25 1.03UT TOYOKAWA-KISO




F20240825100014




No. Good Data




KISO





No. Good Data




0821+394 2024/08/25 1.03UT FUJI -KISO





T20240825101154




BLK: 5,SNR1: 0.61411 ,SNR2: 6.7994




F20240825101154



BLK: 5,SNR1: 0.24564 ,SNR2: 5.0896




0834-19 2024/08/25 1.23UT TOYOKAWA-FUJI



T20240825101154



No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

0834-19 2024/08/25 1.23UT TOYOKAWA-KISO








F20240825101154




No. Good Data




KISO




No. Good Data




0834-19 2024/08/25 1.23UT FUJI -KISO



T20240825101659




BLK:15,SNR1: 2.2381 ,SNR2: 9.5009




Frequency (Hz)

F20240825101659




BLK:15,SNR1: 5.1502 ,SNR2: 9.7391



Frequency (Hz)

0839-071 2024/08/25 1.31UT TOYOKAWA-FUJI



T20240825101659



No. Good Data




Frequency (Hz)

KISO



No. Good Data



Frequency (Hz)


0839-071 2024/08/25 1.31UT TOYOKAWA-KISO





F20240825101659




No. Good Data




KISO





No. Good Data




0839-071 2024/08/25 1.31UT FUJI -KISO




T20240825102800




BLK: 4,SNR1: 0.27010 ,SNR2: 2.6913




F20240825102800




BLK: 4,SNR1:-0.86487E-01,SNR2: 1.0185




3C208 2024/08/25 1.49UT TOYOKAWA-FUJI



T20240825102800





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)

3C208 2024/08/25 1.49UT TOYOKAWA-KISO




F20240825102800




No. Good Data



KISO





No. Good Data




3C208 2024/08/25 1.49UT FUJI -KISO



T20240825104442





BLK: 8, SNR1: 6.1940 , SNR2: 11.712




Frequency (Hz)

3C216 2024/08/25 1.77UT TOYOKAWA-FUJI


F20240825104442



BLK: 8, SNR1: 0.83673 , SNR2: 2.6882



Frequency (Hz)





T20240825104442



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

3C216 2024/08/25 1.77UT TOYOKAWA-KISO



F20240825104442





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C216 2024/08/25 1.77UT FUJI -KISO



T20240825105653




BLK: 2,SNR1: 0.51982 ,SNR2: 1.5028




0919-142 2024/08/25 1.98UT TOYOKAWA-FUJI


F20240825105653



BLK: 2,SNR1: 0.84003 ,SNR2: 3.5247



Frequency (Hz)



T20240825105653





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

0919-142 2024/08/25 1.98UT TOYOKAWA-KISO



F20240825105653





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0919-142 2024/08/25 1.98UT FUJI -KISO



T20240825110332




BLK:25,SNR1: 76.160 ,SNR2: 188.47





0926+117 2024/08/25 2.09UT TOYOKAWA-FUJI

F20240825110332




BLK:25,SNR1: 4.6632 ,SNR2: 17.384





T20240825110332




No. Good Data




KISO





No. Good Data




0926+117 2024/08/25 2.09UT TOYOKAWA-KISO



F20240825110332



No. Good Data




Frequency (Hz)

KISO




No. Good Data




Frequency (Hz)

0926+117 2024/08/25 2.09UT FUJI -KISO







T20240825111117




BLK:15,SNR1: 2.4334 ,SNR2: 12.337




F20240825111117



BLK:15,SNR1: 0.16857 ,SNR2: 2.0221



3C222 2024/08/25 2.22UT TOYOKAWA-FUJI



T20240825111117



No. Good Data



Frequency (Hz)

KISO



No. Good Data



Frequency (Hz)

3C222 2024/08/25 2.22UT TOYOKAWA-KISO



F20240825111117



No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C222 2024/08/25 2.22UT FUJI -KISO



T20240825111817




BLK:10,SNR1: 0.61546 ,SNR2: 3.2594




0941-08 2024/08/25 2.33UT TOYOKAWA-FUJI


F20240825111817



BLK:10,SNR1: 0.17109 ,SNR2: 1.5476




Frequency (Hz)



T20240825111817



No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


0941-08 2024/08/25 2.33UT TOYOKAWA-KISO



F20240825111817




No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0941-08 2024/08/25 2.33UT FUJI -KISO




T20240825112639




BLK:16,SNR1: 2.9786 ,SNR2: 16.313




F20240825112639



BLK:16,SNR1: 0.56410 ,SNR2: 1.5147



3C230 2024/08/25 2.47UT TOYOKAWA-FUJI





T20240825112639




No. Good Data




KISO



No. Good Data





3C230 2024/08/25 2.47UT TOYOKAWA-KISO






F20240825112639





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C230 2024/08/25 2.47UT FUJI -KISO





T20240825114239




BLK:28,SNR1: 1.8795 ,SNR2: 6.0911




F20240825114239



BLK:28,SNR1: 6.8068 ,SNR2: 10.385



3C237 2024/08/25 2.74UT TOYOKAWA-FUJI



T20240825114239





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

3C237 2024/08/25 2.74UT TOYOKAWA-KISO



F20240825114239





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C237 2024/08/25 2.74UT FUJI -KISO




T20240825115637




BLK:17,SNR1: 2.8030 ,SNR2: 6.0469




F20240825115637



BLK:17,SNR1: 0.17225 ,SNR2: 4.4547



3C241 2024/08/25 2.97UT TOYOKAWA-FUJI



T20240825115637



No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C241 2024/08/25 2.97UT TOYOKAWA-KISO





F20240825115637




No.Good Data




KISO





No.Good Data




3C241 2024/08/25 2.97UT FUJI -KISO




T20240825120806




BLK:11,SNR1: 0.69883 ,SNR2: 3.1204




F20240825120806



BLK:11,SNR1:-0.16645E-01,SNR2: 1.4591



1031-11 2024/08/25 3.16UT TOYOKAWA-FUJI





T20240825120806





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1031-11 2024/08/25 3.16UT TOYOKAWA-KISO



F20240825120806





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1031-11 2024/08/25 3.16UT FUJI -KISO



T20240825121239





BLK:14,SNR1: 9.9253 ,SNR2: 62.758





1035-058 2024/08/25 3.24UT TOYOKAWA-FUJI


F20240825121239



BLK:14,SNR1: 2.7084 ,SNR2: 5.2680



T20240825121239




No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


1035-058 2024/08/25 3.24UT TOYOKAWA-KISO



F20240825121239




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1035-058 2024/08/25 3.24UT FUJI -KISO





T20240825122152




BLK: 7,SNR1:-0.70439E-01,SNR2: 0.38857




F20240825122152



BLK: 7,SNR1: 0.53134 ,SNR2: 2.4134



1044-008 2024/08/25 3.39UT TOYOKAWA-FUJI



T20240825122152



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1044-008 2024/08/25 3.39UT TOYOKAWA-KISO



F20240825122152





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

1044-008 2024/08/25 3.39UT FUJI -KISO







T20240825123251




BLK: 8,SNR1: 5.8669 ,SNR2: 5.7257




F20240825123251



BLK: 8,SNR1:-0.23318 ,SNR2: 0.73923



1055+20 2024/08/25 3.58UT TOYOKAWA-FUJI



T20240825123251



No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)


1055+20 2024/08/25 3.58UT TOYOKAWA-KISO



F20240825123251





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


1055+20 2024/08/25 3.58UT FUJI -KISO




T20240825124414




BLK:21,SNR1: 1.0525 ,SNR2: 6.4269




F20240825124415



BLK:21,SNR1: 23.824 ,SNR2: 51.532



1107+109 2024/08/25 3.77UT TOYOKAWA-FUJI



T20240825124414



No.Good Data



Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1107+109 2024/08/25 3.77UT TOYOKAWA-KISO



F20240825124415



No. Good Data




Frequency (Hz)

KISO



No. Good Data




Frequency (Hz)


1107+109 2024/08/25 3.77UT FUJI -KISO





T20240825125457




BLK:12,SNR1: 2.2633 ,SNR2: 14.997




F20240825125457





BLK:12,SNR1: 0.25274 ,SNR2: 1.3649




1117+14 2024/08/25 3.94UT TOYOKAWA-FUJI



T20240825125457





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)

1117+14 2024/08/25 3.94UT TOYOKAWA-KISO







F20240825125457




No.Good Data




KISO





No.Good Data




1117+14 2024/08/25 3.94UT FUJI -KISO




T20240825130429




BLK:10,SNR1: 0.88474 ,SNR2: 1.6742




F20240825130429





BLK:10,SNR1: 0.47270 ,SNR2: 1.4850




1127-14 2024/08/25 4.10UT TOYOKAWA-FUJI



T20240825130429





No. Good Data




Frequency (Hz)

KISO




No. Good Data



Frequency (Hz)


1127-14 2024/08/25 4.10UT TOYOKAWA-KISO



F20240825130429



No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1127-14 2024/08/25 4.10UT FUJI -KISO




T20240825131750




BLK:16,SNR1: 0.61099 ,SNR2: 3.9066




F20240825131750





BLK:16,SNR1:-0.38851E-01,SNR2: 1.4284



3C263.1 2024/08/25 4.33UT TOYOKAWA-FUJI



T20240825131750





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C263.1 2024/08/25 4.33UT TOYOKAWA-KISO



F20240825131750





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C263.1 2024/08/25 4.33UT FUJI -KISO





T20240825132416




BLK: 8,SNR1: 1.1216 ,SNR2: 2.9568




F20240825132416



BLK: 8,SNR1: 0.96676 ,SNR2: 2.0774





3C267 2024/08/25 4.43UT TOYOKAWA-FUJI






T20240825132416





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C267 2024/08/25 4.43UT TOYOKAWA-KISO



F20240825132416





No.Good Data



Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C267 2024/08/25 4.43UT FUJI -KISO





T20240825135004




BLK:10,SNR1: 0.29056 ,SNR2: 2.1460




F20240825135004




BLK:10,SNR1: 0.48067 ,SNR2: 6.5461



1213-17 2024/08/25 4.86UT TOYOKAWA-FUJI



T20240825135004




No. Good Data




Frequency (Hz)

KISO



No. Good Data



Frequency (Hz)

1213-17 2024/08/25 4.86UT TOYOKAWA-KISO



F20240825135004



No. Good Data



Frequency (Hz)

KISO



No. Good Data





Frequency (Hz)


1213-17 2024/08/25 4.86UT FUJI -KISO





T20240825140322




BLK:14,SNR1: 1.6367 ,SNR2: 4.3479




F20240825140322




BLK:14,SNR1: 0.54532 ,SNR2: 2.8087




3C273 2024/08/25 5.08UT TOYOKAWA-FUJI



T20240825140322




KISO




3C273 2024/08/25 5.08UT TOYOKAWA-KISO



F20240825140322





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)

3C273 2024/08/25 5.08UT FUJI -KISO







T20240825141632




BLK:19,SNR1: 0.65298 ,SNR2: 2.9562




F20240825141632





BLK:19,SNR1: 0.92307 ,SNR2: 4.8805




3C275 2024/08/25 5.30UT TOYOKAWA-FUJI



T20240825141632





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

3C275 2024/08/25 5.30UT TOYOKAWA-KISO





F20240825141632




No.Good Data




KISO




No.Good Data




3C275 2024/08/25 5.30UT FUJI -KISO




T20240825142237




BLK: 7,SNR1: 0.35464 ,SNR2: 3.0544




F20240825142237




BLK: 7,SNR1: 2.2357 ,SNR2: 4.7104



1245-19 2024/08/25 5.41UT TOYOKAWA-FUJI



T20240825142237





No.Good Data



Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1245-19 2024/08/25 5.41UT TOYOKAWA-KISO



F20240825142237



No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)


1245-19 2024/08/25 5.41UT FUJI -KISO





T20240825143021




BLK: 4,SNR1: 0.22904 ,SNR2: 1.8124




F20240825143021




BLK: 4,SNR1: 1.3418 ,SNR2: 3.4982



3C279 2024/08/25 5.53UT TOYOKAWA-FUJI



T20240825143021




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

3C279 2024/08/25 5.53UT TOYOKAWA-KISO





F20240825143021




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)

3C279 2024/08/25 5.53UT FUJI -KISO








BLK: 8,SNR1: 54.287 ,SNR2: 120.08




3C283 2024/08/25 5.79UT TOYOKAWA-FUJI



BLK: 8,SNR1: 121.63 ,SNR2: 129.95



T20240825144550




No.Good Data



Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


3C283 2024/08/25 5.79UT TOYOKAWA-KISO



F20240825144550




No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C283 2024/08/25 5.79UT FUJI -KISO





T20240825150015




BLK:28,SNR1: 8.6954 ,SNR2: 21.797




F20240825150015






BLK:28,SNR1: 7.3784 ,SNR2: 21.282






1323+32 2024/08/25 6.03UT TOYOKAWA-FUJI




T20240825150015





KISO




1323+32 2024/08/25 6.03UT TOYOKAWA-KISO



F20240825150015





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1323+32 2024/08/25 6.03UT FUJI -KISO



T20240825150505





BLK:19,SNR1: 2.9075 ,SNR2: 12.935




Frequency (Hz)

F20240825150505




BLK:19,SNR1: 0.34345 ,SNR2: 1.6370






Frequency (Hz)

3C286 2024/08/25 6.11UT TOYOKAWA-FUJI








T20240825150505





KISO




3C286 2024/08/25 6.11UT TOYOKAWA-KISO



F20240825150505





No.Good Data




Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)


3C286 2024/08/25 6.11UT FUJI -KISO





T20240825152132




BLK:21,SNR1: 0.37620 ,SNR2: 1.5179




F20240825152132





BLK:21,SNR1: 6.0834 ,SNR2: 7.9227




1345+12 2024/08/25 6.39UT TOYOKAWA-FUJI



T20240825152132





No. Good Data




Frequency (Hz)

KISO




No. Good Data






Frequency (Hz)




1345+12 2024/08/25 6.39UT TOYOKAWA-KISO




F20240825152132





KISO




1345+12 2024/08/25 6.39UT FUJI -KISO



T20240825153153




BLK: 9,SNR1: 0.15945 ,SNR2: 0.74575




Frequency (Hz)

F20240825153153




BLK: 9,SNR1: 0.77726 ,SNR2: 1.7761




Frequency (Hz)

1355+01 2024/08/25 6.56UT TOYOKAWA-FUJI



T20240825153153




No.Good Data



Frequency (Hz)

KISO



No.Good Data




Frequency (Hz)

1355+01 2024/08/25 6.56UT TOYOKAWA-KISO



F20240825153153




No.Good Data



Frequency (Hz)

KISO



No.Good Data





Frequency (Hz)

1355+01 2024/08/25 6.56UT FUJI -KISO







T20240825155303




BLK: 9,SNR1: 0.57583 ,SNR2: 2.8348




F20240825155303






BLK: 9,SNR1: 0.77470 ,SNR2: 0.82556






3C298 2024/08/25 6.91UT TOYOKAWA-FUJI




T20240825155303






KISO






3C298 2024/08/25 6.91UT TOYOKAWA-KISO




F20240825155303





KISO




3C298 2024/08/25 6.91UT FUJI -KISO



T20240825160447





BLK: 7,SNR1: 0.32763E-01,SNR2: 0.62102




Frequency (Hz)

F20240825160447




BLK: 7,SNR1: 1.0096 ,SNR2: 4.2426






Frequency (Hz)




1428-03 2024/08/25 7.11UT TOYOKAWA-FUJI




T20240825160447






KISO






1428-03 2024/08/25 7.11UT TOYOKAWA-KISO




F20240825160447





KISO




1428-03 2024/08/25 7.11UT FUJI -KISO



T20240825161328




BLK:10,SNR1: 0.30015 ,SNR2: 2.5271




Frequency (Hz)

F20240825161328




BLK:10,SNR1: 0.63669 ,SNR2: 4.0323






Frequency (Hz)




1436-16 2024/08/25 7.25UT TOYOKAWA-FUJI




T20240825161328



KISO






1436-16 2024/08/25 7.25UT TOYOKAWA-KISO








F20240825161328





KISO




1436-16 2024/08/25 7.25UT FUJI -KISO



T20240825162951




BLK: 9,SNR1: 0.87073 ,SNR2: 3.8469




Frequency (Hz)

F20240825162951




BLK: 9,SNR1: 1.7785 ,SNR2: 5.1376






Frequency (Hz)




1453-10 2024/08/25 7.53UT TOYOKAWA-FUJI



T20240825162951





KISO





1453-10 2024/08/25 7.53UT TOYOKAWA-KISO




F20240825162951





KISO




1453-10 2024/08/25 7.53UT FUJI -KISO



T20240825164444




BLK:18,SNR1: 20.949 ,SNR2: 38.299




Frequency (Hz)

F20240825164444




BLK:18,SNR1: 3.9455 ,SNR2: 10.133






Frequency (Hz)

1508-05 2024/08/25 7.77UT TOYOKAWA-FUJI






T20240825164444




No.Good Data

KISO




No.Good Data


1508-05 2024/08/25 7.77UT TOYOKAWA-KISO





F20240825164444




No.Good Data




KISO





No.Good Data




1508-05 2024/08/25 7.77UT FUJI -KISO




T20240825165344




BLK: 9,SNR1: 0.16069 ,SNR2: 1.8400




F20240825165344



BLK: 9,SNR1:-0.21961 ,SNR2: 0.85019





3C318 2024/08/25 7.92UT TOYOKAWA-FUJI






T20240825165344





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C318 2024/08/25 7.92UT TOYOKAWA-KISO




F20240825165344





KISO




3C318 2024/08/25 7.92UT FUJI -KISO



T20240825165931





BLK:23,SNR1: 8.1686 ,SNR2: 20.223




Frequency (Hz)

F20240825165931




BLK:23,SNR1: 7.6057 ,SNR2: 13.621




Frequency (Hz)


1523+03 2024/08/25 8.02UT TOYOKAWA-FUJI



T20240825165931





No.Good Data




Frequency (Hz)

KISO




No.Good Data



Frequency (Hz)


1523+03 2024/08/25 8.02UT TOYOKAWA-KISO



F20240825165931




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1523+03 2024/08/25 8.02UT FUJI -KISO



T20240825171110





BLK:28,SNR1: 4.8110 ,SNR2: 10.983




Frequency (Hz)

F20240825171110




BLK:28,SNR1: 6.9286 ,SNR2: 15.243





Frequency (Hz)


1535+139 2024/08/25 8.21UT TOYOKAWA-FUJI



T20240825171110





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1535+139 2024/08/25 8.21UT TOYOKAWA-KISO



F20240825171110





No.Good Data




Frequency (Hz)

KISO



No.Good Data



Frequency (Hz)

1535+139 2024/08/25 8.21UT FUJI -KISO

