




T20240901062216





No.Good Data




Frequency (Hz)

F20240901062216




No.Good Data





Frequency (Hz)


0510+387 2024/08/31 21.40UT TOYOKAWA-FUJI





T20240901062216




No. Good Data




K20240901062215



No. Good Data





0510+387 2024/08/31 21.40UT TOYOKAWA-KISO






F20240901062216





BLK:12,SNR1: 10.532 ,SNR2: 25.096




Frequency (Hz)

K20240901062215




BLK:12,SNR1: 13.576 ,SNR2: 33.686





Frequency (Hz)


0510+387 2024/08/31 21.40UT FUJI -KISO



T20240901062913





No.Good Data




Frequency (Hz)

F20240901062913




No.Good Data





Frequency (Hz)


3C138 2024/08/31 21.52UT TOYOKAWA-FUJI





T20240901062913




No.Good Data




K20240901062912





No.Good Data




3C138 2024/08/31 21.52UT TOYOKAWA-KISO



F20240901062913





BLK: 5,SNR1: 1.2847 ,SNR2: 3.5677




Frequency (Hz)

3C138 2024/08/31 21.52UT FUJI -KISO


K20240901062912





BLK: 5,SNR1: 2.4638 ,SNR2: 4.7277




Frequency (Hz)





T20240901063415




No. Good Data




F20240901063415





No. Good Data




0523+116 2024/08/31 21.60UT TOYOKAWA-FUJI





T20240901063415




No.Good Data




K20240901063414




No.Good Data




0523+116 2024/08/31 21.60UT TOYOKAWA-KISO





F20240901063415




BLK: 8,SNR1: 5.3246 ,SNR2: 14.101




K20240901063414





BLK: 8,SNR1: 7.3216 ,SNR2: 20.641




0523+116 2024/08/31 21.60UT FUJI -KISO



T20240901064247





No.Good Data




Frequency (Hz)

F20240901064247




No.Good Data





Frequency (Hz)

0531+194 2024/08/31 21.74UT TOYOKAWA-FUJI







T20240901064247




No.Good Data




K20240901064246





No.Good Data




0531+194 2024/08/31 21.74UT TOYOKAWA-KISO



F20240901064247





BLK:17,SNR1: 6.4840 ,SNR2: 12.025




Frequency (Hz)

K20240901064246




BLK:17,SNR1: 4.1500 ,SNR2: 16.755





Frequency (Hz)


0531+194 2024/08/31 21.74UT FUJI -KISO



T20240901065106




No.Good Data




Frequency (Hz)

3C147 2024/08/31 21.88UT TOYOKAWA-FUJI


F20240901065106





No.Good Data




Frequency (Hz)



T20240901065106





No.Good Data




Frequency (Hz)

K20240901065105




No.Good Data





Frequency (Hz)


3C147 2024/08/31 21.88UT TOYOKAWA-KISO



F20240901065106





BLK:13,SNR1: 0.51123 ,SNR2: 1.2168




Frequency (Hz)

3C147 2024/08/31 21.88UT FUJI -KISO


K20240901065105





BLK:13,SNR1: 0.48483 ,SNR2: 2.2626




Frequency (Hz)



T20240901065918




No.Good Data




Frequency (Hz)

F20240901065918




No.Good Data





Frequency (Hz)


0548+16 2024/08/31 22.02UT TOYOKAWA-FUJI



T20240901065918




No.Good Data




Frequency (Hz)

K20240901065917




No.Good Data





Frequency (Hz)


0548+16 2024/08/31 22.02UT TOYOKAWA-KISO



F20240901065918




BLK: 6,SNR1: 2.9666 ,SNR2: 9.0300




Frequency (Hz)

K20240901065917




BLK: 6,SNR1: 1.2949 ,SNR2: 2.8310





Frequency (Hz)

0548+16 2024/08/31 22.02UT FUJI -KISO






T20240901070328




No.Good Data




Frequency (Hz)

F20240901070328




No.Good Data





Frequency (Hz)


0552+12 2024/08/31 22.09UT TOYOKAWA-FUJI



T20240901070328





No.Good Data




Frequency (Hz)

K20240901070327




No.Good Data





Frequency (Hz)


0552+12 2024/08/31 22.09UT TOYOKAWA-KISO



F20240901070328





BLK: 5,SNR1: 3.3685 ,SNR2: 9.4984




Frequency (Hz)

K20240901070327




BLK: 5,SNR1: 1.6987 ,SNR2: 6.3592





Frequency (Hz)


0552+12 2024/08/31 22.09UT FUJI -KISO





T20240901070755




No.Good Data




F20240901070755





No.Good Data




0556+191 2024/08/31 22.16UT TOYOKAWA-FUJI





T20240901070755




No.Good Data




K20240901070754





No.Good Data




0556+191 2024/08/31 22.16UT TOYOKAWA-KISO



F20240901070755





BLK:11,SNR1: 3.9909 ,SNR2: 16.745




Frequency (Hz)

K20240901070754




BLK:11,SNR1: 6.5055 ,SNR2: 16.244





Frequency (Hz)


0556+191 2024/08/31 22.16UT FUJI -KISO



T20240901071228





No.Good Data




Frequency (Hz)

F20240901071228




No.Good Data





Frequency (Hz)


3C152 2024/08/31 22.24UT TOYOKAWA-FUJI





T20240901071228




No.Good Data




K20240901071227



No.Good Data





3C152 2024/08/31 22.24UT TOYOKAWA-KISO






F20240901071228





BLK: 5,SNR1: 0.56336E-01,SNR2: 0.60859




Frequency (Hz)

3C152 2024/08/31 22.24UT FUJI -KISO


K20240901071227





BLK: 5,SNR1: 0.13990 ,SNR2: 2.7872




Frequency (Hz)





T20240901073449




No.Good Data




F20240901073449





No.Good Data




3C161 2024/08/31 22.61UT TOYOKAWA-FUJI



T20240901073449





No.Good Data




Frequency (Hz)

3C161 2024/08/31 22.61UT TOYOKAWA-KISO


K20240901073448




No.Good Data




Frequency (Hz)



F20240901073449





BLK: 5,SNR1: 1.0434 ,SNR2: 7.0221




Frequency (Hz)

3C161 2024/08/31 22.61UT FUJI -KISO


K20240901073448





BLK: 5,SNR1: 0.26155 ,SNR2: 1.8417




Frequency (Hz)





T20240901080222




No.Good Data




F20240901080222





No.Good Data




0652-130 2024/08/31 23.07UT TOYOKAWA-FUJI





T20240901080222




No.Good Data




K20240901080221




No.Good Data




0652-130 2024/08/31 23.07UT TOYOKAWA-KISO



F20240901080222





BLK: 8,SNR1: 1.2555 ,SNR2: 4.0122




Frequency (Hz)

K20240901080221




BLK: 8,SNR1: 10.401 ,SNR2: 32.073





Frequency (Hz)


0652-130 2024/08/31 23.07UT FUJI -KISO



T20240901081358





No. Good Data




Frequency (Hz)

F20240901081358




No. Good Data





Frequency (Hz)

0703+138 2024/08/31 23.26UT TOYOKAWA-FUJI






T20240901081358





No.Good Data




Frequency (Hz)

K20240901081357




No.Good Data




Frequency (Hz)


0703+138 2024/08/31 23.26UT TOYOKAWA-KISO



F20240901081358





BLK: 8,SNR1: 1.0451 ,SNR2: 2.2513




Frequency (Hz)

K20240901081357




BLK: 8,SNR1: 0.94748 ,SNR2: 3.7687





Frequency (Hz)


0703+138 2024/08/31 23.26UT FUJI -KISO



T20240901082321





No.Good Data




Frequency (Hz)

F20240901082321




No.Good Data





Frequency (Hz)


0713-024 2024/08/31 23.42UT TOYOKAWA-FUJI





T20240901082321




No. Good Data




K20240901082320





No. Good Data




0713-024 2024/08/31 23.42UT TOYOKAWA-KISO





F20240901082321




BLK: 9,SNR1: 0.30173 ,SNR2: 2.0961




K20240901082320





BLK: 9,SNR1: 2.6303 ,SNR2: 6.4273




0713-024 2024/08/31 23.42UT FUJI -KISO




T20240901083333




No. Good Data




F20240901083333





No. Good Data




0723+10 2024/08/31 23.59UT TOYOKAWA-FUJI




T20240901083333




No. Good Data




K20240901083332





No. Good Data




0723+10 2024/08/31 23.59UT TOYOKAWA-KISO



F20240901083333





BLK:10,SNR1: 0.88823 ,SNR2: 2.8333




Frequency (Hz)

K20240901083332




BLK:10,SNR1: 0.83724 ,SNR2: 2.5510





Frequency (Hz)

0723+10 2024/08/31 23.59UT FUJI -KISO






T20240901084347





No.Good Data




Frequency (Hz)

F20240901084347




No.Good Data





Frequency (Hz)


0732+33 2024/08/31 23.76UT TOYOKAWA-FUJI





T20240901084347




No. Good Data




K20240901084346





No. Good Data




0732+33 2024/08/31 23.76UT TOYOKAWA-KISO



F20240901084347





BLK: 7,SNR1: 0.10264 ,SNR2: 3.5556




Frequency (Hz)

K20240901084346




BLK: 7,SNR1: 0.65415 ,SNR2: 2.9206





Frequency (Hz)


0732+33 2024/08/31 23.76UT FUJI -KISO





T20240901085149




No. Good Data




F20240901085149





No. Good Data




0741-06 2024/08/31 23.89UT TOYOKAWA-FUJI



T20240901085149




No.Good Data




Frequency (Hz)

K20240901085148




No.Good Data




Frequency (Hz)


0741-06 2024/08/31 23.89UT TOYOKAWA-KISO





F20240901085149




BLK: 8,SNR1: 0.65117E-01,SNR2: 1.1859




K20240901085148





BLK: 8,SNR1: 0.65673 ,SNR2: 2.7853




0741-06 2024/08/31 23.89UT FUJI -KISO





T20240901090134




No. Good Data




F20240901090134





No. Good Data




0752-200 2024/09/01 0.05UT TOYOKAWA-FUJI



T20240901090134





No. Good Data




Frequency (Hz)

K20240901090133




No. Good Data





Frequency (Hz)

0752-200 2024/09/01 0.05UT TOYOKAWA-KISO







F20240901090134




BLK: 4,SNR1: 0.48653 ,SNR2: 2.1065




K20240901090133





BLK: 4,SNR1: 0.21149 ,SNR2: 0.72954




0752-200 2024/09/01 0.05UT FUJI -KISO





T20240901090908




No. Good Data




F20240901090908





No. Good Data




3C190 2024/09/01 0.18UT TOYOKAWA-FUJI



T20240901090908





No. Good Data




Frequency (Hz)

3C190 2024/09/01 0.18UT TOYOKAWA-KISO


K20240901090907





No. Good Data




Frequency (Hz)



F20240901090908





BLK: 5,SNR1: 2.2557 ,SNR2: 3.3247




Frequency (Hz)

3C190 2024/09/01 0.18UT FUJI -KISO


K20240901090907





BLK: 5,SNR1: 0.70238 ,SNR2: 2.5234




Frequency (Hz)





T20240901092133




No. Good Data




F20240901092133





No. Good Data




3C196 2024/09/01 0.39UT TOYOKAWA-FUJI



T20240901092133





No. Good Data




Frequency (Hz)

3C196 2024/09/01 0.39UT TOYOKAWA-KISO


K20240901092132




No. Good Data




Frequency (Hz)



F20240901092133





BLK:11,SNR1: 0.63996 ,SNR2: 1.8594





3C196 2024/09/01 0.39UT FUJI -KISO



K20240901092132




BLK:11,SNR1: 0.58635 ,SNR2: 1.3004





T20240901093243




No. Good Data




F20240901093243



No. Good Data





0821+394 2024/09/01 0.57UT TOYOKAWA-FUJI








T20240901093243




No. Good Data




K20240901093242




No. Good Data




0821+394 2024/09/01 0.57UT TOYOKAWA-KISO




F20240901093243




BLK: 5,SNR1: 0.68912 ,SNR2: 2.2843




K20240901093242





BLK: 5,SNR1: 0.14896 ,SNR2: 1.1619




0821+394 2024/09/01 0.57UT FUJI -KISO





T20240901094423




No. Good Data




F20240901094423





No. Good Data




0834-19 2024/09/01 0.77UT TOYOKAWA-FUJI




T20240901094423




No. Good Data




K20240901094422





No. Good Data




0834-19 2024/09/01 0.77UT TOYOKAWA-KISO





F20240901094423




BLK: 3,SNR1: 0.22188 ,SNR2: 0.64942




K20240901094422





BLK: 3,SNR1: 0.44274 ,SNR2: 2.6002




0834-19 2024/09/01 0.77UT FUJI -KISO





T20240901094928




No. Good Data




F20240901094928





No. Good Data




0839-071 2024/09/01 0.85UT TOYOKAWA-FUJI



T20240901094928





No. Good Data




Frequency (Hz)

K20240901094927




No. Good Data




Frequency (Hz)


0839-071 2024/09/01 0.85UT TOYOKAWA-KISO



F20240901094928




BLK: 3,SNR1: 0.34233 ,SNR2: 1.6143




Frequency (Hz)

K20240901094927




BLK: 3,SNR1: 1.2884 ,SNR2: 6.2711





Frequency (Hz)

0839-071 2024/09/01 0.85UT FUJI -KISO







T20240901100029




No. Good Data




F20240901100029




No. Good Data




3C208 2024/09/01 1.04UT TOYOKAWA-FUJI



T20240901100029




No. Good Data




Frequency (Hz)

K20240901100028




No. Good Data




Frequency (Hz)


3C208 2024/09/01 1.04UT TOYOKAWA-KISO



F20240901100029




BLK: 6,SNR1: 0.57053 ,SNR2: 1.8402





3C208 2024/09/01 1.04UT FUJI -KISO



K20240901100028




BLK: 6,SNR1: 0.26186 ,SNR2: 2.4154





T20240901101710




No. Good Data




F20240901101710





No. Good Data




3C216 2024/09/01 1.31UT TOYOKAWA-FUJI





T20240901101710




No. Good Data




K20240901101709




No. Good Data




3C216 2024/09/01 1.31UT TOYOKAWA-KISO




F20240901101710




BLK: 6,SNR1: 0.45879 ,SNR2: 2.2780




K20240901101709





BLK: 6,SNR1: 0.20901 ,SNR2: 0.93175




3C216 2024/09/01 1.31UT FUJI -KISO



T20240901102922





No. Good Data




Frequency (Hz)

0919-142 2024/09/01 1.52UT TOYOKAWA-FUJI


F20240901102922





No. Good Data




Frequency (Hz)



T20240901102922





No. Good Data




Frequency (Hz)

K20240901102921




No. Good Data




Frequency (Hz)

0919-142 2024/09/01 1.52UT TOYOKAWA-KISO








F20240901102922




BLK: 1,SNR1:-0.50029E-01,SNR2: 0.49360




K20240901102921





BLK: 1,SNR1: 0.74688 ,SNR2: 3.9719




0919-142 2024/09/01 1.52UT FUJI -KISO



T20240901103601





No. Good Data




Frequency (Hz)

F20240901103601




No. Good Data





Frequency (Hz)


0926+117 2024/09/01 1.63UT TOYOKAWA-FUJI



T20240901103601





No. Good Data




Frequency (Hz)

K20240901103600




No. Good Data




Frequency (Hz)


0926+117 2024/09/01 1.63UT TOYOKAWA-KISO





F20240901103601




BLK: 4,SNR1: 2.2738 ,SNR2: 10.509




K20240901103600





BLK: 4,SNR1: 1.3791 ,SNR2: 4.0697




0926+117 2024/09/01 1.63UT FUJI -KISO



T20240901104346





No. Good Data




Frequency (Hz)

F20240901104346




No. Good Data





Frequency (Hz)


3C222 2024/09/01 1.76UT TOYOKAWA-FUJI





T20240901104346




No. Good Data




K20240901104345




No. Good Data




3C222 2024/09/01 1.76UT TOYOKAWA-KISO





F20240901104346




BLK:14,SNR1: 1.7962 ,SNR2: 6.0476




K20240901104345





BLK:14,SNR1: 1.3675 ,SNR2: 3.8238




3C222 2024/09/01 1.76UT FUJI -KISO



T20240901105046





No. Good Data




Frequency (Hz)

F20240901105046




No. Good Data





Frequency (Hz)

0941-08 2024/09/01 1.87UT TOYOKAWA-FUJI






T20240901105046




No. Good Data




Frequency (Hz)

K20240901105045




No. Good Data




Frequency (Hz)


0941-08 2024/09/01 1.87UT TOYOKAWA-KISO



F20240901105046




BLK: 3,SNR1: 0.89282 ,SNR2: 8.2822





0941-08 2024/09/01 1.87UT FUJI -KISO



K20240901105045




BLK: 3,SNR1: 0.71145E-01,SNR2: 0.79874



T20240901105907





No.Good Data




Frequency (Hz)

F20240901105907




No.Good Data





Frequency (Hz)


3C230 2024/09/01 2.01UT TOYOKAWA-FUJI



T20240901105907





No. Good Data




Frequency (Hz)

K20240901105906




No. Good Data





Frequency (Hz)


3C230 2024/09/01 2.01UT TOYOKAWA-KISO




F20240901105907




BLK:13,SNR1: 0.37022 ,SNR2: 1.4249




K20240901105906





BLK:13,SNR1: 0.27392 ,SNR2: 3.1820




3C230 2024/09/01 2.01UT FUJI -KISO



T20240901111315





No. Good Data




Frequency (Hz)

F20240901111316




No. Good Data





Frequency (Hz)


3C236 2024/09/01 2.25UT TOYOKAWA-FUJI



T20240901111315




No. Good Data




Frequency (Hz)

K20240901111314




No. Good Data





Frequency (Hz)


3C236 2024/09/01 2.25UT TOYOKAWA-KISO



F20240901111316




BLK:11,SNR1: 0.78022 ,SNR2: 2.0121





3C236 2024/09/01 2.25UT FUJI -KISO

K20240901111314





BLK:11,SNR1: 0.41815 ,SNR2: 3.5747






T20240901112124





No. Good Data




Frequency (Hz)

F20240901112124




No. Good Data





Frequency (Hz)


1011+110 2024/09/01 2.38UT TOYOKAWA-FUJI




T20240901112124




No. Good Data




K20240901112123





No. Good Data




1011+110 2024/09/01 2.38UT TOYOKAWA-KISO





F20240901112124




BLK: 7,SNR1: 0.39920 ,SNR2: 1.0522




K20240901112123





BLK: 7,SNR1: 0.64008 ,SNR2: 4.0411




1011+110 2024/09/01 2.38UT FUJI -KISO



T20240901112905




No. Good Data




Frequency (Hz)

F20240901112905




No. Good Data





Frequency (Hz)


3C241 2024/09/01 2.51UT TOYOKAWA-FUJI





T20240901112905




No. Good Data




K20240901112904




No. Good Data




3C241 2024/09/01 2.51UT TOYOKAWA-KISO





F20240901112905




BLK:14,SNR1: 1.3039 ,SNR2: 2.4231




K20240901112904





BLK:14,SNR1: 1.3852 ,SNR2: 2.6938




3C241 2024/09/01 2.51UT FUJI -KISO



T20240901114035





No. Good Data




Frequency (Hz)

F20240901114035




No. Good Data





Frequency (Hz)


1031-11 2024/09/01 2.70UT TOYOKAWA-FUJI





T20240901114035




No. Good Data




K20240901114034



No. Good Data




1031-11 2024/09/01 2.70UT TOYOKAWA-KISO







F20240901114035




BLK: 4,SNR1: 0.45153 ,SNR2: 3.6137




K20240901114034





BLK: 4,SNR1: 7.0146 ,SNR2: 17.600




1031-11 2024/09/01 2.70UT FUJI -KISO





T20240901114508




No.Good Data




F20240901114508





No.Good Data




1035-058 2024/09/01 2.78UT TOYOKAWA-FUJI





T20240901114508




No.Good Data




K20240901114507




No.Good Data




1035-058 2024/09/01 2.78UT TOYOKAWA-KISO





F20240901114508




BLK: 6,SNR1: 0.10314 ,SNR2: 1.9782




K20240901114507





BLK: 6,SNR1: 1.0220 ,SNR2: 1.8290




1035-058 2024/09/01 2.78UT FUJI -KISO




T20240901115421




No. Good Data




F20240901115422





No. Good Data




1044-008 2024/09/01 2.93UT TOYOKAWA-FUJI




T20240901115421




No.Good Data




K20240901115420




No.Good Data




1044-008 2024/09/01 2.93UT TOYOKAWA-KISO





F20240901115422




BLK: 5,SNR1: 0.66380 ,SNR2: 2.3196




K20240901115420





BLK: 5,SNR1: 0.10249 ,SNR2: 0.42696




1044-008 2024/09/01 2.93UT FUJI -KISO



T20240901120525





No.Good Data




Frequency (Hz)

F20240901120525




No.Good Data





Frequency (Hz)

1055+01 2024/09/01 3.12UT TOYOKAWA-FUJI






T20240901120525





No. Good Data




Frequency (Hz)

K20240901120524




No. Good Data





Frequency (Hz)


1055+01 2024/09/01 3.12UT TOYOKAWA-KISO





F20240901120525




BLK:11,SNR1: 32.301 ,SNR2: 31.997




K20240901120524





BLK:11,SNR1: 19.474 ,SNR2: 33.801






1055+01 2024/09/01 3.12UT FUJI -KISO




T20240901121643





F20240901121644




1107+109 2024/09/01 3.31UT TOYOKAWA-FUJI



T20240901121643





No.Good Data




Frequency (Hz)

K20240901121642




No.Good Data





Frequency (Hz)


1107+109 2024/09/01 3.31UT TOYOKAWA-KISO





F20240901121644




BLK: 9,SNR1:-0.78559E-01,SNR2: 0.42973




K20240901121642





BLK: 9,SNR1: 0.24476 ,SNR2: 2.9786






1107+109 2024/09/01 3.31UT FUJI -KISO




T20240901122725






F20240901122725






1117+14 2024/09/01 3.49UT TOYOKAWA-FUJI




T20240901122725





K20240901122724




1117+14 2024/09/01 3.49UT TOYOKAWA-KISO



F20240901122725





BLK:22,SNR1: 7.2037 ,SNR2: 14.587





1117+14 2024/09/01 3.49UT FUJI -KISO

K20240901122724






BLK:22,SNR1: 9.7650 ,SNR2: 25.339









T20240901123658





F20240901123658




1127-14 2024/09/01 3.64UT TOYOKAWA-FUJI




T20240901123658




No.Good Data




K20240901123657




No.Good Data




1127-14 2024/09/01 3.64UT TOYOKAWA-KISO




F20240901123658




BLK: 7,SNR1: 11.343 ,SNR2: 33.267




K20240901123657





BLK: 7,SNR1: 14.981 ,SNR2: 36.784




1127-14 2024/09/01 3.64UT FUJI -KISO





T20240901125018




No.Good Data




F20240901125018






No.Good Data






3C263.1 2024/09/01 3.87UT TOYOKAWA-FUJI




T20240901125018





K20240901125017




3C263.1 2024/09/01 3.87UT TOYOKAWA-KISO





F20240901125018




BLK:17,SNR1: 0.93958 ,SNR2: 4.5941




K20240901125017






BLK:17,SNR1: 3.1912 ,SNR2: 14.403






3C263.1 2024/09/01 3.87UT FUJI -KISO




T20240901125645






F20240901125646






3C267 2024/09/01 3.97UT TOYOKAWA-FUJI




T20240901125645



K20240901125644





3C267 2024/09/01 3.97UT TOYOKAWA-KISO








F20240901125646




BLK: 9,SNR1: 6.6685 ,SNR2: 18.080




K20240901125644





BLK: 9,SNR1: 10.229 ,SNR2: 29.598






3C267 2024/09/01 3.97UT FUJI -KISO




T20240901132233





F20240901132234






1213-17 2024/09/01 4.40UT TOYOKAWA-FUJI




T20240901132233





K20240901132232




1213-17 2024/09/01 4.40UT TOYOKAWA-KISO





F20240901132234




BLK: 9,SNR1: 7.6779 ,SNR2: 23.258




K20240901132232






BLK: 9,SNR1: 7.0268 ,SNR2: 20.956





1213-17 2024/09/01 4.40UT FUJI -KISO




T20240901133550




F20240901133550




3C273 2024/09/01 4.63UT TOYOKAWA-FUJI




T20240901133550




No.Good Data




K20240901133549




No.Good Data




3C273 2024/09/01 4.63UT TOYOKAWA-KISO





F20240901133550




BLK:29,SNR1: 0.14675 ,SNR2: 0.84402




K20240901133549





BLK:29,SNR1: 0.61527 ,SNR2: 4.3836






3C273 2024/09/01 4.63UT FUJI -KISO




T20240901134901



F20240901134901





3C275 2024/09/01 4.85UT TOYOKAWA-FUJI








T20240901134901





K20240901134900




3C275 2024/09/01 4.85UT TOYOKAWA-KISO




F20240901134901




BLK: 4,SNR1: 0.12573 ,SNR2: 1.4388




K20240901134900






BLK: 4,SNR1: 0.44515 ,SNR2: 2.1357





3C275 2024/09/01 4.85UT FUJI -KISO




T20240901135506





F20240901135507






1245-19 2024/09/01 4.95UT TOYOKAWA-FUJI




T20240901135506




K20240901135505




1245-19 2024/09/01 4.95UT TOYOKAWA-KISO



F20240901135507




BLK: 3,SNR1: 18.172 ,SNR2: 24.266





1245-19 2024/09/01 4.95UT FUJI -KISO



K20240901135505




BLK: 3,SNR1: 0.32978 ,SNR2: 4.6175




T20240901140250




No.Good Data




F20240901140250





No.Good Data




3C279 2024/09/01 5.08UT TOYOKAWA-FUJI





T20240901140250




No.Good Data




K20240901140249





No.Good Data




3C279 2024/09/01 5.08UT TOYOKAWA-KISO





F20240901140250




BLK: 9,SNR1: 0.72721 ,SNR2: 3.0669




K20240901140249



BLK: 9,SNR1: 4.6891 ,SNR2: 12.230





3C279 2024/09/01 5.08UT FUJI -KISO









T20240901141819





F20240901141820






3C283 2024/09/01 5.33UT TOYOKAWA-FUJI




T20240901141819




K20240901141818




3C283 2024/09/01 5.33UT TOYOKAWA-KISO





F20240901141820




BLK: 7,SNR1: 17.623 ,SNR2: 42.306




K20240901141818






BLK: 7,SNR1: 9.9667 ,SNR2: 26.536






3C283 2024/09/01 5.33UT FUJI -KISO




T20240901143244




F20240901143244




1323+32 2024/09/01 5.57UT TOYOKAWA-FUJI





T20240901143244




No.Good Data




K20240901143243





No.Good Data




1323+32 2024/09/01 5.57UT TOYOKAWA-KISO



F20240901143244





BLK: 7,SNR1: 11.957 ,SNR2: 29.397





1323+32 2024/09/01 5.57UT FUJI -KISO



K20240901143243




BLK: 7,SNR1: 7.1159 ,SNR2: 18.308





T20240901143734




No.Good Data




F20240901143734





No.Good Data






3C286 2024/09/01 5.65UT TOYOKAWA-FUJI




T20240901143734



K20240901143733





3C286 2024/09/01 5.65UT TOYOKAWA-KISO







F20240901143734




BLK:17,SNR1: 1.1624 ,SNR2: 3.7186




K20240901143733





BLK:17,SNR1: 3.8095 ,SNR2: 10.470






3C286 2024/09/01 5.65UT FUJI -KISO




T20240901145401




F20240901145402




1345+12 2024/09/01 5.93UT TOYOKAWA-FUJI





T20240901145401




No.Good Data




K20240901145400





No.Good Data




1345+12 2024/09/01 5.93UT TOYOKAWA-KISO





F20240901145402




BLK:12,SNR1: 14.792 ,SNR2: 36.840




K20240901145400






BLK:12,SNR1: 10.193 ,SNR2: 24.204






1345+12 2024/09/01 5.93UT FUJI -KISO




T20240901150421




F20240901150421




1355+01 2024/09/01 6.10UT TOYOKAWA-FUJI




T20240901150421




No.Good Data




K20240901150420





No.Good Data




1355+01 2024/09/01 6.10UT TOYOKAWA-KISO



F20240901150421




BLK: 8,SNR1: 13.679 ,SNR2: 32.989




Frequency (Hz)

K20240901150420




BLK: 8,SNR1: 17.709 ,SNR2: 41.950




Frequency (Hz)


1355+01 2024/09/01 6.10UT FUJI -KISO





T20240901152532




No.Good Data




F20240901152532



No.Good Data





3C298 2024/09/01 6.45UT TOYOKAWA-FUJI









T20240901152532




K20240901152531





3C298 2024/09/01 6.45UT TOYOKAWA-KISO







BLK: 8,SNR1: 9.5576 ,SNR2: 23.132





BLK: 8,SNR1: 9.3838 ,SNR2: 23.472





3C298 2024/09/01 6.45UT FUJI -KISO




T20240901153716




F20240901153716




1428-03 2024/09/01 6.65UT TOYOKAWA-FUJI





T20240901153716




No.Good Data




K20240901153715




No.Good Data




1428-03 2024/09/01 6.65UT TOYOKAWA-KISO



F20240901153716




BLK: 9,SNR1: 23.614 ,SNR2: 27.108




Frequency (Hz)

K20240901153715




BLK: 9,SNR1: 20.204 ,SNR2: 24.780





Frequency (Hz)


1428-03 2024/09/01 6.65UT FUJI -KISO



T20240901154557




No.Good Data




Frequency (Hz)

F20240901154557




No.Good Data





Frequency (Hz)


1436-16 2024/09/01 6.79UT TOYOKAWA-FUJI



T20240901154557




No.Good Data




Frequency (Hz)

K20240901154556




No.Good Data




Frequency (Hz)


1436-16 2024/09/01 6.79UT TOYOKAWA-KISO





F20240901154557




BLK: 6,SNR1: 9.3711 ,SNR2: 22.469




K20240901154556



BLK: 6,SNR1: 6.7585 ,SNR2: 19.349





1436-16 2024/09/01 6.79UT FUJI -KISO






T20240901160220




No.Good Data




Frequency (Hz)

F20240901160220




No.Good Data




Frequency (Hz)


1453-10 2024/09/01 7.07UT TOYOKAWA-FUJI





T20240901160220




No.Good Data




K20240901160219





No.Good Data




1453-10 2024/09/01 7.07UT TOYOKAWA-KISO



F20240901160220





BLK: 6,SNR1: 1.0284 ,SNR2: 2.2073




Frequency (Hz)

K20240901160219




BLK: 6,SNR1: 1.3434 ,SNR2: 4.9797





Frequency (Hz)



1453-10 2024/09/01 7.07UT FUJI -KISO




T20240901161712





F20240901161712




1508-05 2024/09/01 7.31UT TOYOKAWA-FUJI




T20240901161712




No.Good Data




K20240901161711





No.Good Data




1508-05 2024/09/01 7.31UT TOYOKAWA-KISO



F20240901161712




BLK: 1,SNR1: 0.98428E-01,SNR2: 1.1162




Frequency (Hz)

K20240901161711




BLK: 1,SNR1: 0.40572 ,SNR2: 2.3928





Frequency (Hz)


1508-05 2024/09/01 7.31UT FUJI -KISO



T20240901162612





No.Good Data




Frequency (Hz)

F20240901162612




No.Good Data





Frequency (Hz)


3C318 2024/09/01 7.46UT TOYOKAWA-FUJI



T20240901162612




No.Good Data




Frequency (Hz)

K20240901162611




No.Good Data





Frequency (Hz)

3C318 2024/09/01 7.46UT TOYOKAWA-KISO






F20240901162612





BLK: 6,SNR1: 1.5523 ,SNR2: 4.1285




Frequency (Hz)

K20240901162611




BLK: 6,SNR1: 1.1637 ,SNR2: 3.0086





Frequency (Hz)


3C318 2024/09/01 7.46UT FUJI -KISO



T20240901163159





No.Good Data




Frequency (Hz)

F20240901163159




No.Good Data





Frequency (Hz)


1523+03 2024/09/01 7.56UT TOYOKAWA-FUJI



T20240901163159





No.Good Data




Frequency (Hz)

K20240901163158




No.Good Data





Frequency (Hz)


1523+03 2024/09/01 7.56UT TOYOKAWA-KISO



F20240901163159





BLK:10,SNR1: 1.4505 ,SNR2: 3.5354




Frequency (Hz)

K20240901163158




BLK:10,SNR1: 4.5306 ,SNR2: 11.133





Frequency (Hz)


1523+03 2024/09/01 7.56UT FUJI -KISO



T20240901164339





No.Good Data




Frequency (Hz)

F20240901164339




No.Good Data





Frequency (Hz)


1535+139 2024/09/01 7.76UT TOYOKAWA-FUJI



T20240901164339





No.Good Data




Frequency (Hz)

K20240901164338




No.Good Data





Frequency (Hz)


1535+139 2024/09/01 7.76UT TOYOKAWA-KISO



F20240901164339





BLK: 4, SNR1: 1.9069 , SNR2: 5.8806




Frequency (Hz)

K20240901164338




BLK: 4, SNR1: 0.21375 , SNR2: 1.9621





Frequency (Hz)


1535+139 2024/09/01 7.76UT FUJI -KISO



T20240901165403





No.Good Data




Frequency (Hz)

F20240901165403




No.Good Data





Frequency (Hz)

1545-12 2024/09/01 7.93UT TOYOKAWA-FUJI






T20240901165403




No.Good Data




Frequency (Hz)

K20240901165402




No.Good Data




Frequency (Hz)


1545-12 2024/09/01 7.93UT TOYOKAWA-KISO



F20240901165403





BLK: 3,SNR1:-0.25718 ,SNR2: 0.26060




Frequency (Hz)

K20240901165402




BLK: 3,SNR1:-0.68823E-01,SNR2: 0.46554





Frequency (Hz)


1545-12 2024/09/01 7.93UT FUJI -KISO



T20240901171506





No.Good Data




Frequency (Hz)

F20240901171506




No.Good Data





Frequency (Hz)


1607+26 2024/09/01 8.28UT TOYOKAWA-FUJI



T20240901171506




No.Good Data




Frequency (Hz)

K20240901171505




No.Good Data




Frequency (Hz)


1607+26 2024/09/01 8.28UT TOYOKAWA-KISO



F20240901171506





BLK: 5, SNR1: -0.12866 , SNR2: 0.78769




Frequency (Hz)

K20240901171505



BLK: 5, SNR1: 0.41150 , SNR2: 2.0817



Frequency (Hz)

1607+26 2024/09/01 8.28UT FUJI -KISO

