






T20240903062625




BLK: 8,SNR1: 9.4653 ,SNR2: 16.316




F20240903062624





BLK: 8,SNR1: 11.455 ,SNR2: 33.951




0523+116 2024/09/02 21.47UT TOYOKAWA-FUJI



T20240903062625





BLK:11,SNR1: 5.7595 ,SNR2: 21.298





0523+116 2024/09/02 21.47UT TOYOKAWA-KISO

K20240903062623





BLK:11,SNR1: 2.2598 ,SNR2: 5.5719






F20240903062624





BLK:10,SNR1: 13.358 ,SNR2: 39.394




Frequency (Hz)

K20240903062623




BLK:10,SNR1: 0.44977 ,SNR2: 4.6336





Frequency (Hz)


0523+116 2024/09/02 21.47UT FUJI -KISO



T20240903063456





BLK:10,SNR1: 5.7246 ,SNR2: 21.976





0531+194 2024/09/02 21.61UT TOYOKAWA-FUJI



F20240903063455




BLK:10,SNR1: 0.85276 ,SNR2: 2.8644



T20240903063456





BLK: 9,SNR1: 4.6623 ,SNR2: 15.815





0531+194 2024/09/02 21.61UT TOYOKAWA-KISO


K20240903063454




BLK: 9,SNR1: 1.7900 ,SNR2: 3.3105



F20240903063455




BLK: 4,SNR1: 0.69472 ,SNR2: 2.1407




Frequency (Hz)

K20240903063454




BLK: 4,SNR1: 0.66064 ,SNR2: 2.9937




Frequency (Hz)


0531+194 2024/09/02 21.61UT FUJI -KISO



T20240903064315




BLK: 8,SNR1: 3.0132 ,SNR2: 9.3165




Frequency (Hz)

3C147 2024/09/02 21.75UT TOYOKAWA-FUJI


F20240903064314




BLK: 8,SNR1: 0.17865 ,SNR2: 1.0009




Frequency (Hz)



T20240903064315




BLK:20,SNR1: 3.8143 ,SNR2: 16.653




Frequency (Hz)

3C147 2024/09/02 21.75UT TOYOKAWA-KISO


K20240903064313




BLK:20,SNR1: 2.4317 ,SNR2: 4.7735




Frequency (Hz)



F20240903064314





BLK:20,SNR1: 0.36492 ,SNR2: 1.6655




Frequency (Hz)

3C147 2024/09/02 21.75UT FUJI -KISO


K20240903064313







BLK:20,SNR1: 1.4939 ,SNR2: 3.8358




Frequency (Hz)










0548+16 2024/09/02 21.89UT TOYOKAWA-FUJI










0548+16 2024/09/02 21.89UT TOYOKAWA-KISO



F20240903065126





BLK:18,SNR1: 3.7901 ,SNR2: 9.2113




Frequency (Hz)

K20240903065125




BLK:18,SNR1: 4.4608 ,SNR2: 11.852




Frequency (Hz)


0548+16 2024/09/02 21.89UT FUJI -KISO



T20240903065537




BLK:11,SNR1: 5.2632 ,SNR2: 19.082




Frequency (Hz)

F20240903065537




BLK:11,SNR1: 0.54772 ,SNR2: 1.2954




Frequency (Hz)


0552+12 2024/09/02 21.95UT TOYOKAWA-FUJI



T20240903065537





BLK:10,SNR1: 4.0575 ,SNR2: 17.512




Frequency (Hz)

K20240903065535




BLK:10,SNR1: 0.11883 ,SNR2: 0.49920




Frequency (Hz)


0552+12 2024/09/02 21.95UT TOYOKAWA-KISO



F20240903065537





BLK: 4,SNR1: 0.35821 ,SNR2: 1.2467




Frequency (Hz)

K20240903065535








BLK: 4,SNR1: 0.49720E-02,SNR2: 0.68733




Frequency (Hz)





0552+12 2024/09/02 21.95UT FUJI -KISO






0556+191 2024/09/02 22.03UT TOYOKAWA-FUJI







0556+191 2024/09/02 22.03UT TOYOKAWA-KISO



F20240903070003




BLK: 3,SNR1: 3.6066 ,SNR2: 9.5956




Frequency (Hz)

K20240903070002




BLK: 3,SNR1: 3.6458 ,SNR2: 10.672





Frequency (Hz)

0556+191 2024/09/02 22.03UT FUJI -KISO






T20240903070437





BLK:11,SNR1: 5.7977 ,SNR2: 23.112




Frequency (Hz)

3C152 2024/09/02 22.10UT TOYOKAWA-FUJI


F20240903070436






BLK:11,SNR1: 2.2371 ,SNR2: 6.6663






Frequency (Hz)




T20240903070437





K20240903070435




3C152 2024/09/02 22.10UT TOYOKAWA-KISO



F20240903070436





BLK: 8,SNR1: 8.9567 ,SNR2: 21.251





3C152 2024/09/02 22.10UT FUJI -KISO



K20240903070435




BLK: 8,SNR1: 4.5972 ,SNR2: 11.857



T20240903072658





BLK:10,SNR1: 3.1645 ,SNR2: 10.743




Frequency (Hz)

3C161 2024/09/02 22.48UT TOYOKAWA-FUJI


F20240903072658





BLK:10,SNR1: 4.8145 ,SNR2: 12.951




Frequency (Hz)



T20240903072658




BLK:11,SNR1: 3.1632 ,SNR2: 13.662




Frequency (Hz)

K20240903072656




BLK:11,SNR1: 5.8210 ,SNR2: 14.883





Frequency (Hz)


3C161 2024/09/02 22.48UT TOYOKAWA-KISO





F20240903072658




BLK: 9,SNR1: 5.6461 ,SNR2: 15.107




K20240903072656





BLK: 9,SNR1: 3.9348 ,SNR2: 10.527




3C161 2024/09/02 22.48UT FUJI -KISO



T20240903075431





BLK: 6,SNR1: 5.6514 ,SNR2: 15.970




Frequency (Hz)

F20240903075430




BLK: 6,SNR1:-0.22789 ,SNR2: 0.85998E-02




Frequency (Hz)


0652-130 2024/09/02 22.94UT TOYOKAWA-FUJI



T20240903075431





BLK:13,SNR1: 8.4890 ,SNR2: 16.519





0652-130 2024/09/02 22.94UT TOYOKAWA-KISO

K20240903075429




BLK:13,SNR1: 0.22508 ,SNR2: 3.0597






F20240903075430




BLK: 2,SNR1:-0.13143 ,SNR2: 0.0000




Frequency (Hz)

K20240903075429




BLK: 2,SNR1:-0.62749E-01,SNR2: 0.72483




Frequency (Hz)


0652-130 2024/09/02 22.94UT FUJI -KISO



T20240903080607





BLK:16,SNR1: 5.3488 ,SNR2: 10.720




Frequency (Hz)

F20240903080606




BLK:16,SNR1: 9.0229 ,SNR2: 15.549




Frequency (Hz)


0703+138 2024/09/02 23.13UT TOYOKAWA-FUJI




T20240903080607




BLK:11,SNR1: 6.4845 ,SNR2: 12.629




K20240903080605





BLK:11,SNR1: 0.41726 ,SNR2: 1.8019




0703+138 2024/09/02 23.13UT TOYOKAWA-KISO



F20240903080606





BLK:10,SNR1: 14.448 ,SNR2: 22.201




Frequency (Hz)

K20240903080605




BLK:10,SNR1: 0.95564 ,SNR2: 2.8972





Frequency (Hz)


0703+138 2024/09/02 23.13UT FUJI -KISO



T20240903081530




BLK:12,SNR1: 3.6858 ,SNR2: 14.925




Frequency (Hz)

F20240903081529




BLK:12,SNR1: 0.31522 ,SNR2: 2.7101




Frequency (Hz)


0713-024 2024/09/02 23.29UT TOYOKAWA-FUJI



T20240903081530





BLK:10,SNR1: 6.8412 ,SNR2: 13.098




Frequency (Hz)

K20240903081528




BLK:10,SNR1: 0.47385 ,SNR2: 2.3735




Frequency (Hz)


0713-024 2024/09/02 23.29UT TOYOKAWA-KISO



F20240903081529




BLK: 4,SNR1: 1.0736 ,SNR2: 2.6122




Frequency (Hz)

K20240903081528




BLK: 4,SNR1: 1.5093 ,SNR2: 4.9075





Frequency (Hz)


0713-024 2024/09/02 23.29UT FUJI -KISO





T20240903082542




BLK: 8,SNR1: 5.7097 ,SNR2: 23.553




F20240903082541



BLK: 8,SNR1: 0.86748 ,SNR2: 2.0123





0723+10 2024/09/02 23.46UT TOYOKAWA-FUJI






T20240903082542





BLK:10,SNR1: 5.2147 ,SNR2: 21.477





0723+10 2024/09/02 23.48UT TOYOKAWA-KISO


K20240903082540




BLK:10,SNR1: 0.43289 ,SNR2: 2.2031




F20240903082541




BLK: 8,SNR1: 0.10794 ,SNR2: 0.87678




K20240903082540





BLK: 8,SNR1: 0.78297 ,SNR2: 4.1932




0723+10 2024/09/02 23.46UT FUJI -KISO



T20240903083556





BLK:11,SNR1: 4.9849 ,SNR2: 19.999





0732+33 2024/09/02 23.63UT TOYOKAWA-FUJI



F20240903083556




BLK:11,SNR1: 1.4812 ,SNR2: 1.9800



T20240903083556





BLK: 7,SNR1: 5.6853 ,SNR2: 23.108




Frequency (Hz)

0732+33 2024/09/02 23.63UT TOYOKAWA-KISO


K20240903083554




BLK: 7,SNR1: 1.1298 ,SNR2: 3.1002




Frequency (Hz)



F20240903083556




BLK:10,SNR1: 2.0677 ,SNR2: 5.1564




Frequency (Hz)

K20240903083554









BLK:10,SNR1: 7.6062 ,SNR2: 23.522







Frequency (Hz)


0732+33 2024/09/02 23.63UT FUJI -KISO










0741-06 2024/09/02 23.76UT TOYOKAWA-KISO





F20240903084357




BLK: 2,SNR1:-0.32279E-01,SNR2: 4.5016




K20240903084356



BLK: 2,SNR1: 0.42576 ,SNR2: 1.5662




0741-06 2024/09/02 23.76UT FUJI -KISO






T20240903085343





BLK: 8,SNR1: 4.5034 ,SNR2: 17.553




Frequency (Hz)

0752-200 2024/09/02 23.92UT TOYOKAWA-FUJI


F20240903085342





BLK: 8,SNR1: 0.41095 ,SNR2: 1.8424




Frequency (Hz)



T20240903085343





BLK: 8,SNR1: 4.1794 ,SNR2: 16.646




Frequency (Hz)

0752-200 2024/09/02 23.92UT TOYOKAWA-KISO


K20240903085341





BLK: 8,SNR1:-0.18803E-01,SNR2: 1.8673




Frequency (Hz)



F20240903085342





BLK: 4,SNR1: 1.4414 ,SNR2: 4.7940




Frequency (Hz)

K20240903085341




BLK: 4,SNR1: 0.11298 ,SNR2: 0.58548





Frequency (Hz)


0752-200 2024/09/02 23.92UT FUJI -KISO





T20240903090118




BLK:12,SNR1: 3.3924 ,SNR2: 14.135




F20240903090117





BLK:12,SNR1: 3.8224 ,SNR2: 7.4516




3C190 2024/09/03 0.05UT TOYOKAWA-FUJI





T20240903090118




BLK:13,SNR1: 3.9186 ,SNR2: 16.082




K20240903090116




BLK:13,SNR1: 0.42411 ,SNR2: 3.9546




3C190 2024/09/03 0.05UT TOYOKAWA-KISO





F20240903090117




BLK: 4,SNR1: 0.87628 ,SNR2: 2.4734




K20240903090116





BLK: 4,SNR1: 0.38180E-01,SNR2: 0.77467




3C190 2024/09/03 0.05UT FUJI -KISO



T20240903091342




BLK: 4,SNR1: 4.8659 ,SNR2: 21.793





3C196 2024/09/03 0.26UT TOYOKAWA-FUJI


F20240903091341






BLK: 4,SNR1: 0.54458E-01,SNR2: 1.0648




T20240903091342



K20240903091340




3C196 2024/09/03 0.26UT TOYOKAWA-KISO







F20240903091341




BLK: 3,SNR1: 0.18048E-01,SNR2: 1.3879




K20240903091340





BLK: 3,SNR1: 0.36181 ,SNR2: 12.581




3C196 2024/09/03 0.26UT FUJI -KISO



T20240903092452




BLK:11,SNR1: 3.7524 ,SNR2: 15.513





0821+394 2024/09/03 0.44UT TOYOKAWA-FUJI




F20240903092451







BLK:11,SNR1: 0.18744 ,SNR2: 1.7309




T20240903092452




K20240903092450



F20240903092451




BLK: 8,SNR1: 0.74153E-01,SNR2: 1.9168




Frequency (Hz)

K20240903092450










BLK: 8,SNR1: 1.7047 ,SNR2: 6.1364




Frequency (Hz)








0821+394 2024/09/03 0.44UT FUJI -KISO







0834-19 2024/09/03 0.64UT TOYOKAWA-FUJI








F20240903093631




BLK: 8,SNR1: 0.44809 ,SNR2: 2.9482




K20240903093630





BLK: 8,SNR1: 0.17809 ,SNR2: 1.6860




0834-19 2024/09/03 0.64UT FUJI -KISO




T20240903094137




BLK: 3,SNR1: 3.0161 ,SNR2: 9.4273




F20240903094136



BLK: 3,SNR1: 7.9851 ,SNR2: 22.058





0839-071 2024/09/03 0.72UT TOYOKAWA-FUJI






T20240903094137





BLK:13,SNR1: 4.1000 ,SNR2: 15.639




Frequency (Hz)

0839-071 2024/09/03 0.72UT TOYOKAWA-KISO


K20240903094135




BLK:13,SNR1: 4.7536 ,SNR2: 12.886




Frequency (Hz)




F20240903094136




BLK: 6,SNR1: 0.95190E-01,SNR2: 1.2729




K20240903094135





BLK: 6,SNR1: 0.56038E-01,SNR2: 2.2117




0839-071 2024/09/03 0.72UT FUJI -KISO





T20240903095238




BLK: 7, SNR1: 4.1450 ,SNR2: 13.816




F20240903095237




BLK: 7, SNR1: 0.37990 ,SNR2: 1.1049




3C208 2024/09/03 0.91UT TOYOKAWA-FUJI



T20240903095238





BLK: 9,SNR1: 4.1233 ,SNR2: 14.556





3C208 2024/09/03 0.91UT TOYOKAWA-KISO


K20240903095236




BLK: 9,SNR1: 6.3117 ,SNR2: 14.706



F20240903095237




BLK:10,SNR1: 0.99302 ,SNR2: 1.8340









3C208 2024/09/03 0.91UT FUJI -KISO

K20240903095236








BLK:10,SNR1: 8.0708 ,SNR2: 19.073






3C216 2024/09/03 1.18UT TOYOKAWA-FUJI








3C216 2024/09/03 1.18UT TOYOKAWA-KISO



F20240903100919





BLK: 3,SNR1: 0.31703 ,SNR2: 2.0661




Frequency (Hz)

K20240903100918




BLK: 3,SNR1: 0.97902E-01,SNR2: 1.7546





Frequency (Hz)

3C216 2024/09/03 1.18UT FUJI -KISO






T20240903102131




BLK:10,SNR1: 3.6970 ,SNR2: 13.895




0919-142 2024/09/03 1.39UT TOYOKAWA-FUJI


F20240903102130





BLK:10,SNR1: 3.4458 ,SNR2: 4.2970




Frequency (Hz)



T20240903102131





BLK:14,SNR1: 4.1120 ,SNR2: 19.045





0919-142 2024/09/03 1.39UT TOYOKAWA-KISO


K20240903102129




BLK:14,SNR1: 0.86995 ,SNR2: 3.3481




F20240903102130




BLK: 4,SNR1: 0.83203 ,SNR2: 5.9243




K20240903102129




BLK: 4,SNR1: 2.1163 ,SNR2: 7.8961




0919-142 2024/09/03 1.39UT FUJI -KISO



T20240903102810




BLK: 9,SNR1: 3.6904 ,SNR2: 14.191




Frequency (Hz)

0926+117 2024/09/03 1.50UT TOYOKAWA-FUJI


F20240903102809





BLK: 9,SNR1: 7.1831 ,SNR2: 11.189




Frequency (Hz)



T20240903102810





BLK: 8,SNR1: 3.9949 ,SNR2: 17.680





0926+117 2024/09/03 1.50UT TOYOKAWA-KISO



K20240903102808




BLK: 8,SNR1: 1.7981 ,SNR2: 6.4797



F20240903102809





BLK: 5,SNR1: 8.9158 ,SNR2: 13.465




Frequency (Hz)

K20240903102808








BLK: 5,SNR1: 1.7819 ,SNR2: 6.5907




Frequency (Hz)





0926+117 2024/09/03 1.50UT FUJI -KISO






3C222 2024/09/03 1.63UT TOYOKAWA-FUJI






3C222 2024/09/03 1.63UT TOYOKAWA-KISO






F20240903103554




BLK: 8,SNR1: 1.0714 ,SNR2: 4.6709









3C222 2024/09/03 1.63UT FUJI -KISO

K20240903103553








BLK: 8,SNR1: 2.0923 ,SNR2: 5.1793






0941-08 2024/09/03 1.74UT TOYOKAWA-FUJI








0941-08 2024/09/03 1.74UT TOYOKAWA-KISO





F20240903104254




BLK:11,SNR1:-0.12431 ,SNR2: 1.4518




K20240903104253





BLK:11,SNR1: 0.94599 ,SNR2: 3.9671




0941-08 2024/09/03 1.74UT FUJI -KISO



T20240903105117




BLK:10,SNR1: 4.5607 ,SNR2: 18.936





3C230 2024/09/03 1.88UT TOYOKAWA-FUJI


F20240903105116




BLK:10,SNR1: 1.1009 ,SNR2: 3.7265



T20240903105117




BLK:14,SNR1: 4.4495 ,SNR2: 17.218





3C230 2024/09/03 1.88UT TOYOKAWA-KISO


K20240903105115




BLK:14,SNR1: 2.0570 ,SNR2: 5.4928




F20240903105116




BLK:11,SNR1: 1.6374 ,SNR2: 4.9786




K20240903105115







BLK:11,SNR1: 2.9188 ,SNR2: 7.1389




3C230 2024/09/03 1.88UT FUJI -KISO










3C236 2024/09/03 2.12UT TOYOKAWA-FUJI












3C236 2024/09/03 2.12UT TOYOKAWA-KISO







3C236 2024/09/03 2.12UT FUJI -KISO



T20240903111334




BLK:11,SNR1: 3.7558 ,SNR2: 15.321





1011+110 2024/09/03 2.25UT TOYOKAWA-FUJI


F20240903111333




BLK:11,SNR1: 7.2784 ,SNR2: 17.992





T20240903111334




BLK:14,SNR1: 3.5608 ,SNR2: 11.878




K20240903111332




BLK:14,SNR1: 12.007 ,SNR2: 30.452




1011+110 2024/09/03 2.25UT TOYOKAWA-KISO



F20240903111333





BLK:24,SNR1: 6.9071 ,SNR2: 20.246









1011+110 2024/09/03 2.25UT FUJI -KISO

K20240903111332





BLK:24,SNR1: 16.329 ,SNR2: 40.178






3C241 2024/09/03 2.38UT TOYOKAWA-FUJI








BLK: 9, SNR1: 3.3676 , SNR2: 13.172




3C241 2024/09/03 2.38UT TOYOKAWA-KISO




BLK: 9, SNR1: 8.4387 , SNR2: 21.416



F20240903112114





BLK:11,SNR1: 4.7128 ,SNR2: 13.642





3C241 2024/09/03 2.38UT FUJI -KISO





K20240903112113




BLK:11,SNR1: 6.4434 ,SNR2: 19.142












1031-11 2024/09/03 2.57UT TOYOKAWA-FUJI








1031-11 2024/09/03 2.57UT TOYOKAWA-KISO




F20240903113243




BLK: 6,SNR1: 5.1798 ,SNR2: 14.377




K20240903113242





BLK: 6,SNR1: 4.2930 ,SNR2: 10.924




1031-11 2024/09/03 2.57UT FUJI -KISO



T20240903113717





BLK:11,SNR1: 4.2233 ,SNR2: 15.521





1035-058 2024/09/03 2.65UT TOYOKAWA-FUJI



F20240903113716




BLK:11,SNR1: 5.5502 ,SNR2: 16.005



T20240903113717




BLK:12,SNR1: 3.8601 ,SNR2: 14.093





1035-058 2024/09/03 2.65UT TOYOKAWA-KISO



K20240903113715




BLK:12,SNR1: 10.117 ,SNR2: 29.271



F20240903113716




BLK: 9,SNR1: 7.5109 ,SNR2: 21.583





1035-058 2024/09/03 2.65UT FUJI -KISO



K20240903113715




BLK: 9,SNR1: 8.8409 ,SNR2: 22.782




T20240903114630




BLK:11,SNR1: 214.68 ,SNR2: 205.56




F20240903114630





BLK:11,SNR1: 9.1627 ,SNR2: 26.444




1044-008 2024/09/03 2.80UT TOYOKAWA-FUJI





T20240903114630




BLK:11,SNR1: 777.87 ,SNR2: 755.55




K20240903114628



BLK:11,SNR1: 8.2794 ,SNR2: 22.942




1044-008 2024/09/03 2.80UT TOYOKAWA-KISO







F20240903114630




BLK: 9,SNR1: 9.5827 ,SNR2: 24.550




K20240903114628





BLK: 9,SNR1: 10.577 ,SNR2: 26.347




1044-008 2024/09/03 2.80UT FUJI -KISO



T20240903115735




BLK:10,SNR1: 4.6046 ,SNR2: 18.149





1055+01 2024/09/03 2.99UT TOYOKAWA-FUJI



F20240903115734




BLK:10,SNR1: 9.5626 ,SNR2: 23.913



T20240903115735





BLK: 9,SNR1: 3.5337 ,SNR2: 13.906





1055+01 2024/09/03 2.99UT TOYOKAWA-KISO


K20240903115733




BLK: 9,SNR1: 30.215 ,SNR2: 74.167



F20240903115734




BLK:13,SNR1: 10.837 ,SNR2: 27.430





1055+01 2024/09/03 2.99UT FUJI -KISO


K20240903115733




BLK:13,SNR1: 24.124 ,SNR2: 57.175




T20240903120852




BLK: 3,SNR1: 436.84 ,SNR2: 457.10




F20240903120851




BLK: 3,SNR1: 10.468 ,SNR2: 29.901




1107+109 2024/09/03 3.18UT TOYOKAWA-FUJI




T20240903120852




BLK: 5,SNR1: 436.84 ,SNR2: 457.10




K20240903120850




BLK: 5,SNR1: 9.9814 ,SNR2: 28.867




1107+109 2024/09/03 3.18UT TOYOKAWA-KISO



F20240903120851




BLK: 6,SNR1: 9.9649 ,SNR2: 28.317





1107+109 2024/09/03 3.18UT FUJI -KISO



K20240903120850




BLK: 6,SNR1: 10.812 ,SNR2: 31.277





T20240903121935




BLK: 3,SNR1: 716.68 ,SNR2: 821.97




F20240903121934



BLK: 3,SNR1: 10.070 ,SNR2: 25.359





1117+14 2024/09/03 3.35UT TOYOKAWA-FUJI







T20240903121935




BLK: 5,SNR1: 10.921 ,SNR2: 25.219




K20240903121933





BLK: 5,SNR1: 9.4252 ,SNR2: 23.343




1117+14 2024/09/03 3.35UT TOYOKAWA-KISO





F20240903121934




BLK: 5,SNR1: 6.7271 ,SNR2: 17.040




K20240903121933





BLK: 5,SNR1: 15.555 ,SNR2: 36.533




1117+14 2024/09/03 3.35UT FUJI -KISO




T20240903122907




BLK: 4,SNR1: 1.6434 ,SNR2: 3.1157




F20240903122906




BLK: 4,SNR1: 6.0572 ,SNR2: 17.330




1127-14 2024/09/03 3.51UT TOYOKAWA-FUJI




T20240903122907




BLK: 7,SNR1: 1.1669 ,SNR2: 1.8047




K20240903122905




BLK: 7,SNR1: 11.009 ,SNR2: 29.323




1127-14 2024/09/03 3.51UT TOYOKAWA-KISO




F20240903122906




BLK: 5,SNR1: 6.1099 ,SNR2: 17.716




K20240903122905





BLK: 5,SNR1: 7.2171 ,SNR2: 18.944




1127-14 2024/09/03 3.51UT FUJI -KISO




T20240903124227




BLK: 7,SNR1: 1.3802 ,SNR2: 3.4752




F20240903124226





BLK: 7,SNR1: 9.9321 ,SNR2: 28.843




3C263.1 2024/09/03 3.74UT TOYOKAWA-FUJI




T20240903124227




BLK: 9,SNR1: 1.4584 ,SNR2: 3.5092




K20240903124225





BLK: 9,SNR1: 7.4850 ,SNR2: 21.918




3C263.1 2024/09/03 3.74UT TOYOKAWA-KISO



F20240903124226




BLK: 6, SNR1: 10.222 , SNR2: 30.087





3C263.1 2024/09/03 3.74UT FUJI -KISO

K20240903124225





BLK: 6, SNR1: 12.588 , SNR2: 31.293







T20240903124854




BLK: 2,SNR1: 2.3854 ,SNR2: 5.2805




F20240903124853




BLK: 2,SNR1: 0.44745 ,SNR2: 1.8277




3C267 2024/09/03 3.84UT TOYOKAWA-FUJI



T20240903124854




BLK:12,SNR1: 1.5647 ,SNR2: 3.0268





3C267 2024/09/03 3.84UT TOYOKAWA-KISO


K20240903124852




BLK:12,SNR1: 4.6130 ,SNR2: 8.7375




F20240903124853




BLK: 6,SNR1:-0.54850E-01,SNR2: 1.5433




K20240903124852






BLK: 6,SNR1: 2.4302 ,SNR2: 9.5096






3C267 2024/09/03 3.84UT FUJI -KISO




T20240903131442





F20240903131441




1213-17 2024/09/03 4.27UT TOYOKAWA-FUJI





T20240903131442




No.Good Data




K20240903131440





No.Good Data




1213-17 2024/09/03 4.27UT TOYOKAWA-KISO





F20240903131441




BLK: 5,SNR1: 8.8225 ,SNR2: 24.067




K20240903131440





BLK: 5,SNR1: 8.7538 ,SNR2: 26.147






1213-17 2024/09/03 4.27UT FUJI -KISO




T20240903132759





F20240903132759






3C273 2024/09/03 4.49UT TOYOKAWA-FUJI




T20240903132759



K20240903132757





3C273 2024/09/03 4.49UT TOYOKAWA-KISO






F20240903132759





BLK:12,SNR1: 8.8463 ,SNR2: 21.722





3C273 2024/09/03 4.49UT FUJI -KISO



K20240903132757




BLK:12,SNR1: 11.723 ,SNR2: 28.671





T20240903134110




No.Good Data




F20240903134109






No.Good Data






3C275 2024/09/03 4.71UT TOYOKAWA-FUJI




T20240903134110





K20240903134108




3C275 2024/09/03 4.71UT TOYOKAWA-KISO





F20240903134109




BLK: 6,SNR1: 8.8833 ,SNR2: 22.857




K20240903134108





BLK: 6,SNR1: 12.828 ,SNR2: 29.918






3C275 2024/09/03 4.71UT FUJI -KISO




T20240903134715





F20240903134714






1245-19 2024/09/03 4.82UT TOYOKAWA-FUJI




T20240903134715




K20240903134713




1245-19 2024/09/03 4.82UT TOYOKAWA-KISO




F20240903134714




BLK: 9,SNR1: 0.73967 ,SNR2: 2.1420




K20240903134713





BLK: 9,SNR1: 1.1233 ,SNR2: 2.3712






1245-19 2024/09/03 4.82UT FUJI -KISO




T20240903135459



F20240903135458





3C279 2024/09/03 4.94UT TOYOKAWA-FUJI








T20240903135459




No.Good Data




K20240903135457





No.Good Data




3C279 2024/09/03 4.94UT TOYOKAWA-KISO





F20240903135458




BLK: 6,SNR1: 0.63062 ,SNR2: 2.2835




K20240903135457





BLK: 6,SNR1: 1.1564 ,SNR2: 2.2174




3C279 2024/09/03 4.94UT FUJI -KISO



T20240903141028





No.Good Data




Frequency (Hz)

F20240903141027




No.Good Data






Frequency (Hz)




3C283 2024/09/03 5.20UT TOYOKAWA-FUJI




T20240903141028







K20240903141026




3C283 2024/09/03 5.20UT TOYOKAWA-KISO








3C283 2024/09/03 5.20UT FUJI -KISO





T20240903142453




No.Good Data




F20240903142452





No.Good Data




1323+32 2024/09/03 5.44UT TOYOKAWA-FUJI





T20240903142453




No.Good Data




K20240903142451




No.Good Data




1323+32 2024/09/03 5.44UT TOYOKAWA-KISO




F20240903142452




BLK: 7,SNR1: 9.1358 ,SNR2: 22.821




K20240903142451



BLK: 7,SNR1: 8.0455 ,SNR2: 20.500





1323+32 2024/09/03 5.44UT FUJI -KISO









T20240903145631





F20240903145630






1355+01 2024/09/03 5.97UT TOYOKAWA-FUJI




T20240903145631





K20240903145629




1355+01 2024/09/03 5.97UT TOYOKAWA-KISO





F20240903145630




BLK:10,SNR1: 6.9107 ,SNR2: 14.126




K20240903145629






BLK:10,SNR1: 1.6375 ,SNR2: 4.3245






1355+01 2024/09/03 5.97UT FUJI -KISO




T20240903151741






F20240903151740






3C298 2024/09/03 6.32UT TOYOKAWA-FUJI




T20240903151741





K20240903151739




3C298 2024/09/03 6.32UT TOYOKAWA-KISO





F20240903151740




BLK:12,SNR1: 8.2202 ,SNR2: 22.224




K20240903151739






BLK:12,SNR1: 3.0865 ,SNR2: 5.9963






3C298 2024/09/03 6.32UT FUJI -KISO




T20240903152925




F20240903152924




1428-03 2024/09/03 6.52UT TOYOKAWA-FUJI





T20240903152925




No.Good Data




K20240903152923



No.Good Data





1428-03 2024/09/03 6.52UT TOYOKAWA-KISO








F20240903152924




BLK:10,SNR1: 12.126 ,SNR2: 15.378




K20240903152923





BLK:10,SNR1: 0.56684 ,SNR2: 1.8817






1428-03 2024/09/03 6.52UT FUJI -KISO




T20240903153806





F20240903153805




1436-16 2024/09/03 6.66UT TOYOKAWA-FUJI




T20240903153806




No.Good Data




K20240903153804





No.Good Data




1436-16 2024/09/03 6.66UT TOYOKAWA-KISO





F20240903153805




BLK: 8,SNR1: 1.6427 ,SNR2: 4.2420




K20240903153804





BLK: 8,SNR1: 0.39841 ,SNR2: 4.2571




1436-16 2024/09/03 6.66UT FUJI -KISO



T20240903155429





BLK: 8,SNR1: 0.57803 ,SNR2: 6.5964




Frequency (Hz)

F20240903155428




BLK: 8,SNR1: 1.5190 ,SNR2: 6.2787





Frequency (Hz)


1453-10 2024/09/03 6.94UT TOYOKAWA-FUJI



T20240903155429





BLK: 9,SNR1: 0.56985 ,SNR2: 1.0718




Frequency (Hz)

K20240903155427








BLK: 9,SNR1: 3.8772 ,SNR2: 4.7606




Frequency (Hz)

1453-10 2024/09/03 6.94UT TOYOKAWA-KISO








1453-10 2024/09/03 6.94UT FUJI -KISO



T20240903160922





BLK: 9,SNR1: 0.16029 ,SNR2: 0.74650




Frequency (Hz)

F20240903160921




BLK: 9,SNR1: 0.72652 ,SNR2: 4.9875




Frequency (Hz)



1508-05 2024/09/03 7.18UT TOYOKAWA-FUJI









BLK: 4,SNR1: 0.86001E-01,SNR2: 0.85280





BLK: 4,SNR1: 1.8475 ,SNR2: 8.4651




1508-05 2024/09/03 7.18UT TOYOKAWA-KISO



F20240903160921





BLK: 9,SNR1: 1.3394 ,SNR2: 5.4632




Frequency (Hz)

K20240903160920




BLK: 9,SNR1: 6.4715 ,SNR2: 17.464





Frequency (Hz)


1508-05 2024/09/03 7.18UT FUJI -KISO



T20240903161822




BLK:13,SNR1:-0.37571E-02,SNR2: 0.71753




Frequency (Hz)

F20240903161821




BLK:13,SNR1: 4.9517 ,SNR2: 12.621





Frequency (Hz)


3C318 2024/09/03 7.33UT TOYOKAWA-FUJI




T20240903161822




BLK: 2,SNR1: 0.52838 ,SNR2: 1.7978




K20240903161820




BLK: 2,SNR1: 2.1006 ,SNR2: 6.7479




3C318 2024/09/03 7.33UT TOYOKAWA-KISO




F20240903161821




BLK: 6,SNR1: 1.8451 ,SNR2: 3.7363




K20240903161820





BLK: 6,SNR1: 1.8022 ,SNR2: 5.7962




3C318 2024/09/03 7.33UT FUJI -KISO



T20240903162409





BLK: 3,SNR1: 0.83926 ,SNR2: 1.3754




Frequency (Hz)

F20240903162408




BLK: 3,SNR1: 1.7496 ,SNR2: 15.388





Frequency (Hz)


1523+03 2024/09/03 7.43UT TOYOKAWA-FUJI



T20240903162409




BLK: 6,SNR1: 0.52074 ,SNR2: 2.6155




Frequency (Hz)

K20240903162407




BLK: 6,SNR1: 29.540 ,SNR2: 50.917





Frequency (Hz)


1523+03 2024/09/03 7.43UT TOYOKAWA-KISO



F20240903162408





BLK: 1,SNR1: 1.3330 ,SNR2: 14.403




Frequency (Hz)

K20240903162407




BLK: 1,SNR1:-0.33484 ,SNR2: 0.24687




Frequency (Hz)

1523+03 2024/09/03 7.43UT FUJI -KISO






T20240903163548





BLK: 5,SNR1: 0.51539 ,SNR2: 0.47506




Frequency (Hz)

F20240903163547




BLK: 5,SNR1: 1.0582 ,SNR2: 3.8627





Frequency (Hz)


1535+139 2024/09/03 7.62UT TOYOKAWA-FUJI



T20240903163548





BLK: 2,SNR1: 0.44127 ,SNR2: 1.3322




Frequency (Hz)

K20240903163546




BLK: 2,SNR1: 55.464 ,SNR2: 95.217





Frequency (Hz)


1535+139 2024/09/03 7.62UT TOYOKAWA-KISO



F20240903163547





BLK: 4,SNR1: 0.74716 ,SNR2: 3.0047




Frequency (Hz)

K20240903163546




BLK: 4,SNR1:-0.24473E-01,SNR2: 1.6412





Frequency (Hz)


1535+139 2024/09/03 7.62UT FUJI -KISO



T20240903164612





BLK: 5,SNR1:-0.91995E-01,SNR2: 0.94491




Frequency (Hz)

F20240903164612




BLK: 5,SNR1: 1.1104 ,SNR2: 2.4507





Frequency (Hz)


1545-12 2024/09/03 7.80UT TOYOKAWA-FUJI





T20240903164612




BLK: 3,SNR1:-0.94240E-01,SNR2: 0.96000




K20240903164610




BLK: 3,SNR1: 0.36347E-01,SNR2: 0.44856




1545-12 2024/09/03 7.80UT TOYOKAWA-KISO



F20240903164612





BLK: 8,SNR1: 0.84668 ,SNR2: 2.0468




Frequency (Hz)

K20240903164610




BLK: 8,SNR1: 0.71201E-01,SNR2: 0.98856





Frequency (Hz)


1545-12 2024/09/03 7.80UT FUJI -KISO



T20240903170715




BLK: 5,SNR1: 0.63355E-01,SNR2: 1.3401




Frequency (Hz)

F20240903170714




BLK: 5,SNR1: 2.1038 ,SNR2: 2.7533





Frequency (Hz)


1607+26 2024/09/03 8.15UT TOYOKAWA-FUJI



T20240903170715





BLK: 8,SNR1: 0.78581 ,SNR2: 4.5054




Frequency (Hz)

K20240903170713




BLK: 8,SNR1: 4.5960 ,SNR2: 11.877




Frequency (Hz)

1607+26 2024/09/03 8.15UT TOYOKAWA-KISO






F20240903170714




BLK:14,SNR1: 1.1874 ,SNR2: 3.8837




Frequency (Hz)

K20240903170713



BLK:14,SNR1: 4.6821 ,SNR2: 12.117



Frequency (Hz)

1607+26 2024/09/03 8.15UT FUJI -KISO

