




T20240911062409




BLK: 4,SNR1: 10.250 ,SNR2: 77.487




Frequency (Hz)

F20240911062409




BLK: 4,SNR1: 0.82648 ,SNR2: 1.6793





Frequency (Hz)


0552+12 2024/09/10 21.43UT TOYOKAWA-FUJI



T20240911062409




BLK: 5, SNR1: 0.97217 , SNR2: 3.1410




Frequency (Hz)

K20240911062406




BLK: 5, SNR1: 0.26993 , SNR2: 1.0915




Frequency (Hz)


0552+12 2024/09/10 21.43UT TOYOKAWA-KISO



F20240911062409





BLK: 6,SNR1: 1.2244 ,SNR2: 2.5564




Frequency (Hz)

K20240911062406









BLK: 6,SNR1: 1.0424 ,SNR2: 4.4888




Frequency (Hz)


0552+12 2024/09/10 21.43UT FUJI -KISO







0556+191 2024/09/10 21.50UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.22180 ,SNR2: 0.39795





BLK: 2,SNR1: 0.26101 ,SNR2: 0.93245




0556+191 2024/09/10 21.50UT TOYOKAWA-KISO



F20240911062837





BLK: 5,SNR1: 0.52143 ,SNR2: 2.5778




Frequency (Hz)

K20240911062833




BLK: 5,SNR1: 0.24373 ,SNR2: 1.5881




Frequency (Hz)


0556+191 2024/09/10 21.50UT FUJI -KISO



T20240911063309





BLK: 1,SNR1: 0.69351 ,SNR2: 3.9697




Frequency (Hz)

F20240911063310






BLK: 1,SNR1: 2.2303 ,SNR2: 4.0797





Frequency (Hz)

3C152 2024/09/10 21.58UT TOYOKAWA-FUJI







BLK: 4, SNR1: $-0.82834E-02$, SNR2: 0.83086




BLK: 4, SNR1: 0.87970, SNR2: 3.5725




3C152 2024/09/10 21.58UT TOYOKAWA-KISO




F20240911063310




No.Good Data




K20240911063306





No.Good Data




3C152 2024/09/10 21.58UT FUJI -KISO





T20240911065530




BLK: 8,SNR1: 0.13026 ,SNR2: 2.2450




F20240911065531





BLK: 8,SNR1: 0.70199E-01,SNR2: 2.7722




3C161 2024/09/10 21.95UT TOYOKAWA-FUJI



T20240911065530





BLK:10,SNR1: 0.24695 ,SNR2: 2.3749




Frequency (Hz)

K20240911065527




BLK:10,SNR1: 0.56873 ,SNR2: 3.9019





Frequency (Hz)


3C161 2024/09/10 21.95UT TOYOKAWA-KISO



F20240911065531





BLK: 4,SNR1: 0.11088 ,SNR2: 4.1692




Frequency (Hz)

3C161 2024/09/10 21.95UT FUJI -KISO


K20240911065527





BLK: 4,SNR1: 0.22923 ,SNR2: 1.3064




Frequency (Hz)



T20240911072303





BLK: 7,SNR1: 0.35484 ,SNR2: 1.2529




Frequency (Hz)

F20240911072303




BLK: 7,SNR1: 8.3794 ,SNR2: 25.962





Frequency (Hz)


0652-130 2024/09/10 22.41UT TOYOKAWA-FUJI



T20240911072303





BLK:11,SNR1: 2.0671 ,SNR2: 6.4614




Frequency (Hz)

K20240911072300




BLK:11,SNR1: 5.0108 ,SNR2: 14.391





Frequency (Hz)


0652-130 2024/09/10 22.41UT TOYOKAWA-KISO



F20240911072303





BLK: 8,SNR1: 6.6440 ,SNR2: 20.635




Frequency (Hz)

K20240911072300




BLK: 8,SNR1: 2.8757 ,SNR2: 8.3677




Frequency (Hz)


0652-130 2024/09/10 22.41UT FUJI -KISO



T20240911073439





BLK: 7,SNR1: 0.12714 ,SNR2: 1.0237




Frequency (Hz)

F20240911073440




BLK: 7,SNR1: 4.0560 ,SNR2: 7.2024





Frequency (Hz)


0703+138 2024/09/10 22.61UT TOYOKAWA-FUJI



T20240911073439




BLK: 8,SNR1: 0.28553 ,SNR2: 0.66269




Frequency (Hz)

K20240911073436




BLK: 8,SNR1: 2.1631 ,SNR2: 5.7625





Frequency (Hz)


0703+138 2024/09/10 22.61UT TOYOKAWA-KISO



F20240911073440





BLK: 8,SNR1: 3.0522 ,SNR2: 8.0922




Frequency (Hz)

K20240911073436




BLK: 8,SNR1: 2.2438 ,SNR2: 6.0506





Frequency (Hz)


0703+138 2024/09/10 22.61UT FUJI -KISO



T20240911074402




BLK: 3,SNR1: 1.7233 ,SNR2: 5.3965




Frequency (Hz)

F20240911074402




BLK: 3,SNR1: 4.5837 ,SNR2: 13.732





Frequency (Hz)


0713-024 2024/09/10 22.76UT TOYOKAWA-FUJI



T20240911074402





BLK: 6,SNR1:-0.48356E-02,SNR2: 1.0622




Frequency (Hz)

K20240911074359




BLK: 6,SNR1: 3.6277 ,SNR2: 9.1788





Frequency (Hz)


0713-024 2024/09/10 22.76UT TOYOKAWA-KISO



F20240911074402





BLK: 9,SNR1: 1.5315 ,SNR2: 5.0793




Frequency (Hz)

K20240911074359




BLK: 9,SNR1: 3.3122 ,SNR2: 8.7160





Frequency (Hz)


0713-024 2024/09/10 22.76UT FUJI -KISO



T20240911075414





BLK: 2,SNR1: 0.88888 ,SNR2: 6.5068




Frequency (Hz)

F20240911075415




BLK: 2,SNR1: 1.7351 ,SNR2: 3.2013





Frequency (Hz)


0723+10 2024/09/10 22.93UT TOYOKAWA-FUJI



T20240911075414





BLK: 6,SNR1: 0.41019 ,SNR2: 1.1371




Frequency (Hz)

0723+10 2024/09/10 22.93UT TOYOKAWA-KISO


K20240911075411





BLK: 6,SNR1: 3.1189 ,SNR2: 9.2652




Frequency (Hz)



F20240911075415





BLK: 6,SNR1: 6.4141 ,SNR2: 16.632




Frequency (Hz)

K20240911075411




BLK: 6,SNR1: 2.7807 ,SNR2: 8.4312





Frequency (Hz)


0723+10 2024/09/10 22.93UT FUJI -KISO



T20240911080428




BLK:10,SNR1: 0.46399 ,SNR2: 3.6339




Frequency (Hz)

0732+33 2024/09/10 23.10UT TOYOKAWA-FUJI


F20240911080428





BLK:10,SNR1: 0.96416 ,SNR2: 5.0285




Frequency (Hz)



T20240911080428





BLK:10,SNR1: 0.62304 ,SNR2: 3.9372




Frequency (Hz)

0732+33 2024/09/10 23.10UT TOYOKAWA-KISO


K20240911080425




BLK:10,SNR1: 18.366 ,SNR2: 27.228




Frequency (Hz)




F20240911080428




BLK:12,SNR1: 0.95467 ,SNR2: 5.0806




K20240911080425





BLK:12,SNR1: 18.445 ,SNR2: 21.297




0732+33 2024/09/10 23.10UT FUJI -KISO



T20240911081230





BLK:12,SNR1: 0.83970 ,SNR2: 5.3192




Frequency (Hz)

F20240911081230




BLK:12,SNR1:-0.34165E-01,SNR2: 1.4754





Frequency (Hz)


0741-06 2024/09/10 23.24UT TOYOKAWA-FUJI



T20240911081230





BLK:14,SNR1: 1.0731 ,SNR2: 4.0223




Frequency (Hz)

K20240911081227




BLK:14,SNR1: 70.064 ,SNR2: 84.189




Frequency (Hz)


0741-06 2024/09/10 23.24UT TOYOKAWA-KISO



F20240911081230





BLK: 2,SNR1: 0.76491E-01,SNR2: 0.78920




Frequency (Hz)

K20240911081227




BLK: 2,SNR1: 6.0662 ,SNR2: 27.591




Frequency (Hz)


0741-06 2024/09/10 23.24UT FUJI -KISO



T20240911082215





BLK: 5,SNR1: 2.0727 ,SNR2: 4.5850




Frequency (Hz)

F20240911082215




BLK: 5,SNR1: 4.6122 ,SNR2: 11.507




Frequency (Hz)


0752-200 2024/09/10 23.40UT TOYOKAWA-FUJI



T20240911082215




BLK: 5,SNR1: 0.38491 ,SNR2: 1.3776




Frequency (Hz)

K20240911082212




BLK: 5,SNR1: 1.4557 ,SNR2: 4.6858





Frequency (Hz)


0752-200 2024/09/10 23.40UT TOYOKAWA-KISO



F20240911082215





BLK: 7,SNR1: 3.9698 ,SNR2: 7.5701




Frequency (Hz)

K20240911082212




BLK: 7,SNR1: 4.4726 ,SNR2: 6.6828





Frequency (Hz)


0752-200 2024/09/10 23.40UT FUJI -KISO



T20240911082949





BLK: 3,SNR1: 10.817 ,SNR2: 14.200





3C190 2024/09/10 23.53UT TOYOKAWA-FUJI



F20240911082949




BLK: 3,SNR1: 7.0907 ,SNR2: 18.372



T20240911082949





BLK:12,SNR1: 4.3858 ,SNR2: 17.927




Frequency (Hz)

3C190 2024/09/10 23.53UT TOYOKAWA-KISO


K20240911082946




BLK:12,SNR1: 10.526 ,SNR2: 26.273




Frequency (Hz)



F20240911082949




BLK:13,SNR1: 9.2404 ,SNR2: 23.774




Frequency (Hz)

3C190 2024/09/10 23.53UT FUJI -KISO


K20240911082946





BLK:13,SNR1: 10.411 ,SNR2: 26.545




Frequency (Hz)



T20240911084214





BLK:11,SNR1: 10.182 ,SNR2: 30.440




Frequency (Hz)

F20240911084214




BLK:11,SNR1: 8.3588 ,SNR2: 24.146





Frequency (Hz)


3C196 2024/09/10 23.73UT TOYOKAWA-FUJI



T20240911084214





BLK:10,SNR1: 7.9964 ,SNR2: 23.498




Frequency (Hz)

3C196 2024/09/10 23.73UT TOYOKAWA-KISO


K20240911084211





BLK:10,SNR1: 9.8079 ,SNR2: 27.597




Frequency (Hz)



F20240911084214





BLK:13,SNR1: 9.8816 ,SNR2: 28.451




Frequency (Hz)

3C196 2024/09/10 23.73UT FUJI -KISO


K20240911084211





BLK:13,SNR1: 9.2509 ,SNR2: 26.803




Frequency (Hz)



T20240911085324





BLK: 5, SNR1: 4.0201 , SNR2: 16.239




Frequency (Hz)

F20240911085324




BLK: 5, SNR1: 11.533 , SNR2: 27.827





Frequency (Hz)


0821+394 2024/09/10 23.92UT TOYOKAWA-FUJI



T20240911085324




BLK: 6,SNR1: 6.3870 ,SNR2: 19.066




Frequency (Hz)

K20240911085321




BLK: 6,SNR1: 12.119 ,SNR2: 22.738





Frequency (Hz)


0821+394 2024/09/10 23.92UT TOYOKAWA-KISO



F20240911085324





BLK:11,SNR1: 7.2838 ,SNR2: 19.099




Frequency (Hz)

0821+394 2024/09/10 23.92UT FUJI -KISO


K20240911085321





BLK:11,SNR1: 7.4654 ,SNR2: 21.670




Frequency (Hz)



T20240911090504





BLK: 6,SNR1: 11.024 ,SNR2: 28.103




Frequency (Hz)

0834-19 2024/09/11 0.11UT TOYOKAWA-FUJI


F20240911090504





BLK: 6,SNR1: 9.9602 ,SNR2: 23.309




Frequency (Hz)



T20240911090504





BLK: 9,SNR1: 10.703 ,SNR2: 27.601




Frequency (Hz)

0834-19 2024/09/11 0.11UT TOYOKAWA-KISO


K20240911090501




BLK: 9,SNR1: 8.6473 ,SNR2: 21.916




Frequency (Hz)




F20240911090504




BLK: 6,SNR1: 11.686 ,SNR2: 29.334




K20240911090501





BLK: 6,SNR1: 8.4129 ,SNR2: 21.596




0834-19 2024/09/11 0.11UT FUJI -KISO





T20240911091009




BLK: 2,SNR1: 0.81321 ,SNR2: 3.5477




F20240911091009





BLK: 2,SNR1: 0.26906E-01,SNR2: 2.6026




0839-071 2024/09/11 0.20UT TOYOKAWA-FUJI





T20240911091009




BLK: 9,SNR1: 0.40415 ,SNR2: 2.2149




K20240911091006




BLK: 9,SNR1: 1.0065 ,SNR2: 4.1107




0839-071 2024/09/11 0.20UT TOYOKAWA-KISO




F20240911091009




BLK: 8,SNR1: 0.20903 ,SNR2: 2.1699




K20240911091006





BLK: 8,SNR1: 0.28963 ,SNR2: 1.6422




0839-071 2024/09/11 0.20UT FUJI -KISO



T20240911092110





BLK: 6,SNR1: 0.23135 ,SNR2: 2.3420




Frequency (Hz)

3C208 2024/09/11 0.38UT TOYOKAWA-FUJI


F20240911092110





BLK: 6,SNR1: 1.1872 ,SNR2: 9.8316




Frequency (Hz)





T20240911092110




BLK: 8,SNR1: 0.25708 ,SNR2: 1.0977




K20240911092107




BLK: 8,SNR1: 0.99587 ,SNR2: 4.2385




3C208 2024/09/11 0.38UT TOYOKAWA-KISO





F20240911092110




BLK: 6,SNR1: 1.0381 ,SNR2: 8.0219




K20240911092107





BLK: 6,SNR1: 0.42052 ,SNR2: 3.9740




3C208 2024/09/11 0.38UT FUJI -KISO



T20240911093751





BLK: 8,SNR1: 10.362 ,SNR2: 31.841




Frequency (Hz)

3C216 2024/09/11 0.66UT TOYOKAWA-FUJI


F20240911093751




BLK: 8,SNR1: 10.197 ,SNR2: 25.973




Frequency (Hz)




T20240911093751



Time (sec)




BLK: 7,SNR1: 9.0988 ,SNR2: 23.253



Frequency (Hz)


K20240911093748



Time (sec)




BLK: 7,SNR1: 8.2094 ,SNR2: 22.448




Frequency (Hz)


3C216 2024/09/11 0.66UT TOYOKAWA-KISO



F20240911093751




BLK:10,SNR1: 10.724 ,SNR2: 27.344





3C216 2024/09/11 0.66UT FUJI -KISO



K20240911093748




BLK:10,SNR1: 14.934 ,SNR2: 35.041





T20240911095003




BLK: 7,SNR1: 12.759 ,SNR2: 36.845




F20240911095003





BLK: 7,SNR1: 13.104 ,SNR2: 31.201




0919-142 2024/09/11 0.86UT TOYOKAWA-FUJI



T20240911095003





BLK:10,SNR1: 15.000 ,SNR2: 38.772




Frequency (Hz)

0919-142 2024/09/11 0.86UT TOYOKAWA-KISO


K20240911095000







BLK:10,SNR1: 64.916 ,SNR2: 83.944




Frequency (Hz)







0919-142 2024/09/11 0.86UT FUJI -KISO



T20240911095642




BLK:11,SNR1: 0.66374E-01,SNR2: 0.84145




Frequency (Hz)

F20240911095642




BLK:11,SNR1: 0.56602 ,SNR2: 1.5130





Frequency (Hz)


0926+117 2024/09/11 0.97UT TOYOKAWA-FUJI



T20240911095642





BLK:10,SNR1: 0.14675 ,SNR2: 1.0324




Frequency (Hz)

K20240911095639




BLK:10,SNR1: 1.2214 ,SNR2: 4.0573





Frequency (Hz)


0926+117 2024/09/11 0.97UT TOYOKAWA-KISO



F20240911095642




BLK: 6,SNR1: 1.8282 ,SNR2: 4.5179




Frequency (Hz)

K20240911095639




BLK: 6,SNR1: 0.60216 ,SNR2: 2.4632




Frequency (Hz)


0926+117 2024/09/11 0.97UT FUJI -KISO




T20240911100427




BLK:15,SNR1: 0.26655 ,SNR2: 1.4254




F20240911100427




BLK:15,SNR1: 4.2524 ,SNR2: 14.330




3C222 2024/09/11 1.10UT TOYOKAWA-FUJI




T20240911100427




BLK:15,SNR1: 0.46011 ,SNR2: 1.6608




K20240911100424




BLK:15,SNR1: 19.083 ,SNR2: 26.736




3C222 2024/09/11 1.10UT TOYOKAWA-KISO




F20240911100427




BLK:32,SNR1: 1.8035 ,SNR2: 13.112




K20240911100424




BLK:32,SNR1: 19.644 ,SNR2: 33.225




3C222 2024/09/11 1.10UT FUJI -KISO



T20240911101127




BLK: 3, SNR1: 3.0095 , SNR2: 9.1680





0941-08 2024/09/11 1.22UT TOYOKAWA-FUJI



F20240911101127




BLK: 3, SNR1: 8.5654 , SNR2: 20.656



T20240911101127




BLK: 5, SNR1: 11.614 , SNR2: 33.067





0941-08 2024/09/11 1.22UT TOYOKAWA-KISO


K20240911101124




BLK: 5, SNR1: 11.208 , SNR2: 30.246



F20240911101127




BLK: 3,SNR1: 7.9824 ,SNR2: 23.174





0941-08 2024/09/11 1.22UT FUJI -KISO



K20240911101124




BLK: 3,SNR1: 12.121 ,SNR2: 35.030



T20240911101948





BLK:11,SNR1: 0.37677 ,SNR2: 4.3454




Frequency (Hz)

F20240911101948




BLK:11,SNR1: 0.35691 ,SNR2: 4.5938





Frequency (Hz)


3C230 2024/09/11 1.36UT TOYOKAWA-FUJI



T20240911101948




BLK:13,SNR1: 0.33932 ,SNR2: 4.1209




Frequency (Hz)

3C230 2024/09/11 1.36UT TOYOKAWA-KISO


K20240911101945




BLK:13,SNR1: 1.8980 ,SNR2: 3.7748




Frequency (Hz)



F20240911101948




BLK: 7,SNR1: 0.80052 ,SNR2: 4.3866





3C230 2024/09/11 1.36UT FUJI -KISO


K20240911101945




BLK: 7,SNR1: 1.0365 ,SNR2: 2.2202



T20240911103356





BLK: 5, SNR1: 4.4885 , SNR2: 12.415




Frequency (Hz)

3C236 2024/09/11 1.59UT TOYOKAWA-FUJI


F20240911103356




BLK: 5, SNR1: 4.2708 , SNR2: 12.568




Frequency (Hz)



T20240911103356




BLK: 7, SNR1: 8.7045 ,SNR2: 20.716





3C236 2024/09/11 1.59UT TOYOKAWA-KISO



K20240911103353




BLK: 7, SNR1: 0.15487 ,SNR2: 1.9042




F20240911103356




BLK:10,SNR1: 10.818 ,SNR2: 25.871




K20240911103353





BLK:10,SNR1: 2.8867 ,SNR2: 7.3959




3C236 2024/09/11 1.59UT FUJI -KISO





T20240911104205




BLK:11,SNR1: 0.22151 ,SNR2: 1.4278




F20240911104206





BLK:11,SNR1: 0.21290 ,SNR2: 3.7346




1011+110 2024/09/11 1.73UT TOYOKAWA-FUJI





T20240911104205




BLK: 8,SNR1: 0.36879 ,SNR2: 2.1873




K20240911104202




BLK: 8,SNR1: 1.3696 ,SNR2: 4.0338




1011+110 2024/09/11 1.73UT TOYOKAWA-KISO




F20240911104206




BLK:11,SNR1: 0.53415 ,SNR2: 2.8374




K20240911104202




BLK:11,SNR1: 1.6452 ,SNR2: 3.3702




1011+110 2024/09/11 1.73UT FUJI -KISO



T20240911104946





BLK: 5,SNR1: 6.2530 ,SNR2: 16.162





3C241 2024/09/11 1.86UT TOYOKAWA-FUJI



F20240911104946




BLK: 5,SNR1: 2.1110 ,SNR2: 5.7345




T20240911104946




BLK:12,SNR1: 2.4564 ,SNR2: 6.2503




K20240911104943




BLK:12,SNR1: 1.7659 ,SNR2: 5.2586




3C241 2024/09/11 1.86UT TOYOKAWA-KISO




F20240911104946




BLK:10,SNR1: 0.15138 ,SNR2: 1.9595




K20240911104943





BLK:10,SNR1: 2.2572 ,SNR2: 5.9518




3C241 2024/09/11 1.86UT FUJI -KISO



T20240911110116




BLK: 3,SNR1: 0.38013 ,SNR2: 4.6317





1031-11 2024/09/11 2.05UT TOYOKAWA-FUJI



F20240911110116




BLK: 3,SNR1: 1.2476 ,SNR2: 3.7734



T20240911110116





BLK:11,SNR1: 4.3444 ,SNR2: 13.026





1031-11 2024/09/11 2.05UT TOYOKAWA-KISO



K20240911110113




BLK:11,SNR1: 85.066 ,SNR2: 81.843




F20240911110116




BLK: 8,SNR1: 5.4267 ,SNR2: 14.452




K20240911110113




BLK: 8,SNR1: 34.357 ,SNR2: 66.021




1031-11 2024/09/11 2.05UT FUJI -KISO



T20240911110549





BLK: 5,SNR1: 0.68064 ,SNR2: 1.8717





1035-058 2024/09/11 2.13UT TOYOKAWA-FUJI



F20240911110550




BLK: 5,SNR1: 2.8494 ,SNR2: 13.787




T20240911110549




BLK: 6,SNR1: 1.2002 ,SNR2: 3.8297




K20240911110546





BLK: 6,SNR1: 107.56 ,SNR2: 100.63




1035-058 2024/09/11 2.13UT TOYOKAWA-KISO




F20240911110550




BLK: 5, SNR1: 5.2748 ,SNR2: 13.867




K20240911110546





BLK: 5, SNR1: 64.053 ,SNR2: 71.444




1035-058 2024/09/11 2.13UT FUJI -KISO




T20240911111502




BLK: 4,SNR1: 0.96301E-02,SNR2: 0.48373




F20240911111502





BLK: 4,SNR1:-0.15887E-01,SNR2: 1.0426




1044-008 2024/09/11 2.28UT TOYOKAWA-FUJI




T20240911111502




BLK: 8,SNR1: 0.29191 ,SNR2: 1.1494




K20240911111459





BLK: 8,SNR1: 59.558 ,SNR2: 90.260




1044-008 2024/09/11 2.28UT TOYOKAWA-KISO



F20240911111502





BLK: 3,SNR1:-0.55928E-01,SNR2: 0.0000




Frequency (Hz)

K20240911111459




BLK: 3,SNR1: 41.527 ,SNR2: 73.338




Frequency (Hz)


1044-008 2024/09/11 2.28UT FUJI -KISO



T20240911112606




BLK:16,SNR1: 1.7638 ,SNR2: 2.7693





1055+01 2024/09/11 2.46UT TOYOKAWA-FUJI


F20240911112607




BLK:16,SNR1: 3.2707 ,SNR2: 7.9221



T20240911112606




BLK:16,SNR1: 1.8993 ,SNR2: 3.5102





1055+01 2024/09/11 2.46UT TOYOKAWA-KISO


K20240911112603




BLK:16,SNR1: 1.8958 ,SNR2: 6.0186




F20240911112607




BLK: 6,SNR1: 0.35262 ,SNR2: 6.1680




K20240911112603







BLK: 6,SNR1: 32.720 ,SNR2: 46.859




1055+01 2024/09/11 2.46UT FUJI -KISO







1107+109 2024/09/11 2.65UT TOYOKAWA-FUJI




T20240911113724




BLK:18,SNR1: 3.2106 ,SNR2: 11.231




K20240911113721




BLK:18,SNR1: 15.544 ,SNR2: 23.375




1107+109 2024/09/11 2.65UT TOYOKAWA-KISO



F20240911113724





BLK:11,SNR1: 1.1724 ,SNR2: 4.4412





1107+109 2024/09/11 2.65UT FUJI -KISO


K20240911113721




BLK:11,SNR1: 14.473 ,SNR2: 21.273



T20240911114701




BLK:24,SNR1: 3.4787 ,SNR2: 4.8056




Frequency (Hz)

F20240911114701




BLK:24,SNR1: 2.2039 ,SNR2: 13.007




Frequency (Hz)


3C255 2024/09/11 2.81UT TOYOKAWA-FUJI




T20240911114701




BLK:25,SNR1: 3.6817 ,SNR2: 5.6024




K20240911114658




BLK:25,SNR1: 0.81229 ,SNR2: 2.9344




3C255 2024/09/11 2.81UT TOYOKAWA-KISO




F20240911114701




BLK:16,SNR1: 1.3243 ,SNR2: 10.454




K20240911114658





BLK:16,SNR1: 1.1478 ,SNR2: 4.2521




3C255 2024/09/11 2.81UT FUJI -KISO



T20240911115739





BLK:13,SNR1: 2.4675 ,SNR2: 13.634




Frequency (Hz)

F20240911115739




BLK:13,SNR1:-0.12806 ,SNR2: 1.8485





Frequency (Hz)


1127-14 2024/09/11 2.99UT TOYOKAWA-FUJI



T20240911115739





BLK:17,SNR1: 1.8134 ,SNR2: 10.432





1127-14 2024/09/11 2.99UT TOYOKAWA-KISO


K20240911115736




BLK:17,SNR1: 3.8464 ,SNR2: 13.856





F20240911115739




BLK: 9,SNR1: 0.26490 ,SNR2: 2.1545




K20240911115736




BLK: 9,SNR1: 86.177 ,SNR2: 82.911




1127-14 2024/09/11 2.99UT FUJI -KISO




T20240911121059




BLK:13,SNR1: 1.2053 ,SNR2: 5.9891




F20240911121059




BLK:13,SNR1:-0.10329 ,SNR2: 1.9216




3C263.1 2024/09/11 3.21UT TOYOKAWA-FUJI





T20240911121059




BLK:26,SNR1: 1.4765 ,SNR2: 5.7949




K20240911121056




BLK:26,SNR1: 0.65445 ,SNR2: 1.9680




3C263.1 2024/09/11 3.21UT TOYOKAWA-KISO



F20240911121059





BLK:12,SNR1:-0.23171E-01,SNR2: 0.73829





3C263.1 2024/09/11 3.21UT FUJI -KISO


K20240911121056




BLK:12,SNR1: 0.17555 ,SNR2: 1.4963



T20240911121726




BLK: 4,SNR1: 8.6737 ,SNR2: 22.313





3C267 2024/09/11 3.32UT TOYOKAWA-FUJI



F20240911121726




BLK: 4,SNR1: 5.3652 ,SNR2: 14.699



T20240911121726





BLK: 9,SNR1: 0.77110 ,SNR2: 2.8070




Frequency (Hz)

K20240911121723




BLK: 9,SNR1: 5.7461 ,SNR2: 14.680




Frequency (Hz)


3C267 2024/09/11 3.32UT TOYOKAWA-KISO



F20240911121726




BLK: 6,SNR1: 10.006 ,SNR2: 23.389





3C267 2024/09/11 3.32UT FUJI -KISO



K20240911121723




BLK: 6,SNR1: 11.133 ,SNR2: 27.825



T20240911124314




BLK: 3,SNR1: 14.735 ,SNR2: 39.727





1213-17 2024/09/11 3.75UT TOYOKAWA-FUJI



F20240911124314




BLK: 3,SNR1: 0.45866 ,SNR2: 1.8978



T20240911124314





BLK: 9,SNR1: 12.005 ,SNR2: 19.028





1213-17 2024/09/11 3.75UT TOYOKAWA-KISO


K20240911124311




BLK: 9,SNR1: 1.8757 ,SNR2: 5.2131





F20240911124314




BLK: 5,SNR1: 0.92130 ,SNR2: 1.8218




K20240911124311




BLK: 5,SNR1: 0.73224 ,SNR2: 4.1179




1213-17 2024/09/11 3.75UT FUJI -KISO




T20240911125631




BLK:18,SNR1: 18.901 ,SNR2: 37.991




F20240911125631





BLK:18,SNR1:-0.42985E-01,SNR2: 3.1137




3C273 2024/09/11 3.97UT TOYOKAWA-FUJI





T20240911125631




BLK:29,SNR1: 17.591 ,SNR2: 33.690




K20240911125629




BLK:29,SNR1: 2.3445 ,SNR2: 10.671




3C273 2024/09/11 3.97UT TOYOKAWA-KISO





F20240911125631




BLK:24,SNR1:-0.98766E-01,SNR2: 2.4005




K20240911125629





BLK:24,SNR1: 2.1672 ,SNR2: 10.446




3C273 2024/09/11 3.97UT FUJI -KISO





T20240911130942




BLK: 8,SNR1: 0.24680 ,SNR2: 3.7516




F20240911130942





BLK: 8,SNR1: 0.14958 ,SNR2: 1.6817




3C275 2024/09/11 4.19UT TOYOKAWA-FUJI





T20240911130942




BLK:13,SNR1: 0.29370 ,SNR2: 1.5387




K20240911130939





BLK:13,SNR1: 0.16711 ,SNR2: 0.97465




3C275 2024/09/11 4.19UT TOYOKAWA-KISO





F20240911130942




BLK: 5,SNR1: 0.14884 ,SNR2: 1.3761




K20240911130939





BLK: 5,SNR1:-0.31297E-01,SNR2: 1.2484




3C275 2024/09/11 4.19UT FUJI -KISO





T20240911131547




BLK: 7,SNR1: 2.2778 ,SNR2: 6.1595




F20240911131547





BLK: 7,SNR1: 1.3868 ,SNR2: 4.4571




1245-19 2024/09/11 4.29UT TOYOKAWA-FUJI





T20240911131547




BLK:14,SNR1: 1.4069 ,SNR2: 2.6337




K20240911131544




BLK:14,SNR1: 0.82229 ,SNR2: 3.8645




1245-19 2024/09/11 4.29UT TOYOKAWA-KISO





F20240911131547




BLK: 8,SNR1: 0.95192 ,SNR2: 2.9310




K20240911131544




BLK: 8,SNR1: 0.31188 ,SNR2: 1.3292




1245-19 2024/09/11 4.29UT FUJI -KISO




T20240911132331




BLK:13,SNR1: 0.58690 ,SNR2: 3.9811




F20240911132331




BLK:13,SNR1:-0.15037 ,SNR2: 1.1942




3C279 2024/09/11 4.42UT TOYOKAWA-FUJI





T20240911132331




BLK:22,SNR1: 0.80111 ,SNR2: 4.8728




K20240911132328




BLK:22,SNR1: 0.48411 ,SNR2: 2.2855




3C279 2024/09/11 4.42UT TOYOKAWA-KISO





F20240911132331




BLK: 5,SNR1: 0.73432E-01,SNR2: 4.2897




K20240911132328





BLK: 5,SNR1: 0.64386E-01,SNR2: 0.46950




3C279 2024/09/11 4.42UT FUJI -KISO




T20240911133900




BLK: 8,SNR1: 0.15792 ,SNR2: 1.6401




F20240911133900




BLK: 8,SNR1: 0.54773 ,SNR2: 4.1532




3C283 2024/09/11 4.68UT TOYOKAWA-FUJI





T20240911133900




BLK:20,SNR1: 0.31699 ,SNR2: 2.5627




K20240911133857




BLK:20,SNR1: 0.23795 ,SNR2: 1.8024




3C283 2024/09/11 4.68UT TOYOKAWA-KISO



F20240911133900





BLK:10,SNR1: 0.29765 ,SNR2: 2.9628





3C283 2024/09/11 4.68UT FUJI -KISO


K20240911133857




BLK:10,SNR1: 0.50741 ,SNR2: 3.6196





T20240911135325




BLK:10,SNR1: 0.51192 ,SNR2: 2.6689




F20240911135325




BLK:10,SNR1: 0.77129 ,SNR2: 4.9446




1323+32 2024/09/11 4.92UT TOYOKAWA-FUJI





T20240911135325




BLK:16,SNR1: 0.46679 ,SNR2: 2.6278




K20240911135322




BLK:16,SNR1: 0.41250 ,SNR2: 1.9294




1323+32 2024/09/11 4.92UT TOYOKAWA-KISO





F20240911135325




BLK: 5,SNR1: 0.44832 ,SNR2: 2.4265




K20240911135322





BLK: 5,SNR1: 0.75104 ,SNR2: 4.8363




1323+32 2024/09/11 4.92UT FUJI -KISO



T20240911135815





BLK:18,SNR1: 2.7934 ,SNR2: 19.070





3C286 2024/09/11 5.00UT TOYOKAWA-FUJI


F20240911135815




BLK:18,SNR1: 0.25495 ,SNR2: 2.1840



T20240911135815





BLK:14,SNR1: 2.6392 ,SNR2: 11.876




Frequency (Hz)

3C286 2024/09/11 5.00UT TOYOKAWA-KISO


K20240911135812





BLK:14,SNR1: 3.7416 ,SNR2: 10.507




Frequency (Hz)



F20240911135815





BLK:15,SNR1: 9.1285 ,SNR2: 22.665





3C286 2024/09/11 5.00UT FUJI -KISO


K20240911135812




BLK:15,SNR1: 1.9634 ,SNR2: 4.9642





T20240911141442




BLK:12,SNR1: 0.71256 ,SNR2: 3.4118




F20240911141442




BLK:12,SNR1: 0.24909 ,SNR2: 1.1858




1345+12 2024/09/11 5.27UT TOYOKAWA-FUJI





T20240911141442




BLK:17,SNR1: 0.70341 ,SNR2: 3.7513




K20240911141439




BLK:17,SNR1: 16.742 ,SNR2: 34.958




1345+12 2024/09/11 5.27UT TOYOKAWA-KISO





F20240911141442




BLK: 8,SNR1: 0.19608 ,SNR2: 1.3652




K20240911141439





BLK: 8,SNR1: 16.461 ,SNR2: 34.310




1345+12 2024/09/11 5.27UT FUJI -KISO




T20240911142502




BLK: 5,SNR1: 0.68459 ,SNR2: 5.7288




F20240911142502





BLK: 5,SNR1:-0.12543 ,SNR2: 1.0829




1355+01 2024/09/11 5.45UT TOYOKAWA-FUJI





T20240911142502




BLK: 6,SNR1: 0.42445 ,SNR2: 2.6228




K20240911142500




BLK: 6,SNR1: 6.6021 ,SNR2: 33.011




1355+01 2024/09/11 5.45UT TOYOKAWA-KISO





F20240911142502




BLK: 4,SNR1: 0.15234 ,SNR2: 2.3745




K20240911142500





BLK: 4,SNR1: 23.556 ,SNR2: 50.121




1355+01 2024/09/11 5.45UT FUJI -KISO



T20240911144613




BLK:14,SNR1: 2.4225 ,SNR2: 11.626




Frequency (Hz)

F20240911144613




BLK:14,SNR1: 0.32691E-01,SNR2: 1.8973





Frequency (Hz)


3C298 2024/09/11 5.80UT TOYOKAWA-FUJI



T20240911144613





BLK:24,SNR1: 1.8423 ,SNR2: 9.2444




Frequency (Hz)

K20240911144610




BLK:24,SNR1: 2.0275 ,SNR2: 4.5392





Frequency (Hz)


3C298 2024/09/11 5.80UT TOYOKAWA-KISO



F20240911144613





BLK:13,SNR1: 1.2025 ,SNR2: 2.5417




Frequency (Hz)

K20240911144610




BLK:13,SNR1: 4.8616 ,SNR2: 10.527




Frequency (Hz)


3C298 2024/09/11 5.80UT FUJI -KISO



T20240911145757





No.Good Data




Frequency (Hz)

F20240911145757




No.Good Data





Frequency (Hz)


1428-03 2024/09/11 5.99UT TOYOKAWA-FUJI




T20240911145757




BLK: 3,SNR1: 0.67439E-01,SNR2: 1.1600




K20240911145755




BLK: 3,SNR1: 0.79551E-01,SNR2: 1.8336




1428-03 2024/09/11 5.99UT TOYOKAWA-KISO



F20240911145757




BLK: 3,SNR1: 0.59587 ,SNR2: 2.3616




Frequency (Hz)

K20240911145755




BLK: 3,SNR1: 0.44683 ,SNR2: 1.9582




Frequency (Hz)


1428-03 2024/09/11 5.99UT FUJI -KISO



T20240911150638




BLK: 1,SNR1:-0.29102 ,SNR2: 0.69687




Frequency (Hz)

F20240911150638




BLK: 1,SNR1: 0.61431 ,SNR2: 4.7271





Frequency (Hz)


1436-16 2024/09/11 6.14UT TOYOKAWA-FUJI





T20240911150638




BLK: 4,SNR1: 0.46788 ,SNR2: 1.5123




K20240911150636





BLK: 4,SNR1: 0.18541 ,SNR2: 0.42999




1436-16 2024/09/11 6.14UT TOYOKAWA-KISO



F20240911150638





BLK: 6,SNR1: 1.4436 ,SNR2: 10.702




Frequency (Hz)

K20240911150636




BLK: 6,SNR1: 1.1355 ,SNR2: 3.3616





Frequency (Hz)


1436-16 2024/09/11 6.14UT FUJI -KISO



T20240911152301





No.Good Data




Frequency (Hz)

F20240911152301




No.Good Data





Frequency (Hz)


1453-10 2024/09/11 6.41UT TOYOKAWA-FUJI





T20240911152301




BLK: 3,SNR1: 0.16070 ,SNR2: 1.4280




K20240911152258





BLK: 3,SNR1:-0.85287E-01,SNR2: 1.0881




1453-10 2024/09/11 6.41UT TOYOKAWA-KISO



F20240911152301





BLK: 1,SNR1: 0.79923 ,SNR2: 10.440




Frequency (Hz)

K20240911152258




BLK: 1,SNR1: 0.20109 ,SNR2: 1.0320





Frequency (Hz)


1453-10 2024/09/11 6.41UT FUJI -KISO





T20240911153753




No.Good Data




F20240911153753





No.Good Data




1508-05 2024/09/11 6.66UT TOYOKAWA-FUJI



T20240911153753





BLK: 2,SNR1: 0.34380 ,SNR2: 11.001




Frequency (Hz)

K20240911153751




BLK: 2,SNR1: 41.914 ,SNR2: 72.963




Frequency (Hz)


1508-05 2024/09/11 6.66UT TOYOKAWA-KISO





F20240911153753




BLK: 1,SNR1: 0.75917 ,SNR2: 5.5367




K20240911153751





BLK: 1,SNR1: 117.54 ,SNR2: 179.29




1508-05 2024/09/11 6.66UT FUJI -KISO




T20240911154653




BLK: 7,SNR1: 0.27657 ,SNR2: 0.85836




F20240911154653





BLK: 7,SNR1:-0.87034E-01,SNR2: 1.0732




3C318 2024/09/11 6.81UT TOYOKAWA-FUJI





T20240911154653




BLK:11,SNR1: 0.25076 ,SNR2: 1.6899




K20240911154651




BLK:11,SNR1: 5.6588 ,SNR2: 13.469




3C318 2024/09/11 6.81UT TOYOKAWA-KISO



F20240911154653




BLK: 4,SNR1: 0.11368 ,SNR2: 3.5361




Frequency (Hz)

K20240911154651




BLK: 4,SNR1: 5.4650 ,SNR2: 16.136





Frequency (Hz)


3C318 2024/09/11 6.81UT FUJI -KISO




T20240911155240




BLK: 6,SNR1:-0.52007E-02,SNR2: 0.99552




F20240911155240





BLK: 6,SNR1: 3.3395 ,SNR2: 7.2243




1523+03 2024/09/11 6.91UT TOYOKAWA-FUJI




T20240911155240




BLK: 9,SNR1:-0.10449E-01,SNR2: 0.96087




K20240911155238




BLK: 9,SNR1: 1.3706 ,SNR2: 3.1536




1523+03 2024/09/11 6.91UT TOYOKAWA-KISO



F20240911155240




BLK:10,SNR1: 3.3188 ,SNR2: 8.4014




Frequency (Hz)

K20240911155238




BLK:10,SNR1: 1.4071 ,SNR2: 4.4174





Frequency (Hz)


1523+03 2024/09/11 6.91UT FUJI -KISO




T20240911160420




BLK: 6,SNR1: 0.44113E-01,SNR2: 0.67146




F20240911160420




BLK: 6,SNR1: 1.9917 ,SNR2: 5.7452




1535+139 2024/09/11 7.10UT TOYOKAWA-FUJI



T20240911160420





BLK: 9,SNR1: 0.47844E-01,SNR2: 0.62629




Frequency (Hz)

K20240911160418




BLK: 9,SNR1: 1.9007 ,SNR2: 4.2720




Frequency (Hz)


1535+139 2024/09/11 7.10UT TOYOKAWA-KISO



F20240911160420




BLK: 6,SNR1: 7.2021 ,SNR2: 18.465




Frequency (Hz)

K20240911160418




BLK: 6,SNR1: 0.86833 ,SNR2: 2.1342





Frequency (Hz)


1535+139 2024/09/11 7.10UT FUJI -KISO




T20240911161444




BLK: 5, SNR1: 0.36976E-01, SNR2: 1.3017




F20240911161445





BLK: 5, SNR1: 8.6068, SNR2: 26.547




1545-12 2024/09/11 7.27UT TOYOKAWA-FUJI



T20240911161444




BLK: 4,SNR1: 0.16540 ,SNR2: 1.2374




Frequency (Hz)

K20240911161442




BLK: 4,SNR1: 2.2361 ,SNR2: 5.1676




Frequency (Hz)


1545-12 2024/09/11 7.27UT TOYOKAWA-KISO



F20240911161445




BLK: 8,SNR1: 7.2972 ,SNR2: 22.575




Frequency (Hz)

K20240911161442




BLK: 8,SNR1: 2.8475 ,SNR2: 7.7203





Frequency (Hz)


1545-12 2024/09/11 7.27UT FUJI -KISO



T20240911163547




BLK: 6,SNR1: 0.26493 ,SNR2: 0.61181




Frequency (Hz)

F20240911163548




BLK: 6,SNR1: 4.9179 ,SNR2: 13.661





Frequency (Hz)


1607+26 2024/09/11 7.62UT TOYOKAWA-FUJI



T20240911163547




BLK: 8,SNR1: 0.58842 ,SNR2: 1.4806




Frequency (Hz)

K20240911163545




BLK: 8,SNR1: 11.147 ,SNR2: 28.773





Frequency (Hz)


1607+26 2024/09/11 7.62UT TOYOKAWA-KISO



F20240911163548




BLK: 6,SNR1: 1.9392 ,SNR2: 6.0001




Frequency (Hz)

K20240911163545




BLK: 6,SNR1: 59.146 ,SNR2: 62.867





Frequency (Hz)


1607+26 2024/09/11 7.62UT FUJI -KISO



T20240911165317





BLK: 4,SNR1: 0.15805 ,SNR2: 2.2745




Frequency (Hz)

F20240911165317




BLK: 4,SNR1: 0.29096 ,SNR2: 2.2763





Frequency (Hz)


1623-228 2024/09/11 7.92UT TOYOKAWA-FUJI



T20240911165317





BLK: 2,SNR1: 0.20597 ,SNR2: 1.2178




Frequency (Hz)

K20240911165315




BLK: 2,SNR1: 0.93604 ,SNR2: 2.9229




Frequency (Hz)


1623-228 2024/09/11 7.92UT TOYOKAWA-KISO



F20240911165317





BLK: 1,SNR1:-0.15326 ,SNR2: 0.0000




Frequency (Hz)

K20240911165315



BLK: 1,SNR1:-0.17912 ,SNR2: 0.95276E-01



Frequency (Hz)

1623-228 2024/09/11 7.92UT FUJI -KISO

