




T20240913062517





BLK: 4,SNR1: 0.28904 ,SNR2: 1.9411




Frequency (Hz)

F20240913062518




BLK: 4,SNR1: 0.84630 ,SNR2: 2.7701





Frequency (Hz)


3C152 2024/09/12 21.45UT TOYOKAWA-FUJI





T20240913062517




BLK: 8,SNR1: 0.18327 ,SNR2: 0.98283




K20240913062515



BLK: 8,SNR1: 3.2524 ,SNR2: 6.7920





3C152 2024/09/12 21.45UT TOYOKAWA-KISO






F20240913062518





BLK: 6,SNR1: 0.97430 ,SNR2: 2.9520




Frequency (Hz)

3C152 2024/09/12 21.45UT FUJI -KISO


K20240913062515




BLK: 6,SNR1: 2.4270 ,SNR2: 9.3795




Frequency (Hz)



T20240913064738





BLK:10,SNR1: 0.31323 ,SNR2: 2.5021




Frequency (Hz)

3C161 2024/09/12 21.82UT TOYOKAWA-FUJI


F20240913064738





BLK:10,SNR1: 0.66414 ,SNR2: 2.9733




Frequency (Hz)



T20240913064738




BLK:14,SNR1: 0.29270 ,SNR2: 2.0872





3C161 2024/09/12 21.82UT TOYOKAWA-KISO



K20240913064736




BLK:14,SNR1: 3.7563 ,SNR2: 8.0664



F20240913064738





BLK: 9,SNR1: 0.19603 ,SNR2: 1.9777




Frequency (Hz)

K20240913064736





BLK: 9,SNR1: 2.3800 ,SNR2: 6.0812





Frequency (Hz)

3C161 2024/09/12 21.82UT FUJI -KISO







BLK: 7,SNR1: 3.4528 ,SNR2: 5.6653





BLK: 7,SNR1: 2.7476 ,SNR2: 6.2275




0652-130 2024/09/12 22.28UT TOYOKAWA-FUJI



T20240913071511





BLK:13,SNR1: 0.99339 ,SNR2: 4.7719




Frequency (Hz)

K20240913071509




BLK:13,SNR1: 6.9725 ,SNR2: 12.719





Frequency (Hz)


0652-130 2024/09/12 22.28UT TOYOKAWA-KISO



F20240913071511





BLK:16,SNR1: 2.1285 ,SNR2: 5.1985




Frequency (Hz)

K20240913071509




BLK:16,SNR1: 4.1770 ,SNR2: 17.484





Frequency (Hz)


0652-130 2024/09/12 22.28UT FUJI -KISO



T20240913072647





BLK: 5,SNR1: 0.19563E-01,SNR2: 1.0047




Frequency (Hz)

F20240913072648




BLK: 5,SNR1: 3.6165 ,SNR2: 9.2369





Frequency (Hz)

0703+138 2024/09/12 22.47UT TOYOKAWA-FUJI






T20240913072647





BLK: 3,SNR1:-0.58112E-01,SNR2: 0.85837




Frequency (Hz)

K20240913072645




BLK: 3,SNR1: 8.0867 ,SNR2: 21.543




Frequency (Hz)


0703+138 2024/09/12 22.47UT TOYOKAWA-KISO



F20240913072648




BLK: 7,SNR1: 2.7304 ,SNR2: 7.4570




Frequency (Hz)

K20240913072645




BLK: 7,SNR1: 6.0605 ,SNR2: 15.582





Frequency (Hz)


0703+138 2024/09/12 22.47UT FUJI -KISO



T20240913073610





BLK: 3,SNR1: 0.21961 ,SNR2: 2.0933




Frequency (Hz)

F20240913073610




BLK: 3,SNR1: 0.33938 ,SNR2: 2.0040





Frequency (Hz)


0713-024 2024/09/12 22.63UT TOYOKAWA-FUJI



T20240913073610





BLK: 1, SNR1: -0.23464 , SNR2: 0.14124




Frequency (Hz)

K20240913073608




BLK: 1, SNR1: 4.2617 , SNR2: 21.583





Frequency (Hz)


0713-024 2024/09/12 22.63UT TOYOKAWA-KISO



F20240913073610





BLK: 3,SNR1: 1.5141 ,SNR2: 12.326




Frequency (Hz)

K20240913073608




BLK: 3,SNR1: 0.68798 ,SNR2: 1.8077





Frequency (Hz)


0713-024 2024/09/12 22.63UT FUJI -KISO



T20240913074622




BLK: 2,SNR1: 1.0906 ,SNR2: 4.7500




Frequency (Hz)

0723+10 2024/09/12 22.80UT TOYOKAWA-FUJI


F20240913074622





BLK: 2,SNR1: 0.36530 ,SNR2: 2.3974




Frequency (Hz)



T20240913074622





BLK: 7,SNR1: 0.56478E-01,SNR2: 1.5341




Frequency (Hz)

0723+10 2024/09/12 22.80UT TOYOKAWA-KISO


K20240913074620





BLK: 7,SNR1: 2.0051 ,SNR2: 4.1556




Frequency (Hz)



F20240913074622





BLK: 3,SNR1: 0.36957 ,SNR2: 1.3585




Frequency (Hz)

K20240913074620




BLK: 3,SNR1: 1.0486 ,SNR2: 4.1714





Frequency (Hz)

0723+10 2024/09/12 22.80UT FUJI -KISO






T20240913075636





BLK: 4,SNR1: 0.60463 ,SNR2: 2.4752




Frequency (Hz)

F20240913075636




BLK: 4,SNR1: 0.63273 ,SNR2: 2.3859





Frequency (Hz)


0732+33 2024/09/12 22.97UT TOYOKAWA-FUJI



T20240913075636





BLK: 6,SNR1:-0.22273E-01,SNR2: 0.26289




Frequency (Hz)

K20240913075634




BLK: 6,SNR1: 20.453 ,SNR2: 48.470




Frequency (Hz)


0732+33 2024/09/12 22.97UT TOYOKAWA-KISO



F20240913075636





BLK: 7,SNR1: 0.75981 ,SNR2: 3.1697




Frequency (Hz)

K20240913075634




BLK: 7,SNR1: 21.975 ,SNR2: 36.687




Frequency (Hz)


0732+33 2024/09/12 22.97UT FUJI -KISO



T20240913080438





BLK:10,SNR1: 8.9487 ,SNR2: 26.314




Frequency (Hz)

F20240913080438




BLK:10,SNR1: 14.451 ,SNR2: 35.983




Frequency (Hz)


0741-06 2024/09/12 23.11UT TOYOKAWA-FUJI



T20240913080438




BLK:12,SNR1: 8.7642 ,SNR2: 22.557




Frequency (Hz)

K20240913080436




BLK:12,SNR1: 9.3170 ,SNR2: 23.302




Frequency (Hz)


0741-06 2024/09/12 23.11UT TOYOKAWA-KISO



F20240913080438




BLK:14,SNR1: 7.7004 ,SNR2: 21.705




Frequency (Hz)

K20240913080436




BLK:14,SNR1: 7.8854 ,SNR2: 19.798





Frequency (Hz)


0741-06 2024/09/12 23.11UT FUJI -KISO



T20240913081423





BLK: 4,SNR1: 7.3971 ,SNR2: 21.324




Frequency (Hz)

0752-200 2024/09/12 23.27UT TOYOKAWA-FUJI


F20240913081423





BLK: 4,SNR1: 12.380 ,SNR2: 30.618




Frequency (Hz)



T20240913081423





BLK: 6,SNR1: 11.180 ,SNR2: 27.126




Frequency (Hz)

0752-200 2024/09/12 23.27UT TOYOKAWA-KISO


K20240913081420



BLK: 6,SNR1: 11.530 ,SNR2: 28.438





Frequency (Hz)







F20240913081423




BLK: 7,SNR1: 10.701 ,SNR2: 26.967




K20240913081420





BLK: 7,SNR1: 9.3553 ,SNR2: 23.943




0752-200 2024/09/12 23.27UT FUJI -KISO



T20240913082158





BLK: 3,SNR1: 0.81288E-01,SNR2: 0.45083




Frequency (Hz)

F20240913082158




BLK: 3,SNR1:-0.44607E-01,SNR2: 1.0369





Frequency (Hz)


3C190 2024/09/12 23.39UT TOYOKAWA-FUJI



T20240913082158





BLK: 6,SNR1: 0.98692E-01,SNR2: 0.28047




Frequency (Hz)

K20240913082155




BLK: 6,SNR1: 1.3333 ,SNR2: 8.6595




Frequency (Hz)


3C190 2024/09/12 23.39UT TOYOKAWA-KISO



F20240913082158




BLK: 4,SNR1: 1.2558 ,SNR2: 3.7673




Frequency (Hz)

3C190 2024/09/12 23.39UT FUJI -KISO


K20240913082155





BLK: 4,SNR1: 0.60858 ,SNR2: 1.3859




Frequency (Hz)



T20240913083422




BLK:11,SNR1: 0.96152 ,SNR2: 2.6304




Frequency (Hz)

3C196 2024/09/12 23.60UT TOYOKAWA-FUJI


F20240913083422





BLK:11,SNR1: 7.0275 ,SNR2: 19.073




Frequency (Hz)



T20240913083422





BLK:11,SNR1: 0.77395 ,SNR2: 2.0570




Frequency (Hz)

K20240913083419




BLK:11,SNR1: 8.3109 ,SNR2: 21.656




Frequency (Hz)


3C196 2024/09/12 23.60UT TOYOKAWA-KISO



F20240913083422





BLK:10,SNR1: 7.0075 ,SNR2: 18.465




Frequency (Hz)

3C196 2024/09/12 23.60UT FUJI -KISO


K20240913083419




BLK:10,SNR1: 6.6869 ,SNR2: 19.327




Frequency (Hz)



T20240913084532




BLK: 2,SNR1: 1.6224 ,SNR2: 5.8684





0821+394 2024/09/12 23.79UT TOYOKAWA-FUJI

F20240913084532





BLK: 2,SNR1: 2.5933 ,SNR2: 8.6798






T20240913084532





BLK: 5,SNR1: 2.5032 ,SNR2: 7.4938




Frequency (Hz)

K20240913084529




BLK: 5,SNR1: 8.1152 ,SNR2: 15.907





Frequency (Hz)


0821+394 2024/09/12 23.79UT TOYOKAWA-KISO



F20240913084532





BLK: 6,SNR1: 0.97049E-01,SNR2: 2.0089




Frequency (Hz)

K20240913084529




BLK: 6,SNR1: 5.0261 ,SNR2: 15.607





Frequency (Hz)


0821+394 2024/09/12 23.79UT FUJI -KISO



T20240913085338




BLK: 2,SNR1: 0.14676 ,SNR2: 2.0201




Frequency (Hz)

F20240913085338




BLK: 2,SNR1: 0.18576 ,SNR2: 2.9151





Frequency (Hz)


0830+116 2024/09/12 23.92UT TOYOKAWA-FUJI



T20240913085338





BLK: 6,SNR1: 0.41731 ,SNR2: 2.1841




Frequency (Hz)

K20240913085335




BLK: 6,SNR1: 86.307 ,SNR2: 84.234




Frequency (Hz)


0830+116 2024/09/12 23.92UT TOYOKAWA-KISO



F20240913085338





BLK: 4,SNR1: 0.62940 ,SNR2: 1.3925




Frequency (Hz)

K20240913085335




BLK: 4,SNR1: 0.21156 ,SNR2: 2.4611





Frequency (Hz)


0830+116 2024/09/12 23.92UT FUJI -KISO



T20240913090217





BLK:11,SNR1: 32.807 ,SNR2: 37.870




Frequency (Hz)

F20240913090217




BLK:11,SNR1: 6.7080 ,SNR2: 19.673





Frequency (Hz)


0839-071 2024/09/13 0.07UT TOYOKAWA-FUJI



T20240913090217





BLK:17,SNR1: 7.6357 ,SNR2: 22.110




Frequency (Hz)

0839-071 2024/09/13 0.07UT TOYOKAWA-KISO


K20240913090214





BLK:17,SNR1: 21.561 ,SNR2: 25.804




Frequency (Hz)



F20240913090217





BLK:14,SNR1: 3.1156 ,SNR2: 7.5922




Frequency (Hz)

K20240913090214




BLK:14,SNR1: 9.4921 ,SNR2: 27.170





Frequency (Hz)

0839-071 2024/09/13 0.07UT FUJI -KISO






T20240913091318





BLK: 5, SNR1: 3.2779 , SNR2: 7.0533




Frequency (Hz)

3C208 2024/09/13 0.25UT TOYOKAWA-FUJI


F20240913091318





BLK: 5, SNR1: 5.4517 , SNR2: 12.986




Frequency (Hz)



T20240913091318





BLK: 7,SNR1: 11.170 ,SNR2: 32.398





3C208 2024/09/13 0.25UT TOYOKAWA-KISO



K20240913091315




BLK: 7,SNR1: 7.3764 ,SNR2: 18.459



F20240913091318





BLK: 6,SNR1: 5.7312 ,SNR2: 14.646




Frequency (Hz)

K20240913091315




BLK: 6,SNR1: 8.5433 ,SNR2: 23.686





Frequency (Hz)


3C208 2024/09/13 0.25UT FUJI -KISO



T20240913093000




BLK: 8,SNR1: 0.44130 ,SNR2: 1.9285




Frequency (Hz)

F20240913093000




BLK: 8,SNR1: 0.72575 ,SNR2: 1.9896





Frequency (Hz)


3C216 2024/09/13 0.53UT TOYOKAWA-FUJI




T20240913093000




BLK: 4,SNR1: 0.40088 ,SNR2: 1.0466




K20240913092957




BLK: 4,SNR1: 20.268 ,SNR2: 33.747




3C216 2024/09/13 0.53UT TOYOKAWA-KISO



F20240913093000




BLK: 5,SNR1: 0.35242 ,SNR2: 2.3415





3C216 2024/09/13 0.53UT FUJI -KISO



K20240913092957




BLK: 5,SNR1: 6.6006 ,SNR2: 25.359



T20240913094211




BLK: 5, SNR1: 1.5518 , SNR2: 4.4835




Frequency (Hz)

F20240913094211




BLK: 5, SNR1: 1.1551 , SNR2: 2.5660





Frequency (Hz)


0919-142 2024/09/13 0.73UT TOYOKAWA-FUJI





T20240913094211




BLK: 6,SNR1: 0.85644 ,SNR2: 2.6429




K20240913094208



BLK: 6,SNR1: 2.7828 ,SNR2: 7.0748





0919-142 2024/09/13 0.73UT TOYOKAWA-KISO








F20240913094211




BLK: 2,SNR1:-0.31015 ,SNR2: 0.66121




K20240913094208




BLK: 2,SNR1: 2.1994 ,SNR2: 5.4509




0919-142 2024/09/13 0.73UT FUJI -KISO




T20240913094850




BLK: 3,SNR1: 4.6773 ,SNR2: 14.098




F20240913094850




BLK: 3,SNR1: 7.1291 ,SNR2: 18.092




0926+117 2024/09/13 0.84UT TOYOKAWA-FUJI



T20240913094850





BLK:10,SNR1: 5.4267 ,SNR2: 13.518




Frequency (Hz)

0926+117 2024/09/13 0.84UT TOYOKAWA-KISO


K20240913094847





BLK:10,SNR1: 9.6821 ,SNR2: 24.503




Frequency (Hz)



F20240913094850





BLK:10,SNR1: 6.5736 ,SNR2: 16.704





0926+117 2024/09/13 0.84UT FUJI -KISO



K20240913094847




BLK:10,SNR1: 8.0912 ,SNR2: 20.621





T20240913095635




BLK: 6,SNR1: 6.7983 ,SNR2: 17.755




F20240913095636





BLK: 6,SNR1: 7.6174 ,SNR2: 19.699




3C222 2024/09/13 0.97UT TOYOKAWA-FUJI



T20240913095635





BLK: 9, SNR1: 10.610 , SNR2: 25.867




Frequency (Hz)

3C222 2024/09/13 0.97UT TOYOKAWA-KISO


K20240913095632





BLK: 9, SNR1: 12.670 , SNR2: 30.555




Frequency (Hz)



F20240913095636





BLK:12,SNR1: 7.3063 ,SNR2: 18.877





3C222 2024/09/13 0.97UT FUJI -KISO


K20240913095632




BLK:12,SNR1: 10.742 ,SNR2: 25.313



T20240913100335




BLK: 6,SNR1: 0.26394 ,SNR2: 1.1759





0941-08 2024/09/13 1.09UT TOYOKAWA-FUJI

F20240913100335




BLK: 6,SNR1: 0.17512 ,SNR2: 4.8022






T20240913100335




BLK:10,SNR1: 0.56932 ,SNR2: 1.6060





0941-08 2024/09/13 1.09UT TOYOKAWA-KISO



K20240913100332




BLK:10,SNR1: 3.6037 ,SNR2: 9.4981



F20240913100335





BLK: 7,SNR1: 0.24611 ,SNR2: 3.5343




Frequency (Hz)

K20240913100332




BLK: 7,SNR1: 2.3468 ,SNR2: 7.2526




Frequency (Hz)


0941-08 2024/09/13 1.09UT FUJI -KISO




T20240913101157




BLK:11,SNR1: 1.0454 ,SNR2: 4.0100




F20240913101157




BLK:11,SNR1: 3.4289 ,SNR2: 10.147




3C230 2024/09/13 1.23UT TOYOKAWA-FUJI



T20240913101157





BLK:17,SNR1: 1.6617 ,SNR2: 5.2564




Frequency (Hz)

3C230 2024/09/13 1.23UT TOYOKAWA-KISO


K20240913101154




BLK:17,SNR1: 3.9310 ,SNR2: 10.487




Frequency (Hz)



F20240913101157




BLK: 8,SNR1: 3.1118 ,SNR2: 9.5994





3C230 2024/09/13 1.23UT FUJI -KISO



K20240913101154




BLK: 8,SNR1: 2.2282 ,SNR2: 6.6144



T20240913102604




BLK: 7, SNR1: 3.6257 , SNR2: 8.7713





3C236 2024/09/13 1.46UT TOYOKAWA-FUJI



F20240913102604




BLK: 7, SNR1: 0.18364 , SNR2: 1.9236



T20240913102604





BLK:10,SNR1: 0.24901 ,SNR2: 1.7036




Frequency (Hz)

3C236 2024/09/13 1.46UT TOYOKAWA-KISO


K20240913102601




BLK:10,SNR1: 1.2895 ,SNR2: 3.7865




Frequency (Hz)





F20240913102604




BLK: 7,SNR1: 1.0459 ,SNR2: 2.6594




K20240913102601



BLK: 7,SNR1: 1.7477 ,SNR2: 5.1858





3C236 2024/09/13 1.46UT FUJI -KISO








T20240913103414




BLK: 6,SNR1: 0.34613 ,SNR2: 1.4306




F20240913103414





BLK: 6,SNR1: 7.7507 ,SNR2: 18.756




1011+110 2024/09/13 1.60UT TOYOKAWA-FUJI



T20240913103414




BLK: 7,SNR1: 0.67592E-01,SNR2: 1.9903




Frequency (Hz)

K20240913103411




BLK: 7,SNR1: 1.8345 ,SNR2: 5.3575





Frequency (Hz)


1011+110 2024/09/13 1.60UT TOYOKAWA-KISO




F20240913103414




BLK: 5,SNR1: 1.0429 ,SNR2: 6.6899




K20240913103411





BLK: 5,SNR1: 1.6898 ,SNR2: 4.2952




1011+110 2024/09/13 1.60UT FUJI -KISO




T20240913104155




BLK: 8,SNR1:-0.40338 ,SNR2: 0.92861




F20240913104155




BLK: 8,SNR1: 22.390 ,SNR2: 29.158




3C241 2024/09/13 1.73UT TOYOKAWA-FUJI



T20240913104155




BLK: 4,SNR1: 1.4145 ,SNR2: 9.1156





3C241 2024/09/13 1.73UT TOYOKAWA-KISO


K20240913104152




BLK: 4,SNR1: 13.735 ,SNR2: 17.294



F20240913104155




BLK: 5,SNR1:-0.47246 ,SNR2: 0.52568





3C241 2024/09/13 1.73UT FUJI -KISO


K20240913104152




BLK: 5,SNR1: 21.841 ,SNR2: 27.573



T20240913105324




BLK: 8,SNR1: 8.6632 ,SNR2: 22.696





1031-11 2024/09/13 1.92UT TOYOKAWA-FUJI


F20240913105324




BLK: 8,SNR1: 7.8383 ,SNR2: 22.420



T20240913105324





BLK:11,SNR1: 9.3189 ,SNR2: 23.339





1031-11 2024/09/13 1.92UT TOYOKAWA-KISO

K20240913105321




BLK:11,SNR1: 10.808 ,SNR2: 27.490







F20240913105324




BLK:10,SNR1: 9.5234 ,SNR2: 23.069




K20240913105321




BLK:10,SNR1: 11.203 ,SNR2: 29.189




1031-11 2024/09/13 1.92UT FUJI -KISO




T20240913105757




BLK: 4,SNR1: 0.57002E-01,SNR2: 2.6335




F20240913105757





BLK: 4,SNR1:-0.12650 ,SNR2: 1.0145




1035-058 2024/09/13 1.99UT TOYOKAWA-FUJI




T20240913105757




BLK: 6,SNR1: 0.13009 ,SNR2: 0.97795




K20240913105754





BLK: 6,SNR1: 2.0049 ,SNR2: 7.1735




1035-058 2024/09/13 1.99UT TOYOKAWA-KISO



F20240913105757





BLK: 4, SNR1: 2.1365 ,SNR2: 6.2944




Frequency (Hz)

K20240913105754




BLK: 4, SNR1: 1.5320 ,SNR2: 5.2216





Frequency (Hz)


1035-058 2024/09/13 1.99UT FUJI -KISO





T20240913110710




BLK: 9,SNR1: 2.3490 ,SNR2: 6.7803




F20240913110710





BLK: 9,SNR1: 6.3815 ,SNR2: 16.285




1044-008 2024/09/13 2.15UT TOYOKAWA-FUJI




T20240913110710




BLK: 8,SNR1: 0.53561 ,SNR2: 1.8083




K20240913110707




BLK: 8,SNR1: 71.876 ,SNR2: 90.638




1044-008 2024/09/13 2.15UT TOYOKAWA-KISO





F20240913110710




BLK: 9,SNR1: 7.1058 ,SNR2: 18.999




K20240913110707






BLK: 9,SNR1: 105.71 ,SNR2: 98.447






1044-008 2024/09/13 2.15UT FUJI -KISO



T20240913111814





F20240913111814







T20240913111814




BLK: 7, SNR1: 9.9854 , SNR2: 24.840




K20240913111811





BLK: 7, SNR1: 7.8264 , SNR2: 19.968




1055+01 2024/09/13 2.33UT TOYOKAWA-KISO



F20240913111814





BLK: 6,SNR1: 5.7877 ,SNR2: 15.845




Frequency (Hz)

1055+01 2024/09/13 2.33UT FUJI -KISO


K20240913111811





BLK: 6,SNR1: 6.0067 ,SNR2: 15.914




Frequency (Hz)




T20240913112932




BLK:10,SNR1: 1.4478 ,SNR2: 3.4794




F20240913112932





BLK:10,SNR1: 16.125 ,SNR2: 37.815




1107+109 2024/09/13 2.52UT TOYOKAWA-FUJI



T20240913112932





BLK: 6,SNR1: 10.540 ,SNR2: 26.198





1107+109 2024/09/13 2.52UT TOYOKAWA-KISO


K20240913112929




BLK: 6,SNR1: 12.381 ,SNR2: 31.243





F20240913112932




BLK: 9,SNR1: 16.041 ,SNR2: 37.647




K20240913112929




BLK: 9,SNR1: 12.388 ,SNR2: 30.887




1107+109 2024/09/13 2.52UT FUJI -KISO



T20240913113909




BLK:19,SNR1: 4.9472 ,SNR2: 14.266





3C255 2024/09/13 2.68UT TOYOKAWA-FUJI


F20240913113909




BLK:19,SNR1: 72.462 ,SNR2: 83.577




T20240913113909




BLK:13,SNR1: 2.4015 ,SNR2: 7.1899




K20240913113906




BLK:13,SNR1: 5.4744 ,SNR2: 13.901




3C255 2024/09/13 2.68UT TOYOKAWA-KISO



F20240913113909




BLK:13,SNR1: 78.996 ,SNR2: 88.112





3C255 2024/09/13 2.68UT FUJI -KISO

K20240913113906





BLK:13,SNR1: 5.7209 ,SNR2: 15.456







T20240913114947




BLK: 6,SNR1: 0.95458 ,SNR2: 3.2317




F20240913114947





BLK: 6,SNR1: 2.4380 ,SNR2: 7.0205




1127-14 2024/09/13 2.86UT TOYOKAWA-FUJI



T20240913114947




BLK:11,SNR1: 1.0038 ,SNR2: 3.4089





1127-14 2024/09/13 2.86UT TOYOKAWA-KISO


K20240913114944




BLK:11,SNR1: 8.4653 ,SNR2: 21.242



F20240913114947





BLK: 8,SNR1: 3.1910 ,SNR2: 8.1797





1127-14 2024/09/13 2.86UT FUJI -KISO



K20240913114944




BLK: 8,SNR1: 7.7453 ,SNR2: 18.918



T20240913120307




BLK:12,SNR1: 0.49077 ,SNR2: 5.7396





3C263.1 2024/09/13 3.08UT TOYOKAWA-FUJI



F20240913120307




BLK:12,SNR1:-0.91901E-01,SNR2: 1.5361





T20240913120307




BLK:20,SNR1: 0.38204 ,SNR2: 2.4326




K20240913120304




BLK:20,SNR1: 0.12761 ,SNR2: 0.58701




3C263.1 2024/09/13 3.08UT TOYOKAWA-KISO





F20240913120307




BLK: 6,SNR1: 0.49680E-01,SNR2: 1.4142




K20240913120304





BLK: 6,SNR1: 0.65556E-01,SNR2: 0.51189




3C263.1 2024/09/13 3.08UT FUJI -KISO



T20240913120934




BLK:10,SNR1: 0.70292 ,SNR2: 2.7949





3C267 2024/09/13 3.19UT TOYOKAWA-FUJI



F20240913120934




BLK:10,SNR1: 3.0533 ,SNR2: 7.9787




T20240913120934




BLK:14,SNR1: 0.55069 ,SNR2: 1.8989




K20240913120931



BLK:14,SNR1: 3.8836 ,SNR2: 10.405





3C267 2024/09/13 3.19UT TOYOKAWA-KISO







F20240913120934




BLK: 6,SNR1: 4.5610 ,SNR2: 11.012




K20240913120931





BLK: 6,SNR1: 2.3323 ,SNR2: 6.7593




3C267 2024/09/13 3.19UT FUJI -KISO





T20240913123522




BLK: 3,SNR1: 201.76 ,SNR2: 200.77




F20240913123522





BLK: 3,SNR1: 172.65 ,SNR2: 189.43




1213-17 2024/09/13 3.62UT TOYOKAWA-FUJI




T20240913123522




BLK: 6,SNR1: 189.67 ,SNR2: 187.83




K20240913123519





BLK: 6,SNR1: 137.81 ,SNR2: 169.57




1213-17 2024/09/13 3.62UT TOYOKAWA-KISO




F20240913123522




BLK:10,SNR1: 142.84 ,SNR2: 156.71




K20240913123519




BLK:10,SNR1: 62.684 ,SNR2: 91.543




1213-17 2024/09/13 3.62UT FUJI -KISO




T20240913124839




BLK:24,SNR1: 26.230 ,SNR2: 96.885




F20240913124839




BLK:24,SNR1: 3.9383 ,SNR2: 10.789




3C273 2024/09/13 3.84UT TOYOKAWA-FUJI





T20240913124839




BLK:26,SNR1: 25.048 ,SNR2: 86.209




K20240913124836




BLK:26,SNR1: 3.7561 ,SNR2: 11.543




3C273 2024/09/13 3.84UT TOYOKAWA-KISO



F20240913124839





BLK:25,SNR1: 0.65335 ,SNR2: 5.6752





3C273 2024/09/13 3.84UT FUJI -KISO



K20240913124836




BLK:25,SNR1: 4.0186 ,SNR2: 12.356



T20240913130150




BLK:10,SNR1: 33.411 ,SNR2: 56.284





3C275 2024/09/13 4.06UT TOYOKAWA-FUJI

F20240913130150





BLK:10,SNR1: 7.5890 ,SNR2: 20.114






T20240913130150





BLK:11,SNR1: 33.467 ,SNR2: 56.378





3C275 2024/09/13 4.06UT TOYOKAWA-KISO


K20240913130147




BLK:11,SNR1: 52.362 ,SNR2: 87.332



F20240913130150





BLK: 6,SNR1: 7.6581 ,SNR2: 42.910





3C275 2024/09/13 4.06UT FUJI -KISO



K20240913130147




BLK: 6,SNR1: 52.524 ,SNR2: 87.602





T20240913130755




BLK:13,SNR1: 47.768 ,SNR2: 71.403




F20240913130755





BLK:13,SNR1: 67.782 ,SNR2: 67.853




1245-19 2024/09/13 4.16UT TOYOKAWA-FUJI




T20240913130755




BLK:19,SNR1: 44.747 ,SNR2: 66.885




K20240913130752





BLK:19,SNR1: 0.64742 ,SNR2: 3.9977




1245-19 2024/09/13 4.16UT TOYOKAWA-KISO




F20240913130755




BLK:13,SNR1: 67.757 ,SNR2: 67.828




K20240913130752





BLK:13,SNR1: 0.18296 ,SNR2: 2.3668




1245-19 2024/09/13 4.16UT FUJI -KISO




T20240913131539




BLK: 6,SNR1: 0.98392 ,SNR2: 6.4707




F20240913131539




BLK: 6,SNR1:-0.12823 ,SNR2: 0.99877




3C279 2024/09/13 4.29UT TOYOKAWA-FUJI





T20240913131539




BLK:20,SNR1: 0.99906 ,SNR2: 5.6426




K20240913131536




BLK:20,SNR1: 0.93248 ,SNR2: 3.1452




3C279 2024/09/13 4.29UT TOYOKAWA-KISO



F20240913131539





BLK: 6,SNR1:-0.17667 ,SNR2: 0.67634





3C279 2024/09/13 4.29UT FUJI -KISO

K20240913131536




BLK: 6,SNR1: 0.13902 ,SNR2: 1.6802






T20240913133108




BLK: 9,SNR1: 0.59590 ,SNR2: 5.6062




Frequency (Hz)

F20240913133108




BLK: 9,SNR1: 0.54151 ,SNR2: 1.5093




Frequency (Hz)


3C283 2024/09/13 4.55UT TOYOKAWA-FUJI




T20240913133108




BLK: 6,SNR1: 0.77113 ,SNR2: 2.4094




K20240913133105





BLK: 6,SNR1: 0.52479E-02,SNR2: 1.2157




3C283 2024/09/13 4.55UT TOYOKAWA-KISO





F20240913133108




BLK: 9,SNR1: 0.24834 ,SNR2: 3.6683




K20240913133105





BLK: 9,SNR1: 5.2801 ,SNR2: 13.012




3C283 2024/09/13 4.55UT FUJI -KISO





T20240913134533




BLK: 6,SNR1: 0.20155 ,SNR2: 1.4794




F20240913134534





BLK: 6,SNR1:-0.52272E-01,SNR2: 0.62010




1323+32 2024/09/13 4.79UT TOYOKAWA-FUJI





T20240913134533




BLK: 8,SNR1: 0.16629 ,SNR2: 0.94930




K20240913134530




BLK: 8,SNR1: 38.482 ,SNR2: 44.389




1323+32 2024/09/13 4.79UT TOYOKAWA-KISO




F20240913134534




BLK: 6,SNR1: 0.60069 ,SNR2: 2.5386




K20240913134530





BLK: 6,SNR1: 20.004 ,SNR2: 28.844




1323+32 2024/09/13 4.79UT FUJI -KISO



T20240913135023




BLK:22,SNR1: 1.3952 ,SNR2: 4.7484





3C286 2024/09/13 4.87UT TOYOKAWA-FUJI



F20240913135023




BLK:22,SNR1: 0.19759 ,SNR2: 2.0478



T20240913135023





BLK:13,SNR1: 1.4883 ,SNR2: 5.0335





3C286 2024/09/13 4.87UT TOYOKAWA-KISO

K20240913135020




BLK:13,SNR1: 17.381 ,SNR2: 31.684








F20240913135023




BLK:13,SNR1: 0.59794 ,SNR2: 2.8269




K20240913135020





BLK:13,SNR1: 38.802 ,SNR2: 52.919




3C286 2024/09/13 4.87UT FUJI -KISO




T20240913140650




BLK:18,SNR1: 1.1523 ,SNR2: 4.2869




F20240913140650





BLK:18,SNR1: 1.1172 ,SNR2: 1.7040




1345+12 2024/09/13 5.14UT TOYOKAWA-FUJI





T20240913140650




BLK:15,SNR1: 0.67451 ,SNR2: 4.9787




K20240913140647




BLK:15,SNR1: 7.4787 ,SNR2: 18.447




1345+12 2024/09/13 5.14UT TOYOKAWA-KISO





F20240913140650




BLK:14,SNR1:-0.11786 ,SNR2: 0.77993




K20240913140647





BLK:14,SNR1: 26.820 ,SNR2: 43.401




1345+12 2024/09/13 5.14UT FUJI -KISO




T20240913141711




BLK: 3,SNR1: 0.32207 ,SNR2: 4.5291




F20240913141711





BLK: 3,SNR1: 0.54436 ,SNR2: 1.9363




1355+01 2024/09/13 5.31UT TOYOKAWA-FUJI





T20240913141711




BLK:10,SNR1: 0.18402 ,SNR2: 1.1014




K20240913141708




BLK:10,SNR1: 1.3636 ,SNR2: 5.1102




1355+01 2024/09/13 5.31UT TOYOKAWA-KISO




F20240913141711




BLK:10,SNR1: 0.39511 ,SNR2: 2.4523




K20240913141708





BLK:10,SNR1: 0.87468 ,SNR2: 3.0485




1355+01 2024/09/13 5.31UT FUJI -KISO



T20240913143821




BLK:11,SNR1: 0.71479 ,SNR2: 5.1343





3C298 2024/09/13 5.67UT TOYOKAWA-FUJI

F20240913143821





BLK:11,SNR1: 1.5351 ,SNR2: 4.8536








T20240913143821




BLK:16,SNR1: 1.0092 ,SNR2: 4.3525




K20240913143818




BLK:16,SNR1: 0.85955 ,SNR2: 1.6768




3C298 2024/09/13 5.67UT TOYOKAWA-KISO





F20240913143821




BLK:10,SNR1: 0.51683 ,SNR2: 2.3615




K20240913143818




BLK:10,SNR1: 4.4161 ,SNR2: 8.9262




3C298 2024/09/13 5.67UT FUJI -KISO




T20240913145005




BLK:21,SNR1: 39.398 ,SNR2: 63.090




F20240913145005




BLK:21,SNR1: 15.305 ,SNR2: 28.242




1428-03 2024/09/13 5.86UT TOYOKAWA-FUJI





T20240913145005




BLK:10,SNR1: 81.316 ,SNR2: 90.214




K20240913145002




BLK:10,SNR1: 1.0271 ,SNR2: 2.4605




1428-03 2024/09/13 5.86UT TOYOKAWA-KISO





F20240913145005




BLK: 6,SNR1: 33.599 ,SNR2: 83.490




K20240913145002





BLK: 6,SNR1: 0.29261 ,SNR2: 1.2706




1428-03 2024/09/13 5.86UT FUJI -KISO




T20240913145846




BLK: 4,SNR1: 0.86701E-02,SNR2: 0.56639




F20240913145846





BLK: 4,SNR1: 0.19760 ,SNR2: 3.5825




1436-16 2024/09/13 6.01UT TOYOKAWA-FUJI





T20240913145846




BLK: 2,SNR1: 0.30601 ,SNR2: 0.65576




K20240913145843





BLK: 2,SNR1: 0.41126 ,SNR2: 0.83407




1436-16 2024/09/13 6.01UT TOYOKAWA-KISO



F20240913145846





BLK: 5,SNR1:-0.68248E-01,SNR2: 1.1282




Frequency (Hz)

K20240913145843




BLK: 5,SNR1: 0.26465 ,SNR2: 1.5966





Frequency (Hz)

1436-16 2024/09/13 6.01UT FUJI -KISO






T20240913151509




BLK: 7,SNR1: 3.5959 ,SNR2: 6.7662




Frequency (Hz)

F20240913151509




BLK: 7,SNR1: 1.2118 ,SNR2: 3.7676





Frequency (Hz)


1453-10 2024/09/13 6.28UT TOYOKAWA-FUJI




T20240913151509




BLK: 7,SNR1: 3.8453 ,SNR2: 11.652




K20240913151506




BLK: 7,SNR1: 1.0268 ,SNR2: 3.2421




1453-10 2024/09/13 6.28UT TOYOKAWA-KISO




F20240913151509




BLK:10,SNR1: 0.21276E-01,SNR2: 1.6146




K20240913151506





BLK:10,SNR1: 2.7301 ,SNR2: 8.0752




1453-10 2024/09/13 6.28UT FUJI -KISO





T20240913153002




BLK: 1,SNR1:-0.12296 ,SNR2: 0.70377




F20240913153002





BLK: 1,SNR1:-0.58808E-02,SNR2: 0.68768




1508-05 2024/09/13 6.53UT TOYOKAWA-FUJI





T20240913153002




BLK: 2,SNR1: 0.26879E-01,SNR2: 0.45577




K20240913152959




BLK: 2,SNR1: 3.8617 ,SNR2: 8.5130




1508-05 2024/09/13 6.53UT TOYOKAWA-KISO





F20240913153002




BLK: 3,SNR1: 0.24267 ,SNR2: 1.1996




K20240913152959





BLK: 3,SNR1: 10.430 ,SNR2: 30.108




1508-05 2024/09/13 6.53UT FUJI -KISO



T20240913153902





BLK: 2,SNR1: 93.442 ,SNR2: 106.61




Frequency (Hz)

F20240913153902




BLK: 2,SNR1: 5.6240 ,SNR2: 14.531





Frequency (Hz)


3C318 2024/09/13 6.68UT TOYOKAWA-FUJI



T20240913153902





No.Good Data




Frequency (Hz)

K20240913153859




No.Good Data





Frequency (Hz)

3C318 2024/09/13 6.68UT TOYOKAWA-KISO








F20240913153902




No.Good Data




K20240913153859




No.Good Data




3C318 2024/09/13 6.68UT FUJI -KISO



T20240913154449




BLK: 6,SNR1: 1.7535 ,SNR2: 6.9677




Frequency (Hz)

F20240913154449




BLK: 6,SNR1: 63.938 ,SNR2: 110.78




Frequency (Hz)


1523+03 2024/09/13 6.78UT TOYOKAWA-FUJI





T20240913154449




BLK: 9,SNR1: 2.1782 ,SNR2: 8.1392




K20240913154446




BLK: 9,SNR1: 29.183 ,SNR2: 35.701




1523+03 2024/09/13 6.78UT TOYOKAWA-KISO





F20240913154449




BLK:12,SNR1: 28.909 ,SNR2: 38.822




K20240913154446





BLK:12,SNR1: 66.577 ,SNR2: 79.034




1523+03 2024/09/13 6.78UT FUJI -KISO





T20240913155628




BLK: 6,SNR1: 6.1208 ,SNR2: 14.655




F20240913155628




BLK: 6,SNR1: 4.0305 ,SNR2: 10.044




1535+139 2024/09/13 6.97UT TOYOKAWA-FUJI



T20240913155628




BLK:10,SNR1: 0.64930 ,SNR2: 1.8413




Frequency (Hz)

K20240913155625




BLK:10,SNR1: 3.5091 ,SNR2: 8.3670





Frequency (Hz)


1535+139 2024/09/13 6.97UT TOYOKAWA-KISO




F20240913155628




BLK: 6,SNR1: 4.1161 ,SNR2: 10.283




K20240913155625





BLK: 6,SNR1: 11.140 ,SNR2: 26.773




1535+139 2024/09/13 6.97UT FUJI -KISO




T20240913160652




BLK: 3,SNR1: 0.81741 ,SNR2: 2.0050




F20240913160652



BLK: 3,SNR1: 0.53212 ,SNR2: 2.2881





1545-12 2024/09/13 7.14UT TOYOKAWA-FUJI






T20240913160652




BLK: 2,SNR1: 0.10695 ,SNR2: 1.5432




Frequency (Hz)

K20240913160649




BLK: 2,SNR1: 0.58273E-01,SNR2: 2.0422




Frequency (Hz)


1545-12 2024/09/13 7.14UT TOYOKAWA-KISO



F20240913160652




BLK: 7,SNR1: 0.74326E-01,SNR2: 0.98527




Frequency (Hz)

K20240913160649




BLK: 7,SNR1: 1.6708 ,SNR2: 5.1290





Frequency (Hz)


1545-12 2024/09/13 7.14UT FUJI -KISO




T20240913162755




BLK: 6,SNR1: 1.1854 ,SNR2: 4.0426




F20240913162755




BLK: 6,SNR1:-0.76721E-01,SNR2: 0.97405




1607+26 2024/09/13 7.49UT TOYOKAWA-FUJI



T20240913162755




BLK: 6,SNR1: 2.1971 ,SNR2: 4.9706




Frequency (Hz)

K20240913162752




BLK: 6,SNR1: 0.23034 ,SNR2: 1.1389





Frequency (Hz)


1607+26 2024/09/13 7.49UT TOYOKAWA-KISO



F20240913162755





BLK: 8,SNR1: 0.99441 ,SNR2: 2.0224




Frequency (Hz)

K20240913162752




BLK: 8,SNR1: 0.72028 ,SNR2: 2.3087





Frequency (Hz)


1607+26 2024/09/13 7.49UT FUJI -KISO



T20240913164526




BLK: 9,SNR1: 7.0077 ,SNR2: 19.144




Frequency (Hz)

F20240913164526




BLK: 9,SNR1: 7.0794 ,SNR2: 18.216




Frequency (Hz)


1623-228 2024/09/13 7.79UT TOYOKAWA-FUJI



T20240913164526





BLK: 8,SNR1: 6.1457 ,SNR2: 15.388




Frequency (Hz)

K20240913164523




BLK: 8,SNR1: 8.8106 ,SNR2: 22.695




Frequency (Hz)


1623-228 2024/09/13 7.79UT TOYOKAWA-KISO



F20240913164526




BLK: 7,SNR1: 6.9367 ,SNR2: 17.839




Frequency (Hz)

K20240913164523




BLK: 7,SNR1: 10.364 ,SNR2: 24.777





Frequency (Hz)

1623-228 2024/09/13 7.79UT FUJI -KISO








T20240913165356




BLK: 8,SNR1: 11.558 ,SNR2: 28.173




F20240913165357





BLK: 8,SNR1: 7.3769 ,SNR2: 25.633




1631-222 2024/09/13 7.93UT TOYOKAWA-FUJI



T20240913165356





BLK:11,SNR1: 10.625 ,SNR2: 25.317




Frequency (Hz)

K20240913165353




BLK:11,SNR1: 11.157 ,SNR2: 27.605





Frequency (Hz)


1631-222 2024/09/13 7.93UT TOYOKAWA-KISO




F20240913165357




BLK:14,SNR1: 14.662 ,SNR2: 36.051




K20240913165353





BLK:14,SNR1: 9.8187 ,SNR2: 24.199




1631-222 2024/09/13 7.93UT FUJI -KISO



T20240913165933





BLK: 3,SNR1: 0.18072 ,SNR2: 0.56394




Frequency (Hz)

F20240913165933




BLK: 3,SNR1: 0.66258 ,SNR2: 3.2986





Frequency (Hz)


1638-025 2024/09/13 8.02UT TOYOKAWA-FUJI



T20240913165933





BLK: 4,SNR1: 0.80868E-01,SNR2: 0.77728




Frequency (Hz)

K20240913165930




BLK: 4,SNR1: 0.78832 ,SNR2: 8.1836




Frequency (Hz)


1638-025 2024/09/13 8.02UT TOYOKAWA-KISO



F20240913165933





BLK:19,SNR1: 0.97795E-01,SNR2: 2.2105




Frequency (Hz)

K20240913165930



BLK:19,SNR1: 2.7049 ,SNR2: 6.7787



Frequency (Hz)

1638-025 2024/09/13 8.02UT FUJI -KISO

