




TOYOKAWA 0719-187 2024/10/12(286)05:48:19-05:51:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0727-115 2024/10/12(286)05:56:32-05:59:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0731+021 2024/10/12(286)06:00:14-06:03:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0735+076 2024/10/12(286)06:04:05-06:07:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0741-06 2024/10/12(286)06:10:35-06:14:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0746+162 2024/10/12(286)06:15:22-06:18:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0752-200 2024/10/12(286)06:20:20-06:23:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0755+029 2024/10/12(286)06:23:58-06:27:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C190 2024/10/12(286)06:27:55-06:31:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0806-103 2024/10/12(286)06:35:00-06:38:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C196


2024/10/12(286)06:40:19-06:43:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0817+183 2024/10/12(286)06:47:03-06:50:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0821+394 2024/10/12(286)06:51:29-06:54:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0834-19 2024/10/12(286)07:03:09-07:06:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0839-071 2024/10/12(286)07:08:14-07:11:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C208

2024/10/12(286)07:19:15-07:22:41JST

18160+/- 3610




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 0857-191 2024/10/12(286)07:25:35-07:29:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C216

2024/10/12(286)07:35:57-07:39:23JST


12292+/- 85




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0912-132 2024/10/12(286)07:40:41-07:44:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0919-142 2024/10/12(286)07:48:08-07:51:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0923+392 2024/10/12(286)07:53:19-07:56:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C222 2024/10/12(286)08:02:32-08:05:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0941-08 2024/10/12(286)08:09:32-08:12:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C230

2024/10/12(286)08:17:54-08:21:20JST

11011+/- 45




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C237 2024/10/12(286)08:33:54-08:37:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1011+110 2024/10/12(286)08:40:10-08:43:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C241

2024/10/12(286)08:47:51-08:51:17JST


10785+/- 58




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1025+154 2024/10/12(286)08:54:13-08:57:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1035-058 2024/10/12(286)09:03:54-09:07:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1044-008 2024/10/12(286)09:13:07-09:16:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1055+01 2024/10/12(286)09:24:11-09:27:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1107+109 2024/10/12(286)09:35:29-09:38:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C255 2024/10/12(286)09:45:06-09:48:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1127-14 2024/10/12(286)09:55:44-09:59:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1136-13 2024/10/12(286)10:04:48-10:08:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C263.1 2024/10/12(286)10:09:04-10:12:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C267 2024/10/12(286)10:15:31-10:18:57JST


7916+/- 24




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1154+552 2024/10/12(286)10:22:56-10:26:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1206+439 2024/10/12(286)10:34:45-10:38:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1213-17 2024/10/12(286)10:41:19-10:44:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 3C273 2024/10/12(286)10:54:36-10:58:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C275


2024/10/12(286)11:07:47-11:11:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1245-19 2024/10/12(286)11:13:52-11:17:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C279 2024/10/12(286)11:21:36-11:25:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C283 2024/10/12(286)11:37:05-11:40:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1313+453 2024/10/12(286)11:41:24-11:44:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1323+32 2024/10/12(286)11:51:30-11:54:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C286 2024/10/12(286)11:56:20-11:59:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1334-17 2024/10/12(286)12:02:57-12:06:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1345+12 2024/10/12(286)12:12:47-12:16:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA CMT-02 2024/10/12(286)12:18:00-12:31:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C298 2024/10/12(286)12:44:18-12:47:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA CMT-04 2024/10/12(286)12:56:57-13:10:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1453-10 2024/10/12(286)13:21:06-13:24:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1508-05 2024/10/12(286)13:35:59-13:39:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA CMT-06 2024/10/12(286)13:45:38-13:59:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA CMT-05 2024/10/12(286)14:10:23-14:24:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1607+26 2024/10/12(286)14:33:52-14:37:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1623-228 2024/10/12(286)14:51:23-14:54:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1631-222 2024/10/12(286)14:59:53-15:03:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1638-025 2024/10/12(286)15:05:30-15:08:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1644-106 2024/10/12(286)15:12:24-15:15:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1650+004 2024/10/12(286)15:17:45-15:21:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1656+053 2024/10/12(286)15:23:17-15:26:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1712-033 2024/10/12(286)15:39:47-15:43:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1730-13 2024/10/12(286)15:57:49-16:01:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1748+031 2024/10/12(286)16:15:14-16:18:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1759+13 2024/10/12(286)16:26:07-16:29:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1819-096 2024/10/12(286)16:47:07-16:50:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1830-210 2024/10/12(286)16:58:22-17:01:48JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1850-147 2024/10/12(286)17:17:39-17:21:05JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

