



T20241011061433




No.Good Data



Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0741-06 2024/10/10 21.27UT TOYOKAWA-FUJI



T20241011061433




BLK: 9,SNR1: 0.65765 ,SNR2: 2.1319




Frequency (Hz)

K20241011061430




BLK: 9,SNR1: 2.0737 ,SNR2: 4.5160



Frequency (Hz)

0741-06 2024/10/10 21.27UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241011061430



No.Good Data





Frequency (Hz)


0741-06 2024/10/10 21.27UT FUJI -KISO





T20241011062418




No.Good Data




FUJI



No.Good Data




0752-200 2024/10/10 21.43UT TOYOKAWA-FUJI






T20241011062418




BLK:13,SNR1: 12.033 ,SNR2: 15.576




Frequency (Hz)

K20241011062415




BLK:13,SNR1:-0.36308 ,SNR2: 1.2213



Frequency (Hz)

0752-200 2024/10/10 21.43UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241011062415



No.Good Data



Frequency (Hz)

0752-200 2024/10/10 21.43UT FUJI -KISO





T20241011063152




No.Good Data




FUJI





No.Good Data




3C190 2024/10/10 21.56UT TOYOKAWA-FUJI



T20241011063152





BLK:10,SNR1: 15.192 ,SNR2: 38.502




Frequency (Hz)

3C190 2024/10/10 21.56UT TOYOKAWA-KISO


K20241011063149




BLK:10,SNR1: 10.521 ,SNR2: 25.994




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241011063149




No.Good Data




Frequency (Hz)


3C190 2024/10/10 21.56UT FUJI -KISO





T20241011063858




No.Good Data




FUJI





No.Good Data




0806-103 2024/10/10 21.68UT TOYOKAWA-FUJI



T20241011063858





BLK: 8,SNR1: 0.11343 ,SNR2: 0.60406




Frequency (Hz)

K20241011063855




BLK: 8,SNR1: 0.67412 ,SNR2: 2.3101



Frequency (Hz)

0806-103 2024/10/10 21.68UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241011063855




No.Good Data




Frequency (Hz)

0806-103 2024/10/10 21.68UT FUJI -KISO






T20241011065527




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0821+394 2024/10/10 21.95UT TOYOKAWA-FUJI



T20241011065527





BLK:10,SNR1: 9.1869 ,SNR2: 23.266




Frequency (Hz)

K20241011065524




BLK:10,SNR1: 7.4287 ,SNR2: 19.178




Frequency (Hz)


0821+394 2024/10/10 21.95UT TOYOKAWA-KISO




FUJI




No.Good Data




K20241011065524




No.Good Data




0821+394 2024/10/10 21.95UT FUJI -KISO




T20241011070707




No.Good Data




FUJI





No.Good Data




0834-19 2024/10/10 22.15UT TOYOKAWA-FUJI



T20241011070707





BLK:13,SNR1: 10.377 ,SNR2: 25.659




Frequency (Hz)

K20241011070704




BLK:13,SNR1: 10.706 ,SNR2: 25.536




Frequency (Hz)

0834-19 2024/10/10 22.15UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241011070704





No.Good Data




0834-19 2024/10/10 22.15UT FUJI -KISO




T20241011071212




No.Good Data




FUJI





No.Good Data




0839-071 2024/10/10 22.23UT TOYOKAWA-FUJI



T20241011071212




BLK:11,SNR1: 8.8728 ,SNR2: 23.019




Frequency (Hz)

0839-071 2024/10/10 22.23UT TOYOKAWA-KISO


K20241011071209



BLK:11,SNR1: 4.3869 ,SNR2: 11.247





Frequency (Hz)






FUJI





No.Good Data




Frequency (Hz)

K20241011071209




No.Good Data





Frequency (Hz)


0839-071 2024/10/10 22.23UT FUJI -KISO



T20241011072313





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C208 2024/10/10 22.42UT TOYOKAWA-FUJI



T20241011072313





BLK:13,SNR1: 37.436 ,SNR2: 71.124




Frequency (Hz)

3C208 2024/10/10 22.42UT TOYOKAWA-KISO


K20241011072310




BLK:13,SNR1: 0.29847 ,SNR2: 1.3448



Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241011072310




No.Good Data





Frequency (Hz)


3C208 2024/10/10 22.42UT FUJI -KISO




T20241011073954




No.Good Data




FUJI





No.Good Data




3C216 2024/10/10 22.69UT TOYOKAWA-FUJI



T20241011073954





BLK:11,SNR1: 0.49171 ,SNR2: 1.8376




Frequency (Hz)

K20241011073951




BLK:11,SNR1: 0.15603 ,SNR2: 2.7273




Frequency (Hz)


3C216 2024/10/10 22.69UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241011073951




No.Good Data





Frequency (Hz)


3C216 2024/10/10 22.69UT FUJI -KISO



T20241011075717





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

0923+392 2024/10/10 22.98UT TOYOKAWA-FUJI






T20241011075717





BLK:20,SNR1: 0.72050 ,SNR2: 2.7743




Frequency (Hz)

K20241011075714




BLK:20,SNR1: 1.0710 ,SNR2: 2.5514





Frequency (Hz)


0923+392 2024/10/10 22.98UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241011075714




No.Good Data





Frequency (Hz)


0923+392 2024/10/10 22.98UT FUJI -KISO





T20241011080630




No.Good Data




FUJI




No.Good Data




3C222 2024/10/10 23.14UT TOYOKAWA-FUJI




T20241011080630




BLK:10,SNR1: 4.0715 ,SNR2: 12.387




K20241011080627




BLK:10,SNR1: 20.620 ,SNR2: 25.848




3C222 2024/10/10 23.14UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241011080627




No.Good Data





Frequency (Hz)


3C222 2024/10/10 23.14UT FUJI -KISO





T20241011081330




No.Good Data




FUJI





No.Good Data




0941-08 2024/10/10 23.25UT TOYOKAWA-FUJI



T20241011081330




BLK:13,SNR1: 1.4051 ,SNR2: 3.9059




Frequency (Hz)

0941-08 2024/10/10 23.25UT TOYOKAWA-KISO


K20241011081327





BLK:13,SNR1: 1.7354 ,SNR2: 5.4013




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241011081327




No.Good Data





Frequency (Hz)

0941-08 2024/10/10 23.25UT FUJI -KISO








T20241011082151




No.Good Data




FUJI




No.Good Data




3C230 2024/10/10 23.39UT TOYOKAWA-FUJI



T20241011082151





BLK:14,SNR1: 0.78529 ,SNR2: 4.4544





3C230 2024/10/10 23.39UT TOYOKAWA-KISO

K20241011082148




BLK:14,SNR1: 0.43109 ,SNR2: 4.8022



FUJI





No.Good Data




Frequency (Hz)

K20241011082148




No.Good Data




Frequency (Hz)


3C230 2024/10/10 23.39UT FUJI -KISO




T20241011083752




No. Good Data




FUJI





No. Good Data




3C237 2024/10/10 23.66UT TOYOKAWA-FUJI



T20241011083752





BLK:21,SNR1: 1.2150 ,SNR2: 3.6580




Frequency (Hz)

3C237 2024/10/10 23.66UT TOYOKAWA-KISO


K20241011083749





BLK:21,SNR1: 0.55542 ,SNR2: 1.4532




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241011083749




No.Good Data



Frequency (Hz)

3C237 2024/10/10 23.66UT FUJI -KISO



T20241011084408



No.Good Data




FUJI





No.Good Data




1011+110 2024/10/10 23.76UT TOYOKAWA-FUJI



T20241011084408




BLK: 3,SNR1: 0.48195 ,SNR2: 6.3962




Frequency (Hz)

K20241011084405




BLK: 3,SNR1:-0.64829E-01,SNR2: 1.7818



Frequency (Hz)

1011+110 2024/10/10 23.76UT TOYOKAWA-KISO







FUJI




No.Good Data




K20241011084405




No.Good Data



1011+110 2024/10/10 23.76UT FUJI -KISO




T20241011085149




No.Good Data



FUJI





No.Good Data




3C241 2024/10/10 23.89UT TOYOKAWA-FUJI



T20241011085149





BLK:19,SNR1: 12.014 ,SNR2: 19.298





3C241 2024/10/10 23.89UT TOYOKAWA-KISO

K20241011085146



BLK:19,SNR1: 6.4773 ,SNR2: 26.605



FUJI



No.Good Data



Frequency (Hz)

K20241011085146



No.Good Data





Frequency (Hz)


3C241 2024/10/10 23.89UT FUJI -KISO




T20241011090319




No.Good Data




FUJI





No.Good Data




1031-11 2024/10/11 0.08UT TOYOKAWA-FUJI



T20241011090319





BLK:14,SNR1: 0.29049 ,SNR2: 1.4747





1031-11 2024/10/11 0.08UT TOYOKAWA-KISO

K20241011090316



BLK:14,SNR1: 0.64144 ,SNR2: 3.4061



FUJI



No.Good Data



Frequency (Hz)

K20241011090316



No.Good Data



Frequency (Hz)

1031-11 2024/10/11 0.08UT FUJI -KISO




T20241011090752



No.Good Data




FUJI



No.Good Data




1035-058 2024/10/11 0.16UT TOYOKAWA-FUJI






T20241011090752




BLK:15,SNR1: 6.7290 ,SNR2: 60.193





1035-058 2024/10/11 0.16UT TOYOKAWA-KISO

K20241011090750




BLK:15,SNR1: 5.5745 ,SNR2: 8.9908





FUJI




No.Good Data




K20241011090750



No.Good Data



1035-058 2024/10/11 0.16UT FUJI -KISO



T20241011091705




No.Good Data




FUJI




No.Good Data




1044-008 2024/10/11 0.31UT TOYOKAWA-FUJI




T20241011091705




BLK: 7,SNR1: 0.17714 ,SNR2: 0.70426




K20241011091703




BLK: 7,SNR1: 6.3852 ,SNR2: 19.804




1044-008 2024/10/11 0.31UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241011091703




No.Good Data




Frequency (Hz)

1044-008 2024/10/11 0.31UT FUJI -KISO




T20241011092809



No.Good Data



FUJI




No.Good Data




1055+01 2024/10/11 0.50UT TOYOKAWA-FUJI



T20241011092809




BLK: 9,SNR1: 0.19095 ,SNR2: 0.94228





1055+01 2024/10/11 0.50UT TOYOKAWA-KISO



K20241011092806




BLK: 9,SNR1: 0.13908 ,SNR2: 2.5098



FUJI



No. Good Data



Frequency (Hz)

K20241011092806




No. Good Data



Frequency (Hz)

1055+01 2024/10/11 0.50UT FUJI -KISO






T20241011093927





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1107+109 2024/10/11 0.69UT TOYOKAWA-FUJI



T20241011093927





BLK: 7,SNR1: 0.10396 ,SNR2: 2.4169




Frequency (Hz)

K20241011093924




BLK: 7,SNR1: 0.19505 ,SNR2: 3.5368




Frequency (Hz)


1107+109 2024/10/11 0.69UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241011093924




No. Good Data



Frequency (Hz)

1107+109 2024/10/11 0.69UT FUJI -KISO




T20241011094904



No. Good Data



FUJI








No. Good Data




3C255 2024/10/11 0.85UT TOYOKAWA-FUJI





FUJI




No. Good Data



Frequency (Hz)

K20241011094902



No. Good Data





Frequency (Hz)


3C255 2024/10/11 0.85UT FUJI -KISO



T20241011095942



No. Good Data



Frequency (Hz)

FUJI



No. Good Data




Frequency (Hz)


1127-14 2024/10/11 1.02UT TOYOKAWA-FUJI



T20241011095942




BLK:15,SNR1: 0.61778 ,SNR2: 3.8471





1127-14 2024/10/11 1.02UT TOYOKAWA-KISO

K20241011095940



BLK:15,SNR1: 0.35110 ,SNR2: 1.6778





FUJI



No.Good Data



Frequency (Hz)

K20241011095940




No.Good Data





Frequency (Hz)


1127-14 2024/10/11 1.02UT FUJI -KISO



T20241011100846





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1136-13 2024/10/11 1.17UT TOYOKAWA-FUJI



T20241011100846




BLK: 5, SNR1: 93.769 , SNR2: 114.68





1136-13 2024/10/11 1.17UT TOYOKAWA-KISO

K20241011100843



BLK: 5, SNR1: 0.21408 , SNR2: 5.0281



FUJI



No. Good Data



Frequency (Hz)

K20241011100843



No. Good Data





Frequency (Hz)


1136-13 2024/10/11 1.17UT FUJI -KISO



T20241011104517





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1213-17 2024/10/11 1.78UT TOYOKAWA-FUJI



T20241011104517





BLK:11,SNR1: 0.79105 ,SNR2: 3.9273




1213-17 2024/10/11 1.78UT TOYOKAWA-KISO


K20241011104514



BLK:11,SNR1: 0.71632 ,SNR2: 2.8368



Frequency (Hz)



FUJI



No.Good Data



Frequency (Hz)

K20241011104514




No.Good Data



Frequency (Hz)

1213-17 2024/10/11 1.78UT FUJI -KISO



T20241011105834



No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

3C273 2024/10/11 2.00UT TOYOKAWA-FUJI






T20241011105834




BLK:23,SNR1: 45.020 ,SNR2: 96.223





3C273 2024/10/11 2.00UT TOYOKAWA-KISO



K20241011105832




BLK:23,SNR1: 22.712 ,SNR2: 43.791



FUJI





No.Good Data




Frequency (Hz)

K20241011105832




No.Good Data



Frequency (Hz)


3C273 2024/10/11 2.00UT FUJI -KISO



T202410111111145





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C275 2024/10/11 2.22UT TOYOKAWA-FUJI




T202410111111145




BLK:24,SNR1: 2.2483 ,SNR2: 8.0857




K202410111111143





BLK:24,SNR1: 11.110 ,SNR2: 19.634




3C275 2024/10/11 2.22UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K202410111111143




No.Good Data



Frequency (Hz)


3C275 2024/10/11 2.22UT FUJI -KISO



T20241011111750



No.Good Data




Frequency (Hz)

FUJI



No.Good Data





Frequency (Hz)


1245-19 2024/10/11 2.33UT TOYOKAWA-FUJI




T20241011111750




BLK:28,SNR1: 1.2157 ,SNR2: 7.0318




K20241011111748



BLK:28,SNR1: 0.51465 ,SNR2: 3.3870




1245-19 2024/10/11 2.33UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241011111748



No.Good Data



Frequency (Hz)

1245-19 2024/10/11 2.33UT FUJI -KISO





T20241011114103



No.Good Data



Frequency (Hz)

FUJI



No.Good Data





Frequency (Hz)


3C283 2024/10/11 2.71UT TOYOKAWA-FUJI



T20241011114103




BLK:33,SNR1: 1.9460 ,SNR2: 13.560





3C283 2024/10/11 2.71UT TOYOKAWA-KISO

K20241011114100



BLK:33,SNR1: 1.4077 ,SNR2: 5.1658



FUJI



No.Good Data



Frequency (Hz)

K20241011114100



No.Good Data





Frequency (Hz)

3C283 2024/10/11 2.71UT FUJI -KISO



T20241011115528





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1323+32 2024/10/11 2.95UT TOYOKAWA-FUJI



T20241011115528





BLK:26,SNR1: 1.0743 ,SNR2: 5.0680





1323+32 2024/10/11 2.95UT TOYOKAWA-KISO

K20241011115525



BLK:26,SNR1: 0.35272 ,SNR2: 2.1045



FUJI



No. Good Data



Frequency (Hz)

K20241011115525



No. Good Data




Frequency (Hz)

1323+32 2024/10/11 2.95UT FUJI -KISO





T20241011120018




No.Good Data




FUJI




No.Good Data




3C286 2024/10/11 3.03UT TOYOKAWA-FUJI



T20241011120018




BLK:34,SNR1: 6.5066 ,SNR2: 19.370





3C286 2024/10/11 3.03UT TOYOKAWA-KISO

K20241011120015





BLK:34,SNR1: 1.6223 ,SNR2: 6.1501






FUJI





No.Good Data




Frequency (Hz)

K20241011120015




No.Good Data




Frequency (Hz)

3C286 2024/10/11 3.03UT FUJI -KISO



T20241011121645




No.Good Data



Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1345+12 2024/10/11 3.31UT TOYOKAWA-FUJI



T20241011121645




BLK:35,SNR1: 131.87 ,SNR2: 148.71





1345+12 2024/10/11 3.31UT TOYOKAWA-KISO


K20241011121642



BLK:35,SNR1: 0.53681 ,SNR2: 2.2596



FUJI





No.Good Data




Frequency (Hz)

K20241011121642




No.Good Data



Frequency (Hz)


1345+12 2024/10/11 3.31UT FUJI -KISO



T20241011122158





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


CMT-02 2024/10/11 3.48UT TOYOKAWA-FUJI



T20241011122158





BLK:82,SNR1: 69.797 ,SNR2: 97.709





CMT-02 2024/10/11 3.48UT TOYOKAWA-KISO


K20241011122155



BLK:82,SNR1: 81.002 ,SNR2: 97.890



FUJI





No.Good Data




Frequency (Hz)

K20241011122155



No.Good Data



Frequency (Hz)

CMT-02 2024/10/11 3.48UT FUJI -KISO

