




T20241030055225





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0834-19 2024/10/29 20.90UT TOYOKAWA-FUJI



T20241030055225





BLK: 3, SNR1: 17.339 , SNR2: 22.568




Frequency (Hz)

K20241030055222




BLK: 3, SNR1: 8.6179 , SNR2: 20.121




Frequency (Hz)


0834-19 2024/10/29 20.90UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030055222




No.Good Data




Frequency (Hz)


0834-19 2024/10/29 20.90UT FUJI -KISO




T20241030055730




No.Good Data




FUJI



No.Good Data




0839-071 2024/10/29 20.99UT TOYOKAWA-FUJI






T20241030055730




BLK: 2, SNR1: 1.1963 ,SNR2: 5.4017




Frequency (Hz)

0839-071 2024/10/29 20.99UT TOYOKAWA-KISO


K20241030055728





BLK: 2, SNR1: 1.0452 ,SNR2: 3.8662




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241030055728




No.Good Data





Frequency (Hz)


0839-071 2024/10/29 20.99UT FUJI -KISO





T20241030061451




No.Good Data




FUJI





No.Good Data




0857-191 2024/10/29 21.28UT TOYOKAWA-FUJI



T20241030061451





No.Good Data




Frequency (Hz)

K20241030061449




No.Good Data




Frequency (Hz)


0857-191 2024/10/29 21.28UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030061449




No.Good Data




Frequency (Hz)


0857-191 2024/10/29 21.28UT FUJI -KISO





T20241030062957




No.Good Data




FUJI





No.Good Data




0912-132 2024/10/29 21.53UT TOYOKAWA-FUJI



T20241030062957




BLK:10,SNR1: 0.31925 ,SNR2: 3.1321




Frequency (Hz)

K20241030062955




BLK:10,SNR1: 1.1851 ,SNR2: 5.3692




Frequency (Hz)


0912-132 2024/10/29 21.53UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030062955




No.Good Data





Frequency (Hz)

0912-132 2024/10/29 21.53UT FUJI -KISO






T20241030063724




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0919-142 2024/10/29 21.65UT TOYOKAWA-FUJI



T20241030063724





BLK: 9,SNR1: 7.0792 ,SNR2: 17.286




Frequency (Hz)

K20241030063722




BLK: 9,SNR1: 12.547 ,SNR2: 30.704





Frequency (Hz)


0919-142 2024/10/29 21.65UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030063722




No.Good Data





Frequency (Hz)


0919-142 2024/10/29 21.65UT FUJI -KISO





T20241030064403




No.Good Data




FUJI





No.Good Data




0926+117 2024/10/29 21.76UT TOYOKAWA-FUJI



T20241030064403





BLK: 4, SNR1: 1.9122 , SNR2: 4.5313




Frequency (Hz)

K20241030064401




BLK: 4, SNR1: 5.8382 , SNR2: 11.647





Frequency (Hz)


0926+117 2024/10/29 21.76UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241030064401




No.Good Data




0926+117 2024/10/29 21.76UT FUJI -KISO




T20241030065147




No.Good Data




FUJI





No.Good Data




3C222 2024/10/29 21.89UT TOYOKAWA-FUJI




T20241030065147




BLK: 3,SNR1: 0.56855 ,SNR2: 1.2881




K20241030065145



BLK: 3,SNR1: 5.2056 ,SNR2: 14.716





3C222 2024/10/29 21.89UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241030065145




No.Good Data





Frequency (Hz)


3C222 2024/10/29 21.89UT FUJI -KISO





T20241030065847




No.Good Data




FUJI





No.Good Data




0941-08 2024/10/29 22.01UT TOYOKAWA-FUJI



T20241030065847





BLK: 9,SNR1: 9.4238 ,SNR2: 24.339




Frequency (Hz)

0941-08 2024/10/29 22.01UT TOYOKAWA-KISO


K20241030065845





BLK: 9,SNR1: 11.435 ,SNR2: 29.412




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241030065845




No.Good Data





Frequency (Hz)


0941-08 2024/10/29 22.01UT FUJI -KISO





T20241030070709




No.Good Data




FUJI





No.Good Data




3C230 2024/10/29 22.15UT TOYOKAWA-FUJI




T20241030070709




BLK: 4,SNR1: 0.55534E-01,SNR2: 2.1904




K20241030070707





BLK: 4,SNR1: 4.0900 ,SNR2: 8.2361




3C230 2024/10/29 22.15UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030070707




No.Good Data





Frequency (Hz)


3C230 2024/10/29 22.15UT FUJI -KISO



T20241030072310





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C237 2024/10/29 22.41UT TOYOKAWA-FUJI






T20241030072310





BLK:10,SNR1: 7.8490 ,SNR2: 20.048




Frequency (Hz)

K20241030072308




BLK:10,SNR1: 9.5022 ,SNR2: 24.292





Frequency (Hz)


3C237 2024/10/29 22.41UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030072308




No.Good Data





Frequency (Hz)


3C237 2024/10/29 22.41UT FUJI -KISO





T20241030072926




No.Good Data




FUJI




No.Good Data




1011+110 2024/10/29 22.52UT TOYOKAWA-FUJI





T20241030072926




BLK: 9,SNR1: 0.16735 ,SNR2: 2.0587




K20241030072924





BLK: 9,SNR1: 6.5280 ,SNR2: 13.864




1011+110 2024/10/29 22.52UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030072924




No.Good Data





Frequency (Hz)


1011+110 2024/10/29 22.52UT FUJI -KISO





T20241030073707




No.Good Data




FUJI





No.Good Data




3C241 2024/10/29 22.65UT TOYOKAWA-FUJI



T20241030073707





BLK: 2, SNR1: 0.13598 , SNR2: 2.1267




Frequency (Hz)

3C241 2024/10/29 22.85UT TOYOKAWA-KISO


K20241030073705





BLK: 2, SNR1: 9.7002 , SNR2: 24.638




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241030073705




No.Good Data





Frequency (Hz)

3C241 2024/10/29 22.65UT FUJI -KISO








T20241030074837




No.Good Data




FUJI





No.Good Data




1031-11 2024/10/29 22.84UT TOYOKAWA-FUJI



T20241030074837





BLK: 5, SNR1: 0.53661 , SNR2: 1.3290




Frequency (Hz)

K20241030074835




BLK: 5, SNR1: 5.3947 , SNR2: 14.701





Frequency (Hz)


1031-11 2024/10/29 22.84UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030074835




No.Good Data





Frequency (Hz)


1031-11 2024/10/29 22.84UT FUJI -KISO





T20241030075310




No.Good Data




FUJI





No.Good Data




1035-058 2024/10/29 22.91UT TOYOKAWA-FUJI





T20241030075310




BLK:14,SNR1: 7.4859 ,SNR2: 12.947




K20241030075308





BLK:14,SNR1: 9.7629 ,SNR2: 16.849




1035-058 2024/10/29 22.91UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030075308




No.Good Data





Frequency (Hz)


1035-058 2024/10/29 22.91UT FUJI -KISO





T20241030080223




No.Good Data




FUJI





No.Good Data




1044-008 2024/10/29 23.07UT TOYOKAWA-FUJI



T20241030080223





BLK: 4,SNR1: 0.62246E-01,SNR2: 0.96160





1044-008 2024/10/29 23.07UT TOYOKAWA-KISO

K20241030080221





BLK: 4,SNR1: 1.2645 ,SNR2: 3.9511






FUJI





No.Good Data




Frequency (Hz)

K20241030080221




No.Good Data





Frequency (Hz)


1044-008 2024/10/29 23.07UT FUJI -KISO





T20241030081327




No.Good Data




FUJI





No.Good Data




1055+01 2024/10/29 23.25UT TOYOKAWA-FUJI



T20241030081327




BLK: 8, SNR1: 4.1268 , SNR2: 11.743





1055+01 2024/10/29 23.25UT TOYOKAWA-KISO



K20241030081324




BLK: 8, SNR1: 0.44034 , SNR2: 1.7446



FUJI





No.Good Data




Frequency (Hz)

K20241030081324




No.Good Data





Frequency (Hz)


1055+01 2024/10/29 23.25UT FUJI -KISO





T20241030082445




No.Good Data




FUJI




No.Good Data




1107+109 2024/10/29 23.44UT TOYOKAWA-FUJI



T20241030082445





BLK:13,SNR1: 10.708 ,SNR2: 17.317





1107+109 2024/10/29 23.44UT TOYOKAWA-KISO


K20241030082442




BLK:13,SNR1: 6.5687 ,SNR2: 27.022



FUJI





No. Good Data




Frequency (Hz)

K20241030082442




No. Good Data





Frequency (Hz)


1107+109 2024/10/29 23.44UT FUJI -KISO





T20241030083422




No.Good Data




FUJI



No.Good Data





3C255 2024/10/29 23.60UT TOYOKAWA-FUJI







T20241030083422




BLK:10,SNR1: 0.13456 ,SNR2: 2.2838




K20241030083420





BLK:10,SNR1: 1.2854 ,SNR2: 3.3698




3C255 2024/10/29 23.60UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030083420




No.Good Data





Frequency (Hz)


3C255 2024/10/29 23.60UT FUJI -KISO





T20241030084500




No.Good Data




FUJI





No.Good Data




1127-14 2024/10/29 23.78UT TOYOKAWA-FUJI



T20241030084500




BLK: 8, SNR1: 0.21054 , SNR2: 2.2725




Frequency (Hz)

1127-14 2024/10/29 23.78UT TOYOKAWA-KISO


K20241030084458





BLK: 8, SNR1: 3.0762 , SNR2: 9.1633




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241030084458




No.Good Data





Frequency (Hz)


1127-14 2024/10/29 23.78UT FUJI -KISO





T20241030090447




No. Good Data




FUJI





No. Good Data




3C267 2024/10/30 0.11UT TOYOKAWA-FUJI



T20241030090447





BLK: 8,SNR1: 0.19075 ,SNR2: 0.90393




Frequency (Hz)

3C267 2024/10/30 0.11UT TOYOKAWA-KISO


K20241030090445





BLK: 8,SNR1: 5.9809 ,SNR2: 17.378




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241030090445




No.Good Data




Frequency (Hz)

3C267 2024/10/30 0.11UT FUJI -KISO








T20241030093035




No. Good Data




FUJI




No. Good Data




1213-17 2024/10/30 0.54UT TOYOKAWA-FUJI



T20241030093035





BLK:14,SNR1: 1.1218 ,SNR2: 7.7004





1213-17 2024/10/30 0.54UT TOYOKAWA-KISO



K20241030093033




BLK:14,SNR1: 1.5823 ,SNR2: 10.253



FUJI





No.Good Data




Frequency (Hz)

K20241030093033




No.Good Data





Frequency (Hz)


1213-17 2024/10/30 0.54UT FUJI -KISO





T20241030094352




No. Good Data




FUJI





No. Good Data




3C273 2024/10/30 0.76UT TOYOKAWA-FUJI



T20241030094352





BLK:29,SNR1: 7.5674 ,SNR2: 35.838




Frequency (Hz)

3C273 2024/10/30 0.76UT TOYOKAWA-KISO


K20241030094350





BLK:29,SNR1: 0.94189 ,SNR2: 3.5291




Frequency (Hz)



FUJI





No. Good Data




Frequency (Hz)

K20241030094350




No. Good Data





Frequency (Hz)


3C273 2024/10/30 0.76UT FUJI -KISO



T20241030095703





No. Good Data




Frequency (Hz)

FUJI




No. Good Data




Frequency (Hz)


3C275 2024/10/30 0.98UT TOYOKAWA-FUJI




T20241030095703




BLK:26,SNR1: 0.31736 ,SNR2: 2.9314




K20241030095700



BLK:26,SNR1: 1.8014 ,SNR2: 7.4413





3C275 2024/10/30 0.98UT TOYOKAWA-KISO






FUJI





No. Good Data




Frequency (Hz)

K20241030095700




No. Good Data





Frequency (Hz)


3C275 2024/10/30 0.98UT FUJI -KISO



T20241030100308





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1245-19 2024/10/30 1.08UT TOYOKAWA-FUJI




T20241030100308




BLK:22,SNR1: 0.52750 ,SNR2: 4.9185




K20241030100305





BLK:22,SNR1: 0.49292 ,SNR2: 2.2527




1245-19 2024/10/30 1.08UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241030100305




No. Good Data





Frequency (Hz)


1245-19 2024/10/30 1.08UT FUJI -KISO



T20241030101051





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C279 2024/10/30 1.21UT TOYOKAWA-FUJI



T20241030101051





BLK:18,SNR1: 5.3131 ,SNR2: 8.5775




Frequency (Hz)

3C279 2024/10/30 1.21UT TOYOKAWA-KISO


K20241030101048





BLK:18,SNR1: 1.3773 ,SNR2: 4.6675




Frequency (Hz)



FUJI





No. Good Data




Frequency (Hz)

K20241030101048




No. Good Data





Frequency (Hz)


3C279 2024/10/30 1.21UT FUJI -KISO





T20241030102621




No.Good Data




FUJI



No.Good Data




3C283 2024/10/30 1.47UT TOYOKAWA-FUJI








T20241030102621




BLK:34,SNR1: 2.9690 ,SNR2: 6.7850



K20241030102619




BLK:34,SNR1: 0.79519 ,SNR2: 4.6349





3C283 2024/10/30 1.47UT TOYOKAWA-KISO


Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241030102619




No.Good Data





Frequency (Hz)


3C283 2024/10/30 1.47UT FUJI -KISO



T20241030104045





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1323+32 2024/10/30 1.71UT TOYOKAWA-FUJI



T20241030104045





BLK:11,SNR1: 0.21033 ,SNR2: 1.8526





1323+32 2024/10/30 1.71UT TOYOKAWA-KISO



K20241030104043




BLK:11,SNR1: 0.45307 ,SNR2: 1.8261



FUJI





No.Good Data




Frequency (Hz)

K20241030104043




No.Good Data





Frequency (Hz)


1323+32 2024/10/30 1.71UT FUJI -KISO





T20241030104536




No.Good Data




FUJI




No.Good Data




3C286 2024/10/30 1.79UT TOYOKAWA-FUJI





T20241030104536




BLK:21,SNR1: 1.0583 ,SNR2: 5.2941




K20241030104534





BLK:21,SNR1:-0.10360 ,SNR2: 1.2812




3C286 2024/10/30 1.79UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030104534




No.Good Data





Frequency (Hz)

3C286 2024/10/30 1.79UT FUJI -KISO






T20241030110203





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1345+12 2024/10/30 2.06UT TOYOKAWA-FUJI





T20241030110203




BLK:30,SNR1: 1.1590 ,SNR2: 10.227




K20241030110201





BLK:30,SNR1: 0.32371 ,SNR2: 1.2245




1345+12 2024/10/30 2.06UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030110201




No.Good Data





Frequency (Hz)


1345+12 2024/10/30 2.06UT FUJI -KISO



T20241030111223





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1355+01 2024/10/30 2.23UT TOYOKAWA-FUJI



T20241030111223




BLK:27,SNR1: 2.2683 ,SNR2: 11.092




1355+01 2024/10/30 2.23UT TOYOKAWA-KISO


K20241030111220





BLK:27,SNR1: 0.32481 ,SNR2: 1.1191




Frequency (Hz)



FUJI





No. Good Data




Frequency (Hz)

K20241030111220




No. Good Data





Frequency (Hz)


1355+01 2024/10/30 2.23UT FUJI -KISO





T20241030113334




No.Good Data




FUJI




No.Good Data




3C298 2024/10/30 2.59UT TOYOKAWA-FUJI




T20241030113334




BLK:27,SNR1: 8.5002 ,SNR2: 34.565




K20241030113332



BLK:27,SNR1: 47.584 ,SNR2: 82.550





3C298 2024/10/30 2.59UT TOYOKAWA-KISO






FUJI





No. Good Data




Frequency (Hz)

K20241030113332




No. Good Data





Frequency (Hz)


3C298 2024/10/30 2.59UT FUJI -KISO



T20241030114517





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1428-03 2024/10/30 2.78UT TOYOKAWA-FUJI








1428-03 2024/10/30 2.78UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030114515




No.Good Data





Frequency (Hz)


1428-03 2024/10/30 2.78UT FUJI -KISO



T20241030115120





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1434+03 2024/10/30 2.88UT TOYOKAWA-FUJI





T20241030115120




BLK:16,SNR1: 0.24596 ,SNR2: 2.1982




K20241030115117





BLK:16,SNR1: 0.26486 ,SNR2: 1.1705




1434+03 2024/10/30 2.88UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030115117




No.Good Data





Frequency (Hz)


1434+03 2024/10/30 2.88UT FUJI -KISO



T20241030121022





No.Good Data




Frequency (Hz)

FUJI




No.Good Data







Frequency (Hz)


1453-10 2024/10/30 3.20UT TOYOKAWA-FUJI










1453-10 2024/10/30 3.20UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030121020




No.Good Data





Frequency (Hz)


1453-10 2024/10/30 3.20UT FUJI -KISO



T20241030122514





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1508-05 2024/10/30 3.45UT TOYOKAWA-FUJI





T20241030122514




BLK:11,SNR1: 0.29429 ,SNR2: 2.8013




K20241030122512





BLK:11,SNR1: 0.80799 ,SNR2: 3.1788




1508-05 2024/10/30 3.45UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030122512




No.Good Data





Frequency (Hz)


1508-05 2024/10/30 3.45UT FUJI -KISO



T20241030123414





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C318 2024/10/30 3.60UT TOYOKAWA-FUJI



T20241030123414





BLK:12,SNR1: 0.66828 ,SNR2: 3.1915





3C318 2024/10/30 3.60UT TOYOKAWA-KISO



K20241030123412




BLK:12,SNR1: 52.908 ,SNR2: 82.024



FUJI





No.Good Data




Frequency (Hz)

K20241030123412




No.Good Data





Frequency (Hz)

3C318 2024/10/30 3.60UT FUJI -KISO






T20241030124001





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1523+03 2024/10/30 3.70UT TOYOKAWA-FUJI




T20241030124001




BLK:16,SNR1: 1.0910 ,SNR2: 4.2268




K20241030123959





BLK:16,SNR1: 1.6568 ,SNR2: 5.0985




1523+03 2024/10/30 3.70UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030123959




No.Good Data




Frequency (Hz)


1523+03 2024/10/30 3.70UT FUJI -KISO



T20241030125141





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1535+139 2024/10/30 3.89UT TOYOKAWA-FUJI



T20241030125141





BLK: 5,SNR1:-0.16070E-01,SNR2: 1.1010




Frequency (Hz)

K20241030125139




BLK: 5,SNR1: 0.87768 ,SNR2: 3.0370





Frequency (Hz)


1535+139 2024/10/30 3.89UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030125139




No.Good Data






Frequency (Hz)




1535+139 2024/10/30 3.89UT FUJI -KISO




T20241030130446




FUJI




1548+05 2024/10/30 4.11UT TOYOKAWA-FUJI




T20241030130446




BLK:12,SNR1: 4.8709 ,SNR2: 7.4394




K20241030130443



BLK:12,SNR1: 0.85323 ,SNR2: 3.9147





1548+05 2024/10/30 4.11UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241030130443




No.Good Data






Frequency (Hz)




1548+05 2024/10/30 4.11UT FUJI -KISO




T20241030132308




FUJI




1607+26 2024/10/30 4.41UT TOYOKAWA-FUJI




T20241030132308




BLK: 8,SNR1: 1.5380 ,SNR2: 4.7782




K20241030132306




BLK: 8,SNR1: 7.1266 ,SNR2: 18.576




1607+26 2024/10/30 4.41UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030132306




No.Good Data





Frequency (Hz)


1607+26 2024/10/30 4.41UT FUJI -KISO





T20241030134038




No.Good Data




FUJI




No.Good Data




1623-228 2024/10/30 4.71UT TOYOKAWA-FUJI





T20241030134038




BLK: 2,SNR1: 0.11135 ,SNR2: 1.3155




K20241030134035





BLK: 2,SNR1: 0.66407 ,SNR2: 2.0855




1623-228 2024/10/30 4.71UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030134035




No.Good Data






Frequency (Hz)




1623-228 2024/10/30 4.71UT FUJI -KISO




T20241030134908



FUJI




1631-222 2024/10/30 4.85UT TOYOKAWA-FUJI







T20241030134908




BLK: 7,SNR1: 2.2356 ,SNR2: 5.9187




K20241030134905





BLK: 7,SNR1: 3.9869 ,SNR2: 11.466




1631-222 2024/10/30 4.85UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030134905




No.Good Data





Frequency (Hz)


1631-222 2024/10/30 4.85UT FUJI -KISO



T20241030135446




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1638-025 2024/10/30 4.94UT TOYOKAWA-FUJI





T20241030135446




BLK:10,SNR1: 2.6955 ,SNR2: 11.010




K20241030135443





BLK:10,SNR1: 2.3106 ,SNR2: 7.1970




1638-025 2024/10/30 4.94UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030135443




No.Good Data





Frequency (Hz)


1638-025 2024/10/30 4.94UT FUJI -KISO



T20241030140140





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1644-106 2024/10/30 5.06UT TOYOKAWA-FUJI




T20241030140140




BLK: 5, SNR1: 2.4518 , SNR2: 7.5118




K20241030140137





BLK: 5, SNR1: 3.9902 , SNR2: 10.014




1644-106 2024/10/30 5.06UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030140137




No.Good Data






Frequency (Hz)

1644-106 2024/10/30 5.06UT FUJI -KISO









T20241030140701





FUJI




1650+004 2024/10/30 5.15UT TOYOKAWA-FUJI





T20241030140701




BLK: 9,SNR1: 5.3219 ,SNR2: 13.515




K20241030140659





BLK: 9,SNR1: 11.840 ,SNR2: 29.819




1650+004 2024/10/30 5.15UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030140659




No.Good Data






Frequency (Hz)




1650+004 2024/10/30 5.15UT FUJI -KISO




T20241030141233





FUJI




1656+053 2024/10/30 5.24UT TOYOKAWA-FUJI





T20241030141233




BLK: 6,SNR1: 9.3854 ,SNR2: 22.279




K20241030141231





BLK: 6,SNR1: 9.0981 ,SNR2: 22.536




1656+053 2024/10/30 5.24UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241030141231








No.Good Data




Frequency (Hz)





1656+053 2024/10/30 5.24UT FUJI -KISO






1712-033 2024/10/30 5.51UT TOYOKAWA-FUJI








1712-033 2024/10/30 5.51UT TOYOKAWA-KISO










1712-033 2024/10/30 5.51UT FUJI -KISO








1730-13 2024/10/30 5.81UT TOYOKAWA-FUJI





T20241030144705




BLK: 5, SNR1: 0.65359 , SNR2: 4.1654




K20241030144703





BLK: 5, SNR1: 3.3147 , SNR2: 9.6429




1730-13 2024/10/30 5.81UT TOYOKAWA-KISO





F20241030144707




BLK:11,SNR1: 1.5693 ,SNR2: 3.9848




K20241030144703





BLK:11,SNR1: 3.2711 ,SNR2: 8.4158




1730-13 2024/10/30 5.81UT FUJI -KISO





T20241030150429




BLK: 4,SNR1: 22.051 ,SNR2: 64.214




F20241030150431





BLK: 4,SNR1: 2.4533 ,SNR2: 7.0097




1748+031 2024/10/30 6.10UT TOYOKAWA-FUJI





T20241030150429




BLK: 5,SNR1: 5.0497 ,SNR2: 13.508




K20241030150427





BLK: 5,SNR1: 10.948 ,SNR2: 16.539




1748+031 2024/10/30 6.10UT TOYOKAWA-KISO



F20241030150431





BLK: 2,SNR1: 0.58969 ,SNR2: 3.8876




Frequency (Hz)

K20241030150427




BLK: 2,SNR1: 15.706 ,SNR2: 19.444





Frequency (Hz)


1748+031 2024/10/30 6.10UT FUJI -KISO





T20241030151522




BLK: 8,SNR1: 2.2270 ,SNR2: 5.5665




F20241030151524



BLK: 8,SNR1: 77.907 ,SNR2: 77.148





1759+13 2024/10/30 6.28UT TOYOKAWA-FUJI






T20241030151522




BLK: 8,SNR1: 4.7046 ,SNR2: 10.676




Frequency (Hz)

K20241030151520




BLK: 8,SNR1: 24.068 ,SNR2: 23.462





Frequency (Hz)


1759+13 2024/10/30 6.28UT TOYOKAWA-KISO




F20241030151524




BLK:10,SNR1: 84.235 ,SNR2: 83.414




K20241030151520





BLK:10,SNR1: 23.324 ,SNR2: 22.740




1759+13 2024/10/30 6.28UT FUJI -KISO





T20241030153623




BLK: 5, SNR1: 6.9455 , SNR2: 16.948




F20241030153625





BLK: 5, SNR1: 6.9239 , SNR2: 16.230




1819-096 2024/10/30 6.63UT TOYOKAWA-FUJI





T20241030153623




BLK: 6,SNR1: 4.2051 ,SNR2: 12.097




K20241030153621





BLK: 6,SNR1: 8.8765 ,SNR2: 24.891




1819-096 2024/10/30 6.63UT TOYOKAWA-KISO



F20241030153625





BLK: 7,SNR1: 4.1614 ,SNR2: 10.231




Frequency (Hz)

K20241030153621





BLK: 7,SNR1: 11.018 ,SNR2: 26.409





Frequency (Hz)

1819-096 2024/10/30 6.63UT FUJI -KISO







BLK: 4,SNR1: 0.20939 ,SNR2: 1.3947




BLK: 4,SNR1: 0.80813 ,SNR2: 3.8809




1830-210 2024/10/30 6.82UT TOYOKAWA-FUJI



T20241030154738





BLK: 3, SNR1: 0.72982E-01, SNR2: 1.0164




Frequency (Hz)

K20241030154736








BLK: 3, SNR1: 1.5663, SNR2: 4.1232




Frequency (Hz)

1830-210 2024/10/30 6.82UT TOYOKAWA-KISO






1830-210 2024/10/30 6.82UT FUJI -KISO






T20241030161402




BLK: 7,SNR1: 19.856 ,SNR2: 24.168




Frequency (Hz)

F20241030161404




BLK: 7,SNR1: 21.442 ,SNR2: 25.491




Frequency (Hz)


1858+171 2024/10/30 7.26UT TOYOKAWA-FUJI



T20241030161402




BLK: 2,SNR1: 23.547 ,SNR2: 29.166




Frequency (Hz)

K20241030161359




BLK: 2,SNR1:-0.19619 ,SNR2: 2.1191





Frequency (Hz)


1858+171 2024/10/30 7.26UT TOYOKAWA-KISO



F20241030161404




BLK: 6,SNR1: 21.849 ,SNR2: 29.007




Frequency (Hz)

K20241030161359




BLK: 6,SNR1: 25.155 ,SNR2: 24.622





Frequency (Hz)


1858+171 2024/10/30 7.26UT FUJI -KISO





T20241030162447




BLK: 8, SNR1: 0.35282E-01, SNR2: 1.1701




F20241030162449




BLK: 8, SNR1: 1.2722, SNR2: 2.0988




1908-20 2024/10/30 7.44UT TOYOKAWA-FUJI




T20241030162447




BLK:10,SNR1: 0.72945E-01,SNR2: 1.6392




K20241030162444





BLK:10,SNR1: 0.59561 ,SNR2: 2.0294




1908-20 2024/10/30 7.44UT TOYOKAWA-KISO




F20241030162449




BLK: 3,SNR1: 0.92890E-01,SNR2: 4.5474




K20241030162444




BLK: 3,SNR1: 1.2321 ,SNR2: 3.3538




1908-20 2024/10/30 7.44UT FUJI -KISO




T20241030163138




BLK: 5,SNR1: 0.89432E-01,SNR2: 0.58272




F20241030163140





BLK: 5,SNR1: 1.5515 ,SNR2: 7.6907




1915-121 2024/10/30 7.56UT TOYOKAWA-FUJI



T20241030163138





BLK: 7,SNR1: 0.15581 ,SNR2: 1.2652




Frequency (Hz)

K20241030163135




BLK: 7,SNR1: 2.9072 ,SNR2: 8.2099




Frequency (Hz)

1915-121 2024/10/30 7.56UT TOYOKAWA-KISO






F20241030163140





BLK:13,SNR1: 1.6373 ,SNR2: 4.5917




Frequency (Hz)

K20241030163135




BLK:13,SNR1: 4.0454 ,SNR2: 17.011





Frequency (Hz)


1915-121 2024/10/30 7.56UT FUJI -KISO



T20241030164520




BLK: 4,SNR1: 9.5015 ,SNR2: 22.679




Frequency (Hz)

F20241030164522




BLK: 4,SNR1: 6.7236 ,SNR2: 16.683





Frequency (Hz)


1928-142 2024/10/30 7.78UT TOYOKAWA-FUJI



T20241030164520





BLK: 1, SNR1: 0.12058 , SNR2: 1.8287




Frequency (Hz)

K20241030164517




BLK: 1, SNR1: 4.1699 , SNR2: 11.798




Frequency (Hz)


1928-142 2024/10/30 7.78UT TOYOKAWA-KISO



F20241030164522





BLK: 5, SNR1: 6.2945 , SNR2: 14.555




Frequency (Hz)

K20241030164517




BLK: 5, SNR1: 7.6756 , SNR2: 17.176





Frequency (Hz)


1928-142 2024/10/30 7.78UT FUJI -KISO



T20241030165459





BLK: 8,SNR1: 2.8225 ,SNR2: 3.7546




Frequency (Hz)

1938-15 2024/10/30 7.94UT TOYOKAWA-FUJI


F20241030165501





BLK: 8,SNR1: 1.6164 ,SNR2: 4.6797




Frequency (Hz)



T20241030165459





BLK:10,SNR1: 1.9879 ,SNR2: 4.8304




Frequency (Hz)

K20241030165456




BLK:10,SNR1: 2.6425 ,SNR2: 4.8798




Frequency (Hz)


1938-15 2024/10/30 7.94UT TOYOKAWA-KISO





F20241030165501




BLK: 5, SNR1: 5.9097 , SNR2: 10.599



K20241030165456



BLK: 5, SNR1: 5.9426 , SNR2: 8.8027



1938-15 2024/10/30 7.94UT FUJI -KISO

