




T20241101054433





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0834-19 2024/10/31 20.77UT TOYOKAWA-FUJI



T20241101054433





BLK: 4, SNR1: 24.658 , SNR2: 34.755




Frequency (Hz)

K20241101054431




BLK: 4, SNR1: 13.733 , SNR2: 22.365




Frequency (Hz)

0834-19 2024/10/31 20.77UT TOYOKAWA-KISO



FUJI




No.Good Data



Frequency (Hz)

K20241101054431




No.Good Data





Frequency (Hz)


0834-19 2024/10/31 20.77UT FUJI -KISO




T20241101055506




No.Good Data




FUJI





No.Good Data




0845-177 2024/10/31 20.95UT TOYOKAWA-FUJI



T20241101055506





BLK: 7,SNR1: 12.028 ,SNR2: 16.113




Frequency (Hz)

K20241101055504




BLK: 7,SNR1: 8.9307 ,SNR2: 14.658



Frequency (Hz)

0845-177 2024/10/31 20.95UT TOYOKAWA-KISO



FUJI




No.Good Data



Frequency (Hz)

K20241101055504



No.Good Data





Frequency (Hz)


0845-177 2024/10/31 20.95UT FUJI -KISO




T20241101060021




No.Good Data




FUJI





No.Good Data




0850-206 2024/10/31 21.03UT TOYOKAWA-FUJI



T20241101060021





BLK: 5, SNR1: 0.19513 ,SNR2: 2.3327




Frequency (Hz)

K20241101060019




BLK: 5, SNR1: 0.43952 ,SNR2: 1.4621





Frequency (Hz)

0850-206 2024/10/31 21.03UT TOYOKAWA-KISO






FUJI




No.Good Data




Frequency (Hz)

K20241101060019




No.Good Data





Frequency (Hz)


0850-206 2024/10/31 21.03UT FUJI -KISO




T20241101060659




No.Good Data




FUJI





No.Good Data




0857-191 2024/10/31 21.14UT TOYOKAWA-FUJI



T20241101060659





BLK: 8,SNR1: 7.4203 ,SNR2: 21.046




Frequency (Hz)

K20241101060657




BLK: 8,SNR1: 1.4670 ,SNR2: 9.0885




Frequency (Hz)


0857-191 2024/10/31 21.14UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101060657




No.Good Data





Frequency (Hz)


0857-191 2024/10/31 21.14UT FUJI -KISO





T20241101061304




No.Good Data




FUJI






No.Good Data



0903-041 2024/10/31 21.25UT TOYOKAWA-FUJI






T20241101061304




Frequency (Hz)

0903-041 2024/10/31 21.25UT TOYOKAWA-KISO


K20241101061302



Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241101061302




No.Good Data




Frequency (Hz)


0903-041 2024/10/31 21.25UT FUJI -KISO




T20241101062205




No.Good Data




FUJI



No.Good Data





0912-132 2024/10/31 21.40UT TOYOKAWA-FUJI






T20241101062205





BLK: 8,SNR1: 5.1187 ,SNR2: 12.611




Frequency (Hz)

0912-132 2024/10/31 21.40UT TOYOKAWA-KISO


K20241101062203



BLK: 8,SNR1: 8.5183 ,SNR2: 21.610



Frequency (Hz)





FUJI




No.Good Data



K20241101062203





No.Good Data




0912-132 2024/10/31 21.40UT FUJI -KISO





T20241101062932




No.Good Data




FUJI





No.Good Data




0919-142 2024/10/31 21.52UT TOYOKAWA-FUJI



T20241101062932





BLK: 9,SNR1: 7.1891 ,SNR2: 20.334




Frequency (Hz)

K20241101062929




BLK: 9,SNR1: 7.9729 ,SNR2: 23.027





Frequency (Hz)


0919-142 2024/10/31 21.52UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101062929




No.Good Data





Frequency (Hz)


0919-142 2024/10/31 21.52UT FUJI -KISO





T20241101063611




No.Good Data




FUJI





No.Good Data




0926+117 2024/10/31 21.63UT TOYOKAWA-FUJI



T20241101063611





BLK: 5,SNR1: 0.43931 ,SNR2: 10.761




Frequency (Hz)

0926+117 2024/10/31 21.63UT TOYOKAWA-KISO


K20241101063609






BLK: 5,SNR1: 0.75104 ,SNR2: 2.2216



Frequency (Hz)






FUJI




No.Good Data

K20241101063609





No.Good Data

0926+117 2024/10/31 21.63UT FUJI -KISO








T20241101064356




No.Good Data




FUJI





No.Good Data




3C222 2024/10/31 21.76UT TOYOKAWA-FUJI





T20241101064356




BLK: 6,SNR1: 7.6241 ,SNR2: 19.851




K20241101064354





BLK: 6,SNR1: 8.1414 ,SNR2: 21.047




3C222 2024/10/31 21.76UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241101064354




No.Good Data





Frequency (Hz)


3C222 2024/10/31 21.76UT FUJI -KISO



T20241101065056





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0941-08 2024/10/31 21.88UT TOYOKAWA-FUJI



T20241101065056




BLK: 5, SNR1: 7.3233 ,SNR2: 21.040




Frequency (Hz)

0941-08 2024/10/31 21.88UT TOYOKAWA-KISO


K20241101065054





BLK: 5, SNR1: 9.0560 ,SNR2: 24.772




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241101065054




No.Good Data





Frequency (Hz)


0941-08 2024/10/31 21.88UT FUJI -KISO





T20241101065918




No.Good Data




FUJI





No.Good Data




3C230 2024/10/31 22.02UT TOYOKAWA-FUJI



T20241101065918





BLK: 9,SNR1: 0.16870 ,SNR2: 1.2984




Frequency (Hz)

K20241101065915




BLK: 9,SNR1: 0.95488E-01,SNR2: 1.5862





Frequency (Hz)

3C230 2024/10/31 22.02UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241101065915




No.Good Data





Frequency (Hz)


3C230 2024/10/31 22.02UT FUJI -KISO





T20241101071518




No.Good Data




FUJI





No.Good Data




3C237 2024/10/31 22.28UT TOYOKAWA-FUJI



T20241101071518





BLK: 5, SNR1: 5.6116 , SNR2: 14.137




Frequency (Hz)

3C237 2024/10/31 22.28UT TOYOKAWA-KISO


K20241101071515



BLK: 5, SNR1: 9.5584 , SNR2: 24.677




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241101071515




No.Good Data





Frequency (Hz)


3C237 2024/10/31 22.28UT FUJI -KISO





T20241101072134




No.Good Data




FUJI





No.Good Data




1011+110 2024/10/31 22.39UT TOYOKAWA-FUJI



T20241101072134




BLK: 5,SNR1: 0.41063E-01,SNR2: 0.47872





1011+110 2024/10/31 22.39UT TOYOKAWA-KISO



K20241101072131




BLK: 5,SNR1: 0.80975 ,SNR2: 2.9233



FUJI




No. Good Data




Frequency (Hz)

K20241101072131




No. Good Data





Frequency (Hz)


1011+110 2024/10/31 22.39UT FUJI -KISO





T20241101072915




No.Good Data




FUJI



No.Good Data





3C241 2024/10/31 22.52UT TOYOKAWA-FUJI







T20241101072915




BLK: 4, SNR1: 0.14521 , SNR2: 0.85466




K20241101072912





BLK: 4, SNR1: 3.4630 , SNR2: 9.8656




3C241 2024/10/31 22.52UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101072912




No.Good Data




Frequency (Hz)


3C241 2024/10/31 22.52UT FUJI -KISO





T20241101074045




No.Good Data




FUJI





No.Good Data




1031-11 2024/10/31 22.71UT TOYOKAWA-FUJI



T20241101074045





BLK: 7,SNR1: 3.4688 ,SNR2: 10.295





1031-11 2024/10/31 22.71UT TOYOKAWA-KISO


K20241101074042



BLK: 7,SNR1: 7.6316 ,SNR2: 22.148



FUJI





No.Good Data




Frequency (Hz)

K20241101074042




No.Good Data





Frequency (Hz)


1031-11 2024/10/31 22.71UT FUJI -KISO





T20241101074518




No.Good Data




FUJI






No.Good Data






1035-058 2024/10/31 22.78UT TOYOKAWA-FUJI




T20241101074518



K20241101074515



1035-058 2024/10/31 22.78UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101074515




No.Good Data





Frequency (Hz)

1035-058 2024/10/31 22.78UT FUJI -KISO








T20241101075431




No.Good Data




FUJI





No.Good Data




1044-008 2024/10/31 22.94UT TOYOKAWA-FUJI



T20241101075431





BLK: 4,SNR1: 0.21793 ,SNR2: 0.58415




Frequency (Hz)

K20241101075428




BLK: 4,SNR1: 2.0218 ,SNR2: 6.1595



Frequency (Hz)

1044-008 2024/10/31 22.94UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101075428




No.Good Data




Frequency (Hz)


1044-008 2024/10/31 22.94UT FUJI -KISO





T20241101080535




No.Good Data




FUJI




No.Good Data




1055+01 2024/10/31 23.12UT TOYOKAWA-FUJI



T20241101080535





BLK:14,SNR1: 48.745 ,SNR2: 131.85





1055+01 2024/10/31 23.12UT TOYOKAWA-KISO

K20241101080533



BLK:14,SNR1: 0.41066 ,SNR2: 1.5925



FUJI





No.Good Data




Frequency (Hz)

K20241101080533




No.Good Data





Frequency (Hz)


1055+01 2024/10/31 23.12UT FUJI -KISO





T20241101081653




No.Good Data




FUJI





No.Good Data




1107+109 2024/10/31 23.31UT TOYOKAWA-FUJI



T20241101081653




BLK: 7,SNR1: 0.87610E-01,SNR2: 0.91995





1107+109 2024/10/31 23.31UT TOYOKAWA-KISO

K20241101081651





BLK: 7,SNR1: 0.95154 ,SNR2: 1.9202






FUJI





No.Good Data




Frequency (Hz)

K20241101081651




No.Good Data




Frequency (Hz)


1107+109 2024/10/31 23.31UT FUJI -KISO





T20241101082630




No.Good Data




FUJI





No.Good Data




3C255 2024/10/31 23.47UT TOYOKAWA-FUJI



T20241101082630





BLK:24,SNR1: 1.3140 ,SNR2: 9.8090




Frequency (Hz)

K20241101082627




BLK:24,SNR1: 1.4666 ,SNR2: 4.0410



Frequency (Hz)

3C255 2024/10/31 23.47UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241101082627




No. Good Data




Frequency (Hz)


3C255 2024/10/31 23.47UT FUJI -KISO





T20241101083708




No. Good Data




FUJI





No. Good Data




1127-14 2024/10/31 23.65UT TOYOKAWA-FUJI



T20241101083708





BLK: 9, SNR1: 0.30024 , SNR2: 2.3896





1127-14 2024/10/31 23.65UT TOYOKAWA-KISO



K20241101083705




BLK: 9, SNR1: 6.8388 , SNR2: 17.524



FUJI





No. Good Data




Frequency (Hz)

K20241101083705




No. Good Data





Frequency (Hz)


1127-14 2024/10/31 23.65UT FUJI -KISO





T20241101085028




No. Good Data




FUJI








No. Good Data





3C263.1 2024/10/31 23.87UT TOYOKAWA-FUJI








FUJI





No. Good Data




Frequency (Hz)

K20241101085025




No. Good Data





Frequency (Hz)


3C263.1 2024/10/31 23.87UT FUJI -KISO



T20241101092243





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


1213-17 2024/11/01 0.41UT TOYOKAWA-FUJI



T20241101092243





BLK: 9, SNR1: 0.35570 , SNR2: 2.7830





1213-17 2024/11/01 0.41UT TOYOKAWA-KISO



K20241101092240




BLK: 9, SNR1: 107.20 , SNR2: 130.29



FUJI





No. Good Data




Frequency (Hz)

K20241101092240




No. Good Data





Frequency (Hz)


1213-17 2024/11/01 0.41UT FUJI -KISO



T20241101093600





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C273 2024/11/01 0.63UT TOYOKAWA-FUJI



T20241101093600





BLK:24,SNR1: 18.001 ,SNR2: 113.28





3C273 2024/11/01 0.63UT TOYOKAWA-KISO



K20241101093557




BLK:24,SNR1: 1.0214 ,SNR2: 4.0445



FUJI



No. Good Data




Frequency (Hz)

K20241101093557




No. Good Data





Frequency (Hz)

3C273 2024/11/01 0.63UT FUJI -KISO








T20241101094911




No.Good Data




FUJI




No.Good Data




3C275 2024/11/01 0.85UT TOYOKAWA-FUJI



T20241101094911





BLK: 5,SNR1: 1.1506 ,SNR2: 10.098





3C275 2024/11/01 0.85UT TOYOKAWA-KISO



K20241101094908




BLK: 5,SNR1: 0.23695 ,SNR2: 1.0783



FUJI





No.Good Data




Frequency (Hz)

K20241101094908




No.Good Data





Frequency (Hz)


3C275 2024/11/01 0.85UT FUJI -KISO





T20241101095516




No.Good Data




FUJI




No.Good Data




1245-19 2024/11/01 0.95UT TOYOKAWA-FUJI





T20241101095516




BLK:23,SNR1: 0.52443 ,SNR2: 3.8707




K20241101095513





BLK:23,SNR1: 0.82570 ,SNR2: 1.7020




1245-19 2024/11/01 0.95UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101095513




No.Good Data





Frequency (Hz)


1245-19 2024/11/01 0.95UT FUJI -KISO



T20241101100300





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C279 2024/11/01 1.08UT TOYOKAWA-FUJI





T20241101100300




BLK:27,SNR1: 0.86222 ,SNR2: 5.2261




K20241101100257



BLK:27,SNR1: 0.48544 ,SNR2: 1.5021





3C279 2024/11/01 1.08UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241101100257




No.Good Data





Frequency (Hz)


3C279 2024/11/01 1.08UT FUJI -KISO





T20241101101829




No.Good Data




FUJI





No.Good Data




3C283 2024/11/01 1.34UT TOYOKAWA-FUJI





T20241101101829




BLK:33,SNR1: 1.6432 ,SNR2: 11.098




K20241101101826





BLK:33,SNR1: 2.1780 ,SNR2: 6.0515




3C283 2024/11/01 1.34UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241101101826




No.Good Data





Frequency (Hz)


3C283 2024/11/01 1.34UT FUJI -KISO



T20241101103254





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1323+32 2024/11/01 1.58UT TOYOKAWA-FUJI





T20241101103254




BLK:15,SNR1: 0.33229 ,SNR2: 3.1196




K20241101103251





BLK:15,SNR1: 0.14201 ,SNR2: 1.2416




1323+32 2024/11/01 1.58UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241101103251




No.Good Data





Frequency (Hz)


1323+32 2024/11/01 1.58UT FUJI -KISO





T20241101103744




No. Good Data




FUJI



No. Good Data




3C286 2024/11/01 1.66UT TOYOKAWA-FUJI








T20241101103744




BLK:29,SNR1: 1.3702 ,SNR2: 7.2636




K20241101103742





BLK:29,SNR1: 5.6101 ,SNR2: 15.483




3C286 2024/11/01 1.66UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241101103742




No. Good Data





Frequency (Hz)


3C286 2024/11/01 1.66UT FUJI -KISO



T20241101105411





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1345+12 2024/11/01 1.93UT TOYOKAWA-FUJI




T20241101105411




BLK:30,SNR1: 1.9644 ,SNR2: 8.8419




K20241101105409





BLK:30,SNR1: 0.67518 ,SNR2: 2.2752



1345+12 2024/11/01 1.93UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241101105409




No. Good Data





Frequency (Hz)


1345+12 2024/11/01 1.93UT FUJI -KISO



T20241101110431





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1355+01 2024/11/01 2.10UT TOYOKAWA-FUJI



T20241101110431




BLK:23,SNR1: 2.4749 ,SNR2: 12.743





1355+01 2024/11/01 2.10UT TOYOKAWA-KISO


K20241101110429



BLK:23,SNR1: 0.65974 ,SNR2: 1.9153



FUJI





No. Good Data




Frequency (Hz)

K20241101110429




No. Good Data





Frequency (Hz)

1355+01 2024/11/01 2.10UT FUJI -KISO






T20241101112542





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

3C298 2024/11/01 2.46UT TOYOKAWA-FUJI






3C298 2024/11/01 2.46UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101112540




No.Good Data





Frequency (Hz)


3C298 2024/11/01 2.46UT FUJI -KISO



T20241101113726





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1428-03 2024/11/01 2.65UT TOYOKAWA-FUJI




T20241101113726




BLK: 7,SNR1: 0.29195 ,SNR2: 0.93914




K20241101113724




BLK: 7,SNR1: 3.7471 ,SNR2: 10.546



1428-03 2024/11/01 2.65UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101113724




No.Good Data





Frequency (Hz)


1428-03 2024/11/01 2.65UT FUJI -KISO



T20241101114328





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1434+03 2024/11/01 2.75UT TOYOKAWA-FUJI




T20241101114328




BLK:20,SNR1: 121.70 ,SNR2: 114.93




K20241101114326



BLK:20,SNR1: 72.549 ,SNR2: 107.49



1434+03 2024/11/01 2.75UT TOYOKAWA-KISO





FUJI





No.Good Data




Frequency (Hz)

K20241101114326



No.Good Data





Frequency (Hz)


1434+03 2024/11/01 2.75UT FUJI -KISO



T20241101120230





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1453-10 2024/11/01 3.07UT TOYOKAWA-FUJI



T20241101120230





BLK: 9,SNR1: 0.54836 ,SNR2: 2.1629





1453-10 2024/11/01 3.07UT TOYOKAWA-KISO



K20241101120228




BLK: 9,SNR1: 0.42359 ,SNR2: 2.0179



FUJI





No. Good Data




Frequency (Hz)

K20241101120228




No. Good Data





Frequency (Hz)


1453-10 2024/11/01 3.07UT FUJI -KISO



T20241101121723





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1508-05 2024/11/01 3.32UT TOYOKAWA-FUJI





T20241101121723




BLK:13,SNR1: 0.29040 ,SNR2: 2.8244




K20241101121721




BLK:13,SNR1: 0.63852 ,SNR2: 2.1789




1508-05 2024/11/01 3.32UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101121721




No.Good Data





Frequency (Hz)


1508-05 2024/11/01 3.32UT FUJI -KISO



T20241101122622





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C318 2024/11/01 3.47UT TOYOKAWA-FUJI








T20241101122622




BLK:16,SNR1: 0.50852 ,SNR2: 3.3995




K20241101122620





BLK:16,SNR1: 0.49177 ,SNR2: 1.9477




3C318 2024/11/01 3.47UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241101122620




No.Good Data





Frequency (Hz)


3C318 2024/11/01 3.47UT FUJI -KISO



T20241101123209





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1523+03 2024/11/01 3.56UT TOYOKAWA-FUJI




T20241101123209




BLK:11,SNR1: 0.29449 ,SNR2: 5.2507




K20241101123207





BLK:11,SNR1: 8.8492 ,SNR2: 11.529




1523+03 2024/11/01 3.56UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101123207




No.Good Data





Frequency (Hz)


1523+03 2024/11/01 3.56UT FUJI -KISO



T20241101124349





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1535+139 2024/11/01 3.76UT TOYOKAWA-FUJI





T20241101124349




BLK: 7,SNR1: 1.0376 ,SNR2: 2.2207




K20241101124347





BLK: 7,SNR1: 9.7288 ,SNR2: 24.807




1535+139 2024/11/01 3.76UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101124347




No.Good Data






Frequency (Hz)

1535+139 2024/11/01 3.76UT FUJI -KISO









T20241101125655







FUJI




1548+05 2024/11/01 3.98UT TOYOKAWA-FUJI








1548+05 2024/11/01 3.98UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101125653




No.Good Data






Frequency (Hz)




1548+05 2024/11/01 3.98UT FUJI -KISO




T20241101131516





FUJI




1607+26 2024/11/01 4.28UT TOYOKAWA-FUJI





T20241101131516




BLK: 4,SNR1: 0.44625 ,SNR2: 1.4481




K20241101131514





BLK: 4,SNR1: 1.8410 ,SNR2: 3.5537




1607+26 2024/11/01 4.28UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241101131514




No. Good Data





Frequency (Hz)


1607+26 2024/11/01 4.28UT FUJI -KISO



T20241101133247





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1623-228 2024/11/01 4.57UT TOYOKAWA-FUJI





T20241101133247




BLK: 8,SNR1: 0.10717E-01,SNR2: 1.7682




K20241101133245



BLK: 8,SNR1: 1.0859 ,SNR2: 2.8613





1623-228 2024/11/01 4.57UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241101133245




No.Good Data






Frequency (Hz)




1623-228 2024/11/01 4.57UT FUJI -KISO




T20241101134117




FUJI




1631-222 2024/11/01 4.72UT TOYOKAWA-FUJI




T20241101134117




BLK:10,SNR1: 12.574 ,SNR2: 26.192




K20241101134115





BLK:10,SNR1: 5.4371 ,SNR2: 11.803




1631-222 2024/11/01 4.72UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101134115




No.Good Data





Frequency (Hz)


1631-222 2024/11/01 4.72UT FUJI -KISO



T20241101134654





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1638-025 2024/11/01 4.81UT TOYOKAWA-FUJI




T20241101134654




BLK:12,SNR1: 0.72930 ,SNR2: 2.1940




K20241101134652





BLK:12,SNR1: 2.4290 ,SNR2: 4.7545




1638-025 2024/11/01 4.81UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101134652




No.Good Data






Frequency (Hz)




1638-025 2024/11/01 4.81UT FUJI -KISO




T20241101135348



FUJI





1644-106 2024/11/01 4.92UT TOYOKAWA-FUJI







T20241101135348




BLK: 9,SNR1: 3.6247 ,SNR2: 8.2929




K20241101135346





BLK: 9,SNR1: 4.9241 ,SNR2: 12.557




1644-106 2024/11/01 4.92UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101135346




No.Good Data




Frequency (Hz)


1644-106 2024/11/01 4.92UT FUJI -KISO



T20241101135909





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1650+004 2024/11/01 5.01UT TOYOKAWA-FUJI





T20241101135909




BLK:10,SNR1: 0.22893 ,SNR2: 1.1797




K20241101135907






BLK:10,SNR1: 2.1310 ,SNR2: 4.9236






1650+004 2024/11/01 5.01UT TOYOKAWA-KISO



FUJI





K20241101135907




1650+004 2024/11/01 5.01UT FUJI -KISO



T20241101140441





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1656+053 2024/11/01 5.11UT TOYOKAWA-FUJI



T20241101140441





BLK: 5,SNR1: 6.5832 ,SNR2: 17.104




Frequency (Hz)

K20241101140439




BLK: 5,SNR1: 8.8641 ,SNR2: 21.005






Frequency (Hz)




1656+053 2024/11/01 5.11UT TOYOKAWA-KISO




FUJI



K20241101140439






1656+053 2024/11/01 5.11UT FUJI -KISO








T20241101142111




No.Good Data

FUJI





No.Good Data


1712-033 2024/11/01 5.38UT TOYOKAWA-FUJI





T20241101142111




BLK: 7,SNR1: 0.62119E-01,SNR2: 0.57336




K20241101142109






BLK: 7,SNR1: 0.16310 ,SNR2: 2.6327






1712-033 2024/11/01 5.38UT TOYOKAWA-KISO




FUJI






K20241101142109






1712-033 2024/11/01 5.38UT FUJI -KISO




T20241101143913





FUJI




1730-13 2024/11/01 5.68UT TOYOKAWA-FUJI



T20241101143913





BLK: 8,SNR1: 0.28117 ,SNR2: 2.2537




Frequency (Hz)

K20241101143911




BLK: 8,SNR1: 2.3355 ,SNR2: 4.0399




Frequency (Hz)


1730-13 2024/11/01 5.68UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101143911




No.Good Data






Frequency (Hz)




1730-13 2024/11/01 5.68UT FUJI -KISO




T20241101145638





FUJI




1748+031 2024/11/01 5.97UT TOYOKAWA-FUJI



T20241101145638





BLK: 4,SNR1: 0.38997 ,SNR2: 1.3732




Frequency (Hz)

K20241101145636




BLK: 4,SNR1: 1.3275 ,SNR2: 8.6504






Frequency (Hz)

1748+031 2024/11/01 5.97UT TOYOKAWA-KISO









FUJI






K20241101145636






1748+031 2024/11/01 5.97UT FUJI -KISO




T20241101150731





FUJI




1759+13 2024/11/01 6.15UT TOYOKAWA-FUJI



T20241101150731





BLK: 9, SNR1: 9.6906 , SNR2: 23.477




Frequency (Hz)

K20241101150729




BLK: 9, SNR1: 15.034 , SNR2: 36.960






Frequency (Hz)




1759+13 2024/11/01 6.15UT TOYOKAWA-KISO




FUJI






K20241101150729






1759+13 2024/11/01 6.15UT FUJI -KISO




T20241101152831




FUJI




1819-096 2024/11/01 6.50UT TOYOKAWA-FUJI



T20241101152831





BLK: 7,SNR1: 2.1326 ,SNR2: 6.4057




Frequency (Hz)

K20241101152829




BLK: 7,SNR1: 4.0138 ,SNR2: 11.053





Frequency (Hz)


1819-096 2024/11/01 6.50UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241101152829





No.Good Data




1819-096 2024/11/01 6.50UT FUJI -KISO



T20241101153946





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

1830-210 2024/11/01 6.69UT TOYOKAWA-FUJI








T20241101153946




BLK:20,SNR1: 0.21762 ,SNR2: 0.83188




K20241101153943





BLK:20,SNR1: 9.1033 ,SNR2: 21.376




1830-210 2024/11/01 6.69UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241101153943




No.Good Data




Frequency (Hz)


1830-210 2024/11/01 6.69UT FUJI -KISO



T20241101160611





BLK: 2,SNR1: 0.50412 ,SNR2: 0.85397




Frequency (Hz)

F20241101160612




BLK: 2,SNR1:-0.12491 ,SNR2: 4.7459





Frequency (Hz)


1858+171 2024/11/01 7.13UT TOYOKAWA-FUJI





T20241101160611




BLK: 2,SNR1:-0.47124E-01,SNR2: 0.24133




K20241101160609





BLK: 2,SNR1: 0.40119E-01,SNR2: 1.8844




1858+171 2024/11/01 7.13UT TOYOKAWA-KISO



F20241101160612




BLK: 5,SNR1: 0.25645 ,SNR2: 4.9875




Frequency (Hz)

K20241101160609




BLK: 5,SNR1: 0.71897E-01,SNR2: 1.0777





Frequency (Hz)


1858+171 2024/11/01 7.13UT FUJI -KISO



T20241101161655





BLK: 2, SNR1: 9.0198 , SNR2: 22.825




Frequency (Hz)

F20241101161655




BLK: 2, SNR1: 6.8773 , SNR2: 19.926




Frequency (Hz)


1908-20 2024/11/01 7.31UT TOYOKAWA-FUJI



T20241101161655




BLK: 5,SNR1: 11.556 ,SNR2: 33.015




Frequency (Hz)

K20241101161653




BLK: 5,SNR1: 11.669 ,SNR2: 27.204




Frequency (Hz)


1908-20 2024/11/01 7.31UT TOYOKAWA-KISO



F20241101161655





BLK: 3, SNR1: 6.0588 , SNR2: 17.613




Frequency (Hz)

K20241101161653




BLK: 3, SNR1: 9.6561 , SNR2: 22.851





Frequency (Hz)

1908-20 2024/11/01 7.31UT FUJI -KISO






T20241101162346





BLK: 1,SNR1:-0.21613 ,SNR2: 0.23541




Frequency (Hz)

F20241101162347




BLK: 1,SNR1:-0.78673E-02,SNR2: 1.1745





Frequency (Hz)


1915-121 2024/11/01 7.42UT TOYOKAWA-FUJI



T20241101162346





BLK: 3,SNR1: 0.19467 ,SNR2: 1.0395




Frequency (Hz)

K20241101162344




BLK: 3,SNR1: 1.5856 ,SNR2: 5.3549





Frequency (Hz)


1915-121 2024/11/01 7.42UT TOYOKAWA-KISO



F20241101162347





BLK: 2,SNR1:-0.60157E-01,SNR2: 1.2714




Frequency (Hz)

K20241101162344




BLK: 2,SNR1:-0.13602E-01,SNR2: 0.18731





Frequency (Hz)


1915-121 2024/11/01 7.42UT FUJI -KISO



T20241101163728





BLK: 1,SNR1:-0.10638 ,SNR2: 0.13452




Frequency (Hz)

F20241101163728




BLK: 1,SNR1:-0.67368E-01,SNR2: 1.6079





Frequency (Hz)


1928-142 2024/11/01 7.65UT TOYOKAWA-FUJI



T20241101163728





BLK: 1,SNR1: 0.19492 ,SNR2: 0.46974




Frequency (Hz)

1928-142 2024/11/01 7.65UT TOYOKAWA-KISO


K20241101163726





BLK: 1,SNR1: 0.23682 ,SNR2: 3.7492






Frequency (Hz)








1928-142 2024/11/01 7.65UT FUJI -KISO






1938-15 2024/11/01 7.81UT TOYOKAWA-FUJI






1938-15 2024/11/01 7.81UT TOYOKAWA-KISO






F20241101164707





BLK: 4,SNR1: 0.51218E-01,SNR2: 0.76846




Frequency (Hz)

K20241101164705




BLK: 4,SNR1: 0.45383 ,SNR2: 1.3308





Frequency (Hz)


1938-15 2024/11/01 7.81UT FUJI -KISO



T20241101170155




BLK: 2,SNR1: 0.43976E-01,SNR2: 0.86356




Frequency (Hz)

F20241101170156




BLK: 2,SNR1: 0.50366 ,SNR2: 2.2831





Frequency (Hz)


1953-077 2024/11/01 8.06UT TOYOKAWA-FUJI



T20241101170155





BLK:11,SNR1:-0.74814E-01,SNR2: 1.6272




Frequency (Hz)

K20241101170153





BLK:11,SNR1: 7.1112 ,SNR2: 20.533





Frequency (Hz)

1953-077 2024/11/01 8.06UT TOYOKAWA-KISO






BLK: 3,SNR1: 0.83657 ,SNR2: 3.0271



BLK: 3,SNR1: 10.302 ,SNR2: 26.040



1953-077 2024/11/01 8.06UT FUJI -KISO

