




T20241114054658





BLK: 9,SNR1: 0.17868 ,SNR2: 2.4887




Frequency (Hz)

F20241114054658




BLK: 9,SNR1: 0.68907 ,SNR2: 2.2716





Frequency (Hz)


0928-179 2024/11/13 20.81UT TOYOKAWA-FUJI



T20241114054658





BLK: 8,SNR1: 0.72250E-01,SNR2: 1.5079




Frequency (Hz)

K20241114054655




BLK: 8,SNR1: 0.42453 ,SNR2: 1.3413




Frequency (Hz)


0928-179 2024/11/13 20.81UT TOYOKAWA-KISO





F20241114054658




BLK: 4,SNR1: 0.53456 ,SNR2: 1.6026




K20241114054655





BLK: 4,SNR1:-0.34830E-01,SNR2: 0.98654




0928-179 2024/11/13 20.81UT FUJI -KISO



T20241114055949





BLK: 4,SNR1: 0.32397 ,SNR2: 3.9201




Frequency (Hz)

F20241114055949




BLK: 4,SNR1: 1.0218 ,SNR2: 3.1782





Frequency (Hz)


0941-08 2024/11/13 21.03UT TOYOKAWA-FUJI



T20241114055949





BLK: 4,SNR1:-0.72627E-01,SNR2: 1.8234




Frequency (Hz)

K20241114055946




BLK: 4,SNR1: 0.95296 ,SNR2: 3.4251





Frequency (Hz)


0941-08 2024/11/13 21.03UT TOYOKAWA-KISO



F20241114055949





BLK: 8,SNR1: 0.31669 ,SNR2: 1.4772




Frequency (Hz)

K20241114055946




BLK: 8,SNR1: 1.2079 ,SNR2: 3.6823




Frequency (Hz)


0941-08 2024/11/13 21.03UT FUJI -KISO



T20241114060811




BLK: 3,SNR1: 0.36150E-01,SNR2: 1.1128




Frequency (Hz)

F20241114060811




BLK: 3,SNR1:-0.52817E-02,SNR2: 3.4317




Frequency (Hz)


3C230 2024/11/13 21.16UT TOYOKAWA-FUJI



T20241114060811




BLK: 5, SNR1: 0.11036 ,SNR2: 2.3011




Frequency (Hz)

3C230 2024/11/13 21.16UT TOYOKAWA-KISO


K20241114060808



BLK: 5, SNR1: 2.7851 ,SNR2: 7.0851





Frequency (Hz)






F20241114060811





BLK: 8,SNR1:-0.98065E-02,SNR2: 1.4806




Frequency (Hz)

3C230 2024/11/13 21.16UT FUJI -KISO


K20241114060808




BLK: 8,SNR1: 1.5643 ,SNR2: 4.0256




Frequency (Hz)



T20241114061734




BLK: 5,SNR1: 0.38830E-01,SNR2: 1.3489




Frequency (Hz)

F20241114061734




BLK: 5,SNR1: 0.19480 ,SNR2: 1.8673





Frequency (Hz)


0958-001 2024/11/13 21.32UT TOYOKAWA-FUJI



T20241114061734




BLK: 6,SNR1: 0.10322 ,SNR2: 1.5475




Frequency (Hz)

K20241114061731




BLK: 6,SNR1: 5.8491 ,SNR2: 15.981





Frequency (Hz)


0958-001 2024/11/13 21.32UT TOYOKAWA-KISO



F20241114061734





BLK: 5,SNR1: 0.17920E-01,SNR2: 1.7522




Frequency (Hz)

K20241114061731




BLK: 5,SNR1: 6.1431 ,SNR2: 16.774





Frequency (Hz)


0958-001 2024/11/13 21.32UT FUJI -KISO



T20241114062411





BLK:10,SNR1: 0.54159 ,SNR2: 5.4062




Frequency (Hz)

3C237 2024/11/13 21.43UT TOYOKAWA-FUJI


F20241114062411





BLK:10,SNR1: 0.28740 ,SNR2: 1.3017




Frequency (Hz)



T20241114062411





BLK: 8,SNR1: 0.34175 ,SNR2: 2.7967




Frequency (Hz)

3C237 2024/11/13 21.43UT TOYOKAWA-KISO


K20241114062408




BLK: 8,SNR1: 0.20723 ,SNR2: 0.49793




Frequency (Hz)





F20241114062411




BLK: 3,SNR1:-0.32621E-01,SNR2: 1.8478




K20241114062408




BLK: 3,SNR1:-0.37252E-01,SNR2: 0.79410




3C237 2024/11/13 21.43UT FUJI -KISO



T20241114063028




BLK: 8,SNR1:-0.88484E-02,SNR2: 0.26291




Frequency (Hz)

F20241114063028




BLK: 8,SNR1: 4.2431 ,SNR2: 11.508




Frequency (Hz)

1011+110 2024/11/13 21.54UT TOYOKAWA-FUJI







T20241114063028




BLK: 4,SNR1: 0.87077E-01,SNR2: 0.45652




K20241114063025






BLK: 4,SNR1: 2.1342 ,SNR2: 6.4117





1011+110 2024/11/13 21.54UT TOYOKAWA-KISO




F20241114063028




K20241114063025




1011+110 2024/11/13 21:54UT FUJI -KISO



T20241114063809




BLK: 2,SNR1: 0.19449 ,SNR2: 0.70025




Frequency (Hz)

3C241 2024/11/13 21.66UT TOYOKAWA-FUJI


F20241114063809





BLK: 2,SNR1: 0.61271 ,SNR2: 2.3731




Frequency (Hz)



T20241114063809




BLK: 1,SNR1: 0.13051E-01,SNR2: 0.41202




Frequency (Hz)

3C241 2024/11/13 21.66UT TOYOKAWA-KISO


K20241114063806




BLK: 1,SNR1: 2.3307 ,SNR2: 3.2916




Frequency (Hz)



F20241114063809





BLK: 2,SNR1:-0.50196E-01,SNR2: 0.75423




Frequency (Hz)

3C241 2024/11/13 21.66UT FUJI -KISO


K20241114063806





BLK: 2,SNR1: 0.42737 ,SNR2: 1.9255




Frequency (Hz)



T20241114064938




BLK: 1,SNR1: 0.10258 ,SNR2: 1.0984




Frequency (Hz)

F20241114064938




BLK: 1,SNR1:-0.23953 ,SNR2: 0.0000




Frequency (Hz)


1031-11 2024/11/13 21.86UT TOYOKAWA-FUJI



T20241114064938





BLK: 3,SNR1: -0.10175 ,SNR2: 0.32901




Frequency (Hz)

K20241114064935




BLK: 3,SNR1: 3.6799 ,SNR2: 9.7831





Frequency (Hz)


1031-11 2024/11/13 21.86UT TOYOKAWA-KISO





F20241114064938




BLK: 3,SNR1: 1.1203 ,SNR2: 2.6477




K20241114064935



BLK: 3,SNR1: 0.96879E-01,SNR2: 1.3691





1031-11 2024/11/13 21.86UT FUJI -KISO






T20241114065411





BLK:11,SNR1: 13.495 ,SNR2: 63.934




Frequency (Hz)

1035-058 2024/11/13 21.93UT TOYOKAWA-FUJI


F20241114065411




BLK:11,SNR1: 0.64358 ,SNR2: 2.5951




Frequency (Hz)



T20241114065411




BLK:11,SNR1: 24.809 ,SNR2: 157.98




Frequency (Hz)

1035-058 2024/11/13 21.93UT TOYOKAWA-KISO


K20241114065408





BLK:11,SNR1: 6.5988 ,SNR2: 17.125




Frequency (Hz)



F20241114065411





BLK: 8,SNR1:-0.43994E-01,SNR2: 1.2409




Frequency (Hz)

K20241114065408




BLK: 8,SNR1: 7.3309 ,SNR2: 21.241





Frequency (Hz)


1035-058 2024/11/13 21.93UT FUJI -KISO



T20241114070214




BLK: 4,SNR1:-0.14471E-01,SNR2: 0.31738





1043+158 2024/11/13 22.07UT TOYOKAWA-FUJI



F20241114070214




BLK: 4,SNR1: 8.5325 ,SNR2: 19.901



T20241114070214




BLK: 3,SNR1: -0.50161E-01,SNR2: 0.24715




Frequency (Hz)

K20241114070211




BLK: 3,SNR1: 0.91688E-01,SNR2: 1.3855





Frequency (Hz)


1043+158 2024/11/13 22.07UT TOYOKAWA-KISO



F20241114070214





BLK: 2,SNR1: 5.2627 ,SNR2: 12.121




Frequency (Hz)

K20241114070211




BLK: 2,SNR1: 0.30855 ,SNR2: 1.4806





Frequency (Hz)


1043+158 2024/11/13 22.07UT FUJI -KISO



T20241114071429




BLK: 5,SNR1: 0.18368 ,SNR2: 0.53247




Frequency (Hz)

F20241114071429




BLK: 5,SNR1: 1.2686 ,SNR2: 3.4986





Frequency (Hz)


1055+01 2024/11/13 22.27UT TOYOKAWA-FUJI



T20241114071429




BLK: 9,SNR1: 0.42846 ,SNR2: 3.5765




Frequency (Hz)

K20241114071426




BLK: 9,SNR1: 1.6298 ,SNR2: 4.2058




Frequency (Hz)

1055+01 2024/11/13 22.27UT TOYOKAWA-KISO







F20241114071429




BLK: 5,SNR1:-0.10479 ,SNR2: 1.2546




K20241114071426





BLK: 5,SNR1: 1.6269 ,SNR2: 5.3432




1055+01 2024/11/13 22.27UT FWJ -KISO





T20241114072546




BLK: 4,SNR1: 0.52999E-01,SNR2: 0.74497




F20241114072546





BLK: 4,SNR1: 0.68643 ,SNR2: 2.9616




1107+109 2024/11/13 22.46UT TOYOKAWA-FUJI




T20241114072546




BLK: 4,SNR1:-0.75158E-02,SNR2: 0.45151




K20241114072543




BLK: 4,SNR1: 5.3520 ,SNR2: 13.082




1107+109 2024/11/13 22.46UT TOYOKAWA-KISO





F20241114072546




BLK: 8,SNR1: 2.9819 ,SNR2: 8.8396




K20241114072543





BLK: 8,SNR1: 3.9112 ,SNR2: 12.132




1107+109 2024/11/13 22.46UT FUJI -KISO



T20241114073523





BLK: 6,SNR1: 0.24626 ,SNR2: 0.91114




Frequency (Hz)

3C255 2024/11/13 22.62UT TOYOKAWA-FUJI


F20241114073523





BLK: 6,SNR1:-0.23213 ,SNR2: 1.2286




Frequency (Hz)





T20241114073523




BLK:11,SNR1: 0.44910E-02,SNR2: 1.5141




K20241114073520





BLK:11,SNR1: 4.4644 ,SNR2: 11.550




3C255 2024/11/13 22.62UT TOYOKAWA-KISO





F20241114073523




BLK: 5, SNR1: -0.37856E-01, SNR2: 1.7632




K20241114073520





BLK: 5, SNR1: 2.1161, SNR2: 6.6425




3C255 2024/11/13 22.62UT FUJI -KISO




T20241114074601




BLK: 7, SNR1: 0.15244 , SNR2: 2.1659




F20241114074601



BLK: 7, SNR1: 1.0433 , SNR2: 3.0488




1127-14 2024/11/13 22.80UT TOYOKAWA-FUJI







T20241114074601




BLK: 3,SNR1: 0.20014 ,SNR2: 1.5039




K20241114074558




BLK: 3,SNR1: 2.4490 ,SNR2: 4.9459




1127-14 2024/11/13 22.80UT TOYOKAWA-KISO



F20241114074601




BLK:10,SNR1: 0.50323 ,SNR2: 1.7504




Frequency (Hz)

K20241114074558




BLK:10,SNR1: 3.4771 ,SNR2: 10.028





Frequency (Hz)


1127-14 2024/11/13 22.80UT FUJI -KISO



T20241114075922




BLK: 6,SNR1: 1.9337 ,SNR2: 4.3641




Frequency (Hz)

3C263.1 2024/11/13 23.02UT TOYOKAWA-FUJI


F20241114075922





BLK: 6,SNR1: 2.4592 ,SNR2: 7.8479




Frequency (Hz)



T20241114075922





BLK:14,SNR1: 7.1598 ,SNR2: 25.445





3C263.1 2024/11/13 23.02UT TOYOKAWA-KISO



K20241114075919




BLK:14,SNR1: 7.3240 ,SNR2: 18.789



F20241114075922





BLK:10,SNR1: 94.643 ,SNR2: 93.265




Frequency (Hz)

K20241114075919




BLK:10,SNR1: 5.9008 ,SNR2: 15.288





Frequency (Hz)


3C263.1 2024/11/13 23.02UT FUJI -KISO



T20241114080548




BLK: 8, SNR1: 3.8367 ,SNR2: 45.328





3C267 2024/11/13 23.12UT TOYOKAWA-FUJI



F20241114080548




BLK: 8, SNR1: 34.795 ,SNR2: 66.886



T20241114080548




BLK: 6,SNR1: 5.0193 ,SNR2: 17.956





3C267 2024/11/13 23.12UT TOYOKAWA-KISO



K20241114080545




BLK: 6,SNR1: 7.7398 ,SNR2: 15.977



F20241114080548





BLK:12,SNR1: 23.036 ,SNR2: 44.218




Frequency (Hz)

3C267 2024/11/13 23.12UT FUJI -KISO


K20241114080545



BLK:12,SNR1: 7.0756 ,SNR2: 14.613





Frequency (Hz)








T20241114083136




BLK: 7, SNR1: 0.32407 , SNR2: 2.2183




F20241114083136





BLK: 7, SNR1: 11.639 , SNR2: 22.160




1213-17 2024/11/13 23.55UT TOYOKAWA-FUJI




T20241114083136




BLK:10,SNR1: 0.64144 ,SNR2: 4.2254




K20241114083133




BLK:10,SNR1: 8.0448 ,SNR2: 21.541




1213-17 2024/11/13 23.55UT TOYOKAWA-KISO



F20241114083136




BLK: 8,SNR1: 5.6629 ,SNR2: 14.264





1213-17 2024/11/13 23.55UT FUJI -KISO



K20241114083133




BLK: 8,SNR1: 8.2544 ,SNR2: 21.242



T20241114084454





BLK: 9,SNR1: 7.8914 ,SNR2: 23.238




Frequency (Hz)

3C273 2024/11/13 23.78UT TOYOKAWA-FUJI


F20241114084454





BLK: 9,SNR1: 10.563 ,SNR2: 26.643




Frequency (Hz)



T20241114084454





BLK:10,SNR1: 12.441 ,SNR2: 30.692




Frequency (Hz)

K20241114084451




BLK:10,SNR1: 11.644 ,SNR2: 29.374




Frequency (Hz)


3C273 2024/11/13 23.78UT TOYOKAWA-KISO



F20241114084454




BLK: 8,SNR1: 7.1735 ,SNR2: 20.677





3C273 2024/11/13 23.78UT FUJI -KISO



K20241114084451




BLK: 8,SNR1: 11.304 ,SNR2: 28.517





T20241114085359




No.Good Data




FUJI




No.Good Data




1235-226 2024/11/13 23.93UT TOYOKAWA-FUJI



T20241114085359




BLK:12,SNR1: 3.4377 ,SNR2: 7.9733





1235-226 2024/11/13 23.93UT TOYOKAWA-KISO

K20241114085356



BLK:12,SNR1: 5.7465 ,SNR2: 13.735








FUJI




No.Good Data



K20241114085356




No.Good Data




1235-226 2024/11/13 23.93UT FUJI -KISO



T20241114090409





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1245-19 2024/11/14 0.10UT TOYOKAWA-FUJI



T20241114090409





BLK:18,SNR1: 0.30808 ,SNR2: 2.5501





1245-19 2024/11/14 0.10UT TOYOKAWA-KISO

K20241114090406



BLK:18,SNR1: 0.34387 ,SNR2: 1.6604



FUJI





No. Good Data




Frequency (Hz)

K20241114090406




No. Good Data




Frequency (Hz)


1245-19 2024/11/14 0.10UT FUJI -KISO



T20241114091153





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C279 2024/11/14 0.23UT TOYOKAWA-FUJI



T20241114091153





BLK:13,SNR1: 9.4973 ,SNR2: 23.826





3C279 2024/11/14 0.23UT TOYOKAWA-KISO



K20241114091150




BLK:13,SNR1: 11.006 ,SNR2: 27.529



FUJI





No.Good Data




Frequency (Hz)

K20241114091150




No.Good Data





Frequency (Hz)


3C279 2024/11/14 0.23UT FUJI -KISO





T20241114092722




No. Good Data




FUJI



No. Good Data





3C283 2024/11/14 0.48UT TOYOKAWA-FUJI






T20241114092722





BLK:18,SNR1: 2.0949 ,SNR2: 3.7684





3C283 2024/11/14 0.48UT TOYOKAWA-KISO



K20241114092719




BLK:18,SNR1: 6.4071 ,SNR2: 18.499



FUJI





No. Good Data




Frequency (Hz)

K20241114092719




No. Good Data





Frequency (Hz)


3C283 2024/11/14 0.48UT FUJI -KISO



T20241114094147





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


1323+32 2024/11/14 0.72UT TOYOKAWA-FUJI



T20241114094147




BLK: 5, SNR1: 6.4870 , SNR2: 17.034





1323+32 2024/11/14 0.72UT TOYOKAWA-KISO

K20241114094145



BLK: 5, SNR1: 17.684 , SNR2: 42.838



FUJI





No. Good Data




Frequency (Hz)

K20241114094145




No. Good Data





Frequency (Hz)


1323+32 2024/11/14 0.72UT FUJI -KISO



T20241114094637





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C286 2024/11/14 0.81UT TOYOKAWA-FUJI



T20241114094637




BLK:25,SNR1: 2.3571 ,SNR2: 5.5629





3C286 2024/11/14 0.81UT TOYOKAWA-KISO



K20241114094634




BLK:25,SNR1: 0.49656 ,SNR2: 1.5947



FUJI



No. Good Data




Frequency (Hz)

K20241114094634




No. Good Data





Frequency (Hz)

3C286 2024/11/14 0.81UT FUJI -KISO






T20241114100304





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1345+12 2024/11/14 1.08UT TOYOKAWA-FUJI



T20241114100304





BLK:11,SNR1: 3.7855 ,SNR2: 9.7447




Frequency (Hz)

1345+12 2024/11/14 1.08UT TOYOKAWA-KISO


K20241114100301





BLK:11,SNR1: 11.237 ,SNR2: 25.096




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241114100301




No.Good Data





Frequency (Hz)


1345+12 2024/11/14 1.08UT FUJI -KISO





T20241114101325




No. Good Data




FUJI




No. Good Data




1355+01 2024/11/14 1.25UT TOYOKAWA-FUJI



T20241114101325




BLK:13,SNR1: 0.67264 ,SNR2: 4.0426





1355+01 2024/11/14 1.25UT TOYOKAWA-KISO



K20241114101322




BLK:13,SNR1: 5.0421 ,SNR2: 14.693



FUJI





No.Good Data




Frequency (Hz)

K20241114101322




No.Good Data





Frequency (Hz)


1355+01 2024/11/14 1.25UT FUJI -KISO



T20241114103435





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C298 2024/11/14 1.60UT TOYOKAWA-FUJI




T20241114103435




BLK:28,SNR1: 29.504 ,SNR2: 50.760




K20241114103432



BLK:28,SNR1: 3.7632 ,SNR2: 11.791





3C298 2024/11/14 1.60UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241114103432




No.Good Data





Frequency (Hz)


3C298 2024/11/14 1.60UT FUJI -KISO



T20241114104619





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1428-03 2024/11/14 1.80UT TOYOKAWA-FUJI





T20241114104619




BLK: 8,SNR1: 1.3170 ,SNR2: 3.4272




K20241114104616





BLK: 8,SNR1: 1.3643 ,SNR2: 4.1802




1428-03 2024/11/14 1.80UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241114104616




No.Good Data





Frequency (Hz)


1428-03 2024/11/14 1.80UT FUJI -KISO



T20241114105221





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1434+03 2024/11/14 1.90UT TOYOKAWA-FUJI



T20241114105221




BLK: 9, SNR1: 4.0136 ,SNR2: 10.231





1434+03 2024/11/14 1.90UT TOYOKAWA-KISO



K20241114105218




BLK: 9, SNR1: 12.149 ,SNR2: 29.052



FUJI



No. Good Data



Frequency (Hz)

K20241114105218




No. Good Data





Frequency (Hz)


1434+03 2024/11/14 1.90UT FUJI -KISO



T20241114111124





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1453-10 2024/11/14 2.22UT TOYOKAWA-FUJI






T20241114111124





BLK: 8, SNR1: 9.7738 ,SNR2: 24.657





1453-10 2024/11/14 2.22UT TOYOKAWA-KISO



K20241114111121




BLK: 8, SNR1: 11.673 ,SNR2: 29.042



FUJI





No.Good Data




Frequency (Hz)

K20241114111121




No.Good Data





Frequency (Hz)


1453-10 2024/11/14 2.22UT FUJI -KISO



T20241114112616





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1508-05 2024/11/14 2.47UT TOYOKAWA-FUJI



T20241114112616




BLK: 9,SNR1: 1.7149 ,SNR2: 3.6844





1508-05 2024/11/14 2.47UT TOYOKAWA-KISO



K20241114112613




BLK: 9,SNR1: 9.3118 ,SNR2: 23.031



FUJI





No.Good Data




Frequency (Hz)

K20241114112613




No.Good Data





Frequency (Hz)


1508-05 2024/11/14 2.47UT FUJI -KISO



T20241114113516





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


3C318 2024/11/14 2.62UT TOYOKAWA-FUJI



T20241114113516




BLK:16,SNR1: 3.6109 ,SNR2: 11.020





3C318 2024/11/14 2.62UT TOYOKAWA-KISO


K20241114113513



BLK:16,SNR1: 10.816 ,SNR2: 20.778



FUJI





No.Good Data




Frequency (Hz)

K20241114113513




No.Good Data





Frequency (Hz)

3C318 2024/11/14 2.62UT FUJI -KISO






T20241114114103





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1523+03 2024/11/14 2.71UT TOYOKAWA-FUJI






1523+03 2024/11/14 2.71UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241114114100








No.Good Data




Frequency (Hz)

1523+03 2024/11/14 2.71UT FUJI -KISO








1535+139 2024/11/14 2.91UT TOYOKAWA-FUJI




T20241114115242




BLK: 3,SNR1: 0.38948 ,SNR2: 0.62780




K20241114115239




BLK: 3,SNR1: 0.21670 ,SNR2: 1.6225





1535+139 2024/11/14 2.91UT TOYOKAWA-KISO







BLK: 2,SNR1: 0.15255 ,SNR2: 4.9158





BLK: 2,SNR1: 0.21836 ,SNR2: 0.52889




1535+139 2024/11/14 2.91UT FUJI -KISO



T20241114120306





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1545-12 2024/11/14 3.08UT TOYOKAWA-FUJI





1545-12 2024/11/14 3.08UT TOYOKAWA-KISO





FUJI





No.Good Data




Frequency (Hz)

K20241114120303




No.Good Data






Frequency (Hz)




1545-12 2024/11/14 3.08UT FUJI -KISO




T20241114122409





FUJI




1607+26 2024/11/14 3.43UT TOYOKAWA-FUJI





T20241114122409




BLK: 6,SNR1: 0.16544E-02,SNR2: 1.5153




K20241114122406




BLK: 6,SNR1: 0.55158 ,SNR2: 4.2167




1607+26 2024/11/14 3.43UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241114122406




No.Good Data





Frequency (Hz)


1607+26 2024/11/14 3.43UT FUJI -KISO





T20241114123913




BLK: 3,SNR1: 0.65530 ,SNR2: 5.5220




F20241114123915





BLK: 3,SNR1: 1.2744 ,SNR2: 2.7554




1621-11 2024/11/14 3.68UT TOYOKAWA-FUJI





T20241114123913




BLK: 6,SNR1: 0.89813E-01,SNR2: 1.1150




K20241114123910





BLK: 6,SNR1: 0.53072 ,SNR2: 1.7711




1621-11 2024/11/14 3.68UT TOYOKAWA-KISO



F20241114123915





BLK: 1,SNR1: 0.10295 ,SNR2: 0.44238





1621-11 2024/11/14 3.68UT FUJI -KISO



K20241114123910




BLK: 1,SNR1: 0.21418 ,SNR2: 6.3632





T20241114125010




BLK: 8,SNR1: 2.5216 ,SNR2: 14.720




F20241114125012



BLK: 8,SNR1: 0.50988 ,SNR2: 1.4989




1631-222 2024/11/14 3.86UT TOYOKAWA-FUJI






T20241114125010




BLK:17,SNR1: 2.2570 ,SNR2: 14.139





1631-222 2024/11/14 3.86UT TOYOKAWA-KISO


K20241114125007




BLK:17,SNR1: 0.18788 ,SNR2: 1.5343





F20241114125012




BLK:18,SNR1: 0.50552 ,SNR2: 1.7273




K20241114125007




BLK:18,SNR1: 0.83210E-01,SNR2: 1.3350




1631-222 2024/11/14 3.86UT FUJI -KISO





T20241114125547




BLK:11,SNR1: 1.4804 ,SNR2: 12.128




F20241114125549





BLK:11,SNR1:-0.17518 ,SNR2: 1.7835




1638-025 2024/11/14 3.96UT TOYOKAWA-FUJI



T20241114125547





BLK:13,SNR1: 5.5495 ,SNR2: 10.760




Frequency (Hz)

1638-025 2024/11/14 3.96UT TOYOKAWA-KISO


K20241114125544





BLK:13,SNR1: 2.2335 ,SNR2: 5.5420




Frequency (Hz)





F20241114125549




BLK: 7,SNR1: 8.4207 ,SNR2: 24.262




K20241114125544




BLK: 7,SNR1: 1.0675 ,SNR2: 1.8731




1638-025 2024/11/14 3.96UT FUJI -KISO




T20241114130242




BLK:14,SNR1: 0.40395 ,SNR2: 2.2389




F20241114130243




BLK:14,SNR1: -0.35171E-01,SNR2: 1.3534




1644-106 2024/11/14 4.07UT TOYOKAWA-FUJI





T20241114130242




BLK:10,SNR1: 0.72502 ,SNR2: 1.8068




K20241114130239




BLK:10,SNR1: 0.90484 ,SNR2: 2.7495




1644-106 2024/11/14 4.07UT TOYOKAWA-KISO





F20241114130243




BLK: 4,SNR1: 0.65454 ,SNR2: 2.7806




K20241114130239







BLK: 4,SNR1: 0.96048 ,SNR2: 3.1933




1644-106 2024/11/14 4.07UT FUJI -KISO
















1650+004 2024/11/14 4.16UT TOYOKAWA-FUJI










1650+004 2024/11/14 4.16UT TOYOKAWA-KISO










1650+004 2024/11/14 4.16UT FUJI -KISO






1656+053 2024/11/14 4.25UT TOYOKAWA-FUJI







1656+053 2024/11/14 4.25UT TOYOKAWA-KISO





F20241114131335




BLK: 4,SNR1: 0.23926E-01,SNR2: 1.4616




K20241114131331





BLK: 4,SNR1:-0.47213E-03,SNR2: 1.0664




1656+053 2024/11/14 4.25UT FUJI -KISO




T20241114133004




BLK: 4,SNR1: 0.17590 ,SNR2: 1.1363




F20241114133004





BLK: 4,SNR1: 0.11600 ,SNR2: 1.3520




1712-033 2024/11/14 4.53UT TOYOKAWA-FUJI





T20241114133004




BLK:10,SNR1: 0.13309 ,SNR2: 0.81431




K20241114133001



BLK:10,SNR1: 0.74066 ,SNR2: 2.2601




1712-033 2024/11/14 4.53UT TOYOKAWA-KISO








F20241114133004




BLK: 6,SNR1: -0.19497 ,SNR2: 0.83953




K20241114133001





BLK: 6,SNR1: 1.0412 ,SNR2: 2.6081




1712-033 2024/11/14 4.53UT FUJI -KISO





T20241114134806




BLK: 8,SNR1: 0.65494 ,SNR2: 4.8951




F20241114134806





BLK: 8,SNR1: -0.88154E-02,SNR2: 0.68225




1730-13 2024/11/14 4.83UT TOYOKAWA-FUJI





T20241114134806




BLK: 7,SNR1: 0.43454 ,SNR2: 4.9941




K20241114134803





BLK: 7,SNR1: 0.67154 ,SNR2: 2.8875




1730-13 2024/11/14 4.83UT TOYOKAWA-KISO





F20241114134806




BLK: 5, SNR1: 0.14867 ,SNR2: 1.5024




K20241114134803




BLK: 5, SNR1: 1.8617 ,SNR2: 9.1337




1730-13 2024/11/14 4.83UT FUJI -KISO




T20241114140531




BLK: 4,SNR1: 15.678 ,SNR2: 75.583




F20241114140531




BLK: 4,SNR1: -0.28640 ,SNR2: 1.4841




1748+031 2024/11/14 5.12UT TOYOKAWA-FUJI





T20241114140531




BLK: 5,SNR1: 73.860 ,SNR2: 104.15




K20241114140528




BLK: 5,SNR1:-0.46880E-01,SNR2: 1.4660




1748+031 2024/11/14 5.12UT TOYOKAWA-KISO





F20241114140531




BLK: 4,SNR1: 0.16911 ,SNR2: 9.0094




K20241114140528




BLK: 4,SNR1: 0.21657 ,SNR2: 2.8141





1748+031 2024/11/14 5.12UT FUJI -KISO







BLK: 5,SNR1: 4.1482 ,SNR2: 10.973



BLK: 5,SNR1: 16.523 ,SNR2: 36.982





1759+13 2024/11/14 5.30UT TOYOKAWA-FUJI








T20241114141624




BLK: 7,SNR1: 0.82199 ,SNR2: 2.7406




K20241114141621







BLK: 7,SNR1: 3.7912 ,SNR2: 7.3092




1759+13 2024/11/14 5.30UT TOYOKAWA-KISO








1759+13 2024/11/14 5.30UT FUJI -KISO



T20241114143724





BLK: 5,SNR1: 0.34230 ,SNR2: 0.72484




Frequency (Hz)

F20241114143724




BLK: 5,SNR1: 0.64223 ,SNR2: 1.6831





Frequency (Hz)


1819-096 2024/11/14 5.65UT TOYOKAWA-FUJI





T20241114143724




BLK: 3,SNR1: 0.11565 ,SNR2: 1.2268




K20241114143721





BLK: 3,SNR1: 0.96410E-01,SNR2: 2.4472




1819-096 2024/11/14 5.65UT TOYOKAWA-KISO





F20241114143724




BLK: 7,SNR1:-0.10849 ,SNR2: 0.93654




K20241114143721





BLK: 7,SNR1: 0.91329E-01,SNR2: 1.1321




1819-096 2024/11/14 5.65UT FUJI -KISO





T20241114144839




BLK: 9,SNR1: 0.26203 ,SNR2: 1.7295




F20241114144839





BLK: 9,SNR1: 9.4138 ,SNR2: 22.328




1830-210 2024/11/14 5.84UT TOYOKAWA-FUJI



T20241114144839





BLK: 6,SNR1: 0.77389 ,SNR2: 6.6134




Frequency (Hz)

K20241114144836




BLK: 6,SNR1: 1.1598 ,SNR2: 5.0680





Frequency (Hz)


1830-210 2024/11/14 5.84UT TOYOKAWA-KISO





F20241114144839




BLK: 4,SNR1: 1.1792 ,SNR2: 3.3378




K20241114144836



BLK: 4,SNR1: 5.0516 ,SNR2: 11.693





1830-210 2024/11/14 5.84UT FUJI -KISO







T20241114151504




BLK: 2,SNR1: 0.81552E-01,SNR2: 0.76393




F20241114151505





BLK: 2,SNR1:-0.83673E-01,SNR2: 1.8862




1858+171 2024/11/14 6.28UT TOYOKAWA-FUJI





T20241114151504




BLK: 4,SNR1: 0.11490 ,SNR2: 0.84557




K20241114151501




BLK: 4,SNR1: 3.0018 ,SNR2: 6.3971




1858+171 2024/11/14 6.28UT TOYOKAWA-KISO





F20241114151505




BLK: 5,SNR1:-0.37230E-01,SNR2: 1.7094




K20241114151501





BLK: 5,SNR1: 0.87785 ,SNR2: 4.0407




1858+171 2024/11/14 6.28UT FUJI -KISO





T20241114152549




BLK: 2,SNR1: 2.3891 ,SNR2: 12.725




F20241114152549





BLK: 2,SNR1: 1.5833 ,SNR2: 5.9415




1908-20 2024/11/14 6.46UT TOYOKAWA-FUJI



T20241114152549





BLK: 4,SNR1: 1.0384 ,SNR2: 4.4636




Frequency (Hz)

K20241114152546




BLK: 4,SNR1: 0.33752 ,SNR2: 2.3009





Frequency (Hz)


1908-20 2024/11/14 6.46UT TOYOKAWA-KISO





F20241114152549




BLK: 1,SNR1:-0.62575E-01,SNR2: 0.76523




K20241114152546





BLK: 1,SNR1: 0.11596 ,SNR2: 2.1277




1908-20 2024/11/14 6.46UT FUJI -KISO



T20241114153239




BLK: 4,SNR1: 0.10682 ,SNR2: 1.5536




Frequency (Hz)

F20241114153240








BLK: 4,SNR1: 5.2577 ,SNR2: 13.434




Frequency (Hz)

1915-121 2024/11/14 6.57UT TOYOKAWA-FUJI







1915-121 2024/11/14 6.57UT TOYOKAWA-KISO






F20241114153240





BLK: 6,SNR1: 5.0338 ,SNR2: 12.867




Frequency (Hz)

K20241114153236




BLK: 6,SNR1: 1.8575 ,SNR2: 5.5453





Frequency (Hz)


1915-121 2024/11/14 6.57UT FUJI -KISO



T20241114154621





BLK:14,SNR1: 42.581 ,SNR2: 81.074




Frequency (Hz)

F20241114154621




BLK:14,SNR1: 6.9310 ,SNR2: 18.766





Frequency (Hz)


1928-142 2024/11/14 6.80UT TOYOKAWA-FUJI



T20241114154621




BLK:22,SNR1: 12.245 ,SNR2: 28.354




Frequency (Hz)

K20241114154618




BLK:22,SNR1: 9.8738 ,SNR2: 23.230





Frequency (Hz)


1928-142 2024/11/14 6.80UT TOYOKAWA-KISO




F20241114154621




BLK:17,SNR1: 9.8177 ,SNR2: 24.425




K20241114154618





BLK:17,SNR1: 9.7326 ,SNR2: 23.142




1928-142 2024/11/14 6.80UT FUJI -KISO




T20241114155600




BLK:18,SNR1: 109.46 ,SNR2: 99.652




F20241114155601




BLK:18,SNR1: 19.834 ,SNR2: 34.039




1938-15 2024/11/14 6.96UT TOYOKAWA-FUJI



T20241114155600




BLK:10,SNR1: 112.42 ,SNR2: 113.54




Frequency (Hz)

K20241114155557




BLK:10,SNR1: 53.420 ,SNR2: 69.535




Frequency (Hz)


1938-15 2024/11/14 6.96UT TOYOKAWA-KISO



F20241114155601





BLK:12,SNR1: 21.586 ,SNR2: 46.958




Frequency (Hz)

K20241114155557




BLK:12,SNR1: 30.460 ,SNR2: 44.465





Frequency (Hz)


1938-15 2024/11/14 6.96UT FUJI -KISO





T20241114170133




No.Good Data




F20241114170133



No.Good Data





3C422 2024/11/14 8.05UT TOYOKAWA-FUJI








T20241114170133




No.Good Data




K20241114170130




No.Good Data




3C422 2024/11/14 8.05UT TOYOKAWA-KISO



F20241114170133




BLK: 1,SNR1: 7.9646 ,SNR2: 20.944




Frequency (Hz)

K20241114170130




BLK: 1,SNR1: 16.918 ,SNR2: 25.852





Frequency (Hz)


3C422 2024/11/14 8.05UT FUJI -KISO



T20241114171037




BLK: 7, SNR1: 0.14048 , SNR2: 1.9215




Frequency (Hz)

F20241114171037




BLK: 7, SNR1: 1.0547 , SNR2: 3.4540





Frequency (Hz)


2053-201 2024/11/14 8.21UT TOYOKAWA-FUJI



T20241114171037




BLK: 5,SNR1: 0.44572 ,SNR2: 3.0012




Frequency (Hz)

K20241114171034






BLK: 5,SNR1: 2.2247 ,SNR2: 5.5543




Frequency (Hz)

2053-201 2024/11/14 8.21UT TOYOKAWA-KISO







2053-201 2024/11/14 8.21UT FUJI -KISO



T20241114171642





BLK: 5, SNR1: 12.659 , SNR2: 19.214




Frequency (Hz)

F20241114171642




BLK: 5, SNR1: 9.5736 , SNR2: 22.918




Frequency (Hz)


2059-127 2024/11/14 8.31UT TOYOKAWA-FUJI



T20241114171642





BLK: 6,SNR1: 10.959 ,SNR2: 24.109




Frequency (Hz)

K20241114171639




BLK: 6,SNR1: 11.238 ,SNR2: 26.642





Frequency (Hz)


2059-127 2024/11/14 8.31UT TOYOKAWA-KISO



F20241114171642





BLK: 4, SNR1: 3.7569 , SNR2: 10.020




Frequency (Hz)

K20241114171639




BLK: 4, SNR1: 8.9378 , SNR2: 19.121




Frequency (Hz)

2059-127 2024/11/14 8.31UT FUJI -KISO






T20241114172155




BLK:12,SNR1: 0.87431 ,SNR2: 6.7024




Frequency (Hz)

F20241114172155




BLK:12,SNR1: 116.19 ,SNR2: 128.17




Frequency (Hz)


2104-184 2024/11/14 8.39UT TOYOKAWA-FUJI



T20241114172155





BLK:11,SNR1: 0.88249 ,SNR2: 4.4812




Frequency (Hz)

K20241114172152




BLK:11,SNR1: 4.7470 ,SNR2: 11.810




Frequency (Hz)


2104-184 2024/11/14 8.39UT TOYOKAWA-KISO



F20241114172155





BLK:15,SNR1: 79.867 ,SNR2: 85.795




Frequency (Hz)

K20241114172152



BLK:15,SNR1: 5.3153 ,SNR2: 13.148



Frequency (Hz)

2104-184 2024/11/14 8.39UT FUJI -KISO

