




T20241202054613





BLK: 5, SNR1: 1.5871 ,SNR2: 4.8046




Frequency (Hz)

F20241202054615




BLK: 5, SNR1: 3.5636 ,SNR2: 10.564




Frequency (Hz)


1038-191 2024/12/01 20.80UT TOYOKAWA-FUJI




T20241202054613




BLK: 4,SNR1: 0.41632E-01,SNR2: 1.4969




K20241202054612



BLK: 4,SNR1: 11.060 ,SNR2: 27.992





1038-191 2024/12/01 20.80UT TOYOKAWA-KISO








F20241202054615




BLK: 4,SNR1: 2.5984 ,SNR2: 7.8290




K20241202054612





BLK: 4,SNR1: 7.4364 ,SNR2: 19.878




1038-191 2024/12/01 20.80UT FUJI -KISO



T20241202055646





BLK: 4,SNR1: 0.23769 ,SNR2: 0.75046




Frequency (Hz)

F20241202055648




BLK: 4,SNR1: 1.2697 ,SNR2: 4.4736





Frequency (Hz)


1048-090 2024/12/01 20.97UT TOYOKAWA-FUJI



T20241202055646





BLK: 6,SNR1: 0.76364E-01,SNR2: 0.78780




Frequency (Hz)

K20241202055645




BLK: 6,SNR1: 5.5697 ,SNR2: 14.388




Frequency (Hz)


1048-090 2024/12/01 20.97UT TOYOKAWA-KISO



F20241202055648




BLK: 6,SNR1: 3.5365 ,SNR2: 9.4548




Frequency (Hz)

K20241202055645




BLK: 6,SNR1: 6.4080 ,SNR2: 19.186




Frequency (Hz)


1048-090 2024/12/01 20.97UT FUJI -KISO



T20241202060719




BLK:10,SNR1: 67.451 ,SNR2: 334.36




Frequency (Hz)

F20241202060721




BLK:10,SNR1: 0.11084 ,SNR2: 1.7813





Frequency (Hz)


1059-010 2024/12/01 21.15UT TOYOKAWA-FUJI



T20241202060719





BLK:11,SNR1: 75.883 ,SNR2: 453.42




Frequency (Hz)

K20241202060718




BLK:11,SNR1: 6.6511 ,SNR2: 16.353





Frequency (Hz)


1059-010 2024/12/01 21.15UT TOYOKAWA-KISO



F20241202060721





BLK:17,SNR1: 2.0594 ,SNR2: 5.5928




Frequency (Hz)

K20241202060718




BLK:17,SNR1: 6.1206 ,SNR2: 14.816





Frequency (Hz)


1059-010 2024/12/01 21.15UT FUJI -KISO



T20241202061525





BLK:10,SNR1: 2.9463 ,SNR2: 40.044




Frequency (Hz)

F20241202061527




BLK:10,SNR1: 0.41103E-02,SNR2: 1.0682





Frequency (Hz)

1107+045 2024/12/01 21.29UT TOYOKAWA-FUJI






T20241202061525





BLK: 7,SNR1: 0.79267 ,SNR2: 7.3213




Frequency (Hz)

K20241202061524




BLK: 7,SNR1: 5.4619 ,SNR2: 13.724





Frequency (Hz)


1107+045 2024/12/01 21.29UT TOYOKAWA-KISO



F20241202061527





BLK: 4,SNR1:-0.20303 ,SNR2: 1.0544




Frequency (Hz)

K20241202061524




BLK: 4,SNR1: 2.0442 ,SNR2: 9.4927





Frequency (Hz)


1107+045 2024/12/01 21.29UT FUJI -KISO



T20241202062437





BLK:11,SNR1: 11.082 ,SNR2: 41.861




Frequency (Hz)

3C255 2024/12/01 21.44UT TOYOKAWA-FUJI


F20241202062439





BLK:11,SNR1: 0.13483 ,SNR2: 2.0636




Frequency (Hz)



T20241202062437





BLK: 5, SNR1: 19.653 ,SNR2: 102.37




Frequency (Hz)

3C255 2024/12/01 21.44UT TOYOKAWA-KISO


K20241202062436




BLK: 5, SNR1: 1.0958 ,SNR2: 3.4367




Frequency (Hz)





F20241202062439




BLK: 5, SNR1: 0.30232 , SNR2: 1.5395




K20241202062436




BLK: 5, SNR1: 3.6324 , SNR2: 9.9068




3C255 2024/12/01 21.44UT FUJI -KISO



T20241202063515




BLK: 6,SNR1: 0.50963E-01,SNR2: 2.0609




Frequency (Hz)

F20241202063517




BLK: 6,SNR1: 3.1421 ,SNR2: 5.1582





Frequency (Hz)


1127-14 2024/12/01 21.62UT TOYOKAWA-FUJI



T20241202063515





BLK: 4,SNR1: 0.13439 ,SNR2: 2.4813




Frequency (Hz)

K20241202063514




BLK: 4,SNR1: 0.27331 ,SNR2: 1.6375





Frequency (Hz)


1127-14 2024/12/01 21.62UT TOYOKAWA-KISO



F20241202063517





BLK: 5,SNR1: 0.26709 ,SNR2: 3.0926




Frequency (Hz)

K20241202063514




BLK: 5,SNR1: 0.16613 ,SNR2: 0.85340





Frequency (Hz)

1127-14 2024/12/01 21.62UT FUJI -KISO






T20241202064835




BLK: 4,SNR1: 2.5503 ,SNR2: 22.612





3C263.1 2024/12/01 21.84UT TOYOKAWA-FUJI



F20241202064837




BLK: 4,SNR1:-0.21224 ,SNR2: 0.45689



T20241202064835




BLK: 5, SNR1: 3.1673 ,SNR2: 43.824




Frequency (Hz)

K20241202064834




BLK: 5, SNR1: 1.1149 ,SNR2: 3.1934





Frequency (Hz)


3C263.1 2024/12/01 21.84UT TOYOKAWA-KISO



F20241202064837





BLK: 4,SNR1:-0.11123 ,SNR2: 0.0000




Frequency (Hz)

3C263.1 2024/12/01 21.84UT FUJI -KISO


K20241202064834




BLK: 4,SNR1: 0.82761 ,SNR2: 4.6192




Frequency (Hz)



T20241202065502




BLK: 5,SNR1: 20.610 ,SNR2: 94.221




Frequency (Hz)

3C267 2024/12/01 21.95UT TOYOKAWA-FUJI


F20241202065504




BLK: 5,SNR1: 1.4420 ,SNR2: 3.6535




Frequency (Hz)



T20241202065502




BLK: 1,SNR1: 0.13179 ,SNR2: 1.3910




Frequency (Hz)

3C267 2024/12/01 21.95UT TOYOKAWA-KISO


K20241202065501




BLK: 1,SNR1: 0.20977 ,SNR2: 6.7568




Frequency (Hz)



F20241202065504




BLK: 6,SNR1:-0.29132 ,SNR2: 1.0016





3C267 2024/12/01 21.95UT FUJI -KISO



K20241202065501




BLK: 6,SNR1: 6.9357 ,SNR2: 12.332



T20241202072050





BLK: 2,SNR1:-0.68434E-01,SNR2: 0.96134




Frequency (Hz)

F20241202072052




BLK: 2,SNR1:-0.17955 ,SNR2: 2.7758





Frequency (Hz)


1213-17 2024/12/01 22.38UT TOYOKAWA-FUJI



T20241202072050




BLK: 6,SNR1: 0.48187E-02,SNR2: 0.81244




Frequency (Hz)

K20241202072049




BLK: 6,SNR1: 1.3956 ,SNR2: 4.2131





Frequency (Hz)

1213-17 2024/12/01 22.38UT TOYOKAWA-KISO








F20241202072052




BLK: 4,SNR1:-0.21845 ,SNR2: 1.1343




K20241202072049






BLK: 4,SNR1: 0.48794E-01,SNR2: 3.9306






1213-17 2024/12/01 22.38UT FUJI -KISO




T20241202073407




F20241202073409






3C273 2024/12/01 22.60UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.49649 ,SNR2: 3.6231





BLK: 8,SNR1: 1.3103 ,SNR2: 5.3344




3C273 2024/12/01 22.80UT TOYOKAWA-KISO



F20241202073409





BLK: 5,SNR1: 1.9832 ,SNR2: 10.107




Frequency (Hz)

3C273 2024/12/01 22.60UT FUJI -KISO


K20241202073406





BLK: 5,SNR1: 0.87306E-01,SNR2: 0.48230




Frequency (Hz)



T20241202074718




BLK: 3,SNR1: 0.14417 ,SNR2: 2.2467




Frequency (Hz)

F20241202074720




BLK: 3,SNR1: 0.72859E-01,SNR2: 2.5859





Frequency (Hz)


3C275 2024/12/01 22.82UT TOYOKAWA-FUJI



T20241202074718





BLK: 3,SNR1: 0.27512 ,SNR2: 1.3157




Frequency (Hz)

K20241202074717




BLK: 3,SNR1: 5.1195 ,SNR2: 16.898





Frequency (Hz)


3C275 2024/12/01 22.82UT TOYOKAWA-KISO



F20241202074720





BLK:11,SNR1: 1.0490 ,SNR2: 2.6073




Frequency (Hz)

3C275 2024/12/01 22.82UT FUJI -KISO


K20241202074717





BLK:11,SNR1: 3.1503 ,SNR2: 4.9145




Frequency (Hz)



T20241202075323





BLK: 6,SNR1: 0.59063 ,SNR2: 2.4321




Frequency (Hz)

F20241202075325




BLK: 6,SNR1:-0.10630 ,SNR2: 0.90397





Frequency (Hz)

1245-19 2024/12/01 22.92UT TOYOKAWA-FUJI






T20241202075323





BLK:10,SNR1: 0.53034 ,SNR2: 3.0036




Frequency (Hz)

1245-19 2024/12/01 22.92UT TOYOKAWA-KISO


K20241202075322




BLK:10,SNR1: 0.71402 ,SNR2: 1.0416




Frequency (Hz)





F20241202075325




BLK: 6,SNR1: 0.53431 ,SNR2: 2.2418




K20241202075322





BLK: 6,SNR1: 0.60091 ,SNR2: 2.2048




1245-19 2024/12/01 22.92UT FUJI -KISO



T20241202080107





BLK: 3, SNR1: 6.4069 ,SNR2: 17.810




Frequency (Hz)

3C279 2024/12/01 23.05UT TOYOKAWA-FUJI


F20241202080109





BLK: 3, SNR1: 7.1768 ,SNR2: 17.830




Frequency (Hz)



T20241202080107





BLK: 6,SNR1: 6.8901 ,SNR2: 17.489




Frequency (Hz)

3C279 2024/12/01 23.05UT TOYOKAWA-KISO


K20241202080106





BLK: 6,SNR1: 6.7164 ,SNR2: 23.815




Frequency (Hz)



F20241202080109





BLK: 2,SNR1: 7.3010 ,SNR2: 20.345




Frequency (Hz)

3C279 2024/12/01 23.05UT FUJI -KISO


K20241202080106





BLK: 2,SNR1: 1.5468 ,SNR2: 7.5530




Frequency (Hz)



T20241202081636




BLK: 8,SNR1: 0.42391 ,SNR2: 2.6274




Frequency (Hz)

F20241202081638




BLK: 8,SNR1: 5.0869 ,SNR2: 14.414




Frequency (Hz)


3C283 2024/12/01 23.30UT TOYOKAWA-FUJI



T20241202081636




BLK: 3,SNR1: 0.33324 ,SNR2: 2.7369




Frequency (Hz)

3C283 2024/12/01 23.30UT TOYOKAWA-KISO


K20241202081635





BLK: 3,SNR1: 0.16837 ,SNR2: 0.87877




Frequency (Hz)



F20241202081638





BLK: 5,SNR1: 3.9567 ,SNR2: 11.617




Frequency (Hz)

3C283 2024/12/01 23.30UT FUJI -KISO


K20241202081635



BLK: 5,SNR1: 8.2496 ,SNR2: 26.448





Frequency (Hz)






T20241202083101





BLK: 6,SNR1: 0.99434E-01,SNR2: 0.72329




Frequency (Hz)

F20241202083103




BLK: 6,SNR1: 3.6916 ,SNR2: 6.6442





Frequency (Hz)


1323+32 2024/12/01 23.55UT TOYOKAWA-FUJI



T20241202083101





BLK: 3,SNR1: 0.56624E-02,SNR2: 0.29967





1323+32 2024/12/01 23.55UT TOYOKAWA-KISO


K20241202083100




BLK: 3,SNR1: 0.27638 ,SNR2: 1.5100





F20241202083103




BLK: 4,SNR1: 5.7362 ,SNR2: 10.981




K20241202083100





BLK: 4,SNR1: 0.81234 ,SNR2: 3.1547




1323+32 2024/12/01 23.55UT FUJI -KISO




T20241202083551




BLK: 6,SNR1: 2.4247 ,SNR2: 8.2662




F20241202083553




BLK: 6,SNR1: 7.1119 ,SNR2: 10.243




3C286 2024/12/01 23.63UT TOYOKAWA-FUJI



T20241202083551




BLK:12,SNR1: 8.9218 ,SNR2: 57.095




Frequency (Hz)

3C286 2024/12/01 23.63UT TOYOKAWA-KISO


K20241202083550




BLK:12,SNR1: 6.1024 ,SNR2: 13.296




Frequency (Hz)



F20241202083553




BLK: 4,SNR1: 9.7205 ,SNR2: 13.935





3C286 2024/12/01 23.63UT FUJI -KISO


K20241202083550




BLK: 4,SNR1: 8.9381 ,SNR2: 15.991





T20241202085218




BLK: 3, SNR1: 0.30938 , SNR2: 1.3548




F20241202085220





BLK: 3, SNR1: 0.13381 , SNR2: 3.2186




1345+12 2024/12/01 23.90UT TOYOKAWA-FUJI





T20241202085218




No. Good Data




K20241202085217



No. Good Data




1345+12 2024/12/01 23.90UT TOYOKAWA-KISO








F20241202085220




BLK: 1,SNR1: 0.54036 ,SNR2: 2.5387




K20241202085217





BLK: 1,SNR1: 0.12932E-02,SNR2: 0.11583




1345+12 2024/12/01 23.90UT FUJI -KISO



T20241202090239




BLK: 6,SNR1: 36.984 ,SNR2: 46.379





1355+01 2024/12/02 0.07UT TOYOKAWA-FUJI


F20241202090241




BLK: 6,SNR1:-0.13327 ,SNR2: 2.0947



T20241202090239





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


1355+01 2024/12/02 0.07UT TOYOKAWA-KISO





F20241202090241




No.Good Data




KISO




No.Good Data




1355+01 2024/12/02 0.07UT FUJI -KISO



T20241202092349





BLK:21,SNR1: 5.7354 ,SNR2: 13.326





3C298 2024/12/02 0.43UT TOYOKAWA-FUJI


F20241202092351




BLK:21,SNR1: 14.191 ,SNR2: 24.618



T20241202092349




BLK:24,SNR1: 8.2500 ,SNR2: 11.318





3C298 2024/12/02 0.43UT TOYOKAWA-KISO



K20241202092346




BLK:24,SNR1: 23.942 ,SNR2: 30.207



F20241202092351




BLK:30,SNR1: 13.889 ,SNR2: 24.101





3C298 2024/12/02 0.43UT FUJI -KISO


K20241202092346




BLK:30,SNR1: 25.187 ,SNR2: 31.574





T20241202093533




BLK: 4, SNR1: 13.027 , SNR2: 23.254




F20241202093535



BLK: 4, SNR1: 8.5437 , SNR2: 15.109




1428-03 2024/12/02 0.62UT TOYOKAWA-FUJI






T20241202093533





BLK: 3,SNR1: 12.533 ,SNR2: 22.387





1428-03 2024/12/02 0.62UT TOYOKAWA-KISO


K20241202093530




BLK: 3,SNR1: 17.300 ,SNR2: 31.027



F20241202093535





BLK: 2,SNR1: 21.071 ,SNR2: 27.492





1428-03 2024/12/02 0.62UT FUJI -KISO


K20241202093530




BLK: 2,SNR1: 7.3889 ,SNR2: 22.036



T20241202094414




BLK: 1,SNR1: 7.5516 ,SNR2: 19.018





1436-16 2024/12/02 0.77UT TOYOKAWA-FUJI


F20241202094416




BLK: 1,SNR1: 7.8292 ,SNR2: 19.674



T20241202094414




BLK: 1,SNR1: 16.017 ,SNR2: 26.476





1436-16 2024/12/02 0.77UT TOYOKAWA-KISO



K20241202094411




BLK: 1,SNR1: 18.283 ,SNR2: 29.954



F20241202094416





BLK: 3, SNR1: 17.180 , SNR2: 31.694




Frequency (Hz)

K20241202094411




BLK: 3, SNR1: 21.064 , SNR2: 37.406




Frequency (Hz)


1436-16 2024/12/02 0.77UT FUJI -KISO



T20241202100037




BLK:12,SNR1: 0.92395 ,SNR2: 2.5727





1453-10 2024/12/02 1.04UT TOYOKAWA-FUJI


F20241202100039




BLK:12,SNR1: 0.33438 ,SNR2: 2.2655



T20241202100037




BLK:10,SNR1: 1.4998 ,SNR2: 6.6077





1453-10 2024/12/02 1.04UT TOYOKAWA-KISO


K20241202100035




BLK:10,SNR1: 2.7754 ,SNR2: 11.101



F20241202100039




BLK: 9,SNR1: 0.35857 ,SNR2: 2.4853




Frequency (Hz)

K20241202100035




BLK: 9,SNR1: 6.9511 ,SNR2: 13.089





Frequency (Hz)

1453-10 2024/12/02 1.04UT FUJI -KISO






T20241202101530





BLK: 1, SNR1: 6.9720 , SNR2: 15.329




1508-05 2024/12/02 1.29UT TOYOKAWA-FUJI


F20241202101532





BLK: 1, SNR1: 8.8795 , SNR2: 18.751




Frequency (Hz)



T20241202101530





BLK: 1, SNR1: 6.6007 , SNR2: 15.166




1508-05 2024/12/02 1.29UT TOYOKAWA-KISO


K20241202101527





BLK: 1, SNR1: 10.812 , SNR2: 16.899




Frequency (Hz)



F20241202101532





BLK: 4,SNR1: 10.668 ,SNR2: 17.445





1508-05 2024/12/02 1.29UT FUJI -KISO



K20241202101527




BLK: 4,SNR1: 15.194 ,SNR2: 18.604





T20241202102429




No. Good Data




F20241202102431





No. Good Data




3C318 2024/12/02 1.44UT TOYOKAWA-FUJI





T20241202102429




BLK: 4, SNR1: 0.43025E-01, SNR2: 0.69210




K20241202102426




BLK: 4, SNR1: 2.7768, SNR2: 9.8956





3C318 2024/12/02 1.44UT TOYOKAWA-KISO







BLK: 1,SNR1: -0.21703E-01,SNR2: 0.56533





BLK: 1,SNR1: 9.3230 ,SNR2: 18.103




3C318 2024/12/02 1.44UT FUJI -KISO



T20241202103017




BLK: 3,SNR1: 1.6818 ,SNR2: 11.827





1523+03 2024/12/02 1.53UT TOYOKAWA-FUJI



F20241202103019




BLK: 3,SNR1: 34.490 ,SNR2: 44.966



T20241202103017




BLK: 5, SNR1: 8.4324 , SNR2: 20.012





1523+03 2024/12/02 1.53UT TOYOKAWA-KISO

K20241202103014




BLK: 5, SNR1: 10.704 , SNR2: 18.154






F20241202103019




BLK: 1,SNR1: 2.6839 ,SNR2: 13.888





1523+03 2024/12/02 1.53UT FUJI -KISO



K20241202103014




BLK: 1,SNR1: 8.3983 ,SNR2: 20.576



T20241202104156




BLK: 1, SNR1: 6.1053 , SNR2: 15.993




1535+139 2024/12/02 1.73UT TOYOKAWA-FUJI


F20241202104158





BLK: 1, SNR1: 2.6347 , SNR2: 11.228




Frequency (Hz)





T20241202104156




BLK: 1,SNR1: 0.15901E-01,SNR2: 1.0178




K20241202104153




BLK: 1,SNR1: 0.32632 ,SNR2: 2.3372




1535+139 2024/12/02 1.73UT TOYOKAWA-KISO



F20241202104158





BLK: 2,SNR1: 15.001 ,SNR2: 26.481









1535+139 2024/12/02 1.73UT FUJI -KISO

K20241202104153




BLK: 2,SNR1: 2.4445 ,SNR2: 11.098








1548+05 2024/12/02 1.95UT TOYOKAWA-FUJI



T20241202105502




BLK: 3, SNR1: 1.5767 , SNR2: 4.4417





1548+05 2024/12/02 1.95UT TOYOKAWA-KISO


K20241202105459




BLK: 3, SNR1: 3.6758 , SNR2: 6.9598




F20241202105504




BLK: 2,SNR1: 3.1110 ,SNR2: 7.8411




K20241202105459





BLK: 2,SNR1: 3.7295 ,SNR2: 10.449




1548+05 2024/12/02 1.95UT FUJI -KISO



T20241202111323





BLK:22,SNR1: 9.0147 ,SNR2: 16.816




Frequency (Hz)

1607+26 2024/12/02 2.25UT TOYOKAWA-FUJI


F20241202111325



BLK:22,SNR1: 2.9549 ,SNR2: 13.966





Frequency (Hz)






T20241202111323





BLK:21,SNR1: 7.6317 ,SNR2: 19.757




Frequency (Hz)

1607+26 2024/12/02 2.25UT TOYOKAWA-KISO


K20241202111320





BLK:21,SNR1: 9.0195 ,SNR2: 16.824




Frequency (Hz)



F20241202111325





BLK:24,SNR1: 2.9524 ,SNR2: 13.955




Frequency (Hz)

K20241202111320




BLK:24,SNR1: 8.8595 ,SNR2: 16.529





Frequency (Hz)


1607+26 2024/12/02 2.25UT FUJI -KISO



T20241202112827





BLK: 4,SNR1: 13.456 ,SNR2: 39.456





1621-11 2024/12/02 2.50UT TOYOKAWA-FUJI



F20241202112829




BLK: 4,SNR1: 10.809 ,SNR2: 23.853



T20241202112827





BLK: 3,SNR1: 60.005 ,SNR2: 128.52




Frequency (Hz)

K20241202112824




BLK: 3,SNR1: 0.55464 ,SNR2: 2.9074





Frequency (Hz)


1621-11 2024/12/02 2.50UT TOYOKAWA-KISO



F20241202112829





BLK: 4, SNR1: 0.47951 , SNR2: 4.7779





1621-11 2024/12/02 2.50UT FUJI -KISO


K20241202112824




BLK: 4, SNR1: 6.2328 , SNR2: 14.312




T20241202114501




BLK:23,SNR1: 78.892 ,SNR2: 102.65




F20241202114503




BLK:23,SNR1: 91.140 ,SNR2: 94.388




1638-025 2024/12/02 2.78UT TOYOKAWA-FUJI




T20241202114501




BLK:16,SNR1: 79.466 ,SNR2: 103.39




K20241202114458





BLK:16,SNR1: 3.0861 ,SNR2: 12.932




1638-025 2024/12/02 2.78UT TOYOKAWA-KISO



F20241202114503





BLK:20,SNR1: 82.396 ,SNR2: 83.214




Frequency (Hz)

K20241202114458




BLK:20,SNR1: 5.8178 ,SNR2: 18.047




Frequency (Hz)

1638-025 2024/12/02 2.78UT FUJI -KISO







T20241202115155




BLK:12,SNR1: 2.0375 ,SNR2: 9.2804




F20241202115157





BLK:12,SNR1: 0.26098 ,SNR2: 2.0721




1644-106 2024/12/02 2.89UT TOYOKAWA-FUJI





T20241202115155




BLK:21,SNR1: 2.0899 ,SNR2: 5.2292




K20241202115152





BLK:21,SNR1: 1.3426 ,SNR2: 5.5401




1644-106 2024/12/02 2.89UT TOYOKAWA-KISO





F20241202115157




BLK: 3,SNR1: 1.0507 ,SNR2: 3.1586




K20241202115152





BLK: 3,SNR1: 0.20976 ,SNR2: 0.74441




1644-106 2024/12/02 2.89UT FUJI -KISO





T20241202115716




BLK: 6,SNR1: 11.719 ,SNR2: 24.076




F20241202115718





BLK: 6,SNR1: 5.1032 ,SNR2: 13.745




1650+004 2024/12/02 2.98UT TOYOKAWA-FUJI





T20241202115716




BLK:11,SNR1: 10.544 ,SNR2: 20.622




K20241202115713




BLK:11,SNR1: 5.9980 ,SNR2: 13.119




1650+004 2024/12/02 2.98UT TOYOKAWA-KISO



F20241202115718





BLK: 4,SNR1: 6.3722 ,SNR2: 13.669





1650+004 2024/12/02 2.98UT FUJI -KISO


K20241202115713




BLK: 4,SNR1: 6.3021 ,SNR2: 13.638




T20241202120248




BLK: 4,SNR1: 0.46333 ,SNR2: 1.2806




F20241202120250




BLK: 4,SNR1: 1.3948 ,SNR2: 10.472




1656+053 2024/12/02 3.07UT TOYOKAWA-FUJI




T20241202120248




BLK: 5,SNR1: 0.36496 ,SNR2: 1.5595




K20241202120245



BLK: 5,SNR1: 4.0119 ,SNR2: 12.603




1656+053 2024/12/02 3.07UT TOYOKAWA-KISO








F20241202120250




BLK: 1,SNR1:-0.10598 ,SNR2: 1.1946




K20241202120245




BLK: 1,SNR1: 0.81968 ,SNR2: 4.7091




1656+053 2024/12/02 3.07UT FUJI -KISO




T20241202121918




BLK: 7,SNR1: 7.8696 ,SNR2: 16.617




F20241202121920




BLK: 7,SNR1: 4.7803 ,SNR2: 10.538




1712-033 2024/12/02 3.35UT TOYOKAWA-FUJI



T20241202121918




BLK: 6,SNR1: 12.394 ,SNR2: 17.901





1712-033 2024/12/02 3.35UT TOYOKAWA-KISO


K20241202121915




BLK: 6,SNR1: 4.8972 ,SNR2: 10.276




F20241202121920




BLK: 2,SNR1:-0.36065E-01,SNR2: 3.6897




K20241202121915





BLK: 2,SNR1: 2.3143 ,SNR2: 5.4767




1712-033 2024/12/02 3.35UT FUJI -KISO




T20241202123720




BLK: 8,SNR1: 0.97311 ,SNR2: 3.3024




F20241202123722





BLK: 8,SNR1: 0.34205E-01,SNR2: 1.0317




1730-13 2024/12/02 3.65UT TOYOKAWA-FUJI




T20241202123720




BLK:17,SNR1: 0.89650 ,SNR2: 5.9411




K20241202123717




BLK:17,SNR1: 28.496 ,SNR2: 52.802




1730-13 2024/12/02 3.65UT TOYOKAWA-KISO




F20241202123722




BLK: 1,SNR1: 0.34469 ,SNR2: 2.4002




K20241202123717





BLK: 1,SNR1: 48.860 ,SNR2: 88.516




1730-13 2024/12/02 3.65UT FUJI -KISO





T20241202125445




BLK: 5,SNR1: 5.3835 ,SNR2: 27.888




F20241202125447



BLK: 5,SNR1: 3.1225 ,SNR2: 12.869





1748+031 2024/12/02 3.94UT TOYOKAWA-FUJI







T20241202125445




BLK:11,SNR1: 9.3316 ,SNR2: 38.698




K20241202125443





BLK:11,SNR1: 9.1307 ,SNR2: 19.326




1748+031 2024/12/02 3.94UT TOYOKAWA-KISO




F20241202125447




BLK: 6,SNR1: 8.2607 ,SNR2: 13.401




K20241202125443





BLK: 6,SNR1: 11.028 ,SNR2: 27.660




1748+031 2024/12/02 3.94UT FUJI -KISO




T20241202130538




BLK:10,SNR1: 0.29589 ,SNR2: 2.2446




F20241202130540





BLK:10,SNR1: 2.4035 ,SNR2: 9.8437




1759+13 2024/12/02 4.12UT TOYOKAWA-FUJI




T20241202130538




BLK: 7,SNR1: 0.22648 ,SNR2: 1.9289




K20241202130536




BLK: 7,SNR1: 2.9058 ,SNR2: 5.5184




1759+13 2024/12/02 4.12UT TOYOKAWA-KISO




F20241202130540




BLK: 3,SNR1: 1.2879 ,SNR2: 4.2414




K20241202130536





BLK: 3,SNR1: 1.1498 ,SNR2: 4.8453




1759+13 2024/12/02 4.12UT FUJI -KISO





T20241202132638




BLK: 4,SNR1: 0.39723 ,SNR2: 0.91084




F20241202132640





BLK: 4,SNR1: 0.57944 ,SNR2: 2.2027




1819-096 2024/12/02 4.47UT TOYOKAWA-FUJI




T20241202132638




BLK: 6,SNR1: 0.67864E-01,SNR2: 0.32601




K20241202132636





BLK: 6,SNR1: 0.50069 ,SNR2: 6.2434




1819-096 2024/12/02 4.47UT TOYOKAWA-KISO





F20241202132640




BLK: 4,SNR1:-0.19447 ,SNR2: 0.72148




K20241202132636



BLK: 4,SNR1: 0.28960 ,SNR2: 1.1014






1819-096 2024/12/02 4.47UT FUJI -KISO









T20241202133459







FUJI




1829+29 2024/12/02 4.61UT TOYOKAWA-FUJI







1829+29 2024/12/02 4.61UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241202133457




No.Good Data





Frequency (Hz)


1829+29 2024/12/02 4.61UT FUJI -KISO



T20241202134122





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1835+134 2024/12/02 4.72UT TOYOKAWA-FUJI








1835+134 2024/12/02 4.72UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241202134120




No.Good Data






Frequency (Hz)




1835+134 2024/12/02 4.72UT FUJI -KISO




T20241202140418





FUJI




1858+171 2024/12/02 5.10UT TOYOKAWA-FUJI





T20241202140418




No.Good Data




K20241202140416



No.Good Data





1858+171 2024/12/02 5.10UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241202140416




No.Good Data






Frequency (Hz)




1858+171 2024/12/02 5.10UT FUJI -KISO




T20241202141503




FUJI




1908-20 2024/12/02 5.28UT TOYOKAWA-FUJI





T20241202141503




BLK: 7,SNR1: 0.25995 ,SNR2: 3.0883




K20241202141501





BLK: 7,SNR1: 112.72 ,SNR2: 131.49




1908-20 2024/12/02 5.28UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241202141501




No.Good Data





Frequency (Hz)


1908-20 2024/12/02 5.28UT FUJI -KISO



T20241202142153





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1915-121 2024/12/02 5.39UT TOYOKAWA-FUJI








1915-121 2024/12/02 5.39UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241202142151




No.Good Data






Frequency (Hz)




1915-121 2024/12/02 5.39UT FUJI -KISO




T20241202143535



FUJI





1928-142 2024/12/02 5.62UT TOYOKAWA-FUJI








T20241202143535




BLK: 7,SNR1: 2.4066 ,SNR2: 9.7190




K20241202143533





BLK: 7,SNR1: 2.5327 ,SNR2: 6.1985




1928-142 2024/12/02 5.62UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241202143533




No.Good Data






Frequency (Hz)




1928-142 2024/12/02 5.62UT FUJI -KISO




T20241202144514





FUJI




1938-15 2024/12/02 5.78UT TOYOKAWA-FUJI





T20241202144514




BLK:20,SNR1: 0.51095 ,SNR2: 4.1568




K20241202144512





BLK:20,SNR1: 0.42884 ,SNR2: 1.8812




1938-15 2024/12/02 5.78UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241202144512




No.Good Data





Frequency (Hz)


1938-15 2024/12/02 5.78UT FUJI -KISO



T20241202152010




BLK: 2,SNR1: 0.11765 ,SNR2: 0.71208




Frequency (Hz)

F20241202152012








BLK: 2,SNR1: 3.6107 ,SNR2: 7.1521




Frequency (Hz)

2014+358 2024/12/02 6.36UT TOYOKAWA-FUJI







2014+358 2024/12/02 6.36UT TOYOKAWA-KISO



F20241202152012





BLK: 2,SNR1: 1.1231 ,SNR2: 8.2963




Frequency (Hz)

K20241202152008




BLK: 2,SNR1: 2.1190 ,SNR2: 13.831





Frequency (Hz)

2014+358 2024/12/02 6.36UT FUJI -KISO







T20241202155047




BLK: 3,SNR1: 0.53433E-01,SNR2: 1.3088




F20241202155049





BLK: 3,SNR1: 0.44405E-02,SNR2: 1.3011




3C422 2024/12/02 6.87UT TOYOKAWA-FUJI





T20241202155047




BLK: 3,SNR1: 0.38449E-01,SNR2: 0.87923




K20241202155044





BLK: 3,SNR1: 2.0043 ,SNR2: 9.9492




3C422 2024/12/02 6.87UT TOYOKAWA-KISO



F20241202155049





BLK: 1,SNR1:-0.17925 ,SNR2: 0.42225




Frequency (Hz)

K20241202155044




BLK: 1,SNR1:-0.15063 ,SNR2: 1.9608




Frequency (Hz)


3C422 2024/12/02 6.87UT FUJI -KISO



T20241202161124




BLK: 3,SNR1: 12.796 ,SNR2: 27.941




Frequency (Hz)

F20241202161126




BLK: 3,SNR1: 60.455 ,SNR2: 60.479





Frequency (Hz)


2105-072 2024/12/02 7.22UT TOYOKAWA-FUJI



T20241202161124





BLK: 1,SNR1: 2.5717 ,SNR2: 10.759




Frequency (Hz)

K20241202161122




BLK: 1,SNR1: 9.5211 ,SNR2: 21.049




Frequency (Hz)


2105-072 2024/12/02 7.22UT TOYOKAWA-KISO



F20241202161126




BLK: 4,SNR1: 38.280 ,SNR2: 43.973




Frequency (Hz)

K20241202161122




BLK: 4,SNR1: 46.096 ,SNR2: 56.430





Frequency (Hz)


2105-072 2024/12/02 7.22UT FUJI -KISO



T20241202162713





No.Good Data




Frequency (Hz)

F20241202162715




No.Good Data





Frequency (Hz)


2121-014 2024/12/02 7.48UT TOYOKAWA-FUJI



T20241202162713





BLK: 1,SNR1: 0.29910 ,SNR2: 0.68314




Frequency (Hz)

K20241202162710




BLK: 1,SNR1: 0.78888E-01,SNR2: 1.6081




Frequency (Hz)

2121-014 2024/12/02 7.48UT TOYOKAWA-KISO








F20241202162715




BLK: 3,SNR1:-0.20259 ,SNR2: 0.64769




K20241202162710




BLK: 3,SNR1: 0.31129 ,SNR2: 1.7637




2121-014 2024/12/02 7.48UT FUJI -KISO



T20241202164128




BLK: 2,SNR1: 4.9019 ,SNR2: 20.130




Frequency (Hz)

F20241202164130




BLK: 2,SNR1: 12.384 ,SNR2: 21.727




Frequency (Hz)


2135-209 2024/12/02 7.72UT TOYOKAWA-FUJI




T20241202164128




BLK: 1,SNR1: 10.331 ,SNR2: 25.414




K20241202164126




BLK: 1,SNR1: 13.842 ,SNR2: 19.391




2135-209 2024/12/02 7.72UT TOYOKAWA-KISO



F20241202164130




BLK: 1,SNR1: 12.013 ,SNR2: 29.633




Frequency (Hz)

K20241202164126




BLK: 1,SNR1: 6.6632 ,SNR2: 16.800





Frequency (Hz)


2135-209 2024/12/02 7.72UT FUJI -KISO



T20241202170252




BLK: 1,SNR1: 7.6583 ,SNR2: 18.765




Frequency (Hz)

F20241202170254




BLK: 1,SNR1: 9.0222 ,SNR2: 22.230





Frequency (Hz)


2156-043 2024/12/02 8.08UT TOYOKAWA-FUJI





T20241202170252




No.Good Data




K20241202170250





No.Good Data




2156-043 2024/12/02 8.08UT TOYOKAWA-KISO





F20241202170254




No.Good Data




K20241202170250





No.Good Data




2156-043 2024/12/02 8.08UT FUJI -KISO



T20241202170940




BLK: 6,SNR1: 0.22254 ,SNR2: 3.1576




Frequency (Hz)

F20241202170942




BLK: 6,SNR1: 0.63603 ,SNR2: 2.0426





Frequency (Hz)

2203-18 2024/12/02 8.19UT TOYOKAWA-FUJI






T20241202170940




BLK: 4,SNR1: 0.31276 ,SNR2: 3.1177




Frequency (Hz)

K20241202170937




BLK: 4,SNR1: 0.29213 ,SNR2: 1.1364





Frequency (Hz)


2203-18 2024/12/02 8.19UT TOYOKAWA-KISO



F20241202170942





BLK: 3,SNR1: 1.0134 ,SNR2: 3.5898




Frequency (Hz)

K20241202170937



BLK: 3,SNR1: 2.8599 ,SNR2: 11.474



Frequency (Hz)

2203-18 2024/12/02 8.19UT FUJI -KISO

