








BLK:14,SNR1: 12.218 ,SNR2: 53.974









BLK:14,SNR1: 0.72140E-02,SNR2: 2.4971





3C147 2025/04/28 6.15UT TOYOKAWA-FUJI










T20250428151542




BLK: 8,SNR1:-0.11006E-01,SNR2: 1.7823




F20250428151543









BLK: 8,SNR1: 1.6116 ,SNR2: 11.540




0548+16 2025/04/28 6.29UT TOYOKAWA-FUJI









T20250428151952




BLK:14,SNR1: 21.291 ,SNR2: 53.392




F20250428151953






BLK:14,SNR1: 6.7197 ,SNR2: 22.953






0552+12 2025/04/28 6.36UT TOYOKAWA-FUJI














T20250428152419




BLK:12,SNR1: 6.2493 ,SNR2: 17.874




F20250428152420





BLK:12,SNR1: 8.7669 ,SNR2: 25.470






0556+191 2025/04/28 6.43UT TOYOKAWA-FUJI






0556+191 2025/04/28 6.43UT TOYOKAWA-KISO








0556+191 2025/04/28 6.43UT FUJI -KISO



T20250428152852





BLK:12,SNR1: 3.1720 ,SNR2: 9.5699








3C152 2025/04/28 6.51UT TOYOKAWA-FUJI



F20250428152853




BLK:12,SNR1: 1.6128 ,SNR2: 5.0591










3C152 2025/04/28 6.51UT FUJI -KISO



T20250428155112




BLK:14,SNR1: 29.681 ,SNR2: 38.650





3C161 2025/04/28 6.88UT TOYOKAWA-FUJI




F20250428155113











BLK:14,SNR1: 2.9545 ,SNR2: 10.290

























T20250428163022




BLK: 7,SNR1: 0.64858 ,SNR2: 2.4443




F20250428163023









BLK: 7,SNR1: 5.0270 ,SNR2: 14.318



0703+138 2025/04/28 7.53UT TOYOKAWA-FUJI














T20250428163945




BLK: 4, SNR1: 0.13939 , SNR2: 1.3954




F20250428163946









BLK: 4, SNR1: 2.2733 , SNR2: 4.2236




0713-024 2025/04/28 7.69UT TOYOKAWA-FUJI













BLK: 5, SNR1: 0.17050 , SNR2: 2.0679









BLK: 5, SNR1: 1.6768 , SNR2: 5.4765




0723+10 2025/04/28 7.86UT TOYOKAWA-FUJI










T20250428170011




BLK: 1,SNR1: 0.39792E-01,SNR2: 0.27971



F20250428170012



BLK: 1,SNR1: 0.92971 ,SNR2: 3.8235



0732+33 2025/04/28 8.03UT TOYOKAWA-FUJI

