






T20250815063729




BLK: 6,SNR1: 0.79860 ,SNR2: 7.1530




F20250815063729









BLK: 6,SNR1: 2.4457 ,SNR2: 6.7300




0418+236 2025/08/14 21.65UT TOYOKAWA-FUJI













BLK: 7,SNR1:-0.92725E-02,SNR2: 0.65660






BLK: 7,SNR1: 1.9938 ,SNR2: 4.1211






3C119 2025/08/14 21.84UT TOYOKAWA-FUJI













T20250815073704




BLK: 3,SNR1: 0.62717E-01,SNR2: 0.36710




F20250815073704









BLK: 3,SNR1: 8.2334 ,SNR2: 19.858





3C138 2025/08/14 22.65UT TOYOKAWA-FUJI










T20250815075037




BLK: 4, SNR1: 8.8586 , SNR2: 21.491




F20250815075037









BLK: 4, SNR1: 11.112 , SNR2: 24.253



0531+194 2025/08/14 22.87UT TOYOKAWA-FUJI












T20250815075858




BLK:15,SNR1: 1.6916 ,SNR2: 4.3025




F20250815075858









BLK:15,SNR1: 3.0689 ,SNR2: 8.2428





3C147 2025/08/14 23.01UT TOYOKAWA-FUJI










T20250815080708




BLK: 4,SNR1: -0.91916E-01,SNR2: 0.94337




F20250815080708









BLK: 4,SNR1: -0.12856 ,SNR2: 2.9158





0548+16 2025/08/14 23.15UT TOYOKAWA-FUJI










T20250815081119




BLK: 2,SNR1: 1.5706 ,SNR2: 5.1002




F20250815081119






BLK: 2,SNR1: 0.81914 ,SNR2: 3.5167







0552+12 2025/08/14 23.22UT TOYOKAWA-FUJI















BLK: 3,SNR1: 0.87659E-01,SNR2: 1.0189









BLK: 3,SNR1: 11.230 ,SNR2: 31.754





0556+191 2025/08/14 23.29UT TOYOKAWA-FUJI









T20250815082019




BLK: 4, SNR1: 0.34139 , SNR2: 1.2418




F20250815082019









BLK: 4, SNR1: 3.0340 , SNR2: 6.7433





3C152 2025/08/14 23.37UT TOYOKAWA-FUJI









T20250815084239




BLK: 3, SNR1: 3.4186 , SNR2: 8.2655




F20250815084239






BLK: 3, SNR1: 7.9244 , SNR2: 24.394






3C161 2025/08/14 23.74UT TOYOKAWA-FUJI













T20250815085400




BLK: 5, SNR1: 2.7086 , SNR2: 7.0553




F20250815085400





BLK: 5, SNR1: 9.6548 , SNR2: 20.796







0636-167 2025/08/14 23.93UT TOYOKAWA-FUJI







0636-167 2025/08/14 23.93UT TOYOKAWA-KISO







T20250815091012




BLK: 3, SNR1: 1.0089 , SNR2: 5.1686




F20250815091012









BLK: 3, SNR1: -0.28361 , SNR2: 0.0000



0652-130 2025/08/15 0.20UT TOYOKAWA-FUJI














T20250815092149




BLK: 8, SNR1: 0.18685 , SNR2: 0.57774




F20250815092149









BLK: 8, SNR1: 18.761 , SNR2: 20.814




0703+138 2025/08/15 0.39UT TOYOKAWA-FUJI










T20250815093111




BLK: 4, SNR1: 2.4541 , SNR2: 11.882




F20250815093111









BLK: 4, SNR1: 14.786 , SNR2: 26.368





0713-024 2025/08/15 0.55UT TOYOKAWA-FUJI










T20250815094123




BLK:23,SNR1: 12.938 ,SNR2: 31.826




F20250815094123






BLK:23,SNR1: 13.359 ,SNR2: 31.477






0723+10 2025/08/15 0.72UT TOYOKAWA-FUJI












T20250815095139




BLK: 2, SNR1: 0.32872 , SNR2: 1.5643




F20250815095139









BLK: 2, SNR1: 0.43610 , SNR2: 1.9282







0732+33 2025/08/15 0.89UT TOYOKAWA-FUJI


















0741-06 2025/08/15 1.02UT TOYOKAWA-FUJI









T20250815100924




BLK: 9, SNR1: 9.8033 , SNR2: 23.755




F20250815100924






BLK: 9, SNR1: 12.048 , SNR2: 29.359






0752-200 2025/08/15 1.18UT TOYOKAWA-FUJI













T20250815101659




BLK: 4,SNR1: 0.70595 ,SNR2: 2.0131




F20250815101659









BLK: 4,SNR1: 7.6253 ,SNR2: 17.217





3C190 2025/08/15 1.31UT TOYOKAWA-FUJI









T20250815102925




BLK: 2, SNR1: 5.5302 , SNR2: 13.264




F20250815102925









BLK: 2, SNR1: 6.1468 , SNR2: 15.538







3C196 2025/08/15 1.52UT TOYOKAWA-FUJI



















0821+394 2025/08/15 1.70UT TOYOKAWA-FUJI













BLK: 4,SNR1: 0.10942 ,SNR2: 0.69833









BLK: 4,SNR1: 1.8178 ,SNR2: 6.2932




0834-19 2025/08/15 1.90UT TOYOKAWA-FUJI













BLK: 6,SNR1: 3.6832 ,SNR2: 18.986






BLK: 6,SNR1: 21.693 ,SNR2: 38.530






0839-071 2025/08/15 1.98UT TOYOKAWA-FUJI














T20250815110820




BLK:18,SNR1: 3.3533 ,SNR2: 8.2122




F20250815110820









BLK:18,SNR1: 9.5473 ,SNR2: 25.458











3C208 2025/08/15 2.17UT TOYOKAWA-FUJI


























0919-142 2025/08/15 2.65UT TOYOKAWA-FUJI










0919-142 2025/08/15 2.65UT TOYOKAWA-KISO







0919-142 2025/08/15 2.65UT FUJI -KISO




T20250815114352




BLK:22,SNR1: 1.8274 ,SNR2: 5.8790




F20250815114352





BLK:22,SNR1: 1.8668 ,SNR2: 6.0383






0926+117 2025/08/15 2.76UT TOYOKAWA-FUJI






0926+117 2025/08/15 2.76UT TOYOKAWA-KISO







0926+117 2025/08/15 2.76UT FUJI -KISO




T20250815115136




BLK:14,SNR1: 1.1941 ,SNR2: 6.1652




F20250815115136









BLK:14,SNR1: 1.3112 ,SNR2: 6.7946



3C222 2025/08/15 2.89UT TOYOKAWA-FUJI













T20250815115836




BLK: 8,SNR1: 2.1136 ,SNR2: 7.8445




F20250815115836









BLK: 8,SNR1: 4.5936 ,SNR2: 20.260











0941-08 2025/08/15 3.00UT TOYOKAWA-FUJI





















T20250815122106




BLK:14,SNR1: 0.28836 ,SNR2: 4.0122




F20250815122106






BLK:14,SNR1: 7.4618 ,SNR2: 18.772







3C236 2025/08/15 3.38UT TOYOKAWA-FUJI















BLK: 5,SNR1: 0.17117 ,SNR2: 0.72267









BLK: 5,SNR1: 1.8397 ,SNR2: 4.6071




1011+110 2025/08/15 3.52UT TOYOKAWA-FUJI



















BLK:15,SNR1: 1.0538 ,SNR2: 4.0213





BLK:15,SNR1: 0.75549E-01,SNR2: 5.9360









T20250815124825




BLK: 4,SNR1: 0.12753 ,SNR2: 0.48940




F20250815124825






BLK: 4,SNR1: 0.33214 ,SNR2: 4.5665






1031-11 2025/08/15 3.84UT TOYOKAWA-FUJI













T20250815125259




BLK: 8,SNR1: 0.22190 ,SNR2: 2.5220




F20250815125259









BLK: 8,SNR1:-0.82296E-02,SNR2: 2.0185





1035-058 2025/08/15 3.91UT TOYOKAWA-FUJI









T20250815130211




BLK: 2,SNR1: 0.25755 ,SNR2: 1.1520




F20250815130211








BLK: 2,SNR1: 1.5190 ,SNR2: 4.6867




1044-008 2025/08/15 4.06UT TOYOKAWA-FUJI









1044-008 2025/08/15 4.06UT FUJI -KISO







T20250815131310




BLK: 4,SNR1: 0.16930 ,SNR2: 0.47843




F20250815131310









BLK: 4,SNR1: 0.69420 ,SNR2: 2.1791





1055+20 2025/08/15 4.25UT TOYOKAWA-FUJI










T20250815132433




BLK: 8,SNR1: 0.34174 ,SNR2: 1.4971




F20250815132433






BLK: 8,SNR1: 0.18731 ,SNR2: 0.98447




1107+109 2025/08/15 4.44UT TOYOKAWA-FUJI










T20250815133411




BLK: 9,SNR1: 0.37055 ,SNR2: 3.2209




F20250815133411






BLK: 9,SNR1: 9.5756 ,SNR2: 17.127






3C255 2025/08/15 4.60UT TOYOKAWA-FUJI












T20250815134448




BLK: 5,SNR1: 0.23309 ,SNR2: 0.59034




F20250815134448









BLK: 5,SNR1:-0.14045 ,SNR2: 1.0205




1127-14 2025/08/15 4.77UT TOYOKAWA-FUJI













BLK: 7,SNR1: 0.21576 ,SNR2: 0.74040









BLK: 7,SNR1:-0.27759E-01,SNR2: 1.0976





3C263.1 2025/08/15 5.00UT TOYOKAWA-FUJI










T20250815140436




BLK: 5,SNR1: 0.31619 ,SNR2: 1.7426




F20250815140436






BLK: 5,SNR1: 6.6722 ,SNR2: 16.421







3C267 2025/08/15 5.10UT TOYOKAWA-FUJI















BLK: 5,SNR1: 0.12099 ,SNR2: 0.85810









BLK: 5,SNR1: 0.74994E-01,SNR2: 3.2649




1213-17 2025/08/15 5.53UT TOYOKAWA-FUJI













BLK:13,SNR1: 1.4890 ,SNR2: 3.9964




BLK:13,SNR1:-0.75824E-01,SNR2: 1.2940





3C273 2025/08/15 5.76UT TOYOKAWA-FUJI







BLK:21,SNR1: 1.1785 ,SNR2: 7.0629




BLK:21,SNR1: 0.59967E-01,SNR2: 0.61323





3C273 2025/08/15 5.76UT TOYOKAWA-KISO







BLK:11,SNR1: 0.21687 ,SNR2: 1.5757




BLK:11,SNR1: 0.66824E-01,SNR2: 1.4371





3C273 2025/08/15 5.76UT FUJI -KISO









BLK: 6,SNR1: 1.4093 ,SNR2: 4.5832









BLK: 6,SNR1: 0.31597 ,SNR2: 1.4272





3C275 2025/08/15 5.98UT TOYOKAWA-FUJI

















1245-19 2025/08/15 6.08UT TOYOKAWA-FUJI













BLK: 1,SNR1: 0.29325 ,SNR2: 2.5737






BLK: 1,SNR1: 1.6616 ,SNR2: 10.590







3C279 2025/08/15 6.21UT TOYOKAWA-FUJI















BLK: 6,SNR1: 0.32457 ,SNR2: 1.1999









BLK: 6,SNR1: 1.1641 ,SNR2: 6.4421





3C283 2025/08/15 6.46UT TOYOKAWA-FUJI









T20250815154034




BLK: 9,SNR1: 0.26565 ,SNR2: 2.0573




F20250815154034









BLK: 9,SNR1: 0.16904 ,SNR2: 3.0702




1323+32 2025/08/15 6.70UT TOYOKAWA-FUJI
















BLK: 6,SNR1: 9.5780 ,SNR2: 23.589







BLK: 6,SNR1: 10.037 ,SNR2: 24.379















BLK:16,SNR1: 0.33863 ,SNR2: 1.6587









BLK:16,SNR1: 0.64397 ,SNR2: 1.7866





1345+12 2025/08/15 7.06UT TOYOKAWA-FUJI
















1355+01 2025/08/15 7.23UT TOYOKAWA-FUJI






1355+01 2025/08/15 7.23UT TOYOKAWA-KISO








T20250815163323




BLK:22,SNR1: 1.7961 ,SNR2: 6.2438




Frequency (Hz)

F20250815163323







BLK:22,SNR1: 1.6151 ,SNR2: 4.9986







Frequency (Hz)

3C298 2025/08/15 7.58UT TOYOKAWA-FUJI












BLK: 6,SNR1: 2.2450 ,SNR2: 5.4639



BLK: 6,SNR1: 1.0481 ,SNR2: 3.3756



1428-03 2025/08/15 7.78UT TOYOKAWA-FUJI

