








BLK: 3,SNR1: 9.5839 ,SNR2: 23.599









BLK: 3,SNR1: 8.5607 ,SNR2: 20.805





0548+16 2025/09/08 21.51UT TOYOKAWA-FUJI










T20250909063302




BLK: 7, SNR1: 46.482 , SNR2: 589.90




F20250909063304








BLK: 7, SNR1: 0.26202 , SNR2: 2.0712




0552+12 2025/09/08 21.58UT TOYOKAWA-FUJI










0552+12 2025/09/08 21.58UT FUJI -KISO





T20250909063729




BLK: 1, SNR1: 14.878 , SNR2: 22.426




F20250909063731









BLK: 1, SNR1: 4.0951 , SNR2: 14.585




0556+191 2025/09/08 21.65UT TOYOKAWA-FUJI













BLK: 8,SNR1: 2.3610 ,SNR2: 7.8134









BLK: 8,SNR1: 7.2772 ,SNR2: 17.045





3C152 2025/09/08 21.73UT TOYOKAWA-FUJI








T20250909070422





BLK: 2, SNR1: 6.3249 , SNR2: 14.624








3C161 2025/09/08 22.10UT TOYOKAWA-FUJI




F20250909070424





BLK: 2, SNR1: 2.3882 , SNR2: 10.546










T20250909073155




BLK:10,SNR1: 8.3241 ,SNR2: 21.539




F20250909073157









BLK:10,SNR1: 2.0127 ,SNR2: 6.6684











0652-130 2025/09/08 22.56UT TOYOKAWA-FUJI




















T20250909075254




BLK: 4, SNR1: 5.3096 , SNR2: 14.000




F20250909075256





BLK: 4, SNR1: 4.9453 , SNR2: 12.623







0713-024 2025/09/08 22.91UT TOYOKAWA-FUJI








0713-024 2025/09/08 22.91UT TOYOKAWA-KISO









BLK:11,SNR1: 8.3789 ,SNR2: 22.020









BLK:11,SNR1: 12.997 ,SNR2: 29.255







0723+10 2025/09/08 23.08UT TOYOKAWA-FUJI

















0732+33 2025/09/08 23.25UT TOYOKAWA-FUJI










T20250909082122




BLK: 6,SNR1: 3.8217 ,SNR2: 9.1094




F20250909082124









BLK: 6,SNR1: 6.7483 ,SNR2: 16.474




0741-06 2025/09/08 23.38UT TOYOKAWA-FUJI










T20250909083106




BLK: 5,SNR1: 0.35327 ,SNR2: 1.0588




F20250909083108









BLK: 5,SNR1:-0.67954E-01,SNR2: 1.5548




0752-200 2025/09/08 23.55UT TOYOKAWA-FUJI









T20250909083842




BLK: 5,SNR1: 0.22731E-01,SNR2: 0.82932




F20250909083844









BLK: 5,SNR1: 6.1852 ,SNR2: 17.777





3C190 2025/09/08 23.67UT TOYOKAWA-FUJI










T20250909085107




BLK:18,SNR1: 2.6348 ,SNR2: 8.1073




F20250909085109









BLK:18,SNR1: 5.9818 ,SNR2: 15.399





3C196 2025/09/08 23.88UT TOYOKAWA-FUJI








T20250909090217




BLK: 5, SNR1: 0.13467 , SNR2: 0.35699








0821+394 2025/09/09 0.07UT TOYOKAWA-FUJI




F20250909090219





BLK: 5, SNR1: 0.80541 , SNR2: 7.5550









T20250909091355




BLK: 6, SNR1: 1.0798 , SNR2: 7.7950




F20250909091357









BLK: 6, SNR1: 0.29950 , SNR2: 1.7565




0834-19 2025/09/09 0.26UT TOYOKAWA-FUJI









T20250909091901




BLK: 9,SNR1: 7.2861 ,SNR2: 19.494




F20250909091903









BLK: 9,SNR1: 1.2524 ,SNR2: 4.3299







0839-071 2025/09/09 0.35UT TOYOKAWA-FUJI


















3C208 2025/09/09 0.53UT TOYOKAWA-FUJI










T20250909094644




BLK: 9,SNR1: 0.10153 ,SNR2: 1.4315




F20250909094646









BLK: 9,SNR1: 1.2134 ,SNR2: 3.8642





3C216 2025/09/09 0.81UT TOYOKAWA-FUJI








T20250909095855





BLK: 7,SNR1: 0.15871 ,SNR2: 2.0001




Frequency (Hz)

F20250909095857






BLK: 7,SNR1:-0.11787 ,SNR2: 1.5819




Frequency (Hz)




0919-142 2025/09/09 1.01UT TOYOKAWA-FUJI








0919-142 2025/09/09 1.01UT TOYOKAWA-KISO









BLK: 2, SNR1: 0.16408 , SNR2: 1.2217





BLK: 2, SNR1: 1.8814 , SNR2: 4.6742







0926+117 2025/09/09 1.12UT TOYOKAWA-FUJI






0926+117 2025/09/09 1.12UT TOYOKAWA-KISO







T20250909101319




BLK:15,SNR1: 0.43555 ,SNR2: 1.6846




F20250909101321









BLK:15,SNR1: 7.6019 ,SNR2: 19.629




3C222 2025/09/09 1.25UT TOYOKAWA-FUJI









T20250909102019




BLK: 7,SNR1: 0.22637 ,SNR2: 1.4852




F20250909102021





BLK: 7,SNR1: 0.59553E-01,SNR2: 2.4373







0941-08 2025/09/09 1.37UT TOYOKAWA-FUJI
















0941-08 2025/09/09 1.37UT TOYOKAWA-KISO














T20250909104248




BLK: 8,SNR1:-0.13044 ,SNR2: 0.31489




F20250909104250









BLK: 8,SNR1: 0.59123E-01,SNR2: 2.2056





3C236 2025/09/09 1.74UT TOYOKAWA-FUJI










T20250909105057




BLK:10,SNR1: 0.13135 ,SNR2: 0.86999




F20250909105059









BLK:10,SNR1: 0.71776 ,SNR2: 1.7663




1011+110 2025/09/09 1.88UT TOYOKAWA-FUJI



















BLK:14,SNR1: 0.91010 ,SNR2: 2.7757




BLK:14,SNR1: 0.39296 ,SNR2: 4.8586









T20250909111008




BLK: 4,SNR1: 0.38030 ,SNR2: 1.7636




F20250909111010









BLK: 4,SNR1:-0.20168 ,SNR2: 0.16014











1031-11 2025/09/09 2.20UT TOYOKAWA-FUJI




























1044-008 2025/09/09 2.43UT TOYOKAWA-FUJI



















BLK:14,SNR1: 0.66341 ,SNR2: 3.6812




BLK:14,SNR1: 1.7144 ,SNR2: 8.7496













BLK:19,SNR1: 0.73822 ,SNR2: 2.2622









BLK:19,SNR1: 10.413 ,SNR2: 19.214




1107+109 2025/09/09 2.80UT TOYOKAWA-FUJI













BLK:22,SNR1: 3.3978 ,SNR2: 10.318









BLK:22,SNR1: 3.0681 ,SNR2: 9.4215




3C255 2025/09/09 2.96UT TOYOKAWA-FUJI













BLK: 4,SNR1: 6.9502 ,SNR2: 17.527









BLK: 4,SNR1: 12.301 ,SNR2: 30.075





1127-14 2025/09/09 3.14UT TOYOKAWA-FUJI










T20250909121951




BLK:17,SNR1: 0.37765 ,SNR2: 3.5312




F20250909121953









BLK:17,SNR1: 8.4155 ,SNR2: 27.004





3C263.1 2025/09/09 3.36UT TOYOKAWA-FUJI
















3C267 2025/09/09 3.47UT TOYOKAWA-FUJI







3C267 2025/09/09 3.47UT TOYOKAWA-KISO







T20250909125206




BLK: 6,SNR1: 0.95763 ,SNR2: 4.2117




F20250909125208









BLK: 6,SNR1: 0.19325 ,SNR2: 1.3717




1213-17 2025/09/09 3.90UT TOYOKAWA-FUJI













BLK:20,SNR1: 10.089 ,SNR2: 24.664









BLK:20,SNR1: 0.24614 ,SNR2: 3.0115





3C273 2025/09/09 4.12UT TOYOKAWA-FUJI









T20250909131834




BLK:14,SNR1: 0.12398 ,SNR2: 1.2463




F20250909131836









BLK:14,SNR1: 2.6423 ,SNR2: 10.552





3C275 2025/09/09 4.34UT TOYOKAWA-FUJI










T20250909132439




BLK:13,SNR1: 0.18480 ,SNR2: 1.8014




F20250909132441





BLK:13,SNR1:-0.76651E-01,SNR2: 0.98296







1245-19 2025/09/09 4.44UT TOYOKAWA-FUJI








1245-19 2025/09/09 4.44UT TOYOKAWA-KISO









BLK: 8,SNR1: 0.41588 ,SNR2: 1.3546









BLK: 8,SNR1: -0.26986 ,SNR2: 0.0000




3C279 2025/09/09 4.57UT TOYOKAWA-FUJI









T20250909134752




BLK: 1,SNR1: 4.9996 ,SNR2: 13.410




F20250909134754









BLK: 1,SNR1: 10.070 ,SNR2: 24.612





3C283 2025/09/09 4.83UT TOYOKAWA-FUJI










T20250909140216




BLK: 8,SNR1: 0.43633 ,SNR2: 2.4459




F20250909140218









BLK: 8,SNR1:-0.24720E-01,SNR2: 1.3665





1323+32 2025/09/09 5.07UT TOYOKAWA-FUJI









T20250909140707




BLK:27,SNR1: 1.6666 ,SNR2: 6.4240




F20250909140709









BLK:27,SNR1: 0.44999 ,SNR2: 3.6726




3C286 2025/09/09 5.15UT TOYOKAWA-FUJI













BLK: 9,SNR1: 3.3677 ,SNR2: 8.6652





BLK: 9,SNR1: 5.7526 ,SNR2: 15.695







1345+12 2025/09/09 5.42UT TOYOKAWA-FUJI







1345+12 2025/09/09 5.42UT TOYOKAWA-KISO








T20250909143354




BLK: 6,SNR1: 0.74109 ,SNR2: 3.2614




F20250909143356









BLK: 6,SNR1: 8.3651 ,SNR2: 19.722




1355+01 2025/09/09 5.59UT TOYOKAWA-FUJI













BLK:10,SNR1: 2.2581 ,SNR2: 6.9277









BLK:10,SNR1: 0.14394 ,SNR2: 2.7266





3C298 2025/09/09 5.95UT TOYOKAWA-FUJI









T20250909150649




BLK: 7,SNR1: 0.20720 ,SNR2: 1.9089




F20250909150651









BLK: 7,SNR1: 4.8207 ,SNR2: 13.284




1428-03 2025/09/09 6.14UT TOYOKAWA-FUJI













BLK: 4,SNR1: 0.26043 ,SNR2: 1.2348









BLK: 4,SNR1:-0.17249 ,SNR2: 2.3770




1436-16 2025/09/09 6.29UT TOYOKAWA-FUJI













BLK: 9,SNR1: 15.095 ,SNR2: 35.756





BLK: 9,SNR1: 8.8458 ,SNR2: 22.812







1453-10 2025/09/09 6.56UT TOYOKAWA-FUJI







1453-10 2025/09/09 6.56UT TOYOKAWA-KISO







T20250909154646




BLK: 2,SNR1:-0.91763E-02,SNR2: 1.4805




F20250909154648









BLK: 2,SNR1:-0.14181,SNR2: 3.0889




1508-05 2025/09/09 6.81UT TOYOKAWA-FUJI



















BLK: 3,SNR1: 8.6449 ,SNR2: 21.601





BLK: 3,SNR1: 0.36834 ,SNR2: 3.8809









T20250909160132




BLK: 3,SNR1: 0.25987 ,SNR2: 0.88409




F20250909160134









BLK: 3,SNR1: 0.25560 ,SNR2: 3.6745







1523+03 2025/09/09 7.05UT TOYOKAWA-FUJI


















1535+139 2025/09/09 7.25UT TOYOKAWA-FUJI










T20250909162336




BLK: 6,SNR1: 3.0198 ,SNR2: 8.8988




F20250909162338









BLK: 6,SNR1: 0.88287E-01,SNR2: 2.7088





1545-12 2025/09/09 7.42UT TOYOKAWA-FUJI








T20250909164439





BLK:11,SNR1: 0.59395 ,SNR2: 3.4136




Frequency (Hz)

F20250909164441



BLK:11,SNR1: 1.7737 ,SNR2: 7.5085



Frequency (Hz)

1607+26 2025/09/09 7.77UT TOYOKAWA-FUJI

