





































T20250923065751




BLK: 3, SNR1: 0.68760 , SNR2: 1.2845




F20250923065753









BLK: 3, SNR1: -0.10793 , SNR2: 1.9049




0713-024 2025/09/22 21.99UT TOYOKAWA-FUJI













BLK: 3,SNR1: 0.85127E-01,SNR2: 1.9342









BLK: 3,SNR1: 0.66101 ,SNR2: 2.0533





0723+10 2025/09/22 22.16UT TOYOKAWA-FUJI










T20250923071818




No.Good Data




F20250923071820









No.Good Data





0732+33 2025/09/22 22.33UT TOYOKAWA-FUJI









T20250923072619




BLK: 5, SNR1: 19.635 ,SNR2: 30.290




F20250923072621





BLK: 5, SNR1: 13.415 ,SNR2: 22.972







0741-06 2025/09/22 22.47UT TOYOKAWA-FUJI







0741-06 2025/09/22 22.47UT TOYOKAWA-KISO







T20250923073604




BLK: 9, SNR1: 8.6162 , SNR2: 19.047




F20250923073606









BLK: 9, SNR1: 15.601 , SNR2: 20.375




0752-200 2025/09/22 22.63UT TOYOKAWA-FUJI










T20250923074339




BLK: 9,SNR1: 3.0660 ,SNR2: 9.7240




F20250923074341









BLK: 9,SNR1: 21.849 ,SNR2: 23.113





3C190 2025/09/22 22.76UT TOYOKAWA-FUJI








T20250923075605





BLK: 3,SNR1: 33.296 ,SNR2: 58.439








3C196 2025/09/22 22.96UT TOYOKAWA-FUJI




F20250923075607





BLK: 3,SNR1: 2.5206 ,SNR2: 4.1755










T20250923080714




BLK: 8, SNR1: 6.0851 , SNR2: 10.319




F20250923080716









BLK: 8, SNR1: 7.4540 , SNR2: 12.338




0821+394 2025/09/22 23.15UT TOYOKAWA-FUJI













BLK:11,SNR1: 6.2614 ,SNR2: 8.1575









BLK:11,SNR1: 1.4865 ,SNR2: 2.8212







0834-19 2025/09/22 23.34UT TOYOKAWA-FUJI

















0839-071 2025/09/22 23.43UT TOYOKAWA-FUJI










T20250923083500




BLK: 7, SNR1: 6.1529 , SNR2: 13.730




F20250923083502









BLK: 7, SNR1: 7.7903 , SNR2: 17.228











3C208 2025/09/22 23.61UT TOYOKAWA-FUJI





















T20250923090352




BLK:16,SNR1: 6.8284 ,SNR2: 15.568




F20250923090354









BLK:16,SNR1: 6.6531 ,SNR2: 17.229





0919-142 2025/09/23 0.09UT TOYOKAWA-FUJI










T20250923091031




BLK: 5, SNR1: 0.24190 , SNR2: 1.1531




F20250923091033









BLK: 5, SNR1: 0.97034 , SNR2: 4.3156





0926+117 2025/09/23 0.20UT TOYOKAWA-FUJI









T20250923091816




BLK:10,SNR1: 5.5579 ,SNR2: 15.128




F20250923091818









BLK:10,SNR1: 7.3656 ,SNR2: 18.766





3C222 2025/09/23 0.33UT TOYOKAWA-FUJI









T20250923092516




BLK: 5,SNR1: 0.20567 ,SNR2: 1.1108




F20250923092518









BLK: 5,SNR1: 0.32242 ,SNR2: 1.7974





0941-08 2025/09/23 0.45UT TOYOKAWA-FUJI









T20250923093338




BLK:14,SNR1: 3.0193 ,SNR2: 9.2013




F20250923093340









BLK:14,SNR1: 1.5417 ,SNR2: 4.8921





3C230 2025/09/23 0.59UT TOYOKAWA-FUJI










T20250923094939




BLK: 7, SNR1: 14.486 , SNR2: 35.555




F20250923094941









BLK: 7, SNR1: 9.8351 , SNR2: 22.738




3C237 2025/09/23 0.86UT TOYOKAWA-FUJI










T20250923095555




BLK: 5, SNR1: -0.13628 , SNR2: 0.12674




F20250923095557









BLK: 5, SNR1: 2.4246 , SNR2: 9.9113





1011+110 2025/09/23 0.96UT TOYOKAWA-FUJI










T20250923100336




BLK:11,SNR1: 27.461 ,SNR2: 31.868




F20250923100336









BLK:11,SNR1: 6.7884 ,SNR2: 18.332







3C241 2025/09/23 1.09UT TOYOKAWA-FUJI

















1031-11 2025/09/23 1.28UT TOYOKAWA-FUJI










T20250923101939




BLK: 6,SNR1: 19.596 ,SNR2: 41.123




F20250923101941









BLK: 6,SNR1: 0.34912 ,SNR2: 2.0952











1035-058 2025/09/23 1.36UT TOYOKAWA-FUJI



















T20250923103956




BLK:30,SNR1: 43.246 ,SNR2: 114.03




F20250923103958









BLK:30,SNR1: 1.0256 ,SNR2: 5.3056




1055+01 2025/09/23 1.69UT TOYOKAWA-FUJI









T20250923105113




BLK:11,SNR1: 0.91010 ,SNR2: 2.3530




F20250923105115





BLK:11,SNR1: 1.3639 ,SNR2: 3.6545






1107+109 2025/09/23 1.88UT TOYOKAWA-FUJI











1107+109 2025/09/23 1.88UT TOYOKAWA-KISO











1107+109 2025/09/23 1.88UT FUJI -KISO












T20250923111128





BLK:16,SNR1: 1.5092 ,SNR2: 4.6330







1127-14 2025/09/23 2.22UT TOYOKAWA-FUJI

F20250923111130







BLK:16,SNR1: 2.8941 ,SNR2: 12.920







1127-14 2025/09/23 2.22UT TOYOKAWA-KISO








T20250923112449




BLK: 7, SNR1: 3.7572 , SNR2: 10.126




F20250923112451









BLK: 7, SNR1: 13.001 , SNR2: 32.753




3C263.1 2025/09/23 2.44UT TOYOKAWA-FUJI










T20250923113116




BLK:25,SNR1: 5.8935 ,SNR2: 10.205




F20250923113118









BLK:25,SNR1: 5.5357 ,SNR2: 9.7498




3C267 2025/09/23 2.55UT TOYOKAWA-FUJI









T20250923115703




BLK:10,SNR1: 1.7923 ,SNR2: 4.6522




F20250923115705









BLK:10,SNR1: 0.33877 ,SNR2: 3.9680




1213-17 2025/09/23 2.98UT TOYOKAWA-FUJI









T20250923121021




BLK: 9,SNR1: 6.2836 ,SNR2: 8.9751




F20250923121023









BLK: 9,SNR1: 0.29049 ,SNR2: 3.2491




3C273 2025/09/23 3.20UT TOYOKAWA-FUJI













BLK: 9,SNR1: 12.069 ,SNR2: 27.930





BLK: 9,SNR1: 9.8047 ,SNR2: 24.747







3C275 2025/09/23 3.42UT TOYOKAWA-FUJI






3C275 2025/09/23 3.42UT TOYOKAWA-KISO







T20250923122936




BLK:12,SNR1: 0.44513 ,SNR2: 2.1081




F20250923122938









BLK:12,SNR1: 0.35448 ,SNR2: 1.3237




1245-19 2025/09/23 3.52UT TOYOKAWA-FUJI













BLK:16,SNR1: 3.6958 ,SNR2: 7.2386









BLK:16,SNR1: 24.550 ,SNR2: 57.507




3C279 2025/09/23 3.65UT TOYOKAWA-FUJI













BLK:24,SNR1: 1.4120 ,SNR2: 3.1005









BLK:24,SNR1: 0.92672 ,SNR2: 3.5938




3C283 2025/09/23 3.91UT TOYOKAWA-FUJI









T20250923130714




BLK: 8,SNR1: 2.2811 ,SNR2: 6.0520




F20250923130716









BLK: 8,SNR1: 4.6021 ,SNR2: 13.496




1323+32 2025/09/23 4.15UT TOYOKAWA-FUJI













BLK:19,SNR1: 2.9229 ,SNR2: 6.7200









BLK:19,SNR1: 1.6317 ,SNR2: 4.4843




3C286 2025/09/23 4.23UT TOYOKAWA-FUJI













BLK:15,SNR1: 2.7269 ,SNR2: 7.6968





BLK:15,SNR1: 3.2252 ,SNR2: 9.8224







1345+12 2025/09/23 4.50UT TOYOKAWA-FUJI







1345+12 2025/09/23 4.50UT TOYOKAWA-KISO








T20250923133852




BLK:11,SNR1: 1.1138 ,SNR2: 3.7955




F20250923133854





BLK:11,SNR1: 2.0181 ,SNR2: 8.7081







1355+01 2025/09/23 4.68UT TOYOKAWA-FUJI







1355+01 2025/09/23 4.68UT TOYOKAWA-KISO







T20250923140002




BLK:24,SNR1: 0.97296 ,SNR2: 4.9010




F20250923140004









BLK:24,SNR1: 0.56983 ,SNR2: 3.0614





3C298 2025/09/23 5.03UT TOYOKAWA-FUJI










T20250923141146




BLK:10,SNR1: 0.80097 ,SNR2: 11.950




F20250923141148





BLK:10,SNR1: 11.196 ,SNR2: 24.748







1428-03 2025/09/23 5.22UT TOYOKAWA-FUJI






1428-03 2025/09/23 5.22UT TOYOKAWA-KISO








T20250923142027




BLK: 5,SNR1: 0.72932 ,SNR2: 3.7114




F20250923142029









BLK: 5,SNR1:-0.37881 ,SNR2: 0.0000




1436-16 2025/09/23 5.37UT TOYOKAWA-FUJI













BLK:22,SNR1: 2.3812 ,SNR2: 7.6706





BLK:22,SNR1: 9.9473 ,SNR2: 18.184







1453-10 2025/09/23 5.64UT TOYOKAWA-FUJI







1453-10 2025/09/23 5.64UT TOYOKAWA-KISO







T20250923145143




BLK: 3,SNR1:-0.59524E-01,SNR2: 0.99714




F20250923145145









BLK: 3,SNR1: 2.7282 ,SNR2: 12.398




1508-05 2025/09/23 5.89UT TOYOKAWA-FUJI













BLK: 7,SNR1: 0.17518 ,SNR2: 0.77206









BLK: 7,SNR1: 14.278 ,SNR2: 24.061




3C318 2025/09/23 6.04UT TOYOKAWA-FUJI













BLK:11,SNR1: 3.2999 ,SNR2: 9.9731









BLK:11,SNR1: 1.4649 ,SNR2: 4.9926





1523+03 2025/09/23 6.14UT TOYOKAWA-FUJI









T20250923151809




BLK:12,SNR1:-0.78278E-03,SNR2: 0.55754




F20250923151811









BLK:12,SNR1: 18.476 ,SNR2: 58.926





1535+139 2025/09/23 6.33UT TOYOKAWA-FUJI









T20250923152834




BLK: 6, SNR1: 0.20874 , SNR2: 1.3981




F20250923152836









BLK: 6, SNR1: -0.11758 , SNR2: 1.3447





1545-12 2025/09/23 6.50UT TOYOKAWA-FUJI









T20250923154936




BLK: 7,SNR1:-0.49492E-01,SNR2: 0.37944




F20250923154938









BLK: 7,SNR1: 2.4245 ,SNR2: 4.9403





1607+26 2025/09/23 6.85UT TOYOKAWA-FUJI








T20250923160707





BLK: 4,SNR1: 0.38518 ,SNR2: 5.1257




Frequency (Hz)

F20250923160709







BLK: 4,SNR1: 1.1220 ,SNR2: 3.7467







Frequency (Hz)

1623-228 2025/09/23 7.15UT TOYOKAWA-FUJI













BLK: 6,SNR1: 0.44223 ,SNR2: 1.2851





BLK: 6,SNR1: 0.71338 ,SNR2: 12.026







1631-222 2025/09/23 7.29UT TOYOKAWA-FUJI










1631-222 2025/09/23 7.29UT TOYOKAWA-KISO















1638-025 2025/09/23 7.38UT TOYOKAWA-FUJI








T20250923162809




BLK: 4, SNR1: 0.46536 , SNR2: 2.8595




Frequency (Hz)

F20250923162811







BLK: 4, SNR1: 3.2064 , SNR2: 6.4142







Frequency (Hz)

1644-106 2025/09/23 7.50UT TOYOKAWA-FUJI













BLK: 4,SNR1: 0.20903 ,SNR2: 2.1345









BLK: 4,SNR1: 1.2512 ,SNR2: 3.8728




1650+004 2025/09/23 7.59UT TOYOKAWA-FUJI













BLK: 4, SNR1: 0.54636E-02, SNR2: 0.31389









BLK: 4, SNR1: 0.35623, SNR2: 3.4953







1656+053 2025/09/23 7.68UT TOYOKAWA-FUJI












1712-033 2025/09/23 7.95UT TOYOKAWA-FUJI





1712-033 2025/09/23 7.95UT TOYOKAWA-KISO

