



T20260404064239




BLK: 8,SNR1: 0.27696 ,SNR2: 1.7028




Frequency (Hz)

F20260404064241




BLK: 8,SNR1: 0.11496 ,SNR2: 1.4181




Frequency (Hz)


1938-15 2026/04/03 21.74UT TOYOKAWA-FUJI



T20260404064239




BLK: 8,SNR1: 0.40021E-01,SNR2: 2.3342




Frequency (Hz)

K20260404064237




BLK: 8,SNR1: 6.9539 ,SNR2: 16.381






Frequency (Hz)

1938-15 2026/04/03 21.74UT TOYOKAWA-KISO







F20260404064241





1938-15 2026/04/03 21.74UT FUJI -KISO


K20260404064237



T20260404065012





BLK:11,SNR1: 2.4493 ,SNR2: 7.1574




Frequency (Hz)

1945-190 2026/04/03 21.86UT TOYOKAWA-FUJI


F20260404065014




BLK:11,SNR1:-0.77886E-03,SNR2: 2.4960




Frequency (Hz)



T20260404065012





BLK:18,SNR1: 1.4841 ,SNR2: 4.5016





1945-190 2026/04/03 21.86UT TOYOKAWA-KISO



K20260404065009




BLK:18,SNR1: 5.1938 ,SNR2: 6.8725



F20260404065014





BLK:11,SNR1: 0.32535 ,SNR2: 2.4671




Frequency (Hz)

K20260404065009




BLK:11,SNR1: 6.7304 ,SNR2: 15.293





Frequency (Hz)


1945-190 2026/04/03 21.86UT FUJI -KISO



T20260404065408





BLK: 5,SNR1: 1.2110 ,SNR2: 5.6744




Frequency (Hz)

F20260404065410




BLK: 5,SNR1: 0.61226 ,SNR2: 7.2745





Frequency (Hz)


1949-197 2026/04/03 21.93UT TOYOKAWA-FUJI



T20260404065408





BLK: 5, SNR1: 1.7131 , SNR2: 10.429




Frequency (Hz)

K20260404065405




BLK: 5, SNR1: 1.0383 , SNR2: 4.7823




Frequency (Hz)


1949-197 2026/04/03 21.93UT TOYOKAWA-KISO



F20260404065410




BLK: 1,SNR1:-0.28958 ,SNR2: 0.0000




Frequency (Hz)

K20260404065405




BLK: 1,SNR1: 1.2521 ,SNR2: 3.6010





Frequency (Hz)


1949-197 2026/04/03 21.93UT FUJI -KISO





T20260404070949




No.Good Data




FUJI





No.Good Data




2007+502 2026/04/03 22.19UT TOYOKAWA-FUJI



T20260404070949





No.Good Data




Frequency (Hz)

K20260404070946




No.Good Data





Frequency (Hz)


2007+502 2026/04/03 22.19UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20260404070946




No.Good Data





Frequency (Hz)


2007+502 2026/04/03 22.19UT FUJI -KISO



T20260404071733





BLK:12,SNR1: 5.8649 ,SNR2: 27.788




Frequency (Hz)

2014+358 2026/04/03 22.32UT TOYOKAWA-FUJI


F20260404071735




BLK:12,SNR1: 0.32256 ,SNR2: 2.5119




Frequency (Hz)




T20260404071733




No.Good Data




KISO





No.Good Data




2014+358 2026/04/03 22.32UT TOYOKAWA-KISO




F20280404071735




No.Good Data




KISO





No.Good Data




2014+358 2026/04/03 22.32UT FUJI -KISO



T20260404072542





BLK: 4,SNR1: 16.140 ,SNR2: 29.194




Frequency (Hz)

F20260404072544




BLK: 4,SNR1: 21.866 ,SNR2: 40.217





Frequency (Hz)


2022+119 2026/04/03 22.46UT TOYOKAWA-FUJI





T20260404072542




No.Good Data




K20260404072540




No.Good Data




2022+119 2026/04/03 22.46UT TOYOKAWA-KISO



F20260404072544





BLK: 1,SNR1: 13.112 ,SNR2: 31.202




Frequency (Hz)

K20260404072540




BLK: 1,SNR1: 18.461 ,SNR2: 32.751





Frequency (Hz)


2022+119 2026/04/03 22.46UT FUJI -KISO



T20260404073333





BLK: 4,SNR1: 0.67378 ,SNR2: 5.8018




Frequency (Hz)

F20260404073335




BLK: 4,SNR1: 0.40932 ,SNR2: 2.2891





Frequency (Hz)


2029-018 2026/04/03 22.59UT TOYOKAWA-FUJI



T20260404073333





BLK:10,SNR1: 2.5268 ,SNR2: 14.867




Frequency (Hz)

K20260404073330




BLK:10,SNR1: 0.78748 ,SNR2: 1.8267




Frequency (Hz)


2029-018 2026/04/03 22.59UT TOYOKAWA-KISO



F20260404073335





BLK: 4,SNR1:-0.15772 ,SNR2: 0.0000




Frequency (Hz)

K20260404073330




BLK: 4,SNR1: 0.91970E-01,SNR2: 2.6109





Frequency (Hz)


2029-018 2026/04/03 22.59UT FUJI -KISO



T20260404073749





BLK: 6,SNR1: 15.090 ,SNR2: 70.116




Frequency (Hz)

F20260404073751




BLK: 6,SNR1: 13.629 ,SNR2: 24.245




Frequency (Hz)


2034-066 2026/04/03 22.66UT TOYOKAWA-FUJI



T20260404073749




BLK: 3,SNR1: 99.153 ,SNR2: 340.80




Frequency (Hz)

K20260404073746




BLK: 3,SNR1: 2.1330 ,SNR2: 4.9526





Frequency (Hz)


2034-066 2026/04/03 22.66UT TOYOKAWA-KISO



F20260404073751





No.Good Data




Frequency (Hz)

K20260404073746




No.Good Data





Frequency (Hz)


2034-066 2026/04/03 22.66UT FUJI -KISO



T20260404074218





BLK: 2,SNR1: 10.945 ,SNR2: 27.140




Frequency (Hz)

F20260404074220




BLK: 2,SNR1: 15.019 ,SNR2: 26.644





Frequency (Hz)


2038-013 2026/04/03 22.73UT TOYOKAWA-FUJI



T20260404074218





BLK: 1, SNR1: 17.813 , SNR2: 31.026




Frequency (Hz)

2038-013 2026/04/03 22.73UT TOYOKAWA-KISO


K20260404074216





BLK: 1, SNR1: 6.7606 , SNR2: 15.732




Frequency (Hz)





F20260404074220




No.Good Data




K20260404074216





No.Good Data





2038-013 2026/04/03 22.73UT FUJI -KISO




T20260404074811




F20260404074813




3C422 2026/04/03 22.83UT TOYOKAWA-FUJI




T20260404074811




BLK: 3,SNR1: 16.011 ,SNR2: 39.207




K20260404074808





BLK: 3,SNR1: 10.021 ,SNR2: 26.101




3C422 2026/04/03 22.83UT TOYOKAWA-KISO



F20260404074813





BLK: 1,SNR1: 16.143 ,SNR2: 38.578




Frequency (Hz)

3C422 2026/04/03 22.83UT FUJI -KISO


K20260404074808




BLK: 1,SNR1: 3.2068 ,SNR2: 8.1422




Frequency (Hz)



T20260404080007




BLK:11,SNR1: 14.427 ,SNR2: 44.555




Frequency (Hz)

F20260404080009




BLK:11,SNR1: 1.6555 ,SNR2: 5.0206




Frequency (Hz)


2056+028 2026/04/03 23.03UT TOYOKAWA-FUJI



T20260404080007





BLK:12,SNR1: 16.211 ,SNR2: 49.174




Frequency (Hz)

K20260404080005




BLK:12,SNR1: 7.1283 ,SNR2: 18.648





Frequency (Hz)


2056+028 2026/04/03 23.03UT TOYOKAWA-KISO





F20260404080009




BLK: 1,SNR1: 0.96205 ,SNR2: 3.3284




K20260404080005





BLK: 1,SNR1: 4.0104 ,SNR2: 8.7953




2056+028 2026/04/03 23.03UT FUJI -KISO



T20260404080849





BLK: 4, SNR1: 11.231 ,SNR2: 27.729




Frequency (Hz)

F20260404080851




BLK: 4, SNR1: 11.613 ,SNR2: 28.510





Frequency (Hz)


2105-072 2026/04/03 23.18UT TOYOKAWA-FUJI



T20260404080849





BLK: 3,SNR1: 1.3922 ,SNR2: 9.6091




Frequency (Hz)

K20260404080847




BLK: 3,SNR1: 15.425 ,SNR2: 36.722





Frequency (Hz)


2105-072 2026/04/03 23.18UT TOYOKAWA-KISO



F20260404080851





BLK: 2,SNR1: 12.312 ,SNR2: 30.194




Frequency (Hz)

K20260404080847




BLK: 2,SNR1: 4.8659 ,SNR2: 17.096





Frequency (Hz)


2105-072 2026/04/03 23.18UT FUJI -KISO





T20260404082354




No.Good Data




F20260404082356





No.Good Data




2120-102 2026/04/03 23.43UT TOYOKAWA-FUJI



T20260404082354





BLK: 2,SNR1: 7.8035 ,SNR2: 18.655




Frequency (Hz)

K20260404082351




BLK: 2,SNR1: 18.913 ,SNR2: 33.614





Frequency (Hz)


2120-102 2026/04/03 23.43UT TOYOKAWA-KISO





F20260404082356




No.Good Data




K20260404082351





No.Good Data




2120-102 2026/04/03 23.43UT FUJI -KISO



T20260404083433





BLK: 8,SNR1: 4.4479 ,SNR2: 11.058




Frequency (Hz)

F20260404083435




BLK: 8,SNR1: 2.8604 ,SNR2: 13.615





Frequency (Hz)


2131+379 2026/04/03 23.60UT TOYOKAWA-FUJI





T20260404083433




BLK:10,SNR1: 4.3610 ,SNR2: 10.804




K20260404083431





BLK:10,SNR1: 6.8831 ,SNR2: 17.557




2131+379 2026/04/03 23.60UT TOYOKAWA-KISO



F20260404083435





BLK:10,SNR1: 2.8514 ,SNR2: 13.579




Frequency (Hz)

2131+379 2026/04/03 23.60UT FUJI -KISO


K20260404083431




BLK:10,SNR1: 10.404 ,SNR2: 18.518




Frequency (Hz)




T20260404085112




BLK: 3,SNR1:-0.27195E-01,SNR2: 1.5243




F20260404085114




BLK: 3,SNR1: 6.3193 ,SNR2: 15.758




2147+145 2026/04/03 23.88UT TOYOKAWA-FUJI





T20260404085112




BLK: 2, SNR1: 0.56554 , SNR2: 1.5757




K20260404085110




BLK: 2, SNR1: 3.1761 , SNR2: 7.9148




2147+145 2026/04/03 23.88UT TOYOKAWA-KISO




F20260404085114




BLK: 2,SNR1: 1.5310 ,SNR2: 5.7613




K20260404085110





BLK: 2,SNR1: 1.2978 ,SNR2: 6.0219




2147+145 2026/04/03 23.88UT FUJI -KISO



T20260404090017





BLK: 5, SNR1: 9.1672 ,SNR2: 21.825




Frequency (Hz)

2156-043 2026/04/04 0.03UT TOYOKAWA-FUJI


F20260404090019





BLK: 5, SNR1: 9.5000 ,SNR2: 23.132




Frequency (Hz)



T20260404090017





BLK: 2, SNR1: 16.077 ,SNR2: 34.535




Frequency (Hz)

2156-043 2026/04/04 0.03UT TOYOKAWA-KISO


K20260404090015




BLK: 2, SNR1: 6.5344 ,SNR2: 16.537




Frequency (Hz)




F20260404090019




BLK: 2,SNR1: 2.6281 ,SNR2: 12.084




K20260404090015





BLK: 2,SNR1: 8.7460 ,SNR2: 21.823




2156-043 2026/04/04 0.03UT FUJI -KISO



T20260404090705




BLK: 6,SNR1: 12.551 ,SNR2: 31.190




Frequency (Hz)

2203-18 2026/04/04 0.15UT TOYOKAWA-FUJI


F20260404090707





BLK: 6,SNR1: 12.046 ,SNR2: 30.563




Frequency (Hz)



T20260404090705





BLK: 8,SNR1: 18.970 ,SNR2: 36.452




Frequency (Hz)

2203-18 2026/04/04 0.15UT TOYOKAWA-KISO


K20260404090703





BLK: 8,SNR1: 11.415 ,SNR2: 27.898




Frequency (Hz)



F20260404090707





BLK: 5, SNR1: 11.764 ,SNR2: 34.007




Frequency (Hz)

K20260404090703




BLK: 5, SNR1: 12.145 ,SNR2: 29.547





Frequency (Hz)


2203-18 2026/04/04 0.15UT FUJI -KISO



T20260404091327





BLK: 1,SNR1: 6.1844 ,SNR2: 22.162




Frequency (Hz)

F20260404091329




BLK: 1,SNR1: 10.242 ,SNR2: 18.470





Frequency (Hz)


2210+016 2026/04/04 0.25UT TOYOKAWA-FUJI



T20260404091327





BLK: 1, SNR1: 0.84463 , SNR2: 4.7254




Frequency (Hz)

2210+016 2026/04/04 0.25UT TOYOKAWA-KISO


K20260404091324







BLK: 1, SNR1: 1.6884 , SNR2: 7.5098





Frequency (Hz)







2210+016 2026/04/04 0.25UT FUJI -KISO







BLK: 3, SNR1: 8.6847 ,SNR2: 21.771




BLK: 3, SNR1: 18.434 ,SNR2: 31.133




2217+128 2026/04/04 0.38UT TOYOKAWA-FUJI








BLK: 4, SNR1: 16.273 ,SNR2: 28.706





BLK: 4, SNR1: 16.236 ,SNR2: 28.628




2217+128 2026/04/04 0.38UT TOYOKAWA-KISO





F20260404092052




BLK: 2, SNR1: 18.570 ,SNR2: 33.447




K20260404092047




BLK: 2, SNR1: 0.14302 ,SNR2: 5.1275




2217+128 2026/04/04 0.38UT FUJI -KISO



T20260404092637





BLK: 2, SNR1: 7.0484 , SNR2: 13.682




Frequency (Hz)

3C446 2026/04/04 0.47UT TOYOKAWA-FUJI


F20260404092639




BLK: 2, SNR1: 0.51485 , SNR2: 1.8855




Frequency (Hz)



T20260404092637





BLK: 7,SNR1: 4.3215 ,SNR2: 12.514





3C446 2026/04/04 0.47UT TOYOKAWA-KISO


K20260404092634




BLK: 7,SNR1: 6.1133 ,SNR2: 16.106



F20260404092639




BLK: 4,SNR1:-0.25969 ,SNR2: 0.82186





3C446 2026/04/04 0.47UT FUJI -KISO



K20260404092634




BLK: 4,SNR1: 4.4799 ,SNR2: 11.183



T20260404093320





BLK: 3,SNR1: 22.609 ,SNR2: 47.974




Frequency (Hz)

2229-093 2026/04/04 0.58UT TOYOKAWA-FUJI


F20260404093322




BLK: 3,SNR1: 10.600 ,SNR2: 29.499




Frequency (Hz)



T20260404093320




BLK: 1, SNR1: 15.876 , SNR2: 32.638





2229-093 2026/04/04 0.58UT TOYOKAWA-KISO


K20260404093317




BLK: 1, SNR1: 8.4581 , SNR2: 22.752



F20260404093322




BLK: 4, SNR1: 10.488 , SNR2: 29.192





2229-093 2026/04/04 0.58UT FUJI -KISO



K20260404093317




BLK: 4, SNR1: 6.9981 , SNR2: 18.157





T20260404094148




BLK: 9,SNR1: 7.3751 ,SNR2: 18.857




F20260404094150





BLK: 9,SNR1: 7.0729 ,SNR2: 21.886




2238-113 2026/04/04 0.72UT TOYOKAWA-FUJI





T20260404094148




BLK: 5, SNR1: 7.4578 , SNR2: 13.769




K20260404094145




BLK: 5, SNR1: 6.5350 , SNR2: 19.192




2238-113 2026/04/04 0.72UT TOYOKAWA-KISO



F20260404094150





BLK: 4, SNR1: 7.2899 , SNR2: 21.499





2238-113 2026/04/04 0.72UT FUJI -KISO



K20260404094145




BLK: 4, SNR1: 10.045 , SNR2: 25.088



T20260404095436





BLK: 3,SNR1: 2.1291 ,SNR2: 14.138





3C454.3 2026/04/04 0.94UT TOYOKAWA-FUJI



F20260404095438




BLK: 3,SNR1: 7.6386 ,SNR2: 17.687



T20260404095436





BLK: 4,SNR1: 1.8792 ,SNR2: 8.6938




Frequency (Hz)

3C454.3 2026/04/04 0.94UT TOYOKAWA-KISO


K20260404095433





BLK: 4,SNR1: 21.334 ,SNR2: 37.868




Frequency (Hz)




F20260404095438




BLK: 5, SNR1: 9.7776 , SNR2: 23.844




K20260404095433





BLK: 5, SNR1: 7.5144 , SNR2: 18.803




3C454.3 2026/04/04 0.94UT FUJI -KISO



T20260404100218





BLK:10,SNR1: 3.4638 ,SNR2: 10.414





2259+481 2026/04/04 1.07UT TOYOKAWA-FUJI



F20260404100220




BLK:10,SNR1: 3.3767 ,SNR2: 7.4476



T20260404100218





BLK:15,SNR1: 3.4338 ,SNR2: 10.333





2259+481 2026/04/04 1.07UT TOYOKAWA-KISO



K20260404100215




BLK:15,SNR1: 2.8001 ,SNR2: 8.8052





F20260404100220




BLK:21,SNR1: 5.8049 ,SNR2: 16.628




K20260404100215




BLK:21,SNR1: 9.4888 ,SNR2: 24.469




2259+481 2026/04/04 1.07UT FUJI -KISO



T20260404101713




BLK: 6,SNR1: 5.4291 ,SNR2: 15.718





3C459 2026/04/04 1.32UT TOYOKAWA-FUJI


F20260404101715




BLK: 6,SNR1: $-0.51993E-01$,SNR2: 1.3566



T20260404101713




BLK: 9,SNR1: 4.4045 ,SNR2: 13.181





3C459 2026/04/04 1.32UT TOYOKAWA-KISO


K20260404101710




BLK: 9,SNR1: 5.8386 ,SNR2: 13.210



F20260404101715





BLK:11,SNR1: 0.75816 ,SNR2: 2.5753




Frequency (Hz)

3C459 2026/04/04 1.32UT FUJI -KISO


K20260404101710





BLK:11,SNR1: 8.4304 ,SNR2: 14.884





Frequency (Hz)




T20260404105058





F20260404105100







2347-02 2026/04/04 1.88UT TOYOKAWA-FUJI





T20260404105058




K20260404105055





F20260404105100




BLK: 3,SNR1: 0.17935 ,SNR2: 1.6208




K20260404105055





BLK: 3,SNR1: 3.0981 ,SNR2: 5.9931




2347-02 2026/04/04 1.88UT FUJI -KISO



T20260404105751




BLK: 8,SNR1: 0.78542 ,SNR2: 4.6583




2354+14 2026/04/04 1.99UT TOYOKAWA-FUJI


F20260404105753





BLK: 8,SNR1: 2.5992 ,SNR2: 6.4944




Frequency (Hz)





T20260404105751




BLK: 4, SNR1: 0.43224 , SNR2: 3.1488




K20260404105748




BLK: 4, SNR1: 0.76328 , SNR2: 1.8965




2354+14 2026/04/04 1.99UT TOYOKAWA-KISO





F20260404105753




BLK: 7,SNR1: 1.1507 ,SNR2: 3.1014




K20260404105748




BLK: 7,SNR1: 0.79967 ,SNR2: 2.0978




2354+14 2026/04/04 1.99UT FUJI -KISO



T20260404110654





BLK:15,SNR1: 5.2752 ,SNR2: 13.067





3C2 2026/04/04 2.14UT TOYOKAWA-FUJI


F20260404110656




BLK:15,SNR1: 7.6793 ,SNR2: 19.379



T20260404110654




BLK:15,SNR1: 5.8059 ,SNR2: 17.075





3C2 2026/04/04 2.14UT TOYOKAWA-KISO



K20260404110651




BLK:15,SNR1: 4.0288 ,SNR2: 10.482



F20260404110656




BLK: 7, SNR1: 1.8232 ,SNR2: 4.4534









3C2 2026/04/04 2.14UT FUJI -KISO

K20260404110651





BLK: 7, SNR1: 1.3226 ,SNR2: 5.1207







0011+344 2026/04/04 2.27UT TOYOKAWA-FUJI







BLK: 1, SNR1: 0.67764E-02, SNR2: 0.48533E-01




BLK: 1, SNR1: 3.3071 ,SNR2: 9.9273




0011+344 2026/04/04 2.27UT TOYOKAWA-KISO




F20260404111418




BLK: 1,SNR1: 1.9663 ,SNR2: 10.799




K20260404111413





BLK: 1,SNR1: 0.26368 ,SNR2: 1.9767




0011+344 2026/04/04 2.27UT FUJI -KISO




T20260404112252




BLK:14,SNR1: 3.6559 ,SNR2: 5.9268




F20260404112254





BLK:14,SNR1: 0.38268 ,SNR2: 2.4962




0019-00 2026/04/04 2.41UT TOYOKAWA-FUJI




T20260404112252




BLK:11,SNR1: 4.3542 ,SNR2: 9.4035




K20260404112249




BLK:11,SNR1: 9.7030 ,SNR2: 20.718




0019-00 2026/04/04 2.41UT TOYOKAWA-KISO




F20260404112254




BLK:22,SNR1: 0.17520 ,SNR2: 2.4357




K20260404112249




BLK:22,SNR1: 9.4418 ,SNR2: 20.605




0019-00 2026/04/04 2.41UT FUJI -KISO




T20260404113307




BLK:11,SNR1: 0.74596 ,SNR2: 2.3884




F20260404113309




BLK:11,SNR1: 0.28047 ,SNR2: 1.9535




3C12 2026/04/04 2.58UT TOYOKAWA-FUJI





T20260404113307




BLK:14,SNR1: 0.76057 ,SNR2: 5.1599




K20260404113304





BLK:14,SNR1: 0.86303 ,SNR2: 2.5921




3C12 2026/04/04 2.58UT TOYOKAWA-KISO



F20260404113309





BLK: 9,SNR1: 0.14580 ,SNR2: 1.2544





3C12 2026/04/04 2.58UT FUJI -KISO


K20260404113304




BLK: 9,SNR1: 1.6253 ,SNR2: 3.1286



T20260404114708





BLK: 8,SNR1: 12.331 ,SNR2: 35.463





0044-056 2026/04/04 2.81UT TOYOKAWA-FUJI


F20260404114710




BLK: 8,SNR1: 0.25623 ,SNR2: 3.4090





T20260404114708




BLK: 6, SNR1: 8.2845 , SNR2: 23.753




K20260404114705





BLK: 6, SNR1: 1.6583 , SNR2: 5.3020




0044-056 2026/04/04 2.81UT TOYOKAWA-KISO





F20260404114710




BLK: 4,SNR1: 8.1501 ,SNR2: 19.612




K20260404114705





BLK: 4,SNR1: 10.315 ,SNR2: 29.742




0044-056 2026/04/04 2.81UT FUJI -KISO



T20260404115430




BLK:10,SNR1: 0.59093 ,SNR2: 3.7365





3C26 2026/04/04 2.94UT TOYOKAWA-FUJI



F20260404115432




BLK:10,SNR1: 13.620 ,SNR2: 21.932



T20260404115430




BLK:14,SNR1: 0.60093 ,SNR2: 2.3879





3C26 2026/04/04 2.94UT TOYOKAWA-KISO


K20260404115427




BLK:14,SNR1: 3.9798 ,SNR2: 7.7165



F20260404115432




BLK:12,SNR1: 9.6158 ,SNR2: 25.829





3C26 2026/04/04 2.94UT FUJI -KISO


K20260404115427




BLK:12,SNR1: 5.8917 ,SNR2: 11.376



T20260404115928




BLK:10,SNR1: 10.223 ,SNR2: 24.668





0056-00 2026/04/04 3.02UT TOYOKAWA-FUJI


F20260404115930




BLK:10,SNR1: 9.3956 ,SNR2: 20.910



T20260404115928




BLK: 5,SNR1: 12.872 ,SNR2: 28.754





0056-00 2026/04/04 3.02UT TOYOKAWA-KISO


K20260404115925




BLK: 5,SNR1: 10.889 ,SNR2: 27.483




F20260404115930




BLK: 4,SNR1: 12.818 ,SNR2: 28.992




K20260404115925




BLK: 4,SNR1: 14.597 ,SNR2: 32.605




0056-00 2026/04/04 3.02UT FUJI -KISO



T20260404120910





BLK:17,SNR1: 9.5570 ,SNR2: 20.430





0106+01 2026/04/04 3.18UT TOYOKAWA-FUJI


F20260404120912




BLK:17,SNR1: 1.9765 ,SNR2: 5.4136



T20260404120910





BLK:10,SNR1: 3.0830 ,SNR2: 9.5134





0106+01 2026/04/04 3.18UT TOYOKAWA-KISO



K20260404120907




BLK:10,SNR1: 8.5134 ,SNR2: 21.980



F20260404120912





BLK:11,SNR1: 3.2505 ,SNR2: 8.8890





0106+01 2026/04/04 3.18UT FUJI -KISO



K20260404120907




BLK:11,SNR1: 9.3082 ,SNR2: 23.891





T20260404121833




BLK:15,SNR1: 8.1681 ,SNR2: 14.085




F20260404121835





BLK:15,SNR1: 2.1650 ,SNR2: 3.9635




0115-01 2026/04/04 3.34UT TOYOKAWA-FUJI





T20260404121833




BLK:20,SNR1: 7.8380 ,SNR2: 13.521




K20260404121830





BLK:20,SNR1: 3.7147 ,SNR2: 8.7052




0115-01 2026/04/04 3.34UT TOYOKAWA-KISO





F20260404121835




BLK:15,SNR1: 3.4227 ,SNR2: 6.1790




K20260404121830




BLK:15,SNR1: 3.5343 ,SNR2: 6.3295




0115-01 2026/04/04 3.34UT FUJI -KISO





T20260404123133




BLK:18,SNR1: 1.9094 ,SNR2: 6.7106




F20260404123135




BLK:18,SNR1: 3.3229 ,SNR2: 8.8536




0128+03 2026/04/04 3.55UT TOYOKAWA-FUJI




T20260404123133




BLK:19,SNR1: 2.6055 ,SNR2: 6.9291




K20260404123130





BLK:19,SNR1: 10.843 ,SNR2: 14.297




0128+03 2026/04/04 3.55UT TOYOKAWA-KISO





F20260404123135




BLK:19,SNR1: 9.9508 ,SNR2: 21.010




K20260404123130





BLK:19,SNR1: 14.404 ,SNR2: 18.988




0128+03 2026/04/04 3.55UT FUJI -KISO



T20260404123807





BLK:31,SNR1: 6.3820 ,SNR2: 19.379





3C48 2026/04/04 3.66UT TOYOKAWA-FUJI



F20260404123809




BLK:31,SNR1: 9.2431 ,SNR2: 23.608





T20260404123807




BLK:31,SNR1: 6.5949 ,SNR2: 21.922




K20260404123804





BLK:31,SNR1: 6.1018 ,SNR2: 16.625




3C48 2026/04/04 3.66UT TOYOKAWA-KISO



F20260404123809





BLK:14,SNR1: 5.2998 ,SNR2: 13.704





3C48 2026/04/04 3.66UT FUJI -KISO



K20260404123804




BLK:14,SNR1: 4.3995 ,SNR2: 12.686




T20260404125751




BLK: 3,SNR1: 0.65737E-01,SNR2: 1.7955




F20260404125753





BLK: 3,SNR1: 8.8129 ,SNR2: 19.173




0155-109 2026/04/04 3.99UT TOYOKAWA-FUJI




T20260404125751




BLK: 6,SNR1: 0.50310 ,SNR2: 1.2539




K20260404125748




BLK: 6,SNR1: 21.166 ,SNR2: 28.461




0155-109 2026/04/04 3.99UT TOYOKAWA-KISO



F20260404125753




BLK: 3,SNR1: 12.231 ,SNR2: 25.712





0155-109 2026/04/04 3.99UT FUJI -KISO


K20260404125748




BLK: 3,SNR1: 14.662 ,SNR2: 31.573





T20260404130459




BLK:19,SNR1: 0.84184 ,SNR2: 5.9808




F20260404130501




BLK:19,SNR1: 0.93893E-01,SNR2: 1.9718




0202+15 2026/04/04 4.11UT TOYOKAWA-FUJI





T20260404130459




BLK:22,SNR1: 0.89122 ,SNR2: 5.7300




K20260404130456





BLK:22,SNR1: 0.65936 ,SNR2: 3.0041




0202+15 2026/04/04 4.11UT TOYOKAWA-KISO





F20260404130501




BLK:11,SNR1: 0.14282 ,SNR2: 2.3615




K20260404130456





BLK:11,SNR1: 0.93511 ,SNR2: 4.6682




0202+15 2026/04/04 4.11UT FUJI -KISO





T20260404131649




BLK:13,SNR1: 6.9158 ,SNR2: 17.971




F20260404131651






BLK:13,SNR1: 8.7863 ,SNR2: 19.589






0213+178 2026/04/04 4.31UT TOYOKAWA-FUJI




T20260404131649





K20260404131646




0213+178 2026/04/04 4.31UT TOYOKAWA-KISO





F20260404131651




BLK:18,SNR1: 3.1678 ,SNR2: 9.6559




K20260404131646




BLK:18,SNR1: 1.8991 ,SNR2: 6.5695





0213+178 2026/04/04 4.31UT FUJI -KISO







BLK:16,SNR1: 0.29530 ,SNR2: 1.2578







BLK:16,SNR1: 0.53107 ,SNR2: 5.1157




3C67 2026/04/04 4.44UT TOYOKAWA-FUJI








3C67 2026/04/04 4.44UT TOYOKAWA-KISO



F20260404132434





BLK:14,SNR1: 1.8291 ,SNR2: 6.5878




Frequency (Hz)

3C67 2026/04/04 4.44UT FUJI -KISO


K20260404132429





BLK:14,SNR1: 3.4549 ,SNR2: 6.5620




Frequency (Hz)




T20260404134246




No.Good Data




F20260404134248





No.Good Data




3C71 2026/04/04 4.74UT TOYOKAWA-FUJI




T20260404134246




BLK: 1,SNR1: 0.86122E-01,SNR2: 0.89301




K20260404134243





BLK: 1,SNR1: 12.084 ,SNR2: 29.234




3C71 2026/04/04 4.74UT TOYOKAWA-KISO



F20260404134248





No.Good Data




Frequency (Hz)

K20260404134243








No.Good Data




Frequency (Hz)


3C71 2026/04/04 4.74UT FUJI -KISO







0258+350 2026/04/04 5.06UT TOYOKAWA-FUJI







BLK: 1,SNR1: 0.35875 ,SNR2: 0.78931







BLK: 1,SNR1: 1.8903 ,SNR2: 9.4554




0258+350 2026/04/04 5.06UT TOYOKAWA-KISO








0258+350 2026/04/04 5.06UT FUJI -KISO





T20260404141151




BLK: 3,SNR1: 0.15682 ,SNR2: 1.0571




F20260404141153





BLK: 3,SNR1: 0.65022 ,SNR2: 1.7276




0308+305 2026/04/04 5.23UT TOYOKAWA-FUJI





T20260404141151




BLK: 3,SNR1: 0.92369E-01,SNR2: 0.49909




K20260404141148




BLK: 3,SNR1: 8.0521 ,SNR2: 20.632




0308+305 2026/04/04 5.23UT TOYOKAWA-KISO




F20260404141153




BLK: 4,SNR1: 1.0552 ,SNR2: 3.3039




K20260404141148





BLK: 4,SNR1: 6.9728 ,SNR2: 15.713




0308+305 2026/04/04 5.23UT FUJI -KISO





T20260404142322




BLK: 5,SNR1: 0.92577 ,SNR2: 5.8399




F20260404142324





BLK: 5,SNR1: 6.2556 ,SNR2: 20.276




0320+05 2026/04/04 5.42UT TOYOKAWA-FUJI




T20260404142322




BLK: 2,SNR1: 11.231 ,SNR2: 27.523




K20260404142319




BLK: 2,SNR1: 9.5838 ,SNR2: 23.549




0320+05 2026/04/04 5.42UT TOYOKAWA-KISO




F20260404142324




BLK: 6,SNR1: 2.3268 ,SNR2: 9.8600




K20260404142319





BLK: 6,SNR1: 3.8792 ,SNR2: 9.0012




0320+05 2026/04/04 5.42UT FUJI -KISO





T20260404143644




BLK: 3,SNR1: 9.2085 ,SNR2: 22.425




F20260404143646





BLK: 3,SNR1: 10.077 ,SNR2: 24.480




0333+32 2026/04/04 5.64UT TOYOKAWA-FUJI



T20260404143644





BLK: 1,SNR1: 9.1913 ,SNR2: 22.725




Frequency (Hz)

K20260404143641




BLK: 1,SNR1: 22.326 ,SNR2: 39.989





Frequency (Hz)


0333+32 2026/04/04 5.64UT TOYOKAWA-KISO



F20260404143646





BLK: 1,SNR1: 2.4231 ,SNR2: 11.148




Frequency (Hz)

K20260404143641




BLK: 1,SNR1: 2.7315 ,SNR2: 12.583





Frequency (Hz)


0333+32 2026/04/04 5.64UT FUJI -KISO





T20260404144945




BLK: 6,SNR1: 7.3639 ,SNR2: 18.772




F20260404144947





BLK: 6,SNR1: 10.926 ,SNR2: 19.262




0347+05 2026/04/04 5.86UT TOYOKAWA-FUJI





T20260404144945




BLK: 4,SNR1: 7.4588 ,SNR2: 18.754




K20260404144942





BLK: 4,SNR1: 11.738 ,SNR2: 21.387




0347+05 2026/04/04 5.86UT TOYOKAWA-KISO





F20260404144947




BLK: 9,SNR1: 10.710 ,SNR2: 23.596




K20260404144942





BLK: 9,SNR1: 6.9856 ,SNR2: 17.376




0347+05 2026/04/04 5.86UT FUJI -KISO





T20260404150519




BLK: 3,SNR1: 3.7108 ,SNR2: 12.004




F20260404150521




BLK: 3,SNR1: 2.7840 ,SNR2: 13.149




0403-132 2026/04/04 6.12UT TOYOKAWA-FUJI





T20260404150519




BLK: 6,SNR1: 10.872 ,SNR2: 19.135




K20260404150516





BLK: 6,SNR1: 17.464 ,SNR2: 30.804




0403-132 2026/04/04 6.12UT TOYOKAWA-KISO



F20260404150521





BLK: 1,SNR1: 6.1926 ,SNR2: 14.798




Frequency (Hz)

K20260404150516




BLK: 1,SNR1: 8.8633 ,SNR2: 32.268





Frequency (Hz)


0403-132 2026/04/04 6.12UT FUJI -KISO





T20260404151430




No.Good Data




F20260404151432





No.Good Data




0411+05 2026/04/04 6.27UT TOYOKAWA-FUJI





T20260404151430




No.Good Data




K20260404151427





No.Good Data




0411+05 2026/04/04 6.27UT TOYOKAWA-KISO





F20260404151432




No.Good Data




K20260404151427





No.Good Data




0411+05 2026/04/04 6.27UT FUJI -KISO





T20260404152524




No.Good Data




F20260404152526




No.Good Data




0422+178 2026/04/04 6.45UT TOYOKAWA-FUJI



T20260404152524




No.Good Data




Frequency (Hz)

K20260404152521




No.Good Data




Frequency (Hz)


0422+178 2026/04/04 6.45UT TOYOKAWA-KISO



F20260404152526




BLK: 3,SNR1: 19.866 ,SNR2: 35.019




Frequency (Hz)

K20260404152521




BLK: 3,SNR1: 17.002 ,SNR2: 29.995





Frequency (Hz)


0422+178 2026/04/04 6.45UT FUJI -KISO





T20260404153253




BLK: 2,SNR1: 6.1062 ,SNR2: 15.296




F20260404153255





BLK: 2,SNR1: 6.8612 ,SNR2: 17.349




3C119 2026/04/04 6.58UT TOYOKAWA-FUJI



T20260404153253





BLK: 3,SNR1: 4.5043 ,SNR2: 11.287




Frequency (Hz)

K20260404153250




BLK: 3,SNR1: 6.8372 ,SNR2: 17.134




Frequency (Hz)


3C119 2026/04/04 6.58UT TOYOKAWA-KISO



F20260404153255




BLK: 9,SNR1: 6.9669 ,SNR2: 17.481




Frequency (Hz)

K20260404153250




BLK: 9,SNR1: 6.9251 ,SNR2: 17.260




Frequency (Hz)


3C119 2026/04/04 6.58UT FUJI -KISO



T20260404162059





No.Good Data




Frequency (Hz)

F20260404162101




No.Good Data




Frequency (Hz)


3C138 2026/04/04 7.38UT TOYOKAWA-FUJI



T20260404162059





BLK: 3,SNR1: 4.0793 ,SNR2: 12.117




Frequency (Hz)

K20260404162056




BLK: 3,SNR1: 2.2876 ,SNR2: 10.633





Frequency (Hz)


3C138 2026/04/04 7.38UT TOYOKAWA-KISO





F20260404162101




No.Good Data




K20260404162056




No.Good Data




3C138 2026/04/04 7.38UT FUJI -KISO



T20260404163433




BLK: 6, SNR1: 9.2738 , SNR2: 17.140




Frequency (Hz)

F20260404163435




BLK: 6, SNR1: 10.555 , SNR2: 19.488





Frequency (Hz)


0531+194 2026/04/04 7.60UT TOYOKAWA-FUJI



T20260404163433





BLK: 6,SNR1: 4.9396 ,SNR2: 18.744




Frequency (Hz)

K20260404163431




BLK: 6,SNR1: 11.665 ,SNR2: 21.642




Frequency (Hz)


0531+194 2026/04/04 7.60UT TOYOKAWA-KISO



F20260404163435





BLK:10,SNR1: 5.9743 ,SNR2: 15.465




Frequency (Hz)

K20260404163431








BLK:10,SNR1: 10.463 ,SNR2: 19.405




Frequency (Hz)



0531+194 2026/04/04 7.60UT FUJI -KISO






3C147 2026/04/04 7.74UT TOYOKAWA-FUJI







3C147 2026/04/04 7.74UT TOYOKAWA-KISO




F20260404164256




BLK: 1, SNR1: 6.7744 , SNR2: 16.495




K20260404164251





BLK: 1, SNR1: 6.1499 , SNR2: 15.063




3C147 2026/04/04 7.74UT FUJI -KISO



T20260404165104




BLK: 4,SNR1: 1.9303 ,SNR2: 7.4909




Frequency (Hz)

F20260404165106




BLK: 4,SNR1: 4.8281 ,SNR2: 18.385





Frequency (Hz)


0548+16 2026/04/04 7.88UT TOYOKAWA-FUJI



T20260404165104




BLK: 1, SNR1: 3.6180 , SNR2: 12.902




Frequency (Hz)

K20260404165101




BLK: 1, SNR1: 7.6204 , SNR2: 16.824




Frequency (Hz)


0548+16 2026/04/04 7.88UT TOYOKAWA-KISO



F20260404165106




BLK: 2, SNR1: 21.454 , SNR2: 30.417




Frequency (Hz)

K20260404165101




BLK: 2, SNR1: 6.2343 , SNR2: 15.690




Frequency (Hz)


0548+16 2026/04/04 7.88UT FUJI -KISO



T20260404165514





BLK: 6,SNR1: 49.856 ,SNR2: 166.22




Frequency (Hz)

F20260404165516




BLK: 6,SNR1: 11.740 ,SNR2: 20.378




Frequency (Hz)


0552+12 2026/04/04 7.95UT TOYOKAWA-FUJI



T20260404165514





BLK: 6,SNR1: 56.647 ,SNR2: 100.08




Frequency (Hz)

K20260404165511




BLK: 6,SNR1: 5.9588 ,SNR2: 13.770




Frequency (Hz)


0552+12 2026/04/04 7.95UT TOYOKAWA-KISO



F20260404165516





BLK: 4, SNR1: 10.548 , SNR2: 18.841




Frequency (Hz)

K20260404165511




BLK: 4, SNR1: 5.8592 , SNR2: 13.550





Frequency (Hz)


0552+12 2026/04/04 7.95UT FUJI -KISO



T20260404165941




BLK: 1,SNR1: 59.109 ,SNR2: 155.67




Frequency (Hz)

F20260404165943




BLK: 1,SNR1: 4.6304 ,SNR2: 11.875





Frequency (Hz)


0556+191 2026/04/04 8.02UT TOYOKAWA-FUJI



T20260404165941





BLK: 2, SNR1: 20.547 , SNR2: 71.252




Frequency (Hz)

K20260404165939




BLK: 2, SNR1: 8.1610 , SNR2: 15.917




Frequency (Hz)


0556+191 2026/04/04 8.02UT TOYOKAWA-KISO



F20260404165943





BLK: 2,SNR1: 2.8671 ,SNR2: 7.0373




Frequency (Hz)

K20260404165939




BLK: 2,SNR1: 7.0118 ,SNR2: 12.346





Frequency (Hz)


0556+191 2026/04/04 8.02UT FUJI -KISO



T20260404170414




BLK: 1,SNR1: 1.4427 ,SNR2: 8.8407




Frequency (Hz)

F20260404170416




BLK: 1,SNR1: 3.9612 ,SNR2: 33.792





Frequency (Hz)


3C152 2026/04/04 8.10UT TOYOKAWA-FUJI



T20260404170414




No.Good Data




Frequency (Hz)

K20260404170412




No.Good Data




Frequency (Hz)


3C152 2026/04/04 8.10UT TOYOKAWA-KISO



F20260404170416




No.Good Data




Frequency (Hz)

K20260404170412




No.Good Data




Frequency (Hz)


3C152 2026/04/04 8.10UT FUJI -KISO



T20260404172120





BLK: 3,SNR1: 2.1093 ,SNR2: 4.8509




Frequency (Hz)

F20260404172122




BLK: 3,SNR1: 10.175 ,SNR2: 25.791





Frequency (Hz)


3C158 2026/04/04 8.38UT TOYOKAWA-FUJI



T20260404172120





BLK: 4,SNR1: 1.1064 ,SNR2: 3.4665




Frequency (Hz)

K20260404172117




BLK: 4,SNR1: 9.1624 ,SNR2: 22.926




Frequency (Hz)


3C158 2026/04/04 8.38UT TOYOKAWA-KISO



F20260404172122




BLK: 5,SNR1: 8.8510 ,SNR2: 16.338




Frequency (Hz)

K20260404172117



BLK: 5,SNR1: 10.151 ,SNR2: 23.835



Frequency (Hz)

3C158 2026/04/04 8.38UT FUJI -KISO

