




T20260428060140





BLK: 5,SNR1: 7.5786 ,SNR2: 45.964




Frequency (Hz)

F20260428060142





BLK: 5,SNR1: 1.3432 ,SNR2: 4.0405





Frequency (Hz)

2033+375 2026/04/27 21.06UT TOYOKAWA-FUJI







BLK: 3, SNR1: 24.657 ,SNR2: 102.00





BLK: 3, SNR1: 0.62350 ,SNR2: 6.0642




2033+375 2026/04/27 21.06UT TOYOKAWA-KISO





F20260428060142




No.Good Data




K20260428060138





No.Good Data




2033+375 2026/04/27 21.06UT FUJI -KISO





T20260428060653




No.Good Data




F20260428060655





No.Good Data




2038+363 2026/04/27 21.14UT TOYOKAWA-FUJI





T20260428060653




BLK: 1,SNR1: 16.047 ,SNR2: 28.548




K20260428060651





BLK: 1,SNR1: 18.041 ,SNR2: 32.069




2038+363 2026/04/27 21.14UT TOYOKAWA-KISO



F20260428060655





BLK: 2, SNR1: 16.650 ,SNR2: 31.247




Frequency (Hz)

K20260428060651




BLK: 2, SNR1: 11.408 ,SNR2: 27.894





Frequency (Hz)


2038+363 2026/04/27 21.14UT FUJI -KISO




T20260428061800




BLK: 4,SNR1: 9.7961 ,SNR2: 34.329




F20260428061802





BLK: 4,SNR1: 7.3671 ,SNR2: 25.592




2049+166 2026/04/27 21.33UT TOYOKAWA-FUJI




T20260428061800




BLK: 5,SNR1: 1.0441 ,SNR2: 6.2036




K20260428061758




BLK: 5,SNR1: 7.3198 ,SNR2: 18.721




2049+166 2026/04/27 21.33UT TOYOKAWA-KISO



F20260428061802




BLK: 6,SNR1: 7.9108 ,SNR2: 18.136





2049+166 2026/04/27 21.33UT FUJI -KISO


K20260428061758




BLK: 6,SNR1: 7.2839 ,SNR2: 16.562



T20260428062545





BLK: 7,SNR1: 1.6325 ,SNR2: 8.3253




Frequency (Hz)

F20260428062547




BLK: 7,SNR1: 8.5838 ,SNR2: 21.436





Frequency (Hz)


2056+028 2026/04/27 21.46UT TOYOKAWA-FUJI



T20260428062545





BLK: 9,SNR1: 1.6626 ,SNR2: 8.5825




Frequency (Hz)

K20260428062543




BLK: 9,SNR1: 7.5762 ,SNR2: 24.493





Frequency (Hz)


2056+028 2026/04/27 21.46UT TOYOKAWA-KISO



F20260428062547





BLK: 4, SNR1: 8.6730 , SNR2: 21.660




Frequency (Hz)

2056+028 2026/04/27 21.46UT FUJI -KISO


K20260428062543




BLK: 4, SNR1: 7.2949 , SNR2: 24.476




Frequency (Hz)



T20260428063427




BLK: 3,SNR1: 5.3095 ,SNR2: 23.008




Frequency (Hz)

F20260428063429




BLK: 3,SNR1: 0.15069 ,SNR2: 1.9511




Frequency (Hz)


2105-072 2026/04/27 21.60UT TOYOKAWA-FUJI



T20260428063427





BLK: 2,SNR1: 1.9871 ,SNR2: 8.4089




Frequency (Hz)

K20260428063425




BLK: 2,SNR1: 0.67110 ,SNR2: 4.4039





Frequency (Hz)


2105-072 2026/04/27 21.60UT TOYOKAWA-KISO



F20260428063429





BLK: 2,SNR1: 0.36352 ,SNR2: 3.2994




Frequency (Hz)

K20260428063425




BLK: 2,SNR1: 2.0331 ,SNR2: 4.3317





Frequency (Hz)


2105-072 2026/04/27 21.60UT FUJI -KISO



T20260428064933





No.Good Data




Frequency (Hz)

F20260428064935




No.Good Data





Frequency (Hz)


2120-102 2026/04/27 21.85UT TOYOKAWA-FUJI



T20260428064933





No.Good Data




Frequency (Hz)

K20260428064930




No.Good Data





Frequency (Hz)


2120-102 2026/04/27 21.85UT TOYOKAWA-KISO



F20260428064935





BLK: 1,SNR1: 10.212 ,SNR2: 25.372




Frequency (Hz)

K20260428064930




BLK: 1,SNR1: 11.156 ,SNR2: 26.789





Frequency (Hz)


2120-102 2026/04/27 21.85UT FUJI -KISO



T20260428070012





BLK: 1,SNR1: 26.371 ,SNR2: 42.642




Frequency (Hz)

F20260428070014




BLK: 1,SNR1: 31.376 ,SNR2: 43.193





Frequency (Hz)


2131+379 2026/04/27 22.03UT TOYOKAWA-FUJI



T20260428070012





No.Good Data




Frequency (Hz)

K20260428070010




No.Good Data





Frequency (Hz)


2131+379 2026/04/27 22.03UT TOYOKAWA-KISO





F20260428070014




No.Good Data




K20260428070010





No.Good Data




2131+379 2026/04/27 22.03UT FUJI -KISO



T20260428071650





BLK: 2,SNR1: 0.19667 ,SNR2: 1.3025




Frequency (Hz)

2147+145 2026/04/27 22.31UT TOYOKAWA-FUJI


F20260428071652





BLK: 2,SNR1: 8.6828 ,SNR2: 22.846




Frequency (Hz)



T20260428071650




BLK: 2,SNR1: 0.29810 ,SNR2: 1.1327




Frequency (Hz)

2147+145 2026/04/27 22.31UT TOYOKAWA-KISO


K20260428071648





BLK: 2,SNR1: 1.1260 ,SNR2: 3.0061




Frequency (Hz)





F20260428071652




BLK: 2,SNR1: 2.6584 ,SNR2: 8.3060




K20260428071648





BLK: 2,SNR1: 5.5393 ,SNR2: 10.357




2147+145 2026/04/27 22.31UT FUJI -KISO



T20260428072555





BLK: 1,SNR1: 0.61915 ,SNR2: 3.8093




Frequency (Hz)

2156-043 2026/04/27 22.46UT TOYOKAWA-FUJI


F20260428072557





BLK: 1,SNR1: 9.6626 ,SNR2: 20.908




Frequency (Hz)





T20260428072555




No.Good Data




K20260428072553





No.Good Data




2156-043 2026/04/27 22.46UT TOYOKAWA-KISO



F20260428072557





BLK: 4,SNR1: 6.3934 ,SNR2: 16.080




Frequency (Hz)

2156-043 2026/04/27 22.46UT FUJI -KISO


K20260428072553





BLK: 4,SNR1: 1.6269 ,SNR2: 8.2675




Frequency (Hz)



T20260428073243





BLK: 4,SNR1: 7.9741 ,SNR2: 22.461




Frequency (Hz)

F20260428073245




BLK: 4,SNR1: 6.2388 ,SNR2: 13.559





Frequency (Hz)


2203-18 2026/04/27 22.57UT TOYOKAWA-FUJI



T20260428073243





BLK: 3,SNR1: 8.0584 ,SNR2: 22.684




Frequency (Hz)

K20260428073240




BLK: 3,SNR1: 9.9373 ,SNR2: 22.803





Frequency (Hz)


2203-18 2026/04/27 22.57UT TOYOKAWA-KISO



F20260428073245





BLK: 5,SNR1: 15.578 ,SNR2: 28.946




Frequency (Hz)

K20260428073240




BLK: 5,SNR1: 10.690 ,SNR2: 16.284




Frequency (Hz)


2203-18 2026/04/27 22.57UT FUJI -KISO



T20260428073905




BLK: 3,SNR1: 1.4407 ,SNR2: 3.0185




Frequency (Hz)

F20260428073907




BLK: 3,SNR1: 9.8346 ,SNR2: 15.210




Frequency (Hz)


2210+016 2026/04/27 22.68UT TOYOKAWA-FUJI



T20260428073905




BLK: 1,SNR1: 0.79194 ,SNR2: 2.7996




Frequency (Hz)

K20260428073902




BLK: 1,SNR1: 1.9054 ,SNR2: 6.8150





Frequency (Hz)


2210+016 2026/04/27 22.68UT TOYOKAWA-KISO



F20260428073907





BLK: 1,SNR1: 0.73118 ,SNR2: 3.0669




Frequency (Hz)

K20260428073902




BLK: 1,SNR1: 4.3331 ,SNR2: 12.470





Frequency (Hz)


2210+016 2026/04/27 22.68UT FUJI -KISO



T20260428074629





No. Good Data




Frequency (Hz)

F20260428074631




No. Good Data





Frequency (Hz)


2217+128 2026/04/27 22.80UT TOYOKAWA-FUJI



T20260428074629





BLK: 1,SNR1: 2.7718 ,SNR2: 12.691




Frequency (Hz)

K20260428074627




BLK: 1,SNR1: 11.186 ,SNR2: 27.031





Frequency (Hz)


2217+128 2026/04/27 22.80UT TOYOKAWA-KISO





F20260428074631




No.Good Data




K20260428074627





No.Good Data




2217+128 2026/04/27 22.80UT FUJI -KISO



T20260428075215





BLK: 1,SNR1: 0.69458E-01,SNR2: 2.5413




Frequency (Hz)

F20260428075217




BLK: 1,SNR1: 0.14905 ,SNR2: 3.8086





Frequency (Hz)


3C446 2026/04/27 22.90UT TOYOKAWA-FUJI





T20260428075215




No. Good Data




K20260428075213





No. Good Data




3C446 2026/04/27 22.90UT TOYOKAWA-KISO



F20260428075217





No. Good Data




Frequency (Hz)

3C446 2026/04/27 22.90UT FUJI -KISO


K20260428075213





No. Good Data




Frequency (Hz)



T20260428075859





BLK: 1,SNR1: 12.743 ,SNR2: 29.640




Frequency (Hz)

F20260428075901




BLK: 1,SNR1: 6.5015 ,SNR2: 18.072





Frequency (Hz)


2229-093 2026/04/27 23.01UT TOYOKAWA-FUJI



T20260428075859





No.Good Data




Frequency (Hz)

K20260428075856




No.Good Data





Frequency (Hz)


2229-093 2026/04/27 23.01UT TOYOKAWA-KISO



F20260428075901





BLK: 3,SNR1: 7.1319 ,SNR2: 17.203






2229-093 2026/04/27 23.01UT FUJI -KISO

K20260428075856





BLK: 3,SNR1: 9.0132 ,SNR2: 23.190







BLK: 3,SNR1: 19.863 ,SNR2: 24.935




BLK: 3,SNR1: 3.7274 ,SNR2: 14.044





2238-113 2026/04/27 23.15UT TOYOKAWA-FUJI







BLK: 8, SNR1: 7.8549 ,SNR2: 13.924





BLK: 8, SNR1: 3.8276 ,SNR2: 11.739




2238-113 2026/04/27 23.15UT TOYOKAWA-KISO



F20260428080728





BLK: 1,SNR1: 8.2609 ,SNR2: 14.835




Frequency (Hz)

2238-113 2026/04/27 23.15UT FUJI -KISO


K20260428080723





BLK: 1,SNR1: 15.694 ,SNR2: 28.484




Frequency (Hz)



T20260428082015





BLK: 1, SNR1: 0.31575 , SNR2: 4.6752





3C454.3 2026/04/27 23.37UT TOYOKAWA-FUJI



F20260428082017




BLK: 1, SNR1: 5.7803 , SNR2: 18.397




T20260428082015




BLK: 3,SNR1: 0.28226 ,SNR2: 3.8628




K20260428082012




BLK: 3,SNR1: 8.0376 ,SNR2: 20.122




3C454.3 2026/04/27 23.37UT TOYOKAWA-KISO



F20260428082017





BLK: 1,SNR1: 3.3551 ,SNR2: 11.913





3C454.3 2026/04/27 23.37UT FUJI -KISO



K20260428082012




BLK: 1,SNR1: 2.1293 ,SNR2: 11.369



T20260428082757





BLK: 3,SNR1: 16.514 ,SNR2: 28.963




Frequency (Hz)

F20260428082759




BLK: 3,SNR1: 8.6915 ,SNR2: 21.562





Frequency (Hz)


2259+481 2026/04/27 23.49UT TOYOKAWA-FUJI





T20260428082757




No. Good Data




K20260428082754





No. Good Data




2259+481 2026/04/27 23.49UT TOYOKAWA-KISO



F20260428082759





BLK: 2, SNR1: 3.1036 ,SNR2: 13.655




Frequency (Hz)

K20260428082754




BLK: 2, SNR1: 14.981 ,SNR2: 26.732




Frequency (Hz)


2259+481 2026/04/27 23.49UT FUJI -KISO



T20260428084251




BLK: 6,SNR1: 9.3764 ,SNR2: 16.788





3C459 2026/04/27 23.74UT TOYOKAWA-FUJI


F20260428084253




BLK: 6,SNR1: 1.0837 ,SNR2: 4.3143



T20260428084251





BLK:10,SNR1: 2.0257 ,SNR2: 6.8674





3C459 2026/04/27 23.74UT TOYOKAWA-KISO


K20260428084248




BLK:10,SNR1: 8.7592 ,SNR2: 15.684



F20260428084253





BLK: 7,SNR1: 3.5333 ,SNR2: 8.6067





3C459 2026/04/27 23.74UT FUJI -KISO


K20260428084248




BLK: 7,SNR1: 2.4583 ,SNR2: 7.9329




T20260428091636




BLK:13,SNR1: 2.1988 ,SNR2: 5.4060




F20260428091638




BLK:13,SNR1: 7.1410 ,SNR2: 16.672




2347-02 2026/04/28 0.30UT TOYOKAWA-FUJI



T20260428091636




BLK:10,SNR1: 1.7976 ,SNR2: 4.6192





2347-02 2026/04/28 0.30UT TOYOKAWA-KISO


K20260428091634




BLK:10,SNR1: 8.6002 ,SNR2: 20.917





F20260428091638




BLK:10,SNR1: 8.4115 ,SNR2: 15.056




K20260428091634





BLK:10,SNR1: 12.465 ,SNR2: 22.010




2347-02 2026/04/28 0.30UT FUJI -KISO





T20260428092329




No. Good Data




F20260428092331




No. Good Data




2354+14 2026/04/28 0.42UT TOYOKAWA-FUJI



T20260428092329




BLK: 3,SNR1: 7.4102 ,SNR2: 13.046





2354+14 2026/04/28 0.42UT TOYOKAWA-KISO


K20260428092326




BLK: 3,SNR1: 29.142 ,SNR2: 31.135





F20260428092331




No. Good Data




K20260428092326




No. Good Data




2354+14 2026/04/28 0.42UT FUJI -KISO



T20260428093232




BLK: 6, SNR1: 14.151 , SNR2: 33.639





3C2 2026/04/28 0.57UT TOYOKAWA-FUJI


F20260428093234




BLK: 6, SNR1: 6.7944 , SNR2: 19.065



T20260428093232





BLK: 2, SNR1: 15.541 , SNR2: 36.476





3C2 2026/04/28 0.57UT TOYOKAWA-KISO


K20260428093229




BLK: 2, SNR1: 12.309 , SNR2: 31.072



F20260428093234




BLK: 3,SNR1: 9.5575 ,SNR2: 23.675





3C2 2026/04/28 0.57UT FUJI -KISO



K20260428093229




BLK: 3,SNR1: 14.602 ,SNR2: 35.330



T20260428093954





BLK: 4,SNR1:-0.27132E-01,SNR2: 0.49410





0011+344 2026/04/28 0.69UT TOYOKAWA-FUJI



F20260428093956




BLK: 4,SNR1: 6.0806 ,SNR2: 15.285



T20260428093954





BLK: 5,SNR1: 0.20970 ,SNR2: 0.85056





0011+344 2026/04/28 0.69UT TOYOKAWA-KISO


K20260428093952




BLK: 5,SNR1: 2.8945 ,SNR2: 9.3141



F20260428093956





BLK: 6,SNR1: 3.7004 ,SNR2: 9.1011





0011+344 2026/04/28 0.69UT FUJI -KISO



K20260428093952




BLK: 6,SNR1: 4.3529 ,SNR2: 11.282



T20260428094831





No. Good Data




Frequency (Hz)

F20260428094833




No. Good Data





Frequency (Hz)


0019-00 2026/04/28 0.84UT TOYOKAWA-FUJI



T20260428094831





No. Good Data




Frequency (Hz)

K20260428094828




No. Good Data





Frequency (Hz)


0019-00 2026/04/28 0.84UT TOYOKAWA-KISO




F20260428094833




BLK: 3, SNR1: 3.6804 , SNR2: 10.549




K20260428094828





BLK: 3, SNR1: 20.778 , SNR2: 32.452




0019-00 2026/04/28 0.84UT FUJI -KISO




T20260428095845




BLK: 2, SNR1: 1.9007 ,SNR2: 6.7277




F20260428095847





BLK: 2, SNR1: 6.0611 ,SNR2: 15.145




3C12 2026/04/28 1.01UT TOYOKAWA-FUJI



T20260428095845





BLK: 1,SNR1: 1.2837 ,SNR2: 7.6288





3C12 2026/04/28 1.01UT TOYOKAWA-KISO



K20260428095842




BLK: 1,SNR1: 9.1777 ,SNR2: 22.643





F20260428095847




BLK: 3,SNR1: 10.538 ,SNR2: 24.557




K20260428095842




BLK: 3,SNR1: 9.6521 ,SNR2: 23.699




3C12 2026/04/28 1.01UT FUJI -KISO




T20260428101247




BLK:11,SNR1: 15.641 ,SNR2: 38.487




F20260428101249




BLK:11,SNR1: 8.7318 ,SNR2: 21.845




0044-056 2026/04/28 1.24UT TOYOKAWA-FUJI



T20260428101247




BLK: 4,SNR1: 14.917 ,SNR2: 24.618





0044-056 2026/04/28 1.24UT TOYOKAWA-KISO


K20260428101245




BLK: 4,SNR1: 8.4112 ,SNR2: 21.022




F20260428101249




BLK: 1,SNR1: 1.6133 ,SNR2: 7.9892




K20260428101245




BLK: 1,SNR1: 16.081 ,SNR2: 22.503




0044-056 2026/04/28 1.24UT FUJI -KISO



T20260428102008





BLK: 9,SNR1: 11.870 ,SNR2: 28.802





3C26 2026/04/28 1.36UT TOYOKAWA-FUJI


F20260428102010




BLK: 9,SNR1: 13.922 ,SNR2: 32.738



T20260428102008





BLK: 6,SNR1: 13.079 ,SNR2: 31.316





3C26 2026/04/28 1.36UT TOYOKAWA-KISO



K20260428102005




BLK: 6,SNR1: 11.446 ,SNR2: 26.750



F20260428102010





BLK:10,SNR1: 7.0413 ,SNR2: 19.449





3C26 2026/04/28 1.36UT FUJI -KISO


K20260428102005




BLK:10,SNR1: 9.8559 ,SNR2: 24.333




T20260428102507




BLK: 8,SNR1: 1.9234 ,SNR2: 3.6727




F20260428102509




BLK: 8,SNR1: 6.4657 ,SNR2: 16.306




0056-00 2026/04/28 1.45UT TOYOKAWA-FUJI





T20260428102507




BLK: 7, SNR1: 1.9792 ,SNR2: 5.1806




K20260428102504




BLK: 7, SNR1: 4.8376 ,SNR2: 8.6756




0056-00 2026/04/28 1.45UT TOYOKAWA-KISO





F20260428102509




BLK: 7,SNR1: 0.25968 ,SNR2: 2.9549




K20260428102504





BLK: 7,SNR1: 0.13761 ,SNR2: 4.5370




0056-00 2026/04/28 1.45UT FUJI -KISO



T20260428103449




BLK: 3,SNR1: 0.96806 ,SNR2: 13.942




0106+01 2026/04/28 1.61UT TOYOKAWA-FUJI


F20260428103451





BLK: 3,SNR1: 3.0284 ,SNR2: 12.693




Frequency (Hz)




T20260428103449




BLK: 1,SNR1: 0.25996E-01,SNR2: 1.9434




K20260428103446




BLK: 1,SNR1: 0.52956E-01,SNR2: 1.5473




0106+01 2026/04/28 1.61UT TOYOKAWA-KISO



F20260428103451




BLK: 1,SNR1: 6.1525 ,SNR2: 43.854





0106+01 2026/04/28 1.61UT FUJI -KISO



K20260428103446




BLK: 1,SNR1: 17.884 ,SNR2: 31.466




T20260428104539




BLK: 2,SNR1: 0.38107 ,SNR2: 7.9218




F20260428104541





BLK: 2,SNR1: 3.3765 ,SNR2: 8.6980




0116+31 2026/04/28 1.79UT TOYOKAWA-FUJI



T20260428104539




BLK: 6,SNR1: 0.62453 ,SNR2: 3.3407





0116+31 2026/04/28 1.79UT TOYOKAWA-KISO


K20260428104536




BLK: 6,SNR1: 7.6300 ,SNR2: 14.006



F20260428104541




BLK: 2,SNR1: 1.9674 ,SNR2: 12.294





0116+31 2026/04/28 1.79UT FUJI -KISO


K20260428104536




BLK: 2,SNR1: 8.7275 ,SNR2: 21.831



T20260428105602





BLK: 6,SNR1: 6.4429 ,SNR2: 14.420





3C43 2026/04/28 1.96UT TOYOKAWA-FUJI


F20260428105604




BLK: 6,SNR1: 7.1250 ,SNR2: 16.467



T20260428105602




BLK: 4,SNR1: 5.6834 ,SNR2: 12.753





3C43 2026/04/28 1.96UT TOYOKAWA-KISO



K20260428105559




BLK: 4,SNR1: 4.9305 ,SNR2: 12.128



F20260428105604




BLK: 2,SNR1: 15.021 ,SNR2: 26.541





3C43 2026/04/28 1.96UT FUJI -KISO


K20260428105559




BLK: 2,SNR1: 8.5283 ,SNR2: 20.460



T20260428110346




BLK:26,SNR1: 18.152 ,SNR2: 48.448





3C48 2026/04/28 2.09UT TOYOKAWA-FUJI


F20260428110348




BLK:26,SNR1: 2.5244 ,SNR2: 7.6621





T20260428110346




BLK:29,SNR1: 16.929 ,SNR2: 44.623




K20260428110343




BLK:29,SNR1: 81.201 ,SNR2: 120.31




3C48 2026/04/28 2.09UT TOYOKAWA-KISO



F20260428110348





BLK:13,SNR1: 1.9141 ,SNR2: 6.0965





3C48 2026/04/28 2.09UT FUJI -KISO


K20260428110343




BLK:13,SNR1: 83.467 ,SNR2: 123.67



T20260428112330




BLK: 6,SNR1: 10.235 ,SNR2: 25.042





0155-109 2026/04/28 2.42UT TOYOKAWA-FUJI


F20260428112332




BLK: 6,SNR1: 16.603 ,SNR2: 29.185





T20260428112330




BLK: 6,SNR1: 15.872 ,SNR2: 27.731




K20260428112327




BLK: 6,SNR1: 10.363 ,SNR2: 23.784




0155-109 2026/04/28 2.42UT TOYOKAWA-KISO





F20260428112332




BLK: 9,SNR1: 23.336 ,SNR2: 49.713




K20260428112327




BLK: 9,SNR1: 19.151 ,SNR2: 34.189




0155-109 2026/04/28 2.42UT FUJI -KISO




T20260428113037




BLK:18,SNR1: 31.245 ,SNR2: 67.406




F20260428113039




BLK:18,SNR1: 3.9822 ,SNR2: 15.264




0202+15 2026/04/28 2.54UT TOYOKAWA-FUJI




T20260428113037




BLK:28,SNR1: 23.321 ,SNR2: 50.923




K20260428113034




BLK:28,SNR1: 4.8579 ,SNR2: 18.495




0202+15 2026/04/28 2.54UT TOYOKAWA-KISO




F20260428113039




BLK:26,SNR1: 7.4722 ,SNR2: 14.673




K20260428113034




BLK:26,SNR1: 13.436 ,SNR2: 16.429




0202+15 2026/04/28 2.54UT FUJI -KISO




T20260428114228




BLK:13,SNR1: 3.5824 ,SNR2: 16.274




F20260428114230




BLK:13,SNR1: 3.5023 ,SNR2: 8.8422




0213+178 2026/04/28 2.74UT TOYOKAWA-FUJI




T20260428114228




BLK:16,SNR1: 6.5359 ,SNR2: 13.018




K20260428114225




BLK:16,SNR1: 2.4656 ,SNR2: 4.7973




0213+178 2026/04/28 2.74UT TOYOKAWA-KISO




F20260428114230




BLK:10,SNR1: 6.1392 ,SNR2: 15.263




K20260428114225





BLK:10,SNR1: 1.8538 ,SNR2: 5.1578




0213+178 2026/04/28 2.74UT FUJI -KISO



T20260428115010





BLK: 1,SNR1: 1.9381 ,SNR2: 5.5781





3C67 2026/04/28 2.86UT TOYOKAWA-FUJI


F20260428115012




BLK: 1,SNR1: 19.115 ,SNR2: 33.892



T20260428115010




BLK: 4,SNR1: 12.164 ,SNR2: 29.783





3C67 2026/04/28 2.86UT TOYOKAWA-KISO



K20260428115007




BLK: 4,SNR1: 13.089 ,SNR2: 31.524



F20260428115012





BLK: 2,SNR1: 17.013 ,SNR2: 31.326





3C67 2026/04/28 2.86UT FUJI -KISO



K20260428115007




BLK: 2,SNR1: 18.707 ,SNR2: 35.383





T20260428120825




No.Good Data




F20260428120827





No.Good Data




3C71 2026/04/28 3.17UT TOYOKAWA-FUJI



T20260428120825





No. Good Data




Frequency (Hz)

K20260428120823




No. Good Data




Frequency (Hz)


3C71 2026/04/28 3.17UT TOYOKAWA-KISO



F20260428120827




BLK: 5,SNR1: 16.191 ,SNR2: 28.535





3C71 2026/04/28 3.17UT FUJI -KISO



K20260428120823




BLK: 5,SNR1: 16.868 ,SNR2: 29.987




T20260428122741




BLK: 2,SNR1: 0.25336 ,SNR2: 1.9510




F20260428122743




BLK: 2,SNR1: 0.85830 ,SNR2: 7.1075




0258+350 2026/04/28 3.49UT TOYOKAWA-FUJI




T20260428122741




BLK: 3,SNR1: 0.29384 ,SNR2: 1.7728




K20260428122738




BLK: 3,SNR1: 6.6769 ,SNR2: 12.025




0258+350 2026/04/28 3.49UT TOYOKAWA-KISO




F20260428122743




BLK: 2,SNR1: 1.4380 ,SNR2: 7.4924




K20260428122738





BLK: 2,SNR1: 0.81169 ,SNR2: 4.4489




0258+350 2026/04/28 3.49UT FUJI -KISO





T20260428123730




No.Good Data




F20260428123732




No.Good Data




0308+305 2026/04/28 3.65UT TOYOKAWA-FUJI





T20260428123730




BLK: 2,SNR1: 1.9210 ,SNR2: 3.5370




K20260428123727





BLK: 2,SNR1: 16.399 ,SNR2: 100.86




0308+305 2026/04/28 3.65UT TOYOKAWA-KISO





F20260428123732




BLK: 4,SNR1: 5.6203 ,SNR2: 13.802




K20260428123727





BLK: 4,SNR1: 23.219 ,SNR2: 45.798




0308+305 2026/04/28 3.65UT FUJI -KISO




T20260428124901




BLK:17,SNR1: 2.2885 ,SNR2: 10.789




F20260428124903





BLK:17,SNR1:-0.13118 ,SNR2: 1.0853




0320+05 2026/04/28 3.85UT TOYOKAWA-FUJI



T20260428124901




No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0320+05 2026/04/28 3.85UT TOYOKAWA-KISO



F20260428124903





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0320+05 2026/04/28 3.85UT FUJI -KISO





T20260428130223




No.Good Data




F20260428130225





No.Good Data




0333+32 2026/04/28 4.07UT TOYOKAWA-FUJI



T20260428130223





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0333+32 2026/04/28 4.07UT TOYOKAWA-KISO



F20260428130225





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


0333+32 2026/04/28 4.07UT FUJI -KISO





T20260428131523




BLK: 6,SNR1: 8.8858 ,SNR2: 21.553




F20260428131525




BLK: 6,SNR1: 8.4936 ,SNR2: 20.405




0347+05 2026/04/28 4.28UT TOYOKAWA-FUJI



T20260428131523





No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




0347+05 2026/04/28 4.28UT TOYOKAWA-KISO




F20260428131525





KISO




0347+05 2026/04/28 4.28UT FUJI -KISO





T20260428133057




No.Good Data




F20260428133059





No.Good Data




0403-132 2026/04/28 4.54UT TOYOKAWA-FUJI



T20260428133057





No.Good Data




Frequency (Hz)

K20260428133054




No.Good Data




Frequency (Hz)


0403-132 2026/04/28 4.54UT TOYOKAWA-KISO





F20260428133059




BLK: 1,SNR1: 0.79991 ,SNR2: 4.9488




K20260428133054





BLK: 1,SNR1: 7.8589 ,SNR2: 17.595




0403-132 2026/04/28 4.54UT FUJI -KISO





T20260428134008




BLK: 7,SNR1: 8.6608 ,SNR2: 21.505




F20260428134010




BLK: 7,SNR1: 7.4954 ,SNR2: 18.712




0411+05 2026/04/28 4.70UT TOYOKAWA-FUJI





T20260428134008




BLK: 9,SNR1: 11.668 ,SNR2: 27.630




K20260428134005





BLK: 9,SNR1: 8.2509 ,SNR2: 20.337




0411+05 2026/04/28 4.70UT TOYOKAWA-KISO





F20260428134010




BLK: 3,SNR1: 8.2794 ,SNR2: 20.413




K20260428134005




BLK: 3,SNR1: 8.1531 ,SNR2: 20.145




0411+05 2026/04/28 4.70UT FUJI -KISO




T20260428135102




BLK: 9,SNR1: 7.7283 ,SNR2: 13.698




F20260428135104




BLK: 9,SNR1: 9.5537 ,SNR2: 16.751




0422+178 2026/04/28 4.88UT TOYOKAWA-FUJI




T20260428135102




BLK:13,SNR1: 9.1475 ,SNR2: 16.614




K20260428135059





BLK:13,SNR1: 6.0778 ,SNR2: 15.292




0422+178 2026/04/28 4.88UT TOYOKAWA-KISO




F20260428135104




BLK: 9,SNR1: 7.8885 ,SNR2: 14.042




K20260428135059





BLK: 9,SNR1: 10.567 ,SNR2: 18.740




0422+178 2026/04/28 4.88UT FUJI -KISO





T20260428135837




BLK: 1,SNR1: 101.86 ,SNR2: 526.12




F20260428135839





BLK: 1,SNR1: 0.23284E-01,SNR2: 2.4247




3C120 2026/04/28 5.01UT TOYOKAWA-FUJI





T20260428135837




BLK: 2,SNR1: 53.772 ,SNR2: 401.14




K20260428135834





BLK: 2,SNR1: 9.1968 ,SNR2: 16.728




3C120 2026/04/28 5.01UT TOYOKAWA-KISO





F20260428135839




BLK: 1,SNR1: 0.73830E-01,SNR2: 5.6861




K20260428135834





BLK: 1,SNR1: 0.44483 ,SNR2: 5.4773




3C120 2026/04/28 5.01UT FUJI -KISO




T20260428144638




BLK: 2,SNR1: 11.086 ,SNR2: 26.855




F20260428144640





BLK: 2,SNR1: 10.293 ,SNR2: 25.239




3C138 2026/04/28 5.81UT TOYOKAWA-FUJI





T20260428144638




BLK: 3,SNR1: 11.105 ,SNR2: 27.242




K20260428144635




BLK: 3,SNR1: 8.9668 ,SNR2: 22.474




3C138 2026/04/28 5.81UT TOYOKAWA-KISO





F20260428144640




BLK: 2,SNR1: 8.9286 ,SNR2: 22.280




K20260428144635





BLK: 2,SNR1: 17.931 ,SNR2: 31.608




3C138 2026/04/28 5.81UT FUJI -KISO




T20260428150011




BLK:13,SNR1: 4.9916 ,SNR2: 18.761




F20260428150013





BLK:13,SNR1: 0.94102 ,SNR2: 4.6833




0531+194 2026/04/28 6.03UT TOYOKAWA-FUJI





T20260428150011




BLK:10,SNR1: 4.9981 ,SNR2: 18.785




K20260428150008





BLK:10,SNR1: 0.99269 ,SNR2: 4.1311




0531+194 2026/04/28 6.03UT TOYOKAWA-KISO



F20260428150013





BLK: 3,SNR1: 0.32419 ,SNR2: 6.6212




Frequency (Hz)

K20260428150008




BLK: 3,SNR1: 2.2335 ,SNR2: 4.7595




Frequency (Hz)


0531+194 2026/04/28 6.03UT FUJI -KISO



T20260428150833




BLK:10,SNR1: 5.6124 ,SNR2: 13.814




Frequency (Hz)

F20260428150835




BLK:10,SNR1: 9.5057 ,SNR2: 22.898




Frequency (Hz)


3C147 2026/04/28 6.17UT TOYOKAWA-FUJI



T20260428150833




BLK:14,SNR1: 3.1446 ,SNR2: 13.106





3C147 2026/04/28 6.17UT TOYOKAWA-KISO


K20260428150830




BLK:14,SNR1: 13.792 ,SNR2: 32.514




F20260428150835




BLK: 4,SNR1: 7.3750 ,SNR2: 18.311




K20260428150830





BLK: 4,SNR1: 8.5850 ,SNR2: 20.980




3C147 2026/04/28 6.17UT FUJI -KISO





T20260428151642




No. Good Data




F20260428151644




No. Good Data




0548+16 2026/04/28 6.31UT TOYOKAWA-FUJI




T20260428151642




BLK: 2,SNR1: 6.8079 ,SNR2: 16.979




K20260428151639




BLK: 2,SNR1: 8.1512 ,SNR2: 15.272




0548+16 2026/04/28 6.31UT TOYOKAWA-KISO




F20260428151644




BLK: 1,SNR1: 32.838 ,SNR2: 49.136




K20260428151639




BLK: 1,SNR1: 14.964 ,SNR2: 36.413




0548+16 2026/04/28 6.31UT FUJI -KISO




T20260428152053




BLK: 6,SNR1: 44.584 ,SNR2: 78.765




F20260428152055





BLK: 6,SNR1: 9.2858 ,SNR2: 23.195




0552+12 2026/04/28 6.38UT TOYOKAWA-FUJI




T20260428152053




BLK: 9,SNR1: 36.292 ,SNR2: 129.66




K20260428152050




BLK: 9,SNR1: 6.4215 ,SNR2: 15.949




0552+12 2026/04/28 6.38UT TOYOKAWA-KISO



F20260428152055




BLK: 4,SNR1: 2.0879 ,SNR2: 5.7286




Frequency (Hz)

K20260428152050




BLK: 4,SNR1: 0.56168 ,SNR2: 2.3591





Frequency (Hz)


0552+12 2026/04/28 6.38UT FUJI -KISO



T20260428152520





BLK: 5,SNR1: 0.86978 ,SNR2: 2.5659




Frequency (Hz)

F20260428152522




BLK: 5,SNR1: 1.8317 ,SNR2: 5.3119





Frequency (Hz)


0556+191 2026/04/28 6.45UT TOYOKAWA-FUJI




T20260428152520




BLK: 6,SNR1: 9.5146 ,SNR2: 23.570




K20260428152517





BLK: 6,SNR1: 0.27445 ,SNR2: 1.7383




0556+191 2026/04/28 6.45UT TOYOKAWA-KISO



F20260428152522





BLK: 9,SNR1: 0.20558 ,SNR2: 2.1916




Frequency (Hz)

K20260428152517




BLK: 9,SNR1: 0.45467 ,SNR2: 1.9889





Frequency (Hz)


0556+191 2026/04/28 6.45UT FUJI -KISO



T20260428152952





BLK: 3,SNR1: 1.8296 ,SNR2: 4.6392




Frequency (Hz)

F20260428152954




BLK: 3,SNR1: 7.4643 ,SNR2: 13.385




Frequency (Hz)


3C152 2026/04/28 6.53UT TOYOKAWA-FUJI



T20260428152952





BLK: 5,SNR1: 5.6043 ,SNR2: 13.563




Frequency (Hz)

K20260428152949




BLK: 5,SNR1: 58.267 ,SNR2: 121.92




Frequency (Hz)


3C152 2026/04/28 6.53UT TOYOKAWA-KISO



F20260428152954





BLK: 6,SNR1: 1.3540 ,SNR2: 5.3124




Frequency (Hz)

K20260428152949




BLK: 6,SNR1: 17.548 ,SNR2: 55.767




Frequency (Hz)


3C152 2026/04/28 6.53UT FUJI -KISO



T20260428155213




BLK: 7,SNR1: 9.7777 ,SNR2: 24.315




Frequency (Hz)

F20260428155215




BLK: 7,SNR1: 13.106 ,SNR2: 31.994




Frequency (Hz)


3C161 2026/04/28 6.90UT TOYOKAWA-FUJI



T20260428155213




BLK: 5,SNR1: 83.349 ,SNR2: 99.518




Frequency (Hz)

K20260428155210




BLK: 5,SNR1: 35.340 ,SNR2: 61.335




Frequency (Hz)


3C161 2026/04/28 6.90UT TOYOKAWA-KISO



F20260428155215




BLK: 7,SNR1: 10.740 ,SNR2: 26.331




Frequency (Hz)

K20260428155210




BLK: 7,SNR1: 26.672 ,SNR2: 47.338




Frequency (Hz)


3C161 2026/04/28 6.90UT FUJI -KISO



T20260428161945




BLK: 8,SNR1: 6.0468 ,SNR2: 19.076




Frequency (Hz)

F20260428161947




BLK: 8,SNR1: 7.5454 ,SNR2: 18.606




Frequency (Hz)


0652-130 2026/04/28 7.36UT TOYOKAWA-FUJI



T20260428161945




BLK:13,SNR1: 6.4454 ,SNR2: 16.259




Frequency (Hz)

K20260428161942




BLK:13,SNR1: 6.4430 ,SNR2: 19.979




Frequency (Hz)


0652-130 2026/04/28 7.36UT TOYOKAWA-KISO



F20260428161947




BLK: 6,SNR1: 6.3131 ,SNR2: 15.928




Frequency (Hz)

K20260428161942




BLK: 6,SNR1: 6.3552 ,SNR2: 16.168




Frequency (Hz)


0652-130 2026/04/28 7.36UT FUJI -KISO



T20260428163123





BLK: 2,SNR1: 11.966 ,SNR2: 29.720




Frequency (Hz)

F20260428163125




BLK: 2,SNR1: 9.4658 ,SNR2: 23.218




Frequency (Hz)


0703+138 2026/04/28 7.55UT TOYOKAWA-FUJI



T20260428163123




BLK: 7,SNR1: 7.2444 ,SNR2: 20.582




Frequency (Hz)

K20260428163120




BLK: 7,SNR1: 9.5831 ,SNR2: 24.393





Frequency (Hz)


0703+138 2026/04/28 7.55UT TOYOKAWA-KISO



F20260428163125




BLK: 3,SNR1: 7.5592 ,SNR2: 20.470




Frequency (Hz)

K20260428163120




BLK: 3,SNR1: 9.4835 ,SNR2: 27.390




Frequency (Hz)


0703+138 2026/04/28 7.55UT FUJI -KISO



T20260428164045




No.Good Data




Frequency (Hz)

F20260428164047




No.Good Data




Frequency (Hz)


0713-024 2026/04/28 7.71UT TOYOKAWA-FUJI



T20260428164045





BLK: 1,SNR1: 3.8326 ,SNR2: 9.6251




Frequency (Hz)

K20260428164042




BLK: 1,SNR1: 8.9051 ,SNR2: 23.630




Frequency (Hz)


0713-024 2026/04/28 7.71UT TOYOKAWA-KISO



F20260428164047





BLK: 3,SNR1: 8.3379 ,SNR2: 25.636




Frequency (Hz)

K20260428164042




BLK: 3,SNR1: 7.3369 ,SNR2: 19.706





Frequency (Hz)


0713-024 2026/04/28 7.71UT FUJI -KISO



T20260428165057




BLK: 4,SNR1: 3.8550 ,SNR2: 9.1764




Frequency (Hz)

F20260428165059




BLK: 4,SNR1: 2.0958 ,SNR2: 4.8223





Frequency (Hz)


0723+10 2026/04/28 7.88UT TOYOKAWA-FUJI



T20260428165057




BLK: 2, SNR1: 9.0849 , SNR2: 16.853




Frequency (Hz)

K20260428165054




BLK: 2, SNR1: 4.3453 , SNR2: 10.151




Frequency (Hz)


0723+10 2026/04/28 7.88UT TOYOKAWA-KISO



F20260428165059




BLK: 3,SNR1: 0.32128 ,SNR2: 2.3883




Frequency (Hz)

K20260428165054




BLK: 3,SNR1: 4.5855 ,SNR2: 15.359





Frequency (Hz)


0723+10 2026/04/28 7.88UT FUJI -KISO



T20260428170112





No.Good Data




Frequency (Hz)

F20260428170114




No.Good Data





Frequency (Hz)


0732+33 2026/04/28 8.05UT TOYOKAWA-FUJI



T20260428170112





BLK: 1,SNR1: 0.54826 ,SNR2: 1.8850




Frequency (Hz)

K20260428170109




BLK: 1,SNR1: 10.951 ,SNR2: 26.818





Frequency (Hz)


0732+33 2026/04/28 8.05UT TOYOKAWA-KISO



F20260428170114





BLK: 1,SNR1: 12.213 ,SNR2: 29.883




Frequency (Hz)

K20260428170109




BLK: 1,SNR1: 11.473 ,SNR2: 28.486





Frequency (Hz)


0732+33 2026/04/28 8.05UT FUJI -KISO



T20260428173859




BLK: 8,SNR1: 0.73255 ,SNR2: 2.1289




Frequency (Hz)

F20260428173901




BLK: 8,SNR1: 17.798 ,SNR2: 33.114





Frequency (Hz)


3C196 2026/04/28 8.68UT TOYOKAWA-FUJI



T20260428173859




BLK: 6,SNR1: 10.345 ,SNR2: 26.137




Frequency (Hz)

K20260428173856




BLK: 6,SNR1: 12.877 ,SNR2: 31.003




Frequency (Hz)


3C196 2026/04/28 8.68UT TOYOKAWA-KISO



F20260428173901




BLK: 6,SNR1: 17.940 ,SNR2: 33.374




Frequency (Hz)

K20260428173856



BLK: 6,SNR1: 6.1767 ,SNR2: 16.267



Frequency (Hz)

3C196 2026/04/28 8.68UT FUJI -KISO

