




T20260506054146




BLK:10,SNR1: 0.73694 ,SNR2: 3.3260




Frequency (Hz)

2045+483 2026/05/05 20.72UT TOYOKAWA-FUJI


F20260506054148





BLK:10,SNR1: 1.8932 ,SNR2: 4.6651




Frequency (Hz)




T20260506054146




BLK: 8,SNR1: 1.2541 ,SNR2: 5.2558




K20260506054143





BLK: 8,SNR1: 0.28493 ,SNR2: 4.3585




2045+483 2026/05/05 20.72UT TOYOKAWA-KISO



F20260506054148





BLK: 9,SNR1: 4.9136 ,SNR2: 8.4376




Frequency (Hz)

K20260506054143




BLK: 9,SNR1: 0.13166 ,SNR2: 3.6861





Frequency (Hz)


2045+483 2026/05/05 20.72UT FUJI -KISO



T20260506055655





BLK: 9,SNR1: 0.88451 ,SNR2: 2.7907




Frequency (Hz)

F20260506055657




BLK: 9,SNR1: 3.7313 ,SNR2: 8.2010





Frequency (Hz)


2059+283 2026/05/05 20.98UT TOYOKAWA-FUJI



T20260506055655





BLK:11,SNR1: 2.2942 ,SNR2: 4.5527




Frequency (Hz)

K20260506055653




BLK:11,SNR1: 9.8127 ,SNR2: 24.252





Frequency (Hz)


2059+283 2026/05/05 20.98UT TOYOKAWA-KISO



F20260506055657





BLK: 2,SNR1: 4.9985 ,SNR2: 10.964




Frequency (Hz)

2059+283 2026/05/05 20.98UT FUJI -KISO


K20260506055653





BLK: 2,SNR1: 10.803 ,SNR2: 23.396




Frequency (Hz)



T20260506060459





BLK: 2,SNR1: 6.6387 ,SNR2: 13.751




Frequency (Hz)

2107+238 2026/05/05 21.11UT TOYOKAWA-FUJI


F20260506060501





BLK: 2,SNR1: 12.435 ,SNR2: 30.067




Frequency (Hz)





T20260506060459




BLK: 1,SNR1: 0.43296 ,SNR2: 3.5676




K20260506060457





BLK: 1,SNR1: 1.1887 ,SNR2: 8.5839




2107+238 2026/05/05 21.11UT TOYOKAWA-KISO





F20260506060501




No.Good Data




K20260506060457





No.Good Data




2107+238 2026/05/05 21.11UT FUJI -KISO



T20260506061748





BLK:23,SNR1: 16.161 ,SNR2: 28.835




Frequency (Hz)

F20260506061750




BLK:23,SNR1: 10.942 ,SNR2: 19.634





Frequency (Hz)


2120+168 2026/05/05 21.32UT TOYOKAWA-FUJI



T20260506061748





BLK:23,SNR1: 8.5802 ,SNR2: 21.727




Frequency (Hz)

K20260506061745




BLK:23,SNR1: 10.300 ,SNR2: 24.234





Frequency (Hz)


2120+168 2026/05/05 21.32UT TOYOKAWA-KISO



F20260506061750





BLK:28,SNR1: 7.5782 ,SNR2: 20.710




Frequency (Hz)

2120+168 2026/05/05 21.32UT FUJI -KISO


K20260506061745





BLK:28,SNR1: 9.4447 ,SNR2: 22.707




Frequency (Hz)



T20260506062844





BLK: 1,SNR1: 2.0396 ,SNR2: 7.0286




Frequency (Hz)

2131+379 2026/05/05 21.51UT TOYOKAWA-FUJI


F20260506062846





BLK: 1,SNR1: 4.4881 ,SNR2: 16.840




Frequency (Hz)



T20260506062844





BLK: 1,SNR1: 3.6420 ,SNR2: 15.358




Frequency (Hz)

2131+379 2026/05/05 21.51UT TOYOKAWA-KISO


K20260506062842





BLK: 1,SNR1: 21.028 ,SNR2: 25.518




Frequency (Hz)



F20260506062846





BLK: 3,SNR1: 3.7321 ,SNR2: 15.432




Frequency (Hz)

K20260506062842




BLK: 3,SNR1: 15.237 ,SNR2: 24.420





Frequency (Hz)


2131+379 2026/05/05 21.51UT FUJI -KISO



T20260506063717





BLK: 6,SNR1: 11.494 ,SNR2: 28.867




Frequency (Hz)

F20260506063719




BLK: 6,SNR1: 3.4622 ,SNR2: 10.971




Frequency (Hz)


2139+028 2026/05/05 21.65UT TOYOKAWA-FUJI



T20260506063717




BLK: 6, SNR1: 12.417 ,SNR2: 29.456




Frequency (Hz)

K20260506063714




BLK: 6, SNR1: 8.6125 ,SNR2: 21.346





Frequency (Hz)


2139+028 2026/05/05 21.65UT TOYOKAWA-KISO





F20260506063719




No.Good Data




K20260506063714




No.Good Data




2139+028 2026/05/05 21.65UT FUJI -KISO



T20260506064523




BLK: 3,SNR1: 7.6080 ,SNR2: 19.252




Frequency (Hz)

F20260506064525




BLK: 3,SNR1: 11.925 ,SNR2: 29.104





Frequency (Hz)


2147+145 2026/05/05 21.78UT TOYOKAWA-FUJI



T20260506064523





BLK: 4,SNR1: 5.3524 ,SNR2: 13.992




Frequency (Hz)

2147+145 2026/05/05 21.78UT TOYOKAWA-KISO


K20260506064520




BLK: 4,SNR1: 10.172 ,SNR2: 25.933




Frequency (Hz)



F20260506064525




BLK:11,SNR1: 10.655 ,SNR2: 25.037




Frequency (Hz)

K20260506064520




BLK:11,SNR1: 11.689 ,SNR2: 27.701





Frequency (Hz)


2147+145 2026/05/05 21.78UT FUJI -KISO



T20260506065428





BLK: 4,SNR1: 1.9545 ,SNR2: 7.7777




Frequency (Hz)

F20260506065430




BLK: 4,SNR1: 9.2331 ,SNR2: 15.085




Frequency (Hz)


2156-043 2026/05/05 21.94UT TOYOKAWA-FUJI



T20260506065428





BLK: 4,SNR1: 2.1430 ,SNR2: 10.231




Frequency (Hz)

K20260506065426




BLK: 4,SNR1: 15.615 ,SNR2: 25.019





Frequency (Hz)


2156-043 2026/05/05 21.94UT TOYOKAWA-KISO





F20260506065430




BLK: 4,SNR1: 11.275 ,SNR2: 18.489




K20260506065426





BLK: 4,SNR1: 3.1295 ,SNR2: 11.680




2156-043 2026/05/05 21.94UT FUJI -KISO




T20260506070116




BLK: 1,SNR1: 0.63932 ,SNR2: 2.4197




F20260506070118





BLK: 1,SNR1: 1.4322 ,SNR2: 6.4257




2203-18 2026/05/05 22.05UT TOYOKAWA-FUJI



T20260506070116




BLK: 4,SNR1: 3.7688 ,SNR2: 14.743




Frequency (Hz)

K20260506070114




BLK: 4,SNR1: 7.9109 ,SNR2: 20.464




Frequency (Hz)


2203-18 2026/05/05 22.05UT TOYOKAWA-KISO



F20260506070118




BLK: 5,SNR1: 1.7118 ,SNR2: 5.8920




Frequency (Hz)

K20260506070114




BLK: 5,SNR1: 7.5048 ,SNR2: 19.412





Frequency (Hz)


2203-18 2026/05/05 22.05UT FUJI -KISO



T20260506070738





BLK:29,SNR1: 8.5624 ,SNR2: 21.678




Frequency (Hz)

2210+016 2026/05/05 22.16UT TOYOKAWA-FUJI


F20260506070740





BLK:29,SNR1: 7.8303 ,SNR2: 20.028




Frequency (Hz)



T20260506070738





BLK:34,SNR1: 8.5411 ,SNR2: 21.625




Frequency (Hz)

2210+016 2026/05/05 22.16UT TOYOKAWA-KISO


K20260506070735





BLK:34,SNR1: 7.4998 ,SNR2: 19.199




Frequency (Hz)



F20260506070740





BLK:25,SNR1: 7.9188 ,SNR2: 20.252




Frequency (Hz)

K20260506070735




BLK:25,SNR1: 7.6055 ,SNR2: 19.462




Frequency (Hz)


2210+016 2026/05/05 22.16UT FUJI -KISO



T20260506071501





BLK: 2,SNR1: 0.65215 ,SNR2: 3.0603




Frequency (Hz)

F20260506071503




BLK: 2,SNR1: 7.7487 ,SNR2: 19.307




Frequency (Hz)


2217+128 2026/05/05 22.28UT TOYOKAWA-FUJI





T20260506071501




BLK: 6,SNR1: 1.6667 ,SNR2: 4.1503




K20260506071458




BLK: 6,SNR1: 9.6022 ,SNR2: 23.709




2217+128 2026/05/05 22.28UT TOYOKAWA-KISO



F20260506071503




BLK: 2, SNR1: 2.8852 , SNR2: 13.581





2217+128 2026/05/05 22.28UT FUJI -KISO



K20260506071458




BLK: 2, SNR1: 15.254 , SNR2: 26.959



T20260506072048





BLK:21,SNR1: 9.2948 ,SNR2: 22.923




Frequency (Hz)

3C446 2026/05/05 22.37UT TOYOKAWA-FUJI


F20260506072050





BLK:21,SNR1: 11.966 ,SNR2: 21.239




Frequency (Hz)



T20260506072048





BLK:22,SNR1: 2.8738 ,SNR2: 13.092




Frequency (Hz)

3C446 2026/05/05 22.37UT TOYOKAWA-KISO


K20260506072045





BLK:22,SNR1: 2.6620 ,SNR2: 12.815




Frequency (Hz)



F20260506072050





BLK:21,SNR1: 12.205 ,SNR2: 21.648





3C446 2026/05/05 22.37UT FUJI -KISO



K20260506072045




BLK:21,SNR1: 15.021 ,SNR2: 26.646



T20260506072732




BLK: 2,SNR1: 10.336 ,SNR2: 18.609





2229-093 2026/05/05 22.49UT TOYOKAWA-FUJI



F20260506072734




BLK: 2,SNR1: 2.4749 ,SNR2: 8.1781





T20260506072732




No.Good Data




K20260506072730




No.Good Data




2229-093 2026/05/05 22.49UT TOYOKAWA-KISO




F20260506072734




BLK: 1,SNR1: 5.2665 ,SNR2: 15.745




K20260506072730





BLK: 1,SNR1: 9.9921 ,SNR2: 25.172




2229-093 2026/05/05 22.49UT FUJI -KISO



T20260506073559





BLK:10,SNR1: 2.2842 ,SNR2: 7.6388




Frequency (Hz)

F20260506073601




BLK:10,SNR1:-0.28244 ,SNR2: 0.73589E-03





Frequency (Hz)


2238-113 2026/05/05 22.63UT TOYOKAWA-FUJI



T20260506073559





BLK:16,SNR1: 3.3706 ,SNR2: 8.6141




Frequency (Hz)

K20260506073557




BLK:16,SNR1: 0.92582 ,SNR2: 2.5812





Frequency (Hz)


2238-113 2026/05/05 22.63UT TOYOKAWA-KISO



F20260506073601





BLK:12,SNR1: 0.18316 ,SNR2: 1.5828




Frequency (Hz)

K20260506073557




BLK:12,SNR1: 1.7250 ,SNR2: 3.9238




Frequency (Hz)


2238-113 2026/05/05 22.63UT FUJI -KISO




T20260506074848




BLK: 6,SNR1: 2.1887 ,SNR2: 4.9850




F20260506074850




BLK: 6,SNR1: 1.8257 ,SNR2: 6.1271




3C454.3 2026/05/05 22.84UT TOYOKAWA-FUJI



T20260506074848





BLK:12,SNR1: 0.74884 ,SNR2: 2.7202





3C454.3 2026/05/05 22.84UT TOYOKAWA-KISO


K20260506074846




BLK:12,SNR1: 9.0088 ,SNR2: 15.796



F20260506074850





BLK: 4,SNR1: 9.1318 ,SNR2: 14.055









3C454.3 2026/05/05 22.84UT FUJI -KISO

K20260506074846








BLK: 4,SNR1: 8.2655 ,SNR2: 21.408






2259+481 2026/05/05 22.97UT TOYOKAWA-FUJI







2259+481 2026/05/05 22.97UT TOYOKAWA-KISO





F20260506075632




BLK: 1,SNR1: 5.9727 ,SNR2: 10.765




K20260506075628




BLK: 1,SNR1: 0.43721 ,SNR2: 2.7844




2259+481 2026/05/05 22.97UT FUJI -KISO



T20260506081124




BLK:13,SNR1: 8.7764 ,SNR2: 42.397




Frequency (Hz)

3C459 2026/05/05 23.22UT TOYOKAWA-FUJI


F20260506081126





BLK:13,SNR1: 0.24976 ,SNR2: 2.8936




Frequency (Hz)



T20260506081124





BLK:14,SNR1: 9.0058 ,SNR2: 22.746




Frequency (Hz)

3C459 2026/05/05 23.22UT TOYOKAWA-KISO


K20260506081121




BLK:14,SNR1: 10.290 ,SNR2: 16.635




Frequency (Hz)





F20260506081126




BLK: 3,SNR1: 0.22050 ,SNR2: 1.8911




K20260506081121




BLK: 3,SNR1: 2.4939 ,SNR2: 6.9923




3C459 2026/05/05 23.22UT FUJI -KISO



T20260506084509




BLK: 1, SNR1: 14.027 ,SNR2: 33.356





2347-02 2026/05/05 23.78UT TOYOKAWA-FUJI


F20260506084511




BLK: 1, SNR1: 19.762 ,SNR2: 36.651



T20260506084509




BLK: 4,SNR1: 21.291 ,SNR2: 37.737





2347-02 2026/05/05 23.78UT TOYOKAWA-KISO


K20260506084506




BLK: 4,SNR1: 20.702 ,SNR2: 37.364



F20260506084511




BLK: 2,SNR1: 15.291 ,SNR2: 34.261





2347-02 2026/05/05 23.78UT FUJI -KISO


K20260506084506




BLK: 2,SNR1: 11.015 ,SNR2: 27.042



T20260506085202





BLK: 4,SNR1: 0.92463 ,SNR2: 4.2720





2354+14 2026/05/05 23.90UT TOYOKAWA-FUJI



F20260506085204




BLK: 4,SNR1: 9.2216 ,SNR2: 21.373





T20260506085202




No. Good Data




K20260506085159




No. Good Data




2354+14 2026/05/05 23.90UT TOYOKAWA-KISO



F20260506085204




BLK: 7,SNR1: 11.612 ,SNR2: 28.417





2354+14 2026/05/05 23.90UT FUJI -KISO


K20260506085159




BLK: 7,SNR1: 9.2781 ,SNR2: 22.801



T20260506090105





BLK: 5, SNR1: 2.9528 ,SNR2: 11.076





3C2 2026/05/06 0.05UT TOYOKAWA-FUJI



F20260506090107




BLK: 5, SNR1: 12.455 ,SNR2: 23.049



T20260506090105





BLK: 9,SNR1: 0.47739E-01,SNR2: 1.5406





3C2 2026/05/06 0.05UT TOYOKAWA-KISO


K20260506090102




BLK: 9,SNR1: 10.305 ,SNR2: 24.863



F20260506090107





BLK: 2, SNR1: 3.9166 , SNR2: 10.756





3C2 2026/05/06 0.05UT FUJI -KISO


K20260506090102




BLK: 2, SNR1: 6.7516 , SNR2: 11.592



T20260506090827




BLK:10,SNR1: 11.097 ,SNR2: 24.236





0011+344 2026/05/06 0.17UT TOYOKAWA-FUJI


F20260506090829




BLK:10,SNR1: 10.149 ,SNR2: 24.856



T20260506090827





BLK: 9,SNR1: 10.287 ,SNR2: 21.781





0011+344 2026/05/06 0.17UT TOYOKAWA-KISO


K20260506090824




BLK: 9,SNR1: 9.2412 ,SNR2: 16.199




F20260506090829




BLK:11,SNR1: 14.968 ,SNR2: 26.919




K20260506090824




BLK:11,SNR1: 14.613 ,SNR2: 33.949




0011+344 2026/05/06 0.17UT FUJI -KISO



T20260506091704





BLK: 1,SNR1:-0.46736E-01,SNR2: 0.37126





0019-00 2026/05/06 0.31UT TOYOKAWA-FUJI


F20260506091706




BLK: 1,SNR1: 0.80841 ,SNR2: 3.7097



T20260506091704




BLK: 2,SNR1:-0.78000E-01,SNR2: 0.58544E-01





0019-00 2026/05/06 0.31UT TOYOKAWA-KISO



K20260506091701




BLK: 2,SNR1: 0.78667E-01,SNR2: 1.8756




F20260506091706




BLK: 9,SNR1: 0.12279E-01,SNR2: 0.70395




K20260506091701




BLK: 9,SNR1: 0.49523 ,SNR2: 1.6215




0019-00 2026/05/06 0.31UT FUJI -KISO





T20260506092718




BLK:10,SNR1: 10.557 ,SNR2: 17.197




F20260506092720




BLK:10,SNR1: 10.584 ,SNR2: 24.327




3C12 2026/05/06 0.48UT TOYOKAWA-FUJI



T20260506092718





BLK: 9, SNR1: 9.9781 , SNR2: 17.801





3C12 2026/05/06 0.48UT TOYOKAWA-KISO



K20260506092715




BLK: 9, SNR1: 9.8967 , SNR2: 17.373



F20260506092720





BLK:12,SNR1: 8.5106 ,SNR2: 20.260




Frequency (Hz)

3C12 2026/05/06 0.48UT FUJI -KISO


K20260506092715




BLK:12,SNR1: 13.396 ,SNR2: 23.088




Frequency (Hz)




T20260506094120




BLK: 9,SNR1: 6.1089 ,SNR2: 34.785




F20260506094122





BLK: 9,SNR1: 5.6352 ,SNR2: 10.254




0044-056 2026/05/06 0.72UT TOYOKAWA-FUJI



T20260506094120





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0044-056 2026/05/06 0.72UT TOYOKAWA-KISO





F20260506094122




No.Good Data




KISO




No.Good Data




0044-056 2026/05/06 0.72UT FUJI -KISO



T20260506094841




BLK: 1,SNR1: 11.139 ,SNR2: 27.663





3C26 2026/05/06 0.84UT TOYOKAWA-FUJI



F20260506094843




BLK: 1,SNR1: 3.6936 ,SNR2: 16.214



T20260506094841





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C26 2026/05/06 0.84UT TOYOKAWA-KISO





F20260506094843




No.Good Data




KISO





No.Good Data




3C26 2026/05/06 0.84UT FUJI -KISO



T20260506095339




BLK: 3,SNR1: 0.56810 ,SNR2: 4.1880




0056-00 2026/05/06 0.92UT TOYOKAWA-FUJI


F20260506095341





BLK: 3,SNR1: 0.45646 ,SNR2: 2.9132




Frequency (Hz)



T20260506095339





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0056-00 2026/05/06 0.92UT TOYOKAWA-KISO



F20260506095341





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0056-00 2026/05/06 0.92UT FUJI -KISO




T20260506100322




BLK: 1,SNR1: 8.5482 ,SNR2: 27.072




F20260506100324





BLK: 1,SNR1: 2.2139 ,SNR2: 9.1473




0106+01 2026/05/06 1.08UT TOYOKAWA-FUJI



T20260506100322





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0106+01 2026/05/06 1.08UT TOYOKAWA-KISO



F20260506100324





No.Good Data




Frequency (Hz)

KISO





No.Good Data





Frequency (Hz)

0106+01 2026/05/06 1.08UT FUJI -KISO







BLK: 4, SNR1: 0.11369 , SNR2: 0.55642





BLK: 4, SNR1: 0.78040 , SNR2: 3.4793




0116+31 2026/05/06 1.26UT TOYOKAWA-FUJI



T20260506101412





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0116+31 2026/05/06 1.26UT TOYOKAWA-KISO



F20260506101414





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0116+31 2026/05/06 1.26UT FUJI -KISO



T20260506102434





BLK: 6,SNR1: 4.7526 ,SNR2: 11.930





3C43 2026/05/06 1.44UT TOYOKAWA-FUJI



F20260506102436




BLK: 6,SNR1: 9.9578 ,SNR2: 17.910





T20260506102434




BLK: 2,SNR1: 1.3448 ,SNR2: 8.0027




K20260506102431




BLK: 2,SNR1: 5.9932 ,SNR2: 15.440




3C43 2026/05/06 1.44UT TOYOKAWA-KISO



F20260506102436





BLK: 3,SNR1: 8.2298 ,SNR2: 14.927





3C43 2026/05/06 1.44UT FUJI -KISO



K20260506102431




BLK: 3,SNR1: 3.2144 ,SNR2: 11.983



T20260506103218




BLK: 5,SNR1: 23.325 ,SNR2: 41.690





3C48 2026/05/06 1.57UT TOYOKAWA-FUJI



F20260506103220




BLK: 5,SNR1: 16.098 ,SNR2: 27.967



T20260506103218




BLK: 6,SNR1: 11.512 ,SNR2: 28.503





3C48 2026/05/06 1.57UT TOYOKAWA-KISO


K20260506103215




BLK: 6,SNR1: 11.344 ,SNR2: 27.791



F20260506103220




BLK: 6, SNR1: 11.898 , SNR2: 29.128





3C48 2026/05/06 1.57UT FUJI -KISO



K20260506103215




BLK: 6, SNR1: 15.215 , SNR2: 27.696




T20260506105202




No.Good Data




F20260506105204





No.Good Data




0155-109 2026/05/06 1.90UT TOYOKAWA-FUJI





T20260506105202




BLK: 1,SNR1: 0.19416 ,SNR2: 0.78764




K20260506105159





BLK: 1,SNR1: 8.0100 ,SNR2: 19.333




0155-109 2026/05/06 1.90UT TOYOKAWA-KISO





F20260506105204




No.Good Data




K20260506105159




No.Good Data




0155-109 2026/05/06 1.90UT FUJI -KISO




T20260506105910




BLK: 6,SNR1: 5.6973 ,SNR2: 20.099




F20260506105912




BLK: 6,SNR1: 8.6198 ,SNR2: 21.674




0202+15 2026/05/06 2.01UT TOYOKAWA-FUJI



T20260506105910





BLK: 3, SNR1: 2.6044 , SNR2: 8.6095





0202+15 2026/05/06 2.01UT TOYOKAWA-KISO


K20260506105907




BLK: 3, SNR1: 6.0479 , SNR2: 14.987



F20260506105912





BLK: 4,SNR1: 3.5349 ,SNR2: 8.9187





0202+15 2026/05/06 2.01UT FUJI -KISO



K20260506105907




BLK: 4,SNR1: 0.97813 ,SNR2: 6.6318




T20260506111100




BLK: 3,SNR1:-0.17074E-01,SNR2: 0.62452




F20260506111102





BLK: 3,SNR1: 8.0716 ,SNR2: 14.105




0213+178 2026/05/06 2.21UT TOYOKAWA-FUJI




T20260506111100




BLK: 5,SNR1: 0.45938 ,SNR2: 1.4007




K20260506111057




BLK: 5,SNR1: 3.9502 ,SNR2: 12.713




0213+178 2026/05/06 2.21UT TOYOKAWA-KISO




F20260506111102




BLK: 2,SNR1: 2.1606 ,SNR2: 6.7532




K20260506111057




BLK: 2,SNR1: 2.4555 ,SNR2: 10.051




0213+178 2026/05/06 2.21UT FUJI -KISO



T20260506111843




BLK: 2,SNR1: 2.2134 ,SNR2: 5.8971





3C67 2026/05/06 2.34UT TOYOKAWA-FUJI


F20260506111845




BLK: 2,SNR1: 1.8760 ,SNR2: 6.2007



T20260506111843




BLK: 4,SNR1: 2.8203 ,SNR2: 6.7751





3C67 2026/05/06 2.34UT TOYOKAWA-KISO


K20260506111840




BLK: 4,SNR1: 14.465 ,SNR2: 25.726




F20260506111845




No.Good Data




K20260506111840





No.Good Data




3C67 2026/05/06 2.34UT FUJI -KISO



T20260506113657





BLK: 1,SNR1: 0.65461 ,SNR2: 4.7910





3C71 2026/05/06 2.64UT TOYOKAWA-FUJI


F20260506113659




BLK: 1,SNR1: 1.6438 ,SNR2: 7.0827



T20260506113657




BLK: 5,SNR1: 8.4998 ,SNR2: 20.726





3C71 2026/05/06 2.64UT TOYOKAWA-KISO


K20260506113654




BLK: 5,SNR1: 13.175 ,SNR2: 23.237



F20260506113659





BLK: 1,SNR1: 1.6438 ,SNR2: 7.0829





3C71 2026/05/06 2.64UT FUJI -KISO



K20260506113654




BLK: 1,SNR1: 2.6340 ,SNR2: 8.1949




T20260506115613




BLK:11,SNR1: 1.3559 ,SNR2: 9.6556




F20260506115615





BLK:11,SNR1: 2.0796 ,SNR2: 9.0261




0258+350 2026/05/06 2.97UT TOYOKAWA-FUJI




T20260506115613




BLK:14,SNR1: 1.6157 ,SNR2: 8.9219




K20260506115610




BLK:14,SNR1: 3.5798 ,SNR2: 6.6204




0258+350 2026/05/06 2.97UT TOYOKAWA-KISO




F20260506115615




BLK: 5,SNR1: 3.2855 ,SNR2: 11.598




K20260506115610





BLK: 5,SNR1: 3.3993 ,SNR2: 13.382




0258+350 2026/05/06 2.97UT FUJI -KISO





T20260506120602




BLK:13,SNR1: 1.3481 ,SNR2: 3.1211




F20260506120604





BLK:13,SNR1: 2.2035 ,SNR2: 5.4613




0308+305 2026/05/06 3.13UT TOYOKAWA-FUJI





T20260506120602




BLK: 8,SNR1: 1.6059 ,SNR2: 3.7035




K20260506120559





BLK: 8,SNR1: 1.8690 ,SNR2: 4.6293




0308+305 2026/05/06 3.13UT TOYOKAWA-KISO





F20260506120604




BLK: 3,SNR1: 0.11423 ,SNR2: 1.6165




K20260506120559





BLK: 3,SNR1: 0.56056 ,SNR2: 8.3805




0308+305 2026/05/06 3.13UT FUJI -KISO



T20260506121733





BLK: 7,SNR1: 3.8626 ,SNR2: 13.389





0320+05 2026/05/06 3.32UT TOYOKAWA-FUJI



F20260506121735




BLK: 7,SNR1:-0.26636 ,SNR2: 1.1040





T20260506121733




BLK: 9,SNR1: 2.1111 ,SNR2: 9.1277




K20260506121730




BLK: 9,SNR1: 3.0008 ,SNR2: 5.1731




0320+05 2026/05/06 3.32UT TOYOKAWA-KISO





F20260506121735




BLK: 7,SNR1:-0.30164 ,SNR2: 0.29048




K20260506121730







BLK: 7,SNR1: 2.0165 ,SNR2: 4.0146








0320+05 2026/05/06 3.32UT FUJI -KISO






0333+32 2026/05/06 3.54UT TOYOKAWA-FUJI







0333+32 2026/05/06 3.54UT TOYOKAWA-KISO





F20260506123057




BLK: 6,SNR1: 1.2152 ,SNR2: 3.8152




K20260506123052





BLK: 6,SNR1: 0.16941 ,SNR2: 3.6409




0333+32 2026/05/06 3.54UT FUJI -KISO




T20260506124356




BLK: 6,SNR1: 0.68045E-01,SNR2: 2.0075




F20260506124358





BLK: 6,SNR1:-0.17280 ,SNR2: 1.6355




0347+05 2026/05/06 3.76UT TOYOKAWA-FUJI





T20260506124356




BLK: 8,SNR1: 0.25329 ,SNR2: 0.90543




K20260506124353




BLK: 8,SNR1: 1.3096 ,SNR2: 4.5898




0347+05 2026/05/06 3.76UT TOYOKAWA-KISO



F20260506124358





BLK: 6,SNR1: 0.40320E-01,SNR2: 3.9288





0347+05 2026/05/06 3.76UT FUJI -KISO



K20260506124353




BLK: 6,SNR1: 0.99326 ,SNR2: 3.4846





T20260506125930




BLK: 2,SNR1: 9.7145 ,SNR2: 26.115




F20260506125932





BLK: 2,SNR1: 10.787 ,SNR2: 32.736




0403-132 2026/05/06 4.02UT TOYOKAWA-FUJI





T20260506125930




No.Good Data




K20260506125927





No.Good Data




0403-132 2026/05/06 4.02UT TOYOKAWA-KISO





F20260506125932




No.Good Data




K20260506125927





No.Good Data




0403-132 2026/05/06 4.02UT FUJI -KISO





T20260506130841




BLK:23,SNR1: 9.5577 ,SNR2: 22.758




F20260506130843





BLK:23,SNR1: 6.8880 ,SNR2: 20.069




0411+05 2026/05/06 4.17UT TOYOKAWA-FUJI





T20260506130841




BLK:25,SNR1: 9.5492 ,SNR2: 22.737




K20260506130838





BLK:25,SNR1: 8.5091 ,SNR2: 21.250




0411+05 2026/05/06 4.17UT TOYOKAWA-KISO





F20260506130843




BLK:19,SNR1: 7.6904 ,SNR2: 22.659




K20260506130838




BLK:19,SNR1: 8.5346 ,SNR2: 21.061




0411+05 2026/05/06 4.17UT FUJI -KISO




T20260506131935




BLK:14,SNR1: 9.2843 ,SNR2: 16.583




F20260506131937




BLK:14,SNR1: 9.9824 ,SNR2: 17.421




0422+178 2026/05/06 4.35UT TOYOKAWA-FUJI




T20260506131935




BLK:12,SNR1: 15.208 ,SNR2: 24.344




K20260506131932




BLK:12,SNR1: 43.050 ,SNR2: 52.470




0422+178 2026/05/06 4.35UT TOYOKAWA-KISO




F20260506131937




BLK:17,SNR1: 9.6563 ,SNR2: 17.181




K20260506131932





BLK:17,SNR1: 41.888 ,SNR2: 50.473




0422+178 2026/05/06 4.35UT FUJI -KISO




T20260506132710




BLK: 1,SNR1: 10.855 ,SNR2: 27.838




F20260506132712






BLK: 1,SNR1: 7.1137 ,SNR2: 18.205






3C120 2026/05/06 4.48UT TOYOKAWA-FUJI




T20260506132710




K20260506132707




3C120 2026/05/06 4.48UT TOYOKAWA-KISO



F20260506132712




BLK: 1,SNR1: 7.6176 ,SNR2: 19.379





3C120 2026/05/06 4.48UT FUJI -KISO



K20260506132707




BLK: 1,SNR1: 11.392 ,SNR2: 28.698




T20260506141511




BLK:13,SNR1: 3.2713 ,SNR2: 20.786




F20260506141513





BLK:13,SNR1: 2.0050 ,SNR2: 6.4453




3C138 2026/05/06 5.28UT TOYOKAWA-FUJI




T20260506141511




BLK:21,SNR1: 3.3105 ,SNR2: 20.310




K20260506141508




BLK:21,SNR1: 2.3320 ,SNR2: 5.9482




3C138 2026/05/06 5.28UT TOYOKAWA-KISO





F20260506141513




BLK:12,SNR1: 0.14058 ,SNR2: 4.0356




K20260506141508







BLK:12,SNR1: 1.3603 ,SNR2: 4.3853








3C138 2026/05/06 5.28UT FUJI -KISO






0531+194 2026/05/06 5.51UT TOYOKAWA-FUJI








0531+194 2026/05/06 5.51UT TOYOKAWA-KISO



F20260506142846





BLK:26,SNR1: 0.94760 ,SNR2: 5.0471




Frequency (Hz)

K20260506142841




BLK:26,SNR1: 2.0652 ,SNR2: 4.9561





Frequency (Hz)


0531+194 2026/05/06 5.51UT FUJI -KISO




T20260506143705




BLK:23,SNR1: 5.8581 ,SNR2: 32.181




F20260506143707





BLK:23,SNR1: 1.6671 ,SNR2: 5.5688




3C147 2026/05/06 5.65UT TOYOKAWA-FUJI



T20260506143705





BLK:26,SNR1: 5.6442 ,SNR2: 17.994




Frequency (Hz)

K20260506143702








BLK:26,SNR1: 2.5303 ,SNR2: 6.3852




Frequency (Hz)

3C147 2026/05/06 5.65UT TOYOKAWA-KISO







3C147 2026/05/06 5.65UT FUJI -KISO





T20260506144515




BLK: 3,SNR1: 8.3722 ,SNR2: 18.560




F20260506144517




BLK: 3,SNR1: 7.9595 ,SNR2: 19.613




0548+16 2026/05/06 5.78UT TOYOKAWA-FUJI




T20260506144515




BLK: 1,SNR1: 0.80226 ,SNR2: 3.2249




K20260506144512





BLK: 1,SNR1: 17.114 ,SNR2: 40.685




0548+16 2026/05/06 5.78UT TOYOKAWA-KISO



F20260506144517





No.Good Data




Frequency (Hz)

K20260506144512








No.Good Data




Frequency (Hz)


0548+16 2026/05/06 5.78UT FUJI -KISO







0552+12 2026/05/06 5.85UT TOYOKAWA-FUJI







BLK:11,SNR1: 15.039 ,SNR2: 74.800





BLK:11,SNR1: 0.76087 ,SNR2: 2.2302




0552+12 2026/05/06 5.85UT TOYOKAWA-KISO



F20260506144927





BLK: 7,SNR1: 0.15096 ,SNR2: 1.0473




Frequency (Hz)

K20260506144922




BLK: 7,SNR1: 0.10465 ,SNR2: 1.5219





Frequency (Hz)


0552+12 2026/05/06 5.85UT FUJI -KISO





T20260506145353




BLK:16,SNR1: 9.7340 ,SNR2: 17.380




F20260506145355





BLK:16,SNR1: 27.062 ,SNR2: 43.355




0556+191 2026/05/06 5.93UT TOYOKAWA-FUJI



T20260506145353





BLK:16,SNR1: 9.7608 ,SNR2: 17.427




Frequency (Hz)

K20260506145350




BLK:16,SNR1: 7.4674 ,SNR2: 16.673




Frequency (Hz)


0556+191 2026/05/06 5.93UT TOYOKAWA-KISO





F20260506145355




BLK:25,SNR1: 1.7016 ,SNR2: 3.7523




K20260506145350




BLK:25,SNR1: 7.5156 ,SNR2: 18.241





0556+191 2026/05/06 5.93UT FUJI -KISO







BLK: 9,SNR1: 0.63648E-01,SNR2: 2.1816





BLK: 9,SNR1: 2.8500 ,SNR2: 7.3357




3C152 2026/05/06 6.00UT TOYOKAWA-FUJI



T20260506145825





BLK: 5, SNR1: 0.15407 , SNR2: 2.1612




Frequency (Hz)

K20260506145822








BLK: 5, SNR1: 3.0339 , SNR2: 9.2311




Frequency (Hz)

3C152 2026/05/06 6.00UT TOYOKAWA-KISO








3C152 2026/05/06 6.00UT FUJI -KISO





T20260506152045




BLK: 9,SNR1: 3.5769 ,SNR2: 21.932




F20260506152047





BLK: 9,SNR1:-0.86545E-01,SNR2: 2.6395




3C161 2026/05/06 6.37UT TOYOKAWA-FUJI





T20260506152045




BLK:27,SNR1: 4.3846 ,SNR2: 8.4284




K20260506152042




BLK:27,SNR1: 13.911 ,SNR2: 31.759




3C161 2026/05/06 6.37UT TOYOKAWA-KISO



F20260506152047





BLK: 5,SNR1:-0.86616E-01,SNR2: 2.2669




Frequency (Hz)

K20260506152042




BLK: 5,SNR1: 7.5397 ,SNR2: 13.462





Frequency (Hz)


3C161 2026/05/06 6.37UT FUJI -KISO



T20260506154818




BLK:10,SNR1: 8.0628 ,SNR2: 13.999




Frequency (Hz)

F20260506154820




BLK:10,SNR1: 5.5213 ,SNR2: 13.587





Frequency (Hz)


0652-130 2026/05/06 6.83UT TOYOKAWA-FUJI



T20260506154818




BLK:11,SNR1: 8.2942 ,SNR2: 14.397




Frequency (Hz)

K20260506154815




BLK:11,SNR1: 8.5504 ,SNR2: 14.876




Frequency (Hz)


0652-130 2026/05/06 6.83UT TOYOKAWA-KISO



F20260506154820




BLK:14,SNR1: 4.3092 ,SNR2: 10.506




Frequency (Hz)

K20260506154815




BLK:14,SNR1: 8.2222 ,SNR2: 14.373





Frequency (Hz)


0652-130 2026/05/06 6.83UT FUJI -KISO





T20260506155955




No.Good Data




F20260506155957




No.Good Data




0703+138 2026/05/06 7.03UT TOYOKAWA-FUJI



T20260506155955





BLK: 3,SNR1: 19.330 ,SNR2: 35.222




Frequency (Hz)

K20260506155952




BLK: 3,SNR1: 18.697 ,SNR2: 33.443





Frequency (Hz)


0703+138 2026/05/06 7.03UT TOYOKAWA-KISO



F20260506155957





BLK: 4,SNR1: 18.917 ,SNR2: 33.912




Frequency (Hz)

K20260506155952




BLK: 4,SNR1: 21.058 ,SNR2: 37.364





Frequency (Hz)


0703+138 2026/05/06 7.03UT FUJI -KISO



T20260506160918




BLK: 2,SNR1: 10.964 ,SNR2: 23.580




Frequency (Hz)

F20260506160920




BLK: 2,SNR1:-0.83325E-01,SNR2: 1.2910





Frequency (Hz)


0713-024 2026/05/06 7.18UT TOYOKAWA-FUJI



T20260506160918





BLK:12,SNR1: 3.9258 ,SNR2: 8.5343




Frequency (Hz)

K20260506160915




BLK:12,SNR1: 5.1183 ,SNR2: 10.972




Frequency (Hz)


0713-024 2026/05/06 7.18UT TOYOKAWA-KISO



F20260506160920





BLK: 8,SNR1:-0.30684 ,SNR2: 0.17461E-01




Frequency (Hz)

K20260506160915




BLK: 8,SNR1: 0.20765 ,SNR2: 2.6630





Frequency (Hz)


0713-024 2026/05/06 7.18UT FUJI -KISO





T20260506161930




BLK:11,SNR1: 2.1488 ,SNR2: 5.8880




F20260506161932





BLK:11,SNR1: 1.7238 ,SNR2: 4.2428




0723+10 2026/05/06 7.35UT TOYOKAWA-FUJI





T20260506161930




BLK:18,SNR1: 2.4176 ,SNR2: 7.6630




K20260506161928





BLK:18,SNR1: 3.2449 ,SNR2: 5.6815




0723+10 2026/05/06 7.35UT TOYOKAWA-KISO



F20260506161932





BLK: 8,SNR1: 1.0145 ,SNR2: 2.0365




Frequency (Hz)

K20260506161928




BLK: 8,SNR1: 6.5373 ,SNR2: 9.7613





Frequency (Hz)


0723+10 2026/05/06 7.35UT FUJI -KISO



T20260506162945




BLK: 1,SNR1: 0.76488E-01,SNR2: 0.93037




Frequency (Hz)

F20260506162947




BLK: 1,SNR1:-0.88145E-01,SNR2: 0.61124





Frequency (Hz)


0732+33 2026/05/06 7.52UT TOYOKAWA-FUJI



T20260506162945





BLK: 1,SNR1: 0.76489E-01,SNR2: 0.93032




Frequency (Hz)

K20260506162943




BLK: 1,SNR1: 1.8362 ,SNR2: 5.9839




Frequency (Hz)


0732+33 2026/05/06 7.52UT TOYOKAWA-KISO



F20260506162947





BLK: 1,SNR1: 0.24831E-01,SNR2: 1.4063




Frequency (Hz)

K20260506162943




BLK: 1,SNR1: 0.21451 ,SNR2: 1.4408





Frequency (Hz)


0732+33 2026/05/06 7.52UT FUJI -KISO



T20260506163746




BLK: 3,SNR1: 0.26530 ,SNR2: 1.1227




Frequency (Hz)

F20260506163748




BLK: 3,SNR1: 0.97173 ,SNR2: 7.8837





Frequency (Hz)


0741-06 2026/05/06 7.66UT TOYOKAWA-FUJI



T20260506163746





BLK: 6,SNR1: 0.92116E-01,SNR2: 0.31884




Frequency (Hz)

K20260506163743




BLK: 6,SNR1: 1.2648 ,SNR2: 4.1700




Frequency (Hz)


0741-06 2026/05/06 7.66UT TOYOKAWA-KISO



F20260506163748




BLK: 3,SNR1: 1.0266 ,SNR2: 2.0566




Frequency (Hz)

K20260506163743




BLK: 3,SNR1: 0.52522E-01,SNR2: 2.0342




Frequency (Hz)


0741-06 2026/05/06 7.66UT FUJI -KISO



T20260506165506





No.Good Data




Frequency (Hz)

F20260506165508




No.Good Data




Frequency (Hz)


3C190 2026/05/06 7.95UT TOYOKAWA-FUJI



T20260506165506





BLK: 3,SNR1: 0.22136 ,SNR2: 2.1386




Frequency (Hz)

3C190 2026/05/06 7.95UT TOYOKAWA-KISO


K20260506165503





BLK: 3,SNR1: 1.6210 ,SNR2: 7.8115




Frequency (Hz)



F20260506165508





BLK: 2,SNR1: 19.364 ,SNR2: 34.371




Frequency (Hz)

K20260506165503





BLK: 2,SNR1: 0.41859 ,SNR2: 1.5616





Frequency (Hz)

3C190 2026/05/06 7.95UT FUJI -KISO







BLK: 9,SNR1: 2.0042 ,SNR2: 28.045




BLK: 9,SNR1: 0.43511 ,SNR2: 1.3029





3C196 2026/05/06 8.15UT TOYOKAWA-FUJI







BLK: 6,SNR1: 0.98856 ,SNR2: 2.6483




BLK: 6,SNR1: $-0.98151E-02$,SNR2: 1.9366




3C196 2026/05/06 8.15UT TOYOKAWA-KISO



F20260506170734




BLK: 6,SNR1:-0.67563E-01,SNR2: 1.5185




Frequency (Hz)

K20260506170729




BLK: 6,SNR1: 0.21573 ,SNR2: 2.9327





Frequency (Hz)


3C196 2026/05/06 8.15UT FUJI -KISO



T20260506171841





BLK: 1,SNR1:-0.27557 ,SNR2: 0.20480




Frequency (Hz)

F20260506171843




BLK: 1,SNR1:-0.99225E-01,SNR2: 2.1085





Frequency (Hz)


0821+394 2026/05/06 8.34UT TOYOKAWA-FUJI



T20260506171841




BLK: 2,SNR1: 0.13374 ,SNR2: 0.91878




Frequency (Hz)

K20260506171838




BLK: 2,SNR1: 2.8437 ,SNR2: 8.9834




Frequency (Hz)


0821+394 2026/05/06 8.34UT TOYOKAWA-KISO



F20260506171843





BLK: 1,SNR1: 0.80657E-02,SNR2: 4.3026




Frequency (Hz)

K20260506171838



BLK: 1,SNR1: 2.2884 ,SNR2: 6.6090



Frequency (Hz)

0821+394 2026/05/06 8.34UT Fuji -KISO

