




T20260516053647





BLK: 6,SNR1: 19.089 ,SNR2: 75.940




Frequency (Hz)

F20260516053649




BLK: 6,SNR1: 2.8356 ,SNR2: 8.7326





Frequency (Hz)


2119+435 2026/05/15 20.64UT TOYOKAWA-FUJI



T20260516053647





BLK:10,SNR1: 4.4073 ,SNR2: 13.036




Frequency (Hz)

K20260516053644




BLK:10,SNR1: 1.8601 ,SNR2: 3.7116




Frequency (Hz)


2119+435 2026/05/15 20.64UT TOYOKAWA-KISO



F20260516053649




BLK:16,SNR1: 7.0725 ,SNR2: 20.124





2119+435 2026/05/15 20.64UT FUJI -KISO



K20260516053644




BLK:16,SNR1: 1.8139 ,SNR2: 3.5262



T20260516054427





BLK: 7,SNR1: 36.269 ,SNR2: 63.685




Frequency (Hz)

F20260516054429




BLK: 7,SNR1: 18.945 ,SNR2: 34.527





Frequency (Hz)


2127+456 2026/05/15 20.77UT TOYOKAWA-FUJI



T20260516054427





BLK: 6,SNR1: 34.534 ,SNR2: 82.844




Frequency (Hz)

K20260516054424




BLK: 6,SNR1: 15.558 ,SNR2: 27.387





Frequency (Hz)


2127+456 2026/05/15 20.77UT TOYOKAWA-KISO



F20260516054429





BLK: 3,SNR1: 10.079 ,SNR2: 23.992




Frequency (Hz)

K20260516054424




BLK: 3,SNR1: 8.4725 ,SNR2: 20.738





Frequency (Hz)


2127+456 2026/05/15 20.77UT FUJI -KISO



T20260516054925





BLK: 2,SNR1: 0.23692 ,SNR2: 1.5250




Frequency (Hz)

F20260516054927




BLK: 2,SNR1: 1.6865 ,SNR2: 7.9255





Frequency (Hz)


2131+379 2026/05/15 20.85UT TOYOKAWA-FUJI





T20260516054925




No.Good Data




K20260516054922





No.Good Data




2131+379 2026/05/15 20.85UT TOYOKAWA-KISO



F20260516054927





BLK: 1,SNR1: 0.70244 ,SNR2: 2.8040




Frequency (Hz)

K20260516054922




BLK: 1,SNR1: 0.19103 ,SNR2: 6.4998





Frequency (Hz)


2131+379 2026/05/15 20.85UT FUJI -KISO



T20260516055951





BLK: 9,SNR1: 7.9145 ,SNR2: 28.267




Frequency (Hz)

F20260516055953




BLK: 9,SNR1: 11.526 ,SNR2: 27.410





Frequency (Hz)


2142+279 2026/05/15 21.03UT TOYOKAWA-FUJI



T20260516055951





BLK: 5,SNR1: 11.202 ,SNR2: 27.964




Frequency (Hz)

2142+279 2026/05/15 21.03UT TOYOKAWA-KISO


K20260516055948





BLK: 5,SNR1: 7.3304 ,SNR2: 18.268




Frequency (Hz)



F20260516055953





BLK: 6,SNR1: 6.4017 ,SNR2: 16.392




Frequency (Hz)

K20260516055948




BLK: 6,SNR1: 6.8205 ,SNR2: 17.512





Frequency (Hz)


2142+279 2026/05/15 21.03UT FUJI -KISO



T20260516060945





BLK: 8,SNR1: 5.4761 ,SNR2: 21.966




Frequency (Hz)

F20260516060947




BLK: 8,SNR1: 1.0816 ,SNR2: 5.1767




Frequency (Hz)


2152+450 2026/05/15 21.19UT TOYOKAWA-FUJI



T20260516060945





BLK: 8,SNR1: 50.054 ,SNR2: 119.83




Frequency (Hz)

K20260516060942




BLK: 8,SNR1: 7.9237 ,SNR2: 18.170





Frequency (Hz)


2152+450 2026/05/15 21.19UT TOYOKAWA-KISO



F20260516060947





BLK: 1,SNR1: 0.44788E-01,SNR2: 1.4824




Frequency (Hz)

K20260516060942




BLK: 1,SNR1: 1.3773 ,SNR2: 5.4302





Frequency (Hz)


2152+450 2026/05/15 21.19UT FUJI -KISO



T20260516061847




BLK: 6,SNR1: 7.1886 ,SNR2: 18.131




Frequency (Hz)

F20260516061849




BLK: 6,SNR1: 5.6646 ,SNR2: 19.296





Frequency (Hz)


2201+315 2026/05/15 21.34UT TOYOKAWA-FUJI



T20260516061847





BLK: 3,SNR1: 7.0970 ,SNR2: 17.704




Frequency (Hz)

2201+315 2026/05/15 21.34UT TOYOKAWA-KISO


K20260516061844





BLK: 3,SNR1: 7.3224 ,SNR2: 18.025




Frequency (Hz)



F20260516061849





BLK: 2,SNR1: 5.8937 ,SNR2: 21.093




Frequency (Hz)

K20260516061844




BLK: 2,SNR1: 5.0874 ,SNR2: 18.929





Frequency (Hz)


2201+315 2026/05/15 21.34UT FUJI -KISO



T20260516062452





No.Good Data




Frequency (Hz)

F20260516062454




No.Good Data





Frequency (Hz)


2207+374 2026/05/15 21.44UT TOYOKAWA-FUJI



T20260516062452





BLK:12,SNR1: 6.1688 ,SNR2: 11.004




Frequency (Hz)

K20260516062449




BLK:12,SNR1: 8.9093 ,SNR2: 15.664




Frequency (Hz)


2207+374 2026/05/15 21.44UT TOYOKAWA-KISO



F20260516062454




BLK: 9,SNR1: 7.1094 ,SNR2: 16.120




Frequency (Hz)

K20260516062449





BLK: 9,SNR1: 6.2390 ,SNR2: 14.390





Frequency (Hz)

2207+374 2026/05/15 21.44UT FUJI -KISO







BLK: 3,SNR1: 0.71678E-01,SNR2: 2.4810





BLK: 3,SNR1: 5.4559 ,SNR2: 13.599




2217+128 2026/05/15 21.62UT TOYOKAWA-FUJI



T20260516063542




BLK: 1,SNR1: 0.96257E-01,SNR2: 0.45817





2217+128 2026/05/15 21.62UT TOYOKAWA-KISO



K20260516063539




BLK: 1,SNR1: 2.0564 ,SNR2: 12.014





F20260516063544




BLK: 1,SNR1: 7.9610 ,SNR2: 18.963




K20260516063539





BLK: 1,SNR1: 0.77745 ,SNR2: 3.1066




2217+128 2026/05/15 21.62UT FUJI -KISO



T20260516064129





BLK: 1,SNR1: 11.721 ,SNR2: 28.669




Frequency (Hz)

3C446 2026/05/15 21.72UT TOYOKAWA-FUJI


F20260516064131





BLK: 1,SNR1: 7.9428 ,SNR2: 19.635




Frequency (Hz)



T20260516064129





No.Good Data




Frequency (Hz)

K20260516064126




No.Good Data





Frequency (Hz)


3C446 2026/05/15 21.72UT TOYOKAWA-KISO



F20260516064131





No.Good Data




Frequency (Hz)

3C446 2026/05/15 21.72UT FUJI -KISO


K20260516064126




No.Good Data




Frequency (Hz)








BLK: 2,SNR1: 6.1184 ,SNR2: 10.734







2229-093 2026/05/15 21.83UT TOYOKAWA-FUJI




BLK: 2,SNR1: 0.79643 ,SNR2: 6.5567







2229-093 2026/05/15 21.83UT TOYOKAWA-KISO





F20260516064815




BLK: 4,SNR1: 3.1576 ,SNR2: 11.283




K20260516064810





BLK: 4,SNR1: 9.5874 ,SNR2: 17.888




2229-093 2026/05/15 21.83UT FUJI -KISO




T20260516065640




BLK: 3,SNR1: 5.3395 ,SNR2: 9.8454




F20260516065642





BLK: 3,SNR1: 5.1436 ,SNR2: 11.449




2238-113 2026/05/15 21.97UT TOYOKAWA-FUJI




T20260516065640




BLK: 7, SNR1: 4.1023 ,SNR2: 12.123




K20260516065637




BLK: 7, SNR1: 3.9789 ,SNR2: 11.686




2238-113 2026/05/15 21.97UT TOYOKAWA-KISO



F20260516065642




BLK: 6,SNR1: 5.3733 ,SNR2: 11.930




Frequency (Hz)

K20260516065637








BLK: 6,SNR1: 5.3633 ,SNR2: 9.5867




Frequency (Hz)

2238-113 2026/05/15 21.97UT FUJI -KISO








3C454.3 2026/05/15 22.19UT TOYOKAWA-FUJI



T20260516070929





BLK: 1,SNR1: 1.1103 ,SNR2: 4.1662




Frequency (Hz)

3C454.3 2026/05/15 22.19UT TOYOKAWA-KISO


K20260516070926





BLK: 1,SNR1: 0.15470 ,SNR2: 3.7060




Frequency (Hz)



F20260516070931





BLK: 1,SNR1: 3.6697 ,SNR2: 14.186




Frequency (Hz)

3C454.3 2026/05/15 22.19UT FUJI -KISO


K20260516070926




BLK: 1,SNR1: 0.15470 ,SNR2: 3.7060




Frequency (Hz)




T20260516071711




BLK: 4, SNR1: 0.31267 ,SNR2: 1.6629




F20260516071713





BLK: 4, SNR1: 5.1346 ,SNR2: 12.693




2259+481 2026/05/15 22.31UT TOYOKAWA-FUJI





T20260516071711




BLK: 8,SNR1: 0.54506 ,SNR2: 1.5587




K20260516071708




BLK: 8,SNR1: 3.2307 ,SNR2: 6.3669




2259+481 2026/05/15 22.31UT TOYOKAWA-KISO




F20260516071713




BLK: 7,SNR1: 1.7415 ,SNR2: 4.5024




K20260516071708





BLK: 7,SNR1: 2.0261 ,SNR2: 5.3739




2259+481 2026/05/15 22.31UT FUJI -KISO



T20260516073205





BLK: 1,SNR1: 2.3770 ,SNR2: 13.919




Frequency (Hz)

3C459 2026/05/15 22.56UT TOYOKAWA-FUJI


F20260516073207





BLK: 1,SNR1: 10.323 ,SNR2: 25.324




Frequency (Hz)



T20260516073205





BLK: 2, SNR1: 5.8941 , SNR2: 20.398




Frequency (Hz)

3C459 2026/05/15 22.56UT TOYOKAWA-KISO


K20260516073202





BLK: 2, SNR1: 14.689 , SNR2: 25.888




Frequency (Hz)



F20260516073207





BLK: 1,SNR1: 21.847 ,SNR2: 49.448




Frequency (Hz)

3C459 2026/05/15 22.56UT FUJI -KISO


K20260516073202




BLK: 1,SNR1: 14.731 ,SNR2: 25.961




Frequency (Hz)



T20260516080550




BLK: 3,SNR1: 2.8988 ,SNR2: 21.714





2347-02 2026/05/15 23.13UT TOYOKAWA-FUJI


F20260516080552




BLK: 3,SNR1: 12.216 ,SNR2: 21.625



T20260516080550




BLK: 1,SNR1: 1.6934 ,SNR2: 6.8155





2347-02 2026/05/15 23.13UT TOYOKAWA-KISO


K20260516080548




BLK: 1,SNR1: 13.628 ,SNR2: 25.100



F20260516080552




BLK: 4,SNR1: 2.5313 ,SNR2: 12.039




Frequency (Hz)

K20260516080548




BLK: 4,SNR1: 6.7399 ,SNR2: 16.915





Frequency (Hz)


2347-02 2026/05/15 23.13UT FUJI -KISO





T20260516081243




BLK: 7, SNR1: 0.13574 , SNR2: 0.46560




F20260516081245





BLK: 7, SNR1: 0.83092 , SNR2: 5.9324




2354+14 2026/05/15 23.24UT TOYOKAWA-FUJI



T20260516081243




BLK: 7,SNR1: 0.15793 ,SNR2: 1.3697





2354+14 2026/05/15 23.24UT TOYOKAWA-KISO



K20260516081241




BLK: 7,SNR1: 1.2347 ,SNR2: 4.3005




F20260516081245




BLK:12,SNR1: 9.5215 ,SNR2: 20.582




K20260516081241





BLK:12,SNR1: 1.1125 ,SNR2: 3.7921




2354+14 2026/05/15 23.24UT FUJI -KISO



T20260516082146





BLK: 3,SNR1: 10.320 ,SNR2: 29.970




Frequency (Hz)

3C2 2026/05/15 23.39UT TOYOKAWA-FUJI


F20260516082148





BLK: 3,SNR1: 13.063 ,SNR2: 31.785




Frequency (Hz)



T20260516082146





BLK: 4,SNR1: 11.079 ,SNR2: 35.074





3C2 2026/05/15 23.39UT TOYOKAWA-KISO



K20260516082144




BLK: 4,SNR1: 9.5001 ,SNR2: 27.622



F20260516082148



BLK: 3, SNR1: 11.564 ,SNR2: 29.739





Frequency (Hz)


3C2

2026/05/15 23.39UT FUJI -KISO


K20260516082144




BLK: 3, SNR1: 12.060 ,SNR2: 30.406




Frequency (Hz)



T20260516082908




BLK:15,SNR1: 2.3248 ,SNR2: 7.6508





0011+344 2026/05/15 23.51UT TOYOKAWA-FUJI


F20260516082910




BLK:15,SNR1: 9.4749 ,SNR2: 17.674





T20260516082908




BLK:15,SNR1: 2.2997 ,SNR2: 7.5822




K20260516082905




BLK:15,SNR1: 0.10387 ,SNR2: 6.2329




0011+344 2026/05/15 23.51UT TOYOKAWA-KISO





F20260516082910




BLK:21,SNR1: 9.2133 ,SNR2: 17.192




K20260516082905




BLK:21,SNR1: 7.8019 ,SNR2: 14.605




0011+344 2026/05/15 23.51UT FUJI -KISO



T20260516083744




BLK: 8, SNR1: 6.6896 , SNR2: 19.949





0019-00 2026/05/15 23.66UT TOYOKAWA-FUJI



F20260516083746




BLK: 8, SNR1: 6.3887 , SNR2: 16.622



T20260516083744





BLK: 5,SNR1: 5.0344 ,SNR2: 16.049




Frequency (Hz)

0019-00 2026/05/15 23.66UT TOYOKAWA-KISO


K20260516083742




BLK: 5,SNR1: 5.8040 ,SNR2: 18.756




Frequency (Hz)




F20260516083746




BLK: 7, SNR1: 8.8822 ,SNR2: 15.775




K20260516083742





BLK: 7, SNR1: 6.9044 ,SNR2: 21.723




0019-00 2026/05/15 23.66UT FUJI -KISO



T20260516084759





BLK: 7,SNR1: 11.389 ,SNR2: 30.319





3C12 2026/05/15 23.83UT TOYOKAWA-FUJI



F20260516084801




BLK: 7,SNR1: 11.604 ,SNR2: 29.801



T20260516084759




BLK: 5, SNR1: 6.2559 ,SNR2: 17.735





3C12 2026/05/15 23.83UT TOYOKAWA-KISO



K20260516084757




BLK: 5, SNR1: 11.367 ,SNR2: 28.595



F20260516084801




BLK: 4, SNR1: 12.697 , SNR2: 37.254





3C12 2026/05/15 23.83UT FUJI -KISO


K20260516084757




BLK: 4, SNR1: 6.6977 , SNR2: 19.974



T20260516090201




BLK:25,SNR1: 7.7734 ,SNR2: 22.215





0044-056 2026/05/16 0.06UT TOYOKAWA-FUJI



F20260516090203




BLK:25,SNR1: 7.2178 ,SNR2: 20.857



T20260516090201





BLK:25,SNR1: 8.6048 ,SNR2: 22.970




Frequency (Hz)

K20260516090158




BLK:25,SNR1: 10.938 ,SNR2: 27.565





Frequency (Hz)


0044-056 2026/05/16 0.06UT TOYOKAWA-KISO



F20260516090203





BLK:17,SNR1: 7.2120 ,SNR2: 20.839




Frequency (Hz)

K20260516090158




BLK:17,SNR1: 11.158 ,SNR2: 28.117





Frequency (Hz)


0044-056 2026/05/16 0.06UT FUJI -KISO




T20260516090922




No. Good Data




F20260516090924




No. Good Data




3C26 2026/05/16 0.18UT TOYOKAWA-FUJI




T20260516090922




BLK: 2,SNR1: 1.3303 ,SNR2: 2.9703




K20260516090919




BLK: 2,SNR1: 1.7165 ,SNR2: 5.6365




3C26 2026/05/16 0.18UT TOYOKAWA-KISO



F20260516090924




BLK: 1,SNR1:-0.12376 ,SNR2: 0.43707E-01





3C26 2026/05/16 0.18UT FUJI -KISO



K20260516090919




BLK: 1,SNR1: 0.44885 ,SNR2: 1.7226



T20260516091420




BLK: 1,SNR1: 5.1155 ,SNR2: 19.457




0056-00 2026/05/16 0.27UT TOYOKAWA-FUJI


F20260516091422





BLK: 1,SNR1: 4.8606 ,SNR2: 17.347




Frequency (Hz)



T20260516091420





No. Good Data




Frequency (Hz)

K20260516091417




No. Good Data





Frequency (Hz)


0056-00 2026/05/16 0.27UT TOYOKAWA-KISO





F20260516091422




No.Good Data




K20260516091417




No.Good Data




0056-00 2026/05/16 0.27UT FUJI -KISO



T20260516092403





BLK: 3,SNR1: 13.402 ,SNR2: 32.274




0106+01 2026/05/16 0.43UT TOYOKAWA-FUJI


F20260516092405




BLK: 3,SNR1: 10.689 ,SNR2: 27.238




Frequency (Hz)



T20260516092403




BLK: 1,SNR1: 14.374 ,SNR2: 28.321





0106+01 2026/05/16 0.43UT TOYOKAWA-KISO



K20260516092400




BLK: 1,SNR1: 2.3158 ,SNR2: 11.432



F20260516092405




BLK: 2, SNR1: 5.4195 , SNR2: 9.7694





0106+01 2026/05/16 0.43UT FUJI -KISO


K20260516092400




BLK: 2, SNR1: 0.14125 , SNR2: 3.7170




T20260516093453




No. Good Data




F20260516093455





No. Good Data




0116+31 2026/05/16 0.61UT TOYOKAWA-FUJI



T20260516093453





BLK: 2, SNR1: 13.718 ,SNR2: 20.670




0116+31 2026/05/16 0.61UT TOYOKAWA-KISO


K20260516093450




BLK: 2, SNR1: 3.6228 ,SNR2: 11.408




Frequency (Hz)



F20260516093455





BLK: 4, SNR1: 7.4237 , SNR2: 27.679





0116+31 2026/05/16 0.61UT FUJI -KISO



K20260516093450




BLK: 4, SNR1: 16.679 , SNR2: 24.537



T20260516094625





BLK: 3,SNR1: 9.7067 ,SNR2: 25.033





0128+03 2026/05/16 0.80UT TOYOKAWA-FUJI



F20260516094627




BLK: 3,SNR1: 8.1215 ,SNR2: 20.752



T20260516094625





BLK: 3,SNR1: 10.372 ,SNR2: 26.431





0128+03 2026/05/16 0.80UT TOYOKAWA-KISO



K20260516094622




BLK: 3,SNR1: 7.9964 ,SNR2: 23.939



F20260516094627





BLK: 2,SNR1: 8.0814 ,SNR2: 20.651





0128+03 2026/05/16 0.80UT FUJI -KISO


K20260516094622




BLK: 2,SNR1: 7.9477 ,SNR2: 23.796



T20260516095259




BLK:24,SNR1: 7.0879 ,SNR2: 21.518





3C48 2026/05/16 0.91UT TOYOKAWA-FUJI


F20260516095301




BLK:24,SNR1: 0.51807 ,SNR2: 5.5920





T20260516095259




BLK:31,SNR1: 6.6183 ,SNR2: 42.059




K20260516095256





BLK:31,SNR1: 1.1347 ,SNR2: 3.9198




3C48 2026/05/16 0.91UT TOYOKAWA-KISO



F20260516095301





BLK:25,SNR1: 0.53663 ,SNR2: 5.1440




Frequency (Hz)

3C48 2026/05/16 0.91UT FUJI -KISO


K20260516095256




BLK:25,SNR1: 1.0851 ,SNR2: 3.6286




Frequency (Hz)



T20260516101243




BLK: 2,SNR1: 6.7413 ,SNR2: 17.092




0155-109 2026/05/16 1.24UT TOYOKAWA-FUJI


F20260516101245




BLK: 2,SNR1: 6.3308 ,SNR2: 15.911




Frequency (Hz)



T20260516101243




BLK: 4,SNR1: 6.1739 ,SNR2: 15.530




0155-109 2026/05/16 1.24UT TOYOKAWA-KISO


K20260516101240




BLK: 4,SNR1: 7.5558 ,SNR2: 26.234




Frequency (Hz)




F20260516101245




BLK: 4,SNR1: 6.3991 ,SNR2: 20.991




K20260516101240




BLK: 4,SNR1: 5.6635 ,SNR2: 17.332




0155-109 2026/05/16 1.24UT FUJI -KISO








BLK: 8,SNR1: 10.410 ,SNR2: 25.691







0202+15 2026/05/16 1.36UT TOYOKAWA-FUJI




BLK: 8,SNR1: 7.1246 ,SNR2: 18.190







0202+15 2026/05/16 1.36UT TOYOKAWA-KISO





F20260516101953




BLK: 1,SNR1: 4.8938 ,SNR2: 14.865




K20260516101948





BLK: 1,SNR1: 10.312 ,SNR2: 26.158




0202+15 2026/05/16 1.36UT FUJI -KISO



T20260516103141





BLK: 2,SNR1: 6.7952 ,SNR2: 16.830




Frequency (Hz)

F20260516103143




BLK: 2,SNR1: 8.4247 ,SNR2: 18.774





Frequency (Hz)


0213+178 2026/05/16 1.56UT TOYOKAWA-FUJI



T20260516103141





BLK: 2,SNR1: 8.5752 ,SNR2: 24.278




Frequency (Hz)

K20260516103138




BLK: 2,SNR1: 17.350 ,SNR2: 33.384





Frequency (Hz)


0213+178 2026/05/16 1.56UT TOYOKAWA-KISO





F20260516103143




BLK: 2,SNR1: 27.905 ,SNR2: 38.616




K20260516103138




BLK: 2,SNR1: 15.317 ,SNR2: 34.165




0213+178 2026/05/16 1.56UT FUJI -KISO



T20260516103924




BLK:14,SNR1: 1.0047 ,SNR2: 4.2030





3C67 2026/05/16 1.68UT TOYOKAWA-FUJI


F20260516103926




BLK:14,SNR1: 3.7654 ,SNR2: 8.5715



T20260516103924




BLK:17,SNR1: 0.57004 ,SNR2: 4.0163





3C67 2026/05/16 1.68UT TOYOKAWA-KISO



K20260516103921




BLK:17,SNR1: 0.74121 ,SNR2: 2.7023



F20260516103926





BLK: 3,SNR1: 0.29039 ,SNR2: 1.6022




Frequency (Hz)

3C67 2026/05/16 1.68UT FUJI -KISO


K20260516103921





BLK: 3,SNR1: 0.48953 ,SNR2: 1.9942




Frequency (Hz)



T20260516105738




BLK: 3,SNR1: 7.2689 ,SNR2: 21.298





3C71 2026/05/16 1.99UT TOYOKAWA-FUJI



F20260516105740




BLK: 3,SNR1: 2.3998 ,SNR2: 8.0800



T20260516105738




BLK: 2,SNR1: 6.4999 ,SNR2: 16.334





3C71 2026/05/16 1.99UT TOYOKAWA-KISO


K20260516105735




BLK: 2,SNR1: 16.284 ,SNR2: 38.699



F20260516105740




BLK: 2,SNR1: 5.4841 ,SNR2: 15.848





3C71 2026/05/16 1.99UT FUJI -KISO


K20260516105735




BLK: 2,SNR1: 10.977 ,SNR2: 26.402




T20260516111654




BLK: 4,SNR1: 0.21303E-01,SNR2: 0.75606




F20260516111656




BLK: 4,SNR1: 1.3343 ,SNR2: 5.6771




0258+350 2026/05/16 2.31UT TOYOKAWA-FUJI





T20260516111654




BLK: 4,SNR1: 0.19642 ,SNR2: 1.0595




K20260516111651




BLK: 4,SNR1: 0.44341 ,SNR2: 1.3650




0258+350 2026/05/16 2.31UT TOYOKAWA-KISO





F20260516111656




BLK: 5,SNR1: 0.22385 ,SNR2: 3.5415




K20260516111651




BLK: 5,SNR1: 0.87215 ,SNR2: 3.8496




0258+350 2026/05/16 2.31UT FUJI -KISO



T20260516112643




BLK: 5,SNR1: 5.5932 ,SNR2: 14.000





0308+305 2026/05/16 2.47UT TOYOKAWA-FUJI


F20260516112645




BLK: 5,SNR1: 13.195 ,SNR2: 31.028



T20260516112643




BLK: 5,SNR1: 3.1183 ,SNR2: 9.0232





0308+305 2026/05/16 2.47UT TOYOKAWA-KISO


K20260516112640




BLK: 5,SNR1: 3.1700 ,SNR2: 10.641





F20260516112645




BLK: 2,SNR1: 1.8946 ,SNR2: 6.5556




K20260516112640





BLK: 2,SNR1: 0.26503 ,SNR2: 0.97886




0308+305 2026/05/16 2.47UT FUJI -KISO




T20260516113814




BLK:10,SNR1: 1.8445 ,SNR2: 7.9081




F20260516113816





BLK:10,SNR1: 0.25863E-01,SNR2: 1.4156




0320+05 2026/05/16 2.67UT TOYOKAWA-FUJI





T20260516113814




BLK:24,SNR1: 1.6636 ,SNR2: 5.2813




K20260516113811




BLK:24,SNR1: 0.31766 ,SNR2: 1.1305




0320+05 2026/05/16 2.67UT TOYOKAWA-KISO





F20260516113816




BLK:11,SNR1: 0.46986E-01,SNR2: 1.4957




K20260516113811





BLK:11,SNR1: 0.31014 ,SNR2: 3.3930




0320+05 2026/05/16 2.67UT FUJI -KISO



T20260516115136





No.Good Data




Frequency (Hz)

F20260516115138




No.Good Data




Frequency (Hz)


0333+32 2026/05/16 2.89UT TOYOKAWA-FUJI





T20260516115136




BLK: 8,SNR1: 14.319 ,SNR2: 25.307




K20260516115133





BLK: 8,SNR1: 12.067 ,SNR2: 21.004




0333+32 2026/05/16 2.89UT TOYOKAWA-KISO



F20260516115138





BLK: 6,SNR1: 8.7197 ,SNR2: 15.650




Frequency (Hz)

K20260516115133




BLK: 6,SNR1: 10.077 ,SNR2: 17.977





Frequency (Hz)


0333+32 2026/05/16 2.89UT FUJI -KISO





T20260516120437




BLK:17,SNR1:-0.24042E-01,SNR2: 0.55450




F20260516120439




BLK:17,SNR1: 8.3896 ,SNR2: 28.583




0347+05 2026/05/16 3.11UT TOYOKAWA-FUJI




T20260516120437




BLK:11,SNR1: 0.29066 ,SNR2: 0.69279




K20260516120434





BLK:11,SNR1: 1.9003 ,SNR2: 4.0031




0347+05 2026/05/16 3.11UT TOYOKAWA-KISO





F20260516120439




BLK:11,SNR1: 4.6463 ,SNR2: 16.272




K20260516120434





BLK:11,SNR1: 4.5419 ,SNR2: 8.8519




0347+05 2026/05/16 3.11UT FUJI -KISO




T20260516122011




BLK: 2,SNR1: 0.58405 ,SNR2: 6.5404




F20260516122013





BLK: 2,SNR1: 0.54266 ,SNR2: 2.3610




0403-132 2026/05/16 3.36UT TOYOKAWA-FUJI





T20260516122011




No. Good Data




K20260516122008




No. Good Data




0403-132 2026/05/16 3.36UT TOYOKAWA-KISO





F20260516122013




BLK: 1,SNR1: 0.68570 ,SNR2: 2.7230




K20260516122008





BLK: 1,SNR1: 2.3366 ,SNR2: 7.6413




0403-132 2026/05/16 3.36UT FUJI -KISO





T20260516122922




BLK: 7,SNR1:-0.46296E-02,SNR2: 0.71194




F20260516122924





BLK: 7,SNR1:-0.99037E-02,SNR2: 1.6965




0411+05 2026/05/16 3.52UT TOYOKAWA-FUJI




T20260516122922




BLK: 9,SNR1:-0.39595E-01,SNR2: 0.56565




K20260516122919




BLK: 9,SNR1: 2.7657 ,SNR2: 7.1318




0411+05 2026/05/16 3.52UT TOYOKAWA-KISO




F20260516122924




BLK: 2,SNR1: 1.6028 ,SNR2: 5.4411




K20260516122919





BLK: 2,SNR1: 5.1582 ,SNR2: 12.904




0411+05 2026/05/16 3.52UT FUJI -KISO




T20260516124016




BLK: 7,SNR1: 5.2917 ,SNR2: 9.4088




F20260516124018





BLK: 7,SNR1: 24.595 ,SNR2: 31.577




0422+178 2026/05/16 3.70UT TOYOKAWA-FUJI





T20260516124016




BLK: 3,SNR1: 2.3241 ,SNR2: 7.6371




K20260516124013




BLK: 3,SNR1: 3.0108 ,SNR2: 6.2856




0422+178 2026/05/16 3.70UT TOYOKAWA-KISO





F20260516124018




BLK: 5,SNR1: 15.413 ,SNR2: 26.730




K20260516124013




BLK: 5,SNR1: 5.3610 ,SNR2: 16.244




0422+178 2026/05/16 3.70UT FUJI -KISO




T20260516124745




BLK:16,SNR1: 1.7155 ,SNR2: 15.131




F20260516124747





BLK:16,SNR1: 2.0937 ,SNR2: 5.1332




3C119 2026/05/16 3.82UT TOYOKAWA-FUJI



T20260516124745





BLK:24,SNR1: 2.8021 ,SNR2: 6.8785




Frequency (Hz)

K20260516124742




BLK:24,SNR1: 1.4797 ,SNR2: 3.1389




Frequency (Hz)


3C119 2026/05/16 3.82UT TOYOKAWA-KISO



F20260516124747




BLK: 5,SNR1: 0.76040 ,SNR2: 2.2783





3C119 2026/05/16 3.82UT FUJI -KISO


K20260516124742




BLK: 5,SNR1: 3.1137 ,SNR2: 6.3575




T20260516133552




BLK:18,SNR1: 2.0382 ,SNR2: 9.9479




F20260516133554





BLK:18,SNR1: 2.1849 ,SNR2: 5.4242




3C138 2026/05/16 4.63UT TOYOKAWA-FUJI





T20260516133552




BLK:20,SNR1: 1.7823 ,SNR2: 11.854




K20260516133549




BLK:20,SNR1: 2.3216 ,SNR2: 4.7490




3C138 2026/05/16 4.63UT TOYOKAWA-KISO



F20260516133554




BLK: 5,SNR1: 2.0416 ,SNR2: 6.2512





3C138 2026/05/16 4.63UT FUJI -KISO


K20260516133549




BLK: 5,SNR1: 0.92546 ,SNR2: 4.1600




T20260516134925




BLK:13,SNR1: 0.56978 ,SNR2: 4.4128




F20260516134927




BLK:13,SNR1:-0.24402 ,SNR2: 1.3430




0531+194 2026/05/16 4.85UT TOYOKAWA-FUJI




T20260516134925




BLK:18,SNR1: 0.79852 ,SNR2: 5.2872




K20260516134922




BLK:18,SNR1: 0.75219 ,SNR2: 2.8273




0531+194 2026/05/16 4.85UT TOYOKAWA-KISO




F20260516134927




BLK: 6,SNR1:-0.70471E-01,SNR2: 1.5410




K20260516134922





BLK: 6,SNR1: 2.0798 ,SNR2: 4.1279




0531+194 2026/05/16 4.85UT FUJI -KISO





T20260516135746




BLK:19,SNR1: 9.0315 ,SNR2: 19.827




F20260516135748





BLK:19,SNR1: 22.825 ,SNR2: 32.427




3C147 2026/05/16 4.99UT TOYOKAWA-FUJI





T20260516135746




BLK:29,SNR1: 9.1097 ,SNR2: 20.047




K20260516135743





BLK:29,SNR1: 9.2701 ,SNR2: 20.505




3C147 2026/05/16 4.99UT TOYOKAWA-KISO





F20260516135748




BLK:13,SNR1: 22.992 ,SNR2: 32.418




K20260516135743





BLK:13,SNR1: 9.2733 ,SNR2: 20.292




3C147 2026/05/16 4.99UT FUJI -KISO





T20260516140556




BLK: 2,SNR1: 0.33580 ,SNR2: 6.8807




F20260516140558





BLK: 2,SNR1:-0.29376 ,SNR2: 0.24097




0548+16 2026/05/16 5.13UT TOYOKAWA-FUJI





T20260516140556




BLK:10,SNR1: 0.25036 ,SNR2: 2.4992




K20260516140553





BLK:10,SNR1: 0.17898 ,SNR2: 0.57597




0548+16 2026/05/16 5.13UT TOYOKAWA-KISO





F20260516140558




BLK: 2,SNR1: 0.56252 ,SNR2: 5.6264




K20260516140553





BLK: 2,SNR1:-0.47164E-01,SNR2: 0.43846




0548+16 2026/05/16 5.13UT FUJI -KISO




T20260516141006




BLK: 7,SNR1: 14.340 ,SNR2: 79.029




F20260516141008





BLK: 7,SNR1: 0.16837 ,SNR2: 1.0574




0552+12 2026/05/16 5.20UT TOYOKAWA-FUJI





T20260516141006




BLK: 9,SNR1: 4.8429 ,SNR2: 25.908




K20260516141003




BLK: 9,SNR1: 0.67481 ,SNR2: 3.0047




0552+12 2026/05/16 5.20UT TOYOKAWA-KISO





F20260516141008




BLK: 7,SNR1: 0.93132 ,SNR2: 2.8185




K20260516141003





BLK: 7,SNR1: 0.53172 ,SNR2: 2.2662




0552+12 2026/05/16 5.20UT FUJI -KISO




T20260516141434




BLK: 4,SNR1: 4.4687 ,SNR2: 35.939




F20260516141436





BLK: 4,SNR1:-0.28399 ,SNR2: 0.93079




0556+191 2026/05/16 5.27UT TOYOKAWA-FUJI





T20260516141434




BLK: 9,SNR1: 5.8420 ,SNR2: 56.036




K20260516141431




BLK: 9,SNR1: 0.60122 ,SNR2: 4.4731




0556+191 2026/05/16 5.27UT TOYOKAWA-KISO



F20260516141436





BLK: 4,SNR1:-0.27054 ,SNR2: 1.4194




Frequency (Hz)

K20260516141431




BLK: 4,SNR1: 0.19116E-01,SNR2: 0.36746




Frequency (Hz)


0556+191 2026/05/16 5.27UT FUJI -KISO





T20260516142218




BLK: 4,SNR1: 6.2134 ,SNR2: 14.659




F20260516142220




BLK: 4,SNR1: 5.4482 ,SNR2: 13.602




0605-08 2026/05/16 5.40UT TOYOKAWA-FUJI




T20260516142218




BLK: 6,SNR1: 3.4040 ,SNR2: 7.8907




K20260516142215





BLK: 6,SNR1: 5.3685 ,SNR2: 13.974




0605-08 2026/05/16 5.40UT TOYOKAWA-KISO



F20260516142220





BLK: 6,SNR1:-0.44490E-02,SNR2: 4.8885




Frequency (Hz)

K20260516142215




BLK: 6,SNR1: 1.9453 ,SNR2: 7.9492





Frequency (Hz)


0605-08 2026/05/16 5.40UT FUJI -KISO



T20260516144126




BLK: 6,SNR1: 1.3227 ,SNR2: 5.0782




Frequency (Hz)

F20260516144128




BLK: 6,SNR1:-0.18643 ,SNR2: 1.0502





Frequency (Hz)


3C161 2026/05/16 5.72UT TOYOKAWA-FUJI




T20260516144126




BLK: 6,SNR1: 0.81061 ,SNR2: 3.3729




K20260516144123




BLK: 6,SNR1: 0.99153 ,SNR2: 6.0231




3C161 2026/05/16 5.72UT TOYOKAWA-KISO




F20260516144128




BLK: 6,SNR1:-0.15876 ,SNR2: 1.0021




K20260516144123





BLK: 6,SNR1: 0.96330 ,SNR2: 5.9730




3C161 2026/05/16 5.72UT FUJI -KISO



T20260516150859





BLK: 6,SNR1: 5.3915 ,SNR2: 17.217




Frequency (Hz)

F20260516150901




BLK: 6,SNR1: 7.2119 ,SNR2: 22.412





Frequency (Hz)


0652-130 2026/05/16 6.18UT TOYOKAWA-FUJI




T20260516150859




BLK: 6,SNR1: 5.7929 ,SNR2: 18.161




K20260516150856




BLK: 6,SNR1: 5.4111 ,SNR2: 17.599




0652-130 2026/05/16 6.18UT TOYOKAWA-KISO




F20260516150901




BLK: 2,SNR1: 4.5602 ,SNR2: 14.969




K20260516150856





BLK: 2,SNR1: 5.4578 ,SNR2: 17.816




0652-130 2026/05/16 6.18UT FUJI -KISO



T20260516152036




BLK: 6,SNR1: 3.7024 ,SNR2: 10.866




Frequency (Hz)

F20260516152038




BLK: 6,SNR1: 4.9286 ,SNR2: 9.1575





Frequency (Hz)


0703+138 2026/05/16 6.37UT TOYOKAWA-FUJI



T20260516152036




BLK: 7,SNR1: 3.6782 ,SNR2: 10.805




Frequency (Hz)

K20260516152033




BLK: 7,SNR1: 9.5785 ,SNR2: 14.311




Frequency (Hz)


0703+138 2026/05/16 6.37UT TOYOKAWA-KISO



F20260516152038




BLK:16,SNR1: 4.8636 ,SNR2: 8.7504




Frequency (Hz)

K20260516152033




BLK:16,SNR1: 4.7944 ,SNR2: 12.392





Frequency (Hz)


0703+138 2026/05/16 6.37UT FUJI -KISO



T20260516152959





BLK: 3,SNR1: 11.659 ,SNR2: 33.793




Frequency (Hz)

F20260516153001




BLK: 3,SNR1: 8.7162 ,SNR2: 24.863





Frequency (Hz)


0713-024 2026/05/16 6.53UT TOYOKAWA-FUJI



T20260516152959





BLK: 1,SNR1: 13.122 ,SNR2: 31.694




Frequency (Hz)

K20260516152956




BLK: 1,SNR1: 13.933 ,SNR2: 36.571





Frequency (Hz)


0713-024 2026/05/16 6.53UT TOYOKAWA-KISO



F20260516153001





BLK: 5,SNR1: 8.8009 ,SNR2: 25.109




Frequency (Hz)

K20260516152956




BLK: 5,SNR1: 10.084 ,SNR2: 25.167





Frequency (Hz)


0713-024 2026/05/16 6.53UT FUJI -KISO





T20260516154011




No.Good Data




F20260516154013




No.Good Data




0723+10 2026/05/16 6.70UT TOYOKAWA-FUJI



T20260516154011




BLK: 2,SNR1: 4.0829 ,SNR2: 9.8351




Frequency (Hz)

K20260516154008




BLK: 2,SNR1: 4.3104 ,SNR2: 13.733





Frequency (Hz)


0723+10 2026/05/16 6.70UT TOYOKAWA-KISO



F20260516154013




No.Good Data




Frequency (Hz)

K20260516154008




No.Good Data





Frequency (Hz)


0723+10 2026/05/16 6.70UT FUJI -KISO



T20260516155026




BLK: 2,SNR1: 1.3342 ,SNR2: 4.5303




Frequency (Hz)

F20260516155028




BLK: 2,SNR1: 4.0076 ,SNR2: 13.771





Frequency (Hz)


0732+33 2026/05/16 6.87UT TOYOKAWA-FUJI



T20260516155026




BLK: 1,SNR1: 1.6063 ,SNR2: 5.4026




Frequency (Hz)

K20260516155023




BLK: 1,SNR1: 3.0720 ,SNR2: 9.8796




Frequency (Hz)


0732+33 2026/05/16 6.87UT TOYOKAWA-KISO



F20260516155028




BLK: 2,SNR1: 5.0412 ,SNR2: 15.969




Frequency (Hz)

K20260516155023




BLK: 2,SNR1: 7.7621 ,SNR2: 22.175





Frequency (Hz)


0732+33 2026/05/16 6.87UT FUJI -KISO



T20260516155827





No.Good Data




Frequency (Hz)

F20260516155829




No.Good Data





Frequency (Hz)


0741-06 2026/05/16 7.00UT TOYOKAWA-FUJI



T20260516155827





BLK: 4,SNR1: 0.18789 ,SNR2: 1.9369




Frequency (Hz)

K20260516155824




BLK: 4,SNR1: 0.36970 ,SNR2: 2.1480





Frequency (Hz)


0741-06 2026/05/16 7.00UT TOYOKAWA-KISO





F20260516155829




No.Good Data




K20260516155824




No.Good Data




0741-06 2026/05/16 7.00UT FUJI -KISO



T20260516160811




BLK: 6,SNR1: 0.97785E-01,SNR2: 2.0229




Frequency (Hz)

F20260516160813




BLK: 6,SNR1: 6.1077 ,SNR2: 16.363





Frequency (Hz)


0752-200 2026/05/16 7.16UT TOYOKAWA-FUJI



T20260516160811





BLK: 4,SNR1: 0.33254E-01,SNR2: 1.2617




Frequency (Hz)

K20260516160808




BLK: 4,SNR1: 0.26862 ,SNR2: 1.2111




Frequency (Hz)


0752-200 2026/05/16 7.16UT TOYOKAWA-KISO



F20260516160813





BLK: 4,SNR1: 1.8973 ,SNR2: 12.967




Frequency (Hz)

K20260516160808




BLK: 4,SNR1: 0.50963 ,SNR2: 3.9466




Frequency (Hz)


0752-200 2026/05/16 7.16UT FUJI -KISO



T20260516161547





BLK: 3,SNR1: 12.370 ,SNR2: 22.152




Frequency (Hz)

F20260516161549




BLK: 3,SNR1: 8.1568 ,SNR2: 24.787




Frequency (Hz)


3C190 2026/05/16 7.29UT TOYOKAWA-FUJI



T20260516161547





BLK: 9,SNR1: 10.057 ,SNR2: 24.320




Frequency (Hz)

K20260516161544





BLK: 9,SNR1: 8.8775 ,SNR2: 22.628





Frequency (Hz)

3C190 2026/05/16 7.29UT TOYOKAWA-KISO







BLK: 9,SNR1: 7.0929 ,SNR2: 17.704





BLK: 9,SNR1: 8.8700 ,SNR2: 22.611




3C190 2026/05/16 7.29UT FUJI -KISO



T20260516162813




BLK: 2,SNR1:-0.23228 ,SNR2: 0.67753E-01




Frequency (Hz)

F20260516162815




BLK: 2,SNR1: 0.53617E-01,SNR2: 1.8633





Frequency (Hz)


3C196 2026/05/16 7.50UT TOYOKAWA-FUJI





T20260516162813




BLK: 5,SNR1: 0.52600E-01,SNR2: 0.38630




K20260516162810





BLK: 5,SNR1: 0.29956 ,SNR2: 0.92469




3C196 2026/05/16 7.50UT TOYOKAWA-KISO



F20260516162815





BLK: 1,SNR1: 0.29432 ,SNR2: 1.1449




Frequency (Hz)

K20260516162810




BLK: 1,SNR1: 0.27211 ,SNR2: 0.74772





Frequency (Hz)


3C196 2026/05/16 7.50UT FUJI -KISO



T20260516163922





BLK:10,SNR1: 8.2239 ,SNR2: 19.044




Frequency (Hz)

F20260516163924




BLK:10,SNR1: 7.1668 ,SNR2: 19.196




Frequency (Hz)


0821+394 2026/05/16 7.68UT TOYOKAWA-FUJI



T20260516163922




BLK: 6,SNR1: 9.0949 ,SNR2: 20.303




Frequency (Hz)

K20260516163919




BLK: 6,SNR1: 8.7186 ,SNR2: 22.508




Frequency (Hz)


0821+394 2026/05/16 7.68UT TOYOKAWA-KISO



F20260516163924




BLK:10,SNR1: 6.9769 ,SNR2: 17.837




Frequency (Hz)

K20260516163919




BLK:10,SNR1: 9.3643 ,SNR2: 28.696




Frequency (Hz)


0821+394 2026/05/16 7.68UT FUJI -KISO



T20260516170707





No.Good Data




Frequency (Hz)

F20260516170709




No.Good Data





Frequency (Hz)


3C208 2026/05/16 8.15UT TOYOKAWA-FUJI



T20260516170707





BLK: 2, SNR1: 10.058 , SNR2: 36.195




Frequency (Hz)

3C208 2026/05/16 8.15UT TOYOKAWA-KISO


K20260516170704





BLK: 2, SNR1: 2.6866 , SNR2: 14.973




Frequency (Hz)



F20260516170709





BLK: 2,SNR1: 1.0046 ,SNR2: 3.6222




Frequency (Hz)

K20260516170704




BLK: 2,SNR1: 9.6764 ,SNR2: 20.424




Frequency (Hz)


3C208 2026/05/16 8.15UT FUJI -KISO



T20260516172350





BLK: 5, SNR1: 7.1056 , SNR2: 18.320




Frequency (Hz)

F20260516172352




BLK: 5, SNR1: 11.917 , SNR2: 28.392




Frequency (Hz)


3C216 2026/05/16 8.43UT TOYOKAWA-FUJI



T20260516172350




BLK: 1, SNR1: 1.9171 , SNR2: 4.9129




Frequency (Hz)

K20260516172347




BLK: 1, SNR1: 3.0261 , SNR2: 9.0846




Frequency (Hz)


3C216 2026/05/16 8.43UT TOYOKAWA-KISO



F20260516172352




BLK: 4,SNR1: 13.901 ,SNR2: 24.328




Frequency (Hz)

K20260516172347




BLK: 4,SNR1: 7.7170 ,SNR2: 20.274





Frequency (Hz)


3C216 2026/05/16 8.43UT FUJI -KISO



T20260516174112





No.Good Data




Frequency (Hz)

F20260516174114




No.Good Data





Frequency (Hz)


0923+392 2026/05/16 8.71UT TOYOKAWA-FUJI



T20260516174112





BLK: 1,SNR1: 0.23308E-01,SNR2: 1.1936




Frequency (Hz)

K20260516174109




BLK: 1,SNR1: 1.0586 ,SNR2: 4.4446





Frequency (Hz)


0923+392 2026/05/16 8.71UT TOYOKAWA-KISO



F20260516174114





No.Good Data




Frequency (Hz)

K20260516174109




No.Good Data





Frequency (Hz)


0923+392 2026/05/16 8.71UT FWJ -KISO



T20260516174914




BLK: 3,SNR1: 0.29535 ,SNR2: 1.8428




Frequency (Hz)

F20260516174916




BLK: 3,SNR1: 9.5545 ,SNR2: 25.414





Frequency (Hz)


0931+399 2026/05/16 8.85UT TOYOKAWA-FUJI



T20260516174914





BLK: 1,SNR1: 0.56866E-02,SNR2: 1.3695




Frequency (Hz)

K20260516174911




BLK: 1,SNR1: 1.4500 ,SNR2: 7.2100





Frequency (Hz)


0931+399 2026/05/16 8.85UT TOYOKAWA-KISO



F20260516174916





BLK: 7,SNR1: 0.68848 ,SNR2: 2.8615




Frequency (Hz)

K20260516174911



BLK: 7,SNR1: 0.72572 ,SNR2: 2.8948



Frequency (Hz)

0931+399 2026/05/16 8.85UT FUJI -KISO

