




T20260522054610




BLK: 1,SNR1: 12.281 ,SNR2: 30.013




F20260522054610





BLK: 1,SNR1: 9.3516 ,SNR2: 23.025




2152+450 2026/05/21 20.80UT TOYOKAWA-FUJI



T20260522054610





BLK: 3,SNR1: 17.572 ,SNR2: 31.304




Frequency (Hz)

K20260522054607




BLK: 3,SNR1: 19.960 ,SNR2: 42.973





Frequency (Hz)


2152+450 2026/05/21 20.80UT TOYOKAWA-KISO



F20260522054610





BLK: 2,SNR1: 23.906 ,SNR2: 42.005




Frequency (Hz)

K20260522054607




BLK: 2,SNR1: 22.429 ,SNR2: 40.964





Frequency (Hz)


2152+450 2026/05/21 20.80UT FUJI -KISO



T20260522055435





BLK: 2,SNR1: 0.23783 ,SNR2: 0.68715




Frequency (Hz)

F20260522055435




BLK: 2,SNR1: 0.82880E-01,SNR2: 1.3570





Frequency (Hz)


2200+420 2026/05/21 20.94UT TOYOKAWA-FUJI



T20260522055435





BLK: 1,SNR1: 0.34943E-01,SNR2: 1.2475




Frequency (Hz)

K20260522055432




BLK: 1,SNR1: 2.2056 ,SNR2: 11.818





Frequency (Hz)


2200+420 2026/05/21 20.94UT TOYOKAWA-KISO



F20260522055435





BLK: 2,SNR1: 11.083 ,SNR2: 26.790




Frequency (Hz)

K20260522055432




BLK: 2,SNR1: 1.1288 ,SNR2: 8.9387





Frequency (Hz)


2200+420 2026/05/21 20.94UT FUJI -KISO



T20260522060116





No.Good Data




Frequency (Hz)

F20260522060116




No.Good Data





Frequency (Hz)


2207+374 2026/05/21 21.05UT TOYOKAWA-FUJI



T20260522060116





BLK: 1,SNR1: 0.24141 ,SNR2: 5.8704




Frequency (Hz)

2207+374 2026/05/21 21.05UT TOYOKAWA-KISO


K20260522060113





BLK: 1,SNR1: 6.2812 ,SNR2: 11.774




Frequency (Hz)



F20260522060116





BLK: 1,SNR1: 2.7088 ,SNR2: 8.4366




Frequency (Hz)

K20260522060113




BLK: 1,SNR1: 5.8101 ,SNR2: 15.941





Frequency (Hz)


2207+374 2026/05/21 21.05UT FUJI -KISO



T20260522063739





BLK: 2,SNR1: 6.1463 ,SNR2: 15.813





2243+394 2026/05/21 21.66UT TOYOKAWA-FUJI



F20260522063740




BLK: 2,SNR1: 8.2048 ,SNR2: 20.369





T20260522063739




BLK: 3,SNR1: 6.9830 ,SNR2: 17.754




K20260522063736




BLK: 3,SNR1: 6.7769 ,SNR2: 17.254




2243+394 2026/05/21 21.66UT TOYOKAWA-KISO



F20260522063740





BLK: 3,SNR1: 6.4478 ,SNR2: 16.860




Frequency (Hz)

2243+394 2026/05/21 21.66UT FUJI -KISO


K20260522063736




BLK: 3,SNR1: 6.0347 ,SNR2: 14.928




Frequency (Hz)



T20260522064553





BLK:16,SNR1: 13.095 ,SNR2: 29.859




Frequency (Hz)

F20260522064553




BLK:16,SNR1: 13.506 ,SNR2: 30.775




Frequency (Hz)


3C454.3 2026/05/21 21.79UT TOYOKAWA-FUJI




T20260522064553




No.Good Data




KISO





No.Good Data




3C454.3 2026/05/21 21.79UT TOYOKAWA-KISO




F20280522064553




No.Good Data




KISO





No.Good Data




3C454.3 2026/05/21 21.79UT FUJI -KISO



T20260522065335





BLK: 4,SNR1: 1.6240 ,SNR2: 14.982




Frequency (Hz)

2259+481 2026/05/21 21.92UT TOYOKAWA-FUJI


F20260522065335





BLK: 4,SNR1: 2.6108 ,SNR2: 6.3448




Frequency (Hz)





T20280522065335




No.Good Data




KISO





No.Good Data




2259+481 2026/05/21 21.92UT TOYOKAWA-KISO





F20280522065335




No.Good Data




KISO





No.Good Data




2259+481 2026/05/21 21.92UT FUJI -KISO



T20260522070829





No.Good Data




Frequency (Hz)

F20260522070829




No.Good Data





Frequency (Hz)


3C459 2026/05/21 22.17UT TOYOKAWA-FUJI



T20260522070829





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C459 2026/05/21 22.17UT TOYOKAWA-KISO





F20260522070829




No.Good Data




KISO





No.Good Data




3C459 2026/05/21 22.17UT FUJI -KISO



T20260522074214





BLK: 5, SNR1: 13.653 ,SNR2: 34.583




Frequency (Hz)

2347-02 2026/05/21 22.73UT TOYOKAWA-FUJI


F20260522074214





BLK: 5, SNR1: 10.784 ,SNR2: 31.284




Frequency (Hz)



T20260522074214





BLK: 6,SNR1: 13.351 ,SNR2: 32.231




Frequency (Hz)

K20260522074211




BLK: 6,SNR1: 9.8616 ,SNR2: 29.436





Frequency (Hz)


2347-02 2026/05/21 22.73UT TOYOKAWA-KISO



F20260522074214





BLK: 5,SNR1: 9.8042 ,SNR2: 28.461




Frequency (Hz)

K20260522074211




BLK: 5,SNR1: 9.4073 ,SNR2: 27.660





Frequency (Hz)


2347-02 2026/05/21 22.73UT FUJI -KISO



T20260522074908





BLK: 3,SNR1: 3.8146 ,SNR2: 11.703




Frequency (Hz)

2354+14 2026/05/21 22.85UT TOYOKAWA-FUJI


F20260522074908





BLK: 3,SNR1: 9.6467 ,SNR2: 17.301




Frequency (Hz)



T20260522074908





BLK: 3,SNR1: 3.8218 ,SNR2: 11.721




Frequency (Hz)

2354+14 2026/05/21 22.85UT TOYOKAWA-KISO


K20260522074905





BLK: 3,SNR1: 11.243 ,SNR2: 17.160




Frequency (Hz)



F20260522074908





BLK: 4,SNR1: 9.3691 ,SNR2: 16.822




Frequency (Hz)

K20260522074905




BLK: 4,SNR1: 3.7980 ,SNR2: 11.624





Frequency (Hz)


2354+14 2026/05/21 22.85UT FUJI -KISO



T20260522075811



BLK: 4,SNR1: 1.9128 ,SNR2: 5.5832




Frequency (Hz)


3C2

2026/05/21 23.00UT TOYOKAWA-FUJI


F20260522075811





BLK: 4,SNR1: 9.7733 ,SNR2: 24.947




Frequency (Hz)





T20260522075811




No.Good Data




K20260522075808





No.Good Data




3C2 2026/05/21 23.00UT TOYOKAWA-KISO



F20260522075811





BLK: 5,SNR1: 11.978 ,SNR2: 28.908




Frequency (Hz)

3C2 2026/05/21 23.00UT FUJI -KISO


K20260522075808





BLK: 5,SNR1: 9.2568 ,SNR2: 23.608




Frequency (Hz)



T20260522080532





BLK: 2,SNR1:-0.36581E-01,SNR2: 0.56583




Frequency (Hz)

F20260522080532




BLK: 2,SNR1: 7.4242 ,SNR2: 13.165





Frequency (Hz)


0011+344 2026/05/21 23.12UT TOYOKAWA-FUJI



T20260522080532




BLK: 2,SNR1: 0.29100 ,SNR2: 1.6956




Frequency (Hz)

K20260522080529




BLK: 2,SNR1: 3.6531 ,SNR2: 13.093





Frequency (Hz)


0011+344 2026/05/21 23.12UT TOYOKAWA-KISO



F20260522080532





BLK: 1,SNR1: 0.98818 ,SNR2: 5.5774




Frequency (Hz)

K20260522080529




BLK: 1,SNR1: 1.5874 ,SNR2: 21.202





Frequency (Hz)


0011+344 2026/05/21 23.12UT FUJI -KISO



T20260522081409





BLK: 4,SNR1: 1.5936 ,SNR2: 3.1776




Frequency (Hz)

0019-00 2026/05/21 23.26UT TOYOKAWA-FUJI


F20260522081409





BLK: 4,SNR1: 0.64360 ,SNR2: 3.6376




Frequency (Hz)



T20260522081409





BLK: 3,SNR1: 6.7055 ,SNR2: 18.790




Frequency (Hz)

0019-00 2026/05/21 23.28UT TOYOKAWA-KISO


K20260522081407





BLK: 3,SNR1: 1.6382 ,SNR2: 15.942




Frequency (Hz)





F20260522081409




BLK: 3,SNR1: 0.76300 ,SNR2: 3.3447




K20260522081407





BLK: 3,SNR1: 2.0579 ,SNR2: 6.4902




0019-00 2026/05/21 23.26UT FUJI -KISO



T20260522082423





BLK: 3,SNR1: 6.5355 ,SNR2: 17.127




Frequency (Hz)

3C12 2026/05/21 23.43UT TOYOKAWA-FUJI


F20260522082423




BLK: 3,SNR1: 0.23886 ,SNR2: 2.4959




Frequency (Hz)



T20260522082423




BLK: 5,SNR1: 4.6783 ,SNR2: 13.229




Frequency (Hz)

3C12 2026/05/21 23.43UT TOYOKAWA-KISO


K20260522082421




BLK: 5,SNR1: 0.66303 ,SNR2: 3.4726




Frequency (Hz)



F20260522082423




BLK: 9,SNR1: 1.2263 ,SNR2: 6.9756




Frequency (Hz)

3C12 2026/05/21 23.43UT FUJI -KISO


K20260522082421





BLK: 9,SNR1: 0.74839 ,SNR2: 2.8979




Frequency (Hz)



T20260522083825





BLK: 6,SNR1: 50.013 ,SNR2: 69.039




Frequency (Hz)

F20260522083825




BLK: 6,SNR1: 1.0008 ,SNR2: 3.7709





Frequency (Hz)


0044-056 2026/05/21 23.67UT TOYOKAWA-FUJI



T20260522083825





BLK: 5,SNR1: 2.4023 ,SNR2: 5.8507




Frequency (Hz)

K20260522083822




BLK: 5,SNR1: 6.2330 ,SNR2: 15.565




Frequency (Hz)


0044-056 2026/05/21 23.67UT TOYOKAWA-KISO





F20260522083825




BLK: 8,SNR1: 2.0933 ,SNR2: 5.2010




K20260522083822





BLK: 8,SNR1: 6.1393 ,SNR2: 15.399




0044-056 2026/05/21 23.67UT FUJI -KISO



T20260522084546





BLK: 3,SNR1: 0.17060 ,SNR2: 2.0015




Frequency (Hz)

3C26 2026/05/21 23.79UT TOYOKAWA-FUJI


F20260522084546





BLK: 3,SNR1:-0.44548E-01,SNR2: 1.4883




Frequency (Hz)



T20260522084546





BLK: 1,SNR1: 0.29793E-01,SNR2: 3.6830




Frequency (Hz)

3C26 2026/05/21 23.79UT TOYOKAWA-KISO


K20260522084544





BLK: 1,SNR1: 1.8007 ,SNR2: 7.3764




Frequency (Hz)



F20260522084546




BLK: 4,SNR1: 2.8257 ,SNR2: 5.2158





3C26 2026/05/21 23.79UT FUJI -KISO


K20260522084544




BLK: 4,SNR1: 1.2254 ,SNR2: 4.5492



T20260522085045





BLK: 1,SNR1: 3.8937 ,SNR2: 9.2380




Frequency (Hz)

0056-00 2026/05/21 23.87UT TOYOKAWA-FUJI


F20260522085045





BLK: 1,SNR1: 12.314 ,SNR2: 27.232




Frequency (Hz)



T20260522085045




BLK: 2,SNR1: 4.1050 ,SNR2: 22.478




Frequency (Hz)

0056-00 2026/05/21 23.87UT TOYOKAWA-KISO


K20260522085043




BLK: 2,SNR1: 4.6171 ,SNR2: 8.9364




Frequency (Hz)




F20260522085045




No.Good Data




K20260522085043





No.Good Data




0056-00 2026/05/21 23.87UT FUJI -KISO



T20260522090027





BLK: 6, SNR1: 36.213 , SNR2: 63.622




Frequency (Hz)

F20260522090027




BLK: 6, SNR1: 22.074 , SNR2: 34.034





Frequency (Hz)


0106+01 2026/05/22 0.04UT TOYOKAWA-FUJI



T20260522090027





BLK: 3,SNR1: 100.87 ,SNR2: 173.55




Frequency (Hz)

0106+01 2026/05/22 0.04UT TOYOKAWA-KISO


K20260522090024




BLK: 3,SNR1: 19.370 ,SNR2: 33.654




Frequency (Hz)




F20260522090027




BLK: 4, SNR1: 22.225 ,SNR2: 34.268




K20260522090024




BLK: 4, SNR1: 13.408 ,SNR2: 24.117




0106+01 2026/05/22 0.04UT FUJI -KISO



T20260522091117





BLK:11,SNR1: 6.9640 ,SNR2: 12.094





0116+31 2026/05/22 0.22UT TOYOKAWA-FUJI


F20260522091117




BLK:11,SNR1: 1.1347 ,SNR2: 6.1340



T20260522091117





BLK:11,SNR1: 8.0320 ,SNR2: 13.793





0116+31 2026/05/22 0.22UT TOYOKAWA-KISO



K20260522091115




BLK:11,SNR1: 6.0304 ,SNR2: 10.641





F20260522091117




BLK:12,SNR1: 11.089 ,SNR2: 19.787




K20260522091115





BLK:12,SNR1: 7.4872 ,SNR2: 13.413




0116+31 2026/05/22 0.22UT FUJI -KISO




T20260522092250




BLK: 6,SNR1: 0.89877E-01,SNR2: 0.63249




F20260522092250





BLK: 6,SNR1:-0.97528E-01,SNR2: 0.51707




0128+03 2026/05/22 0.41UT TOYOKAWA-FUJI



T20260522092250





BLK: 4, SNR1: 0.17963 , SNR2: 1.0617




0128+03 2026/05/22 0.41UT TOYOKAWA-KISO


K20260522092248




BLK: 4, SNR1: 0.89056 , SNR2: 4.3901




Frequency (Hz)





F20260522092250




BLK: 2,SNR1: 0.66742E-01,SNR2: 2.0026




K20260522092248





BLK: 2,SNR1: 1.2607 ,SNR2: 9.8340




0128+03 2026/05/22 0.41UT FUJI -KISO



T20260522092924





BLK: 4, SNR1: 24.382 , SNR2: 43.988




3C48 2026/05/22 0.52UT TOYOKAWA-FUJI


F20260522092924




BLK: 4, SNR1: 11.204 , SNR2: 27.403




Frequency (Hz)



T20260522092924




BLK: 4, SNR1: 12.136 ,SNR2: 29.644





3C48 2026/05/22 0.52UT TOYOKAWA-KISO


K20260522092921




BLK: 4, SNR1: 24.698 ,SNR2: 32.258



F20260522092924




BLK: 2, SNR1: 24.027 ,SNR2: 43.373





3C48 2026/05/22 0.52UT FUJI -KISO



K20260522092921




BLK: 2, SNR1: 18.894 ,SNR2: 37.487



T20260522094908




BLK: 1,SNR1: 17.803 ,SNR2: 31.859





0155-109 2026/05/22 0.85UT TOYOKAWA-FUJI



F20260522094908




BLK: 1,SNR1: 22.502 ,SNR2: 39.876





T20260522094908




No. Good Data




K20260522094906




No. Good Data




0155-109 2026/05/22 0.85UT TOYOKAWA-KISO



F20260522094908




BLK: 1, SNR1: 11.341 , SNR2: 28.166





0155-109 2026/05/22 0.85UT FUJI -KISO



K20260522094906




BLK: 1, SNR1: 21.055 , SNR2: 38.062





T20260522095616




BLK:15,SNR1: 0.41691 ,SNR2: 2.2000




F20260522095616





BLK:15,SNR1: 0.58494 ,SNR2: 6.2222




0202+15 2026/05/22 0.97UT TOYOKAWA-FUJI



T20260522095616





BLK:14,SNR1: 0.31983 ,SNR2: 3.5437





0202+15 2026/05/22 0.97UT TOYOKAWA-KISO


K20260522095614




BLK:14,SNR1: 0.42731 ,SNR2: 1.6230




F20260522095616




BLK: 4,SNR1: 0.67120E-01,SNR2: 0.60042




K20260522095614





BLK: 4,SNR1: 0.40169 ,SNR2: 1.4395




0202+15 2026/05/22 09:57 UT FUJI -KISO



T20260522100806





BLK:14,SNR1: 0.80676 ,SNR2: 9.8069





0213+178 2026/05/22 1.16UT TOYOKAWA-FUJI



F20260522100807




BLK:14,SNR1: 7.8789 ,SNR2: 14.172



T20260522100806




BLK:17,SNR1: 8.0109 ,SNR2: 20.695





0213+178 2026/05/22 1.16UT TOYOKAWA-KISO



K20260522100803




BLK:17,SNR1: 7.9000 ,SNR2: 20.465




F20260522100807




BLK:25,SNR1: 7.5156 ,SNR2: 13.516




K20260522100803





BLK:25,SNR1: 7.9172 ,SNR2: 20.506




0213+178 2026/05/22 1.16UT FUJI -KISO



T20260522101549





BLK: 3,SNR1: 22.236 ,SNR2: 34.295




Frequency (Hz)

3C67 2026/05/22 1.29UT TOYOKAWA-FUJI


F20260522101549




BLK: 3,SNR1: 21.663 ,SNR2: 39.410




Frequency (Hz)



T20260522101549





BLK: 4,SNR1: 12.318 ,SNR2: 21.842




Frequency (Hz)

3C67 2026/05/22 1.29UT TOYOKAWA-KISO


K20260522101546




BLK: 4,SNR1: 20.577 ,SNR2: 36.099




Frequency (Hz)



F20260522101549




BLK: 4,SNR1: 22.291 ,SNR2: 40.238





3C67 2026/05/22 1.29UT FUJI -KISO



K20260522101546




BLK: 4,SNR1: 7.5774 ,SNR2: 17.829



T20260522103403




BLK: 7, SNR1: 9.3577 ,SNR2: 16.743





3C71 2026/05/22 1.60UT TOYOKAWA-FUJI



F20260522103403




BLK: 7, SNR1: 8.5551 ,SNR2: 19.565



T20260522103403




BLK: 7, SNR1: 9.1035 ,SNR2: 16.290





3C71 2026/05/22 1.60UT TOYOKAWA-KISO


K20260522103400




BLK: 7, SNR1: 8.2644 ,SNR2: 12.684



F20260522103403




BLK: 1,SNR1: 9.8655 ,SNR2: 23.134





3C71 2026/05/22 1.60UT FUJI -KISO



K20260522103400




BLK: 1,SNR1: 10.185 ,SNR2: 19.320




T20260522105319




BLK: 7,SNR1: 0.19677 ,SNR2: 0.72303




F20260522105319





BLK: 7,SNR1: 7.9221 ,SNR2: 14.408




0258+350 2026/05/22 1.92UT TOYOKAWA-FUJI




T20260522105319




BLK: 4,SNR1:-0.11790E-02,SNR2: 0.52368




K20260522105316




BLK: 4,SNR1: 0.97500 ,SNR2: 5.3026




0258+350 2026/05/22 1.92UT TOYOKAWA-KISO




F20260522105319




BLK: 7,SNR1: 8.8630 ,SNR2: 15.741




K20260522105316




BLK: 7,SNR1: 1.1090 ,SNR2: 6.3862




0258+350 2026/05/22 1.92UT FUJI -KISO





T20260522110308




BLK:16,SNR1: 5.5013 ,SNR2: 9.6831




F20260522110308




BLK:16,SNR1: 9.5115 ,SNR2: 16.819





0308+305 2026/05/22 2.08UT TOYOKAWA-FUJI







BLK:18,SNR1: 5.1457 ,SNR2: 11.734





BLK:18,SNR1: 7.8051 ,SNR2: 14.156




0308+305 2026/05/22 2.08UT TOYOKAWA-KISO



F20260522110308





BLK:25,SNR1: 9.4798 ,SNR2: 16.758





0308+305 2026/05/22 2.08UT FUJI -KISO


K20260522110305




BLK:25,SNR1: 2.5662 ,SNR2: 8.1155



T20260522111439




BLK:11,SNR1: 1.7384 ,SNR2: 16.815




0320+05 2026/05/22 2.27UT TOYOKAWA-FUJI


F20260522111439




BLK:11,SNR1: 5.9701 ,SNR2: 10.669




Frequency (Hz)




T20260522111439




BLK:19,SNR1: 1.6412 ,SNR2: 5.3231




K20260522111436




BLK:19,SNR1: 1.0066 ,SNR2: 3.4666




0320+05 2026/05/22 2.27UT TOYOKAWA-KISO




F20260522111439




BLK:13,SNR1:-0.23751 ,SNR2: 0.58984




K20260522111436




BLK:13,SNR1: 1.1414 ,SNR2: 3.9966




0320+05 2026/05/22 2.27UT FUJI -KISO





T20260522112801




BLK:11,SNR1: 0.21839 ,SNR2: 2.2309




F20260522112801




BLK:11,SNR1: 0.12407 ,SNR2: 1.7151




0333+32 2026/05/22 2.50UT TOYOKAWA-FUJI





T20260522112801




BLK:20,SNR1: 0.23050 ,SNR2: 1.7337




K20260522112758




BLK:20,SNR1: 6.2600 ,SNR2: 17.198




0333+32 2026/05/22 2.50UT TOYOKAWA-KISO





F20260522112801




BLK:16,SNR1: 1.6129 ,SNR2: 4.4266




K20260522112758





BLK:16,SNR1: 1.0075 ,SNR2: 3.3355




0333+32 2026/05/22 2.50UT FUJI -KISO



T20260522114102




BLK: 9,SNR1: 0.91401 ,SNR2: 3.0923





0347+05 2026/05/22 2.71UT TOYOKAWA-FUJI



F20260522114102




BLK: 9,SNR1: 6.1617 ,SNR2: 15.089




T20260522114102




BLK:10,SNR1: 0.38620 ,SNR2: 1.6265




K20260522114059




BLK:10,SNR1: 5.2089 ,SNR2: 13.526




0347+05 2026/05/22 2.71UT TOYOKAWA-KISO




F20260522114102




BLK: 1,SNR1: 5.0017 ,SNR2: 12.233




K20260522114059





BLK: 1,SNR1: 3.2364 ,SNR2: 9.4271




0347+05 2026/05/22 2.71UT FUJI -KISO




T20260522115636




BLK: 5,SNR1: 0.77008 ,SNR2: 4.3079




F20260522115636





BLK: 5,SNR1: 4.8881 ,SNR2: 7.0652




0403-132 2026/05/22 2.97UT TOYOKAWA-FUJI





T20260522115636




BLK: 5,SNR1: 12.065 ,SNR2: 18.526




K20260522115634




BLK: 5,SNR1: 4.4529 ,SNR2: 10.667




0403-132 2026/05/22 2.97UT TOYOKAWA-KISO





F20260522115636




BLK: 4,SNR1: 5.2773 ,SNR2: 8.6890




K20260522115634





BLK: 4,SNR1: 1.5126 ,SNR2: 5.0534




0403-132 2026/05/22 2.97UT FUJI -KISO





T20260522120547




BLK: 9,SNR1: 0.17197 ,SNR2: 1.2320




F20260522120547





BLK: 9,SNR1: 9.9603 ,SNR2: 18.396




0411+05 2026/05/22 3.12UT TOYOKAWA-FUJI





T20260522120547




BLK:11,SNR1: 0.33684 ,SNR2: 0.75901




K20260522120545





BLK:11,SNR1: 7.9400 ,SNR2: 19.340




0411+05 2026/05/22 3.12UT TOYOKAWA-KISO




F20260522120547




BLK:11,SNR1: 12.379 ,SNR2: 29.160




K20260522120545





BLK:11,SNR1: 7.3937 ,SNR2: 13.684




0411+05 2026/05/22 3.12UT FUJI -KISO




T20260522121640




BLK: 5, SNR1: 24.872 , SNR2: 58.153




F20260522121640





BLK: 5, SNR1: 18.357 , SNR2: 32.599




0422+178 2026/05/22 3.31UT TOYOKAWA-FUJI




T20260522121640




BLK: 6, SNR1: 29.810 , SNR2: 75.453




K20260522121637




BLK: 6, SNR1: 17.228 , SNR2: 40.470




0422+178 2026/05/22 3.31UT TOYOKAWA-KISO



F20260522121640




BLK: 2,SNR1: 17.214 ,SNR2: 39.829





0422+178 2026/05/22 3.31UT FUJI -KISO


K20260522121637




BLK: 2,SNR1: 18.712 ,SNR2: 33.892





T20260522122410




BLK:21,SNR1: 3.2587 ,SNR2: 7.8261




F20260522122410




BLK:21,SNR1:-0.20407 ,SNR2: 0.88110




3C119 2026/05/22 3.43UT TOYOKAWA-FUJI




T20260522122410




BLK:34,SNR1: 3.0476 ,SNR2: 9.2057




K20260522122407





BLK:34,SNR1: 0.55616 ,SNR2: 3.7072




3C119 2026/05/22 3.43UT TOYOKAWA-KISO



F20260522122410





BLK:18,SNR1:-0.45802E-02,SNR2: 3.0021




Frequency (Hz)

K20260522122407




BLK:18,SNR1: 0.63265 ,SNR2: 5.6703




Frequency (Hz)


3C119 2026/05/22 3.43UT FUJI -KISO




T20260522131216




BLK:27,SNR1: 4.9565 ,SNR2: 13.142




F20260522131216




BLK:27,SNR1: 0.10932 ,SNR2: 2.1412




3C138 2026/05/22 4.23UT TOYOKAWA-FUJI





T20260522131216




BLK:21,SNR1: 5.1725 ,SNR2: 34.281




K20260522131213




BLK:21,SNR1: 0.95739 ,SNR2: 4.8864




3C138 2026/05/22 4.23UT TOYOKAWA-KISO





F20260522131216




BLK:21,SNR1:-0.83546E-01,SNR2: 2.0175




K20260522131213





BLK:21,SNR1: 0.92352 ,SNR2: 4.4663




3C138 2026/05/22 4.23UT FUJI -KISO



T20260522132550





BLK: 4,SNR1: 0.90859 ,SNR2: 5.3570




Frequency (Hz)

F20260522132550




BLK: 4,SNR1: 0.81103 ,SNR2: 4.9996





Frequency (Hz)


0531+194 2026/05/22 4.46UT TOYOKAWA-FUJI



T20260522132550





BLK: 3,SNR1: 6.4965 ,SNR2: 20.776




Frequency (Hz)

K20260522132548




BLK: 3,SNR1: 1.5198 ,SNR2: 7.5578




Frequency (Hz)


0531+194 2026/05/22 4.46UT TOYOKAWA-KISO




F20260522132550




BLK: 3,SNR1: 11.002 ,SNR2: 26.964




K20260522132548





BLK: 3,SNR1: 5.9677 ,SNR2: 15.384




0531+194 2026/05/22 4.46UT FUJI -KISO





T20260522133411




BLK:23,SNR1: 7.6802 ,SNR2: 13.429




F20260522133411





BLK:23,SNR1: 2.1192 ,SNR2: 7.5935




3C147 2026/05/22 4.60UT TOYOKAWA-FUJI




T20260522133411




BLK:23,SNR1: 7.7258 ,SNR2: 13.510




K20260522133408





BLK:23,SNR1: 9.1935 ,SNR2: 19.670




3C147 2026/05/22 4.60UT TOYOKAWA-KISO



F20260522133411





BLK:14,SNR1: 2.2704 ,SNR2: 8.3481





3C147 2026/05/22 4.60UT FUJI -KISO



K20260522133408




BLK:14,SNR1: 5.6647 ,SNR2: 8.7443



T20260522134221




BLK: 8,SNR1: 0.27440 ,SNR2: 1.6914




Frequency (Hz)

F20260522134221




BLK: 8,SNR1: 0.59060 ,SNR2: 1.8853





Frequency (Hz)


0548+16 2026/05/22 4.73UT TOYOKAWA-FUJI





T20260522134221




BLK:10,SNR1: 0.38421 ,SNR2: 2.3537




K20260522134218




BLK:10,SNR1: 0.76576 ,SNR2: 2.7256




0548+16 2026/05/22 4.73UT TOYOKAWA-KISO





F20260522134221




BLK: 7,SNR1: 0.25203 ,SNR2: 1.5928




K20260522134218





BLK: 7,SNR1: 0.43314 ,SNR2: 1.6879




0548+16 2026/05/22 4.73UT FUJI -KISO





T20260522134631




BLK: 4,SNR1: 9.6898 ,SNR2: 27.364




F20260522134631





BLK: 4,SNR1: 22.765 ,SNR2: 26.942




0552+12 2026/05/22 4.80UT TOYOKAWA-FUJI




T20260522134631




BLK: 9,SNR1: 7.6671 ,SNR2: 18.824




K20260522134628





BLK: 9,SNR1: 10.056 ,SNR2: 25.196




0552+12 2026/05/22 4.80UT TOYOKAWA-KISO




F20260522134631




BLK: 1,SNR1: 111.15 ,SNR2: 105.47




K20260522134628





BLK: 1,SNR1: 2.9554 ,SNR2: 11.197




0552+12 2026/05/22 4.80UT FUJI -KISO





T20260522135058




BLK: 9,SNR1: 5.4784 ,SNR2: 13.280




F20260522135058





BLK: 9,SNR1: 8.2060 ,SNR2: 22.073




0556+191 2026/05/22 4.88UT TOYOKAWA-FUJI




T20260522135058




BLK: 2,SNR1: 6.1647 ,SNR2: 14.966




K20260522135056





BLK: 2,SNR1: 4.6029 ,SNR2: 11.632




0556+191 2026/05/22 4.88UT TOYOKAWA-KISO





F20260522135058




BLK: 7,SNR1: 6.3610 ,SNR2: 15.866




K20260522135056




BLK: 7,SNR1: 6.3947 ,SNR2: 18.752




0556+191 2026/05/22 4.88UT FUJI -KISO





T20260522135843




BLK: 1,SNR1: 18.541 ,SNR2: 39.037




F20260522135843




BLK: 1,SNR1: 8.3501 ,SNR2: 19.812




0605-08 2026/05/22 5.01UT TOYOKAWA-FUJI





T20260522135843




BLK: 1,SNR1: 9.3499 ,SNR2: 23.158




K20260522135840





BLK: 1,SNR1: 10.643 ,SNR2: 26.487




0605-08 2026/05/22 5.01UT TOYOKAWA-KISO





F20260522135843




BLK: 1,SNR1: 4.3056 ,SNR2: 13.047




K20260522135840





BLK: 1,SNR1: 11.613 ,SNR2: 29.303




0605-08 2026/05/22 5.01UT FUJI -KISO





T20260522141751




No.Good Data




F20260522141751




No.Good Data




3C161 2026/05/22 5.33UT TOYOKAWA-FUJI



T20260522141751





BLK: 2,SNR1: 7.2237 ,SNR2: 17.404





3C161 2026/05/22 5.33UT TOYOKAWA-KISO


K20260522141748




BLK: 2,SNR1: 74.412 ,SNR2: 80.353



F20260522141751





BLK: 4,SNR1: 2.2916 ,SNR2: 22.961





3C161 2026/05/22 5.33UT FUJI -KISO



K20260522141748




BLK: 4,SNR1: 148.31 ,SNR2: 152.06




T20260522144524




BLK: 2,SNR1: 9.8695 ,SNR2: 24.370




F20260522144524




BLK: 2,SNR1: 10.839 ,SNR2: 27.011




0652-130 2026/05/22 5.78UT TOYOKAWA-FUJI




T20260522144524




BLK: 3,SNR1: 8.3590 ,SNR2: 21.543




K20260522144521




BLK: 3,SNR1: 15.592 ,SNR2: 30.419




0652-130 2026/05/22 5.78UT TOYOKAWA-KISO




F20260522144524




BLK: 3,SNR1: 10.354 ,SNR2: 24.999




K20260522144521





BLK: 3,SNR1: 13.775 ,SNR2: 33.013




0652-130 2026/05/22 5.78UT FUJI -KISO




T20260522145701




BLK: 3,SNR1: 2.9192 ,SNR2: 5.9078




F20260522145701





BLK: 3,SNR1: 13.673 ,SNR2: 24.155




0703+138 2026/05/22 5.98UT TOYOKAWA-FUJI




T20260522145701




BLK: 3,SNR1: 4.9917 ,SNR2: 7.7890




K20260522145658




BLK: 3,SNR1: 14.828 ,SNR2: 30.555




0703+138 2026/05/22 5.98UT TOYOKAWA-KISO




F20260522145701




BLK: 3,SNR1: 9.4768 ,SNR2: 23.284




K20260522145658




BLK: 3,SNR1: 8.8081 ,SNR2: 21.738




0703+138 2026/05/22 5.98UT FUJI -KISO




T20260522150623




BLK: 2,SNR1: 10.206 ,SNR2: 25.094




F20260522150623




BLK: 2,SNR1: 13.592 ,SNR2: 33.145






0713-024 2026/05/22 6.13UT TOYOKAWA-FUJI




T20260522150623




K20260522150621




0713-024 2026/05/22 6.13UT TOYOKAWA-KISO





F20260522150623




BLK: 6,SNR1: 11.679 ,SNR2: 25.226




K20260522150621





BLK: 6,SNR1: 15.132 ,SNR2: 31.523




0713-024 2026/05/22 6.13UT FUJI -KISO





T20260522151635




BLK: 3,SNR1: 8.7784 ,SNR2: 21.619




F20260522151635




BLK: 3,SNR1: 9.2006 ,SNR2: 22.671




0723+10 2026/05/22 6.30UT TOYOKAWA-FUJI





T20260522151635




BLK: 2,SNR1: 10.695 ,SNR2: 26.057




K20260522151632




BLK: 2,SNR1: 9.8259 ,SNR2: 24.153




0723+10 2026/05/22 6.30UT TOYOKAWA-KISO





F20260522151635




BLK: 1,SNR1: 7.6556 ,SNR2: 15.823




K20260522151632




BLK: 1,SNR1: 7.4208 ,SNR2: 18.471




0723+10 2026/05/22 6.30UT FUJI -KISO




T20260522152651




BLK: 4,SNR1: 9.3212 ,SNR2: 22.695




F20260522152651





BLK: 4,SNR1: 7.8607 ,SNR2: 19.475




0732+33 2026/05/22 6.48UT TOYOKAWA-FUJI




T20260522152651




BLK: 4,SNR1: 9.8474 ,SNR2: 23.872




K20260522152648





BLK: 4,SNR1: 8.2261 ,SNR2: 20.229




0732+33 2026/05/22 6.48UT TOYOKAWA-KISO



F20260522152651





BLK: 3,SNR1: 7.8534 ,SNR2: 19.625




Frequency (Hz)

K20260522152648




BLK: 3,SNR1: 13.192 ,SNR2: 29.275





Frequency (Hz)


0732+33 2026/05/22 6.48UT FUJI -KISO




T20260522153451




BLK: 1,SNR1: 0.45133 ,SNR2: 4.0309




F20260522153451





BLK: 1,SNR1:-0.26453 ,SNR2: 0.77812




0741-06 2026/05/22 6.61UT TOYOKAWA-FUJI




T20260522153451




BLK: 3,SNR1: 0.34608 ,SNR2: 1.0705




K20260522153448




BLK: 3,SNR1: 0.93032 ,SNR2: 4.0473




0741-06 2026/05/22 6.61UT TOYOKAWA-KISO




F20260522153451




BLK: 2,SNR1: 1.6160 ,SNR2: 4.4219




K20260522153448




BLK: 2,SNR1:-0.27721E-01,SNR2: 0.46828




0741-06 2026/05/22 6.61UT FUJI -KISO



T20260522154435





BLK: 5,SNR1: 9.5891 ,SNR2: 25.063




Frequency (Hz)

F20260522154435




BLK: 5,SNR1:-0.96412E-01,SNR2: 1.8841





Frequency (Hz)


0752-200 2026/05/22 6.77UT TOYOKAWA-FUJI



T20260522154435





BLK: 3,SNR1: 4.5244 ,SNR2: 8.0352




Frequency (Hz)

K20260522154433




BLK: 3,SNR1: 2.4835 ,SNR2: 7.9055





Frequency (Hz)


0752-200 2026/05/22 6.77UT TOYOKAWA-KISO





F20260522154435




BLK:10,SNR1: 7.1376 ,SNR2: 18.386




K20260522154433





BLK:10,SNR1: 7.1374 ,SNR2: 19.006




0752-200 2026/05/22 6.77UT FUJI -KISO



T20260522155211





No.Good Data




Frequency (Hz)

F20260522155211




No.Good Data





Frequency (Hz)


3C190 2026/05/22 6.90UT TOYOKAWA-FUJI



T20260522155211





BLK: 2,SNR1: 9.5563 ,SNR2: 23.398




Frequency (Hz)

K20260522155208




BLK: 2,SNR1: 24.469 ,SNR2: 59.002




Frequency (Hz)


3C190 2026/05/22 6.90UT TOYOKAWA-KISO



F20260522155211




BLK: 1,SNR1: 18.379 ,SNR2: 32.615




Frequency (Hz)

K20260522155208




BLK: 1,SNR1: 20.906 ,SNR2: 46.780




Frequency (Hz)


3C190 2026/05/22 6.90UT FUJI -KISO



T20260522160437




BLK: 1,SNR1: 7.6531 ,SNR2: 18.990




Frequency (Hz)

F20260522160437




BLK: 1,SNR1: 5.9688 ,SNR2: 18.703





Frequency (Hz)


3C196 2026/05/22 7.11UT TOYOKAWA-FUJI





T20260522160437




No.Good Data




K20260522160434




No.Good Data




3C196 2026/05/22 7.11UT TOYOKAWA-KISO



F20260522160437




BLK: 2,SNR1: 12.854 ,SNR2: 27.621




Frequency (Hz)

K20260522160434




BLK: 2,SNR1: 12.143 ,SNR2: 26.161





Frequency (Hz)


3C196 2026/05/22 7.11UT FUJI -KISO





T20260522161547




BLK: 3,SNR1: 0.31692E-01,SNR2: 1.0312




F20260522161547





BLK: 3,SNR1: 6.9904 ,SNR2: 14.222




0821+394 2026/05/22 7.29UT TOYOKAWA-FUJI




T20260522161547




BLK: 1,SNR1: 0.10669 ,SNR2: 0.88357




K20260522161544




BLK: 1,SNR1: 9.1978 ,SNR2: 13.783




0821+394 2026/05/22 7.29UT TOYOKAWA-KISO



F20260522161547




BLK: 3,SNR1: 23.920 ,SNR2: 38.501




Frequency (Hz)

K20260522161544




BLK: 3,SNR1: 4.3461 ,SNR2: 11.471




Frequency (Hz)


0821+394 2026/05/22 7.29UT FUJI -KISO



T20260522163230




BLK: 9,SNR1: 15.036 ,SNR2: 36.691




Frequency (Hz)

F20260522163230




BLK: 9,SNR1: 8.4956 ,SNR2: 20.947




Frequency (Hz)


0839-071 2026/05/22 7.57UT TOYOKAWA-FUJI



T20260522163230




BLK: 6,SNR1: 24.700 ,SNR2: 60.194




Frequency (Hz)

K20260522163227




BLK: 6,SNR1: 9.6316 ,SNR2: 18.263




Frequency (Hz)


0839-071 2026/05/22 7.57UT TOYOKAWA-KISO



F20260522163230




BLK: 3,SNR1: 2.1194 ,SNR2: 7.9536




Frequency (Hz)

K20260522163227




BLK: 3,SNR1: 10.979 ,SNR2: 19.134





Frequency (Hz)


0839-071 2026/05/22 7.57UT FUJI -KISO



T20260522164332





BLK: 8,SNR1: 8.3365 ,SNR2: 14.660




Frequency (Hz)

F20260522164332




BLK: 8,SNR1: 2.9453 ,SNR2: 9.0375





Frequency (Hz)


3C208 2026/05/22 7.75UT TOYOKAWA-FUJI



T20260522164332





BLK: 8,SNR1: 9.3986 ,SNR2: 27.622




Frequency (Hz)

K20260522164329




BLK: 8,SNR1: 8.5449 ,SNR2: 15.954





Frequency (Hz)


3C208 2026/05/22 7.75UT TOYOKAWA-KISO



F20260522164332





BLK: 7,SNR1: 2.9964 ,SNR2: 9.1733




Frequency (Hz)

K20260522164329




BLK: 7,SNR1: 8.4048 ,SNR2: 15.700





Frequency (Hz)


3C208 2026/05/22 7.75UT FUJI -KISO



T20260522170014





BLK: 6,SNR1: 0.44453 ,SNR2: 3.1161




Frequency (Hz)

F20260522170014




BLK: 6,SNR1: 7.3396 ,SNR2: 18.451





Frequency (Hz)


3C216 2026/05/22 8.03UT TOYOKAWA-FUJI



T20260522170014





BLK: 3,SNR1: 0.18799 ,SNR2: 2.1578




Frequency (Hz)

K20260522170011




BLK: 3,SNR1: 2.6638 ,SNR2: 8.8273




Frequency (Hz)


3C216 2026/05/22 8.03UT TOYOKAWA-KISO



F20260522170014





BLK: 3,SNR1: 3.2149 ,SNR2: 7.5338




Frequency (Hz)

K20260522170011



BLK: 3,SNR1: 3.9260 ,SNR2: 12.897



Frequency (Hz)

3C216 2026/05/22 8.03UT FUJI -KISO

