




T20260525053422





BLK: 1,SNR1: 0.50170 ,SNR2: 8.0532




Frequency (Hz)

F20260525053422




BLK: 1,SNR1: 0.55769 ,SNR2: 3.6839





Frequency (Hz)


2152+450 2026/05/24 20.60UT TOYOKAWA-FUJI



T20260525053422





BLK: 2,SNR1: 0.46104 ,SNR2: 2.9612




Frequency (Hz)

K20260525053419




BLK: 2,SNR1: 0.59090 ,SNR2: 4.2436





Frequency (Hz)


2152+450 2026/05/24 20.60UT TOYOKAWA-KISO



F20260525053422





BLK: 1,SNR1: 5.6716 ,SNR2: 18.604




Frequency (Hz)

K20260525053419




BLK: 1,SNR1: 0.61680 ,SNR2: 5.5464





Frequency (Hz)


2152+450 2026/05/24 20.60UT FUJI -KISO



T20260525054248





BLK: 5, SNR1: 5.0921 ,SNR2: 13.687




Frequency (Hz)

F20260525054248




BLK: 5, SNR1: 7.1435 ,SNR2: 18.525





Frequency (Hz)


2200+420 2026/05/24 20.74UT TOYOKAWA-FUJI



T20260525054248





BLK: 8,SNR1: 5.0292 ,SNR2: 13.376




Frequency (Hz)

K20260525054245




BLK: 8,SNR1: 5.0564 ,SNR2: 13.391




Frequency (Hz)


2200+420 2026/05/24 20.74UT TOYOKAWA-KISO



F20260525054248




BLK: 9,SNR1: 4.5915 ,SNR2: 12.543




Frequency (Hz)

K20260525054245




BLK: 9,SNR1: 4.9459 ,SNR2: 15.594





Frequency (Hz)


2200+420 2026/05/24 20.74UT FUJI -KISO



T20260525054928





BLK: 4,SNR1:-0.41925E-01,SNR2: 0.65285




Frequency (Hz)

F20260525054928




BLK: 4,SNR1: 5.9662 ,SNR2: 14.314





Frequency (Hz)


2207+374 2026/05/24 20.85UT TOYOKAWA-FUJI



T20260525054928





BLK: 8,SNR1: 1.3481 ,SNR2: 3.9373




Frequency (Hz)

K20260525054925




BLK: 8,SNR1: 2.1886 ,SNR2: 5.3602




Frequency (Hz)


2207+374 2026/05/24 20.85UT TOYOKAWA-KISO



F20260525054928





BLK: 5,SNR1: 6.9488 ,SNR2: 17.112




Frequency (Hz)

K20260525054925




BLK: 5,SNR1: 2.2847 ,SNR2: 6.7546





Frequency (Hz)


2207+374 2026/05/24 20.85UT FUJI -KISO



T20260525060925





BLK: 2,SNR1: 9.3220 ,SNR2: 23.215




Frequency (Hz)

F20260525060925




BLK: 2,SNR1: 11.425 ,SNR2: 28.045





Frequency (Hz)


2227+444 2026/05/24 21.19UT TOYOKAWA-FUJI



T20260525060925





BLK: 4,SNR1: 8.1919 ,SNR2: 20.479




Frequency (Hz)

K20260525060922




BLK: 4,SNR1: 9.6427 ,SNR2: 23.794





Frequency (Hz)


2227+444 2026/05/24 21.19UT TOYOKAWA-KISO



F20260525060925





BLK: 2,SNR1: 9.4002 ,SNR2: 23.192




Frequency (Hz)

2227+444 2026/05/24 21.19UT FUJI -KISO


K20260525060922





BLK: 2,SNR1: 9.7501 ,SNR2: 24.051




Frequency (Hz)



T20260525062134





BLK:22,SNR1: 8.0244 ,SNR2: 24.308




Frequency (Hz)

F20260525062135




BLK:22,SNR1: 15.224 ,SNR2: 34.804





Frequency (Hz)


2239+333 2026/05/24 21.39UT TOYOKAWA-FUJI



T20260525062134





BLK:23,SNR1: 7.9080 ,SNR2: 23.968




Frequency (Hz)

K20260525062131




BLK:23,SNR1: 8.7848 ,SNR2: 25.195





Frequency (Hz)


2239+333 2026/05/24 21.39UT TOYOKAWA-KISO



F20260525062135





BLK:20,SNR1: 14.711 ,SNR2: 34.391




Frequency (Hz)

K20260525062131




BLK:20,SNR1: 9.7002 ,SNR2: 28.184





Frequency (Hz)


2239+333 2026/05/24 21.39UT FUJI -KISO



T20260525062551





BLK: 4,SNR1: 10.363 ,SNR2: 26.377




Frequency (Hz)

F20260525062551




BLK: 4,SNR1: 12.397 ,SNR2: 23.143





Frequency (Hz)


2243+394 2026/05/24 21.46UT TOYOKAWA-FUJI



T20260525062551





BLK: 4,SNR1: 7.4702 ,SNR2: 21.282




Frequency (Hz)

K20260525062548




BLK: 4,SNR1: 15.928 ,SNR2: 39.280





Frequency (Hz)


2243+394 2026/05/24 21.46UT TOYOKAWA-KISO



F20260525062551





BLK: 4,SNR1: 7.7877 ,SNR2: 20.626




Frequency (Hz)

K20260525062548




BLK: 4,SNR1: 13.185 ,SNR2: 32.056





Frequency (Hz)


2243+394 2026/05/24 21.46UT FUJI -KISO





T20260525063405




No.Good Data




F20260525063405





No.Good Data




3C454.3 2026/05/24 21.60UT TOYOKAWA-FUJI



T20260525063405





No.Good Data




Frequency (Hz)

K20260525063402




No.Good Data





Frequency (Hz)


3C454.3 2026/05/24 21.60UT TOYOKAWA-KISO



F20260525063405





BLK: 1,SNR1: 19.173 ,SNR2: 34.200




Frequency (Hz)

3C454.3 2026/05/24 21.60UT FUJI -KISO


K20260525063402





BLK: 1,SNR1: 7.1366 ,SNR2: 21.681




Frequency (Hz)



T20260525064147





BLK: 2,SNR1: 0.60157E-01,SNR2: 0.61741




Frequency (Hz)

F20260525064147




BLK: 2,SNR1: 0.68469E-02,SNR2: 1.3519





Frequency (Hz)


2259+481 2026/05/24 21.72UT TOYOKAWA-FUJI



T20260525064147





BLK: 1,SNR1: 0.41671 ,SNR2: 1.6485




Frequency (Hz)

K20260525064144




BLK: 1,SNR1: 0.82278 ,SNR2: 4.5934





Frequency (Hz)


2259+481 2026/05/24 21.72UT TOYOKAWA-KISO



F20260525064147





BLK: 2,SNR1: 0.37953 ,SNR2: 2.7462




Frequency (Hz)

K20260525064144




BLK: 2,SNR1: 2.2014 ,SNR2: 6.4265




Frequency (Hz)


2259+481 2026/05/24 21.72UT FUJI -KISO



T20260525065642




BLK: 3,SNR1: 3.9009 ,SNR2: 12.199




Frequency (Hz)

3C459 2026/05/24 21.97UT TOYOKAWA-FUJI


F20260525065642





BLK: 3,SNR1: 8.4773 ,SNR2: 21.915




Frequency (Hz)



T20260525065642





No.Good Data




Frequency (Hz)

K20260525065639




No.Good Data





Frequency (Hz)


3C459 2026/05/24 21.97UT TOYOKAWA-KISO



F20260525065642





BLK: 2,SNR1: 8.7229 ,SNR2: 22.551




Frequency (Hz)

3C459 2026/05/24 21.97UT FUJI -KISO


K20260525065639





BLK: 2,SNR1: 4.1411 ,SNR2: 12.949




Frequency (Hz)



T20260525070802





BLK: 2,SNR1: 10.428 ,SNR2: 23.058




Frequency (Hz)

F20260525070802




BLK: 2,SNR1: 9.6730 ,SNR2: 22.145





Frequency (Hz)


2325+269 2026/05/24 22.16UT TOYOKAWA-FUJI



T20260525070802





No.Good Data




Frequency (Hz)

K20260525070759




No.Good Data





Frequency (Hz)


2325+269 2026/05/24 22.16UT TOYOKAWA-KISO




F20260525070802




BLK: 3,SNR1: 9.7495 ,SNR2: 21.797




K20260525070759





BLK: 3,SNR1: 4.2280 ,SNR2: 12.324




2325+269 2026/05/24 22.16UT FUJI -KISO




T20260525073027




BLK: 6,SNR1: 0.13940 ,SNR2: 1.2072




F20260525073027





BLK: 6,SNR1: 5.3791 ,SNR2: 9.7261




2347-02 2026/05/24 22.54UT TOYOKAWA-FUJI





T20260525073027




BLK: 7,SNR1: 1.3539 ,SNR2: 2.3424




K20260525073024




BLK: 7,SNR1: 0.84085 ,SNR2: 3.5175




2347-02 2026/05/24 22.54UT TOYOKAWA-KISO



F20260525073027





BLK: 4,SNR1:-0.10639 ,SNR2: 0.48199




Frequency (Hz)

K20260525073024




BLK: 4,SNR1: 0.36027 ,SNR2: 1.4920





Frequency (Hz)


2347-02 2026/05/24 22.54UT FUJI -KISO



T20260525073720




BLK: 4,SNR1: 100.54 ,SNR2: 134.26





2354+14 2026/05/24 22.65UT TOYOKAWA-FUJI



F20260525073720




BLK: 4,SNR1: 3.8159 ,SNR2: 7.2082



T20260525073720





BLK: 1,SNR1: 100.95 ,SNR2: 134.81




Frequency (Hz)

K20260525073717




BLK: 1,SNR1: 0.22464 ,SNR2: 0.67155




Frequency (Hz)


2354+14 2026/05/24 22.65UT TOYOKAWA-KISO



F20260525073720





BLK: 8,SNR1: 5.1828 ,SNR2: 15.018




Frequency (Hz)

K20260525073717




BLK: 8,SNR1: 6.2778 ,SNR2: 12.132




Frequency (Hz)


2354+14 2026/05/24 22.65UT FUJI -KISO



T20260525074623



BLK: 1,SNR1: 63.834 ,SNR2: 99.008





Frequency (Hz)


3C2

2026/05/24 22.80UT TOYOKAWA-FUJI


F20260525074623





BLK: 1,SNR1: 10.047 ,SNR2: 24.858




Frequency (Hz)



T20260525074623



BLK: 1,SNR1: 93.408 ,SNR2: 166.41





Frequency (Hz)


3C2

2026/05/24 22.80UT TOYOKAWA-KISO


K20260525074620





BLK: 1,SNR1: 16.696 ,SNR2: 40.405




Frequency (Hz)



F20260525074623



BLK: 3,SNR1: 9.8189 ,SNR2: 24.457





Frequency (Hz)


3C2

2026/05/24 22.80UT FUJI -KISO


K20260525074620




BLK: 3,SNR1: 18.635 ,SNR2: 42.735




Frequency (Hz)



T20260525075345





BLK:14,SNR1: 1.9352 ,SNR2: 4.9295





0011+344 2026/05/24 22.92UT TOYOKAWA-FUJI


F20260525075345




BLK:14,SNR1: 2.5784 ,SNR2: 7.5851



T20260525075345




BLK: 6,SNR1: 0.37306 ,SNR2: 1.4016




Frequency (Hz)

K20260525075342




BLK: 6,SNR1: 4.8418 ,SNR2: 8.7035




Frequency (Hz)


0011+344 2026/05/24 22.92UT TOYOKAWA-KISO




F20260525075345




BLK:16,SNR1: 2.0245 ,SNR2: 5.0853




K20260525075342





BLK:16,SNR1: 5.7065 ,SNR2: 9.7998




0011+344 2026/05/24 22.92UT FUJI -KISO



T20260525080221





BLK: 4,SNR1: 0.45775E-01,SNR2: 0.59087




Frequency (Hz)

F20260525080221




BLK: 4,SNR1:-0.98224E-01,SNR2: 1.4692





Frequency (Hz)


0019-00 2026/05/24 23.07UT TOYOKAWA-FUJI



T20260525080221




BLK: 5,SNR1: 0.14520 ,SNR2: 0.63940





0019-00 2026/05/24 23.07UT TOYOKAWA-KISO


K20260525080218




BLK: 5,SNR1: 1.3091 ,SNR2: 4.7794





F20260525080221




BLK: 4,SNR1:-0.41201E-01,SNR2: 1.8557




K20260525080218




BLK: 4,SNR1: 13.815 ,SNR2: 21.272







0019-00 2026/05/24 23.07UT FUJI -KISO




T20260525081236




F20260525081236



T20260525081236




BLK: 4,SNR1: 10.842 ,SNR2: 26.895





3C12 2026/05/24 23.24UT TOYOKAWA-KISO


K20260525081233




BLK: 4,SNR1: 15.489 ,SNR2: 27.535



F20260525081236




BLK: 3,SNR1: 16.134 ,SNR2: 28.969





3C12 2026/05/24 23.24UT FUJI -KISO



K20260525081233




BLK: 3,SNR1: 13.058 ,SNR2: 23.211





T20260525082637




BLK: 3,SNR1: 0.11930 ,SNR2: 1.1065




F20260525082637





BLK: 3,SNR1: 1.6384 ,SNR2: 3.3247




0044-056 2026/05/24 23.47UT TOYOKAWA-FUJI




T20260525082637




BLK: 8,SNR1: 3.6493 ,SNR2: 17.076




K20260525082634




BLK: 8,SNR1: 0.75107 ,SNR2: 2.7656




0044-056 2026/05/24 23.47UT TOYOKAWA-KISO




F20260525082637




BLK: 9,SNR1:-0.75548E-02,SNR2: 0.88023




K20260525082634




BLK: 9,SNR1: 0.84794 ,SNR2: 2.9558




0044-056 2026/05/24 23.47UT FUJI -KISO



T20260525083359




BLK: 3,SNR1: 0.72995E-01,SNR2: 1.3511




Frequency (Hz)

3C26 2026/05/24 23.59UT TOYOKAWA-FUJI


F20260525083359




BLK: 3,SNR1: 2.3824 ,SNR2: 5.8014




Frequency (Hz)



T20260525083359




BLK: 6,SNR1: 0.43321E-01,SNR2: 0.44575




Frequency (Hz)

3C26 2026/05/24 23.59UT TOYOKAWA-KISO


K20260525083356





BLK: 6,SNR1: 1.9809 ,SNR2: 4.1757




Frequency (Hz)



F20260525083359





BLK: 2,SNR1: 1.4300 ,SNR2: 3.0165




Frequency (Hz)

3C26 2026/05/24 23.59UT FUJI -KISO


K20260525083356





BLK: 2,SNR1: 1.1303 ,SNR2: 4.1935




Frequency (Hz)



T20260525083857




BLK: 1,SNR1: 0.52235 ,SNR2: 3.8346





0056-00 2026/05/24 23.68UT TOYOKAWA-FUJI



F20260525083857




BLK: 1,SNR1: 0.80931 ,SNR2: 5.8817



T20260525083857





BLK: 1,SNR1: 10.125 ,SNR2: 25.222





0056-00 2026/05/24 23.68UT TOYOKAWA-KISO


K20260525083854




BLK: 1,SNR1: 11.407 ,SNR2: 27.983




F20260525083857




BLK: 1,SNR1: 13.768 ,SNR2: 33.083




K20260525083854





BLK: 1,SNR1: 11.407 ,SNR2: 27.983




0056-00 2026/05/24 23.68UT FUJI -KISO



T20260525084840




BLK: 6,SNR1: 9.5845 ,SNR2: 96.002





0106+01 2026/05/24 23.84UT TOYOKAWA-FUJI


F20260525084840




BLK: 6,SNR1:-0.10170 ,SNR2: 0.85504



T20260525084840





BLK: 3,SNR1: 0.88969E-02,SNR2: 0.37651





0106+01 2026/05/24 23.84UT TOYOKAWA-KISO


K20260525084837




BLK: 3,SNR1: 0.32156 ,SNR2: 1.3301





F20260525084840




BLK:16,SNR1: 2.3277 ,SNR2: 6.2508




K20260525084837




BLK:16,SNR1: 7.8433 ,SNR2: 14.064




0106+01 2026/05/24 23.84UT FUJI -KISO



T20260525091102




BLK: 4,SNR1: 6.0074 ,SNR2: 5.8543





0128+03 2026/05/25 0.21UT TOYOKAWA-FUJI


F20260525091102




BLK: 4,SNR1: 3.2535 ,SNR2: 10.349



T20260525091102





BLK: 4, SNR1: 6.3608 , SNR2: 6.1593





0128+03 2026/05/25 0.21UT TOYOKAWA-KISO


K20260525091059




BLK: 4, SNR1: 8.9833 , SNR2: 17.394





F20260525091102




BLK: 4,SNR1: 16.987 ,SNR2: 38.230




K20260525091059





BLK: 4,SNR1: 0.86777E-01,SNR2: 4.1681




0128+03 2026/05/25 0.21UT FUJI -KISO



T20260525091736




BLK:26,SNR1: 6.0779 ,SNR2: 41.304





3C48 2026/05/25 0.32UT TOYOKAWA-FUJI



F20260525091736




BLK:26,SNR1: 5.9536 ,SNR2: 16.048



T20260525091736





BLK:29,SNR1: 6.1345 ,SNR2: 40.269





3C48 2026/05/25 0.32UT TOYOKAWA-KISO


K20260525091733




BLK:29,SNR1: 1.7247 ,SNR2: 6.7464



F20260525091736





BLK:26,SNR1: 1.9126 ,SNR2: 5.1294





3C48 2026/05/25 0.32UT FUJI -KISO



K20260525091733




BLK:26,SNR1: 1.5108 ,SNR2: 5.8756



T20260525093720





BLK: 4,SNR1: 0.50920 ,SNR2: 1.4556




Frequency (Hz)

F20260525093720




BLK: 4,SNR1: 0.17617 ,SNR2: 2.9815





Frequency (Hz)


0155-109 2026/05/25 0.65UT TOYOKAWA-FUJI



T20260525093720





BLK: 3,SNR1: 0.19128 ,SNR2: 2.0007




Frequency (Hz)

0155-109 2026/05/25 0.65UT TOYOKAWA-KISO


K20260525093717





BLK: 3,SNR1: 2.1681 ,SNR2: 10.675




Frequency (Hz)



F20260525093720





BLK: 1,SNR1: 3.7356 ,SNR2: 9.0991




Frequency (Hz)

K20260525093717




BLK: 1,SNR1: 0.21696 ,SNR2: 1.5856





Frequency (Hz)


0155-109 2026/05/25 0.65UT FUJI -KISO



T20260525094428





BLK:15,SNR1: 1.4489 ,SNR2: 19.572





0202+15 2026/05/25 0.77UT TOYOKAWA-FUJI



F20260525094428




BLK:15,SNR1: 6.4135 ,SNR2: 11.493



T20260525094428





BLK:17,SNR1: 1.9098 ,SNR2: 23.563





0202+15 2026/05/25 0.77UT TOYOKAWA-KISO



K20260525094425




BLK:17,SNR1: 1.1905 ,SNR2: 5.8255





F20260525094428




BLK: 5,SNR1: 8.4952 ,SNR2: 15.092




K20260525094425





BLK: 5,SNR1: 1.3470 ,SNR2: 7.7747




0202+15 2026/05/25 0.77UT FUJI -KISO




T20260525095618




No.Good Data




F20260525095618





No.Good Data




0213+178 2026/05/25 0.97UT TOYOKAWA-FUJI



T20260525095618





BLK: 1,SNR1: 1.2304 ,SNR2: 6.3329





0213+178 2026/05/25 0.97UT TOYOKAWA-KISO


K20260525095616




BLK: 1,SNR1: 2.3721 ,SNR2: 9.4551



F20260525095618




BLK: 1,SNR1: 0.23307 ,SNR2: 4.6778





0213+178 2026/05/25 0.97UT FUJI -KISO


K20260525095616




BLK: 1,SNR1: 1.2046 ,SNR2: 5.6757



T20260525100401




BLK:16,SNR1: 1.8204 ,SNR2: 12.674





3C67 2026/05/25 1.10UT TOYOKAWA-FUJI


F20260525100401




BLK:16,SNR1: 6.3818 ,SNR2: 17.246



T20260525100401





BLK:23,SNR1: 1.6223 ,SNR2: 11.187





3C67 2026/05/25 1.10UT TOYOKAWA-KISO



K20260525100358




BLK:23,SNR1: 0.54479 ,SNR2: 2.1388



F20260525100401




BLK:20,SNR1: 0.37400 ,SNR2: 1.2961





3C67 2026/05/25 1.10UT FUJI -KISO


K20260525100358




BLK:20,SNR1: 0.59012 ,SNR2: 2.0691



T20260525102215




BLK: 4,SNR1: 1.8015 ,SNR2: 4.0293





3C71 2026/05/25 1.40UT TOYOKAWA-FUJI



F20260525102215




BLK: 4,SNR1: 3.2441 ,SNR2: 9.0531





T20260525102215




No. Good Data




K20260525102212




No. Good Data




3C71 2026/05/25 1.40UT TOYOKAWA-KISO



F20260525102215





BLK: 3,SNR1: 0.19087 ,SNR2: 2.4335




Frequency (Hz)

3C71 2026/05/25 1.40UT FUJI -KISO


K20260525102212





BLK: 3,SNR1: 2.7711 ,SNR2: 8.2322




Frequency (Hz)




T20260525104131




BLK: 4,SNR1: 0.10128 ,SNR2: 1.5288




F20260525104131





BLK: 4,SNR1:-0.87357E-01,SNR2: 1.1316




0258+350 2026/05/25 1.72UT TOYOKAWA-FUJI





T20260525104131




BLK: 8,SNR1: 0.17896 ,SNR2: 0.99472




K20260525104128





BLK: 8,SNR1: 0.76278 ,SNR2: 3.8299




0258+350 2026/05/25 1.72UT TOYOKAWA-KISO




F20260525104131




BLK:10,SNR1: 0.24251E-01,SNR2: 0.83828




K20260525104128




BLK:10,SNR1: 0.70860 ,SNR2: 3.4103




0258+350 2026/05/25 1.72UT FUJI -KISO



T20260525105120




BLK: 1,SNR1: 0.77785 ,SNR2: 4.3249





0308+305 2026/05/25 1.88UT TOYOKAWA-FUJI



F20260525105120




BLK: 1,SNR1: 11.056 ,SNR2: 27.333



T20260525105120





BLK: 2,SNR1: 1.5737 ,SNR2: 20.256




Frequency (Hz)

K20260525105117




BLK: 2,SNR1: 12.814 ,SNR2: 31.423





Frequency (Hz)


0308+305 2026/05/25 1.88UT TOYOKAWA-KISO





F20260525105120




No. Good Data




K20260525105117




No. Good Data




0308+305 2026/05/25 1.88UT FUJI -KISO




T20260525110251




BLK:15,SNR1: 10.472 ,SNR2: 14.463




F20260525110251





BLK:15,SNR1:-0.46668E-01,SNR2: 2.3430




0320+05 2026/05/25 2.08UT TOYOKAWA-FUJI



T20260525110251





BLK:16,SNR1: 1.7357 ,SNR2: 5.4472





0320+05 2026/05/25 2.08UT TOYOKAWA-KISO


K20260525110248




BLK:16,SNR1: 1.0451 ,SNR2: 5.4802



F20260525110251





BLK: 5,SNR1:-0.17375 ,SNR2: 1.2269





0320+05 2026/05/25 2.08UT FUJI -KISO


K20260525110248




BLK: 5,SNR1: 0.56017 ,SNR2: 3.0584



T20260525111613




BLK: 3,SNR1: 0.68655 ,SNR2: 2.2698




Frequency (Hz)

F20260525111613




BLK: 3,SNR1: 0.14739 ,SNR2: 1.6879





Frequency (Hz)


0333+32 2026/05/25 2.30UT TOYOKAWA-FUJI





T20260525111613




BLK:17,SNR1: 0.38680 ,SNR2: 1.6150




K20260525111610




BLK:17,SNR1: 0.37010 ,SNR2: 0.95038




0333+32 2026/05/25 2.30UT TOYOKAWA-KISO





F20260525111613




BLK:10,SNR1: 0.22141 ,SNR2: 0.82594




K20260525111610




BLK:10,SNR1: 0.65474 ,SNR2: 2.5219




0333+32 2026/05/25 2.30UT FUJI -KISO




T20260525112914




BLK: 9,SNR1: 17.154 ,SNR2: 30.353




F20260525112914




BLK: 9,SNR1:-0.25943 ,SNR2: 0.10393E-01




0347+05 2026/05/25 2.52UT TOYOKAWA-FUJI



T20260525112914




BLK:15,SNR1: 17.859 ,SNR2: 28.820





0347+05 2026/05/25 2.52UT TOYOKAWA-KISO


K20260525112911




BLK:15,SNR1: 0.26647 ,SNR2: 3.2261




F20260525112914




BLK: 3,SNR1:-0.33133 ,SNR2: 0.0000




K20260525112911





BLK: 3,SNR1: 0.14218 ,SNR2: 1.6612




0347+05 2026/05/25 2.52UT FUJI -KISO





T20260525114448




BLK: 5,SNR1: 3.5620 ,SNR2: 7.0841




F20260525114448




BLK: 5,SNR1: 0.65388 ,SNR2: 4.9374




0403-132 2026/05/25 2.77UT TOYOKAWA-FUJI




T20260525114448




BLK: 9,SNR1: 11.571 ,SNR2: 20.496




K20260525114446




BLK: 9,SNR1: 11.909 ,SNR2: 27.989




0403-132 2026/05/25 2.77UT TOYOKAWA-KISO




F20260525114448




BLK: 4,SNR1: 0.56004 ,SNR2: 4.7827




K20260525114446





BLK: 4,SNR1: 5.3388 ,SNR2: 10.450




0403-132 2026/05/25 2.77UT FUJI -KISO




T20260525115359




BLK: 9,SNR1: 0.63103 ,SNR2: 2.8768




F20260525115359





BLK: 9,SNR1: 0.93230 ,SNR2: 5.9568




0411+05 2026/05/25 2.93UT TOYOKAWA-FUJI




T20260525115359




BLK:15,SNR1: 1.0979 ,SNR2: 4.1339




K20260525115356




BLK:15,SNR1: 0.58092 ,SNR2: 2.5961




0411+05 2026/05/25 2.93UT TOYOKAWA-KISO




F20260525115359




BLK: 9,SNR1: 0.16596 ,SNR2: 1.5372




K20260525115356





BLK: 9,SNR1: 1.1184 ,SNR2: 4.3188




0411+05 2026/05/25 2.93UT FUJI -KISO




T20260525120453




BLK:14,SNR1: 9.2866 ,SNR2: 22.167




F20260525120453





BLK:14,SNR1: 11.894 ,SNR2: 30.493




0422+178 2026/05/25 3.11UT TOYOKAWA-FUJI



T20260525120453





BLK:13,SNR1: 9.2999 ,SNR2: 22.199





0422+178 2026/05/25 3.11UT TOYOKAWA-KISO


K20260525120450




BLK:13,SNR1: 10.085 ,SNR2: 29.218





F20260525120453




BLK: 7,SNR1: 13.794 ,SNR2: 35.301




K20260525120450





BLK: 7,SNR1: 9.8309 ,SNR2: 28.462




0422+178 2026/05/25 3.11UT FUJI -KISO





T20260525121222




BLK:26,SNR1: 6.2021 ,SNR2: 19.783




F20260525121222





BLK:26,SNR1: 0.55714 ,SNR2: 3.6490




3C119 2026/05/25 3.23UT TOYOKAWA-FUJI





T20260525121222




BLK:30,SNR1: 6.1824 ,SNR2: 23.327




K20260525121219





BLK:30,SNR1: 1.3303 ,SNR2: 4.1675




3C119 2026/05/25 3.23UT TOYOKAWA-KISO





F20260525121222




BLK:27,SNR1: 3.5489 ,SNR2: 16.504




K20260525121219




BLK:27,SNR1: 1.2983 ,SNR2: 3.8474




3C119 2026/05/25 3.23UT FUJI -KISO




T20260525130028




BLK:18,SNR1: 2.6551 ,SNR2: 7.0654




F20260525130028





BLK:18,SNR1: 0.38834 ,SNR2: 2.7426




3C138 2026/05/25 4.04UT TOYOKAWA-FUJI



T20260525130028





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


3C138 2026/05/25 4.04UT TOYOKAWA-KISO



F20260525130028





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


3C138 2026/05/25 4.04UT FUJI -KISO




T20260525131402




BLK: 8,SNR1: 1.1235 ,SNR2: 3.0629




F20260525131402





BLK: 8,SNR1: 1.5375 ,SNR2: 3.8619




0531+194 2026/05/25 4.26UT TOYOKAWA-FUJI



T20260525131402





No.Good Data




Frequency (Hz)

KISO




No.Good Data




Frequency (Hz)


0531+194 2026/05/25 4.26UT TOYOKAWA-KISO



F20260525131402





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0531+194 2026/05/25 4.26UT FUJI -KISO



T20260525132223




BLK:14,SNR1: 14.562 ,SNR2: 32.125





3C147 2026/05/25 4.40UT TOYOKAWA-FUJI



F20260525132223




BLK:14,SNR1: 3.5726 ,SNR2: 7.9353



T20260525132223




No.Good Data




Frequency (Hz)

KISO




No.Good Data






Frequency (Hz)




3C147 2026/05/25 4.40UT TOYOKAWA-KISO




F20260525132223




KISO




3C147 2026/05/25 4.40UT FUJI -KISO





T20260525133033




BLK: 2,SNR1: 17.160 ,SNR2: 37.134




F20260525133033





BLK: 2,SNR1: 17.178 ,SNR2: 31.895




0548+16 2026/05/25 4.54UT TOYOKAWA-FUJI



T20260525133033





No. Good Data




Frequency (Hz)

KISO




No. Good Data






Frequency (Hz)




0548+16 2026/05/25 4.54UT TOYOKAWA-KISO




F20260525133033





KISO




0548+16 2026/05/25 4.54UT FUJI -KISO





T20260525133443




BLK: 2,SNR1: 9.0305 ,SNR2: 20.365




F20260525133443




BLK: 2,SNR1: 19.790 ,SNR2: 33.109




0552+12 2026/05/25 4.61UT TOYOKAWA-FUJI



T20260525133443





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0552+12 2026/05/25 4.61UT TOYOKAWA-KISO



F20260525133443





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0552+12 2026/05/25 4.61UT FUJI -KISO





T20260525133910




BLK: 4,SNR1: 7.6378 ,SNR2: 23.202




F20260525133910





BLK: 4,SNR1: 14.921 ,SNR2: 26.813




0556+191 2026/05/25 4.68UT TOYOKAWA-FUJI





T20260525133910




No.Good Data




KISO





No.Good Data




0556+191 2026/05/25 4.68UT TOYOKAWA-KISO





F20260525133910




No.Good Data




KISO





No.Good Data




0556+191 2026/05/25 4.68UT FUJI -KISO





T20260525134655




BLK: 4,SNR1: 7.1344 ,SNR2: 20.199




F20260525134655





BLK: 4,SNR1: 10.086 ,SNR2: 21.537




0605-08 2026/05/25 4.81UT TOYOKAWA-FUJI





T20260525134655




BLK: 5,SNR1: 2.1660 ,SNR2: 5.0391




K20260525134652




BLK: 5,SNR1: 2.3641 ,SNR2: 7.6176




0605-08 2026/05/25 4.81UT TOYOKAWA-KISO





F20260525134655




BLK: 7,SNR1: 3.1532 ,SNR2: 9.5765




K20260525134652





BLK: 7,SNR1: 2.2968 ,SNR2: 7.4509




0605-08 2026/05/25 4.81UT FUJI -KISO



T20260525140603





BLK: 2,SNR1: 2.7714 ,SNR2: 7.4214





3C161 2026/05/25 5.13UT TOYOKAWA-FUJI



F20260525140603




BLK: 2,SNR1: 14.775 ,SNR2: 35.938





T20260525140603




BLK: 4,SNR1: 0.98393 ,SNR2: 2.7087




K20260525140600




BLK: 4,SNR1: 3.5463 ,SNR2: 11.620







3C161 2026/05/25 5.13UT TOYOKAWA-KISO




F20260525140603




K20260525140600





T20260525143336




BLK: 3,SNR1: 2.0028 ,SNR2: 5.2040




F20260525143336




BLK: 3,SNR1: 11.444 ,SNR2: 26.988




0652-130 2026/05/25 5.59UT TOYOKAWA-FUJI





T20260525143336




BLK: 1,SNR1: 4.1362 ,SNR2: 7.6107




K20260525143333




BLK: 1,SNR1: 14.337 ,SNR2: 41.391




0652-130 2026/05/25 5.59UT TOYOKAWA-KISO





F20260525143336




BLK: 7,SNR1: 8.8374 ,SNR2: 20.912




K20260525143333





BLK: 7,SNR1: 10.395 ,SNR2: 29.688




0652-130 2026/05/25 5.59UT FUJI -KISO



T20260525144513




BLK: 3,SNR1: 8.5988 ,SNR2: 21.284




Frequency (Hz)

F20260525144513




BLK: 3,SNR1: 7.4927 ,SNR2: 18.579




Frequency (Hz)


0703+138 2026/05/25 5.78UT TOYOKAWA-FUJI




T20260525144513




BLK: 7,SNR1: 9.0175 ,SNR2: 22.060




K20260525144510





BLK: 7,SNR1: 3.5239 ,SNR2: 10.398




0703+138 2026/05/25 5.78UT TOYOKAWA-KISO



F20260525144513





BLK: 5,SNR1: 2.1778 ,SNR2: 6.6369




Frequency (Hz)

K20260525144510




BLK: 5,SNR1: 12.149 ,SNR2: 21.862




Frequency (Hz)


0703+138 2026/05/25 5.78UT FUJI -KISO



T20260525145435





BLK: 3,SNR1:-0.11485E-01,SNR2: 0.83429




Frequency (Hz)

F20260525145435




BLK: 3,SNR1:-0.26357 ,SNR2: 0.65031





Frequency (Hz)


0713-024 2026/05/25 5.94UT TOYOKAWA-FUJI





T20260525145435




BLK: 7,SNR1: 0.41887 ,SNR2: 1.8565




K20260525145432





BLK: 7,SNR1: 1.1056 ,SNR2: 4.1525




0713-024 2026/05/25 5.94UT TOYOKAWA-KISO



F20260525145435





BLK: 7,SNR1: 1.3389 ,SNR2: 5.4490




Frequency (Hz)

K20260525145432




BLK: 7,SNR1: 1.0460 ,SNR2: 4.0643





Frequency (Hz)


0713-024 2026/05/25 5.94UT FUJI -KISO



T20260525150448





BLK: 7,SNR1: 0.42221 ,SNR2: 1.0722




Frequency (Hz)

F20260525150448




BLK: 7,SNR1: 2.1819 ,SNR2: 6.5761





Frequency (Hz)


0723+10 2026/05/25 6.11UT TOYOKAWA-FUJI



T20260525150448




BLK:13,SNR1: 0.18303 ,SNR2: 0.92449




Frequency (Hz)

K20260525150445




BLK:13,SNR1: 9.6236 ,SNR2: 21.122





Frequency (Hz)


0723+10 2026/05/25 6.11UT TOYOKAWA-KISO



F20260525150448





BLK:17,SNR1: 7.0732 ,SNR2: 10.191




Frequency (Hz)

K20260525150445




BLK:17,SNR1: 9.2647 ,SNR2: 20.359




Frequency (Hz)


0723+10 2026/05/25 6.11UT FUJI -KISO





T20260525151503




BLK:11,SNR1: 10.309 ,SNR2: 18.100




F20260525151503





BLK:11,SNR1: 12.196 ,SNR2: 25.833




0732+33 2026/05/25 6.28UT TOYOKAWA-FUJI





T20260525151503




BLK:11,SNR1: 10.005 ,SNR2: 20.978




K20260525151501





BLK:11,SNR1: 14.098 ,SNR2: 23.812




0732+33 2026/05/25 6.28UT TOYOKAWA-KISO



F20260525151503





BLK: 1,SNR1: 16.527 ,SNR2: 31.470




Frequency (Hz)

K20260525151501




BLK: 1,SNR1: 12.220 ,SNR2: 27.027





Frequency (Hz)


0732+33 2026/05/25 6.28UT FUJI -KISO




T20260525152304




BLK: 9,SNR1: 3.0760 ,SNR2: 7.6137




F20260525152304





BLK: 9,SNR1: 7.8323 ,SNR2: 18.835




0741-06 2026/05/25 6.41UT TOYOKAWA-FUJI




T20260525152304




BLK: 9,SNR1: 3.1957 ,SNR2: 7.9549




K20260525152301




BLK: 9,SNR1: 7.6472 ,SNR2: 25.603




0741-06 2026/05/25 6.41UT TOYOKAWA-KISO




F20260525152304




BLK:10,SNR1: 5.9733 ,SNR2: 19.539




K20260525152301





BLK:10,SNR1: 7.3934 ,SNR2: 24.763




0741-06 2026/05/25 6.41UT FUJI -KISO



T20260525153248




BLK: 5,SNR1: 9.8083 ,SNR2: 25.229




Frequency (Hz)

F20260525153248




BLK: 5,SNR1: 4.1734 ,SNR2: 8.8534





Frequency (Hz)


0752-200 2026/05/25 6.57UT TOYOKAWA-FUJI





T20260525153248




BLK:12,SNR1: 70.809 ,SNR2: 167.44




K20260525153246




BLK:12,SNR1: 8.8729 ,SNR2: 19.375




0752-200 2026/05/25 6.57UT TOYOKAWA-KISO



F20260525153248




BLK: 9,SNR1: 8.6184 ,SNR2: 15.920




Frequency (Hz)

K20260525153246




BLK: 9,SNR1: 8.5179 ,SNR2: 19.004





Frequency (Hz)


0752-200 2026/05/25 6.57UT FUJI -KISO



T20260525154024





BLK: 3,SNR1: 3.9350 ,SNR2: 10.590




Frequency (Hz)

F20260525154024




BLK: 3,SNR1: 6.3237 ,SNR2: 18.794





Frequency (Hz)


3C190 2026/05/25 6.70UT TOYOKAWA-FUJI



T20260525154024




BLK: 5,SNR1: 2.8144 ,SNR2: 7.9174




Frequency (Hz)

K20260525154021




BLK: 5,SNR1: 4.5984 ,SNR2: 11.712





Frequency (Hz)


3C190 2026/05/25 6.70UT TOYOKAWA-KISO




F20260525154024




BLK: 3,SNR1: 5.1391 ,SNR2: 15.921




K20260525154021




BLK: 3,SNR1: 2.6939 ,SNR2: 10.139




3C190 2026/05/25 6.70UT FUJI -KISO




T20260525155250




BLK: 9,SNR1: 6.9504 ,SNR2: 17.881




F20260525155250




BLK: 9,SNR1: 6.7665 ,SNR2: 19.900




3C196 2026/05/25 6.91UT TOYOKAWA-FUJI



T20260525155250





BLK:21,SNR1: 5.5743 ,SNR2: 14.345




Frequency (Hz)

K20260525155248




BLK:21,SNR1: 8.4795 ,SNR2: 21.911




Frequency (Hz)


3C196 2026/05/25 6.91UT TOYOKAWA-KISO



F20260525155250





BLK:15,SNR1: 7.2907 ,SNR2: 18.813




Frequency (Hz)

K20260525155248




BLK:15,SNR1: 2.5558 ,SNR2: 8.0107




Frequency (Hz)


3C196 2026/05/25 6.91UT FUJI -KISO



T20260525160359




BLK: 6,SNR1: 7.3702 ,SNR2: 21.634




Frequency (Hz)

F20260525160359




BLK: 6,SNR1: 7.0900 ,SNR2: 18.390




Frequency (Hz)


0821+394 2026/05/25 7.09UT TOYOKAWA-FUJI



T20260525160359




BLK: 6,SNR1: 7.0074 ,SNR2: 20.104




Frequency (Hz)

K20260525160356




BLK: 6,SNR1: 6.8330 ,SNR2: 19.580




Frequency (Hz)


0821+394 2026/05/25 7.09UT TOYOKAWA-KISO



F20260525160359




BLK: 1,SNR1: 2.5974 ,SNR2: 8.1760




Frequency (Hz)

K20260525160356




BLK: 1,SNR1: 8.3789 ,SNR2: 24.540





Frequency (Hz)


0821+394 2026/05/25 7.09UT FUJI -KISO



T20260525161537





BLK: 3,SNR1: 0.82947E-01,SNR2: 0.52554




Frequency (Hz)

F20260525161537




BLK: 3,SNR1: 0.40973 ,SNR2: 2.9363





Frequency (Hz)


0834-19 2026/05/25 7.29UT TOYOKAWA-FUJI



T20260525161537





BLK: 5,SNR1: 0.10953 ,SNR2: 1.1102




Frequency (Hz)

K20260525161534




BLK: 5,SNR1: 0.32711 ,SNR2: 1.4988





Frequency (Hz)


0834-19 2026/05/25 7.29UT TOYOKAWA-KISO



F20260525161537





BLK: 4,SNR1: 0.32020 ,SNR2: 2.6218




Frequency (Hz)

K20260525161534




BLK: 4,SNR1: 1.4068 ,SNR2: 2.9671





Frequency (Hz)


0834-19 2026/05/25 7.29UT FUJI -KISO



T20260525162043





BLK: 5,SNR1: 19.410 ,SNR2: 28.399




Frequency (Hz)

F20260525162043




BLK: 5,SNR1: 2.1146 ,SNR2: 6.0751





Frequency (Hz)


0839-071 2026/05/25 7.37UT TOYOKAWA-FUJI



T20260525162043




BLK:20,SNR1: 12.711 ,SNR2: 18.583




Frequency (Hz)

K20260525162040




BLK:20,SNR1: 7.7734 ,SNR2: 20.155




Frequency (Hz)


0839-071 2026/05/25 7.37UT TOYOKAWA-KISO



F20260525162043





BLK:11,SNR1: 1.1867 ,SNR2: 6.1549




Frequency (Hz)

K20260525162040




BLK:11,SNR1: 7.7681 ,SNR2: 20.143





Frequency (Hz)


0839-071 2026/05/25 7.37UT FUJI -KISO



T20260525163144





BLK: 8,SNR1: 0.33107 ,SNR2: 2.1040




Frequency (Hz)

F20260525163144




BLK: 8,SNR1: 3.0224 ,SNR2: 6.5693





Frequency (Hz)


3C208 2026/05/25 7.56UT TOYOKAWA-FUJI



T20260525163144




BLK: 8,SNR1: 0.27506 ,SNR2: 1.6578




Frequency (Hz)

K20260525163141




BLK: 8,SNR1: 10.016 ,SNR2: 13.147




Frequency (Hz)


3C208 2026/05/25 7.56UT TOYOKAWA-KISO



F20260525163144




BLK:11,SNR1: 10.672 ,SNR2: 26.038




Frequency (Hz)

K20260525163141




BLK:11,SNR1: 14.026 ,SNR2: 16.563





Frequency (Hz)


3C208 2026/05/25 7.56UT FUJI -KISO



T20260525164826





BLK:20,SNR1: 8.6414 ,SNR2: 20.474




Frequency (Hz)

F20260525164826




BLK:20,SNR1: 9.4475 ,SNR2: 23.700





Frequency (Hz)


3C216 2026/05/25 7.84UT TOYOKAWA-FUJI



T20260525164826





BLK:17,SNR1: 9.7844 ,SNR2: 22.733




Frequency (Hz)

3C216 2026/05/25 7.84UT TOYOKAWA-KISO


K20260525164823





BLK:17,SNR1: 9.7639 ,SNR2: 22.569




Frequency (Hz)



F20260525164826





BLK:18,SNR1: 10.232 ,SNR2: 18.228




Frequency (Hz)

3C216 2026/05/25 7.84UT FUJI -KISO


K20260525164823





BLK:18,SNR1: 3.5212 ,SNR2: 10.358




Frequency (Hz)



T20260525170716





BLK: 5,SNR1: 8.9506 ,SNR2: 21.977




Frequency (Hz)

F20260525170716




BLK: 5,SNR1: 1.8314 ,SNR2: 3.2673





Frequency (Hz)


0926+117 2026/05/25 8.15UT TOYOKAWA-FUJI



T20260525170716




BLK: 7,SNR1: 6.8756 ,SNR2: 17.718




Frequency (Hz)

K20260525170713




BLK: 7,SNR1: 0.84234 ,SNR2: 3.6246





Frequency (Hz)


0926+117 2026/05/25 8.15UT TOYOKAWA-KISO



F20260525170716




BLK: 7,SNR1: 7.1495 ,SNR2: 18.028




Frequency (Hz)

K20260525170713




BLK: 7,SNR1: 0.53603 ,SNR2: 2.6140





Frequency (Hz)


0926+117 2026/05/25 8.15UT FUJI -KISO



T20260525174430





BLK:11,SNR1: 6.3381 ,SNR2: 14.179




Frequency (Hz)

F20260525174430




BLK:11,SNR1: 1.4897 ,SNR2: 4.0782





Frequency (Hz)


3C236 2026/05/25 8.77UT TOYOKAWA-FUJI



T20260525174430




BLK:12,SNR1: 6.2427 ,SNR2: 13.802




Frequency (Hz)

K20260525174427





BLK:12,SNR1: 2.8374 ,SNR2: 5.7088





Frequency (Hz)

3C236 2026/05/25 8.77UT TOYOKAWA-KISO






BLK:15,SNR1: 3.1386 ,SNR2: 8.2032



BLK:15,SNR1: 5.1124 ,SNR2: 10.060



3C236 2026/05/25 8.77UT FUJI -KISO

