




T20260603141912




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0713-024 2026/06/03 5.35UT TOYOKAWA-FUJI



T20260603141912





BLK: 5, SNR1: 9.3494 ,SNR2: 21.320




Frequency (Hz)

K20260603141910




BLK: 5, SNR1: 9.1915 ,SNR2: 23.416





Frequency (Hz)


0713-024 2026/06/03 5.35UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20260603141910




No.Good Data





Frequency (Hz)


0713-024 2026/06/03 5.35UT FUJI -KISO



T20260603142925





BLK: 5,SNR1: 4.4845 ,SNR2: 9.7559




Frequency (Hz)

F20260603142925




BLK: 5,SNR1: 13.524 ,SNR2: 28.838





Frequency (Hz)


0723+10 2026/06/03 5.52UT TOYOKAWA-FUJI



T20260603142925





BLK: 3,SNR1: 12.590 ,SNR2: 31.753




Frequency (Hz)

K20260603142922




BLK: 3,SNR1: 11.397 ,SNR2: 32.574





Frequency (Hz)


0723+10 2026/06/03 5.52UT TOYOKAWA-KISO



F20260603142925





BLK: 3,SNR1: 12.780 ,SNR2: 27.635




Frequency (Hz)

K20260603142922




BLK: 3,SNR1: 11.951 ,SNR2: 30.172





Frequency (Hz)


0723+10 2026/06/03 5.52UT FUJI -KISO



T20260603143940





BLK:10,SNR1: 2.4609 ,SNR2: 5.6755




Frequency (Hz)

0732+33 2026/06/03 5.69UT TOYOKAWA-FUJI


F20260603143940





BLK:10,SNR1: 4.7191 ,SNR2: 13.735




Frequency (Hz)



T20260603143940





BLK:13,SNR1: 2.9777 ,SNR2: 6.6001




Frequency (Hz)

K20260603143938




BLK:13,SNR1: 4.8664 ,SNR2: 9.7178





Frequency (Hz)


0732+33 2026/06/03 5.69UT TOYOKAWA-KISO



F20260603143940





BLK:12,SNR1: 3.3118 ,SNR2: 9.8128




Frequency (Hz)

K20260603143938




BLK:12,SNR1: 1.6080 ,SNR2: 6.5831





Frequency (Hz)


0732+33 2026/06/03 5.69UT FUJI -KISO



T20260603144740





BLK: 5,SNR1: 1.4271 ,SNR2: 4.6190




Frequency (Hz)

F20260603144740




BLK: 5,SNR1: 0.64218 ,SNR2: 5.9068




Frequency (Hz)


0741-06 2026/06/03 5.82UT TOYOKAWA-FUJI



T20260603144740





BLK:12,SNR1: 0.79525 ,SNR2: 2.6616




Frequency (Hz)

K20260603144737




BLK:12,SNR1: 1.9458 ,SNR2: 8.1528




Frequency (Hz)


0741-06 2026/06/03 5.82UT TOYOKAWA-KISO



F20260603144740





BLK: 8,SNR1: 0.34700 ,SNR2: 3.7279




Frequency (Hz)

K20260603144737




BLK: 8,SNR1: 1.3792 ,SNR2: 4.5625





Frequency (Hz)


0741-06 2026/06/03 5.82UT FUJI -KISO



T20260603145724





BLK: 6,SNR1: 0.60510 ,SNR2: 1.5120




Frequency (Hz)

F20260603145724




BLK: 6,SNR1: 2.5597 ,SNR2: 10.108





Frequency (Hz)


0752-200 2026/06/03 5.98UT TOYOKAWA-FUJI



T20260603145724





BLK: 5,SNR1: 0.16743 ,SNR2: 1.5184




Frequency (Hz)

K20260603145721




BLK: 5,SNR1: 1.2619 ,SNR2: 7.9166





Frequency (Hz)


0752-200 2026/06/03 5.98UT TOYOKAWA-KISO



F20260603145724





BLK: 3,SNR1: 0.47549 ,SNR2: 5.8532




Frequency (Hz)

K20260603145721




BLK: 3,SNR1: 2.4973 ,SNR2: 9.4345





Frequency (Hz)


0752-200 2026/06/03 5.98UT FUJI -KISO



T20260603150500




BLK: 2,SNR1: 0.79893 ,SNR2: 4.9145




Frequency (Hz)

3C190 2026/06/03 6.11UT TOYOKAWA-FUJI


F20260603150500





BLK: 2,SNR1: 8.9724 ,SNR2: 22.254




Frequency (Hz)





T20260603150500




No.Good Data




K20260603150457





No.Good Data




3C190 2026/06/03 6.11UT TOYOKAWA-KISO



F20260603150500





BLK: 1,SNR1: 5.0134 ,SNR2: 15.195




Frequency (Hz)

3C190 2026/06/03 6.11UT FUJI -KISO


K20260603150457





BLK: 1,SNR1: 4.2098 ,SNR2: 8.4839




Frequency (Hz)



T20260603151727





BLK: 3,SNR1: 1.2614 ,SNR2: 4.2107




Frequency (Hz)

3C196 2026/06/03 6.32UT TOYOKAWA-FUJI


F20260603151727





BLK: 3,SNR1: 2.5658 ,SNR2: 6.5237




Frequency (Hz)



T20260603151727




BLK: 2,SNR1: 0.34851 ,SNR2: 2.2309




Frequency (Hz)

3C196 2026/06/03 6.32UT TOYOKAWA-KISO


K20260603151724





BLK: 2,SNR1: 1.0482 ,SNR2: 4.2631




Frequency (Hz)



F20260603151727





BLK: 3,SNR1: 5.6290 ,SNR2: 14.421




Frequency (Hz)

3C196 2026/06/03 6.32UT FUJI -KISO


K20260603151724





BLK: 3,SNR1: 3.8140 ,SNR2: 8.0056




Frequency (Hz)



T20260603152836





BLK:10,SNR1: 0.22391 ,SNR2: 1.3481




Frequency (Hz)

F20260603152836




BLK:10,SNR1: 2.3017 ,SNR2: 5.5258





Frequency (Hz)


0821+394 2026/06/03 6.50UT TOYOKAWA-FUJI



T20260603152836





BLK: 8,SNR1: 0.22592 ,SNR2: 1.0012




Frequency (Hz)

K20260603152833




BLK: 8,SNR1: 1.3188 ,SNR2: 5.4769





Frequency (Hz)


0821+394 2026/06/03 6.50UT TOYOKAWA-KISO



F20260603152836





BLK:17,SNR1: 1.6070 ,SNR2: 5.5636




Frequency (Hz)

K20260603152833




BLK:17,SNR1: 2.0350 ,SNR2: 7.6677





Frequency (Hz)


0821+394 2026/06/03 6.50UT FUJI -KISO



T20260603154014





BLK: 3,SNR1: 2.5430 ,SNR2: 7.1744




Frequency (Hz)

F20260603154015




BLK: 3,SNR1: 7.9098 ,SNR2: 20.234





Frequency (Hz)


0834-19 2026/06/03 6.70UT TOYOKAWA-FUJI



T20260603154014





BLK: 6,SNR1: 6.4759 ,SNR2: 14.161




Frequency (Hz)

K20260603154011




BLK: 6,SNR1: 9.1751 ,SNR2: 20.042





Frequency (Hz)


0834-19 2026/06/03 6.70UT TOYOKAWA-KISO



F20260603154015





BLK: 2,SNR1: 4.7638 ,SNR2: 10.139




Frequency (Hz)

K20260603154011




BLK: 2,SNR1: 10.271 ,SNR2: 25.638





Frequency (Hz)


0834-19 2026/06/03 6.70UT FUJI -KISO



T20260603154519





No.Good Data




Frequency (Hz)

0839-071 2026/06/03 6.78UT TOYOKAWA-FUJI


F20260603154519





No.Good Data




Frequency (Hz)



T20260603154519





No.Good Data




Frequency (Hz)

K20260603154516




No.Good Data





Frequency (Hz)


0839-071 2026/06/03 6.78UT TOYOKAWA-KISO



F20260603154519





BLK: 1,SNR1: 2.0831 ,SNR2: 10.122




Frequency (Hz)

K20260603154516




BLK: 1,SNR1: 18.542 ,SNR2: 31.564





Frequency (Hz)


0839-071 2026/06/03 6.78UT FUJI -KISO



T20260603155621





BLK: 8,SNR1: 7.3648 ,SNR2: 19.485




Frequency (Hz)

F20260603155621




BLK: 8,SNR1: 9.5639 ,SNR2: 23.580





Frequency (Hz)


3C208 2026/06/03 6.97UT TOYOKAWA-FUJI



T20260603155621





BLK: 4,SNR1: 13.155 ,SNR2: 40.562




Frequency (Hz)

3C208 2026/06/03 6.97UT TOYOKAWA-KISO


K20260603155618





BLK: 4,SNR1: 9.4610 ,SNR2: 23.556




Frequency (Hz)



F20260603155621





BLK: 9,SNR1: 9.9042 ,SNR2: 24.270




Frequency (Hz)

3C208 2026/06/03 6.97UT FUJI -KISO


K20260603155618




BLK: 9,SNR1: 11.137 ,SNR2: 27.281




Frequency (Hz)



T20260603161303




BLK: 7,SNR1: 0.59537 ,SNR2: 1.1964




Frequency (Hz)

F20260603161303




BLK: 7,SNR1: 4.3507 ,SNR2: 9.6984




Frequency (Hz)


3C216 2026/06/03 7.25UT TOYOKAWA-FUJI



T20260603161303




BLK: 6,SNR1: 2.3837 ,SNR2: 3.7394




Frequency (Hz)

3C216 2026/06/03 7.25UT TOYOKAWA-KISO


K20260603161300





BLK: 6,SNR1: 5.6670 ,SNR2: 11.690




Frequency (Hz)



F20260603161303





BLK: 6,SNR1: 5.6241 ,SNR2: 9.9419




Frequency (Hz)

3C216 2026/06/03 7.25UT FUJI -KISO


K20260603161300





BLK: 6,SNR1: 6.9182 ,SNR2: 17.830




Frequency (Hz)



T20260603162513





BLK: 2,SNR1: 4.8340 ,SNR2: 16.213




Frequency (Hz)

0919-142 2026/06/03 7.45UT TOYOKAWA-FUJI


F20260603162513





BLK: 2,SNR1: 5.5837 ,SNR2: 18.726




Frequency (Hz)



T20260603162513





BLK: 2,SNR1: 6.2173 ,SNR2: 20.652




Frequency (Hz)

0919-142 2026/06/03 7.45UT TOYOKAWA-KISO


K20260603162510




BLK: 2,SNR1: 4.6382 ,SNR2: 15.744




Frequency (Hz)




F20260603162513




BLK: 4,SNR1: 4.5906 ,SNR2: 15.615




K20260603162510





BLK: 4,SNR1: 4.3787 ,SNR2: 14.938




0919-142 2026/06/03 7.45UT FUJI -KISO



T20260603163153





BLK:13,SNR1: 6.9957 ,SNR2: 22.851




Frequency (Hz)

F20260603163153




BLK:13,SNR1: 6.6235 ,SNR2: 19.113





Frequency (Hz)


0926+117 2026/06/03 7.56UT TOYOKAWA-FUJI



T20260603163153





BLK: 5,SNR1: 6.9222 ,SNR2: 20.142




Frequency (Hz)

0926+117 2026/06/03 7.56UT TOYOKAWA-KISO


K20260603163150




BLK: 5,SNR1: 9.1212 ,SNR2: 22.814




Frequency (Hz)



F20260603163153




BLK: 4,SNR1: 7.9840 ,SNR2: 19.782





0926+117 2026/06/03 7.56UT FWJ -KISO


K20260603163150




BLK: 4,SNR1: 8.4169 ,SNR2: 20.888



T20260603163937





BLK: 4,SNR1: 2.4665 ,SNR2: 6.0332




Frequency (Hz)

3C222 2026/06/03 7.69UT TOYOKAWA-FUJI


F20260603163937




BLK: 4,SNR1: 6.0029 ,SNR2: 10.877




Frequency (Hz)



T20260603163937





BLK: 4,SNR1: 4.5796 ,SNR2: 10.433





3C222 2026/06/03 7.69UT TOYOKAWA-KISO



K20260603163934




BLK: 4,SNR1: 7.8695 ,SNR2: 20.676



F20260603163937





BLK: 2, SNR1: 12.467 , SNR2: 29.206





3C222 2026/06/03 7.69UT FUJI -KISO



K20260603163934




BLK: 2, SNR1: 7.8449 , SNR2: 20.612



T20260603165459




BLK: 2, SNR1: 2.6521 , SNR2: 12.008





3C230 2026/06/03 7.94UT TOYOKAWA-FUJI



F20260603165459




BLK: 2, SNR1: 12.634 , SNR2: 31.198




T20260603165459




BLK: 2,SNR1: 11.517 ,SNR2: 28.576




K20260603165456





BLK: 2,SNR1: 10.841 ,SNR2: 26.905




3C230 2026/06/03 7.94UT TOYOKAWA-KISO



F20260603165459





BLK: 1,SNR1: 17.332 ,SNR2: 42.446




Frequency (Hz)

3C230 2026/06/03 7.94UT FUJI -KISO


K20260603165456





BLK: 1,SNR1: 12.484 ,SNR2: 30.572




Frequency (Hz)



T20260603172457





BLK: 4,SNR1: 8.6562 ,SNR2: 21.983




Frequency (Hz)

3C241 2026/06/03 8.44UT TOYOKAWA-FUJI


F20260603172457





BLK: 4,SNR1: 8.6496 ,SNR2: 21.326




Frequency (Hz)



T20260603172457





BLK: 4,SNR1: 8.6671 ,SNR2: 22.011




Frequency (Hz)

3C241 2026/06/03 8.44UT TOYOKAWA-KISO


K20260603172454





BLK: 4,SNR1: 8.4908 ,SNR2: 20.998




Frequency (Hz)



F20260603172457





No.Good Data




Frequency (Hz)

K20260603172454




No.Good Data





Frequency (Hz)


3C241 2026/06/03 8.44UT FUJI -KISO



T20260603174017





BLK: 3,SNR1: 2.3819 ,SNR2: 4.9746





1034+404 2026/06/03 8.70UT TOYOKAWA-FUJI



F20260603174017




BLK: 3,SNR1: 7.1768 ,SNR2: 17.884




T20260603174017




No. Good Data




K20260603174014





No. Good Data




1034+404 2026/06/03 8.70UT TOYOKAWA-KISO




F20260603174017




BLK: 1,SNR1: 11.568 ,SNR2: 28.405



K20260603174014



BLK: 1,SNR1: 2.4867 ,SNR2: 11.597



1034+404 2026/06/03 8.70UT FUJI -KISO

