




T202606052214





BLK:15,SNR1: 12.977 ,SNR2: 22.597




Frequency (Hz)

F202606052214




BLK:15,SNR1: 7.9359 ,SNR2: 18.802




Frequency (Hz)


2227+444 2026/06/05 20.40UT TOYOKAWA-FUJI



T202606052214





BLK:17,SNR1: 8.3398 ,SNR2: 14.524




Frequency (Hz)

K202606052211




BLK:17,SNR1: 19.845 ,SNR2: 21.796





Frequency (Hz)


2227+444 2026/06/05 20.40UT TOYOKAWA-KISO



F20260606052214





BLK:28,SNR1: 8.6219 ,SNR2: 15.458




Frequency (Hz)

K20260606052211




BLK:28,SNR1: 19.855 ,SNR2: 21.805





Frequency (Hz)


2227+444 2026/06/05 20.40UT FUJI -KISO



T20260606053840





BLK:11,SNR1: 1.9382 ,SNR2: 18.183




Frequency (Hz)

F20260606053840




BLK:11,SNR1: 5.9420 ,SNR2: 18.394





Frequency (Hz)


2243+394 2026/06/05 20.67UT TOYOKAWA-FUJI



T202606053840





BLK:10,SNR1: 1.7128 ,SNR2: 6.3195




Frequency (Hz)

K202606053837




BLK:10,SNR1: 8.6970 ,SNR2: 20.774





Frequency (Hz)


2243+394 2026/06/05 20.67UT TOYOKAWA-KISO



F20260606053840





BLK: 9,SNR1: 5.8525 ,SNR2: 14.074




Frequency (Hz)

2243+394 2026/06/05 20.67UT FUJI -KISO


K20260606053837





BLK: 9,SNR1: 5.5745 ,SNR2: 13.583




Frequency (Hz)



T20260606055437





BLK: 1,SNR1: 0.58061 ,SNR2: 2.2190




Frequency (Hz)

F20260606055437




BLK: 1,SNR1: 0.60138 ,SNR2: 3.1373





Frequency (Hz)


2259+481 2026/06/05 20.94UT TOYOKAWA-FUJI



T20260606055437





BLK: 3,SNR1: 0.50533 ,SNR2: 9.4052




Frequency (Hz)

2259+481 2026/06/05 20.94UT TOYOKAWA-KISO


K20260606055434





BLK: 3,SNR1: 1.6955 ,SNR2: 6.2719




Frequency (Hz)



F20260606055437





BLK: 1,SNR1: 3.2361 ,SNR2: 9.1234




Frequency (Hz)

2259+481 2026/06/05 20.94UT FUJI -KISO


K20260606055434





BLK: 1,SNR1: 0.34377 ,SNR2: 1.9572




Frequency (Hz)



T2026060602051





BLK: 2,SNR1: 0.18894 ,SNR2: 0.90649




Frequency (Hz)

F2026060602051




BLK: 2,SNR1: 0.71109 ,SNR2: 2.4581





Frequency (Hz)


2325+269 2026/06/05 21.38UT TOYOKAWA-FUJI



T2026060602051





BLK: 3,SNR1:-0.11829E-02,SNR2: 0.31151




Frequency (Hz)

K2026060602048




BLK: 3,SNR1: 1.3497 ,SNR2: 6.2185





Frequency (Hz)


2325+269 2026/06/05 21.38UT TOYOKAWA-KISO



F2026060602051




BLK: 2,SNR1: 0.65905 ,SNR2: 2.2712




Frequency (Hz)

K2026060602048




BLK: 2,SNR1: 0.19121 ,SNR2: 3.5851





Frequency (Hz)


2325+269 2026/06/05 21.38UT FUJI -KISO



T20260606062933





BLK: 5,SNR1: 18.267 ,SNR2: 32.184




Frequency (Hz)

F20260606062933




BLK: 5,SNR1: 13.938 ,SNR2: 24.633





Frequency (Hz)


2334+085 2026/06/05 21.52UT TOYOKAWA-FUJI



T20260606062933





BLK:11,SNR1: 3.3469 ,SNR2: 10.118




Frequency (Hz)

K20260606062930




BLK:11,SNR1: 2.8798 ,SNR2: 8.8634





Frequency (Hz)


2334+085 2026/06/05 21.52UT TOYOKAWA-KISO



F20260606062933





BLK:11,SNR1: 13.567 ,SNR2: 24.170




Frequency (Hz)

K20260606062930




BLK:11,SNR1: 2.9521 ,SNR2: 9.0454





Frequency (Hz)


2334+085 2026/06/05 21.52UT FUJI -KISO



T20260606064316





BLK: 4,SNR1: 1.3022 ,SNR2: 5.9238




Frequency (Hz)

F20260606064316




BLK: 4,SNR1: 2.6817 ,SNR2: 7.5504




Frequency (Hz)


2347-02 2026/06/05 21.75UT TOYOKAWA-FUJI



T20260606064316




BLK:10,SNR1: 6.2355 ,SNR2: 32.154




Frequency (Hz)

K20260606064313




BLK:10,SNR1: 9.8155 ,SNR2: 21.435




Frequency (Hz)


2347-02 2026/06/05 21.75UT TOYOKAWA-KISO



F20260606064316




BLK: 8,SNR1: 2.3677 ,SNR2: 6.8604




Frequency (Hz)

K20260606064313





BLK: 8,SNR1: 9.6653 ,SNR2: 21.129





Frequency (Hz)

2347-02 2026/06/05 21.75UT FUJI -KISO







BLK: 3,SNR1: 0.99164E-01,SNR2: 0.38494




BLK: 3,SNR1: 1.9756 ,SNR2: 5.7342





2354+14 2026/06/05 21.86UT TOYOKAWA-FUJI







BLK: 3,SNR1: 9.1787 ,SNR2: 22.104





BLK: 3,SNR1: 8.0399 ,SNR2: 19.680




2354+14 2026/06/05 21.86UT TOYOKAWA-KISO



F2026060605009





BLK: 6,SNR1: 6.9196 ,SNR2: 17.217




Frequency (Hz)

2354+14 2026/06/05 21.86UT FUJI -KISO


K2026060605006





BLK: 6,SNR1: 9.2850 ,SNR2: 21.576




Frequency (Hz)



T20260606065912



BLK: 7,SNR1: 1.9844 ,SNR2: 4.9876





Frequency (Hz)


3C2

2026/06/05 22.01UT TOYOKAWA-FUJI


F20260606065912





BLK: 7,SNR1: 4.9331 ,SNR2: 13.932




Frequency (Hz)



T20260606065912



BLK:13,SNR1: 1.9053 ,SNR2: 3.6041





Frequency (Hz)


3C2

2026/06/05 22.01UT TOYOKAWA-KISO


K20260606065909




BLK:13,SNR1: 9.5500 ,SNR2: 26.907




Frequency (Hz)



F20260606065912



BLK:10,SNR1: 6.4609 ,SNR2: 18.716




Frequency (Hz)


3C2

2026/06/05 22.01UT FUJI -KISO


K20260606065909





BLK:10,SNR1: 9.6424 ,SNR2: 27.147




Frequency (Hz)



T202606070634




BLK: 3,SNR1: 0.98111E-02,SNR2: 0.67754E-01




Frequency (Hz)

F202606070634




BLK: 3,SNR1: 0.25770 ,SNR2: 1.1899





Frequency (Hz)


0011+344 2026/06/05 22.14UT TOYOKAWA-FUJI





T20260606070634




BLK: 4,SNR1: 0.28494 ,SNR2: 0.48444




K20260606070631




BLK: 4,SNR1: 0.96746 ,SNR2: 4.9696




0011+344 2026/06/05 22.14UT TOYOKAWA-KISO



F20260606070634




BLK: 5,SNR1: 0.99191 ,SNR2: 3.1660




Frequency (Hz)

K20260606070631




BLK: 5,SNR1: 0.31146 ,SNR2: 1.5870





Frequency (Hz)


0011+344 2026/06/05 22.14UT FUJI -KISO



T202606071511




BLK: 4,SNR1: 0.15680 ,SNR2: 1.4810




Frequency (Hz)

F202606071511




BLK: 4,SNR1: 11.532 ,SNR2: 25.386





Frequency (Hz)


0019-00 2026/06/05 22.28UT TOYOKAWA-FUJI



T202606071511




BLK: 7,SNR1: 0.11575 ,SNR2: 0.68274




Frequency (Hz)

K202606071509




BLK: 7,SNR1: 2.6561 ,SNR2: 7.9644





Frequency (Hz)


0019-00 2026/06/05 22.28UT TOYOKAWA-KISO



F202606071511





BLK: 3,SNR1: 0.13767E-01,SNR2: 1.2652




Frequency (Hz)

K202606071509




BLK: 3,SNR1: 1.6915 ,SNR2: 4.7994




Frequency (Hz)


0019-00 2026/06/05 22.28UT FUJI -KISO



T20260606072525




BLK:12,SNR1: 3.8141 ,SNR2: 8.2236




Frequency (Hz)

3C12 2026/06/05 22.45UT TOYOKAWA-FUJI


F20260606072525





BLK:12,SNR1: 3.9701 ,SNR2: 11.137




Frequency (Hz)



T20260606072525





BLK:13,SNR1: 3.6762 ,SNR2: 7.9534




Frequency (Hz)

3C12 2026/06/05 22.45UT TOYOKAWA-KISO


K20260606072522




BLK:13,SNR1: 7.9503 ,SNR2: 20.895




Frequency (Hz)



F20260606072525





BLK:16,SNR1: 1.4694 ,SNR2: 4.7125




Frequency (Hz)

3C12 2026/06/05 22.45UT FUJI -KISO


K20260606072522





BLK:16,SNR1: 7.9434 ,SNR2: 20.878




Frequency (Hz)



T20260606073927




BLK: 6, SNR1: 2.8759 , SNR2: 13.690





0044-056 2026/06/05 22.69UT TOYOKAWA-FUJI



F20260606073927




BLK: 6, SNR1: 1.6650 , SNR2: 4.9889



T20260606073927





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0044-056 2026/06/05 22.69UT TOYOKAWA-KISO





F202606073927




No.Good Data




KISO





No.Good Data




0044-056 2026/06/05 22.69UT FUJI -KISO



T20260606074648



BLK: 4,SNR1: 0.26671E-01,SNR2: 0.79280




Frequency (Hz)


3C26

2026/06/05 22.81UT TOYOKAWA-FUJI


F20260606074648





BLK: 4,SNR1:-0.32253 ,SNR2: 0.24091




Frequency (Hz)





T20260606074648




No. Good Data




KISO





No. Good Data




3C26 2026/06/05 22.81UT TOYOKAWA-KISO





F202606074648




No.Good Data




KISO





No.Good Data




3C26 2026/06/05 22.81UT FUJI -KISO



T20260606075147





BLK: 7,SNR1: 7.5811 ,SNR2: 18.980




Frequency (Hz)

0056-00 2026/06/05 22.89UT TOYOKAWA-FUJI


F20260606075147




BLK: 7,SNR1: 15.047 ,SNR2: 27.202




Frequency (Hz)





T20260606075147




No.Good Data




KISO





No.Good Data




0056-00 2026/06/05 22.89UT TOYOKAWA-KISO





F202606075147




No.Good Data




KISO





No.Good Data




0056-00 2026/06/05 22.89UT FUJI -KISO



T20260606080129





BLK: 2, SNR1: 2.2684 , SNR2: 10.662





0106+01 2026/06/05 23.05UT TOYOKAWA-FUJI


F20260606080129




BLK: 2, SNR1: 82.691 , SNR2: 80.708





T20260606080129




No.Good Data




KISO





No.Good Data




0106+01 2026/06/05 23.05UT TOYOKAWA-KISO





F20260606080129




No.Good Data




KISO





No.Good Data




0106+01 2026/06/05 23.05UT FUJI -KISO



T202606081052





BLK: 2,SNR1: 16.758 ,SNR2: 39.113




Frequency (Hz)

0115-01 2026/06/05 23.21UT TOYOKAWA-FUJI


F202606081052





BLK: 2,SNR1: 16.244 ,SNR2: 34.645




Frequency (Hz)



T20260606081052





No.Good Data




Frequency (Hz)

KISO




No.Good Data





Frequency (Hz)


0115-01 2026/06/05 23.21UT TOYOKAWA-KISO





F202606081052




No.Good Data




KISO




No.Good Data




0115-01 2026/06/05 23.21UT FUJI -KISO



T20260606082351




BLK: 9, SNR1: 8.8882 , SNR2: 15.458





0128+03 2026/06/05 23.43UT TOYOKAWA-FUJI


F20260606082351




BLK: 9, SNR1: 6.1126 , SNR2: 15.647



T20260606082351




BLK: 7,SNR1: 5.2403 ,SNR2: 13.359





0128+03 2026/06/05 23.43UT TOYOKAWA-KISO


K20260606082348




BLK: 7,SNR1: 6.0728 ,SNR2: 14.174




F20260606082351




BLK: 7, SNR1: 5.7784 , SNR2: 20.141




K20260606082348





BLK: 7, SNR1: 7.0637 , SNR2: 17.393




0128+03 2026/06/05 23.43UT FUJI -KISO



T20260606083026





BLK: 3, SNR1: 19.851 , SNR2: 42.034




Frequency (Hz)

3C48 2026/06/05 23.54UT TOYOKAWA-FUJI


F20260606083026




BLK: 3, SNR1: 9.2923 , SNR2: 21.041




Frequency (Hz)



T20260606083026




BLK: 3, SNR1: 30.713 ,SNR2: 66.313





3C48 2026/06/05 23.54UT TOYOKAWA-KISO



K20260606083023




BLK: 3, SNR1: 16.146 ,SNR2: 37.931





F20260606083026




No. Good Data




K20260606083023




No. Good Data




3C48 2026/06/05 23.54UT FUJI -KISO



T20260606085009




BLK: 5,SNR1: 1.0459 ,SNR2: 6.9992





0155-109 2026/06/05 23.86UT TOYOKAWA-FUJI


F20260606085009




BLK: 5,SNR1:-0.29602 ,SNR2: 0.22555



T20260606085009




BLK: 3,SNR1: 1.0916 ,SNR2: 4.9955





0155-109 2026/06/05 23.86UT TOYOKAWA-KISO


K20260606085006




BLK: 3,SNR1: 0.28011E-01,SNR2: 0.53147



F20260606085009




BLK: 1,SNR1:-0.37930 ,SNR2: 0.27616




Frequency (Hz)

K20260606085006




BLK: 1,SNR1: 0.30307 ,SNR2: 0.45742





Frequency (Hz)


0155-109 2026/06/05 23.86UT FUJI -KISO



T20260606090907





BLK: 4, SNR1: 7.1640 , SNR2: 18.808




Frequency (Hz)

0213+178 2026/06/06 0.18UT TOYOKAWA-FUJI


F20260606090907





BLK: 4, SNR1: 7.2316 , SNR2: 18.508




Frequency (Hz)



T20260606090907




BLK: 3, SNR1: 6.5751 , SNR2: 17.583





0213+178 2026/06/06 0.18UT TOYOKAWA-KISO


K20260606090904




BLK: 3, SNR1: 6.7887 , SNR2: 17.610




F202606090907




BLK: 5,SNR1: 8.9360 ,SNR2: 22.128




K202606090904





BLK: 5,SNR1: 10.366 ,SNR2: 26.376




0213+178 2026/06/06 0.18UT FUJI -KISO



T202606091841





BLK: 4, SNR1: 12.578 ,SNR2: 31.655





0223+341 2026/06/06 0.34UT TOYOKAWA-FUJI



F202606091841




BLK: 4, SNR1: 15.742 ,SNR2: 38.055





T20260606091841




BLK: 2, SNR1: 12.582 , SNR2: 31.665




K20260606091838





BLK: 2, SNR1: 7.1664 , SNR2: 20.351




0223+341 2026/06/06 0.34UT TOYOKAWA-KISO





F202606091841




BLK: 2,SNR1: 11.136 ,SNR2: 20.781




K202606091838





BLK: 2,SNR1: 8.4628 ,SNR2: 24.330




0223+341 2026/06/06 0.34UT FUJI -KISO



T20260606093504





BLK: 2, SNR1: 10.911 , SNR2: 26.096




Frequency (Hz)

3C71 2026/06/06 0.61UT TOYOKAWA-FUJI


F20260606093504




BLK: 2, SNR1: 7.5232 , SNR2: 18.482




Frequency (Hz)



T20260606093504




BLK: 3,SNR1: 5.7627 ,SNR2: 21.975





3C71 2026/06/06 0.61UT TOYOKAWA-KISO



K20260606093501




BLK: 3,SNR1: 9.9010 ,SNR2: 23.742



F20260606093504





BLK: 7, SNR1: 7.5923 ,SNR2: 19.124





3C71 2026/06/06 0.61UT FUJI -KISO



K20260606093501




BLK: 7, SNR1: 6.3759 ,SNR2: 15.933



T202606095420




BLK: 1,SNR1: 20.978 ,SNR2: 38.633





0258+350 2026/06/06 0.93UT TOYOKAWA-FUJI



F202606095420




BLK: 1,SNR1: 13.847 ,SNR2: 33.368



T202606095420




BLK: 1,SNR1: 11.529 ,SNR2: 29.031





0258+350 2026/06/06 0.93UT TOYOKAWA-KISO


K202606095417




BLK: 1,SNR1: 10.506 ,SNR2: 26.049



F20260606095420




BLK: 1,SNR1: 14.542 ,SNR2: 24.984





0258+350 2026/06/06 0.93UT FUJI -KISO


K20260606095417




BLK: 1,SNR1: 8.1634 ,SNR2: 20.824



T20260606100410




BLK: 5, SNR1: 6.0989 , SNR2: 21.515




0308+305 2026/06/06 1.10UT TOYOKAWA-FUJI


F20260606100410




BLK: 5, SNR1: 7.7249 , SNR2: 19.389




Frequency (Hz)



T20260606100410





BLK: 3, SNR1: 7.1484 , SNR2: 24.843





0308+305 2026/06/06 1.10UT TOYOKAWA-KISO


K20260606100407




BLK: 3, SNR1: 5.7523 , SNR2: 14.814



F20260606100410




BLK: 3,SNR1: 7.2538 ,SNR2: 25.127




0308+305 2026/06/06 1.10UT FUJI -KISO


K20260606100407





BLK: 3,SNR1: 5.5645 ,SNR2: 14.620




0308+305 2026/06/06 1.10UT FUJI -KISO



T20260606101230





BLK: 5, SNR1: 2.6478 , SNR2: 5.7522





3C84 2026/06/06 1.24UT TOYOKAWA-FUJI



F20260606101230




BLK: 5, SNR1: 5.8249 , SNR2: 12.743



T20260606101230




BLK: 3,SNR1: 0.20020 ,SNR2: 4.6949





3C84 2026/06/06 1.24UT TOYOKAWA-KISO


K20260606101228




BLK: 3,SNR1: 3.1383 ,SNR2: 10.733



F20260606101230




BLK: 3,SNR1: 24.187 ,SNR2: 52.052





3C84 2026/06/06 1.24UT FUJI -KISO



K20260606101228




BLK: 3,SNR1: 3.7806 ,SNR2: 13.085





T20260606101945




No. Good Data




F20260606101945





No. Good Data




0324+119 2026/06/06 1.36UT TOYOKAWA-FUJI



T20260606101945





BLK: 2, SNR1: 2.3581 , SNR2: 11.239





0324+119 2026/06/06 1.36UT TOYOKAWA-KISO


K20260606101942




BLK: 2, SNR1: 15.056 , SNR2: 36.683





F20260606101945




BLK: 4,SNR1: 8.8784 ,SNR2: 21.922




K20260606101942





BLK: 4,SNR1: 10.823 ,SNR2: 26.549




0324+119 2026/06/06 1.36UT FUJI -KISO





T20260606102903




BLK: 4,SNR1: 1.2538 ,SNR2: 3.3240




F20260606102903




BLK: 4,SNR1: 6.6628 ,SNR2: 12.113




0333+32 2026/06/06 1.51UT TOYOKAWA-FUJI




T20260606102903




BLK: 3,SNR1: 0.31293 ,SNR2: 2.9264




K20260606102900




BLK: 3,SNR1: 6.9117 ,SNR2: 17.167




0333+32 2026/06/06 1.51UT TOYOKAWA-KISO




F20260606102903




BLK: 5,SNR1: 6.2156 ,SNR2: 11.007




K20260606102900




BLK: 5,SNR1: 7.5241 ,SNR2: 18.563




0333+32 2026/06/06 1.51UT FUJI -KISO




T20260606104203




BLK: 7,SNR1: 0.67868 ,SNR2: 1.5861




F20260606104203




BLK: 7,SNR1: 4.2649 ,SNR2: 10.848




0347+05 2026/06/06 1.73UT TOYOKAWA-FUJI



T20260606104203




BLK: 8,SNR1: 0.27416 ,SNR2: 2.0560





0347+05 2026/06/06 1.73UT TOYOKAWA-KISO




K20260606104201






BLK: 8,SNR1: 10.145 ,SNR2: 17.855




F20260606104203




K20260606104201




0347+05 2026/06/06 1.73UT FUJI -KISO




T20260606105737




BLK: 5,SNR1: 1.1349 ,SNR2: 3.0915




F20260606105737




BLK: 5,SNR1:-0.26264 ,SNR2: 0.55672




0403-132 2026/06/06 1.99UT TOYOKAWA-FUJI




T20260606105737




BLK:17,SNR1: 1.5428 ,SNR2: 3.0153




K20260606105734




BLK:17,SNR1: 2.6995 ,SNR2: 11.920




0403-132 2026/06/06 1.99UT TOYOKAWA-KISO




F20260606105737




BLK:13,SNR1: 1.7191 ,SNR2: 8.0080




K20260606105734





BLK:13,SNR1: 1.3925 ,SNR2: 5.5639




0403-132 2026/06/06 1.99UT FUJI -KISO




T20260606110648




BLK: 6,SNR1: 0.13077 ,SNR2: 0.79960




F20260606110648





BLK: 6,SNR1: 2.7203 ,SNR2: 8.5370




0411+05 2026/06/06 2.14UT TOYOKAWA-FUJI




T20260606110648




BLK:11,SNR1: 0.17437 ,SNR2: 1.0081




K20260606110645




BLK:11,SNR1: 4.2961 ,SNR2: 8.6716




0411+05 2026/06/06 2.14UT TOYOKAWA-KISO




F20260606110648




BLK: 8,SNR1: 0.93748 ,SNR2: 4.9352




K20260606110645





BLK: 8,SNR1: 8.7558 ,SNR2: 13.756




0411+05 2026/06/06 2.14UT FUJI -KISO





T20260606111742




BLK:10,SNR1: 0.31212 ,SNR2: 2.1195




F20260606111742





BLK:10,SNR1: 3.3644 ,SNR2: 5.9294




0422+178 2026/06/06 2.32UT TOYOKAWA-FUJI





T20260606111742




BLK:12,SNR1: 0.31751 ,SNR2: 2.3179




K20260606111739





BLK:12,SNR1: 1.0831 ,SNR2: 4.7423




0422+178 2026/06/06 2.32UT TOYOKAWA-KISO





F20260606111742




BLK: 4,SNR1:-0.10340 ,SNR2: 0.99369




K20260606111739




BLK: 4,SNR1: 1.0408 ,SNR2: 3.6823




0422+178 2026/06/06 2.32UT FUJI -KISO




T20260606112512




BLK:15,SNR1: 6.1088 ,SNR2: 17.711




F20260606112512




BLK:15,SNR1: 4.9358 ,SNR2: 12.140




3C119 2026/06/06 2.45UT TOYOKAWA-FUJI




T20260606112512




BLK:18,SNR1: 6.7210 ,SNR2: 17.356




K20260606112509




BLK:18,SNR1: 4.2306 ,SNR2: 10.882




3C119 2026/06/06 2.45UT TOYOKAWA-KISO




F20260606112512




BLK: 7,SNR1: 4.6311 ,SNR2: 11.039




K20260606112509




BLK: 7,SNR1: 4.5512 ,SNR2: 11.588




3C119 2026/06/06 2.45UT FUJI -KISO




T20260606121318




BLK:23,SNR1: 10.836 ,SNR2: 29.298




F20260606121318





BLK:23,SNR1: 6.4598 ,SNR2: 16.016




3C138 2026/06/06 3.25UT TOYOKAWA-FUJI





T20260606121318




BLK:24,SNR1: 10.548 ,SNR2: 27.426




K20260606121316




BLK:24,SNR1: 3.7228 ,SNR2: 13.740




3C138 2026/06/06 3.25UT TOYOKAWA-KISO



F20260606121318





BLK:15,SNR1: 2.3507 ,SNR2: 5.9738





3C138 2026/06/06 3.25UT FUJI -KISO


K20260606121316




BLK:15,SNR1: 2.3107 ,SNR2: 8.7368




T20260606122651




BLK:14,SNR1: 4.7340 ,SNR2: 13.303




F20260606122651





BLK:14,SNR1: 1.5881 ,SNR2: 5.1107




0531+194 2026/06/06 3.48UT TOYOKAWA-FUJI





T20260606122651




BLK:21,SNR1: 4.2692 ,SNR2: 8.3988




K20260606122648




BLK:21,SNR1: 8.8852 ,SNR2: 15.591




0531+194 2026/06/06 3.48UT TOYOKAWA-KISO



F20260606122651





BLK:28,SNR1: 5.3915 ,SNR2: 8.3712





0531+194 2026/06/06 3.48UT FUJI -KISO



K20260606122648




BLK:28,SNR1: 8.8605 ,SNR2: 15.542





T20260606123513




BLK:21,SNR1: 8.6679 ,SNR2: 20.035




F20260606123513





BLK:21,SNR1: 3.4641 ,SNR2: 9.2103




3C147 2026/06/06 3.62UT TOYOKAWA-FUJI




T20260606123513




BLK:34,SNR1: 7.0092 ,SNR2: 11.799




K20260606123510





BLK:34,SNR1: 3.1798 ,SNR2: 6.4283




3C147 2026/06/06 3.62UT TOYOKAWA-KISO




F20260606123513




BLK:14,SNR1: 2.0479 ,SNR2: 4.1004




K20260606123510





BLK:14,SNR1: 3.1698 ,SNR2: 13.863




3C147 2026/06/06 3.62UT FUJI -KISO



T20260606124322





BLK:24,SNR1: 16.536 ,SNR2: 29.158





0548+16 2026/06/06 3.75UT TOYOKAWA-FUJI



F20260606124322




BLK:24,SNR1: 21.266 ,SNR2: 27.675




T20260606124322




BLK:32,SNR1: 16.214 ,SNR2: 28.590




K20260606124319




BLK:32,SNR1: 7.5483 ,SNR2: 18.966




0548+16 2026/06/06 3.75UT TOYOKAWA-KISO




F20260606124322




BLK:27,SNR1: 22.879 ,SNR2: 29.583




K20260606124319





BLK:27,SNR1: 7.6365 ,SNR2: 19.185




0548+16 2026/06/06 3.75UT FUJI -KISO





T20260606124733




BLK:15,SNR1: 40.642 ,SNR2: 62.490




F20260606124733





BLK:15,SNR1: 10.522 ,SNR2: 25.712




0552+12 2026/06/06 3.82UT TOYOKAWA-FUJI





T20260606124733




BLK:14,SNR1: 41.803 ,SNR2: 63.802




K20260606124731





BLK:14,SNR1: 10.464 ,SNR2: 20.478




0552+12 2026/06/06 3.82UT TOYOKAWA-KISO





F20260606124733




BLK:10,SNR1: 28.749 ,SNR2: 51.251




K20260606124731





BLK:10,SNR1: 32.325 ,SNR2: 60.835




0552+12 2026/06/06 3.82UT FUJI -KISO





T20260606125200




BLK:16,SNR1: 9.9101 ,SNR2: 21.668




F20260606125200





BLK:16,SNR1: 7.8284 ,SNR2: 20.328




0556+191 2026/06/06 3.89UT TOYOKAWA-FUJI





T20260606125200




BLK:19,SNR1: 10.009 ,SNR2: 21.874




K20260606125158





BLK:19,SNR1: 3.3769 ,SNR2: 9.9730




0556+191 2026/06/06 3.89UT TOYOKAWA-KISO





F20260606125200




BLK:21,SNR1: 7.8546 ,SNR2: 20.372




K20260606125158





BLK:21,SNR1: 16.434 ,SNR2: 23.931




0556+191 2026/06/06 3.89UT FUJI -KISO





T20260606125945




BLK: 5,SNR1: 0.84767 ,SNR2: 3.7824




F20260606125945




BLK: 5,SNR1: 0.14439 ,SNR2: 1.9000




0605-08 2026/06/06 4.02UT TOYOKAWA-FUJI




T20260606125945




BLK: 8,SNR1: 0.68501 ,SNR2: 3.3704




K20260606125942





BLK: 8,SNR1: 1.4620 ,SNR2: 4.7731




0605-08 2026/06/06 4.02UT TOYOKAWA-KISO



F20260606125945





BLK: 4,SNR1:-0.14259 ,SNR2: 0.93967





0605-08 2026/06/06 4.02UT FUJI -KISO



K20260606125942




BLK: 4,SNR1: 1.0590 ,SNR2: 3.4583



T20260606131852





BLK:14,SNR1: 8.4119 ,SNR2: 18.835





3C161 2026/06/06 4.34UT TOYOKAWA-FUJI



F20260606131852




BLK:14,SNR1: 9.6731 ,SNR2: 15.200





T20260606131852




BLK:20,SNR1: 8.2606 ,SNR2: 18.504




K20260606131849





BLK:20,SNR1: 11.320 ,SNR2: 24.701




3C161 2026/06/06 4.34UT TOYOKAWA-KISO





F20260606131852




BLK:11,SNR1: 9.7837 ,SNR2: 22.067




K20260606131849





BLK:11,SNR1: 3.6974 ,SNR2: 10.817




3C161 2026/06/06 4.34UT FUJI -KISO





T20260606134625




BLK: 6,SNR1: 9.3860 ,SNR2: 17.052




F20260606134625





BLK: 6,SNR1: 3.3327 ,SNR2: 5.7100




0652-130 2026/06/06 4.80UT TOYOKAWA-FUJI





T20260606134625




BLK: 9,SNR1: 4.0320 ,SNR2: 10.448




K20260606134622




BLK: 9,SNR1: 8.4263 ,SNR2: 22.095




0652-130 2026/06/06 4.80UT TOYOKAWA-KISO





F20260606134625




BLK: 6,SNR1: 4.6085 ,SNR2: 7.8372




K20260606134622




BLK: 6,SNR1: 2.4002 ,SNR2: 7.6829




0652-130 2026/06/06 4.80UT FUJI -KISO




T20260606135802




BLK: 5,SNR1: 8.2427 ,SNR2: 20.793




F20260606135802




BLK: 5,SNR1: 7.7458 ,SNR2: 18.877




0703+138 2026/06/06 5.00UT TOYOKAWA-FUJI




T20260606135802




BLK: 5,SNR1: 3.6249 ,SNR2: 9.1194




K20260606135759




BLK: 5,SNR1: 4.7054 ,SNR2: 8.2655




0703+138 2026/06/06 5.00UT TOYOKAWA-KISO




F20260606135802




BLK: 8,SNR1: 6.6508 ,SNR2: 15.835




K20260606135759





BLK: 8,SNR1: 2.8194 ,SNR2: 5.5979




0703+138 2026/06/06 5.00UT FUJI -KISO





T20260606140725




BLK: 2,SNR1: 9.9813 ,SNR2: 24.819




F20260606140725





BLK: 2,SNR1: 10.722 ,SNR2: 25.960




0713-024 2026/06/06 5.15UT TOYOKAWA-FUJI





T20260606140725




No.Good Data




K20260606140722





No.Good Data




0713-024 2026/06/06 5.15UT TOYOKAWA-KISO





F20260606140725




BLK: 3,SNR1: 3.2047 ,SNR2: 8.1283




K20260606140722




BLK: 3,SNR1: 8.4551 ,SNR2: 20.916




0713-024 2026/06/06 5.15UT FUJI -KISO





T20260606141737




BLK: 2,SNR1: 9.0424 ,SNR2: 21.084




F20260606141737




BLK: 2,SNR1: 2.7396 ,SNR2: 13.061




0723+10 2026/06/06 5.32UT TOYOKAWA-FUJI




T20260606141737




BLK: 1,SNR1: 12.880 ,SNR2: 31.796




K20260606141734





BLK: 1,SNR1: 22.044 ,SNR2: 40.561




0723+10 2026/06/06 5.32UT TOYOKAWA-KISO



F20260606141737




BLK: 2,SNR1: 26.653 ,SNR2: 47.791




Frequency (Hz)

K20260606141734




BLK: 2,SNR1: 10.803 ,SNR2: 26.541





Frequency (Hz)


0723+10 2026/06/06 5.32UT FUJI -KISO




T20260606142752




BLK: 1,SNR1: 0.81538E-01,SNR2: 0.84111




F20260606142752





BLK: 1,SNR1: 3.5972 ,SNR2: 9.7131




0732+33 2026/06/06 5.49UT TOYOKAWA-FUJI




T20260606142752




BLK: 2,SNR1: 0.13089 ,SNR2: 1.1175




K20260606142750




BLK: 2,SNR1: 11.545 ,SNR2: 21.974




0732+33 2026/06/06 5.49UT TOYOKAWA-KISO




F20260606142752




BLK: 1,SNR1: 11.210 ,SNR2: 27.241




K20260606142750




BLK: 1,SNR1: 6.7497 ,SNR2: 17.309




0732+33 2026/06/06 5.49UT FUJI -KISO




T20260606143553




BLK: 6,SNR1: 0.73777 ,SNR2: 2.0171




F20260606143553





BLK: 6,SNR1: 2.5572 ,SNR2: 7.5686




0741-06 2026/06/06 5.63UT TOYOKAWA-FUJI




T20260606143553




BLK: 4,SNR1: 0.37524 ,SNR2: 3.7611




K20260606143551




BLK: 4,SNR1: 2.5269 ,SNR2: 8.8713




0741-06 2026/06/06 5.63UT TOYOKAWA-KISO





F20260606143553




BLK: 7,SNR1: 2.8916 ,SNR2: 8.5037




K20260606143551





BLK: 7,SNR1: 4.8949 ,SNR2: 7.9502




0741-06 2026/06/06 5.63UT FUJI -KISO



T20260606144537





BLK: 3,SNR1: 0.19277 ,SNR2: 1.7031




Frequency (Hz)

F20260606144537




BLK: 3,SNR1: 0.87230 ,SNR2: 4.8262




Frequency (Hz)


0752-200 2026/06/06 5.79UT TOYOKAWA-FUJI




T20260606144537




BLK: 6,SNR1:-0.21680E-01,SNR2: 0.98529




K20260606144534





BLK: 6,SNR1: 2.7950 ,SNR2: 11.805




0752-200 2026/06/06 5.79UT TOYOKAWA-KISO



F20260606144537





BLK: 2,SNR1: 0.69682 ,SNR2: 6.0904




Frequency (Hz)

K20260606144534




BLK: 2,SNR1: 0.97723 ,SNR2: 4.5352




Frequency (Hz)


0752-200 2026/06/06 5.79UT FUJI -KISO



T20260606145313




BLK: 2,SNR1: 19.030 ,SNR2: 34.431




Frequency (Hz)

F20260606145313




BLK: 2,SNR1: 15.432 ,SNR2: 28.434





Frequency (Hz)


3C190 2026/06/06 5.92UT TOYOKAWA-FUJI



T20260606145313





No.Good Data




Frequency (Hz)

K20260606145310




No.Good Data




Frequency (Hz)


3C190 2026/06/06 5.92UT TOYOKAWA-KISO





F20260606145313




BLK: 3,SNR1: 8.4817 ,SNR2: 20.696




K20260606145310





BLK: 3,SNR1: 7.8229 ,SNR2: 19.370




3C190 2026/06/06 5.92UT FUJI -KISO



T20260606150539




BLK: 4,SNR1: 8.9359 ,SNR2: 22.319




Frequency (Hz)

F20260606150539




BLK: 4,SNR1: 8.9901 ,SNR2: 22.447





Frequency (Hz)


3C196 2026/06/06 6.12UT TOYOKAWA-FUJI



T20260606150539





BLK: 2,SNR1: 3.9407 ,SNR2: 12.088




Frequency (Hz)

K20260606150536




BLK: 2,SNR1: 2.1604 ,SNR2: 10.431




Frequency (Hz)


3C196 2026/06/06 6.12UT TOYOKAWA-KISO




F20260606150539




BLK: 3,SNR1: 20.362 ,SNR2: 48.725




K20260606150536





BLK: 3,SNR1: 1.6789 ,SNR2: 11.412




3C196 2026/06/06 6.12UT FUJI -KISO





T20260606151648




No.Good Data




F20260606151648





No.Good Data




0821+394 2026/06/06 6.31UT TOYOKAWA-FUJI





T20260606151648




No.Good Data




K20260606151645





No.Good Data




0821+394 2026/06/06 6.31UT TOYOKAWA-KISO





F20260606151648




BLK: 2,SNR1: 18.820 ,SNR2: 33.431




K20260606151645





BLK: 2,SNR1: 17.220 ,SNR2: 30.104




0821+394 2026/06/06 6.31UT FUJI -KISO



T20260606152826





BLK: 2,SNR1: 14.862 ,SNR2: 26.506




Frequency (Hz)

F20260606152826




BLK: 2,SNR1: 13.582 ,SNR2: 32.707





Frequency (Hz)


0834-19 2026/06/06 6.50UT TOYOKAWA-FUJI



T20260606152826





BLK: 3,SNR1: 11.513 ,SNR2: 28.170




Frequency (Hz)

K20260606152823




BLK: 3,SNR1: 12.451 ,SNR2: 30.030




Frequency (Hz)


0834-19 2026/06/06 6.50UT TOYOKAWA-KISO



F20260606152826




BLK: 1,SNR1: 19.448 ,SNR2: 34.892




Frequency (Hz)

K20260606152823




BLK: 1,SNR1: 2.4497 ,SNR2: 11.391




Frequency (Hz)


0834-19 2026/06/06 6.50UT FUJI -KISO



T20260606153332




BLK: 1,SNR1: 11.501 ,SNR2: 28.400




Frequency (Hz)

F20260606153332




BLK: 1,SNR1: 7.3982 ,SNR2: 18.198




Frequency (Hz)


0839-071 2026/06/06 6.59UT TOYOKAWA-FUJI



T20260606153332




BLK: 2,SNR1: 8.2187 ,SNR2: 20.396




Frequency (Hz)

K20260606153329




BLK: 2,SNR1: 7.4219 ,SNR2: 18.355




Frequency (Hz)


0839-071 2026/06/06 6.59UT TOYOKAWA-KISO



F20260606153332




BLK: 4,SNR1: 11.733 ,SNR2: 28.596




Frequency (Hz)

K20260606153329




BLK: 4,SNR1: 9.4312 ,SNR2: 23.259




Frequency (Hz)


0839-071 2026/06/06 6.59UT FUJI -KISO



T20260606154433




BLK: 5,SNR1: 0.32377 ,SNR2: 2.1830




Frequency (Hz)

F20260606154433




BLK: 5,SNR1: 3.1381 ,SNR2: 11.283




Frequency (Hz)


3C208 2026/06/06 6.77UT TOYOKAWA-FUJI




T20260606154433




BLK: 7,SNR1: 0.63743 ,SNR2: 1.8577




K20260606154430





BLK: 7,SNR1: 8.3493 ,SNR2: 18.681




3C208 2026/06/06 6.77UT TOYOKAWA-KISO



F20260606154433




BLK: 4,SNR1: 3.6992 ,SNR2: 8.4140




Frequency (Hz)

K20260606154430




BLK: 4,SNR1: 2.9304 ,SNR2: 8.8514





Frequency (Hz)


3C208 2026/06/06 6.77UT FUJI -KISO





T20260606160116




No.Good Data




F20260606160116





No.Good Data




3C216 2026/06/06 7.05UT TOYOKAWA-FUJI





T20260606160116




No.Good Data




K20260606160113





No.Good Data




3C216 2026/06/06 7.05UT TOYOKAWA-KISO



F20260606160116




BLK: 2,SNR1: 7.5330 ,SNR2: 18.856




Frequency (Hz)

3C216 2026/06/06 7.05UT FUJI -KISO


K20260606160113





BLK: 2,SNR1: 7.6206 ,SNR2: 19.078




Frequency (Hz)



T20260606161325





BLK: 1,SNR1: 5.9048 ,SNR2: 13.007




Frequency (Hz)

0919-142 2026/06/06 7.25UT TOYOKAWA-FUJI


F20260606161325





BLK: 1,SNR1: 8.5866 ,SNR2: 18.712




Frequency (Hz)



T20260606161325




No.Good Data




Frequency (Hz)

K20260606161322




No.Good Data





Frequency (Hz)


0919-142 2026/06/06 7.25UT TOYOKAWA-KISO



F20260606161325




BLK: 1,SNR1: 7.6623 ,SNR2: 17.100




Frequency (Hz)

K20260606161322




BLK: 1,SNR1: 10.464 ,SNR2: 22.953





Frequency (Hz)


0919-142 2026/06/06 7.25UT FUJI -KISO





T20260606162005




BLK: 3,SNR1: 9.3255 ,SNR2: 22.923




F20260606162005





BLK: 3,SNR1: 8.6949 ,SNR2: 21.488




0926+117 2026/06/06 7.36UT TOYOKAWA-FUJI



T20260606162005





BLK: 2, SNR1: 6.8025 , SNR2: 20.821




Frequency (Hz)

K20260606162002




BLK: 2, SNR1: 9.0333 , SNR2: 23.364





Frequency (Hz)


0926+117 2026/06/06 7.36UT TOYOKAWA-KISO



F20260606162005





BLK: 6,SNR1: 7.9282 ,SNR2: 14.066




Frequency (Hz)

K20260606162002




BLK: 6,SNR1: 8.0221 ,SNR2: 20.753





Frequency (Hz)


0926+117 2026/06/06 7.36UT FUJI -KISO



T20260606162749





BLK: 8,SNR1: 0.94539 ,SNR2: 3.1281




Frequency (Hz)

F20260606162749




BLK: 8,SNR1: 0.41098 ,SNR2: 2.1957





Frequency (Hz)


3C222 2026/06/06 7.49UT TOYOKAWA-FUJI



T20260606162749





BLK: 3,SNR1: 7.0913 ,SNR2: 17.383




Frequency (Hz)

3C222 2026/06/06 7.49UT TOYOKAWA-KISO


K20260606162746




BLK: 3,SNR1: 0.51348 ,SNR2: 1.9710




Frequency (Hz)



F20260606162749





BLK: 4,SNR1: 0.53772 ,SNR2: 2.6432




Frequency (Hz)

K20260606162746




BLK: 4,SNR1: 1.0328 ,SNR2: 4.6287





Frequency (Hz)


3C222 2026/06/06 7.49UT FUJI -KISO



T20260606163449





BLK: 1,SNR1: 27.343 ,SNR2: 49.357




Frequency (Hz)

F20260606163449




BLK: 1,SNR1: 9.9273 ,SNR2: 24.394





Frequency (Hz)


0941-08 2026/06/06 7.61UT TOYOKAWA-FUJI



T20260606163449




BLK: 1,SNR1: 14.324 ,SNR2: 25.311




Frequency (Hz)

K20260606163446




BLK: 1,SNR1: 11.252 ,SNR2: 27.235




Frequency (Hz)


0941-08 2026/06/06 7.61UT TOYOKAWA-KISO



F20260606163449




BLK: 2, SNR1: 10.788 , SNR2: 26.425




Frequency (Hz)

K20260606163446




BLK: 2, SNR1: 2.7263 , SNR2: 12.240





Frequency (Hz)


0941-08 2026/06/06 7.61UT FUJI -KISO



T20260606164311





BLK: 1,SNR1: 11.633 ,SNR2: 26.854




Frequency (Hz)

F20260606164311




BLK: 1,SNR1: 21.505 ,SNR2: 38.865





Frequency (Hz)


3C230 2026/06/06 7.75UT TOYOKAWA-FUJI



T20260606164311





No.Good Data




Frequency (Hz)

K20260606164308




No.Good Data




Frequency (Hz)


3C230 2026/06/06 7.75UT TOYOKAWA-KISO



F20260606164311





BLK: 6,SNR1: 11.936 ,SNR2: 21.624




Frequency (Hz)

K20260606164308




BLK: 6,SNR1: 13.780 ,SNR2: 24.137





Frequency (Hz)


3C230 2026/06/06 7.75UT FUJI -KISO



T20260606165912





No.Good Data




Frequency (Hz)

F20260606165912




No.Good Data





Frequency (Hz)


3C237 2026/06/06 8.01UT TOYOKAWA-FUJI



T20260606165912





No.Good Data




Frequency (Hz)

K20260606165909




No.Good Data




Frequency (Hz)


3C237 2026/06/06 8.01UT TOYOKAWA-KISO



F20260606165912





BLK: 1,SNR1: 7.1752 ,SNR2: 17.900




Frequency (Hz)

K20260606165909




BLK: 1,SNR1: 10.560 ,SNR2: 26.236




Frequency (Hz)


3C237 2026/06/06 8.01UT FUJI -KISO



T20260606170528




BLK: 5, SNR1: 4.5998 , SNR2: 13.235




Frequency (Hz)

F20260606170528




BLK: 5, SNR1: 10.296 , SNR2: 21.771




Frequency (Hz)


1011+110 2026/06/06 8.12UT TOYOKAWA-FUJI



T20260606170528





BLK: 8,SNR1: 2.7161 ,SNR2: 8.6694




Frequency (Hz)

K20260606170526




BLK: 8,SNR1: 11.097 ,SNR2: 19.678




Frequency (Hz)


1011+110 2026/06/06 8.12UT TOYOKAWA-KISO



F20260606170528





BLK: 4,SNR1: 12.439 ,SNR2: 26.258




Frequency (Hz)

K20260606170526




BLK: 4,SNR1: 2.7897 ,SNR2: 8.6276





Frequency (Hz)


1011+110 2026/06/06 8.12UT FWJ -KISO



T20260606171310





BLK: 1,SNR1: 4.5182 ,SNR2: 10.613




Frequency (Hz)

F20260606171310




BLK: 1,SNR1: 0.48771 ,SNR2: 3.8346





Frequency (Hz)


3C241 2026/06/06 8.25UT TOYOKAWA-FUJI



T20260606171310





BLK: 2,SNR1: 3.8572 ,SNR2: 6.9228




Frequency (Hz)

K20260606171308




BLK: 2,SNR1: 8.9136 ,SNR2: 20.131





Frequency (Hz)


3C241 2026/06/06 8.25UT TOYOKAWA-KISO



F20260606171310




BLK: 4,SNR1: 8.0403 ,SNR2: 19.356




Frequency (Hz)

K20260606171308



BLK: 4,SNR1: 8.8433 ,SNR2: 19.482



Frequency (Hz)

3C241 2026/06/06 8.25UT FUJI -KISO

