



T20260611053035





BLK: 5,SNR1: 0.17235 ,SNR2: 0.97778




Frequency (Hz)

F20260611053035




BLK: 5,SNR1: 2.6479 ,SNR2: 6.6532





Frequency (Hz)


2255+416 2026/06/10 20.54UT TOYOKAWA-FUJI



T20260611053035





BLK: 9,SNR1: 0.18934 ,SNR2: 1.3736




Frequency (Hz)

K20260611053032




BLK: 9,SNR1: 0.90457 ,SNR2: 3.5449





Frequency (Hz)


2255+416 2026/06/10 20.54UT TOYOKAWA-KISO



F20260611053035





BLK: 5, SNR1: 6.3045 ,SNR2: 16.237




Frequency (Hz)

K20260611053032




BLK: 5, SNR1: 7.5647 ,SNR2: 19.512





Frequency (Hz)


2255+416 2026/06/10 20.54UT FUJI -KISO



T20260611053457





BLK:11,SNR1: 5.1658 ,SNR2: 12.638




Frequency (Hz)

F20260611053457




BLK:11,SNR1: 4.8768 ,SNR2: 12.095





Frequency (Hz)


2259+481 2026/06/10 20.61UT TOYOKAWA-FUJI



T20260611053457





BLK:11,SNR1: 6.7990 ,SNR2: 16.853




Frequency (Hz)

K20260611053454




BLK:11,SNR1: 5.5129 ,SNR2: 13.341





Frequency (Hz)


2259+481 2026/06/10 20.61UT TOYOKAWA-KISO



F20260611053457




BLK: 8,SNR1: 5.9003 ,SNR2: 15.365




Frequency (Hz)

2259+481 2026/06/10 20.61UT FUJI -KISO


K20260611053454




BLK: 8,SNR1: 5.3469 ,SNR2: 12.971




Frequency (Hz)



T20260611054659





BLK: 7,SNR1: 4.7018 ,SNR2: 11.074




Frequency (Hz)

F20260611054659




BLK: 7,SNR1: 1.8760 ,SNR2: 6.5432




Frequency (Hz)


2311+469 2026/06/10 20.81UT TOYOKAWA-FUJI



T20260611054659




BLK: 8,SNR1: 3.9884 ,SNR2: 10.016




Frequency (Hz)

K20260611054656




BLK: 8,SNR1: 4.8873 ,SNR2: 11.594





Frequency (Hz)


2311+469 2026/06/10 20.81UT TOYOKAWA-KISO





F20260611054659




No.Good Data




K20260611054656





No.Good Data




2311+469 2026/06/10 20.81UT FUJI -KISO



T20260611060112





BLK: 5, SNR1: 7.3463 ,SNR2: 21.158




Frequency (Hz)

F20260611060112




BLK: 5, SNR1: 12.392 ,SNR2: 30.611





Frequency (Hz)


2325+269 2026/06/10 21.05UT TOYOKAWA-FUJI



T20260611060112





BLK: 4,SNR1: 9.9167 ,SNR2: 24.960




Frequency (Hz)

K20260611060109




BLK: 4,SNR1: 9.0872 ,SNR2: 22.641





Frequency (Hz)


2325+269 2026/06/10 21.05UT TOYOKAWA-KISO





F20260611060112




BLK: 3,SNR1: 14.560 ,SNR2: 35.428




K20260611060109





BLK: 3,SNR1: 9.0876 ,SNR2: 22.642




2325+269 2026/06/10 21.05UT FUJI -KISO



T20260611063030





No. Good Data




Frequency (Hz)

F20260611063030




No. Good Data





Frequency (Hz)


2354+14 2026/06/10 21.54UT TOYOKAWA-FUJI



T20260611063030





BLK: 1,SNR1: 0.18648 ,SNR2: 1.5650




Frequency (Hz)

K20260611063027




BLK: 1,SNR1: 5.0986 ,SNR2: 12.419





Frequency (Hz)


2354+14 2026/06/10 21.54UT TOYOKAWA-KISO



F20260611063030





BLK: 1,SNR1: 3.9235 ,SNR2: 10.269




Frequency (Hz)

K20260611063027




BLK: 1,SNR1: 6.6630 ,SNR2: 23.196





Frequency (Hz)


2354+14 2026/06/10 21.54UT FUJI -KISO



T20260611063933



BLK: 7,SNR1: 5.4693 ,SNR2: 13.869





Frequency (Hz)


3C2

2026/06/10 21.69UT TOYOKAWA-FUJI


F20260611063934





BLK: 7,SNR1: 6.4275 ,SNR2: 16.332




Frequency (Hz)



T20260611063933



BLK: 3,SNR1: 6.5867 ,SNR2: 18.574





Frequency (Hz)


3C2

2026/06/10 21.69UT TOYOKAWA-KISO


K20260611063931





BLK: 3,SNR1: 6.4489 ,SNR2: 16.056




Frequency (Hz)



F20260611063934





BLK: 4, SNR1: 4.7983 ,SNR2: 12.094




Frequency (Hz)

3C2 2026/06/10 21.69UT FUJI -KISO


K20260611063931





BLK: 4, SNR1: 8.3458 ,SNR2: 20.782




Frequency (Hz)



T20260611064654




BLK: 2,SNR1: 4.8999 ,SNR2: 14.654




Frequency (Hz)

F20260611064654




BLK: 2,SNR1: 10.983 ,SNR2: 26.758





Frequency (Hz)


0011+344 2026/06/10 21.81UT TOYOKAWA-FUJI



T20260611064654





BLK: 4,SNR1: 10.413 ,SNR2: 30.191




Frequency (Hz)

K20260611064651




BLK: 4,SNR1: 9.8292 ,SNR2: 28.415




Frequency (Hz)


0011+344 2026/06/10 21.81UT TOYOKAWA-KISO




F20260611064654




BLK: 2,SNR1: 7.6656 ,SNR2: 19.719




K20260611064651





BLK: 2,SNR1: 9.1907 ,SNR2: 22.888




0011+344 2026/06/10 21.81UT FUJI -KISO



T20260611065531





BLK: 6,SNR1: 9.0326 ,SNR2: 26.113




Frequency (Hz)

F20260611065531




BLK: 6,SNR1: 12.513 ,SNR2: 29.401





Frequency (Hz)


0019-00 2026/06/10 21.95UT TOYOKAWA-FUJI



T20260611065531





BLK: 4,SNR1: 10.781 ,SNR2: 31.632




Frequency (Hz)

K20260611065528




BLK: 4,SNR1: 12.265 ,SNR2: 35.498





Frequency (Hz)


0019-00 2026/06/10 21.95UT TOYOKAWA-KISO



F20260611065531




BLK:10,SNR1: 7.1653 ,SNR2: 19.966




Frequency (Hz)

K20260611065528




BLK:10,SNR1: 13.199 ,SNR2: 32.798




Frequency (Hz)


0019-00 2026/06/10 21.95UT FUJI -KISO



T20260611070545





BLK: 8,SNR1: 0.94336 ,SNR2: 2.3229




Frequency (Hz)

3C12 2026/06/10 22.12UT TOYOKAWA-FUJI


F20260611070545




BLK: 8,SNR1: 1.7198 ,SNR2: 4.4887




Frequency (Hz)



T20260611070545





BLK: 7,SNR1: 0.29985 ,SNR2: 0.97447




Frequency (Hz)

3C12 2026/06/10 22.12UT TOYOKAWA-KISO


K20260611070542





BLK: 7,SNR1: 8.9360 ,SNR2: 22.805




Frequency (Hz)



F20260611070545





BLK: 3,SNR1: 2.2623 ,SNR2: 6.7806




Frequency (Hz)

3C12 2026/06/10 22.12UT FUJI -KISO


K20260611070542





BLK: 3,SNR1: 6.2380 ,SNR2: 18.598




Frequency (Hz)



T20260611071404





BLK: 4, SNR1: 11.936 , SNR2: 21.267




Frequency (Hz)

F20260611071404




BLK: 4, SNR1: 7.4960 , SNR2: 18.854





Frequency (Hz)


0038+328 2026/06/10 22.26UT TOYOKAWA-FUJI



T20260611071404





BLK: 4,SNR1: 13.810 ,SNR2: 24.506




Frequency (Hz)

K20260611071401




BLK: 4,SNR1: 8.5344 ,SNR2: 20.537





Frequency (Hz)


0038+328 2026/06/10 22.28UT TOYOKAWA-KISO





F20260611071404




BLK: 1,SNR1: 0.75080 ,SNR2: 4.6771




K20260611071401





BLK: 1,SNR1:-0.37790E-01,SNR2: 0.80233




0038+328 2026/06/10 22.26UT FUJI -KISO



T20260611072708





BLK: 2,SNR1: 13.511 ,SNR2: 34.142




Frequency (Hz)

3C26 2026/06/10 22.48UT TOYOKAWA-FUJI


F20260611072708





BLK: 2,SNR1: 10.319 ,SNR2: 27.500




Frequency (Hz)



T20260611072708





BLK:11,SNR1: 6.5957 ,SNR2: 17.432




Frequency (Hz)

3C26 2026/06/10 22.48UT TOYOKAWA-KISO


K20260611072705





BLK:11,SNR1: 7.5182 ,SNR2: 19.891




Frequency (Hz)



F20260611072708





BLK: 9,SNR1: 7.4852 ,SNR2: 21.341




Frequency (Hz)

3C26 2026/06/10 22.48UT FUJI -KISO


K20260611072705





BLK: 9,SNR1: 7.5596 ,SNR2: 20.731




Frequency (Hz)





T20260611073207




No.Good Data




F20260611073207





No.Good Data




0056-00 2026/06/10 22.56UT TOYOKAWA-FUJI



T20260611073207





BLK: 1,SNR1: 7.7947 ,SNR2: 22.312




Frequency (Hz)

0056-00 2026/06/10 22.58UT TOYOKAWA-KISO


K20260611073204





BLK: 1,SNR1: 13.361 ,SNR2: 30.965




Frequency (Hz)





F20260611073207




BLK: 3,SNR1: 7.7603 ,SNR2: 19.785




K20260611073204





BLK: 3,SNR1: 11.101 ,SNR2: 26.218




0056-00 2026/06/10 22.56UT FUJI -KISO



T20260611074149





BLK: 2,SNR1: 0.25799 ,SNR2: 0.75451




Frequency (Hz)

F20260611074149




BLK: 2,SNR1: 2.0726 ,SNR2: 6.7827





Frequency (Hz)


0106+01 2026/06/10 22.73UT TOYOKAWA-FUJI



T20260611074149





BLK: 3,SNR1: 1.6023 ,SNR2: 4.7051




Frequency (Hz)

K20260611074146




BLK: 3,SNR1: 8.9271 ,SNR2: 19.551




Frequency (Hz)


0106+01 2026/06/10 22.73UT TOYOKAWA-KISO



F20260611074149





BLK:16,SNR1: 1.5374 ,SNR2: 5.0927




Frequency (Hz)

K20260611074146




BLK:16,SNR1: 2.9961 ,SNR2: 9.1368




Frequency (Hz)


0106+01 2026/06/10 22.73UT FUJI -KISO



T20260611075112




BLK: 5,SNR1: 1.5768 ,SNR2: 4.8579





0115-01 2026/06/10 22.88UT TOYOKAWA-FUJI


F20260611075112




BLK: 5,SNR1: 0.36275 ,SNR2: 1.2092



T20260611075112




BLK: 4,SNR1: 5.0171 ,SNR2: 14.599





0115-01 2026/06/10 22.88UT TOYOKAWA-KISO


K20260611075109




BLK: 4,SNR1: 6.8532 ,SNR2: 17.705



F20260611075112




BLK: 3,SNR1: 2.0011 ,SNR2: 6.5212





0115-01 2026/06/10 22.88UT FWJ -KISO



K20260611075109




BLK: 3,SNR1: 8.9596 ,SNR2: 21.977



T20260611080412





BLK:15,SNR1: 11.385 ,SNR2: 24.300





0128+03 2026/06/10 23.10UT TOYOKAWA-FUJI



F20260611080412




BLK:15,SNR1: 10.453 ,SNR2: 25.937



T20260611080412




BLK:18,SNR1: 7.1313 ,SNR2: 18.374





0128+03 2026/06/10 23.10UT TOYOKAWA-KISO



K20260611080409




BLK:18,SNR1: 9.2107 ,SNR2: 20.574





F20260611080412




BLK:23,SNR1: 10.106 ,SNR2: 25.091




K20260611080409





BLK:23,SNR1: 9.1171 ,SNR2: 20.590




0128+03 2026/06/10 23.10UT FUJI -KISO



T20260611081046





BLK: 8,SNR1: 9.6094 ,SNR2: 23.628





3C48 2026/06/10 23.21UT TOYOKAWA-FUJI



F20260611081046




BLK: 8,SNR1: 7.8033 ,SNR2: 19.097



T20260611081046





BLK: 8, SNR1: 9.2147 ,SNR2: 23.010





3C48 2026/06/10 23.21UT TOYOKAWA-KISO



K20260611081043




BLK: 8, SNR1: 10.120 ,SNR2: 24.932



F20260611081046





BLK: 2,SNR1: 9.5554 ,SNR2: 22.843





3C48 2026/06/10 23.21UT FUJI -KISO


K20260611081043




BLK: 2,SNR1: 14.072 ,SNR2: 34.390



T20260611083030




BLK: 4,SNR1: 11.619 ,SNR2: 25.635





0155-109 2026/06/10 23.54UT TOYOKAWA-FUJI


F20260611083030




BLK: 4,SNR1: 9.6469 ,SNR2: 20.450



T20260611083030




BLK: 8,SNR1: 13.055 ,SNR2: 28.117





0155-109 2026/06/10 23.54UT TOYOKAWA-KISO


K20260611083027




BLK: 8,SNR1: 8.2026 ,SNR2: 21.239




F20260611083030




BLK: 6,SNR1: 13.421 ,SNR2: 23.460




K20260611083027





BLK: 6,SNR1: 7.9869 ,SNR2: 20.704




0155-109 2026/06/10 23.54UT FUJI -KISO



T20260611083738




BLK: 4, SNR1: 4.3229 ,SNR2: 9.7320





0202+15 2026/06/10 23.66UT TOYOKAWA-FUJI



F20260611083738




BLK: 4, SNR1: 0.60552 ,SNR2: 1.6156




T20260611083738




BLK: 7,SNR1: 0.22514E-01,SNR2: 0.70829




K20260611083735




BLK: 7,SNR1: 1.5407 ,SNR2: 5.2980




0202+15 2026/06/10 23.66UT TOYOKAWA-KISO




F20260611083738




BLK: 8,SNR1: 0.11108E-01,SNR2: 0.56444




K20260611083735







BLK: 8,SNR1: 1.4554 ,SNR2: 5.4836




0202+15 2026/06/10 23.66UT FUJI -KISO







0213+178 2026/06/10 23.85UT TOYOKAWA-FUJI





T20260611084928




BLK:12,SNR1: 1.6453 ,SNR2: 4.9254




K20260611084925




BLK:12,SNR1: 4.2593 ,SNR2: 11.401




0213+178 2026/06/10 23.85UT TOYOKAWA-KISO





F20260611084928




BLK:11,SNR1: 0.31038 ,SNR2: 3.2639




K20260611084925




BLK:11,SNR1: 4.3679 ,SNR2: 11.567




0213+178 2026/06/10 23.85UT FUJI -KISO




T20260611091525




BLK: 2,SNR1:-0.29188E-01,SNR2: 0.87259




F20260611091525




BLK: 2,SNR1: 4.4981 ,SNR2: 9.8859




3C71 2026/06/11 0.29UT TOYOKAWA-FUJI



T20260611091525




BLK: 2,SNR1: 0.29112 ,SNR2: 1.8695





3C71 2026/06/11 0.29UT TOYOKAWA-KISO


K20260611091523




BLK: 2,SNR1: 8.0579 ,SNR2: 15.706



F20260611091525




BLK: 1,SNR1: 0.74987 ,SNR2: 4.7743





3C71 2026/06/11 0.29UT FUJI -KISO


K20260611091523




BLK: 1,SNR1: 0.31381 ,SNR2: 2.5711





T20260611093441




BLK: 3,SNR1:-0.34294E-01,SNR2: 2.3118




F20260611093441





BLK: 3,SNR1: 1.3632 ,SNR2: 3.7906




0258+350 2026/06/11 0.61UT TOYOKAWA-FUJI



T20260611093441





BLK: 4,SNR1: 0.63484 ,SNR2: 1.3983




Frequency (Hz)

K20260611093438




BLK: 4,SNR1: 1.3943 ,SNR2: 5.2938




Frequency (Hz)


0258+350 2026/06/11 0.61UT TOYOKAWA-KISO





F20260611093441




BLK:15,SNR1: 1.9536 ,SNR2: 5.7662




K20260611093438




BLK:15,SNR1: 8.2168 ,SNR2: 24.561




0258+350 2026/06/11 0.61UT FUJI -KISO



T20260611094430




BLK:19,SNR1: 2.7525 ,SNR2: 6.4951





0308+305 2026/06/11 0.77UT TOYOKAWA-FUJI


F20260611094430




BLK:19,SNR1: 1.4798 ,SNR2: 5.4333



T20260611094430




BLK:25,SNR1: 2.3334 ,SNR2: 5.4209





0308+305 2026/06/11 0.77UT TOYOKAWA-KISO



K20260611094428




BLK:25,SNR1: 9.1306 ,SNR2: 13.421



F20260611094430





BLK:26,SNR1: 1.5249 ,SNR2: 4.1942




Frequency (Hz)

0308+305 2026/06/11 0.77UT FUJI -KISO


K20260611094428




BLK:26,SNR1: 4.7523 ,SNR2: 12.396




Frequency (Hz)





T20260611095251




BLK:13,SNR1: 0.63358 ,SNR2: 1.5608




F20260611095251




BLK:13,SNR1: 6.2657 ,SNR2: 9.7660




3C84 2026/06/11 0.91UT TOYOKAWA-FUJI



T20260611095251




BLK:22,SNR1: 3.3316 ,SNR2: 9.9575





3C84 2026/06/11 0.91UT TOYOKAWA-KISO



K20260611095248




BLK:22,SNR1: 3.4118 ,SNR2: 10.002



F20260611095251




BLK:12,SNR1: 9.5671 ,SNR2: 16.984





3C84 2026/06/11 0.91UT FUJI -KISO


K20260611095248




BLK:12,SNR1: 2.7042 ,SNR2: 8.3051



T20260611100006




BLK: 1,SNR1: 4.8270 ,SNR2: 12.047




0324+119 2026/06/11 1.03UT TOYOKAWA-FUJI


F20260611100006




BLK: 1,SNR1: 11.488 ,SNR2: 32.735




Frequency (Hz)



T20260611100006




BLK: 5, SNR1: 9.9736 , SNR2: 26.618





0324+119 2026/06/11 1.03UT TOYOKAWA-KISO


K20260611100003




BLK: 5, SNR1: 8.2662 , SNR2: 22.802



F20260611100006





BLK: 4,SNR1: 9.1178 ,SNR2: 23.244





0324+119 2026/06/11 1.03UT FUJI -KISO



K20260611100003




BLK: 4,SNR1: 12.154 ,SNR2: 28.267



T20260611100923





BLK: 6,SNR1: 10.245 ,SNR2: 24.444





0333+32 2026/06/11 1.18UT TOYOKAWA-FUJI



F20260611100923




BLK: 6,SNR1: 13.909 ,SNR2: 34.265



T20260611100923





BLK: 4, SNR1: 15.500 ,SNR2: 35.727




0333+32 2026/06/11 1.18UT TOYOKAWA-KISO


K20260611100920





BLK: 4, SNR1: 11.464 ,SNR2: 29.254




Frequency (Hz)



F20260611100923





BLK: 9,SNR1: 15.947 ,SNR2: 37.237





0333+32 2026/06/11 1.18UT FUJI -KISO



K20260611100920




BLK: 9,SNR1: 11.207 ,SNR2: 27.814



T20260611102224




BLK: 1,SNR1: 10.818 ,SNR2: 26.587




0347+05 2026/06/11 1.40UT TOYOKAWA-FUJI


F20260611102224





BLK: 1,SNR1: 21.092 ,SNR2: 48.232




Frequency (Hz)



T20260611102224




BLK: 1,SNR1: 10.564 ,SNR2: 26.283





0347+05 2026/06/11 1.40UT TOYOKAWA-KISO


K20260611102221




BLK: 1,SNR1: 10.496 ,SNR2: 26.112



F20260611102224





BLK: 1,SNR1: 9.7565 ,SNR2: 29.317





0347+05 2026/06/11 1.40UT FUJI -KISO


K20260611102221




BLK: 1,SNR1: 9.4521 ,SNR2: 23.656




T20260611103758




BLK:14,SNR1: 2.5993 ,SNR2: 8.2418




F20260611103758




BLK:14,SNR1: 4.4334 ,SNR2: 16.098




0403-132 2026/06/11 1.66UT TOYOKAWA-FUJI




T20260611103758




BLK:13,SNR1: 3.2554 ,SNR2: 9.9628




K20260611103756




BLK:13,SNR1: 8.4360 ,SNR2: 14.674




0403-132 2026/06/11 1.66UT TOYOKAWA-KISO




F20260611103758




BLK:10,SNR1: 5.4756 ,SNR2: 14.007




K20260611103756





BLK:10,SNR1: 6.7106 ,SNR2: 12.059




0403-132 2026/06/11 1.66UT FUJI -KISO




T20260611104709




BLK:15,SNR1: 4.3675 ,SNR2: 10.490




F20260611104709





BLK:15,SNR1: 3.6690 ,SNR2: 12.963




0411+05 2026/06/11 1.81UT TOYOKAWA-FUJI





T20260611104709




BLK:16,SNR1: 1.8359 ,SNR2: 4.5732




K20260611104706




BLK:16,SNR1: 7.4642 ,SNR2: 16.513




0411+05 2026/06/11 1.81UT TOYOKAWA-KISO





F20260611104709




BLK:19,SNR1: 3.6789 ,SNR2: 12.737




K20260611104706







BLK:19,SNR1: 7.2180 ,SNR2: 16.000





0411+05 2026/06/11 1.81UT FUJI -KISO







0418+236 2026/06/11 1.93UT TOYOKAWA-FUJI







BLK:38,SNR1: 11.146 ,SNR2: 13.159




BLK:38,SNR1: 33.814 ,SNR2: 33.013




0418+236 2026/06/11 1.93UT TOYOKAWA-KISO





F20260611105404




BLK:35,SNR1: 44.657 ,SNR2: 43.588




K20260611105401




BLK:35,SNR1: 28.404 ,SNR2: 35.824




0418+236 2026/06/11 1.93UT FUJI -KISO




T20260611110532




BLK:21,SNR1: 8.5565 ,SNR2: 21.299




F20260611110532




BLK:21,SNR1: 4.8275 ,SNR2: 12.645




3C119 2026/06/11 2.12UT TOYOKAWA-FUJI




T20260611110532




BLK:19,SNR1: 7.8438 ,SNR2: 19.492




K20260611110529




BLK:19,SNR1: 31.270 ,SNR2: 54.434




3C119 2026/06/11 2.12UT TOYOKAWA-KISO



F20260611110532





BLK:19,SNR1: 5.2794 ,SNR2: 13.766









3C119 2026/06/11 2.12UT FUJI -KISO

K20260611110529





BLK:19,SNR1: 34.169 ,SNR2: 83.809







3C138 2026/06/11 2.92UT TOYOKAWA-FUJI







BLK:17,SNR1: 12.887 ,SNR2: 13.561




BLK:17,SNR1: 6.8910 ,SNR2: 18.847




3C138 2026/06/11 2.92UT TOYOKAWA-KISO



F20260611115338




BLK:18,SNR1: 7.0132 ,SNR2: 19.971





3C138 2026/06/11 2.92UT FUJI -KISO


K20260611115335




BLK:18,SNR1: 7.3912 ,SNR2: 19.407




T20260611120712




BLK:11,SNR1: 10.530 ,SNR2: 14.253




F20260611120712




BLK:11,SNR1: 6.4119 ,SNR2: 13.814




0531+194 2026/06/11 3.15UT TOYOKAWA-FUJI




T20260611120712




BLK:12,SNR1: 15.129 ,SNR2: 21.469




K20260611120709




BLK:12,SNR1: 1.2737 ,SNR2: 5.7696




0531+194 2026/06/11 3.15UT TOYOKAWA-KISO




F20260611120712




BLK: 9,SNR1: 2.4552 ,SNR2: 5.9168




K20260611120709




BLK: 9,SNR1: 1.2086 ,SNR2: 5.5512




0531+194 2026/06/11 3.15UT FUJI -KISO



T20260611121533




BLK:17,SNR1: 12.123 ,SNR2: 20.956





3C147 2026/06/11 3.29UT TOYOKAWA-FUJI


F20260611121533




BLK:17,SNR1: 10.374 ,SNR2: 18.743




T20260611121533




BLK:28,SNR1: 14.736 ,SNR2: 25.501




K20260611121530




BLK:28,SNR1: 6.9287 ,SNR2: 17.028




3C147 2026/06/11 3.29UT TOYOKAWA-KISO



F20260611121533




BLK: 5,SNR1: 8.1987 ,SNR2: 14.513





3C147 2026/06/11 3.29UT FUJI -KISO



K20260611121530




BLK: 5,SNR1: 7.5951 ,SNR2: 13.560





T20260611122343




BLK: 8,SNR1: 3.1577 ,SNR2: 6.3605




F20260611122343




BLK: 8,SNR1: 0.92301 ,SNR2: 7.8128




0548+16 2026/06/11 3.42UT TOYOKAWA-FUJI





T20260611122343




BLK:13,SNR1: 3.2180 ,SNR2: 6.5510




K20260611122340





BLK:13,SNR1: 1.6464 ,SNR2: 6.7481




0548+16 2026/06/11 3.42UT TOYOKAWA-KISO




F20260611122343




BLK:10,SNR1:-0.67190E-02,SNR2: 0.81832




K20260611122340





BLK:10,SNR1: 2.9187 ,SNR2: 7.5717




0548+16 2026/06/11 3.42UT FUJI -KISO



T20260611122753




BLK: 8,SNR1: 15.565 ,SNR2: 37.567





0552+12 2026/06/11 3.49UT TOYOKAWA-FUJI



F20260611122753




BLK: 8,SNR1: 7.6198 ,SNR2: 18.589




T20260611122753




BLK:11,SNR1: 14.422 ,SNR2: 25.365




K20260611122750




BLK:11,SNR1: 7.6579 ,SNR2: 18.739




0552+12 2026/06/11 3.49UT TOYOKAWA-KISO



F20260611122753




BLK: 4,SNR1: 1.6738 ,SNR2: 8.4076





0552+12 2026/06/11 3.49UT FUJI -KISO



K20260611122750




BLK: 4,SNR1: 10.169 ,SNR2: 25.132





T20260611123220




BLK:15,SNR1: 0.49610 ,SNR2: 1.6767




F20260611123220





BLK:15,SNR1: 4.1016 ,SNR2: 8.9533




0556+191 2026/06/11 3.57UT TOYOKAWA-FUJI




T20260611123220




BLK: 9,SNR1: 0.47286 ,SNR2: 1.9946




K20260611123217




BLK: 9,SNR1: 1.1716 ,SNR2: 4.3885




0556+191 2026/06/11 3.57UT TOYOKAWA-KISO





F20260611123220




BLK: 1,SNR1:-0.12929 ,SNR2: 1.1373




K20260611123217





BLK: 1,SNR1: 0.99506 ,SNR2: 10.771




0556+191 2026/06/11 3.57UT FUJI -KISO



T20260611124005




BLK: 1,SNR1: 17.990 ,SNR2: 32.089





0605-08 2026/06/11 3.70UT TOYOKAWA-FUJI



F20260611124005




BLK: 1,SNR1: 8.1068 ,SNR2: 20.146




T20260611124005




BLK: 2,SNR1: 9.3873 ,SNR2: 24.565




K20260611124002




BLK: 2,SNR1: 8.3170 ,SNR2: 20.832




0605-08 2026/06/11 3.70UT TOYOKAWA-KISO




F20260611124005




BLK: 4,SNR1: 7.9660 ,SNR2: 19.696




K20260611124002





BLK: 4,SNR1: 7.6433 ,SNR2: 19.514




0605-08 2026/06/11 3.70UT FUJI -KISO




T20260611125913




BLK: 8,SNR1: 1.6674 ,SNR2: 6.5364




F20260611125913





BLK: 8,SNR1: 0.13395 ,SNR2: 1.3524




3C161 2026/06/11 4.02UT TOYOKAWA-FUJI




T20260611125913




BLK: 8,SNR1: 1.6556 ,SNR2: 5.6373




K20260611125910




BLK: 8,SNR1: 4.1928 ,SNR2: 10.850




3C161 2026/06/11 4.02UT TOYOKAWA-KISO



F20260611125913





BLK: 4,SNR1:-0.18378 ,SNR2: 1.6533





3C161 2026/06/11 4.02UT FUJI -KISO



K20260611125910




BLK: 4,SNR1: 4.6600 ,SNR2: 12.177





T20260611132646




No.Good Data




F20260611132646





No.Good Data




0652-130 2026/06/11 4.47UT TOYOKAWA-FUJI





T20260611132646




No.Good Data




K20260611132643




No.Good Data




0652-130 2026/06/11 4.47UT TOYOKAWA-KISO




F20260611132646




BLK: 1,SNR1: 10.975 ,SNR2: 27.200




K20260611132643





BLK: 1,SNR1: 21.729 ,SNR2: 52.599




0652-130 2026/06/11 4.47UT FUJI -KISO





T20260611133823




BLK: 5,SNR1: 7.8001 ,SNR2: 13.984




F20260611133824




BLK: 5,SNR1: 7.4401 ,SNR2: 18.047




0703+138 2026/06/11 4.67UT TOYOKAWA-FUJI



T20260611133823





BLK: 7,SNR1: 5.5519 ,SNR2: 14.087





0703+138 2026/06/11 4.67UT TOYOKAWA-KISO


K20260611133820




BLK: 7,SNR1: 6.5029 ,SNR2: 16.339





F20260611133824




BLK: 9,SNR1: 6.9909 ,SNR2: 18.494




K20260611133820




BLK: 9,SNR1: 6.7354 ,SNR2: 16.631




0703+138 2026/06/11 4.67UT FUJI -KISO





T20260611134745




BLK: 6,SNR1: 6.7452 ,SNR2: 16.936




F20260611134745




BLK: 6,SNR1: 6.7830 ,SNR2: 17.035




0713-024 2026/06/11 4.82UT TOYOKAWA-FUJI




T20260611134745




BLK: 7,SNR1: 6.3488 ,SNR2: 16.072




K20260611134742





BLK: 7,SNR1: 8.9897 ,SNR2: 21.787




0713-024 2026/06/11 4.82UT TOYOKAWA-KISO




F20260611134745




BLK: 3,SNR1: 8.0456 ,SNR2: 28.321




K20260611134742





BLK: 3,SNR1: 10.069 ,SNR2: 24.923




0713-024 2026/06/11 4.82UT FUJI -KISO





T20260611135757




BLK: 2,SNR1: 4.4026 ,SNR2: 16.453




F20260611135757




BLK: 2,SNR1: 10.961 ,SNR2: 26.961




0723+10 2026/06/11 4.99UT TOYOKAWA-FUJI




T20260611135757




BLK: 2,SNR1: 4.4765 ,SNR2: 16.659




K20260611135754




BLK: 2,SNR1: 14.488 ,SNR2: 25.731




0723+10 2026/06/11 4.99UT TOYOKAWA-KISO




F20260611135757




BLK: 2,SNR1: 10.123 ,SNR2: 24.865




K20260611135754





BLK: 2,SNR1: 3.0170 ,SNR2: 13.307




0723+10 2026/06/11 4.99UT FUJI -KISO





T20260611140813




BLK: 5,SNR1: 14.534 ,SNR2: 34.140




F20260611140813





BLK: 5,SNR1: 14.518 ,SNR2: 23.666




0732+33 2026/06/11 5.17UT TOYOKAWA-FUJI




T20260611140813




BLK: 3,SNR1: 12.225 ,SNR2: 27.934




K20260611140810





BLK: 3,SNR1: 10.289 ,SNR2: 25.927




0732+33 2026/06/11 5.17UT TOYOKAWA-KISO




F20260611140813




BLK: 4,SNR1: 5.7205 ,SNR2: 20.626




K20260611140810





BLK: 4,SNR1: 3.5482 ,SNR2: 15.277




0732+33 2026/06/11 5.17UT FUJI -KISO




T20260611141613




BLK: 4,SNR1: 8.4624 ,SNR2: 25.152




F20260611141613





BLK: 4,SNR1: 8.5887 ,SNR2: 26.688




0741-06 2026/06/11 5.30UT TOYOKAWA-FUJI




T20260611141613




BLK: 1,SNR1: 8.4684 ,SNR2: 19.027




K20260611141610




BLK: 1,SNR1: 9.2946 ,SNR2: 27.319




0741-06 2026/06/11 5.30UT TOYOKAWA-KISO




F20260611141613




BLK: 1,SNR1: 9.3337 ,SNR2: 28.317




K20260611141610





BLK: 1,SNR1: 5.5767 ,SNR2: 16.875




0741-06 2026/06/11 5.30UT FUJI -KISO





T20260611142557




BLK: 6,SNR1: 16.451 ,SNR2: 38.171




F20260611142557





BLK: 6,SNR1: 11.259 ,SNR2: 27.577




0752-200 2026/06/11 5.46UT TOYOKAWA-FUJI





T20260611142557




BLK: 8,SNR1: 7.1915 ,SNR2: 17.901




K20260611142554





BLK: 8,SNR1: 8.0207 ,SNR2: 20.823




0752-200 2026/06/11 5.46UT TOYOKAWA-KISO



F20260611142557





BLK: 3,SNR1: 3.2197 ,SNR2: 12.713




Frequency (Hz)

K20260611142554




BLK: 3,SNR1: 10.368 ,SNR2: 19.299





Frequency (Hz)


0752-200 2026/06/11 5.46UT FUJI -KISO





T20260611143333




BLK: 3,SNR1: 5.7947 ,SNR2: 15.391




F20260611143333





BLK: 3,SNR1: 2.5087 ,SNR2: 11.462




3C190 2026/06/11 5.59UT TOYOKAWA-FUJI




T20260611143333




BLK: 3,SNR1: 22.446 ,SNR2: 40.612




K20260611143330




BLK: 3,SNR1: 7.7038 ,SNR2: 19.085




3C190 2026/06/11 5.59UT TOYOKAWA-KISO




F20260611143333




BLK: 2,SNR1: 15.538 ,SNR2: 38.297




K20260611143330





BLK: 2,SNR1: 2.6993 ,SNR2: 12.767




3C190 2026/06/11 5.59UT FUJI -KISO




T20260611144600




BLK: 4,SNR1: 22.173 ,SNR2: 40.436




F20260611144600





BLK: 4,SNR1: 9.2722 ,SNR2: 22.608




3C196 2026/06/11 5.79UT TOYOKAWA-FUJI



T20260611144600




BLK: 2,SNR1: 13.113 ,SNR2: 31.972




Frequency (Hz)

K20260611144557




BLK: 2,SNR1: 8.0299 ,SNR2: 20.138




Frequency (Hz)


3C196 2026/06/11 5.79UT TOYOKAWA-KISO



F20260611144600




BLK: 1,SNR1: 2.6649 ,SNR2: 12.019




Frequency (Hz)

3C196 2026/06/11 5.79UT FUJI -KISO


K20260611144557





BLK: 1,SNR1: 2.3462 ,SNR2: 11.217




Frequency (Hz)




T20260611145709




BLK: 1,SNR1: 27.044 ,SNR2: 24.096




F20260611145709





BLK: 1,SNR1: 3.1674 ,SNR2: 9.5479




0821+394 2026/06/11 5.98UT TOYOKAWA-FUJI





T20260611145709




BLK: 3,SNR1: 27.125 ,SNR2: 24.160




K20260611145706




BLK: 3,SNR1: 11.709 ,SNR2: 19.092




0821+394 2026/06/11 5.98UT TOYOKAWA-KISO





F20260611145709




BLK: 3,SNR1: 3.9859 ,SNR2: 11.786




K20260611145706





BLK: 3,SNR1: 3.0143 ,SNR2: 9.1927




0821+394 2026/06/11 5.98UT FUJI -KISO



T20260611150846





BLK: 1,SNR1: 7.4211 ,SNR2: 23.957




Frequency (Hz)

F20260611150846




BLK: 1,SNR1: 8.9344 ,SNR2: 22.150





Frequency (Hz)


0834-19 2026/06/11 6.17UT TOYOKAWA-FUJI



T20260611150846





BLK: 2,SNR1: 7.4288 ,SNR2: 23.974




Frequency (Hz)

K20260611150843




BLK: 2,SNR1: 9.4297 ,SNR2: 16.592





Frequency (Hz)


0834-19 2026/06/11 6.17UT TOYOKAWA-KISO



F20260611150846





BLK: 3,SNR1: 8.6752 ,SNR2: 21.531




Frequency (Hz)

K20260611150843




BLK: 3,SNR1: 19.632 ,SNR2: 30.855





Frequency (Hz)


0834-19 2026/06/11 6.17UT FUJI -KISO




T20260611151352




BLK:13,SNR1: 10.580 ,SNR2: 25.848




F20260611151352





BLK:13,SNR1: 6.0668 ,SNR2: 18.094




0839-071 2026/06/11 6.26UT TOYOKAWA-FUJI




T20260611151352




BLK: 6,SNR1: 23.033 ,SNR2: 41.976




K20260611151349




BLK: 6,SNR1: 8.8538 ,SNR2: 22.138





0839-071 2026/06/11 6.26UT TOYOKAWA-KISO







BLK: 8,SNR1: 4.3537 ,SNR2: 10.888




BLK: 8,SNR1: 6.1139 ,SNR2: 15.660




0839-071 2026/06/11 6.26UT FUJI -KISO



T20260611152454




BLK: 3,SNR1: 9.7609 ,SNR2: 16.651




Frequency (Hz)

F20260611152454




BLK: 3,SNR1: 3.9665 ,SNR2: 12.304




Frequency (Hz)


3C208 2026/06/11 6.44UT TOYOKAWA-FUJI



T20260611152454




BLK: 1,SNR1: 4.1987 ,SNR2: 12.847




Frequency (Hz)

K20260611152452




BLK: 1,SNR1: 0.63411 ,SNR2: 3.5416




Frequency (Hz)


3C208 2026/06/11 6.44UT TOYOKAWA-KISO




F20260611152454




BLK: 2,SNR1: 7.6591 ,SNR2: 13.739




K20260611152452





BLK: 2,SNR1: 2.8058 ,SNR2: 10.829




3C208 2026/06/11 6.44UT FUJI -KISO



T20260611154136





No.Good Data




Frequency (Hz)

F20260611154136




No.Good Data




Frequency (Hz)


3C216 2026/06/11 6.72UT TOYOKAWA-FUJI




T20260611154136




BLK: 2,SNR1: 0.78953 ,SNR2: 2.6768




K20260611154133





BLK: 2,SNR1: 4.7704 ,SNR2: 9.0265




3C216 2026/06/11 6.72UT TOYOKAWA-KISO





F20260611154136




No.Good Data




K20260611154133




No.Good Data




3C216 2026/06/11 6.72UT FUJI -KISO





T20260611155346




BLK: 4,SNR1: 0.64533 ,SNR2: 4.2312




F20260611155346





BLK: 4,SNR1: 4.3218 ,SNR2: 13.326




0919-142 2026/06/11 6.92UT TOYOKAWA-FUJI



T20260611155346




BLK: 3,SNR1: 0.43939 ,SNR2: 5.1460




Frequency (Hz)

K20260611155343




BLK: 3,SNR1: 5.4051 ,SNR2: 19.509




Frequency (Hz)


0919-142 2026/06/11 6.92UT TOYOKAWA-KISO



F20260611155346




BLK: 1,SNR1: 12.321 ,SNR2: 25.240




Frequency (Hz)

K20260611155343




BLK: 1,SNR1: 9.3525 ,SNR2: 15.878





Frequency (Hz)


0919-142 2026/06/11 6.92UT FUJI -KISO



T20260611160025




BLK: 4,SNR1: 1.8611 ,SNR2: 7.8541




Frequency (Hz)

F20260611160025




BLK: 4,SNR1: 0.85739E-01,SNR2: 0.79671





Frequency (Hz)


0926+117 2026/06/11 7.04UT TOYOKAWA-FUJI



T20260611160025




BLK: 5,SNR1: 2.4920 ,SNR2: 5.4345




Frequency (Hz)

K20260611160022




BLK: 5,SNR1: 2.6668 ,SNR2: 5.1766




Frequency (Hz)


0926+117 2026/06/11 7.04UT TOYOKAWA-KISO



F20260611160025




BLK: 3,SNR1: 0.42319 ,SNR2: 1.6455




Frequency (Hz)

K20260611160022




BLK: 3,SNR1: 0.77920 ,SNR2: 3.3142





Frequency (Hz)


0926+117 2026/06/11 7.04UT FUJI -KISO



T20260611160810




BLK: 1,SNR1: 0.12208 ,SNR2: 0.88168




Frequency (Hz)

F20260611160810




BLK: 1,SNR1:-0.19919 ,SNR2: 0.80092





Frequency (Hz)


3C222 2026/06/11 7.16UT TOYOKAWA-FUJI





T20260611160810




BLK: 6,SNR1: 0.15574 ,SNR2: 0.83758




K20260611160807




BLK: 6,SNR1: 0.41663 ,SNR2: 1.7186




3C222 2026/06/11 7.16UT TOYOKAWA-KISO



F20260611160810





BLK: 3,SNR1:-0.17057 ,SNR2: 0.0000




Frequency (Hz)

K20260611160807




BLK: 3,SNR1: 0.13227 ,SNR2: 6.2611




Frequency (Hz)


3C222 2026/06/11 7.16UT FUJI -KISO



T20260611161510




BLK: 1,SNR1: 0.49382 ,SNR2: 6.0249




Frequency (Hz)

F20260611161510




BLK: 1,SNR1: 3.6208 ,SNR2: 9.4938




Frequency (Hz)


0941-08 2026/06/11 7.28UT TOYOKAWA-FUJI



T20260611161510




BLK: 2,SNR1: 9.2439 ,SNR2: 23.444




Frequency (Hz)

K20260611161508




BLK: 2,SNR1: 15.945 ,SNR2: 24.696




Frequency (Hz)


0941-08 2026/06/11 7.28UT TOYOKAWA-KISO



F20260611161510




BLK: 2,SNR1: 1.7878 ,SNR2: 6.3039




Frequency (Hz)

K20260611161508




BLK: 2,SNR1: 11.334 ,SNR2: 20.330





Frequency (Hz)


0941-08 2026/06/11 7.28UT FUJI -KISO



T20260611162332





BLK: 2,SNR1: 0.53796 ,SNR2: 1.4373




Frequency (Hz)

F20260611162332




BLK: 2,SNR1: 9.1800 ,SNR2: 16.178





Frequency (Hz)


3C230 2026/06/11 7.42UT TOYOKAWA-FUJI



T20260611162332




BLK: 3,SNR1:-0.19472E-01,SNR2: 2.4061




Frequency (Hz)

K20260611162329




BLK: 3,SNR1: 12.855 ,SNR2: 22.886




Frequency (Hz)


3C230 2026/06/11 7.42UT TOYOKAWA-KISO



F20260611162332




BLK: 5,SNR1: 9.9043 ,SNR2: 17.421




Frequency (Hz)

K20260611162329




BLK: 5,SNR1: 11.398 ,SNR2: 20.145




Frequency (Hz)


3C230 2026/06/11 7.42UT FUJI -KISO



T20260611163932





BLK: 1,SNR1: 1.4806 ,SNR2: 4.1237




Frequency (Hz)

F20260611163932




BLK: 1,SNR1: 3.6728 ,SNR2: 8.2926




Frequency (Hz)


3C237 2026/06/11 7.69UT TOYOKAWA-FUJI



T20260611163932





No.Good Data




Frequency (Hz)

K20260611163930




No.Good Data





Frequency (Hz)


3C237 2026/06/11 7.69UT TOYOKAWA-KISO



F20260611163932





No.Good Data




Frequency (Hz)

K20260611163930




No.Good Data




Frequency (Hz)


3C237 2026/06/11 7.69UT FUJI -KISO



T20260611164549




BLK: 1,SNR1: 2.0113 ,SNR2: 4.8030




Frequency (Hz)

F20260611164549




BLK: 1,SNR1: 19.489 ,SNR2: 38.567




Frequency (Hz)


1011+110 2026/06/11 7.79UT TOYOKAWA-FUJI



T20260611164549




BLK: 3,SNR1: 6.5455 ,SNR2: 14.309




Frequency (Hz)

K20260611164547




BLK: 3,SNR1: 13.997 ,SNR2: 29.166




Frequency (Hz)


1011+110 2026/06/11 7.79UT TOYOKAWA-KISO



F20260611164549





BLK: 2,SNR1: 15.691 ,SNR2: 31.084




Frequency (Hz)

K20260611164547




BLK: 2,SNR1: 7.2039 ,SNR2: 18.562





Frequency (Hz)


1011+110 2026/06/11 7.79UT FUJI -KISO



T20260611165330





BLK: 3,SNR1: 7.9080 ,SNR2: 19.680




Frequency (Hz)

F20260611165330




BLK: 3,SNR1: 9.9249 ,SNR2: 24.224





Frequency (Hz)


3C241 2026/06/11 7.92UT TOYOKAWA-FUJI



T20260611165330




BLK: 3,SNR1: 3.4318 ,SNR2: 8.7608




Frequency (Hz)

K20260611165327




BLK: 3,SNR1: 10.825 ,SNR2: 26.410





Frequency (Hz)


3C241 2026/06/11 7.92UT TOYOKAWA-KISO



F20260611165330




BLK: 3,SNR1: 15.931 ,SNR2: 28.576




Frequency (Hz)

K20260611165327




BLK: 3,SNR1: 5.6738 ,SNR2: 13.978




Frequency (Hz)


3C241 2026/06/11 7.92UT FUJI -KISO



T20260611172944




BLK: 4,SNR1: 0.62083 ,SNR2: 2.2296




Frequency (Hz)

F20260611172944




BLK: 4,SNR1: 8.0701 ,SNR2: 17.589




Frequency (Hz)


1055+20 2026/06/11 8.52UT TOYOKAWA-FUJI



T20260611172944




BLK: 7,SNR1: 0.24289 ,SNR2: 1.0455




Frequency (Hz)

K20260611172941




BLK: 7,SNR1: 6.1130 ,SNR2: 15.030




Frequency (Hz)


1055+20 2026/06/11 8.52UT TOYOKAWA-KISO



F20260611172944




BLK: 3,SNR1: 16.096 ,SNR2: 29.660




Frequency (Hz)

K20260611172941



BLK: 3,SNR1: 6.9739 ,SNR2: 17.463



Frequency (Hz)

1055+20 2026/06/11 8.52UT FUJI -KISO

