




T20260615051914





BLK: 7,SNR1: 7.5864 ,SNR2: 18.890




Frequency (Hz)

F20260615051914




BLK: 7,SNR1: 6.1403 ,SNR2: 15.585




Frequency (Hz)


2259+481 2026/06/14 20.35UT TOYOKAWA-FUJI




T20260615051914




BLK: 8,SNR1: 12.723 ,SNR2: 30.827




K20260615051911





BLK: 8,SNR1: 8.3892 ,SNR2: 20.538




2259+481 2026/06/14 20.35UT TOYOKAWA-KISO



F20260615051914





BLK: 6,SNR1: 9.2506 ,SNR2: 16.560




Frequency (Hz)

K20260615051911




BLK: 6,SNR1: 7.3090 ,SNR2: 18.011





Frequency (Hz)


2259+481 2026/06/14 20.35UT FUJI -KISO





T20260615053517




No.Good Data




F20260615053517





No.Good Data




2315+396 2026/06/14 20.62UT TOYOKAWA-FUJI





T20260615053517




No.Good Data




K20260615053515





No.Good Data




2315+396 2026/06/14 20.62UT TOYOKAWA-KISO



F20260615053517





BLK: 1,SNR1: 3.9198 ,SNR2: 8.9443




Frequency (Hz)

K20260615053515




BLK: 1,SNR1: 0.60960E-01,SNR2: 2.7424





Frequency (Hz)


2315+396 2026/06/14 20.62UT FUJI -KISO



T20260615055555





BLK: 3,SNR1: 6.7723 ,SNR2: 18.473




Frequency (Hz)

F20260615055555




BLK: 3,SNR1: 11.983 ,SNR2: 29.349





Frequency (Hz)


2335+267 2026/06/14 20.96UT TOYOKAWA-FUJI



T20260615055555





BLK: 2,SNR1: 3.9010 ,SNR2: 15.056




Frequency (Hz)

K20260615055552




BLK: 2,SNR1: 10.162 ,SNR2: 24.809





Frequency (Hz)


2335+267 2026/06/14 20.96UT TOYOKAWA-KISO



F20260615055555





BLK: 2,SNR1: 5.8993 ,SNR2: 17.067




Frequency (Hz)

K20260615055552




BLK: 2,SNR1: 11.661 ,SNR2: 29.318





Frequency (Hz)


2335+267 2026/06/14 20.96UT FUJI -KISO



T20260615061446





BLK: 7,SNR1: 18.891 ,SNR2: 33.957




Frequency (Hz)

F20260615061446




BLK: 7,SNR1: 10.005 ,SNR2: 25.893





Frequency (Hz)


2354+14 2026/06/14 21.27UT TOYOKAWA-FUJI



T20260615061446





BLK: 1,SNR1: 11.665 ,SNR2: 28.927




Frequency (Hz)

2354+14 2026/06/14 21.27UT TOYOKAWA-KISO


K20260615061444





BLK: 1,SNR1: 16.147 ,SNR2: 29.069




Frequency (Hz)



F20260615061446




BLK: 2,SNR1: 13.810 ,SNR2: 33.708





2354+14 2026/06/14 21.27UT FUJI -KISO



K20260615061444




BLK: 2,SNR1: 13.473 ,SNR2: 32.902



T20260615063111





BLK: 3,SNR1: 10.007 ,SNR2: 24.584




Frequency (Hz)

F20260615063111




BLK: 3,SNR1: 8.0819 ,SNR2: 23.031





Frequency (Hz)


0011+344 2026/06/14 21.55UT TOYOKAWA-FUJI



T20260615063111




BLK: 3,SNR1: 9.7799 ,SNR2: 24.315




Frequency (Hz)

K20260615063108




BLK: 3,SNR1: 9.1924 ,SNR2: 26.295





Frequency (Hz)


0011+344 2026/06/14 21.55UT TOYOKAWA-KISO



F20260615063111





BLK: 2,SNR1: 8.4419 ,SNR2: 22.654




Frequency (Hz)

K20260615063108




BLK: 2,SNR1: 9.9970 ,SNR2: 26.057





Frequency (Hz)


0011+344 2026/06/14 21.55UT FUJI -KISO



T20260615063947




BLK: 1,SNR1: 10.552 ,SNR2: 25.985




Frequency (Hz)

F20260615063947




BLK: 1,SNR1: 13.407 ,SNR2: 31.691





Frequency (Hz)


0019-00 2026/06/14 21.69UT TOYOKAWA-FUJI



T20260615063947





BLK: 1, SNR1: 10.971 ,SNR2: 26.825





0019-00 2026/06/14 21.69UT TOYOKAWA-KISO



K20260615063944




BLK: 1, SNR1: 10.855 ,SNR2: 26.965



F20260615063947





BLK: 3,SNR1: 36.429 ,SNR2: 63.836




Frequency (Hz)

K20260615063944




BLK: 3,SNR1: 18.538 ,SNR2: 33.912





Frequency (Hz)


0019-00 2026/06/14 21.69UT FUJI -KISO





T20260615065002




No.Good Data




F20260615065002





No.Good Data




3C12 2026/06/14 21.86UT TOYOKAWA-FUJI





T20260615065002




BLK: 1,SNR1: 1.4968 ,SNR2: 4.2852




K20260615064959




BLK: 1,SNR1: 27.686 ,SNR2: 49.772




3C12 2026/06/14 21.86UT TOYOKAWA-KISO



F20260615065002




BLK: 3,SNR1: 9.0357 ,SNR2: 21.230




Frequency (Hz)

3C12 2026/06/14 21.86UT FUJI -KISO


K20260615064959





BLK: 3,SNR1: 8.4781 ,SNR2: 20.981




Frequency (Hz)



T20260615065820





BLK: 2,SNR1: 5.9496 ,SNR2: 14.762




Frequency (Hz)

F20260615065820




BLK: 2,SNR1: 8.4946 ,SNR2: 20.790





Frequency (Hz)


0038+328 2026/06/14 22.00UT TOYOKAWA-FUJI



T20260615065820





BLK: 3,SNR1: 4.7310 ,SNR2: 11.790




Frequency (Hz)

K20260615065817




BLK: 3,SNR1: 4.5559 ,SNR2: 11.509




Frequency (Hz)


0038+328 2026/06/14 22.00UT TOYOKAWA-KISO



F20260615065820




BLK: 5,SNR1: 7.4026 ,SNR2: 18.375





0038+328 2026/06/14 22.00UT FUJI -KISO



K20260615065817




BLK: 5,SNR1: 6.5380 ,SNR2: 16.003



T20260615071125





BLK: 8,SNR1: 27.654 ,SNR2: 24.578




Frequency (Hz)

3C26 2026/06/14 22.22UT TOYOKAWA-FUJI


F20260615071125





BLK: 8,SNR1: 3.1724 ,SNR2: 9.6627




Frequency (Hz)



T20260615071125





BLK:10,SNR1: 26.868 ,SNR2: 23.875




Frequency (Hz)

3C26 2026/06/14 22.22UT TOYOKAWA-KISO


K20260615071122





BLK:10,SNR1: 2.4178 ,SNR2: 7.9080




Frequency (Hz)



F20260615071125





BLK:10,SNR1: 3.7056 ,SNR2: 11.123




Frequency (Hz)

3C26 2026/06/14 22.22UT FUJI -KISO


K20260615071122





BLK:10,SNR1: 2.5523 ,SNR2: 8.2522




Frequency (Hz)



T20260615071623




BLK: 9,SNR1: 2.9444 ,SNR2: 14.238




Frequency (Hz)

0056-00 2026/06/14 22.30UT TOYOKAWA-FUJI


F20260615071623





BLK: 9,SNR1: 0.39091 ,SNR2: 3.7199




Frequency (Hz)



T20260615071623




BLK:15,SNR1: 2.7500 ,SNR2: 13.084




Frequency (Hz)

0056-00 2026/06/14 22.30UT TOYOKAWA-KISO


K20260615071620





BLK:15,SNR1: 1.1951 ,SNR2: 4.0544




Frequency (Hz)



F20260615071623





BLK:11,SNR1: 0.79099 ,SNR2: 2.6407




Frequency (Hz)

K20260615071620




BLK:11,SNR1: 1.6544 ,SNR2: 5.2971





Frequency (Hz)


0056-00 2026/06/14 22.30UT FUJI -KISO



T20260615072606





BLK: 1,SNR1: 0.37186 ,SNR2: 1.0664




Frequency (Hz)

F20260615072606




BLK: 1,SNR1: 0.27284 ,SNR2: 4.5493





Frequency (Hz)


0106+01 2026/06/14 22.46UT TOYOKAWA-FUJI



T20260615072606





BLK: 6,SNR1: 0.38976 ,SNR2: 2.0446




Frequency (Hz)

K20260615072604




BLK: 6,SNR1: 0.89630 ,SNR2: 3.5981




Frequency (Hz)


0106+01 2026/06/14 22.48UT TOYOKAWA-KISO



F20260615072606




BLK: 2,SNR1:-0.10570 ,SNR2: 1.0569




Frequency (Hz)

K20260615072604




BLK: 2,SNR1: 4.3453 ,SNR2: 10.824





Frequency (Hz)


0106+01 2026/06/14 22.46UT FUJI -KISO



T20260615073528





BLK: 2,SNR1: 1.3635 ,SNR2: 5.7480




Frequency (Hz)

F20260615073528




BLK: 2,SNR1: 3.7861 ,SNR2: 8.7411





Frequency (Hz)


0115-01 2026/06/14 22.62UT TOYOKAWA-FUJI



T20260615073528





BLK: 4,SNR1: 0.90847 ,SNR2: 3.5844




Frequency (Hz)

0115-01 2026/06/14 22.62UT TOYOKAWA-KISO


K20260615073526




BLK: 4,SNR1: 14.876 ,SNR2: 26.672




Frequency (Hz)



F20260615073528




BLK: 4,SNR1: 5.0152 ,SNR2: 15.958





0115-01 2026/06/14 22.62UT FUJI -KISO


K20260615073526




BLK: 4,SNR1: 14.709 ,SNR2: 26.381



T20260615074828




BLK: 6,SNR1: 0.49861 ,SNR2: 1.5695





0128+03 2026/06/14 22.84UT TOYOKAWA-FUJI


F20260615074828




BLK: 6,SNR1: 0.18932 ,SNR2: 1.8752



T20260615074828




BLK: 9,SNR1: 6.6844 ,SNR2: 18.976





0128+03 2026/06/14 22.84UT TOYOKAWA-KISO



K20260615074825




BLK: 9,SNR1: 2.6298 ,SNR2: 10.092





F20260615074828




BLK: 2,SNR1: 0.36981 ,SNR2: 2.4516




K20260615074825




BLK: 2,SNR1: 4.2850 ,SNR2: 10.917




0128+03 2026/06/14 22.84UT FUJI -KISO



T20260615075502




BLK: 8,SNR1: 6.1872 ,SNR2: 14.772





3C48 2026/06/14 22.95UT TOYOKAWA-FUJI


F20260615075502




BLK: 8,SNR1: 7.2029 ,SNR2: 18.047



T20260615075502




BLK: 7,SNR1: 4.2160 ,SNR2: 10.809





3C48 2026/06/14 22.95UT TOYOKAWA-KISO



K20260615075459




BLK: 7,SNR1: 2.8139 ,SNR2: 5.9101



F20260615075502





BLK: 5,SNR1: 8.2880 ,SNR2: 21.193




Frequency (Hz)

3C48 2026/06/14 22.95UT FUJI -KISO


K20260615075459





BLK: 5,SNR1: 2.5408 ,SNR2: 5.0518




Frequency (Hz)



T20260615081446




BLK: 7,SNR1: 2.3727 ,SNR2: 5.9416





0155-109 2026/06/14 23.27UT TOYOKAWA-FUJI



F20260615081446




BLK: 7,SNR1: 0.36237 ,SNR2: 1.8142



T20260615081446





BLK: 7,SNR1: 0.71671 ,SNR2: 4.6889





0155-109 2026/06/14 23.27UT TOYOKAWA-KISO



K20260615081444




BLK: 7,SNR1: 2.1592 ,SNR2: 6.3966



F20260615081446





BLK: 7,SNR1: 0.32957 ,SNR2: 2.3729




Frequency (Hz)

K20260615081444




BLK: 7,SNR1: 8.1710 ,SNR2: 22.507





Frequency (Hz)


0155-109 2026/06/14 23.27UT FUJI -KISO



T20260615082154





BLK: 7,SNR1: 0.24031 ,SNR2: 0.79290




Frequency (Hz)

F20260615082154




BLK: 7,SNR1: 6.7438 ,SNR2: 16.768





Frequency (Hz)


0202+15 2026/06/14 23.39UT TOYOKAWA-FUJI



T20260615082154





BLK:11,SNR1: 0.26793E-01,SNR2: 1.3872





0202+15 2026/06/14 23.39UT TOYOKAWA-KISO


K20260615082151




BLK:11,SNR1: 2.4607 ,SNR2: 4.9017



F20260615082154





BLK: 5,SNR1: 7.8460 ,SNR2: 19.433




Frequency (Hz)

K20260615082151




BLK: 5,SNR1: 1.3218 ,SNR2: 5.1341




Frequency (Hz)


0202+15 2026/06/14 23.39UT FUJI -KISO



T20260615083344




BLK: 7, SNR1: 1.7220 , SNR2: 5.1656




Frequency (Hz)

F20260615083344




BLK: 7, SNR1: 3.1045 , SNR2: 9.3205




Frequency (Hz)


0213+178 2026/06/14 23.59UT TOYOKAWA-FUJI



T20260615083344





BLK:12,SNR1: 3.5668 ,SNR2: 10.625





0213+178 2026/06/14 23.59UT TOYOKAWA-KISO


K20260615083341




BLK:12,SNR1: 8.4267 ,SNR2: 19.927



F20260615083344





BLK: 5,SNR1: 3.4220 ,SNR2: 10.202




Frequency (Hz)

K20260615083341




BLK: 5,SNR1: 8.4380 ,SNR2: 19.953




Frequency (Hz)


0213+178 2026/06/14 23.59UT FUJI -KISO



T20260615084127




BLK:10,SNR1: 4.7958 ,SNR2: 20.627




Frequency (Hz)

3C67 2026/06/14 23.72UT TOYOKAWA-FUJI


F20260615084127




BLK:10,SNR1: 3.1123 ,SNR2: 7.4327




Frequency (Hz)



T20260615084127





BLK:10,SNR1: 2.1117 ,SNR2: 6.6218





3C67 2026/06/14 23.72UT TOYOKAWA-KISO


K20260615084124




BLK:10,SNR1: 1.9139 ,SNR2: 7.4650



F20260615084127





BLK: 5,SNR1: 4.7506 ,SNR2: 10.083





3C67 2026/06/14 23.72UT FUJI -KISO



K20260615084124




BLK: 5,SNR1: 0.78549 ,SNR2: 3.6960



T20260615091857




BLK: 5,SNR1: 0.15134 ,SNR2: 0.59927





0258+350 2026/06/15 0.34UT TOYOKAWA-FUJI



F20260615091857




BLK: 5,SNR1: 16.270 ,SNR2: 37.363



T20260615091857





BLK: 7, SNR1: 0.12611 , SNR2: 0.28970





0258+350 2026/06/15 0.34UT TOYOKAWA-KISO



K20260615091854




BLK: 7, SNR1: 2.0981 , SNR2: 10.087





F20260615091857




BLK: 5,SNR1: 2.1566 ,SNR2: 6.1042




K20260615091854




BLK: 5,SNR1: 8.0307 ,SNR2: 15.701




0258+350 2026/06/15 0.34UT FUJI -KISO



T20260615092846




BLK:12,SNR1: 21.544 ,SNR2: 49.145





0308+305 2026/06/15 0.51UT TOYOKAWA-FUJI



F20260615092846




BLK:12,SNR1: 6.3037 ,SNR2: 16.235





T20260615092846




BLK: 8,SNR1: 7.0266 ,SNR2: 13.266




K20260615092843




BLK: 8,SNR1: 1.7351 ,SNR2: 7.2066




0308+305 2026/06/15 0.51UT TOYOKAWA-KISO





F20260615092846




BLK: 5,SNR1: 7.9706 ,SNR2: 19.069




K20260615092843





BLK: 5,SNR1: 6.3772 ,SNR2: 19.411




0308+305 2026/06/15 0.51UT FUJI -KISO



T20260615093707





BLK: 9,SNR1: 8.6414 ,SNR2: 22.112





3C84 2026/06/15 0.65UT TOYOKAWA-FUJI



F20260615093707




BLK: 9,SNR1: 9.5807 ,SNR2: 23.950



T20260615093707




BLK: 7,SNR1: 9.3323 ,SNR2: 23.523





3C84 2026/06/15 0.65UT TOYOKAWA-KISO



K20260615093704




BLK: 7,SNR1: 11.859 ,SNR2: 27.549



F20260615093707




BLK: 5, SNR1: 16.158 ,SNR2: 37.661





3C84 2026/06/15 0.65UT FUJI -KISO



K20260615093704




BLK: 5, SNR1: 18.402 ,SNR2: 43.195



T20260615094422





BLK: 7,SNR1: 104.14 ,SNR2: 211.49





0324+119 2026/06/15 0.77UT TOYOKAWA-FUJI



F20260615094422




BLK: 7,SNR1: 0.31655 ,SNR2: 2.9819



T20260615094422





BLK: 5,SNR1: 120.49 ,SNR2: 263.08





0324+119 2026/06/15 0.77UT TOYOKAWA-KISO



K20260615094419




BLK: 5,SNR1: 0.94751 ,SNR2: 3.9947





F20260615094422




BLK: 1,SNR1: 0.71055 ,SNR2: 4.6997




K20260615094419





BLK: 1,SNR1: 0.50882 ,SNR2: 2.4539




0324+119 2026/06/15 0.77UT FUJI -KISO



T20260615095339





BLK:13,SNR1: 5.0231 ,SNR2: 8.6673





0333+32 2026/06/15 0.92UT TOYOKAWA-FUJI



F20260615095339




BLK:13,SNR1: 2.9185 ,SNR2: 9.2564



T20260615095339




BLK: 4,SNR1: 13.979 ,SNR2: 13.595





0333+32 2026/06/15 0.92UT TOYOKAWA-KISO



K20260615095336




BLK: 4,SNR1: 0.40396 ,SNR2: 3.1685




F20260615095339




BLK: 6,SNR1:-0.50027E-02,SNR2: 1.9162




K20260615095336





BLK: 6,SNR1: 0.39803 ,SNR2: 2.5422




0333+32 2026/06/15 0.92UT FUJI -KISO




T20260615100640




BLK: 5,SNR1: 0.81014 ,SNR2: 2.5487




F20260615100640





BLK: 5,SNR1: 0.38861 ,SNR2: 3.0266




0347+05 2026/06/15 1.14UT TOYOKAWA-FUJI



T20260615100640





BLK: 9,SNR1: 10.611 ,SNR2: 17.989




0347+05 2026/06/15 1.14UT TOYOKAWA-KISO


K20260615100637




BLK: 9,SNR1: 3.9275 ,SNR2: 7.8868




Frequency (Hz)





F20260615100640




BLK: 9,SNR1: 0.12823 ,SNR2: 2.2368




K20260615100637





BLK: 9,SNR1: 1.2170 ,SNR2: 4.3017




0347+05 2026/06/15 1.14UT FUJI -KISO



T20260615102214




BLK: 3,SNR1: 0.40526 ,SNR2: 2.6592





0403-132 2026/06/15 1.40UT TOYOKAWA-FUJI



F20260615102214




BLK: 3,SNR1: 0.16512 ,SNR2: 2.5717



T20260615102214




BLK:10,SNR1: 3.6480 ,SNR2: 5.5068





0403-132 2026/06/15 1.40UT TOYOKAWA-KISO


K20260615102211




BLK:10,SNR1: 3.0216 ,SNR2: 9.1957




F20260615102214




BLK: 7,SNR1: 0.27204 ,SNR2: 3.7603




K20260615102211





BLK: 7,SNR1: 3.1192 ,SNR2: 9.4807




0403-132 2026/06/15 1.40UT FUJI -KISO



T20260615103125




BLK: 6,SNR1: 3.6054 ,SNR2: 6.2833





0411+05 2026/06/15 1.55UT TOYOKAWA-FUJI



F20260615103125




BLK: 6,SNR1: 7.4514 ,SNR2: 19.316



T20260615103125





BLK: 4,SNR1: 8.0764 ,SNR2: 20.223





0411+05 2026/06/15 1.55UT TOYOKAWA-KISO


K20260615103122




BLK: 4,SNR1: 1.6715 ,SNR2: 5.6083





F20260615103125




BLK:10,SNR1: 6.6334 ,SNR2: 11.736




K20260615103122





BLK:10,SNR1: 8.4094 ,SNR2: 21.766




0411+05 2026/06/15 1.55UT FUJI -KISO




T20260615103820




BLK: 9,SNR1: 3.9136 ,SNR2: 12.203




F20260615103821





BLK: 9,SNR1: 12.513 ,SNR2: 30.058




0418+236 2026/06/15 1.67UT TOYOKAWA-FUJI



T20260615103820





BLK:12,SNR1: 3.5868 ,SNR2: 11.250





0418+236 2026/06/15 1.67UT TOYOKAWA-KISO


K20260615103817




BLK:12,SNR1: 8.8105 ,SNR2: 17.082




F20260615103821




BLK:22,SNR1: 9.4873 ,SNR2: 20.793




K20260615103817




BLK:22,SNR1: 6.6207 ,SNR2: 12.876




0418+236 2026/06/15 1.67UT FUJI -KISO




T20260615104948




BLK:15,SNR1: 4.7492 ,SNR2: 34.541




F20260615104948





BLK:15,SNR1: 1.5937 ,SNR2: 5.8249




3C119 2026/06/15 1.86UT TOYOKAWA-FUJI




T20260615104948




BLK:26,SNR1: 4.3569 ,SNR2: 12.224




K20260615104945




BLK:26,SNR1: 4.1943 ,SNR2: 8.3745




3C119 2026/06/15 1.86UT TOYOKAWA-KISO




F20260615104948




BLK: 4,SNR1: 4.3338 ,SNR2: 9.4375




K20260615104945





BLK: 4,SNR1: 8.4308 ,SNR2: 11.312




3C119 2026/06/15 1.86UT FUJI -KISO



T20260615113755





BLK:10,SNR1: 19.441 ,SNR2: 34.733




3C138 2026/06/15 2.66UT TOYOKAWA-FUJI


F20260615113755





BLK:10,SNR1: 15.625 ,SNR2: 28.488




Frequency (Hz)



T20260615113755





BLK: 9,SNR1: 8.3213 ,SNR2: 20.521





3C138 2026/06/15 2.66UT TOYOKAWA-KISO



K20260615113752




BLK: 9,SNR1: 10.371 ,SNR2: 25.455



F20260615113755





BLK: 3,SNR1: 7.8932 ,SNR2: 19.527





3C138 2026/06/15 2.66UT FUJI -KISO



K20260615113752




BLK: 3,SNR1: 11.434 ,SNR2: 27.968



T20260615115128





BLK:10,SNR1: 7.1099 ,SNR2: 17.914





0531+194 2026/06/15 2.89UT TOYOKAWA-FUJI



F20260615115128




BLK:10,SNR1: 8.4326 ,SNR2: 20.793




T20260615115128




BLK: 9,SNR1: 8.0794 ,SNR2: 20.058




K20260615115125




BLK: 9,SNR1: 6.8408 ,SNR2: 16.995




0531+194 2026/06/15 2.89UT TOYOKAWA-KISO




F20260615115128




BLK: 8,SNR1: 6.8808 ,SNR2: 17.210




K20260615115125





BLK: 8,SNR1: 6.6316 ,SNR2: 16.548




0531+194 2026/06/15 2.89UT FUJI -KISO





T20260615115950




BLK:10,SNR1: 36.098 ,SNR2: 35.582




F20260615115950





BLK:10,SNR1: 16.366 ,SNR2: 35.085




3C147 2026/06/15 3.03UT TOYOKAWA-FUJI





T20260615115950




BLK:17,SNR1: 16.653 ,SNR2: 29.581




K20260615115947





BLK:17,SNR1: 11.561 ,SNR2: 28.651




3C147 2026/06/15 3.03UT TOYOKAWA-KISO



F20260615115950





BLK: 8,SNR1: 16.896 ,SNR2: 40.445





3C147 2026/06/15 3.03UT FUJI -KISO


K20260615115947




BLK: 8,SNR1: 44.685 ,SNR2: 62.244




T20260615120759




BLK: 5,SNR1: 6.0262 ,SNR2: 14.728




F20260615120759




BLK: 5,SNR1: 10.218 ,SNR2: 25.119




0548+16 2026/06/15 3.16UT TOYOKAWA-FUJI



T20260615120759




BLK: 5,SNR1: 10.314 ,SNR2: 24.195





0548+16 2026/06/15 3.16UT TOYOKAWA-KISO


K20260615120756




BLK: 5,SNR1: 11.369 ,SNR2: 27.884




F20260615120759




BLK: 5,SNR1: 10.219 ,SNR2: 25.123




K20260615120756




BLK: 5,SNR1: 10.017 ,SNR2: 24.646




0548+16 2026/06/15 3.16UT FUJI -KISO




T20260615121209




BLK: 4,SNR1: 4.6019 ,SNR2: 13.574




F20260615121209




BLK: 4,SNR1: 15.587 ,SNR2: 28.202




0552+12 2026/06/15 3.23UT TOYOKAWA-FUJI




T20260615121209




BLK: 7,SNR1: 14.125 ,SNR2: 29.832




K20260615121206




BLK: 7,SNR1: 10.889 ,SNR2: 18.918




0552+12 2026/06/15 3.23UT TOYOKAWA-KISO



F20260615121209




BLK: 5,SNR1: 3.9633 ,SNR2: 11.118





0552+12 2026/06/15 3.23UT FUJI -KISO



K20260615121206




BLK: 5,SNR1: 8.8752 ,SNR2: 15.605




T20260615121637




BLK: 2,SNR1: 0.37782 ,SNR2: 4.0195




F20260615121637







BLK: 2,SNR1: 18.316 ,SNR2: 33.748




0556+191 2026/06/15 3.31UT TOYOKAWA-FUJI







0556+191 2026/06/15 3.31UT TOYOKAWA-KISO





F20260615121637




BLK: 1,SNR1: 1.3617 ,SNR2: 7.2372




K20260615121634




BLK: 1,SNR1: 8.2836 ,SNR2: 20.903




0556+191 2026/06/15 3.31UT FUJI -KISO




T20260615122421




BLK: 3,SNR1: 12.695 ,SNR2: 23.529




F20260615122421




BLK: 3,SNR1: 17.708 ,SNR2: 34.549




0605-08 2026/06/15 3.43UT TOYOKAWA-FUJI





T20260615122421




BLK: 3,SNR1: 12.996 ,SNR2: 24.076




K20260615122418




BLK: 3,SNR1: 11.600 ,SNR2: 28.347




0605-08 2026/06/15 3.43UT TOYOKAWA-KISO



F20260615122421





BLK: 5,SNR1: 8.9795 ,SNR2: 22.186





0605-08 2026/06/15 3.43UT FUJI -KISO


K20260615122418




BLK: 5,SNR1: 11.630 ,SNR2: 28.446



T20260615124329





BLK: 5,SNR1: 2.3053 ,SNR2: 10.836





3C161 2026/06/15 3.75UT TOYOKAWA-FUJI


F20260615124329




BLK: 5,SNR1: 8.7767 ,SNR2: 21.337




T20260615124329




BLK: 1,SNR1: 8.0408 ,SNR2: 26.691




K20260615124327




BLK: 1,SNR1: 11.386 ,SNR2: 27.877




3C161 2026/06/15 3.75UT TOYOKAWA-KISO




F20260615124329




BLK: 1,SNR1: 1.9785 ,SNR2: 9.5583




K20260615124327




BLK: 1,SNR1: 19.088 ,SNR2: 34.276







3C161 2026/06/15 3.75UT FUJI -KISO




T20260615131102




F20260615131102




T20260615131102




BLK: 3,SNR1: 1.3707 ,SNR2: 6.0131




K20260615131059





BLK: 3,SNR1: 6.9377 ,SNR2: 17.603




0652-130 2026/06/15 4.21UT TOYOKAWA-KISO




F20260615131102




BLK: 5,SNR1: 7.4978 ,SNR2: 21.833




K20260615131059





BLK: 5,SNR1: 6.3190 ,SNR2: 15.909




0652-130 2026/06/15 4.21UT FUJI -KISO



T20260615132239





No.Good Data




Frequency (Hz)

F20260615132239




No.Good Data





Frequency (Hz)


0703+138 2026/06/15 4.41UT TOYOKAWA-FUJI



T20260615132239





BLK: 2,SNR1: 0.19558 ,SNR2: 0.81937




Frequency (Hz)

K20260615132236




BLK: 2,SNR1: 5.4511 ,SNR2: 13.775




Frequency (Hz)


0703+138 2026/06/15 4.41UT TOYOKAWA-KISO





F20260615132239




BLK: 2,SNR1: 2.3134 ,SNR2: 10.415




K20260615132236





BLK: 2,SNR1: 10.219 ,SNR2: 25.138




0703+138 2026/06/15 4.41UT FUJI -KISO




T20260615133201




BLK: 8,SNR1: 4.0415 ,SNR2: 8.7484




F20260615133201





BLK: 8,SNR1: 1.8331 ,SNR2: 9.1050




0713-024 2026/06/15 4.56UT TOYOKAWA-FUJI




T20260615133201




BLK:13,SNR1: 10.249 ,SNR2: 21.699




K20260615133158




BLK:13,SNR1: 8.7859 ,SNR2: 20.618




0713-024 2026/06/15 4.56UT TOYOKAWA-KISO




F20260615133201




BLK:15,SNR1: 7.4502 ,SNR2: 17.705




K20260615133158





BLK:15,SNR1: 8.2678 ,SNR2: 19.639




0713-024 2026/06/15 4.56UT FUJI -KISO




T20260615134214




No.Good Data




F20260615134214





No.Good Data




0723+10 2026/06/15 4.73UT TOYOKAWA-FUJI




T20260615134214




BLK: 2,SNR1: 16.414 ,SNR2: 27.778




K20260615134211




BLK: 2,SNR1: 14.098 ,SNR2: 22.969




0723+10 2026/06/15 4.73UT TOYOKAWA-KISO




F20260615134214




BLK: 1,SNR1: 12.198 ,SNR2: 25.980




K20260615134211





BLK: 1,SNR1: 18.868 ,SNR2: 37.891




0723+10 2026/06/15 4.73UT FUJI -KISO




T20260615135229




BLK: 6,SNR1: 0.34649 ,SNR2: 3.5582




F20260615135229





BLK: 6,SNR1: 25.139 ,SNR2: 44.004




0732+33 2026/06/15 4.90UT TOYOKAWA-FUJI





T20260615135229




BLK: 5,SNR1: 0.48420 ,SNR2: 2.1699




K20260615135226




BLK: 5,SNR1: 2.3432 ,SNR2: 8.7334




0732+33 2026/06/15 4.90UT TOYOKAWA-KISO





F20260615135229




BLK: 3,SNR1: 35.820 ,SNR2: 62.142




K20260615135226





BLK: 3,SNR1: 2.6339 ,SNR2: 8.8440




0732+33 2026/06/15 4.90UT FUJI -KISO




T20260615140030




BLK: 6,SNR1: 4.1436 ,SNR2: 12.146




F20260615140030





BLK: 6,SNR1: 3.2914 ,SNR2: 9.9507




0741-06 2026/06/15 5.04UT TOYOKAWA-FUJI





T20260615140030




BLK: 6,SNR1: 4.1396 ,SNR2: 12.138




K20260615140027




BLK: 6,SNR1: 8.6034 ,SNR2: 18.832




0741-06 2026/06/15 5.04UT TOYOKAWA-KISO





F20260615140030




BLK: 7,SNR1: 3.8865 ,SNR2: 11.383




K20260615140027





BLK: 7,SNR1: 9.3130 ,SNR2: 20.356




0741-06 2026/06/15 5.04UT FUJI -KISO





T20260615141014




BLK:13,SNR1: 10.492 ,SNR2: 24.075




F20260615141014





BLK:13,SNR1: 11.120 ,SNR2: 25.826




0752-200 2026/06/15 5.20UT TOYOKAWA-FUJI





T20260615141014




BLK:11,SNR1: 10.503 ,SNR2: 24.099




K20260615141011





BLK:11,SNR1: 9.2779 ,SNR2: 22.807




0752-200 2026/06/15 5.20UT TOYOKAWA-KISO





F20260615141014




BLK:11,SNR1: 9.3116 ,SNR2: 23.090




K20260615141011





BLK:11,SNR1: 9.4723 ,SNR2: 22.934




0752-200 2026/06/15 5.20UT FUJI -KISO





T20260615141750




BLK: 5,SNR1: 1.2946 ,SNR2: 9.4731




F20260615141750





BLK: 5,SNR1: 8.7819 ,SNR2: 21.656




3C190 2026/06/15 5.33UT TOYOKAWA-FUJI





T20260615141750




BLK:10,SNR1: 0.56145 ,SNR2: 2.8329




K20260615141747





BLK:10,SNR1: 5.0542 ,SNR2: 16.618




3C190 2026/06/15 5.33UT TOYOKAWA-KISO




F20260615141750




BLK: 2,SNR1: 5.3625 ,SNR2: 13.488




K20260615141747





BLK: 2,SNR1: 14.643 ,SNR2: 27.251




3C190 2026/06/15 5.33UT FUJI -KISO





T20260615143016




BLK: 1,SNR1: 10.694 ,SNR2: 23.482




F20260615143017





BLK: 1,SNR1: 13.404 ,SNR2: 22.468




3C196 2026/06/15 5.53UT TOYOKAWA-FUJI





T20260615143016




BLK: 4,SNR1: 9.7035 ,SNR2: 21.487




K20260615143013





BLK: 4,SNR1: 2.7532 ,SNR2: 8.6928




3C196 2026/06/15 5.53UT TOYOKAWA-KISO




F20260615143017




No.Good Data




K20260615143013





No.Good Data




3C196 2026/06/15 5.53UT FUJI -KISO




T20260615144125




BLK: 4,SNR1: 0.13243 ,SNR2: 1.3341




F20260615144125





BLK: 4,SNR1: 3.2781 ,SNR2: 10.486




0821+394 2026/06/15 5.72UT TOYOKAWA-FUJI



T20260615144125





BLK: 1,SNR1: 0.30677 ,SNR2: 2.8803




Frequency (Hz)

K20260615144122




BLK: 1,SNR1: 11.617 ,SNR2: 28.575





Frequency (Hz)


0821+394 2026/06/15 5.72UT TOYOKAWA-KISO





F20260615144125




No.Good Data




K20260615144122





No.Good Data




0821+394 2026/06/15 5.72UT FUJI -KISO





T20260615145303




No.Good Data




F20260615145303





No.Good Data




0834-19 2026/06/15 5.91UT TOYOKAWA-FUJI







0834-19 2026/06/15 5.91UT TOYOKAWA-KISO



F20260615145303





BLK: 2,SNR1: 1.4038 ,SNR2: 4.8907




Frequency (Hz)

K20260615145300




BLK: 2,SNR1: 0.40764 ,SNR2: 2.7357




Frequency (Hz)


0834-19 2026/06/15 5.91UT FUJI -KISO



T20260615145809





BLK: 1,SNR1: 9.8757 ,SNR2: 24.569




Frequency (Hz)

F20260615145809




BLK: 1,SNR1: 8.4600 ,SNR2: 21.193




Frequency (Hz)


0839-071 2026/06/15 6.00UT TOYOKAWA-FUJI




T20260615145809




BLK: 4,SNR1: 8.9337 ,SNR2: 22.042




K20260615145806





BLK: 4,SNR1: 8.9858 ,SNR2: 22.211




0839-071 2026/06/15 6.00UT TOYOKAWA-KISO





F20260615145809




BLK: 1,SNR1: 2.8442 ,SNR2: 13.100




K20260615145806





BLK: 1,SNR1: 9.5562 ,SNR2: 23.517




0839-071 2026/06/15 6.00UT FUJI -KISO



T20260615150910





BLK: 2,SNR1: 11.444 ,SNR2: 28.042




Frequency (Hz)

F20260615150910




BLK: 2,SNR1: 19.155 ,SNR2: 34.043





Frequency (Hz)


3C208 2026/06/15 6.18UT TOYOKAWA-FUJI



T20260615150910




BLK: 2,SNR1: 11.501 ,SNR2: 28.174




Frequency (Hz)

K20260615150907




BLK: 2,SNR1: 9.3457 ,SNR2: 23.310





Frequency (Hz)


3C208 2026/06/15 6.18UT TOYOKAWA-KISO




F20260615150910




BLK: 2,SNR1: 17.907 ,SNR2: 31.599




K20260615150907





BLK: 2,SNR1: 8.8521 ,SNR2: 15.872




3C208 2026/06/15 6.18UT FUJI -KISO





T20260615152553




BLK: 8,SNR1: 0.11890 ,SNR2: 0.58193




F20260615152553





BLK: 8,SNR1: 4.3947 ,SNR2: 9.0448




3C216 2026/06/15 6.46UT TOYOKAWA-FUJI





T20260615152553




BLK: 3,SNR1: 0.10787E-01,SNR2: 0.70461




K20260615152550





BLK: 3,SNR1: 1.0462 ,SNR2: 4.0170




3C216 2026/06/15 6.46UT TOYOKAWA-KISO





F20260615152553




BLK: 7,SNR1: 2.4796 ,SNR2: 9.5760




K20260615152550





BLK: 7,SNR1: 0.62384 ,SNR2: 2.6692




3C216 2026/06/15 6.46UT FUJI -KISO



T20260615153802




BLK: 6,SNR1: 0.88904 ,SNR2: 2.9832




Frequency (Hz)

F20260615153802




BLK: 6,SNR1: 1.5667 ,SNR2: 5.4617





Frequency (Hz)


0919-142 2026/06/15 6.66UT TOYOKAWA-FUJI



T20260615153802




BLK:10,SNR1: 6.0759 ,SNR2: 14.946




Frequency (Hz)

K20260615153759




BLK:10,SNR1: 6.9469 ,SNR2: 12.981




Frequency (Hz)


0919-142 2026/06/15 6.66UT TOYOKAWA-KISO



F20260615153802




BLK: 4,SNR1: 1.4330 ,SNR2: 5.7686




Frequency (Hz)

K20260615153759




BLK: 4,SNR1: 4.3101 ,SNR2: 12.053




Frequency (Hz)


0919-142 2026/06/15 6.66UT FUJI -KISO



T20260615154442




BLK: 4,SNR1: 8.9826 ,SNR2: 23.117




Frequency (Hz)

F20260615154442




BLK: 4,SNR1: 10.023 ,SNR2: 25.526




Frequency (Hz)


0926+117 2026/06/15 6.77UT TOYOKAWA-FUJI



T20260615154442





BLK: 2,SNR1: 10.880 ,SNR2: 27.620




Frequency (Hz)

K20260615154439




BLK: 2,SNR1: 9.7777 ,SNR2: 24.550





Frequency (Hz)


0926+117 2026/06/15 6.77UT TOYOKAWA-KISO





F20260615154442




No.Good Data




K20260615154439





No.Good Data




0926+117 2026/06/15 6.77UT FUJI -KISO



T20260615155226




BLK: 3,SNR1: 10.437 ,SNR2: 25.856




Frequency (Hz)

F20260615155226




BLK: 3,SNR1: 8.4317 ,SNR2: 21.170





Frequency (Hz)


3C222 2026/06/15 6.90UT TOYOKAWA-FUJI



T20260615155226




BLK:11,SNR1: 9.6193 ,SNR2: 24.328




Frequency (Hz)

3C222 2026/06/15 6.90UT TOYOKAWA-KISO


K20260615155223





BLK:11,SNR1: 24.951 ,SNR2: 57.709




Frequency (Hz)



F20260615155226




BLK:10,SNR1: 7.6104 ,SNR2: 19.426




Frequency (Hz)

K20260615155223




BLK:10,SNR1: 22.837 ,SNR2: 45.190





Frequency (Hz)


3C222 2026/06/15 6.90UT FUJI -KISO




T20260615155926




BLK: 8,SNR1: 0.71848 ,SNR2: 2.1171




F20260615155927





BLK: 8,SNR1: 7.8584 ,SNR2: 14.104




0941-08 2026/06/15 7.02UT TOYOKAWA-FUJI



T20260615155926





BLK: 8,SNR1: 0.37091 ,SNR2: 1.2173




Frequency (Hz)

K20260615155923




BLK: 8,SNR1: 1.4385 ,SNR2: 4.5376




Frequency (Hz)


0941-08 2026/06/15 7.02UT TOYOKAWA-KISO



F20260615155927





BLK: 8,SNR1: 1.0952 ,SNR2: 6.4181




Frequency (Hz)

K20260615155923




BLK: 8,SNR1: 1.4244 ,SNR2: 4.7222





Frequency (Hz)


0941-08 2026/06/15 7.02UT FUJI -KISO



T20260615160748





BLK: 2,SNR1: 10.651 ,SNR2: 26.523




Frequency (Hz)

3C230 2026/06/15 7.16UT TOYOKAWA-FUJI


F20260615160748





BLK: 2,SNR1: 10.044 ,SNR2: 27.108




Frequency (Hz)



T20260615160748





BLK: 1,SNR1: 11.028 ,SNR2: 27.452




Frequency (Hz)

K20260615160745




BLK: 1,SNR1: 12.419 ,SNR2: 31.113





Frequency (Hz)


3C230 2026/06/15 7.16UT TOYOKAWA-KISO



F20260615160748





BLK: 2,SNR1: 0.43263 ,SNR2: 2.9079




Frequency (Hz)

K20260615160745




BLK: 2,SNR1: 0.43905 ,SNR2: 2.7040





Frequency (Hz)


3C230 2026/06/15 7.16UT FUJI -KISO




T20260615162349




BLK: 2, SNR1: 9.5044 , SNR2: 24.376




F20260615162349





BLK: 2, SNR1: 9.5189 , SNR2: 23.605




3C237 2026/06/15 7.43UT TOYOKAWA-FUJI




T20260615162349




BLK: 1, SNR1: 1.3834 , SNR2: 4.2402




K20260615162346




BLK: 1, SNR1: 9.4151 , SNR2: 18.381




3C237 2026/06/15 7.43UT TOYOKAWA-KISO



F20260615162349




BLK: 1,SNR1: 2.2019 ,SNR2: 8.9299




Frequency (Hz)

K20260615162346




BLK: 1,SNR1: 2.5448 ,SNR2: 15.310





Frequency (Hz)


3C237 2026/06/15 7.43UT FUJI -KISO



T20260615163005





BLK: 6,SNR1: 0.13697 ,SNR2: 3.1353




Frequency (Hz)

F20260615163005




BLK: 6,SNR1: 3.0446 ,SNR2: 8.4180





Frequency (Hz)


1011+110 2026/06/15 7.53UT TOYOKAWA-FUJI



T20260615163005




BLK: 3,SNR1: 1.1196 ,SNR2: 3.3425




Frequency (Hz)

K20260615163002




BLK: 3,SNR1: 1.4156 ,SNR2: 5.4183




Frequency (Hz)


1011+110 2026/06/15 7.53UT TOYOKAWA-KISO



F20260615163005




No.Good Data




Frequency (Hz)

K20260615163002




No.Good Data





Frequency (Hz)


1011+110 2026/06/15 7.53UT FUJI -KISO



T20260615163746




BLK: 1, SNR1: 3.3641 , SNR2: 7.8985




Frequency (Hz)

3C241 2026/06/15 7.66UT TOYOKAWA-FUJI


F20260615163746





BLK: 1, SNR1: 4.7757 , SNR2: 23.938




Frequency (Hz)



T20260615163746




BLK: 4,SNR1: 5.2114 ,SNR2: 18.604




Frequency (Hz)

3C241 2026/06/15 7.66UT TOYOKAWA-KISO


K20260615163743




BLK: 4,SNR1: 5.6237 ,SNR2: 19.638




Frequency (Hz)



F20260615163746




BLK: 4,SNR1: 11.937 ,SNR2: 29.254




Frequency (Hz)

K20260615163743




BLK: 4,SNR1: 11.930 ,SNR2: 29.316





Frequency (Hz)


3C241 2026/06/15 7.66UT FUJI -KISO



T20260615174908





BLK: 4,SNR1: 2.6704 ,SNR2: 8.1035




Frequency (Hz)

F20260615174908




BLK: 4,SNR1: 2.6872 ,SNR2: 11.600





Frequency (Hz)


1130+335 2026/06/15 8.85UT TOYOKAWA-FUJI



T20260615174908





BLK: 8,SNR1: 6.9404 ,SNR2: 15.361




Frequency (Hz)

K20260615174905




BLK: 8,SNR1: 2.2215 ,SNR2: 7.2999





Frequency (Hz)


1130+335 2026/06/15 8.85UT TOYOKAWA-KISO



F20260615174908





BLK: 1,SNR1: 0.74355 ,SNR2: 3.0648




Frequency (Hz)

K20260615174905



BLK: 1,SNR1: 1.6077 ,SNR2: 5.3641



Frequency (Hz)

1130+335 2026/06/15 8.85UT FUJI -KISO

