




T20260616051518





BLK: 6,SNR1: 21.628 ,SNR2: 38.742




Frequency (Hz)

F20260616051518




BLK: 6,SNR1: 16.071 ,SNR2: 28.051





Frequency (Hz)


2259+481 2026/06/15 20.28UT TOYOKAWA-FUJI



T20260616051518





BLK: 7,SNR1: 7.9768 ,SNR2: 19.715




Frequency (Hz)

K20260616051515




BLK: 7,SNR1: 12.467 ,SNR2: 22.211





Frequency (Hz)


2259+481 2026/06/15 20.28UT TOYOKAWA-KISO



F20260616051518





BLK: 1,SNR1: 5.3364 ,SNR2: 9.9078




Frequency (Hz)

2259+481 2026/06/15 20.28UT FUJI -KISO


K20260616051515





BLK: 1,SNR1: 3.4757 ,SNR2: 10.988




Frequency (Hz)



T20260616052719





BLK: 2,SNR1: 7.2480 ,SNR2: 25.724




Frequency (Hz)

F20260616052719




BLK: 2,SNR1: 7.6012 ,SNR2: 22.981





Frequency (Hz)


2311+469 2026/06/15 20.48UT TOYOKAWA-FUJI



T20260616052719





BLK: 1,SNR1: 7.7268 ,SNR2: 24.059




Frequency (Hz)

K20260616052716




BLK: 1,SNR1: 7.3418 ,SNR2: 16.598





Frequency (Hz)


2311+469 2026/06/15 20.48UT TOYOKAWA-KISO



F20260616052719





BLK: 3,SNR1: 7.5048 ,SNR2: 19.595




Frequency (Hz)

2311+469 2026/06/15 20.48UT FUJI -KISO


K20260616052716





BLK: 3,SNR1: 7.1511 ,SNR2: 23.710




Frequency (Hz)



T20260616062715




BLK: 6,SNR1: 9.1559 ,SNR2: 22.573




Frequency (Hz)

F20260616062715




BLK: 6,SNR1: 5.0259 ,SNR2: 12.655





Frequency (Hz)


0011+344 2026/06/15 21.48UT TOYOKAWA-FUJI



T20260616062715





BLK: 6,SNR1: 6.2168 ,SNR2: 11.306




Frequency (Hz)

K20260616062712




BLK: 6,SNR1: 40.170 ,SNR2: 53.651





Frequency (Hz)


0011+344 2026/06/15 21.48UT TOYOKAWA-KISO



F20260616062715





BLK: 3,SNR1: 4.2743 ,SNR2: 11.429




Frequency (Hz)

K20260616062712




BLK: 3,SNR1: 5.0188 ,SNR2: 13.447





Frequency (Hz)


0011+344 2026/06/15 21.48UT FUJI -KISO



T20260616064606





BLK: 8,SNR1: 3.2290 ,SNR2: 9.8356




Frequency (Hz)

3C12 2026/06/15 21.80UT TOYOKAWA-FUJI


F20260616064606





BLK: 8,SNR1: 3.9480 ,SNR2: 11.479




Frequency (Hz)





T20260616064606




BLK: 9,SNR1: 3.2293 ,SNR2: 9.8358




K20260616064603





BLK: 9,SNR1: 8.1438 ,SNR2: 21.045




3C12 2026/06/15 21.80UT TOYOKAWA-KISO





F20260616064606




BLK:12,SNR1: 21.435 ,SNR2: 23.643




K20260616064603





BLK:12,SNR1: 8.1735 ,SNR2: 21.123




3C12 2026/06/15 21.80UT FUJI -KISO



T20260616065424





BLK: 3,SNR1: 0.89097 ,SNR2: 7.4224




Frequency (Hz)

F20260616065424




BLK: 3,SNR1: 13.229 ,SNR2: 21.704





Frequency (Hz)


0038+328 2026/06/15 21.93UT TOYOKAWA-FUJI





T20260616065424




No.Good Data




K20260616065421





No.Good Data




0038+328 2026/06/15 21.93UT TOYOKAWA-KISO



F20260616065424





BLK: 3,SNR1: 9.9740 ,SNR2: 24.254




Frequency (Hz)

K20260616065421




BLK: 3,SNR1: 9.9360 ,SNR2: 23.711





Frequency (Hz)


0038+328 2026/06/15 21.93UT FUJI -KISO



T20260616070729



BLK: 3,SNR1: 0.13623 ,SNR2: 1.5077





Frequency (Hz)


3C26

2026/06/15 22.15UT TOYOKAWA-FUJI


F20260616070729





BLK: 3,SNR1: 7.9774 ,SNR2: 19.870




Frequency (Hz)



T20260616070729





No.Good Data




Frequency (Hz)

K20260616070726




No.Good Data




Frequency (Hz)


3C26 2026/06/15 22.15UT TOYOKAWA-KISO



F20260616070729




BLK: 2,SNR1: 9.7171 ,SNR2: 24.735




Frequency (Hz)

3C26 2026/06/15 22.15UT FUJI -KISO


K20260616070726




BLK: 2,SNR1: 9.5065 ,SNR2: 23.691




Frequency (Hz)



T20260616071228




BLK: 8,SNR1: 6.2997 ,SNR2: 9.9381




Frequency (Hz)

0056-00 2026/06/15 22.24UT TOYOKAWA-FUJI


F20260616071228




BLK: 8,SNR1: 9.3853 ,SNR2: 20.621




Frequency (Hz)



T20260616071228




BLK: 9,SNR1: 6.0435 ,SNR2: 9.5159




Frequency (Hz)

K20260616071225




BLK: 9,SNR1: 8.1272 ,SNR2: 14.260





Frequency (Hz)


0056-00 2026/06/15 22.24UT TOYOKAWA-KISO



F20260616071228





BLK: 6,SNR1: 9.0004 ,SNR2: 14.078




Frequency (Hz)

K20260616071225




BLK: 6,SNR1: 24.945 ,SNR2: 26.665




Frequency (Hz)


0056-00 2026/06/15 22.24UT FUJI -KISO



T20260616072210





BLK: 4,SNR1:-0.38586E-01,SNR2: 1.5132




Frequency (Hz)

F20260616072210




BLK: 4,SNR1:-0.21647 ,SNR2: 0.75254





Frequency (Hz)


0106+01 2026/06/15 22.40UT TOYOKAWA-FUJI



T20260616072210





BLK: 6,SNR1: 0.11731 ,SNR2: 1.0426




Frequency (Hz)

K20260616072207




BLK: 6,SNR1: 0.94623 ,SNR2: 2.9271





Frequency (Hz)


0106+01 2026/06/15 22.40UT TOYOKAWA-KISO



F20260616072210





BLK: 5,SNR1: 0.16380 ,SNR2: 2.2274




Frequency (Hz)

K20260616072207




BLK: 5,SNR1: 0.31378 ,SNR2: 2.0862




Frequency (Hz)


0106+01 2026/06/15 22.40UT FUJI -KISO



T20260616073133





BLK: 5,SNR1: 0.79372 ,SNR2: 3.9365




Frequency (Hz)

F20260616073133




BLK: 5,SNR1: 1.2490 ,SNR2: 3.3052





Frequency (Hz)


0115-01 2026/06/15 22.55UT TOYOKAWA-FUJI



T20260616073133





BLK: 9,SNR1: 0.38434 ,SNR2: 2.9911




Frequency (Hz)

K20260616073130




BLK: 9,SNR1: 5.2021 ,SNR2: 6.8359




Frequency (Hz)


0115-01 2026/06/15 22.55UT TOYOKAWA-KISO



F20260616073133




BLK: 6,SNR1: 0.31360 ,SNR2: 3.7887




Frequency (Hz)

0115-01 2026/06/15 22.55UT FUJI -KISO


K20260616073130





BLK: 6,SNR1: 2.2783 ,SNR2: 9.0806




Frequency (Hz)




T20260616074432




BLK: 5,SNR1: 3.6550 ,SNR2: 10.900




F20260616074432





BLK: 5,SNR1: 1.5210 ,SNR2: 3.7717




0128+03 2026/06/15 22.77UT TOYOKAWA-FUJI




T20260616074432




BLK:11,SNR1: 3.5796 ,SNR2: 10.661




K20260616074429




BLK:11,SNR1: 1.7822 ,SNR2: 5.8965




0128+03 2026/06/15 22.77UT TOYOKAWA-KISO





F20260616074432




BLK:11,SNR1:-0.70758E-01,SNR2: 1.4646




K20260616074429





BLK:11,SNR1: 1.7660 ,SNR2: 5.8714




0128+03 2026/06/15 22.77UT FUJI -KISO



T20260616075107





BLK: 5,SNR1: 9.8921 ,SNR2: 24.492




Frequency (Hz)

3C48 2026/06/15 22.88UT TOYOKAWA-FUJI


F20260616075107





BLK: 5,SNR1: 6.6763 ,SNR2: 18.876




Frequency (Hz)



T20260616075107





BLK: 3, SNR1: 4.3375 ,SNR2: 12.591




Frequency (Hz)

3C48 2026/06/15 22.88UT TOYOKAWA-KISO


K20260616075104





BLK: 3, SNR1: 6.5265 ,SNR2: 18.832




Frequency (Hz)





F20260616075107




No.Good Data




K20260616075104





No.Good Data




3C48 2026/06/15 22.88UT FUJI -KISO



T20260616081050





BLK: 2,SNR1: 10.954 ,SNR2: 26.433




Frequency (Hz)

F20260616081050




BLK: 2,SNR1: 7.6475 ,SNR2: 19.547





Frequency (Hz)


0155-109 2026/06/15 23.21UT TOYOKAWA-FUJI



T20260616081050





BLK: 4,SNR1: 9.1679 ,SNR2: 23.036




Frequency (Hz)

K20260616081047




BLK: 4,SNR1: 9.4906 ,SNR2: 23.652





Frequency (Hz)


0155-109 2026/06/15 23.21UT TOYOKAWA-KISO



F20260616081050





BLK: 4,SNR1: 10.482 ,SNR2: 26.478




Frequency (Hz)

K20260616081047




BLK: 4,SNR1: 9.5768 ,SNR2: 23.861





Frequency (Hz)


0155-109 2026/06/15 23.21UT FUJI -KISO



T20260616081758





BLK: 4,SNR1: 0.17143 ,SNR2: 0.94860




Frequency (Hz)

F20260616081758




BLK: 4,SNR1: 0.36338 ,SNR2: 2.0733




Frequency (Hz)


0202+15 2026/06/15 23.33UT TOYOKAWA-FUJI




T20260616081758




BLK: 3,SNR1: 0.10765 ,SNR2: 0.42151




K20260616081755





BLK: 3,SNR1: 0.98115 ,SNR2: 5.9213




0202+15 2026/06/15 23.33UT TOYOKAWA-KISO




F20260616081758




BLK: 1,SNR1: 0.21904 ,SNR2: 1.9860




K20260616081755





BLK: 1,SNR1: 2.0951 ,SNR2: 15.802




0202+15 2026/06/15 23.33UT FUJI -KISO



T20260616082948





BLK: 7,SNR1: 0.11541 ,SNR2: 0.82042




Frequency (Hz)

F20260616082948




BLK: 7,SNR1: 0.44115 ,SNR2: 3.0072





Frequency (Hz)


0213+178 2026/06/15 23.52UT TOYOKAWA-FUJI



T20260616082948





BLK:10,SNR1: 0.50647E-01,SNR2: 1.1907




Frequency (Hz)

K20260616082945




BLK:10,SNR1: 1.6392 ,SNR2: 5.4425





Frequency (Hz)


0213+178 2026/06/15 23.52UT TOYOKAWA-KISO





F20260616082948




BLK:23,SNR1: 0.50230 ,SNR2: 3.0393




K20260616082945




BLK:23,SNR1: 2.0882 ,SNR2: 6.5270




0213+178 2026/06/15 23.52UT FUJI -KISO



T20260616083731




BLK: 6,SNR1: 2.3323 ,SNR2: 6.8192




Frequency (Hz)

3C67 2026/06/15 23.65UT TOYOKAWA-FUJI


F20260616083731




BLK: 6,SNR1: 7.1973 ,SNR2: 18.282




Frequency (Hz)



T20260616083731



BLK: 3,SNR1: 0.73416E-01,SNR2: 1.0875




Frequency (Hz)


3C67

2026/06/15 23.65UT TOYOKAWA-KISO


K20260616083728




BLK: 3,SNR1: 0.71157 ,SNR2: 6.1692




Frequency (Hz)



F20260616083731





BLK: 3,SNR1: 6.8863 ,SNR2: 19.886





3C67 2026/06/15 23.65UT FUJI -KISO



K20260616083728




BLK: 3,SNR1: 11.500 ,SNR2: 20.950



T20260616085336




BLK:16,SNR1: 3.0166 ,SNR2: 9.0462





0237+097 2026/06/15 23.92UT TOYOKAWA-FUJI



F20260616085336




BLK:16,SNR1: 6.0850 ,SNR2: 9.9602



T20260616085336





BLK:20,SNR1: 2.7527 ,SNR2: 8.5707





0237+097 2026/06/15 23.92UT TOYOKAWA-KISO


K20260616085333




BLK:20,SNR1: 7.4642 ,SNR2: 13.192




F20260616085336




BLK: 8,SNR1: 5.3694 ,SNR2: 12.008




K20260616085333





BLK: 8,SNR1: 7.9213 ,SNR2: 14.215




0237+097 2026/06/15 23.92UT FUJI -KISO



T20260616091501




BLK: 3,SNR1: 0.26867 ,SNR2: 0.48827




Frequency (Hz)

F20260616091501




BLK: 3,SNR1:-0.18680E-01,SNR2: 0.79348





Frequency (Hz)


0258+350 2026/06/16 0.28UT TOYOKAWA-FUJI





T20260616091501




BLK: 6,SNR1: 0.12680 ,SNR2: 0.38965




K20260616091458




BLK: 6,SNR1: 0.53018 ,SNR2: 1.9401




0258+350 2026/06/16 0.28UT TOYOKAWA-KISO




F20260616091501




BLK: 4,SNR1: 0.36752E-01,SNR2: 0.70497




K20260616091458





BLK: 4,SNR1: 0.49268 ,SNR2: 2.0968




0258+350 2026/06/16 0.28UT FUJI -KISO



T20260616092451




BLK:11,SNR1: 3.4245 ,SNR2: 10.353





0308+305 2026/06/16 0.44UT TOYOKAWA-FUJI



F20260616092451




BLK:11,SNR1: 5.2701 ,SNR2: 12.623



T20260616092451





BLK:19,SNR1: 3.3559 ,SNR2: 10.163





0308+305 2026/06/16 0.44UT TOYOKAWA-KISO


K20260616092448




BLK:19,SNR1: 22.579 ,SNR2: 20.113





F20260616092451




BLK:10,SNR1: 7.1947 ,SNR2: 18.962




K20260616092448





BLK:10,SNR1: 22.848 ,SNR2: 20.357




0308+305 2026/06/16 0.44UT FUJI -KISO



T20260616093311




BLK: 6,SNR1: 9.2532 ,SNR2: 27.278





3C84 2026/06/16 0.58UT TOYOKAWA-FUJI



F20260616093311




BLK: 6,SNR1: 9.7549 ,SNR2: 25.409



T20260616093311




BLK: 3, SNR1: 2.4331 , SNR2: 5.2058





3C84 2026/06/16 0.58UT TOYOKAWA-KISO


K20260616093308




BLK: 3, SNR1: 14.403 , SNR2: 27.588



F20260616093311




BLK: 3, SNR1: 11.165 ,SNR2: 28.710





3C84 2026/06/16 0.58UT FUJI -KISO


K20260616093308




BLK: 3, SNR1: 9.3948 ,SNR2: 27.178



T20260616094026




BLK: 1,SNR1: 0.86718E-02,SNR2: 1.3996





0324+119 2026/06/16 0.70UT TOYOKAWA-FUJI


F20260616094026




BLK: 1,SNR1: 1.9720 ,SNR2: 6.6981



T20260616094026




BLK: 3,SNR1: 5.1327 ,SNR2: 10.819





0324+119 2026/06/16 0.70UT TOYOKAWA-KISO



K20260616094023




BLK: 3,SNR1: 1.2272 ,SNR2: 4.7638





F20260616094026




No. Good Data




K20260616094023




No. Good Data




0324+119 2026/06/16 0.70UT FUJI -KISO




T20260616094944




BLK: 6,SNR1: 1.1636 ,SNR2: 3.8449




F20260616094944




BLK: 6,SNR1: 2.0993 ,SNR2: 5.7058




0333+32 2026/06/16 0.86UT TOYOKAWA-FUJI





T20260616094944




BLK:11,SNR1: 2.6213 ,SNR2: 8.2421




K20260616094941




BLK:11,SNR1: 3.1776 ,SNR2: 9.6903




0333+32 2026/06/16 0.86UT TOYOKAWA-KISO





F20260616094944




BLK: 8,SNR1: 2.3836 ,SNR2: 4.1935




K20260616094941





BLK: 8,SNR1: 2.9311 ,SNR2: 9.0435




0333+32 2026/06/16 0.86UT FUJI -KISO



T20260616100244




BLK: 7, SNR1: 7.4720 ,SNR2: 22.370





0347+05 2026/06/16 1.07UT TOYOKAWA-FUJI



F20260616100244




BLK: 7, SNR1: 6.2487 ,SNR2: 13.878



T20260616100244




BLK: 3,SNR1: 2.3058 ,SNR2: 6.9305





0347+05 2026/06/16 1.07UT TOYOKAWA-KISO


K20260616100241




BLK: 3,SNR1: 1.7241 ,SNR2: 7.0593



F20260616100244




BLK: 2,SNR1: 1.7881 ,SNR2: 7.0269





0347+05 2026/06/16 1.07UT FUJI -KISO


K20260616100241




BLK: 2,SNR1: 3.4152 ,SNR2: 12.834



T20260616101818




BLK: 7,SNR1: 1.8129 ,SNR2: 5.4316





0403-132 2026/06/16 1.33UT TOYOKAWA-FUJI


F20260616101818




BLK: 7,SNR1: 1.6472 ,SNR2: 4.1521



T20260616101818





BLK:11,SNR1: 1.8881 ,SNR2: 5.7748





0403-132 2026/06/16 1.33UT TOYOKAWA-KISO


K20260616101815




BLK:11,SNR1: 7.9147 ,SNR2: 23.300



F20260616101818





BLK: 8,SNR1: 6.0755 ,SNR2: 13.516




0403-132 2026/06/16 1.33UT FUJI -KISO


K20260616101815





BLK: 8,SNR1: 22.011 ,SNR2: 28.507




Frequency (Hz)



T20260616102729




BLK: 7,SNR1: 23.556 ,SNR2: 56.443




0411+05 2026/06/16 1.49UT TOYOKAWA-FUJI


F20260616102729





BLK: 7,SNR1: 2.2684 ,SNR2: 8.7444




Frequency (Hz)



T20260616102729




BLK: 6,SNR1: 1.6214 ,SNR2: 8.2763





0411+05 2026/06/16 1.49UT TOYOKAWA-KISO


K20260616102726




BLK: 6,SNR1: 1.6959 ,SNR2: 6.9813




F20260616102729




BLK: 3,SNR1: 1.3155 ,SNR2: 2.7608




K20260616102726





BLK: 3,SNR1: 2.9161 ,SNR2: 5.9912




0411+05 2026/06/16 1.49UT FUJI -KISO





T20260616103424




No. Good Data




F20260616103424





No. Good Data




0418+236 2026/06/16 1.60UT TOYOKAWA-FUJI



T20260616103424





BLK: 2,SNR1: 0.33699 ,SNR2: 2.7097





0418+236 2026/06/16 1.60UT TOYOKAWA-KISO



K20260616103421




BLK: 2,SNR1: 0.11522 ,SNR2: 4.1090



F20260616103424





BLK:10,SNR1: 10.416 ,SNR2: 22.566





0418+236 2026/06/16 1.60UT FUJI -KISO


K20260616103421




BLK:10,SNR1: 17.028 ,SNR2: 29.343




T20260616104553




BLK: 9,SNR1: 8.2199 ,SNR2: 14.375




F20260616104553




BLK: 9,SNR1: 0.92913 ,SNR2: 4.4831




3C119 2026/06/16 1.79UT TOYOKAWA-FUJI




T20260616104553




BLK:10,SNR1: 5.3437 ,SNR2: 13.089




K20260616104550




BLK:10,SNR1: 2.3469 ,SNR2: 9.8941




3C119 2026/06/16 1.79UT TOYOKAWA-KISO



F20260616104553




BLK: 4,SNR1: 7.7915 ,SNR2: 19.484





3C119 2026/06/16 1.79UT FUJI -KISO



K20260616104550




BLK: 4,SNR1: 8.9256 ,SNR2: 17.348



T20260616113359




BLK: 5, SNR1: 8.4578 , SNR2: 20.943




3C138 2026/06/16 2.59UT TOYOKAWA-FUJI


F20260616113359





BLK: 5, SNR1: 15.360 , SNR2: 28.656




Frequency (Hz)



T20260616113359




BLK: 7, SNR1: 8.0727 ,SNR2: 20.050





3C138 2026/06/16 2.59UT TOYOKAWA-KISO


K20260616113356




BLK: 7, SNR1: 9.0168 ,SNR2: 22.205



F20260616113359





BLK: 4,SNR1: 28.696 ,SNR2: 44.119





3C138 2026/06/16 2.59UT FUJI -KISO


K20260616113356




BLK: 4,SNR1: 11.560 ,SNR2: 28.268




T20260616114732




BLK:29,SNR1: 79.727 ,SNR2: 119.91




F20260616114733




BLK:29,SNR1: 22.700 ,SNR2: 29.358




0531+194 2026/06/16 2.82UT TOYOKAWA-FUJI





T20260616114732




BLK:28,SNR1: 85.628 ,SNR2: 125.05




K20260616114729





BLK:28,SNR1: 35.093 ,SNR2: 45.993





0531+194 2026/06/16 2.82UT TOYOKAWA-KISO




F20260616114733




K20260616114729




0531+194 2026/06/16 2.82UT FUJI -KISO





T20260616115554




BLK:13,SNR1: 5.3517 ,SNR2: 27.025




F20260616115554




BLK:13,SNR1: 9.9701 ,SNR2: 24.900




3C147 2026/06/16 2.96UT TOYOKAWA-FUJI




T20260616115554




BLK: 6, SNR1: 8.7978 ,SNR2: 21.741




K20260616115551




BLK: 6, SNR1: 7.6974 ,SNR2: 19.128




3C147 2026/06/16 2.96UT TOYOKAWA-KISO



F20260616115554




BLK: 5,SNR1: 7.7829 ,SNR2: 19.626





3C147 2026/06/16 2.96UT FUJI -KISO



K20260616115551




BLK: 5,SNR1: 7.1248 ,SNR2: 18.021



T20260616120403




BLK: 5,SNR1: 9.0085 ,SNR2: 22.199





0548+16 2026/06/16 3.10UT TOYOKAWA-FUJI


F20260616120403




BLK: 5,SNR1: 7.7872 ,SNR2: 18.973



T20260616120403




BLK: 3,SNR1: 6.3443 ,SNR2: 15.993




0548+16 2026/06/16 3.10UT TOYOKAWA-KISO


K20260616120400




BLK: 3,SNR1: 6.2607 ,SNR2: 15.081




Frequency (Hz)




F20260616120403




BLK: 4,SNR1: 12.883 ,SNR2: 23.034




K20260616120400





BLK: 4,SNR1: 8.5218 ,SNR2: 21.029




0548+16 2026/06/16 3.10UT FUJI -KISO




T20260616120814




BLK: 4,SNR1: 8.7964 ,SNR2: 21.940




F20260616120814





BLK: 4,SNR1: 8.9544 ,SNR2: 21.767




0552+12 2026/06/16 3.17UT TOYOKAWA-FUJI



T20260616120814




BLK: 8,SNR1: 9.7718 ,SNR2: 24.556




0552+12 2026/06/16 3.17UT TOYOKAWA-KISO


K20260616120811




BLK: 8,SNR1: 6.8498 ,SNR2: 17.367




Frequency (Hz)




F20260616120814




BLK: 9,SNR1: 6.9727 ,SNR2: 22.164




K20260616120811




BLK: 9,SNR1: 5.9877 ,SNR2: 19.723




0552+12 2026/06/16 3.17UT FUJI -KISO



T20260616121241





BLK: 8,SNR1: 30.511 ,SNR2: 43.983





0556+191 2026/06/16 3.24UT TOYOKAWA-FUJI


F20260616121241




BLK: 8,SNR1: 10.179 ,SNR2: 26.286



T20260616121241




BLK: 5, SNR1: 76.788 , SNR2: 79.530





0556+191 2026/06/16 3.24UT TOYOKAWA-KISO



K20260616121238




BLK: 5, SNR1: 6.7882 , SNR2: 16.927




F20260616121241




BLK: 4, SNR1: 8.7002 ,SNR2: 21.464




K20260616121238





BLK: 4, SNR1: 8.2625 ,SNR2: 20.438




0556+191 2026/06/16 3.24UT FUJI -KISO



T20260616121713




BLK: 1,SNR1: 10.744 ,SNR2: 23.345





3C152 2026/06/16 3.32UT TOYOKAWA-FUJI



F20260616121713




BLK: 1,SNR1: 24.832 ,SNR2: 50.628




T20260616121713




BLK: 2,SNR1: 24.896 ,SNR2: 43.076




K20260616121710





BLK: 2,SNR1: 40.073 ,SNR2: 47.614






3C152 2026/06/16 3.32UT TOYOKAWA-KISO




F20260616121713




K20260616121710




3C152 2026/06/16 3.32UT FUJI -KISO





T20260616123933




BLK: 5,SNR1: 12.235 ,SNR2: 21.398




F20260616123933




BLK: 5,SNR1: 11.292 ,SNR2: 18.679




3C161 2026/06/16 3.69UT TOYOKAWA-FUJI





T20260616123933




BLK: 4,SNR1: 3.4576 ,SNR2: 10.552




K20260616123930




BLK: 4,SNR1: 3.2390 ,SNR2: 9.7621




3C161 2026/06/16 3.69UT TOYOKAWA-KISO



F20260616123933





BLK: 2,SNR1: 4.2315 ,SNR2: 10.150





3C161 2026/06/16 3.69UT FUJI -KISO


K20260616123930




BLK: 2,SNR1: 3.0590 ,SNR2: 11.949




T20260616130706




No. Good Data




F20260616130706





No. Good Data




0652-130 2026/06/16 4.15UT TOYOKAWA-FUJI



T20260616130706





BLK: 2,SNR1: 16.210 ,SNR2: 26.996




0652-130 2026/06/16 4.15UT TOYOKAWA-KISO


K20260616130703





BLK: 2,SNR1: 12.971 ,SNR2: 29.203




Frequency (Hz)





F20260616130706




BLK: 1,SNR1: 0.38064 ,SNR2: 3.2370




K20260616130703





BLK: 1,SNR1: 11.939 ,SNR2: 28.868




0652-130 2026/06/16 4.15UT FUJI -KISO





T20260616131843




No.Good Data




F20260616131843




No.Good Data




0703+138 2026/06/16 4.34UT TOYOKAWA-FUJI




T20260616131843




BLK: 2,SNR1: 1.2555 ,SNR2: 7.7242




K20260616131840




BLK: 2,SNR1: 7.3297 ,SNR2: 18.283




0703+138 2026/06/16 4.34UT TOYOKAWA-KISO




F20260616131843




BLK: 1,SNR1: 2.3462 ,SNR2: 11.145




K20260616131840





BLK: 1,SNR1: 8.9682 ,SNR2: 21.389




0703+138 2026/06/16 4.34UT FUJI -KISO





T20260616132806




BLK: 1,SNR1: 0.24901 ,SNR2: 3.9284




F20260616132806





BLK: 1,SNR1: 4.2057 ,SNR2: 10.798




0713-024 2026/06/16 4.50UT TOYOKAWA-FUJI



T20260616132806





No.Good Data




Frequency (Hz)

K20260616132803




No.Good Data





Frequency (Hz)


0713-024 2026/06/16 4.50UT TOYOKAWA-KISO





F20260616132806




No.Good Data




K20260616132803





No.Good Data




0713-024 2026/06/16 4.50UT FUJI -KISO





T20260616133818




BLK: 7,SNR1: 1.9593 ,SNR2: 13.236




F20260616133818




BLK: 7,SNR1: 8.0084 ,SNR2: 18.776




0723+10 2026/06/16 4.67UT TOYOKAWA-FUJI




T20260616133818




BLK: 7,SNR1: 4.4813 ,SNR2: 18.298




K20260616133815




BLK: 7,SNR1: 1.8871 ,SNR2: 7.9441




0723+10 2026/06/16 4.67UT TOYOKAWA-KISO




F20260616133818




BLK: 1,SNR1: 7.2699 ,SNR2: 16.095




K20260616133815





BLK: 1,SNR1: 10.778 ,SNR2: 19.285




0723+10 2026/06/16 4.67UT FUJI -KISO





T20260616134833




BLK: 7,SNR1: 0.11157 ,SNR2: 1.0526




F20260616134833





BLK: 7,SNR1: 3.8527 ,SNR2: 12.889




0732+33 2026/06/16 4.84UT TOYOKAWA-FUJI





T20260616134833




BLK: 8,SNR1: 1.7214 ,SNR2: 3.6087




K20260616134830





BLK: 8,SNR1: 4.4413 ,SNR2: 9.0225




0732+33 2026/06/16 4.84UT TOYOKAWA-KISO



F20260616134833





BLK:11,SNR1: 4.4649 ,SNR2: 11.235





0732+33 2026/06/16 4.84UT FUJI -KISO



K20260616134830




BLK:11,SNR1: 5.7031 ,SNR2: 14.509




T20260616135634




BLK: 5,SNR1: 1.2697 ,SNR2: 4.8371




F20260616135634




BLK: 5,SNR1:-0.19943 ,SNR2: 0.94850




0741-06 2026/06/16 4.97UT TOYOKAWA-FUJI





T20260616135634




BLK: 2,SNR1: 0.78450 ,SNR2: 3.9607




K20260616135631




BLK: 2,SNR1: 1.5870 ,SNR2: 13.318




0741-06 2026/06/16 4.97UT TOYOKAWA-KISO



F20260616135634





BLK: 1,SNR1:-0.12006 ,SNR2: 2.0392





0741-06 2026/06/16 4.97UT FUJI -KISO



K20260616135631




BLK: 1,SNR1: 1.5345 ,SNR2: 13.162





T20260616140618




BLK: 1,SNR1: 9.2885 ,SNR2: 23.035




F20260616140618





BLK: 1,SNR1: 1.7623 ,SNR2: 6.1671




0752-200 2026/06/16 5.13UT TOYOKAWA-FUJI




T20260616140618




BLK: 1,SNR1: 2.1252 ,SNR2: 8.1272




K20260616140615




BLK: 1,SNR1: 1.2929 ,SNR2: 10.186




0752-200 2026/06/16 5.13UT TOYOKAWA-KISO





F20260616140618




BLK: 4,SNR1: 0.18433E-01,SNR2: 1.4616




K20260616140615





BLK: 4,SNR1: 3.5364 ,SNR2: 13.403




0752-200 2026/06/16 5.13UT FUJI -KISO





T20260616141354




BLK: 4,SNR1: 2.2197 ,SNR2: 5.3485




F20260616141354




BLK: 4,SNR1: 10.974 ,SNR2: 26.914




3C190 2026/06/16 5.26UT TOYOKAWA-FUJI




T20260616141354




BLK: 7,SNR1: 0.91712 ,SNR2: 7.9212




K20260616141351





BLK: 7,SNR1: 68.663 ,SNR2: 78.760




3C190 2026/06/16 5.26UT TOYOKAWA-KISO



F20260616141354





BLK: 5,SNR1: 4.7768 ,SNR2: 8.8552





3C190 2026/06/16 5.26UT FUJI -KISO



K20260616141351




BLK: 5,SNR1: 79.578 ,SNR2: 100.96



T20260616142620





BLK:20,SNR1: 10.631 ,SNR2: 23.834





3C196 2026/06/16 5.47UT TOYOKAWA-FUJI


F20260616142620




BLK:20,SNR1: 15.915 ,SNR2: 36.615





T20260616142620




BLK:21,SNR1: 10.709 ,SNR2: 24.304




K20260616142617







BLK:21,SNR1: 11.335 ,SNR2: 27.027




3C196 2026/06/16 5.47UT TOYOKAWA-KISO








3C196 2026/06/16 5.47UT FUJI -KISO





T20260616143729




BLK: 3,SNR1: 3.9989 ,SNR2: 16.150




F20260616143729





BLK: 3,SNR1: 4.0789 ,SNR2: 15.771




0821+394 2026/06/16 5.65UT TOYOKAWA-FUJI





T20260616143729




No.Good Data




K20260616143726





No.Good Data




0821+394 2026/06/16 5.65UT TOYOKAWA-KISO





F20260616143729




No.Good Data




K20260616143726





No.Good Data




0821+394 2026/06/16 5.65UT FUJI -KISO



T20260616144907





No.Good Data




Frequency (Hz)

F20260616144907




No.Good Data





Frequency (Hz)


0834-19 2026/06/16 5.85UT TOYOKAWA-FUJI





T20260616144907




BLK: 2,SNR1: 15.725 ,SNR2: 27.923




K20260616144904





BLK: 2,SNR1: 13.126 ,SNR2: 29.321




0834-19 2026/06/16 5.85UT TOYOKAWA-KISO




F20260616144907




BLK: 1,SNR1: 9.5135 ,SNR2: 24.969




K20260616144904





BLK: 1,SNR1: 14.712 ,SNR2: 32.726




0834-19 2026/06/16 5.85UT FUJI -KISO




T20260616145413




BLK:10,SNR1: 27.779 ,SNR2: 37.123




F20260616145413





BLK:10,SNR1: 8.9239 ,SNR2: 19.389




0839-071 2026/06/16 5.93UT TOYOKAWA-FUJI





T20260616145413




BLK: 7,SNR1: 13.351 ,SNR2: 94.597




K20260616145410




BLK: 7,SNR1: 6.2048 ,SNR2: 15.482




0839-071 2026/06/16 5.93UT TOYOKAWA-KISO





F20260616145413




BLK: 2,SNR1: 0.72314 ,SNR2: 7.3712




K20260616145410





BLK: 2,SNR1: 0.98518 ,SNR2: 3.4494




0839-071 2026/06/16 5.93UT FUJI -KISO



T20260616150514





BLK: 1,SNR1: 0.94213E-01,SNR2: 0.97464




Frequency (Hz)

F20260616150514




BLK: 1,SNR1: 1.3474 ,SNR2: 4.7681





Frequency (Hz)


3C208 2026/06/16 6.12UT TOYOKAWA-FUJI



T20260616150514





BLK: 7,SNR1: 2.7634 ,SNR2: 7.2815




Frequency (Hz)

K20260616150511




BLK: 7,SNR1: 11.605 ,SNR2: 29.395




Frequency (Hz)


3C208 2026/06/16 6.12UT TOYOKAWA-KISO




F20260616150514




BLK: 3,SNR1: 1.3521 ,SNR2: 5.8450




K20260616150511





BLK: 3,SNR1: 0.69034 ,SNR2: 2.4928




3C208 2026/06/16 6.12UT FUJI -KISO




T20260616152157




BLK: 1,SNR1: 9.2589 ,SNR2: 26.739




F20260616152157





BLK: 1,SNR1: 18.101 ,SNR2: 33.482




3C216 2026/06/16 6.39UT TOYOKAWA-FUJI




T20260616152157




BLK: 2,SNR1: 9.2072 ,SNR2: 26.589




K20260616152154




BLK: 2,SNR1: 10.726 ,SNR2: 27.662




3C216 2026/06/16 6.39UT TOYOKAWA-KISO



F20260616152157





BLK: 1,SNR1: 18.101 ,SNR2: 33.482




Frequency (Hz)

K20260616152154




BLK: 1,SNR1: 11.076 ,SNR2: 28.555





Frequency (Hz)


3C216 2026/06/16 6.39UT FUJI -KISO



T20260616153406




BLK:21,SNR1: 7.1514 ,SNR2: 20.637




Frequency (Hz)

F20260616153406




BLK:21,SNR1: 3.4701 ,SNR2: 9.7514





Frequency (Hz)


0919-142 2026/06/16 6.60UT TOYOKAWA-FUJI




T20260616153406




BLK:29,SNR1: 7.7629 ,SNR2: 22.342




K20260616153403




BLK:29,SNR1: 13.600 ,SNR2: 23.981




0919-142 2026/06/16 6.60UT TOYOKAWA-KISO



F20260616153406





BLK:25,SNR1: 3.3952 ,SNR2: 11.819




Frequency (Hz)

K20260616153403




BLK:25,SNR1: 13.805 ,SNR2: 24.339





Frequency (Hz)


0919-142 2026/06/16 6.60UT FUJI -KISO



T20260616154046




BLK: 8,SNR1: 1.1270 ,SNR2: 3.6323




Frequency (Hz)

F20260616154046




BLK: 8,SNR1: 1.5003 ,SNR2: 3.5605





Frequency (Hz)


0926+117 2026/06/16 6.71UT TOYOKAWA-FUJI



T20260616154046





BLK:15,SNR1: 1.1969 ,SNR2: 3.1690




Frequency (Hz)

K20260616154043




BLK:15,SNR1: 7.8838 ,SNR2: 20.321





Frequency (Hz)


0926+117 2026/06/16 6.71UT TOYOKAWA-KISO





F20260616154046




BLK:14,SNR1: 0.77195 ,SNR2: 2.2578




K20260616154043





BLK:14,SNR1: 7.8613 ,SNR2: 20.264




0926+117 2026/06/16 6.71UT FUJI -KISO




T20260616154830




BLK: 4,SNR1: 3.4756 ,SNR2: 15.061




F20260616154830





BLK: 4,SNR1: 0.96738 ,SNR2: 2.3588




3C222 2026/06/16 6.84UT TOYOKAWA-FUJI





T20260616154830




BLK: 6,SNR1: 0.16331 ,SNR2: 1.1884




K20260616154827




BLK: 6,SNR1: 0.68591 ,SNR2: 3.1158




3C222 2026/06/16 6.84UT TOYOKAWA-KISO





F20260616154830




BLK: 5,SNR1: 0.19546 ,SNR2: 1.2178




K20260616154827





BLK: 5,SNR1: 0.89444 ,SNR2: 5.1267




3C222 2026/06/16 6.84UT FUJI -KISO



T20260616155530




BLK: 4,SNR1: 6.6006 ,SNR2: 17.016




Frequency (Hz)

F20260616155530




BLK: 4,SNR1: 5.2422 ,SNR2: 14.148




Frequency (Hz)


0941-08 2026/06/16 6.95UT TOYOKAWA-FUJI



T20260616155530




BLK: 6,SNR1: 5.8102 ,SNR2: 14.971




Frequency (Hz)

K20260616155527




BLK: 6,SNR1: 5.9307 ,SNR2: 17.344




Frequency (Hz)


0941-08 2026/06/16 6.95UT TOYOKAWA-KISO



F20260616155530




BLK: 3,SNR1: 9.9797 ,SNR2: 14.885




Frequency (Hz)

K20260616155527




BLK: 3,SNR1: 3.0620 ,SNR2: 11.963





Frequency (Hz)


0941-08 2026/06/16 6.95UT FUJI -KISO



T20260616160352





BLK: 4,SNR1: 2.0857 ,SNR2: 3.8407




Frequency (Hz)

F20260616160352




BLK: 4,SNR1: 0.69156E-01,SNR2: 1.5024





Frequency (Hz)


3C230 2026/06/16 7.09UT TOYOKAWA-FUJI



T20260616160352





BLK: 3,SNR1: 0.16390 ,SNR2: 2.6902




Frequency (Hz)

3C230 2026/06/16 7.09UT TOYOKAWA-KISO


K20260616160349




BLK: 3,SNR1: 1.4112 ,SNR2: 7.5230




Frequency (Hz)



F20260616160352





BLK: 3,SNR1: 2.5306 ,SNR2: 5.4378




Frequency (Hz)

K20260616160349




BLK: 3,SNR1: 0.36668 ,SNR2: 3.2625





Frequency (Hz)


3C230 2026/06/16 7.09UT FUJI -KISO



T20260616161953





BLK: 2, SNR1: 16.143 , SNR2: 38.163




Frequency (Hz)

F20260616161953




BLK: 2, SNR1: 7.6796 , SNR2: 22.214





Frequency (Hz)


3C237 2026/06/16 7.36UT TOYOKAWA-FUJI



T20260616161953




BLK: 6,SNR1: 7.6268 ,SNR2: 19.279




Frequency (Hz)

K20260616161950




BLK: 6,SNR1: 10.099 ,SNR2: 26.850





Frequency (Hz)


3C237 2026/06/16 7.36UT TOYOKAWA-KISO



F20260616161953





BLK: 1,SNR1: 2.0928 ,SNR2: 4.9278




Frequency (Hz)

K20260616161950




BLK: 1,SNR1: 8.3208 ,SNR2: 16.891





Frequency (Hz)


3C237 2026/06/16 7.36UT FUJI -KISO



T20260616162609




BLK:10,SNR1: 0.59500 ,SNR2: 2.0671




Frequency (Hz)

F20260616162609




BLK:10,SNR1: 0.58730 ,SNR2: 5.2921





Frequency (Hz)


1011+110 2026/06/16 7.46UT TOYOKAWA-FUJI



T20260616162609





BLK:15,SNR1: 0.45497 ,SNR2: 2.8034




Frequency (Hz)

K20260616162606




BLK:15,SNR1: 7.4499 ,SNR2: 19.041





Frequency (Hz)


1011+110 2026/06/16 7.46UT TOYOKAWA-KISO



F20260616162609




BLK:12,SNR1: 1.6815 ,SNR2: 3.7536




Frequency (Hz)

K20260616162606




BLK:12,SNR1: 7.6309 ,SNR2: 19.507





Frequency (Hz)


1011+110 2026/06/16 7.46UT FUJI -KISO



T20260616163351





BLK: 3,SNR1:-0.64416E-01,SNR2: 0.96822




Frequency (Hz)

F20260616163351




BLK: 3,SNR1: 15.099 ,SNR2: 35.819





Frequency (Hz)


3C241 2026/06/16 7.59UT TOYOKAWA-FUJI



T20260616163351





BLK: 2,SNR1: 0.90483 ,SNR2: 2.8883




Frequency (Hz)

K20260616163348




BLK: 2,SNR1: 8.1767 ,SNR2: 14.521





Frequency (Hz)


3C241 2026/06/16 7.59UT TOYOKAWA-KISO





F20260616163351




No.Good Data




K20260616163348





No.Good Data




3C241 2026/06/16 7.59UT FUJI -KISO



T20260616174513





BLK: 6,SNR1: 5.8974 ,SNR2: 10.608




Frequency (Hz)

F20260616174513




BLK: 6,SNR1: 2.0459 ,SNR2: 5.2928





Frequency (Hz)


1130+335 2026/06/16 8.78UT TOYOKAWA-FUJI



T20260616174513





BLK: 6,SNR1: 5.9085 ,SNR2: 10.638




Frequency (Hz)

K20260616174510




BLK: 6,SNR1: 6.6135 ,SNR2: 13.633





Frequency (Hz)


1130+335 2026/06/16 8.78UT TOYOKAWA-KISO



F20260616174513




BLK: 3,SNR1: 0.79086 ,SNR2: 2.2282




Frequency (Hz)

K20260616174510




BLK: 3,SNR1: 1.1288 ,SNR2: 5.0640





Frequency (Hz)


1130+335 2026/06/16 8.78UT FUJI -KISO



T20260616180305




BLK: 3,SNR1: 0.27951 ,SNR2: 1.1252




Frequency (Hz)

F20260616180305




BLK: 3,SNR1: 4.0663 ,SNR2: 6.5508





Frequency (Hz)


1148+387 2026/06/16 9.08UT TOYOKAWA-FUJI



T20260616180305





BLK: 4,SNR1: 0.34763 ,SNR2: 2.5805




Frequency (Hz)

K20260616180302




BLK: 4,SNR1: 1.9280 ,SNR2: 6.3129




Frequency (Hz)


1148+387 2026/06/16 9.08UT TOYOKAWA-KISO



F20260616180305





BLK: 1,SNR1: 0.70025 ,SNR2: 3.6216




Frequency (Hz)

K20260616180302



BLK: 1,SNR1: 0.21724 ,SNR2: 2.4452



Frequency (Hz)

1148+387 2026/06/16 9.08UT FUJI -KISO

