




T20260629092711





BLK:21,SNR1: 8.0232 ,SNR2: 23.406




Frequency (Hz)

F20260629092711




BLK:21,SNR1: 8.9583 ,SNR2: 24.341





Frequency (Hz)


0403-132 2026/06/29 0.48UT TOYOKAWA-FUJI



T20260629092711





BLK:18,SNR1: 8.0590 ,SNR2: 23.623




Frequency (Hz)

K20260629092708




BLK:18,SNR1: 7.5948 ,SNR2: 19.727





Frequency (Hz)


0403-132 2026/06/29 0.48UT TOYOKAWA-KISO



F20260629092711





BLK:22,SNR1: 10.238 ,SNR2: 24.485




Frequency (Hz)

K20260629092708




BLK:22,SNR1: 12.380 ,SNR2: 22.173





Frequency (Hz)


0403-132 2026/06/29 0.48UT FUJI -KISO



T20260629093623





BLK: 4,SNR1: 0.45959 ,SNR2: 1.8364




Frequency (Hz)

F20260629093623




BLK: 4,SNR1: 5.5846 ,SNR2: 18.760





Frequency (Hz)


0411+05 2026/06/29 0.63UT TOYOKAWA-FUJI



T20260629093623





BLK: 1,SNR1: 0.77638 ,SNR2: 2.7376




Frequency (Hz)

0411+05 2026/06/29 0.63UT TOYOKAWA-KISO


K20260629093620





BLK: 1,SNR1: 1.4523 ,SNR2: 6.8960




Frequency (Hz)



F20260629093623





BLK: 1,SNR1: 4.3509 ,SNR2: 24.428




Frequency (Hz)

0411+05 2026/06/29 0.63UT FUJI -KISO


K20260629093620





BLK: 1,SNR1: 7.7713 ,SNR2: 19.591




Frequency (Hz)



T20260629094318





BLK:15,SNR1: 0.47370 ,SNR2: 1.5403




Frequency (Hz)

F20260629094318




BLK:15,SNR1: 3.5653 ,SNR2: 8.5399





Frequency (Hz)


0418+236 2026/06/29 0.75UT TOYOKAWA-FUJI



T20260629094318





BLK: 9,SNR1: 0.18328 ,SNR2: 0.86154




Frequency (Hz)

K20260629094315




BLK: 9,SNR1: 0.58598 ,SNR2: 2.5658





Frequency (Hz)


0418+236 2026/06/29 0.75UT TOYOKAWA-KISO



F20260629094318





BLK:12,SNR1: 4.4165 ,SNR2: 9.6865




Frequency (Hz)

K20260629094315




BLK:12,SNR1: 1.4329 ,SNR2: 4.6291





Frequency (Hz)


0418+236 2026/06/29 0.75UT FUJI -KISO



T20260629095446





BLK:15,SNR1: 4.8985 ,SNR2: 8.6971




Frequency (Hz)

3C119 2026/06/29 0.94UT TOYOKAWA-FUJI


F20260629095446





BLK:15,SNR1: 6.3634 ,SNR2: 11.349




Frequency (Hz)



T20260629095446





BLK:15,SNR1: 5.1689 ,SNR2: 9.2075




Frequency (Hz)

3C119 2026/06/29 0.94UT TOYOKAWA-KISO


K20260629095443





BLK:15,SNR1: 7.7825 ,SNR2: 13.948




Frequency (Hz)



F20260629095446





BLK:17,SNR1: 6.1877 ,SNR2: 11.020




Frequency (Hz)

3C119 2026/06/29 0.94UT FUJI -KISO


K20260629095443





BLK:17,SNR1: 7.0906 ,SNR2: 12.403




Frequency (Hz)



T20260629104252





BLK:22,SNR1: 5.0023 ,SNR2: 20.032




Frequency (Hz)

3C138 2026/06/29 1.74UT TOYOKAWA-FUJI


F20260629104252





BLK:22,SNR1: 9.7917 ,SNR2: 22.796




Frequency (Hz)



T20260629104252





BLK:23,SNR1: 4.6221 ,SNR2: 18.756




Frequency (Hz)

3C138 2026/06/29 1.74UT TOYOKAWA-KISO


K20260629104249





BLK:23,SNR1: 2.7235 ,SNR2: 6.6998




Frequency (Hz)





F20260629104252




BLK:12,SNR1: 2.0350 ,SNR2: 5.7121




K20260629104249





BLK:12,SNR1: 5.9921 ,SNR2: 10.384




3C138 2026/06/29 1.74UT FUJI -KISO



T20260629105625





BLK:19,SNR1: 6.8084 ,SNR2: 12.623




Frequency (Hz)

F20260629105625




BLK:19,SNR1: 4.0969 ,SNR2: 10.525





Frequency (Hz)


0531+194 2026/06/29 1.97UT TOYOKAWA-FUJI



T20260629105625





BLK:17,SNR1: 5.1950 ,SNR2: 19.145




Frequency (Hz)

K20260629105622




BLK:17,SNR1: 2.3916 ,SNR2: 5.7428





Frequency (Hz)


0531+194 2026/06/29 1.97UT TOYOKAWA-KISO



F20260629105625





BLK:10,SNR1: 1.8577 ,SNR2: 8.2497




Frequency (Hz)

K20260629105622




BLK:10,SNR1: 1.4121 ,SNR2: 7.5967





Frequency (Hz)


0531+194 2026/06/29 1.97UT FUJI -KISO



T20260629110447





BLK:21,SNR1: 20.020 ,SNR2: 90.330




Frequency (Hz)

3C147 2026/06/29 2.11UT TOYOKAWA-FUJI


F20260629110447





BLK:21,SNR1: 1.8306 ,SNR2: 5.9759




Frequency (Hz)



T20260629110447





BLK:37,SNR1: 18.806 ,SNR2: 88.824




Frequency (Hz)

K20260629110444




BLK:37,SNR1: 4.5952 ,SNR2: 17.468





Frequency (Hz)


3C147 2026/06/29 2.11UT TOYOKAWA-KISO



F20260629110447





BLK:27,SNR1: 1.6993 ,SNR2: 5.7140




Frequency (Hz)

3C147 2026/06/29 2.11UT FUJI -KISO


K20260629110444





BLK:27,SNR1: 5.0164 ,SNR2: 18.962




Frequency (Hz)



T20260629111256




BLK:15,SNR1: 14.584 ,SNR2: 25.791




Frequency (Hz)

F20260629111256




BLK:15,SNR1: 7.5605 ,SNR2: 18.666





Frequency (Hz)


0548+16 2026/06/29 2.24UT TOYOKAWA-FUJI



T20260629111256





BLK:18,SNR1: 8.9241 ,SNR2: 22.368




Frequency (Hz)

K20260629111253




BLK:18,SNR1: 2.4886 ,SNR2: 12.110




Frequency (Hz)


0548+16 2026/06/29 2.24UT TOYOKAWA-KISO



F20260629111256





BLK:10,SNR1: 7.9792 ,SNR2: 19.723




Frequency (Hz)

0548+16 2026/06/29 2.24UT FUJI -KISO


K20260629111253




BLK:10,SNR1: 16.762 ,SNR2: 40.271




Frequency (Hz)



T20260629111707





BLK: 8,SNR1: 8.6758 ,SNR2: 20.335




Frequency (Hz)

F20260629111707




BLK: 8,SNR1: 8.6967 ,SNR2: 15.216




Frequency (Hz)


0552+12 2026/06/29 2.31UT TOYOKAWA-FUJI



T20260629111707




BLK: 8,SNR1: 1.3669 ,SNR2: 3.3554




Frequency (Hz)

0552+12 2026/06/29 2.31UT TOYOKAWA-KISO


K20260629111704





BLK: 8,SNR1: 7.8450 ,SNR2: 19.670




Frequency (Hz)



F20260629111707





BLK: 2,SNR1: 8.4168 ,SNR2: 14.751




Frequency (Hz)

K20260629111704




BLK: 2,SNR1: 16.747 ,SNR2: 29.598





Frequency (Hz)


0552+12 2026/06/29 2.31UT FUJI -KISO



T20260629112134





BLK: 4,SNR1: 13.180 ,SNR2: 30.385




Frequency (Hz)

0556+191 2026/06/29 2.39UT TOYOKAWA-FUJI


F20260629112134





BLK: 4,SNR1: 14.126 ,SNR2: 34.488




Frequency (Hz)



T20260629112134





BLK: 5,SNR1: 9.7763 ,SNR2: 29.061




Frequency (Hz)

0556+191 2026/06/29 2.39UT TOYOKAWA-KISO


K20260629112131





BLK: 5,SNR1: 9.9336 ,SNR2: 24.835




Frequency (Hz)



F20260629112134





BLK: 4,SNR1: 7.9565 ,SNR2: 22.850




Frequency (Hz)

K20260629112131




BLK: 4,SNR1: 9.9031 ,SNR2: 24.662





Frequency (Hz)


0556+191 2026/06/29 2.39UT FUJI -KISO



T20260629112919





BLK: 6,SNR1: 0.12612 ,SNR2: 1.8277




Frequency (Hz)

F20260629112919




BLK: 6,SNR1: 6.2148 ,SNR2: 13.449





Frequency (Hz)


0605-08 2026/06/29 2.52UT TOYOKAWA-FUJI



T20260629112919




BLK: 6,SNR1: 0.68079E-01,SNR2: 1.4601





0605-08 2026/06/29 2.52UT TOYOKAWA-KISO


K20260629112916




BLK: 6,SNR1: 5.2237 ,SNR2: 9.3149




F20260629112919




BLK: 2,SNR1: 0.97751 ,SNR2: 4.1546




K20260629112916





BLK: 2,SNR1: 5.3130 ,SNR2: 12.826




0605-08 2026/06/29 2.52UT FUJI -KISO



T20260629114827





BLK:21,SNR1: 4.7609 ,SNR2: 6.6544




Frequency (Hz)

3C161 2026/06/29 2.84UT TOYOKAWA-FUJI


F20260629114827





BLK:21,SNR1: 2.1001 ,SNR2: 5.2085




Frequency (Hz)




T20260629114827




BLK:21,SNR1: 4.9944 ,SNR2: 6.4547




K20260629114824




BLK:21,SNR1: 3.5217 ,SNR2: 8.3942




3C161 2026/06/29 2.84UT TOYOKAWA-KISO



F20260629114827




BLK:10,SNR1: 1.2710 ,SNR2: 2.9643





3C161 2026/06/29 2.84UT FUJI -KISO



K20260629114824




BLK:10,SNR1: 1.5434 ,SNR2: 4.9983



T20260629121559





BLK: 3,SNR1: 6.1157 ,SNR2: 14.692




Frequency (Hz)

F20260629121559




BLK: 3,SNR1:-0.72305E-01,SNR2: 1.8451





Frequency (Hz)


0652-130 2026/06/29 3.29UT TOYOKAWA-FUJI



T20260629121559





BLK: 5,SNR1: 4.9317 ,SNR2: 12.115




Frequency (Hz)

0652-130 2026/06/29 3.29UT TOYOKAWA-KISO


K20260629121556





BLK: 5,SNR1: 5.8712 ,SNR2: 14.871




Frequency (Hz)



F20260629121559





BLK: 3,SNR1: 1.5557 ,SNR2: 3.5721




Frequency (Hz)

K20260629121556




BLK: 3,SNR1: 8.5496 ,SNR2: 21.484




Frequency (Hz)


0652-130 2026/06/29 3.29UT FUJI -KISO



T20260629122737




BLK: 1,SNR1: 0.29013 ,SNR2: 1.9329





0703+138 2026/06/29 3.49UT TOYOKAWA-FUJI


F20260629122737




BLK: 1,SNR1: 0.10833 ,SNR2: 0.76776



T20260629122737




BLK: 3,SNR1: 0.23072 ,SNR2: 2.5904





0703+138 2026/06/29 3.49UT TOYOKAWA-KISO


K20260629122734




BLK: 3,SNR1: 0.22266 ,SNR2: 1.1929




F20260629122737




BLK: 2,SNR1:-0.24460 ,SNR2: 1.4299




K20260629122734





BLK: 2,SNR1: 0.66743 ,SNR2: 3.6536




0703+138 2026/06/29 3.49UT FUJI -KISO



T20260629123659





BLK: 3,SNR1: 5.1263 ,SNR2: 13.210




Frequency (Hz)

0713-024 2026/06/29 3.64UT TOYOKAWA-FUJI


F20260629123659





BLK: 3,SNR1: 19.686 ,SNR2: 38.304




Frequency (Hz)



T20260629123659





BLK: 1,SNR1: 16.805 ,SNR2: 40.083




Frequency (Hz)

K20260629123656




BLK: 1,SNR1: 2.1042 ,SNR2: 10.107





Frequency (Hz)


0713-024 2026/06/29 3.64UT TOYOKAWA-KISO



F20260629123659





BLK: 2,SNR1: 19.774 ,SNR2: 39.597




Frequency (Hz)

K20260629123656




BLK: 2,SNR1: 9.4714 ,SNR2: 23.821





Frequency (Hz)


0713-024 2026/06/29 3.64UT FUJI -KISO



T20260629124711





BLK: 5,SNR1: 0.60528 ,SNR2: 5.2157





0723+10 2026/06/29 3.81UT TOYOKAWA-FUJI



F20260629124711




BLK: 5,SNR1: 1.6755 ,SNR2: 8.2601





T20260629124711




BLK: 6,SNR1: 0.49971 ,SNR2: 1.5652




K20260629124708





BLK: 6,SNR1: 1.1050 ,SNR2: 5.0403




0723+10 2026/06/29 3.81UT TOYOKAWA-KISO





F20260629124711




BLK: 4,SNR1: 10.590 ,SNR2: 25.978




K20260629124708





BLK: 4,SNR1: 9.4793 ,SNR2: 23.342




0723+10 2026/06/29 3.81UT FUJI -KISO



T20260629125727




BLK: 1,SNR1: 9.2168 ,SNR2: 22.697





0732+33 2026/06/29 3.99UT TOYOKAWA-FUJI



F20260629125727




BLK: 1,SNR1: 60.242 ,SNR2: 77.442




T20260629125727




No. Good Data




K20260629125724




No. Good Data




0732+33 2026/06/29 3.99UT TOYOKAWA-KISO



F20260629125727




BLK: 2,SNR1: 37.906 ,SNR2: 64.786





0732+33 2026/06/29 3.99UT FUJI -KISO


K20260629125724




BLK: 2,SNR1: 10.279 ,SNR2: 25.711




T20260629130527




BLK: 8,SNR1: 0.63826 ,SNR2: 4.5926




F20260629130527




BLK: 8,SNR1: 0.96508 ,SNR2: 3.4654




0741-06 2026/06/29 4.12UT TOYOKAWA-FUJI





T20260629130527




BLK:15,SNR1: 0.73936 ,SNR2: 2.4759




K20260629130524




BLK:15,SNR1: 0.94224 ,SNR2: 2.0053




0741-06 2026/06/29 4.12UT TOYOKAWA-KISO




F20260629130527




BLK: 7,SNR1:-0.12761 ,SNR2: 0.93057




K20260629130524





BLK: 7,SNR1: 0.95649 ,SNR2: 3.1582




0741-06 2026/06/29 4.12UT FUJI -KISO



T20260629131511




No. Good Data




Frequency (Hz)

F20260629131511




No. Good Data





Frequency (Hz)


0752-200 2026/06/29 4.28UT TOYOKAWA-FUJI



T20260629131511





No.Good Data




Frequency (Hz)

K20260629131508




No.Good Data




Frequency (Hz)


0752-200 2026/06/29 4.28UT TOYOKAWA-KISO





F20260629131511




BLK: 1,SNR1: 6.6200 ,SNR2: 20.374




K20260629131508





BLK: 1,SNR1: 8.2597 ,SNR2: 20.494




0752-200 2026/06/29 4.28UT FUJI -KISO





T20260629132247




No. Good Data




F20260629132247





No. Good Data




3C190 2026/06/29 4.41UT TOYOKAWA-FUJI



T20260629132247





BLK: 1, SNR1: 11.322 ,SNR2: 27.954




Frequency (Hz)

3C190 2026/06/29 4.41UT TOYOKAWA-KISO


K20260629132244




BLK: 1, SNR1: 13.370 ,SNR2: 23.532




Frequency (Hz)



F20260629132247




BLK: 3, SNR1: 8.4221 , SNR2: 20.759





3C190 2026/06/29 4.41UT FUJI -KISO



K20260629132244




BLK: 3, SNR1: 6.9054 , SNR2: 17.726



T20260629133513





BLK: 7, SNR1: 7.1607 , SNR2: 17.891





3C196 2026/06/29 4.62UT TOYOKAWA-FUJI



F20260629133513




BLK: 7, SNR1: 7.1053 , SNR2: 17.998



T20260629133513




BLK: 7, SNR1: 8.6677 ,SNR2: 21.534





3C196 2026/06/29 4.62UT TOYOKAWA-KISO



K20260629133510




BLK: 7, SNR1: 7.1577 ,SNR2: 17.997



F20260629133513




BLK: 3, SNR1: 10.939 , SNR2: 26.705





3C196 2026/06/29 4.62UT FUJI -KISO



K20260629133510




BLK: 3, SNR1: 8.6312 , SNR2: 21.445



T20260629134622





BLK: 3,SNR1: 9.5228 ,SNR2: 23.470





0821+394 2026/06/29 4.80UT TOYOKAWA-FUJI



F20260629134622




BLK: 3,SNR1: 13.122 ,SNR2: 32.399



T20260629134622




BLK: 4,SNR1: 9.5141 ,SNR2: 23.450





0821+394 2026/06/29 4.80UT TOYOKAWA-KISO



K20260629134619




BLK: 4,SNR1: 9.7276 ,SNR2: 23.906



F20260629134622




BLK: 2, SNR1: 23.329 ,SNR2: 44.027





0821+394 2026/06/29 4.80UT FUJI -KISO



K20260629134619




BLK: 2, SNR1: 11.622 ,SNR2: 28.120



T20260629135800





BLK: 2, SNR1: 2.1715 ,SNR2: 10.180





0834-19 2026/06/29 4.99UT TOYOKAWA-FUJI



F20260629135800




BLK: 2, SNR1: 7.5195 ,SNR2: 18.650



T20260629135800




BLK: 2, SNR1: 6.1802 ,SNR2: 20.172





0834-19 2026/06/29 4.99UT TOYOKAWA-KISO



K20260629135757




BLK: 2, SNR1: 1.1905 ,SNR2: 6.4095



F20260629135800




BLK: 2, SNR1: 9.4099 , SNR2: 23.444





0834-19 2026/06/29 4.99UT FUJI -KISO



K20260629135757




BLK: 2, SNR1: 40.209 , SNR2: 52.358




T20260629140306




BLK: 3,SNR1: 0.85292E-01,SNR2: 1.7508




F20260629140306





BLK: 3,SNR1:-0.14496 ,SNR2: 1.0848




0839-071 2026/06/29 5.08UT TOYOKAWA-FUJI





T20260629140306




BLK: 3,SNR1: 0.17239 ,SNR2: 0.86107




K20260629140303




BLK: 3,SNR1: 1.2549 ,SNR2: 2.5520




0839-071 2026/06/29 5.08UT TOYOKAWA-KISO





F20260629140306




BLK: 5,SNR1: 0.84860 ,SNR2: 2.8866




K20260629140303




BLK: 5,SNR1: 2.0600 ,SNR2: 6.2619




0839-071 2026/06/29 5.08UT FUJI -KISO



T20260629141408





BLK: 1,SNR1: 0.44699 ,SNR2: 2.5407





3C208 2026/06/29 5.26UT TOYOKAWA-FUJI



F20260629141408




BLK: 1,SNR1: 1.4296 ,SNR2: 6.9828





T20260629141408




No. Good Data




K20260629141405





No. Good Data




3C208 2026/06/29 5.26UT TOYOKAWA-KISO



F20260629141408





BLK: 2,SNR1: 19.352 ,SNR2: 41.805




Frequency (Hz)

3C208 2026/06/29 5.26UT FUJI -KISO


K20260629141405




BLK: 2,SNR1: 4.2560 ,SNR2: 12.169




Frequency (Hz)



T20260629143050




BLK: 4,SNR1: 5.1516 ,SNR2: 13.118





3C216 2026/06/29 5.54UT TOYOKAWA-FUJI


F20260629143050




BLK: 4,SNR1: 8.2186 ,SNR2: 20.333




T20260629143050




BLK: 2,SNR1: 2.6659 ,SNR2: 6.9032




K20260629143047





BLK: 2,SNR1: 9.3758 ,SNR2: 16.258




3C216 2026/06/29 5.54UT TOYOKAWA-KISO





F20260629143050




No.Good Data




K20260629143047





No.Good Data




3C216 2026/06/29 5.54UT FUJI -KISO





T20260629144300




No. Good Data




F20260629144300




No. Good Data




0919-142 2026/06/29 5.74UT TOYOKAWA-FUJI



T20260629144300





BLK: 1,SNR1: 10.836 ,SNR2: 26.896




0919-142 2026/06/29 5.74UT TOYOKAWA-KISO


K20260629144257





BLK: 1,SNR1: 8.7237 ,SNR2: 21.758




Frequency (Hz)





F20260629144300




No. Good Data




K20260629144257





No. Good Data




0919-142 2026/06/29 5.74UT FUJI -KISO





T20260629144939




BLK: 6,SNR1: 0.22117E-01,SNR2: 0.80348




F20260629144939





BLK: 6,SNR1: 0.45186 ,SNR2: 1.7802




0926+117 2026/06/29 5.86UT TOYOKAWA-FUJI





T20260629144939




BLK: 2,SNR1: 0.21048 ,SNR2: 0.76366




K20260629144936





BLK: 2,SNR1: 0.53754 ,SNR2: 1.0307




0926+117 2026/06/29 5.86UT TOYOKAWA-KISO





F20260629144939




BLK: 3,SNR1: 1.0586 ,SNR2: 6.1176




K20260629144936





BLK: 3,SNR1: 0.52366 ,SNR2: 1.7711




0926+117 2026/06/29 5.86UT FUJI -KISO





T20260629145724




No.Good Data




F20260629145724





No.Good Data




3C222 2026/06/29 5.98UT TOYOKAWA-FUJI





T20260629145724




No.Good Data




K20260629145721




No.Good Data




3C222 2026/06/29 5.98UT TOYOKAWA-KISO



F20260629145724




BLK: 1,SNR1: 1.0402 ,SNR2: 4.3136





3C222 2026/06/29 5.98UT FUJI -KISO



K20260629145721




BLK: 1,SNR1: 7.4101 ,SNR2: 18.678



T20260629150424





No. Good Data





0941-08 2026/06/29 6.10UT TOYOKAWA-FUJI



F20260629150424




No. Good Data



T20260629150424




BLK: 2,SNR1: 3.7853 ,SNR2: 9.8081





0941-08 2026/06/29 6.10UT TOYOKAWA-KISO



K20260629150421




BLK: 2,SNR1: 5.1271 ,SNR2: 16.389



F20260629150424





No.Good Data




Frequency (Hz)

K20260629150421




No.Good Data




Frequency (Hz)


0941-08 2026/06/29 6.10UT FUJI -KISO




T20260629151246




BLK: 5,SNR1: 11.326 ,SNR2: 27.720




F20260629151246




BLK: 5,SNR1: 9.1459 ,SNR2: 22.232




3C230 2026/06/29 6.24UT TOYOKAWA-FUJI



T20260629151246




BLK: 3,SNR1: 18.626 ,SNR2: 33.179





3C230 2026/06/29 6.24UT TOYOKAWA-KISO


K20260629151243




BLK: 3,SNR1: 10.480 ,SNR2: 25.779



F20260629151246




BLK: 6,SNR1: 11.546 ,SNR2: 27.943




Frequency (Hz)

3C230 2026/06/29 6.24UT FUJI -KISO


K20260629151243





BLK: 6,SNR1: 9.4187 ,SNR2: 23.195




Frequency (Hz)




T20260629152846




BLK:13,SNR1: 4.9317 ,SNR2: 8.5992




F20260629152846





BLK:13,SNR1: 1.6171 ,SNR2: 5.9519




3C237 2026/06/29 6.51UT TOYOKAWA-FUJI





T20260629152846




BLK:12,SNR1: 5.4084 ,SNR2: 9.4189




K20260629152843




BLK:12,SNR1: 11.279 ,SNR2: 19.809




3C237 2026/06/29 6.51UT TOYOKAWA-KISO



F20260629152846





BLK:15,SNR1: 1.2680 ,SNR2: 4.7570





3C237 2026/06/29 6.51UT FUJI -KISO


K20260629152843




BLK:15,SNR1: 10.888 ,SNR2: 19.120



T20260629153503





BLK: 3,SNR1: 7.2225 ,SNR2: 21.142




1011+110 2026/06/29 6.61UT TOYOKAWA-FUJI


F20260629153503





BLK: 3,SNR1: 7.2396 ,SNR2: 21.243




Frequency (Hz)



T20260629153503





BLK: 3,SNR1: 7.6004 ,SNR2: 22.083




Frequency (Hz)

K20260629153500




BLK: 3,SNR1: 7.8312 ,SNR2: 23.719





Frequency (Hz)


1011+110 2026/06/29 6.61UT TOYOKAWA-KISO



F20260629153503




BLK: 4,SNR1: 10.904 ,SNR2: 29.078





1011+110 2026/06/29 6.61UT FUJI -KISO


K20260629153500




BLK: 4,SNR1: 8.4868 ,SNR2: 25.329




T20260629154244




BLK:11,SNR1: 0.54597 ,SNR2: 1.1766




F20260629154244





BLK:11,SNR1: 0.14167 ,SNR2: 2.0836




3C241 2026/06/29 6.74UT TOYOKAWA-FUJI





T20260629154244




BLK: 7,SNR1: 0.38206 ,SNR2: 2.1723




K20260629154241




BLK: 7,SNR1: 0.11019 ,SNR2: 1.5188




3C241 2026/06/29 6.74UT TOYOKAWA-KISO



F20260629154244




BLK: 8,SNR1: 0.64802 ,SNR2: 2.7570





3C241 2026/06/29 6.74UT FUJI -KISO



K20260629154241




BLK: 8,SNR1: 0.21634 ,SNR2: 0.88286



T20260629155413





BLK: 7,SNR1: 0.19015 ,SNR2: 2.3653




Frequency (Hz)

F20260629155413




BLK: 7,SNR1:-0.94515E-01,SNR2: 1.3402




Frequency (Hz)


1031-11 2026/06/29 6.93UT TOYOKAWA-FUJI




T20260629155413




BLK:23,SNR1: 0.61586 ,SNR2: 2.4469




K20260629155410




BLK:23,SNR1: 2.1019 ,SNR2: 6.6478




1031-11 2026/06/29 6.93UT TOYOKAWA-KISO





F20260629155413




BLK:11,SNR1: 1.0882 ,SNR2: 6.7728




K20260629155410




BLK:11,SNR1: 3.0303 ,SNR2: 6.1010




1031-11 2026/06/29 6.93UT FUJI -KISO




T20260629155846




BLK:15,SNR1: 20.009 ,SNR2: 45.271




F20260629155846




BLK:15,SNR1: 14.250 ,SNR2: 25.680




1035-058 2026/06/29 7.01UT TOYOKAWA-FUJI




T20260629155846




BLK:10,SNR1: 12.482 ,SNR2: 28.333




K20260629155843




BLK:10,SNR1: 4.5124 ,SNR2: 10.919




1035-058 2026/06/29 7.01UT TOYOKAWA-KISO





F20260629155846




BLK: 4,SNR1: 15.865 ,SNR2: 28.810




K20260629155843





BLK: 4,SNR1: 5.5040 ,SNR2: 13.141




1035-058 2026/06/29 7.01UT FUJI -KISO





T20260629160759




BLK: 5,SNR1: 9.8395 ,SNR2: 24.175




F20260629160759




BLK: 5,SNR1: 9.1906 ,SNR2: 22.377




1044-008 2026/06/29 7.16UT TOYOKAWA-FUJI





T20260629160759




BLK: 4,SNR1: 10.567 ,SNR2: 25.892




K20260629160756





BLK: 4,SNR1: 7.9969 ,SNR2: 19.698




1044-008 2026/06/29 7.16UT TOYOKAWA-KISO





F20260629160759




BLK: 5,SNR1: 9.2264 ,SNR2: 22.775




K20260629160756




BLK: 5,SNR1: 16.202 ,SNR2: 28.609




1044-008 2026/06/29 7.16UT FUJI -KISO



T20260629161903





BLK: 7,SNR1: 10.495 ,SNR2: 25.447





1055+01 2026/06/29 7.35UT TOYOKAWA-FUJI


F20260629161903




BLK: 7,SNR1: 12.688 ,SNR2: 21.474




T20260629161903




BLK: 5,SNR1: 9.8420 ,SNR2: 23.887




K20260629161900




BLK: 5,SNR1: 8.6230 ,SNR2: 21.568




1055+01 2026/06/29 7.35UT TOYOKAWA-KISO



F20260629161903




BLK: 7,SNR1: 19.103 ,SNR2: 36.471





1055+01 2026/06/29 7.35UT FUJI -KISO



K20260629161900




BLK: 7,SNR1: 8.6754 ,SNR2: 21.672




T20260629163021




BLK: 5,SNR1: 4.2625 ,SNR2: 15.306




F20260629163021





BLK: 5,SNR1: 5.0346 ,SNR2: 17.647




1107+109 2026/06/29 7.53UT TOYOKAWA-FUJI




T20260629163021




No.Good Data




K20260629163018





No.Good Data




1107+109 2026/06/29 7.53UT TOYOKAWA-KISO





F20260629163021




No.Good Data




K20260629163018




No.Good Data




1107+109 2026/06/29 7.53UT FUJI -KISO



T20260629163958




BLK: 2,SNR1: 9.9771 ,SNR2: 24.471





3C255 2026/06/29 7.69UT TOYOKAWA-FUJI



F20260629163958




BLK: 2,SNR1: 14.453 ,SNR2: 34.723



T20260629163958





BLK: 1,SNR1: 11.754 ,SNR2: 28.754




Frequency (Hz)

3C255 2026/06/29 7.69UT TOYOKAWA-KISO


K20260629163955




BLK: 1,SNR1: 8.4773 ,SNR2: 21.262




Frequency (Hz)





F20260629163958




BLK: 1,SNR1: 11.708 ,SNR2: 28.713




K20260629163955




BLK: 1,SNR1: 11.842 ,SNR2: 29.103




3C255 2026/06/29 7.69UT FUJI -KISO




T20260629170356




BLK: 5,SNR1: 14.237 ,SNR2: 34.698




F20260629170356




BLK: 5,SNR1: 12.014 ,SNR2: 29.060




3C263.1 2026/06/29 8.09UT TOYOKAWA-FUJI




T20260629170356




BLK: 3,SNR1: 12.439 ,SNR2: 30.011




K20260629170353




BLK: 3,SNR1: 11.050 ,SNR2: 26.758




3C263.1 2026/06/29 8.09UT TOYOKAWA-KISO



F20260629170356




BLK: 5,SNR1: 13.010 ,SNR2: 31.397





3C263.1 2026/06/29 8.09UT FUJI -KISO



K20260629170353




BLK: 5,SNR1: 9.8241 ,SNR2: 23.893





T20260629171023




BLK:10,SNR1: 0.71277 ,SNR2: 1.9650




F20260629171023





BLK:10,SNR1: 1.7387 ,SNR2: 4.3674




3C267 2026/06/29 8.20UT TOYOKAWA-FUJI





T20260629171023




BLK:14,SNR1: 0.61689 ,SNR2: 2.0214




K20260629171020




BLK:14,SNR1: 6.0866 ,SNR2: 15.569




3C267 2026/06/29 8.20UT TOYOKAWA-KISO





F20260629171023




BLK: 9,SNR1: 2.1126 ,SNR2: 5.3409




K20260629171020




BLK: 9,SNR1: 6.6447 ,SNR2: 17.010




3C267 2026/06/29 8.20UT FUJI -KISO





T20260629172937




BLK: 7,SNR1: 7.0058 ,SNR2: 20.643




F20260629172937





BLK: 7,SNR1: 9.1379 ,SNR2: 23.822




1206+439 2026/06/29 8.52UT TOYOKAWA-FUJI




T20260629172937




BLK: 5,SNR1: 2.1023 ,SNR2: 5.6694




K20260629172934





BLK: 5,SNR1: 8.7473 ,SNR2: 26.443




1206+439 2026/06/29 8.52UT TOYOKAWA-KISO




F20260629172937




BLK: 4,SNR1: 12.814 ,SNR2: 32.954



K20260629172934



BLK: 4,SNR1: 7.8855 ,SNR2: 20.727



1206+439 2026/06/29 8.52UT FUJI -KISO

