




T20260702055130





BLK: 4,SNR1: 17.288 ,SNR2: 33.770




Frequency (Hz)

F20260702055130




BLK: 4,SNR1: 18.787 ,SNR2: 33.496





Frequency (Hz)


0038+328 2026/07/01 20.89UT TOYOKAWA-FUJI





T20260702055130




No.Good Data




K20260702055127





No.Good Data




0038+328 2026/07/01 20.89UT TOYOKAWA-KISO



F20260702055130





BLK: 3, SNR1: 34.955 , SNR2: 60.727




Frequency (Hz)

K20260702055127




BLK: 3, SNR1: 18.475 , SNR2: 35.718





Frequency (Hz)


0038+328 2026/07/01 20.89UT FUJI -KISO



T20260702060623





BLK: 6,SNR1: 2.4878 ,SNR2: 7.8262




Frequency (Hz)

F20260702060623




BLK: 6,SNR1: 3.4287 ,SNR2: 10.255





Frequency (Hz)


0053+261 2026/07/01 21.13UT TOYOKAWA-FUJI



T20260702060623





BLK: 4,SNR1: 5.8134 ,SNR2: 12.901




Frequency (Hz)

K20260702060620




BLK: 4,SNR1: 5.9646 ,SNR2: 10.595




Frequency (Hz)


0053+261 2026/07/01 21.13UT TOYOKAWA-KISO



F20260702060623




BLK: 1,SNR1: 3.1495 ,SNR2: 9.7176




Frequency (Hz)

K20260702060620




BLK: 1,SNR1: 3.6245 ,SNR2: 10.608





Frequency (Hz)


0053+261 2026/07/01 21.13UT FUJI -KISO



T20260702062255





BLK: 1,SNR1: 10.271 ,SNR2: 25.289




Frequency (Hz)

F20260702062255




BLK: 1,SNR1: 10.919 ,SNR2: 26.891





Frequency (Hz)


0109+416 2026/07/01 21.41UT TOYOKAWA-FUJI





T20260702062255




No.Good Data




K20260702062252





No.Good Data




0109+416 2026/07/01 21.41UT TOYOKAWA-KISO



F20260702062255





BLK: 4, SNR1: 9.6555 , SNR2: 22.407




Frequency (Hz)

K20260702062252




BLK: 4, SNR1: 9.3846 , SNR2: 22.815





Frequency (Hz)


0109+416 2026/07/01 21.41UT FUJI -KISO



T20260702063400





BLK: 1,SNR1: 10.188 ,SNR2: 25.097




Frequency (Hz)

F20260702063400




BLK: 1,SNR1: 12.869 ,SNR2: 31.032





Frequency (Hz)


0120+405 2026/07/01 21.59UT TOYOKAWA-FUJI



T20260702063400





BLK: 3,SNR1: 25.350 ,SNR2: 46.190




Frequency (Hz)

K20260702063357




BLK: 3,SNR1: 12.482 ,SNR2: 30.134





Frequency (Hz)


0120+405 2026/07/01 21.59UT TOYOKAWA-KISO



F20260702063400





BLK: 4,SNR1: 8.6507 ,SNR2: 21.384




Frequency (Hz)

K20260702063357




BLK: 4,SNR1: 25.398 ,SNR2: 45.495





Frequency (Hz)


0120+405 2026/07/01 21.59UT FUJI -KISO



T20260702064138





No.Good Data




Frequency (Hz)

F20260702064138




No.Good Data





Frequency (Hz)


0128+03 2026/07/01 21.72UT TOYOKAWA-FUJI



T20260702064138





BLK: 2,SNR1: 9.7321 ,SNR2: 16.594




Frequency (Hz)

K20260702064136




BLK: 2,SNR1: 9.4900 ,SNR2: 20.104





Frequency (Hz)


0128+03 2026/07/01 21.72UT TOYOKAWA-KISO



F20260702064138





BLK: 1,SNR1: 6.9878 ,SNR2: 20.864




Frequency (Hz)

K20260702064136




BLK: 1,SNR1: 6.7954 ,SNR2: 17.960





Frequency (Hz)


0128+03 2026/07/01 21.72UT FUJI -KISO



T20260702064812





BLK: 2,SNR1: 1.3750 ,SNR2: 6.3010




Frequency (Hz)

3C48 2026/07/01 21.83UT TOYOKAWA-FUJI


F20260702064812





BLK: 2,SNR1: 9.0914 ,SNR2: 22.395




Frequency (Hz)



T20260702064812




BLK: 7,SNR1: 3.7813 ,SNR2: 9.0798




Frequency (Hz)

3C48 2026/07/01 21.83UT TOYOKAWA-KISO


K20260702064809





BLK: 7,SNR1: 15.330 ,SNR2: 27.783




Frequency (Hz)



F20260702064812





BLK: 1,SNR1: 5.0185 ,SNR2: 16.921




Frequency (Hz)

3C48 2026/07/01 21.83UT FUJI -KISO


K20260702064809





BLK: 1,SNR1: 10.042 ,SNR2: 24.671




Frequency (Hz)



T20260702070756





No.Good Data




Frequency (Hz)

F20260702070756




No.Good Data





Frequency (Hz)


0155-109 2026/07/01 22.16UT TOYOKAWA-FUJI



T20260702070756





BLK: 1,SNR1: 18.570 ,SNR2: 33.006




Frequency (Hz)

0155-109 2026/07/01 22.16UT TOYOKAWA-KISO


K20260702070753





BLK: 1,SNR1: 8.2070 ,SNR2: 21.419




Frequency (Hz)



F20260702070756





BLK: 2,SNR1: 24.382 ,SNR2: 42.934




Frequency (Hz)

K20260702070753




BLK: 2,SNR1: 9.5720 ,SNR2: 24.191





Frequency (Hz)


0155-109 2026/07/01 22.16UT FUJI -KISO



T20260702071504





BLK: 2,SNR1: 0.91023 ,SNR2: 4.9002




Frequency (Hz)

F20260702071504




BLK: 2,SNR1: 13.418 ,SNR2: 40.280





Frequency (Hz)


0202+15 2026/07/01 22.28UT TOYOKAWA-FUJI



T20260702071504





BLK: 2,SNR1: 5.3045 ,SNR2: 6.7519




Frequency (Hz)

0202+15 2026/07/01 22.28UT TOYOKAWA-KISO


K20260702071501




BLK: 2,SNR1: 14.073 ,SNR2: 41.288




Frequency (Hz)




F20260702071504




No.Good Data




K20260702071501





No.Good Data




0202+15 2026/07/01 22.28UT FUJI -KISO



T20260702072654





BLK: 8,SNR1: 20.748 ,SNR2: 23.912




Frequency (Hz)

F20260702072654




BLK: 8,SNR1: 8.9132 ,SNR2: 16.005





Frequency (Hz)


0213+178 2026/07/01 22.48UT TOYOKAWA-FUJI



T20260702072654





BLK:14,SNR1: 11.875 ,SNR2: 18.689




Frequency (Hz)

K20260702072651




BLK:14,SNR1: 2.3518 ,SNR2: 7.6623





Frequency (Hz)


0213+178 2026/07/01 22.48UT TOYOKAWA-KISO



F20260702072654





BLK:11,SNR1: 8.9144 ,SNR2: 16.007




Frequency (Hz)

K20260702072651




BLK:11,SNR1: 2.3455 ,SNR2: 7.6467





Frequency (Hz)


0213+178 2026/07/01 22.48UT FUJI -KISO





T20260702073437




No.Good Data




F20260702073437





No.Good Data




3C67 2026/07/01 22.61UT TOYOKAWA-FUJI





T20260702073437




No.Good Data




K20260702073434





No.Good Data




3C67 2026/07/01 22.81UT TOYOKAWA-KISO



F20260702073437





BLK: 1,SNR1: 10.323 ,SNR2: 25.395




Frequency (Hz)

3C67 2026/07/01 22.61UT FUJI -KISO


K20260702073434




BLK: 1,SNR1: 3.9284 ,SNR2: 17.129




Frequency (Hz)



T20260702075251





BLK: 5,SNR1: 1.9113 ,SNR2: 4.5164




Frequency (Hz)

3C71 2026/07/01 22.91UT TOYOKAWA-FUJI


F20260702075251





BLK: 5,SNR1: 17.823 ,SNR2: 26.413




Frequency (Hz)



T20260702075251





BLK: 5,SNR1: 8.9218 ,SNR2: 19.818




Frequency (Hz)

3C71 2026/07/01 22.91UT TOYOKAWA-KISO


K20260702075248





BLK: 5,SNR1: 9.0178 ,SNR2: 16.158




Frequency (Hz)



F20260702075251





BLK: 6,SNR1: 17.759 ,SNR2: 26.318




Frequency (Hz)

3C71 2026/07/01 22.91UT FUJI -KISO


K20260702075248





BLK: 6,SNR1: 8.2296 ,SNR2: 14.431




Frequency (Hz)



T20260702081207





BLK:30,SNR1: 0.61340 ,SNR2: 1.7381




Frequency (Hz)

F20260702081207




BLK:30,SNR1: 3.5829 ,SNR2: 6.1830





Frequency (Hz)


0258+350 2026/07/01 23.23UT TOYOKAWA-FUJI



T20260702081207





BLK:30,SNR1: 0.55087 ,SNR2: 1.5942




Frequency (Hz)

K20260702081204




BLK:30,SNR1: 4.7384 ,SNR2: 9.4441




Frequency (Hz)


0258+350 2026/07/01 23.23UT TOYOKAWA-KISO





F20260702081207




BLK:30,SNR1: 2.9030 ,SNR2: 8.3265




K20260702081204





BLK:30,SNR1: 4.5905 ,SNR2: 10.848




0258+350 2026/07/01 23.23UT FUJI -KISO



T20260702082156





BLK: 2,SNR1: 22.474 ,SNR2: 40.648




Frequency (Hz)

F20260702082156




BLK: 2,SNR1: 11.478 ,SNR2: 27.836





Frequency (Hz)


0308+305 2026/07/01 23.39UT TOYOKAWA-FUJI



T20260702082156





BLK: 3,SNR1: 18.849 ,SNR2: 32.918




Frequency (Hz)

K20260702082153




BLK: 3,SNR1: 16.498 ,SNR2: 29.110





Frequency (Hz)


0308+305 2026/07/01 23.39UT TOYOKAWA-KISO





F20260702082156




BLK: 4,SNR1: 8.9117 ,SNR2: 21.798




K20260702082153





BLK: 4,SNR1: 8.4357 ,SNR2: 20.918




0308+305 2026/07/01 23.39UT FUJI -KISO



T20260702083327




BLK:18,SNR1: 7.6054 ,SNR2: 23.564




Frequency (Hz)

F20260702083327




BLK:18,SNR1: 9.4810 ,SNR2: 27.875





Frequency (Hz)


0320+05 2026/07/01 23.59UT TOYOKAWA-FUJI



T20260702083327





BLK:26,SNR1: 8.7150 ,SNR2: 25.723




Frequency (Hz)

0320+05 2026/07/01 23.59UT TOYOKAWA-KISO


K20260702083324





BLK:26,SNR1: 8.5695 ,SNR2: 26.393




Frequency (Hz)





F20260702083327




BLK:22,SNR1: 9.7324 ,SNR2: 25.106




K20260702083324





BLK:22,SNR1: 8.8767 ,SNR2: 22.651




0320+05 2026/07/01 23.59UT FUJI -KISO





T20260702084649




BLK: 4,SNR1: 4.8085 ,SNR2: 13.137




F20260702084649





BLK: 4,SNR1: 5.2983 ,SNR2: 19.106




0333+32 2026/07/01 23.81UT TOYOKAWA-FUJI



T20260702084649





BLK:11,SNR1: 3.4100 ,SNR2: 10.605




Frequency (Hz)

0333+32 2026/07/01 23.81UT TOYOKAWA-KISO


K20260702084647





BLK:11,SNR1: 17.487 ,SNR2: 21.218




Frequency (Hz)



F20260702084649





BLK: 2,SNR1: 4.4823 ,SNR2: 16.765




Frequency (Hz)

0333+32 2026/07/01 23.81UT FUJI -KISO


K20260702084647





BLK: 2,SNR1: 5.7720 ,SNR2: 21.047




Frequency (Hz)





T20260702085403




BLK: 2,SNR1: 0.68029E-01,SNR2: 0.66073




F20260702085403





BLK: 2,SNR1:-0.76325E-01,SNR2: 2.5236




0341+065 2026/07/01 23.93UT TOYOKAWA-FUJI



T20260702085403




BLK: 1,SNR1: 0.33320 ,SNR2: 1.5765





0341+065 2026/07/01 23.93UT TOYOKAWA-KISO


K20260702085400




BLK: 1,SNR1: 6.0881 ,SNR2: 15.392




F20260702085403




BLK: 6,SNR1: 20.389 ,SNR2: 43.313




K20260702085400




BLK: 6,SNR1: 18.420 ,SNR2: 43.527




0341+065 2026/07/01 23.93UT FUJI -KISO




T20260702091524




BLK: 6,SNR1: 10.566 ,SNR2: 23.725




F20260702091524




BLK: 6,SNR1: 4.1162 ,SNR2: 10.730




0403-132 2026/07/02 0.28UT TOYOKAWA-FUJI





T20260702091524




BLK: 1,SNR1: 1.8467 ,SNR2: 6.1622




K20260702091521





BLK: 1,SNR1: 10.558 ,SNR2: 26.662




0403-132 2026/07/02 0.28UT TOYOKAWA-KISO





F20260702091524




No.Good Data




K20260702091521





No.Good Data




0403-132 2026/07/02 0.28UT FUJI -KISO



T20260702092435




BLK: 5, SNR1: 12.902 ,SNR2: 30.340





0411+05 2026/07/02 0.44UT TOYOKAWA-FUJI



F20260702092435




BLK: 5, SNR1: 12.718 ,SNR2: 31.115



T20260702092435




BLK: 5, SNR1: 13.646 , SNR2: 31.626





0411+05 2026/07/02 0.44UT TOYOKAWA-KISO


K20260702092432




BLK: 5, SNR1: 7.6535 , SNR2: 20.666




F20260702092435




BLK: 4, SNR1: 8.7651 ,SNR2: 26.138




K20260702092432




BLK: 4, SNR1: 7.9484 ,SNR2: 23.688




0411+05 2026/07/02 0.44UT FUJI -KISO



T20260702093130





BLK: 1,SNR1: 5.7275 ,SNR2: 14.430





0418+236 2026/07/02 0.55UT TOYOKAWA-FUJI


F20260702093130




BLK: 1,SNR1: 18.136 ,SNR2: 33.007



T20260702093130




BLK: 5,SNR1: 7.8829 ,SNR2: 14.124





0418+236 2026/07/02 0.55UT TOYOKAWA-KISO



K20260702093127




BLK: 5,SNR1: 9.2405 ,SNR2: 16.505





F20260702093130




BLK: 2,SNR1:-0.21745E-01,SNR2: 3.7909




K20260702093127





BLK: 2,SNR1: 9.1473 ,SNR2: 15.892




0418+236 2026/07/02 0.55UT FUJI -KISO





T20260702094258




BLK:18,SNR1: 2.2467 ,SNR2: 6.7671




F20260702094258




BLK:18,SNR1: 1.4494 ,SNR2: 4.3417




3C119 2026/07/02 0.74UT TOYOKAWA-FUJI



T20260702094258





BLK:22,SNR1: 1.7325 ,SNR2: 7.9783





3C119 2026/07/02 0.74UT TOYOKAWA-KISO


K20260702094255




BLK:22,SNR1: 1.6316 ,SNR2: 4.6692




F20260702094258




BLK:14,SNR1: 1.0582 ,SNR2: 3.5866




K20260702094255





BLK:14,SNR1: 0.76534 ,SNR2: 3.0785




3C119 2026/07/02 0.74UT FUJI -KISO



T20260702103104





BLK: 2, SNR1: 16.218 , SNR2: 36.006




Frequency (Hz)

3C138 2026/07/02 1.55UT TOYOKAWA-FUJI


F20260702103104





BLK: 2, SNR1: 15.689 , SNR2: 33.492




Frequency (Hz)



T20260702103104




BLK: 4,SNR1: 10.812 ,SNR2: 25.568





3C138 2026/07/02 1.55UT TOYOKAWA-KISO


K20260702103101




BLK: 4,SNR1: 9.4952 ,SNR2: 24.979



F20260702103104




BLK: 3,SNR1: 20.722 ,SNR2: 36.738





3C138 2026/07/02 1.55UT FUJI -KISO


K20260702103101




BLK: 3,SNR1: 15.786 ,SNR2: 35.737



T20260702104438




BLK:30,SNR1: 11.119 ,SNR2: 19.649





0531+194 2026/07/02 1.77UT TOYOKAWA-FUJI


F20260702104438




BLK:30,SNR1: 83.600 ,SNR2: 118.67




T20260702104438




BLK:32,SNR1: 10.929 ,SNR2: 19.311




K20260702104435




BLK:32,SNR1: 8.6037 ,SNR2: 15.113




0531+194 2026/07/02 1.77UT TOYOKAWA-KISO




F20260702104438




BLK:26,SNR1: 89.310 ,SNR2: 125.89




K20260702104435




BLK:26,SNR1: 11.673 ,SNR2: 15.386




0531+194 2026/07/02 1.77UT FUJI -KISO



T20260702105259




BLK: 5,SNR1: 44.069 ,SNR2: 77.853





3C147 2026/07/02 1.91UT TOYOKAWA-FUJI


F20260702105259




BLK: 5,SNR1: 12.121 ,SNR2: 21.812




T20260702105259




BLK:12,SNR1: 32.990 ,SNR2: 59.426




K20260702105256




BLK:12,SNR1: 15.203 ,SNR2: 34.327




3C147 2026/07/02 1.91UT TOYOKAWA-KISO



F20260702105259




BLK: 4,SNR1: 14.020 ,SNR2: 24.915





3C147 2026/07/02 1.91UT FUJI -KISO


K20260702105256




BLK: 4,SNR1: 15.256 ,SNR2: 27.236



T20260702110109




BLK:21,SNR1: 1.1412 ,SNR2: 5.4023





0548+16 2026/07/02 2.05UT TOYOKAWA-FUJI


F20260702110109




BLK:21,SNR1: 7.0389 ,SNR2: 12.958





T20260702110109




BLK:18,SNR1: 1.2929 ,SNR2: 5.8047




K20260702110106




BLK:18,SNR1: 4.6316 ,SNR2: 9.0059




0548+16 2026/07/02 2.05UT TOYOKAWA-KISO




F20260702110109




BLK:22,SNR1: 6.0459 ,SNR2: 12.839




K20260702110106




BLK:22,SNR1: 5.6751 ,SNR2: 8.2229




0548+16 2026/07/02 2.05UT FUJI -KISO



T20260702110519




BLK:17,SNR1: 7.2936 ,SNR2: 20.585





0552+12 2026/07/02 2.12UT TOYOKAWA-FUJI


F20260702110519




BLK:17,SNR1: 7.9247 ,SNR2: 12.014



T20260702110519




BLK:14,SNR1: 2.0666 ,SNR2: 5.1431




0552+12 2026/07/02 2.12UT TOYOKAWA-KISO


K20260702110516




BLK:14,SNR1: 2.0313 ,SNR2: 6.1370




Frequency (Hz)




F20260702110519




BLK:21,SNR1: 7.6927 ,SNR2: 13.857




K20260702110516




BLK:21,SNR1: 1.9288 ,SNR2: 6.2991




0552+12 2026/07/02 2.12UT FUJI -KISO




T20260702110946




BLK:35,SNR1: 17.005 ,SNR2: 22.003




F20260702110946




BLK:35,SNR1: 53.660 ,SNR2: 59.209




0556+191 2026/07/02 2.19UT TOYOKAWA-FUJI




T20260702110946




BLK:26,SNR1: 13.565 ,SNR2: 17.440




K20260702110943




BLK:26,SNR1: 18.871 ,SNR2: 33.852




0556+191 2026/07/02 2.19UT TOYOKAWA-KISO





F20260702110946




BLK:21,SNR1: 58.266 ,SNR2: 65.712




K20260702110943





BLK:21,SNR1: 6.6591 ,SNR2: 18.095




0556+191 2026/07/02 2.19UT FUJI -KISO



T20260702111731





BLK: 6,SNR1: 6.4960 ,SNR2: 16.564





0605-08 2026/07/02 2.32UT TOYOKAWA-FUJI



F20260702111731




BLK: 6,SNR1: 6.8910 ,SNR2: 12.629





T20260702111731




BLK: 3,SNR1: 7.1156 ,SNR2: 12.777




K20260702111728





BLK: 3,SNR1: 6.3353 ,SNR2: 16.583




0605-08 2026/07/02 2.32UT TOYOKAWA-KISO





F20260702111731




BLK: 6,SNR1: 15.754 ,SNR2: 27.333




K20260702111728




BLK: 6,SNR1: 16.427 ,SNR2: 28.860




0605-08 2026/07/02 2.32UT FUJI -KISO




T20260702113639




BLK:39,SNR1: 320.27 ,SNR2: 314.09




F20260702113639




BLK:39,SNR1: 21.438 ,SNR2: 23.024




3C161 2026/07/02 2.64UT TOYOKAWA-FUJI




T20260702113639




BLK:37,SNR1: 326.65 ,SNR2: 320.34




K20260702113636




BLK:37,SNR1: 18.600 ,SNR2: 24.350




3C161 2026/07/02 2.64UT TOYOKAWA-KISO




F20260702113639




BLK:38,SNR1: 22.411 ,SNR2: 23.939




K20260702113636




BLK:38,SNR1: 18.605 ,SNR2: 24.360




3C161 2026/07/02 2.64UT FUJI -KISO




T20260702120412




BLK:36,SNR1: 198.11 ,SNR2: 195.24




F20260702120412




BLK:36,SNR1: 14.958 ,SNR2: 26.366




0652-130 2026/07/02 3.1OUT TOYOKAWA-FUJI





T20260702120412




BLK:30,SNR1: 207.37 ,SNR2: 204.36




K20260702120409




BLK:30,SNR1: 8.3445 ,SNR2: 14.987




0652-130 2026/07/02 3.10UT TOYOKAWA-KISO





F20260702120412




BLK:24,SNR1: 15.677 ,SNR2: 27.845




K20260702120409




BLK:24,SNR1: 8.2925 ,SNR2: 14.899




0652-130 2026/07/02 3.10UT FUJI -KISO




T20260702121549




BLK:31,SNR1: 152.28 ,SNR2: 144.47




F20260702121549




BLK:31,SNR1: 19.634 ,SNR2: 33.910




0703+138 2026/07/02 3.29UT TOYOKAWA-FUJI



T20260702121549





BLK:25,SNR1: 100.19 ,SNR2: 116.22





0703+138 2026/07/02 3.29UT TOYOKAWA-KISO


K20260702121546




BLK:25,SNR1: 18.312 ,SNR2: 32.155



F20260702121549





BLK: 3,SNR1: 19.104 ,SNR2: 32.571





0703+138 2026/07/02 3.29UT FUJI -KISO


K20260702121546




BLK: 3,SNR1: 17.378 ,SNR2: 30.697



T20260702122511




BLK:10,SNR1: 11.242 ,SNR2: 27.628





0713-024 2026/07/02 3.45UT TOYOKAWA-FUJI


F20260702122511




BLK:10,SNR1: 13.589 ,SNR2: 33.134




T20260702122511




BLK: 7,SNR1: 11.925 ,SNR2: 29.225




K20260702122508




BLK: 7,SNR1: 8.4481 ,SNR2: 21.227




0713-024 2026/07/02 3.45UT TOYOKAWA-KISO





F20260702122511




BLK: 1,SNR1: 10.095 ,SNR2: 23.936




K20260702122508




BLK: 1,SNR1: 14.521 ,SNR2: 28.160




0713-024 2026/07/02 3.45UT FUJI -KISO



T20260702123523




BLK:10,SNR1: 9.5788 ,SNR2: 17.141





0723+10 2026/07/02 3.62UT TOYOKAWA-FUJI


F20260702123523




BLK:10,SNR1: 6.7345 ,SNR2: 15.340



T20260702123523




BLK: 8,SNR1: 9.5822 ,SNR2: 17.162





0723+10 2026/07/02 3.62UT TOYOKAWA-KISO



K20260702123520




BLK: 8,SNR1: 0.10492 ,SNR2: 3.4712





F20260702123523




BLK:15,SNR1: 9.3648 ,SNR2: 20.454




K20260702123520




BLK:15,SNR1: 8.6643 ,SNR2: 14.897




0723+10 2026/07/02 3.62UT FUJI -KISO





T20260702124539




BLK:25,SNR1: 0.87102 ,SNR2: 3.0447




F20260702124539




BLK:25,SNR1: 5.6767 ,SNR2: 13.974




0732+33 2026/07/02 3.79UT TOYOKAWA-FUJI




T20260702124539




BLK:24,SNR1: 0.91585 ,SNR2: 3.2529




K20260702124537





BLK:24,SNR1: 3.7826 ,SNR2: 7.7122




0732+33 2026/07/02 3.79UT TOYOKAWA-KISO




F20260702124539




BLK:20,SNR1: 4.9648 ,SNR2: 12.002




K20260702124537





BLK:20,SNR1: 3.3937 ,SNR2: 7.0169




0732+33 2026/07/02 3.79UT FUJI -KISO




T20260702125339




BLK: 2,SNR1: 12.007 ,SNR2: 29.353




F20260702125339





BLK: 2,SNR1: 18.737 ,SNR2: 43.491




0741-06 2026/07/02 3.92UT TOYOKAWA-FUJI



T20260702125339




No.Good Data




Frequency (Hz)

K20260702125336




No.Good Data




Frequency (Hz)


0741-06 2026/07/02 3.92UT TOYOKAWA-KISO




F20260702125339




No.Good Data




K20260702125336




No.Good Data




0741-06 2026/07/02 3.92UT FUJI -KISO



T20260702130323





BLK: 8,SNR1: 7.3016 ,SNR2: 18.297





0752-200 2026/07/02 4.08UT TOYOKAWA-FUJI


F20260702130323




BLK: 8,SNR1: 14.776 ,SNR2: 26.097



T20260702130323




BLK: 5,SNR1: 6.9100 ,SNR2: 23.957





0752-200 2026/07/02 4.08UT TOYOKAWA-KISO


K20260702130320




BLK: 5,SNR1: 11.422 ,SNR2: 20.306



F20260702130323





BLK: 7,SNR1: 6.7428 ,SNR2: 24.347





0752-200 2026/07/02 4.08UT FUJI -KISO


K20260702130320




BLK: 7,SNR1: 6.4612 ,SNR2: 23.359





T20260702131059




BLK: 7,SNR1: 3.3985 ,SNR2: 8.2607




F20260702131059




BLK: 7,SNR1: 5.8638 ,SNR2: 10.868




3C190 2026/07/02 4.21UT TOYOKAWA-FUJI





T20260702131059




BLK: 4,SNR1: 5.7316 ,SNR2: 18.859




K20260702131056





BLK: 4,SNR1: 3.9202 ,SNR2: 9.2799




3C190 2026/07/02 4.21UT TOYOKAWA-KISO





F20260702131059




BLK: 7,SNR1: 4.3465 ,SNR2: 9.7209




K20260702131056




BLK: 7,SNR1: 3.4560 ,SNR2: 8.4102




3C190 2026/07/02 4.21UT FUJI -KISO





T20260702132326




BLK:11,SNR1: 21.178 ,SNR2: 24.323




F20260702132326




BLK:11,SNR1: 16.891 ,SNR2: 24.706




3C196 2026/07/02 4.42UT TOYOKAWA-FUJI





T20260702132326




BLK:20,SNR1: 20.838 ,SNR2: 23.272




K20260702132323




BLK:20,SNR1: 2.1436 ,SNR2: 7.1596




3C196 2026/07/02 4.42UT TOYOKAWA-KISO



F20260702132326





BLK:19,SNR1: 13.830 ,SNR2: 20.231





3C196 2026/07/02 4.42UT FUJI -KISO



K20260702132323




BLK:19,SNR1: 2.1253 ,SNR2: 7.1085





T20260702133435




BLK: 7,SNR1: 3.2032 ,SNR2: 7.5079




F20260702133435





BLK: 7,SNR1: 1.9369 ,SNR2: 3.7022




0821+394 2026/07/02 4.60UT TOYOKAWA-FUJI





T20260702133435




BLK:12,SNR1: 5.9138 ,SNR2: 14.703




K20260702133432





BLK:12,SNR1: 0.22774 ,SNR2: 3.9749




0821+394 2026/07/02 4.60UT TOYOKAWA-KISO





F20260702133435




BLK:12,SNR1: 0.91240 ,SNR2: 2.5666




K20260702133432




BLK:12,SNR1: 1.0642 ,SNR2: 4.7334




0821+394 2026/07/02 4.60UT FUJI -KISO





T20260702134613




BLK: 1,SNR1: 7.7922 ,SNR2: 19.400




F20260702134613




BLK: 1,SNR1: 20.212 ,SNR2: 47.200




0834-19 2026/07/02 4.80UT TOYOKAWA-FUJI





T20260702134613




BLK: 2,SNR1: 18.624 ,SNR2: 32.373




K20260702134610




BLK: 2,SNR1: 16.022 ,SNR2: 28.882




0834-19 2026/07/02 4.80UT TOYOKAWA-KISO





F20260702134613




BLK: 3,SNR1: 20.047 ,SNR2: 35.553




K20260702134610





BLK: 3,SNR1: 19.342 ,SNR2: 34.945




0834-19 2026/07/02 4.80UT FUJI -KISO




T20260702135118




BLK: 1,SNR1: 1.2875 ,SNR2: 12.848




F20260702135118





BLK: 1,SNR1: 6.5506 ,SNR2: 11.792




0839-071 2026/07/02 4.88UT TOYOKAWA-FUJI




T20260702135118




BLK: 5,SNR1: 11.676 ,SNR2: 28.086




K20260702135115





BLK: 5,SNR1: 11.272 ,SNR2: 33.487




0839-071 2026/07/02 4.88UT TOYOKAWA-KISO



F20260702135118





BLK: 1,SNR1: 9.6070 ,SNR2: 12.792




Frequency (Hz)

K20260702135115




BLK: 1,SNR1: 7.4322 ,SNR2: 20.107





Frequency (Hz)


0839-071 2026/07/02 4.88UT FUJI -KISO




T20260702140220




BLK: 3,SNR1: 22.101 ,SNR2: 39.519




F20260702140220





BLK: 3,SNR1: 15.462 ,SNR2: 35.394




3C208 2026/07/02 5.07UT TOYOKAWA-FUJI




T20260702140220




BLK: 4,SNR1: 20.170 ,SNR2: 36.165




K20260702140217




BLK: 4,SNR1: 23.322 ,SNR2: 41.896




3C208 2026/07/02 5.07UT TOYOKAWA-KISO



F20260702140220




BLK: 4,SNR1: 14.869 ,SNR2: 26.160





3C208 2026/07/02 5.07UT FUJI -KISO



K20260702140217




BLK: 4,SNR1: 18.389 ,SNR2: 33.956



T20260702141902





BLK: 2,SNR1: 12.063 ,SNR2: 29.164





3C216 2026/07/02 5.35UT TOYOKAWA-FUJI



F20260702141902




BLK: 2,SNR1: 12.279 ,SNR2: 29.631





T20260702141902




BLK: 1,SNR1: 7.7281 ,SNR2: 21.138




K20260702141859





BLK: 1,SNR1: 2.6156 ,SNR2: 12.436




3C216 2026/07/02 5.35UT TOYOKAWA-KISO



F20260702141902





No.Good Data




Frequency (Hz)

K20260702141859




No.Good Data





Frequency (Hz)


3C216 2026/07/02 5.35UT FUJI -KISO




T20260702143112




BLK:27,SNR1: 0.55062 ,SNR2: 2.4616




F20260702143112





BLK:27,SNR1:-0.95523E-01,SNR2: 1.9828




0919-142 2026/07/02 5.55UT TOYOKAWA-FUJI





T20260702143112




BLK:21,SNR1: 0.58784 ,SNR2: 2.7285




K20260702143109





BLK:21,SNR1: 0.39971 ,SNR2: 1.8605




0919-142 2026/07/02 5.55UT TOYOKAWA-KISO



F20260702143112





BLK:19,SNR1:-0.78463E-01,SNR2: 2.0793




Frequency (Hz)

K20260702143109




BLK:19,SNR1: 0.38513 ,SNR2: 1.6528




Frequency (Hz)


0919-142 2026/07/02 5.55UT FUJI -KISO





T20260702143752




BLK: 4,SNR1: 7.3718 ,SNR2: 21.229




F20260702143752




BLK: 4,SNR1: 20.643 ,SNR2: 47.686




0926+117 2026/07/02 5.66UT TOYOKAWA-FUJI





T20260702143752




BLK: 9,SNR1: 8.4995 ,SNR2: 24.215




K20260702143749





BLK: 9,SNR1: 10.067 ,SNR2: 25.421




0926+117 2026/07/02 5.66UT TOYOKAWA-KISO





F20260702143752




BLK: 6,SNR1: 14.717 ,SNR2: 34.606




K20260702143749





BLK: 6,SNR1: 9.3283 ,SNR2: 23.312




0926+117 2026/07/02 5.66UT FUJI -KISO



T20260702144536





BLK:15,SNR1: 0.16498 ,SNR2: 0.63839




Frequency (Hz)

F20260702144536




BLK:15,SNR1: 3.1868 ,SNR2: 8.1134





Frequency (Hz)


3C222 2026/07/02 5.79UT TOYOKAWA-FUJI





T20260702144536




BLK:15,SNR1: 0.19543 ,SNR2: 0.74953




K20260702144534




BLK:15,SNR1: 4.5323 ,SNR2: 7.0947




3C222 2026/07/02 5.79UT TOYOKAWA-KISO




F20260702144536




BLK:17,SNR1: 2.9989 ,SNR2: 7.9224




K20260702144534





BLK:17,SNR1: 4.3852 ,SNR2: 6.8962




3C222 2026/07/02 5.79UT FUJI -KISO




T20260702145236




BLK: 9,SNR1: 7.1015 ,SNR2: 20.715




F20260702145236





BLK: 9,SNR1: 9.0502 ,SNR2: 26.095




0941-08 2026/07/02 5.90UT TOYOKAWA-FUJI





T20260702145236




BLK: 7,SNR1: 7.3767 ,SNR2: 21.589




K20260702145233




BLK: 7,SNR1: 9.2545 ,SNR2: 26.744




0941-08 2026/07/02 5.90UT TOYOKAWA-KISO





F20260702145236




BLK: 9,SNR1: 11.623 ,SNR2: 27.585




K20260702145233





BLK: 9,SNR1: 11.971 ,SNR2: 28.424




0941-08 2026/07/02 5.90UT FUJI -KISO




T20260702150058




BLK:11,SNR1: 8.3402 ,SNR2: 21.171




F20260702150058





BLK:11,SNR1: 1.6333 ,SNR2: 2.6466




3C230 2026/07/02 6.04UT TOYOKAWA-FUJI




T20260702150058




BLK: 9,SNR1: 3.5952 ,SNR2: 9.9539




K20260702150055





BLK: 9,SNR1: 0.62706 ,SNR2: 2.4292




3C230 2026/07/02 6.04UT TOYOKAWA-KISO



F20260702150058




BLK:20,SNR1: 0.36219 ,SNR2: 1.5182




Frequency (Hz)

K20260702150055




BLK:20,SNR1: 3.1924 ,SNR2: 5.7358




Frequency (Hz)


3C230 2026/07/02 6.04UT FUJI -KISO





T20260702151659




BLK: 5,SNR1: 1.8005 ,SNR2: 3.2615




F20260702151659




BLK: 5,SNR1: 0.22584 ,SNR2: 1.5690




3C237 2026/07/02 6.31UT TOYOKAWA-FUJI



T20260702151659




BLK:12,SNR1: 0.58907 ,SNR2: 2.1887




Frequency (Hz)

K20260702151656




BLK:12,SNR1: 6.4355 ,SNR2: 14.829





Frequency (Hz)


3C237 2026/07/02 6.31UT TOYOKAWA-KISO



F20260702151659





BLK:15,SNR1: 6.6282 ,SNR2: 14.955




Frequency (Hz)

K20260702151656




BLK:15,SNR1: 6.3044 ,SNR2: 14.536





Frequency (Hz)


3C237 2026/07/02 6.31UT FUJI -KISO





T20260702152315




BLK:24,SNR1: 11.714 ,SNR2: 28.410




F20260702152315





BLK:24,SNR1: 8.4533 ,SNR2: 21.802




1011+110 2026/07/02 6.42UT TOYOKAWA-FUJI





T20260702152315




BLK:25,SNR1: 11.705 ,SNR2: 28.071




K20260702152312





BLK:25,SNR1: 7.1224 ,SNR2: 20.611




1011+110 2026/07/02 6.42UT TOYOKAWA-KISO





F20260702152315




BLK:23,SNR1: 8.5590 ,SNR2: 19.511




K20260702152312





BLK:23,SNR1: 6.6177 ,SNR2: 17.608




1011+110 2026/07/02 6.42UT FUJI -KISO




T20260702153056




BLK: 5,SNR1: 0.40345 ,SNR2: 1.1567




F20260702153056





BLK: 5,SNR1: 4.2548 ,SNR2: 10.275




3C241 2026/07/02 6.54UT TOYOKAWA-FUJI




T20260702153056




BLK: 3,SNR1: 1.2653 ,SNR2: 9.4769




K20260702153053





BLK: 3,SNR1: 0.84963 ,SNR2: 2.7566




3C241 2026/07/02 6.54UT TOYOKAWA-KISO




F20260702153056




BLK: 2,SNR1: 9.4665 ,SNR2: 23.756




K20260702153053




BLK: 2,SNR1: 1.7442 ,SNR2: 6.2908




3C241 2026/07/02 6.54UT FUJI -KISO



T20260702154225




BLK: 1,SNR1: 15.106 ,SNR2: 27.020




Frequency (Hz)

F20260702154225




BLK: 1,SNR1: 0.40175 ,SNR2: 8.8773




Frequency (Hz)


1031-11 2026/07/02 6.74UT TOYOKAWA-FUJI



T20260702154225




BLK: 1,SNR1: 3.6065 ,SNR2: 12.195




Frequency (Hz)

K20260702154222




BLK: 1,SNR1: 2.2273 ,SNR2: 21.256





Frequency (Hz)


1031-11 2026/07/02 6.74UT TOYOKAWA-KISO



F20260702154225





No.Good Data




Frequency (Hz)

K20260702154222




No.Good Data




Frequency (Hz)


1031-11 2026/07/02 6.74UT FUJI -KISO




T20260702154658




No.Good Data




F20260702154658




No.Good Data




1035-058 2026/07/02 6.81UT TOYOKAWA-FUJI



T20260702154658




BLK: 2,SNR1: 11.155 ,SNR2: 27.795




Frequency (Hz)

K20260702154655




BLK: 2,SNR1: 10.864 ,SNR2: 27.083




Frequency (Hz)


1035-058 2026/07/02 6.81UT TOYOKAWA-KISO



F20260702154658




BLK: 2,SNR1: 8.6272 ,SNR2: 26.123




Frequency (Hz)

K20260702154655




BLK: 2,SNR1: 10.686 ,SNR2: 26.647





Frequency (Hz)


1035-058 2026/07/02 6.81UT FUJI -KISO





T20260702155611




BLK: 1,SNR1: 4.0488 ,SNR2: 16.659




F20260702155611





BLK: 1,SNR1: 75.553 ,SNR2: 168.87




1044-008 2026/07/02 6.96UT TOYOKAWA-FUJI



T20260702155611





BLK: 2,SNR1: 7.5482 ,SNR2: 21.147




Frequency (Hz)

K20260702155608




BLK: 2,SNR1: 9.3062 ,SNR2: 26.832





Frequency (Hz)


1044-008 2026/07/02 6.96UT TOYOKAWA-KISO



F20260702155611





BLK: 4,SNR1: 63.983 ,SNR2: 78.263




Frequency (Hz)

K20260702155608




BLK: 4,SNR1: 30.679 ,SNR2: 50.718





Frequency (Hz)


1044-008 2026/07/02 6.96UT FUJI -KISO



T20260702160716





BLK: 2,SNR1: 0.52197 ,SNR2: 3.6353




Frequency (Hz)

F20260702160716




BLK: 2,SNR1: 0.77565E-01,SNR2: 2.2000





Frequency (Hz)


1055+01 2026/07/02 7.15UT TOYOKAWA-FUJI





T20260702160716




No.Good Data




K20260702160713





No.Good Data




1055+01 2026/07/02 7.15UT TOYOKAWA-KISO



F20260702160716





BLK: 3,SNR1:-0.92893E-01,SNR2: 2.2513




Frequency (Hz)

K20260702160713




BLK: 3,SNR1: 1.9467 ,SNR2: 5.7768




Frequency (Hz)


1055+01 2026/07/02 7.15UT FUJI -KISO



T20260702161833





BLK: 6,SNR1: 102.92 ,SNR2: 203.03




Frequency (Hz)

F20260702161833




BLK: 6,SNR1: 14.361 ,SNR2: 25.590





Frequency (Hz)


1107+109 2026/07/02 7.34UT TOYOKAWA-FUJI



T20260702161833




BLK: 3,SNR1: 40.122 ,SNR2: 82.450




Frequency (Hz)

K20260702161830




BLK: 3,SNR1: 11.795 ,SNR2: 33.753





Frequency (Hz)


1107+109 2026/07/02 7.34UT TOYOKAWA-KISO



F20260702161833





BLK: 1,SNR1: 8.3505 ,SNR2: 20.949




Frequency (Hz)

K20260702161830




BLK: 1,SNR1: 11.907 ,SNR2: 29.026




Frequency (Hz)


1107+109 2026/07/02 7.34UT FUJI -KISO



T20260702162811




BLK:11,SNR1: 0.44179 ,SNR2: 2.9974




Frequency (Hz)

F20260702162811




BLK:11,SNR1: 5.8697 ,SNR2: 12.707




Frequency (Hz)


3C255 2026/07/02 7.50UT TOYOKAWA-FUJI





T20260702162811




BLK:11,SNR1: 0.37350 ,SNR2: 2.3730




K20260702162808




BLK:11,SNR1: 6.8655 ,SNR2: 12.615




3C255 2026/07/02 7.50UT TOYOKAWA-KISO



F20260702162811





BLK: 8,SNR1: 2.8059 ,SNR2: 6.5633




Frequency (Hz)

K20260702162808




BLK: 8,SNR1: 5.6628 ,SNR2: 10.143





Frequency (Hz)


3C255 2026/07/02 7.50UT FUJI -KISO



T20260702165209




BLK: 1,SNR1: 4.0287 ,SNR2: 10.175




Frequency (Hz)

F20260702165209




BLK: 1,SNR1: 15.046 ,SNR2: 26.664





Frequency (Hz)


3C263.1 2026/07/02 7.90UT TOYOKAWA-FUJI



T20260702165209





BLK: 3,SNR1: 1.8876 ,SNR2: 4.7156




Frequency (Hz)

K20260702165206




BLK: 3,SNR1: 80.652 ,SNR2: 154.48




Frequency (Hz)


3C263.1 2026/07/02 7.90UT TOYOKAWA-KISO



F20260702165209





No.Good Data




Frequency (Hz)

K20260702165206




No.Good Data





Frequency (Hz)


3C263.1 2026/07/02 7.90UT FUJI -KISO



T20260702165836




BLK:10,SNR1: 0.12009 ,SNR2: 0.95658




Frequency (Hz)

F20260702165836




BLK:10,SNR1: 3.0646 ,SNR2: 9.1357





Frequency (Hz)


3C267 2026/07/02 8.00UT TOYOKAWA-FUJI



T20260702165836




BLK: 6,SNR1: 0.17191 ,SNR2: 0.89662




Frequency (Hz)

K20260702165833




BLK: 6,SNR1: 6.7233 ,SNR2: 17.785




Frequency (Hz)


3C267 2026/07/02 8.00UT TOYOKAWA-KISO



F20260702165836





BLK: 5,SNR1: 4.7061 ,SNR2: 12.392




Frequency (Hz)

K20260702165833




BLK: 5,SNR1: 6.6831 ,SNR2: 19.462





Frequency (Hz)


3C267 2026/07/02 8.00UT FUJI -KISO



T20260702171750





BLK: 3,SNR1: 11.458 ,SNR2: 26.678




Frequency (Hz)

F20260702171750




BLK: 3,SNR1: 2.9335 ,SNR2: 8.7933





Frequency (Hz)


1206+439 2026/07/02 8.33UT TOYOKAWA-FUJI



T20260702171750





BLK: 6,SNR1: 0.64133 ,SNR2: 2.5458




Frequency (Hz)

K20260702171747




BLK: 6,SNR1: 4.4682 ,SNR2: 11.470





Frequency (Hz)


1206+439 2026/07/02 8.33UT TOYOKAWA-KISO



F20260702171750




BLK: 2,SNR1: 2.9918 ,SNR2: 9.1208




Frequency (Hz)

K20260702171747




BLK: 2,SNR1: 10.298 ,SNR2: 24.518





Frequency (Hz)


1206+439 2026/07/02 8.33UT FUJI -KISO



T20260702174737





BLK: 7,SNR1: 15.600 ,SNR2: 28.051




Frequency (Hz)

F20260702174737




BLK: 7,SNR1: 1.7463 ,SNR2: 6.5537





Frequency (Hz)


1236+327 2026/07/02 8.82UT TOYOKAWA-FUJI



T20260702174737





BLK: 3,SNR1: 0.20691E-01,SNR2: 0.71516




Frequency (Hz)

K20260702174734




BLK: 3,SNR1: 2.3683 ,SNR2: 7.5766




Frequency (Hz)


1236+327 2026/07/02 8.82UT TOYOKAWA-KISO



F20260702174737





BLK: 8,SNR1: 3.3136 ,SNR2: 5.8936




Frequency (Hz)

K20260702174734



BLK: 8,SNR1: 2.4223 ,SNR2: 7.8127



Frequency (Hz)

1236+327 2026/07/02 8.82UT FUJI -KISO

