




T20260703054054





BLK: 1,SNR1: 0.32546 ,SNR2: 2.0744




Frequency (Hz)

F20260703054054




BLK: 1,SNR1: 3.4661 ,SNR2: 12.132





Frequency (Hz)


0031+391 2026/07/02 20.71UT TOYOKAWA-FUJI



T20260703054054





BLK: 2, SNR1: 2.6607 ,SNR2: 9.2324




Frequency (Hz)

K20260703054051




BLK: 2, SNR1: 3.4433 ,SNR2: 15.436





Frequency (Hz)


0031+391 2026/07/02 20.71UT TOYOKAWA-KISO



F20260703054054





BLK: 2,SNR1: 22.457 ,SNR2: 40.777




Frequency (Hz)

0031+391 2026/07/02 20.71UT FUJI -KISO


K20260703054051





BLK: 2,SNR1: 11.394 ,SNR2: 27.838




Frequency (Hz)



T20260703060227





BLK: 5,SNR1: 7.8949 ,SNR2: 23.103




Frequency (Hz)

F20260703060227




BLK: 5,SNR1: 12.104 ,SNR2: 22.341





Frequency (Hz)


0053+261 2026/07/02 21.07UT TOYOKAWA-FUJI



T20260703060227





BLK: 3,SNR1: 5.1302 ,SNR2: 30.867





0053+261 2026/07/02 21.07UT TOYOKAWA-KISO



K20260703060224




BLK: 3,SNR1: 2.2458 ,SNR2: 8.0373



F20260703060227





BLK: 1,SNR1: 2.6831 ,SNR2: 6.4418




Frequency (Hz)

K20260703060224




BLK: 1,SNR1: 2.4062 ,SNR2: 13.493





Frequency (Hz)


0053+261 2026/07/02 21.07UT FUJI -KISO



T20260703061859





BLK: 1,SNR1: 2.4475 ,SNR2: 11.842




Frequency (Hz)

F20260703061859




BLK: 1,SNR1: 2.4057 ,SNR2: 11.288





Frequency (Hz)


0109+416 2026/07/02 21.34UT TOYOKAWA-FUJI





T20260703061859




No.Good Data




K20260703061857





No.Good Data




0109+416 2026/07/02 21.34UT TOYOKAWA-KISO



F20260703061859





BLK: 1,SNR1: 16.969 ,SNR2: 41.119




Frequency (Hz)

K20260703061857




BLK: 1,SNR1: 11.490 ,SNR2: 27.779





Frequency (Hz)


0109+416 2026/07/02 21.34UT FUJI -KISO



T20260703063004





BLK: 3,SNR1: 10.011 ,SNR2: 22.289




Frequency (Hz)

F20260703063004




BLK: 3,SNR1: 3.8677 ,SNR2: 11.404





Frequency (Hz)


0120+405 2026/07/02 21.53UT TOYOKAWA-FUJI



T20260703063004





BLK: 3,SNR1: 9.7173 ,SNR2: 17.228




Frequency (Hz)

K20260703063001




BLK: 3,SNR1: 3.3417 ,SNR2: 9.9297





Frequency (Hz)


0120+405 2026/07/02 21.53UT TOYOKAWA-KISO



F20260703063004





BLK: 5, SNR1: 9.2228 ,SNR2: 16.135




Frequency (Hz)

K20260703063001




BLK: 5, SNR1: 3.1337 ,SNR2: 9.4800





Frequency (Hz)


0120+405 2026/07/02 21.53UT FUJI -KISO



T20260703063742





No.Good Data




Frequency (Hz)

F20260703063742




No.Good Data





Frequency (Hz)


0128+03 2026/07/02 21.66UT TOYOKAWA-FUJI



T20260703063742





No.Good Data




Frequency (Hz)

K20260703063739




No.Good Data





Frequency (Hz)


0128+03 2026/07/02 21.66UT TOYOKAWA-KISO



F20260703063742





BLK: 1,SNR1: 7.5052 ,SNR2: 19.835




Frequency (Hz)

K20260703063739




BLK: 1,SNR1: 8.6147 ,SNR2: 22.948





Frequency (Hz)


0128+03 2026/07/02 21.66UT FUJI -KISO



T20260703064416





BLK: 8,SNR1: 0.67634 ,SNR2: 3.0556




Frequency (Hz)

3C48 2026/07/02 21.77UT TOYOKAWA-FUJI


F20260703064416





BLK: 8,SNR1: 10.489 ,SNR2: 26.104




Frequency (Hz)



T20260703064416



BLK:12,SNR1: 0.71451 ,SNR2: 3.5899





Frequency (Hz)


3C48

2026/07/02 21.77UT TOYOKAWA-KISO


K20260703064413





BLK:12,SNR1: 3.9196 ,SNR2: 9.7992




Frequency (Hz)



F20260703064416




BLK: 4,SNR1: 0.62490 ,SNR2: 4.8235




Frequency (Hz)

3C48 2026/07/02 21.77UT FUJI -KISO


K20260703064413





BLK: 4,SNR1: 0.11553 ,SNR2: 0.98487




Frequency (Hz)





T20260703070400




No.Good Data




F20260703070400





No.Good Data




0155-109 2026/07/02 22.09UT TOYOKAWA-FUJI



T20260703070400





No.Good Data




Frequency (Hz)

K20260703070357




No.Good Data




Frequency (Hz)


0155-109 2026/07/02 22.09UT TOYOKAWA-KISO



F20260703070400





BLK: 1,SNR1: 4.6074 ,SNR2: 13.643




Frequency (Hz)

K20260703070357




BLK: 1,SNR1: 12.317 ,SNR2: 32.206





Frequency (Hz)


0155-109 2026/07/02 22.09UT FUJI -KISO



T20260703071108





BLK:12,SNR1: 8.6946 ,SNR2: 20.815




Frequency (Hz)

F20260703071108




BLK:12,SNR1: 6.7571 ,SNR2: 15.224





Frequency (Hz)


0202+15 2026/07/02 22.21UT TOYOKAWA-FUJI



T20260703071108





BLK: 8,SNR1: 5.3379 ,SNR2: 15.155




Frequency (Hz)

K20260703071105




BLK: 8,SNR1: 4.3126 ,SNR2: 9.9398





Frequency (Hz)


0202+15 2026/07/02 22.21UT TOYOKAWA-KISO



F20260703071108





BLK:13,SNR1: 10.428 ,SNR2: 18.528




Frequency (Hz)

K20260703071105




BLK:13,SNR1: 4.3847 ,SNR2: 10.495





Frequency (Hz)


0202+15 2026/07/02 22.21UT FUJI -KISO



T20260703072258





BLK: 4,SNR1: 3.6111 ,SNR2: 8.5544




Frequency (Hz)

F20260703072258




BLK: 4,SNR1: 12.439 ,SNR2: 27.291





Frequency (Hz)


0213+178 2026/07/02 22.41UT TOYOKAWA-FUJI





T20260703072258




No.Good Data




K20260703072256





No.Good Data




0213+178 2026/07/02 22.41UT TOYOKAWA-KISO




F20260703072258




BLK: 2,SNR1: 4.1797 ,SNR2: 16.502




K20260703072256





BLK: 2,SNR1: 5.3438 ,SNR2: 17.564




0213+178 2026/07/02 22.41UT FUJI -KISO



T20260703073041





BLK: 4,SNR1: 1.9667 ,SNR2: 9.3421




Frequency (Hz)

3C67 2026/07/02 22.54UT TOYOKAWA-FUJI


F20260703073041





BLK: 4,SNR1: 7.8755 ,SNR2: 19.545




Frequency (Hz)



T20260703073041





BLK: 5,SNR1: 9.6166 ,SNR2: 23.397




Frequency (Hz)

3C67 2026/07/02 22.54UT TOYOKAWA-KISO


K20260703073038





BLK: 5,SNR1: 9.1329 ,SNR2: 22.564




Frequency (Hz)



F20260703073041





BLK: 4,SNR1: 7.3334 ,SNR2: 18.181




Frequency (Hz)

3C67 2026/07/02 22.54UT FUJI -KISO


K20260703073038




BLK: 4,SNR1: 13.316 ,SNR2: 24.557




Frequency (Hz)




T20260703074855




BLK: 2,SNR1: 5.5862 ,SNR2: 15.051




F20260703074855





BLK: 2,SNR1: 12.677 ,SNR2: 33.550




3C71 2026/07/02 22.84UT TOYOKAWA-FUJI



T20260703074855



No.Good Data




Frequency (Hz)


3C71

2026/07/02 22.84UT TOYOKAWA-KISO


K20260703074852





No.Good Data




Frequency (Hz)





F20260703074855




No.Good Data




K20260703074852





No.Good Data




3C71 2026/07/02 22.84UT FUJI -KISO



T20260703080811





BLK: 7,SNR1: 10.351 ,SNR2: 19.136




Frequency (Hz)

F20260703080811




BLK: 7,SNR1: 13.267 ,SNR2: 24.116





Frequency (Hz)


0258+350 2026/07/02 23.16UT TOYOKAWA-FUJI



T20260703080811




BLK: 5,SNR1: 6.2970 ,SNR2: 16.228




Frequency (Hz)

K20260703080808




BLK: 5,SNR1: 12.914 ,SNR2: 22.878





Frequency (Hz)


0258+350 2026/07/02 23.16UT TOYOKAWA-KISO



F20260703080811





BLK: 5,SNR1: 19.047 ,SNR2: 33.562




Frequency (Hz)

K20260703080808




BLK: 5,SNR1: 15.018 ,SNR2: 26.955




Frequency (Hz)


0258+350 2026/07/02 23.16UT FUJI -KISO



T20260703081800




BLK: 5,SNR1: 0.14224 ,SNR2: 0.61332




Frequency (Hz)

F20260703081800




BLK: 5,SNR1: 5.5151 ,SNR2: 12.931




Frequency (Hz)


0308+305 2026/07/02 23.33UT TOYOKAWA-FUJI



T20260703081800




BLK: 5,SNR1: 0.28152E-02,SNR2: 0.47444




Frequency (Hz)

K20260703081757




BLK: 5,SNR1: 3.3930 ,SNR2: 7.3925





Frequency (Hz)


0308+305 2026/07/02 23.33UT TOYOKAWA-KISO





F20260703081800




BLK: 7,SNR1: 1.5317 ,SNR2: 3.5854




K20260703081757





BLK: 7,SNR1: 1.8500 ,SNR2: 4.4754




0308+305 2026/07/02 23.33UT FUJI -KISO



T20260703082931





BLK: 5,SNR1: 0.45961 ,SNR2: 3.2141




Frequency (Hz)

F20260703082931




BLK: 5,SNR1: 0.19894E-01,SNR2: 1.6644





Frequency (Hz)


0320+05 2026/07/02 23.52UT TOYOKAWA-FUJI



T20260703082931





BLK:13,SNR1: 106.47 ,SNR2: 171.59




Frequency (Hz)

0320+05 2026/07/02 23.52UT TOYOKAWA-KISO


K20260703082928




BLK:13,SNR1: 9.0179 ,SNR2: 19.228




Frequency (Hz)



F20260703082931




BLK:17,SNR1: 8.7326 ,SNR2: 18.878





0320+05 2026/07/02 23.52UT FUJI -KISO


K20260703082928




BLK:17,SNR1: 4.1620 ,SNR2: 6.5129




T20260703084253




BLK: 7,SNR1:-0.31897E-01,SNR2: 1.0283




F20260703084253





BLK: 7,SNR1: 0.88907 ,SNR2: 6.4857




0333+32 2026/07/02 23.74UT TOYOKAWA-FUJI




T20260703084253




BLK: 6,SNR1: 0.11572E-01,SNR2: 0.44938




K20260703084251




BLK: 6,SNR1: 1.2386 ,SNR2: 3.9872




0333+32 2026/07/02 23.74UT TOYOKAWA-KISO





F20260703084253




BLK: 8,SNR1: 1.3149 ,SNR2: 4.8742




K20260703084251





BLK: 8,SNR1: 2.6648 ,SNR2: 6.6493




0333+32 2026/07/02 23.74UT FUJI -KISO



T20260703085413





BLK:23,SNR1: 2.8449 ,SNR2: 13.316




Frequency (Hz)

F20260703085413




BLK:23,SNR1: 8.2673 ,SNR2: 20.720





Frequency (Hz)


0345+176 2026/07/02 23.93UT TOYOKAWA-FUJI



T20260703085413





BLK:31,SNR1: 2.7945 ,SNR2: 13.117





0345+176 2026/07/02 23.93UT TOYOKAWA-KISO


K20260703085410




BLK:31,SNR1: 14.325 ,SNR2: 25.337





F20260703085413




BLK:27,SNR1: 8.1374 ,SNR2: 20.340




K20260703085410




BLK:27,SNR1: 14.685 ,SNR2: 25.995




0345+176 2026/07/02 23.93UT FUJI -KISO





T20260703091128




BLK: 2,SNR1: 8.3959 ,SNR2: 15.475




F20260703091128




BLK: 2,SNR1: 11.404 ,SNR2: 28.526




0403-132 2026/07/03 0.22UT TOYOKAWA-FUJI



T20260703091128





BLK: 3,SNR1: 6.2113 ,SNR2: 18.062





0403-132 2026/07/03 0.22UT TOYOKAWA-KISO



K20260703091125




BLK: 3,SNR1: 5.1821 ,SNR2: 14.703





F20260703091128




No. Good Data




K20260703091125





No. Good Data




0403-132 2026/07/03 0.22UT FUJI -KISO





T20260703092039




BLK: 5,SNR1: 8.4124 ,SNR2: 25.110




F20260703092039





BLK: 5,SNR1: 7.9050 ,SNR2: 22.455




0411+05 2026/07/03 0.37UT TOYOKAWA-FUJI



T20260703092039





BLK: 2, SNR1: 42.365 ,SNR2: 118.17




Frequency (Hz)

K20260703092036




BLK: 2, SNR1: 7.0998 ,SNR2: 18.252





Frequency (Hz)


0411+05 2026/07/03 0.37UT TOYOKAWA-KISO



F20260703092039





BLK: 4, SNR1: 7.0439 ,SNR2: 18.157





0411+05 2026/07/03 0.37UT FUJI -KISO



K20260703092036




BLK: 4, SNR1: 8.2106 ,SNR2: 21.909



T20260703092734





BLK: 3,SNR1: 11.314 ,SNR2: 28.444





0418+236 2026/07/03 0.49UT TOYOKAWA-FUJI



F20260703092734




BLK: 3,SNR1: 10.852 ,SNR2: 24.388



T20260703092734





BLK: 6, SNR1: 10.463 , SNR2: 24.709




Frequency (Hz)

K20260703092731




BLK: 6, SNR1: 10.453 , SNR2: 24.958





Frequency (Hz)


0418+236 2026/07/03 0.49UT TOYOKAWA-KISO





F20260703092734




BLK: 2, SNR1: 9.6552 , SNR2: 21.696




K20260703092731




BLK: 2, SNR1: 14.342 , SNR2: 31.852




0418+236 2026/07/03 0.49UT FUJI -KISO



T20260703093902




BLK: 8,SNR1: 14.526 ,SNR2: 34.957





3C119 2026/07/03 0.68UT TOYOKAWA-FUJI


F20260703093902




BLK: 8,SNR1: 9.9345 ,SNR2: 25.782





T20260703093902




BLK:12,SNR1: 10.909 ,SNR2: 27.793




K20260703093859




BLK:12,SNR1: 7.6379 ,SNR2: 19.769




3C119 2026/07/03 0.68UT TOYOKAWA-KISO



F20260703093902





BLK: 6,SNR1: 12.138 ,SNR2: 30.796





3C119 2026/07/03 0.68UT FUJI -KISO



K20260703093859




BLK: 6,SNR1: 8.0699 ,SNR2: 20.870



T20260703102708





BLK:27,SNR1: 2.8452 ,SNR2: 12.066




Frequency (Hz)

F20260703102708




BLK:27,SNR1: 1.4518 ,SNR2: 5.1905





Frequency (Hz)


3C138 2026/07/03 1.48UT TOYOKAWA-FUJI





T20260703102708




BLK:24,SNR1: 3.8366 ,SNR2: 16.333




K20260703102705




BLK:24,SNR1: 3.3730 ,SNR2: 5.8668




3C138 2026/07/03 1.48UT TOYOKAWA-KISO




F20260703102708




BLK: 8, SNR1: 0.44232 , SNR2: 3.1103




K20260703102705




BLK: 8, SNR1: 3.5732 , SNR2: 9.2810




3C138 2026/07/03 1.48UT FUJI -KISO



T20260703104042




BLK:10,SNR1: 2.4766 ,SNR2: 21.876





0531+194 2026/07/03 1.71UT TOYOKAWA-FUJI


F20260703104042




BLK:10,SNR1: 8.7992 ,SNR2: 21.188



T20260703104042




BLK:13,SNR1: 2.8786 ,SNR2: 21.038





0531+194 2026/07/03 1.71UT TOYOKAWA-KISO



K20260703104039




BLK:13,SNR1: 17.907 ,SNR2: 31.666





F20260703104042




No. Good Data




K20260703104039





No. Good Data




0531+194 2026/07/03 1.71UT FUJI -KISO





T20260703104903




BLK: 6,SNR1: 15.237 ,SNR2: 26.954




F20260703104903




BLK: 6,SNR1: 19.057 ,SNR2: 34.251




3C147 2026/07/03 1.85UT TOYOKAWA-FUJI



T20260703104903




BLK: 6,SNR1: 15.105 ,SNR2: 27.047





3C147 2026/07/03 1.85UT TOYOKAWA-KISO



K20260703104900




BLK: 6,SNR1: 1.3885 ,SNR2: 11.613



F20260703104903





BLK: 4,SNR1: 17.380 ,SNR2: 37.231




Frequency (Hz)

3C147 2026/07/03 1.85UT FUJI -KISO


K20260703104900




BLK: 4,SNR1: 17.267 ,SNR2: 31.268




Frequency (Hz)



T20260703105713





BLK:10,SNR1: 58.479 ,SNR2: 81.268




0548+16 2026/07/03 1.98UT TOYOKAWA-FUJI


F20260703105713




BLK:10,SNR1: 12.208 ,SNR2: 21.451




Frequency (Hz)





T20260703105713




BLK: 6,SNR1: 70.219 ,SNR2: 82.384




K20260703105710




BLK: 6,SNR1: 10.395 ,SNR2: 19.283




0548+16 2026/07/03 1.98UT TOYOKAWA-KISO



F20260703105713





BLK: 5,SNR1: 12.085 ,SNR2: 21.671





0548+16 2026/07/03 1.98UT FUJI -KISO


K20260703105710




BLK: 5,SNR1: 5.9950 ,SNR2: 15.064



T20260703110123




BLK:14,SNR1: 31.723 ,SNR2: 76.028





0552+12 2026/07/03 2.05UT TOYOKAWA-FUJI


F20260703110123




BLK:14,SNR1: 10.437 ,SNR2: 19.308



T20260703110123




BLK:15,SNR1: 25.044 ,SNR2: 42.139




0552+12 2026/07/03 2.05UT TOYOKAWA-KISO


K20260703110120




BLK:15,SNR1: 9.4071 ,SNR2: 22.551




Frequency (Hz)




F20260703110123




BLK: 6,SNR1: 7.0191 ,SNR2: 17.701




K20260703110120





BLK: 6,SNR1: 9.9251 ,SNR2: 24.704




0552+12 2026/07/03 2.05UT FUJI -KISO



T20260703110550




BLK: 2,SNR1: 0.33390 ,SNR2: 2.5955





0556+191 2026/07/03 2.13UT TOYOKAWA-FUJI


F20260703110550




BLK: 2,SNR1: 10.773 ,SNR2: 26.443



T20260703110550





BLK: 4,SNR1: 0.47058 ,SNR2: 3.6337





0556+191 2026/07/03 2.13UT TOYOKAWA-KISO


K20260703110547




BLK: 4,SNR1: 2.5941 ,SNR2: 11.830




F20260703110550




BLK: 2,SNR1: 10.413 ,SNR2: 25.543




K20260703110547




BLK: 2,SNR1: 2.7959 ,SNR2: 12.672




0556+191 2026/07/03 2.13UT FUJI -KISO



T20260703111335




BLK: 5,SNR1: 10.314 ,SNR2: 25.275




0605-08 2026/07/03 2.25UT TOYOKAWA-FUJI


F20260703111335




BLK: 5,SNR1: 19.627 ,SNR2: 36.145




Frequency (Hz)



T20260703111335




BLK: 3,SNR1: 10.827 ,SNR2: 26.584





0605-08 2026/07/03 2.25UT TOYOKAWA-KISO


K20260703111332




BLK: 3,SNR1: 1.0515 ,SNR2: 5.8403



F20260703111335




BLK: 2,SNR1: 11.373 ,SNR2: 27.303





0605-08 2026/07/03 2.25UT FUJI -KISO


K20260703111332




BLK: 2,SNR1: 28.964 ,SNR2: 51.815





T20260703113243




BLK: 9,SNR1: 3.3491 ,SNR2: 16.570




F20260703113243




BLK: 9,SNR1: 9.8515 ,SNR2: 17.482




3C161 2026/07/03 2.57UT TOYOKAWA-FUJI





T20260703113243




BLK:25,SNR1: 2.5462 ,SNR2: 12.839




K20260703113240





BLK:25,SNR1: 1.0311 ,SNR2: 4.4031




3C161 2026/07/03 2.57UT TOYOKAWA-KISO



F20260703113243





BLK: 3,SNR1: 0.20329 ,SNR2: 1.5741




Frequency (Hz)

3C161 2026/07/03 2.57UT FUJI -KISO


K20260703113240





BLK: 3,SNR1: 1.1696 ,SNR2: 4.7374




Frequency (Hz)



T20260703120016





BLK: 5,SNR1: 9.5462 ,SNR2: 23.544




Frequency (Hz)

F20260703120016




BLK: 5,SNR1: 20.821 ,SNR2: 37.309





Frequency (Hz)


0652-130 2026/07/03 3.03UT TOYOKAWA-FUJI



T20260703120016





BLK: 2,SNR1: 2.5538 ,SNR2: 11.693




Frequency (Hz)

0652-130 2026/07/03 3.03UT TOYOKAWA-KISO


K20260703120013





BLK: 2,SNR1: 2.4364 ,SNR2: 11.443




Frequency (Hz)



F20260703120016




BLK: 6,SNR1: 2.4457 ,SNR2: 11.180




Frequency (Hz)

K20260703120013




BLK: 6,SNR1: 2.4574 ,SNR2: 11.237




Frequency (Hz)


0652-130 2026/07/03 3.03UT FUJI -KISO



T20260703121153





BLK: 5,SNR1: 19.597 ,SNR2: 36.056




Frequency (Hz)

F20260703121153




BLK: 5,SNR1: 10.317 ,SNR2: 25.626





Frequency (Hz)


0703+138 2026/07/03 3.23UT TOYOKAWA-FUJI



T20260703121153





BLK: 1,SNR1: 2.1244 ,SNR2: 10.292




Frequency (Hz)

0703+138 2026/07/03 3.23UT TOYOKAWA-KISO


K20260703121150




BLK: 1,SNR1: 8.6475 ,SNR2: 21.678




Frequency (Hz)



F20260703121153




BLK: 5, SNR1: 26.279 ,SNR2: 63.311





0703+138 2026/07/03 3.23UT FUJI -KISO



K20260703121150




BLK: 5, SNR1: 9.9479 ,SNR2: 24.744



T20260703122115




BLK: 3,SNR1: 11.393 ,SNR2: 27.886





0713-024 2026/07/03 3.38UT TOYOKAWA-FUJI



F20260703122115




BLK: 3,SNR1: 11.860 ,SNR2: 28.617





T20260703122115




No. Good Data




K20260703122112




No. Good Data




0713-024 2026/07/03 3.38UT TOYOKAWA-KISO



F20260703122115





BLK: 2,SNR1: 15.005 ,SNR2: 35.649





0713-024 2026/07/03 3.38UT FUJI -KISO


K20260703122112




BLK: 2,SNR1: 7.7277 ,SNR2: 19.147



T20260703123128





BLK: 2,SNR1: 1.6270 ,SNR2: 8.9243





0723+10 2026/07/03 3.55UT TOYOKAWA-FUJI


F20260703123128




BLK: 2,SNR1: 21.826 ,SNR2: 40.065



T20260703123128




BLK: 5,SNR1: 1.8707 ,SNR2: 9.4459





0723+10 2026/07/03 3.55UT TOYOKAWA-KISO


K20260703123125




BLK: 5,SNR1: 12.632 ,SNR2: 21.891




F20260703123128




BLK: 1,SNR1: 17.722 ,SNR2: 31.219




K20260703123125




BLK: 1,SNR1:-0.23639E-01,SNR2: 2.9886




0723+10 2026/07/03 3.55UT FUJI -KISO



T20260703124143





BLK: 1,SNR1: 8.3483 ,SNR2: 20.578





0732+33 2026/07/03 3.72UT TOYOKAWA-FUJI



F20260703124143




BLK: 1,SNR1: 9.1029 ,SNR2: 22.662




T20260703124143




BLK: 4,SNR1: 9.6804 ,SNR2: 23.181




K20260703124140





BLK: 4,SNR1: 4.2187 ,SNR2: 14.695




0732+33 2026/07/03 3.72UT TOYOKAWA-KISO





F20260703124143




BLK: 1,SNR1: 6.2060 ,SNR2: 15.723




K20260703124140





BLK: 1,SNR1: 6.2375 ,SNR2: 16.057




0732+33 2026/07/03 3.72UT FUJI -KISO




T20260703124943




No.Good Data




F20260703124943





No.Good Data




0741-06 2026/07/03 3.86UT TOYOKAWA-FUJI





T20260703124943




No. Good Data




K20260703124940





No. Good Data




0741-06 2026/07/03 3.86UT TOYOKAWA-KISO





F20260703124943




No.Good Data




K20260703124940





No.Good Data




0741-06 2026/07/03 3.86UT FUJI -KISO



T20260703125927





No.Good Data




Frequency (Hz)

F20260703125927




No.Good Data





Frequency (Hz)


0752-200 2026/07/03 4.02UT TOYOKAWA-FUJI



T20260703125927





BLK: 3,SNR1: 11.300 ,SNR2: 19.747





0752-200 2026/07/03 4.02UT TOYOKAWA-KISO



K20260703125924




BLK: 3,SNR1: 11.390 ,SNR2: 20.012



F20260703125927





BLK: 1,SNR1: 1.5265 ,SNR2: 8.1456





0752-200 2026/07/03 4.02UT FUJI -KISO


K20260703125924




BLK: 1,SNR1: 2.9040 ,SNR2: 12.931




T20260703130703




BLK: 2,SNR1: 9.3802 ,SNR2: 16.225




F20260703130703




BLK: 2,SNR1: 4.3452 ,SNR2: 11.013




3C190 2026/07/03 4.15UT TOYOKAWA-FUJI



T20260703130703




BLK: 7,SNR1: 9.2448 ,SNR2: 15.975





3C190 2026/07/03 4.15UT TOYOKAWA-KISO



K20260703130700




BLK: 7,SNR1: 1.8699 ,SNR2: 11.613



F20260703130703





BLK: 3,SNR1: 3.7623 ,SNR2: 14.238




Frequency (Hz)

K20260703130700




BLK: 3,SNR1: 9.6496 ,SNR2: 16.700




Frequency (Hz)


3C190 2026/07/03 4.15UT FUJI -KISO




T20260703131930




BLK:13,SNR1: 4.9459 ,SNR2: 16.979




F20260703131930




BLK:13,SNR1: 11.808 ,SNR2: 20.949




3C196 2026/07/03 4.35UT TOYOKAWA-FUJI



T20260703131930




BLK: 8,SNR1: 4.1132 ,SNR2: 14.017





3C196 2026/07/03 4.35UT TOYOKAWA-KISO



K20260703131927




BLK: 8,SNR1: 5.7757 ,SNR2: 14.413



F20260703131930




BLK: 5,SNR1: 6.3084 ,SNR2: 15.014





3C196 2026/07/03 4.35UT FUJI -KISO



K20260703131927




BLK: 5,SNR1: 6.7511 ,SNR2: 16.842




T20260703133039




BLK: 2,SNR1: 8.8701 ,SNR2: 25.570




F20260703133039





BLK: 2,SNR1: 11.627 ,SNR2: 34.092




0821+394 2026/07/03 4.54UT TOYOKAWA-FUJI





T20260703133039




BLK: 5,SNR1: 9.1139 ,SNR2: 16.305




K20260703133036




BLK: 5,SNR1: 9.4461 ,SNR2: 17.597




0821+394 2026/07/03 4.54UT TOYOKAWA-KISO





F20260703133039




BLK: 1,SNR1: 3.1815 ,SNR2: 11.955




K20260703133036





BLK: 1,SNR1: 4.6798 ,SNR2: 13.006




0821+394 2026/07/03 4.54UT FUJI -KISO



T20260703134217





BLK: 2,SNR1: 1.4561 ,SNR2: 9.4800





0834-19 2026/07/03 4.73UT TOYOKAWA-FUJI



F20260703134217




BLK: 2,SNR1: 6.6448 ,SNR2: 23.135





T20260703134217




No.Good Data




K20260703134214





No.Good Data




0834-19 2026/07/03 4.73UT TOYOKAWA-KISO





F20260703134217




BLK: 1,SNR1: 6.2166 ,SNR2: 15.218




K20260703134214




BLK: 1,SNR1: 6.7616 ,SNR2: 17.369




0834-19 2026/07/03 4.73UT FUJI -KISO




T20260703134722




BLK: 2,SNR1: 10.511 ,SNR2: 26.488




F20260703134722




BLK: 2,SNR1: 5.0303 ,SNR2: 13.045




0839-071 2026/07/03 4.82UT TOYOKAWA-FUJI




T20260703134722




BLK: 9,SNR1: 6.3824 ,SNR2: 16.519




K20260703134719





BLK: 9,SNR1: 5.9484 ,SNR2: 15.237




0839-071 2026/07/03 4.82UT TOYOKAWA-KISO





F20260703134722




No.Good Data




K20260703134719





No.Good Data




0839-071 2026/07/03 4.82UT FUJI -KISO





T20260703135824




BLK:11,SNR1: 4.9959 ,SNR2: 14.348




F20260703135824





BLK:11,SNR1: 12.592 ,SNR2: 22.224




3C208 2026/07/03 5.00UT TOYOKAWA-FUJI



T20260703135824





BLK:10,SNR1: 9.5651 ,SNR2: 21.204





3C208 2026/07/03 5.00UT TOYOKAWA-KISO



K20260703135821




BLK:10,SNR1: 13.796 ,SNR2: 32.421



F20260703135824





BLK: 8,SNR1: 14.030 ,SNR2: 24.732





3C208 2026/07/03 5.00UT FUJI -KISO



K20260703135821




BLK: 8,SNR1: 13.659 ,SNR2: 31.757





T20260703141506




No.Good Data




F20260703141506




No.Good Data




3C216 2026/07/03 5.28UT TOYOKAWA-FUJI





T20260703141506




BLK: 2,SNR1: 18.091 ,SNR2: 31.694




K20260703141503




BLK: 2,SNR1: 16.702 ,SNR2: 29.378




3C216 2026/07/03 5.28UT TOYOKAWA-KISO





F20260703141506




No.Good Data




K20260703141503




No.Good Data




3C216 2026/07/03 5.28UT FUJI -KISO





T20260703142716




BLK: 7,SNR1: 1.2690 ,SNR2: 2.3358




F20260703142716




BLK: 7,SNR1: 0.22089 ,SNR2: 1.2770




0919-142 2026/07/03 5.48UT TOYOKAWA-FUJI





T20260703142716




BLK: 7,SNR1: 0.97163 ,SNR2: 1.9799




K20260703142713




BLK: 7,SNR1: 7.1831 ,SNR2: 12.845




0919-142 2026/07/03 5.48UT TOYOKAWA-KISO





F20260703142716




BLK: 7,SNR1: 8.5985 ,SNR2: 16.071




K20260703142713




BLK: 7,SNR1: 7.2227 ,SNR2: 12.913




0919-142 2026/07/03 5.48UT FUJI -KISO




T20260703143356




BLK: 1,SNR1: 3.2455 ,SNR2: 13.437




F20260703143356




BLK: 1,SNR1: 5.2359 ,SNR2: 19.938




0926+117 2026/07/03 5.59UT TOYOKAWA-FUJI




T20260703143356




BLK: 2,SNR1: 11.757 ,SNR2: 28.851




K20260703143353





BLK: 2,SNR1: 18.247 ,SNR2: 32.071




0926+117 2026/07/03 5.59UT TOYOKAWA-KISO



F20260703143356





BLK: 2,SNR1: 9.6481 ,SNR2: 23.746




Frequency (Hz)

K20260703143353




BLK: 2,SNR1: 2.0734 ,SNR2: 9.8677





Frequency (Hz)


0926+117 2026/07/03 5.59UT FUJI -KISO





T20260703144140




No.Good Data




F20260703144140





No.Good Data




3C222 2026/07/03 5.72UT TOYOKAWA-FUJI





T20260703144140




BLK: 2,SNR1: 0.24987 ,SNR2: 2.3858




K20260703144137




BLK: 2,SNR1: 9.8906 ,SNR2: 24.622




3C222 2026/07/03 5.72UT TOYOKAWA-KISO





F20260703144140




BLK: 2,SNR1: 11.858 ,SNR2: 28.889




K20260703144137




BLK: 2,SNR1: 9.1422 ,SNR2: 22.806




3C222 2026/07/03 5.72UT FUJI -KISO




T20260703144840




BLK: 8,SNR1: 1.2209 ,SNR2: 3.7742




F20260703144840




BLK: 8,SNR1: 2.0516 ,SNR2: 5.3954




0941-08 2026/07/03 5.84UT TOYOKAWA-FUJI




T20260703144840




BLK: 4,SNR1: 2.8422 ,SNR2: 8.5492




K20260703144837





BLK: 4,SNR1: 2.3183 ,SNR2: 5.9464




0941-08 2026/07/03 5.84UT TOYOKAWA-KISO



F20260703144840





BLK: 8,SNR1: 4.5622 ,SNR2: 11.672




Frequency (Hz)

K20260703144837




BLK: 8,SNR1: 5.9030 ,SNR2: 15.910





Frequency (Hz)


0941-08 2026/07/03 5.84UT FUJI -KISO





T20260703145702




BLK: 4,SNR1: 10.813 ,SNR2: 18.595




F20260703145702





BLK: 4,SNR1: 8.9522 ,SNR2: 22.081




3C230 2026/07/03 5.98UT TOYOKAWA-FUJI





T20260703145702




BLK: 6,SNR1: 12.483 ,SNR2: 21.577




K20260703145659





BLK: 6,SNR1: 9.5903 ,SNR2: 24.632




3C230 2026/07/03 5.98UT TOYOKAWA-KISO





F20260703145702




No.Good Data




K20260703145659





No.Good Data




3C230 2026/07/03 5.98UT FUJI -KISO



T20260703151303





BLK:13,SNR1: 1.6792 ,SNR2: 4.7950




Frequency (Hz)

F20260703151303




BLK:13,SNR1: 8.1801 ,SNR2: 20.353





Frequency (Hz)


3C237 2026/07/03 6.25UT TOYOKAWA-FUJI



T20260703151303





BLK:11,SNR1: 0.53132 ,SNR2: 1.7113




Frequency (Hz)

K20260703151300




BLK:11,SNR1: 3.3933 ,SNR2: 9.9220




Frequency (Hz)


3C237 2026/07/03 6.25UT TOYOKAWA-KISO




F20260703151303




BLK: 7,SNR1: 6.5264 ,SNR2: 18.755




K20260703151300




BLK: 7,SNR1: 4.9347 ,SNR2: 14.310




3C237 2026/07/03 6.25UT FUJI -KISO



T20260703151919




BLK: 6,SNR1: 8.7072 ,SNR2: 22.357




Frequency (Hz)

F20260703151919




BLK: 6,SNR1: 6.7752 ,SNR2: 17.836





Frequency (Hz)


1011+110 2026/07/03 6.35UT TOYOKAWA-FUJI




T20260703151919




BLK:10,SNR1: 8.7265 ,SNR2: 22.404




K20260703151916




BLK:10,SNR1: 11.166 ,SNR2: 26.841




1011+110 2026/07/03 6.35UT TOYOKAWA-KISO




F20260703151919




BLK: 8,SNR1: 6.6391 ,SNR2: 17.631




K20260703151916




BLK: 8,SNR1: 13.861 ,SNR2: 32.444




1011+110 2026/07/03 6.35UT FUJI -KISO



T20260703152700





BLK:11,SNR1: 16.284 ,SNR2: 27.510




Frequency (Hz)

F20260703152700




BLK:11,SNR1: 6.3116 ,SNR2: 18.601




Frequency (Hz)


3C241 2026/07/03 6.48UT TOYOKAWA-FUJI



T20260703152700





BLK:10,SNR1: 16.576 ,SNR2: 28.071




Frequency (Hz)

K20260703152657




BLK:10,SNR1: 12.920 ,SNR2: 21.914





Frequency (Hz)


3C241 2026/07/03 6.48UT TOYOKAWA-KISO





F20260703152700




BLK: 7,SNR1: 6.3187 ,SNR2: 18.613




K20260703152657





BLK: 7,SNR1: 9.6793 ,SNR2: 33.157




3C241 2026/07/03 6.48UT FUJI -KISO



T20260703153829





BLK:26,SNR1: 12.720 ,SNR2: 23.261




Frequency (Hz)

F20260703153829




BLK:26,SNR1: 8.6595 ,SNR2: 16.292





Frequency (Hz)


1031-11 2026/07/03 6.67UT TOYOKAWA-FUJI



T20260703153829




BLK:29,SNR1: 12.440 ,SNR2: 28.281




Frequency (Hz)

K20260703153826




BLK:29,SNR1: 12.261 ,SNR2: 28.943





Frequency (Hz)


1031-11 2026/07/03 6.67UT TOYOKAWA-KISO



F20260703153829





BLK:30,SNR1: 8.7516 ,SNR2: 16.460




Frequency (Hz)

K20260703153826




BLK:30,SNR1: 10.030 ,SNR2: 23.722




Frequency (Hz)


1031-11 2026/07/03 6.67UT FUJI -KISO



T20260703154303




BLK: 9,SNR1: 4.3771 ,SNR2: 14.382




Frequency (Hz)

F20260703154303




BLK: 9,SNR1: 7.9745 ,SNR2: 19.634




Frequency (Hz)


1035-058 2026/07/03 6.75UT TOYOKAWA-FUJI




T20260703154303




BLK: 3, SNR1: 4.3442 , SNR2: 14.278




K20260703154300




BLK: 3, SNR1: 9.7557 , SNR2: 23.922




1035-058 2026/07/03 6.75UT TOYOKAWA-KISO



F20260703154303




BLK: 3,SNR1: 10.149 ,SNR2: 24.728




Frequency (Hz)

K20260703154300




BLK: 3,SNR1: 9.3400 ,SNR2: 22.875




Frequency (Hz)


1035-058 2026/07/03 6.75UT FUJI -KISO



T20260703155215





No.Good Data




Frequency (Hz)

F20260703155215




No.Good Data




Frequency (Hz)


1044-008 2026/07/03 6.90UT TOYOKAWA-FUJI



T20260703155215





BLK: 2,SNR1: 11.052 ,SNR2: 31.538




Frequency (Hz)

K20260703155212




BLK: 2,SNR1: 7.3223 ,SNR2: 19.037





Frequency (Hz)


1044-008 2026/07/03 6.90UT TOYOKAWA-KISO



F20260703155215





BLK: 4,SNR1: 8.3912 ,SNR2: 15.309




Frequency (Hz)

K20260703155212




BLK: 4,SNR1: 8.5646 ,SNR2: 15.984





Frequency (Hz)


1044-008 2026/07/03 6.90UT FUJI -KISO



T20260703160320





BLK: 1,SNR1: 2.2135 ,SNR2: 10.532




Frequency (Hz)

F20260703160320




BLK: 1,SNR1: 8.8841 ,SNR2: 21.886





Frequency (Hz)


1055+01 2026/07/03 7.08UT TOYOKAWA-FUJI



T20260703160320





BLK: 3,SNR1: 5.1706 ,SNR2: 14.177




Frequency (Hz)

K20260703160317




BLK: 3,SNR1: 7.9505 ,SNR2: 20.490





Frequency (Hz)


1055+01 2026/07/03 7.08UT TOYOKAWA-KISO



F20260703160320





BLK: 1,SNR1: 2.3570 ,SNR2: 11.031




Frequency (Hz)

K20260703160317




BLK: 1,SNR1: 3.2745 ,SNR2: 8.0782




Frequency (Hz)


1055+01 2026/07/03 7.08UT FUJI -KISO



T20260703161437





BLK: 1,SNR1: 8.1763 ,SNR2: 23.542




Frequency (Hz)

F20260703161437




BLK: 1,SNR1: 0.60957 ,SNR2: 1.9172





Frequency (Hz)


1107+109 2026/07/03 7.27UT TOYOKAWA-FUJI



T20260703161437





BLK: 5,SNR1: 4.1986 ,SNR2: 12.028




Frequency (Hz)

K20260703161434




BLK: 5,SNR1: 3.8169 ,SNR2: 11.565





Frequency (Hz)


1107+109 2026/07/03 7.27UT TOYOKAWA-KISO



F20260703161437





BLK: 5,SNR1: 7.5104 ,SNR2: 19.999




Frequency (Hz)

K20260703161434




BLK: 5,SNR1: 8.5770 ,SNR2: 22.760





Frequency (Hz)


1107+109 2026/07/03 7.27UT FUJI -KISO





T20260703162415




BLK: 5,SNR1: 3.1136 ,SNR2: 7.3864




F20260703162415




BLK: 5,SNR1: 1.6798 ,SNR2: 6.2471




3C255 2026/07/03 7.43UT TOYOKAWA-FUJI



T20260703162415





BLK: 1,SNR1: 2.3178 ,SNR2: 10.099




Frequency (Hz)

K20260703162412




BLK: 1,SNR1: 1.4236 ,SNR2: 5.4571





Frequency (Hz)


3C255 2026/07/03 7.43UT TOYOKAWA-KISO



F20260703162415





BLK: 1,SNR1: 3.3686 ,SNR2: 23.028




Frequency (Hz)

K20260703162412




BLK: 1,SNR1: 0.66980 ,SNR2: 2.0607





Frequency (Hz)


3C255 2026/07/03 7.43UT FUJI -KISO



T20260703164813





BLK: 4,SNR1: 2.9438 ,SNR2: 16.915




Frequency (Hz)

F20260703164813




BLK: 4,SNR1: 3.8251 ,SNR2: 9.3600





Frequency (Hz)


3C263.1 2026/07/03 7.83UT TOYOKAWA-FUJI



T20260703164813





No.Good Data




Frequency (Hz)

K20260703164810




No.Good Data




Frequency (Hz)


3C263.1 2026/07/03 7.83UT TOYOKAWA-KISO



F20260703164813





BLK: 2,SNR1: 1.5789 ,SNR2: 2.4533




Frequency (Hz)

K20260703164810




BLK: 2,SNR1: 0.65281E-01,SNR2: 1.4468




Frequency (Hz)


3C263.1 2026/07/03 7.83UT FUJI -KISO



T20260703165440




BLK: 8,SNR1: 0.56924 ,SNR2: 6.8036




Frequency (Hz)

F20260703165440




BLK: 8,SNR1: 5.4821 ,SNR2: 9.9167





Frequency (Hz)


3C267 2026/07/03 7.94UT TOYOKAWA-FUJI



T20260703165440





BLK: 8,SNR1: 0.87826 ,SNR2: 3.2918




Frequency (Hz)

K20260703165437




BLK: 8,SNR1: 5.0124 ,SNR2: 9.0379




Frequency (Hz)


3C267 2026/07/03 7.94UT TOYOKAWA-KISO



F20260703165440




BLK: 9,SNR1: 7.4053 ,SNR2: 13.264




Frequency (Hz)

K20260703165437




BLK: 9,SNR1: 5.3000 ,SNR2: 9.5679





Frequency (Hz)


3C267 2026/07/03 7.94UT FUJI -KISO



T20260703171354




BLK: 3,SNR1: 15.555 ,SNR2: 39.376




Frequency (Hz)

F20260703171354




BLK: 3,SNR1: 14.664 ,SNR2: 27.167




Frequency (Hz)


1206+439 2026/07/03 8.26UT TOYOKAWA-FUJI



T20260703171354




BLK: 4, SNR1: 7.2127 , SNR2: 18.209




Frequency (Hz)

K20260703171351




BLK: 4, SNR1: 6.8420 , SNR2: 19.920




Frequency (Hz)


1206+439 2026/07/03 8.26UT TOYOKAWA-KISO



F20260703171354




BLK: 4,SNR1: 7.4466 ,SNR2: 19.016




Frequency (Hz)

K20260703171351




BLK: 4,SNR1: 15.444 ,SNR2: 35.750





Frequency (Hz)


1206+439 2026/07/03 8.26UT FUJI -KISO



T20260703174342





No.Good Data




Frequency (Hz)

F20260703174342




No.Good Data





Frequency (Hz)


1236+327 2026/07/03 8.76UT TOYOKAWA-FUJI



T20260703174342





No.Good Data




Frequency (Hz)

K20260703174339




No.Good Data





Frequency (Hz)


1236+327 2026/07/03 8.76UT TOYOKAWA-KISO



F20260703174342





No.Good Data




Frequency (Hz)

K20260703174339



No.Good Data



Frequency (Hz)

1236+327 2026/07/03 8.76UT FUJI -KISO

