






T20260410062349




BLK: 6,SNR1: 13.269 ,SNR2: 23.513




F20260410062351





BLK: 6,SNR1: 7.1790 ,SNR2: 18.476




1944+183 2026/04/09 21.43UT TOYOKAWA-FUJI





T20260410062349




BLK: 2, SNR1: 8.4535 ,SNR2: 19.878




K20260410062346





BLK: 2, SNR1: 10.138 ,SNR2: 25.060




1944+183 2026/04/09 21.43UT TOYOKAWA-KISO





F20260410062351




BLK: 6,SNR1: 17.466 ,SNR2: 30.859




K20260410062346





BLK: 6,SNR1: 18.924 ,SNR2: 36.579




1944+183 2026/04/09 21.43UT FUJI -KISO



T20260410063124





BLK: 5,SNR1: 12.671 ,SNR2: 32.020




Frequency (Hz)

F20260410063126




BLK: 5,SNR1: 10.709 ,SNR2: 22.394





Frequency (Hz)


1951+149 2026/04/09 21.55UT TOYOKAWA-FUJI



T20260410063124





BLK: 4,SNR1: 7.9087 ,SNR2: 19.576




Frequency (Hz)

K20260410063121




BLK: 4,SNR1: 11.629 ,SNR2: 28.611





Frequency (Hz)


1951+149 2026/04/09 21.55UT TOYOKAWA-KISO



F20260410063126





BLK: 7,SNR1: 8.7033 ,SNR2: 20.178




Frequency (Hz)

1951+149 2026/04/09 21.55UT FUJI -KISO


K20260410063121





BLK: 7,SNR1: 13.172 ,SNR2: 27.788




Frequency (Hz)





T20260410064613




No.Good Data




FUJI





No.Good Data




2007+502 2026/04/09 21.80UT TOYOKAWA-FUJI



T20260410064613





BLK: 1,SNR1: 21.439 ,SNR2: 44.639




Frequency (Hz)

K20260410064610




BLK: 1,SNR1: 29.606 ,SNR2: 41.919





Frequency (Hz)


2007+502 2026/04/09 21.80UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20260410064610




No.Good Data




Frequency (Hz)


2007+502 2026/04/09 21.80UT FUJI -KISO




T20260410065358



Time (sec)




BLK: 4,SNR1: 17.439 ,SNR2: 32.696




Frequency (Hz)


F20260410065400



Time (sec)




BLK: 4,SNR1: 5.8471 ,SNR2: 17.227





Frequency (Hz)


2014+358 2026/04/09 21.93UT TOYOKAWA-FUJI



T20260410065358





BLK: 8,SNR1: 8.2152 ,SNR2: 20.439




Frequency (Hz)

K20260410065355




BLK: 8,SNR1: 8.1684 ,SNR2: 21.017





Frequency (Hz)


2014+358 2026/04/09 21.93UT TOYOKAWA-KISO



F20260410065400





BLK: 4,SNR1: 5.8511 ,SNR2: 17.238




Frequency (Hz)

K20260410065355




BLK: 4,SNR1: 11.317 ,SNR2: 27.973




Frequency (Hz)


2014+358 2026/04/09 21.93UT FUJI -KISO



T20260410070206





BLK: 8,SNR1: 6.3310 ,SNR2: 16.940




Frequency (Hz)

2022+119 2026/04/09 22.06UT TOYOKAWA-FUJI


F20260410070208




BLK: 8,SNR1: 8.0167 ,SNR2: 23.271




Frequency (Hz)



T20260410070206





BLK: 3,SNR1: 8.4003 ,SNR2: 21.456




Frequency (Hz)

K20260410070203




BLK: 3,SNR1: 8.4775 ,SNR2: 25.330





Frequency (Hz)


2022+119 2026/04/09 22.06UT TOYOKAWA-KISO



F20260410070208





BLK: 3,SNR1: 9.7283 ,SNR2: 27.708




Frequency (Hz)

K20260410070203




BLK: 3,SNR1: 7.3416 ,SNR2: 19.644





Frequency (Hz)


2022+119 2026/04/09 22.06UT FUJI -KISO



T20260410070958





BLK:10,SNR1: 12.140 ,SNR2: 22.523




Frequency (Hz)

2029-018 2026/04/09 22.19UT TOYOKAWA-FUJI


F20260410071000





BLK:10,SNR1: 7.1300 ,SNR2: 20.841




Frequency (Hz)



T20260410070958





BLK: 5,SNR1: 6.8142 ,SNR2: 17.562




Frequency (Hz)

K20260410070955




BLK: 5,SNR1: 7.5147 ,SNR2: 18.928





Frequency (Hz)


2029-018 2026/04/09 22.19UT TOYOKAWA-KISO



F20260410071000





BLK: 5, SNR1: 7.1622 ,SNR2: 23.573




Frequency (Hz)

K20260410070955




BLK: 5, SNR1: 10.030 ,SNR2: 18.678





Frequency (Hz)


2029-018 2026/04/09 22.19UT FUJI -KISO



T20260410071414





BLK:14,SNR1: 17.166 ,SNR2: 32.107




Frequency (Hz)

F20260410071416




BLK:14,SNR1: 5.2806 ,SNR2: 15.840





Frequency (Hz)


2034-066 2026/04/09 22.27UT TOYOKAWA-FUJI



T20260410071414





BLK:15,SNR1: 22.792 ,SNR2: 41.783




Frequency (Hz)

K20260410071411




BLK:15,SNR1: 6.8868 ,SNR2: 20.129





Frequency (Hz)


2034-066 2026/04/09 22.27UT TOYOKAWA-KISO



F20260410071416





BLK:15,SNR1: 7.8434 ,SNR2: 22.599




Frequency (Hz)

K20260410071411




BLK:15,SNR1: 6.8947 ,SNR2: 20.153





Frequency (Hz)


2034-066 2026/04/09 22.27UT FUJI -KISO



T20260410071843





BLK: 3,SNR1: 28.482 ,SNR2: 66.879




Frequency (Hz)

F20260410071845




BLK: 3,SNR1: 8.6413 ,SNR2: 21.317





Frequency (Hz)


2038-013 2026/04/09 22.34UT TOYOKAWA-FUJI



T20260410071843





BLK: 4,SNR1: 31.208 ,SNR2: 66.070




Frequency (Hz)

K20260410071840




BLK: 4,SNR1: 13.041 ,SNR2: 23.041





Frequency (Hz)


2038-013 2026/04/09 22.34UT TOYOKAWA-KISO



F20260410071845





BLK: 5, SNR1: 18.962 , SNR2: 33.037




Frequency (Hz)

K20260410071840




BLK: 5, SNR1: 12.785 , SNR2: 26.925





Frequency (Hz)


2038-013 2026/04/09 22.34UT FUJI -KISO



T20260410072436





BLK: 8,SNR1: 2.4852 ,SNR2: 6.1026




Frequency (Hz)

3C422 2026/04/09 22.44UT TOYOKAWA-FUJI


F20260410072438





BLK: 8,SNR1: 10.453 ,SNR2: 26.336




Frequency (Hz)





T20260410072436




BLK: 5, SNR1: 5.4074 ,SNR2: 13.533




K20260410072433





BLK: 5, SNR1: 9.4900 ,SNR2: 28.278




3C422 2026/04/09 22.44UT TOYOKAWA-KISO



F20260410072438





BLK: 9,SNR1: 9.9833 ,SNR2: 30.247





3C422 2026/04/09 22.44UT FUJI -KISO



K20260410072433




BLK: 9,SNR1: 7.2580 ,SNR2: 18.899



T20260410073631





BLK:13,SNR1: 14.174 ,SNR2: 43.711





2056+028 2026/04/09 22.64UT TOYOKAWA-FUJI



F20260410073633




BLK:13,SNR1: 3.4035 ,SNR2: 8.1737





T20260410073631




BLK: 9,SNR1: 29.325 ,SNR2: 70.281




K20260410073628





BLK: 9,SNR1: 10.630 ,SNR2: 22.750




2056+028 2026/04/09 22.64UT TOYOKAWA-KISO



F20260410073633





BLK:11,SNR1: 5.5682 ,SNR2: 15.941




Frequency (Hz)

K20260410073628




BLK:11,SNR1: 9.6497 ,SNR2: 21.429






Frequency (Hz)



2056+028 2026/04/09 22.64UT FUJI -KISO




T20260410074513




F20260410074515





2105-072 2026/04/09 22.78UT TOYOKAWA-FUJI







BLK: 4,SNR1: 0.21394 ,SNR2: 2.2884





BLK: 4,SNR1: 4.4180 ,SNR2: 12.166




2105-072 2026/04/09 22.78UT TOYOKAWA-KISO



F20260410074515





BLK: 3,SNR1: 3.3970 ,SNR2: 9.8149




Frequency (Hz)

K20260410074510




BLK: 3,SNR1: 3.6342 ,SNR2: 10.441





Frequency (Hz)


2105-072 2026/04/09 22.78UT FUJI -KISO



T20260410080019





BLK: 4,SNR1: 2.8244 ,SNR2: 7.0484




Frequency (Hz)

F20260410080021




BLK: 4,SNR1: 1.1853 ,SNR2: 3.6546





Frequency (Hz)


2120-102 2026/04/09 23.03UT TOYOKAWA-FUJI



T20260410080019





BLK: 5,SNR1: 11.828 ,SNR2: 28.499




Frequency (Hz)

K20260410080016




BLK: 5,SNR1: 8.1156 ,SNR2: 23.019




Frequency (Hz)


2120-102 2026/04/09 23.03UT TOYOKAWA-KISO




F20260410080021




BLK: 6,SNR1: 0.85103 ,SNR2: 2.6100




K20260410080016





BLK: 6,SNR1: 2.8075 ,SNR2: 8.1505




2120-102 2026/04/09 23.03UT FUJI -KISO



T20260410081058





BLK:11,SNR1: 1.7088 ,SNR2: 5.5243




Frequency (Hz)

F20260410081100




BLK:11,SNR1: 0.83816 ,SNR2: 3.2616




Frequency (Hz)


2131+379 2026/04/09 23.21UT TOYOKAWA-FUJI




T20260410081058




BLK:15,SNR1: 1.4868 ,SNR2: 4.9117




K20260410081055




BLK:15,SNR1: 1.5003 ,SNR2: 4.4840




2131+379 2026/04/09 23.21UT TOYOKAWA-KISO



F20260410081100




BLK:10,SNR1: 0.30560 ,SNR2: 2.0423




Frequency (Hz)

K20260410081055





BLK:10,SNR1: 1.7589 ,SNR2: 3.5441





Frequency (Hz)

2131+379 2026/04/09 23.21UT FUJI -KISO







BLK: 1,SNR1: -0.65612E-01,SNR2: 1.3918





BLK: 1,SNR1: 7.8565 ,SNR2: 18.101




2147+145 2026/04/09 23.49UT TOYOKAWA-FUJI





T20260410082736




No.Good Data




K20260410082733




No.Good Data




2147+145 2026/04/09 23.49UT TOYOKAWA-KISO




F20260410082738




BLK: 1,SNR1: 11.483 ,SNR2: 25.639




K20260410082733





BLK: 1,SNR1: 2.0661 ,SNR2: 4.3858




2147+145 2026/04/09 23.49UT FUJI -KISO



T20260410083641





BLK: 6,SNR1: 59.756 ,SNR2: 74.947




Frequency (Hz)

2156-043 2026/04/09 23.64UT TOYOKAWA-FUJI


F20260410083643





BLK: 6,SNR1: 4.8340 ,SNR2: 11.503




Frequency (Hz)



T20260410083641





BLK: 2,SNR1: 1.3182 ,SNR2: 3.6310




Frequency (Hz)

K20260410083638




BLK: 2,SNR1: 3.2422 ,SNR2: 7.9241




Frequency (Hz)


2156-043 2026/04/09 23.64UT TOYOKAWA-KISO





F20260410083643




BLK: 3,SNR1: 1.5096 ,SNR2: 7.5984




K20260410083638




BLK: 3,SNR1: 7.8496 ,SNR2: 12.347




2156-043 2026/04/09 23.64UT FUJI -KISO




T20260410084330




BLK:10,SNR1:-0.99537E-01,SNR2: 1.1043




F20260410084332





BLK:10,SNR1: 2.0726 ,SNR2: 5.5012




2203-18 2026/04/09 23.75UT TOYOKAWA-FUJI




T20260410084330




BLK:15,SNR1:-0.98212E-01,SNR2: 1.1048




K20260410084327




BLK:15,SNR1: 7.0175 ,SNR2: 15.690




2203-18 2026/04/09 23.75UT TOYOKAWA-KISO




F20260410084332




BLK:13,SNR1: 1.8095 ,SNR2: 4.6712




K20260410084327





BLK:13,SNR1: 7.4332 ,SNR2: 16.604




2203-18 2026/04/09 23.75UT FUJI -KISO



T20260410084952





BLK:10,SNR1: 10.769 ,SNR2: 27.440




Frequency (Hz)

F20260410084954




BLK:10,SNR1: 11.820 ,SNR2: 30.097





Frequency (Hz)


2210+016 2026/04/09 23.86UT TOYOKAWA-FUJI



T20260410084952





BLK: 7,SNR1: 11.443 ,SNR2: 29.153




Frequency (Hz)

K20260410084949




BLK: 7,SNR1: 11.568 ,SNR2: 32.521





Frequency (Hz)


2210+016 2026/04/09 23.86UT TOYOKAWA-KISO




F20260410084954




BLK: 4, SNR1: 13.690 , SNR2: 34.565




K20260410084949




BLK: 4, SNR1: 11.013 , SNR2: 31.851




2210+016 2026/04/09 23.86UT FUJI -KISO



T20260410090302




BLK: 2, SNR1: 6.8456 , SNR2: 26.091





3C446 2026/04/10 0.08UT TOYOKAWA-FUJI


F20260410090304




BLK: 2, SNR1: 14.039 , SNR2: 34.238



T20260410090302




BLK: 3, SNR1: 12.200 , SNR2: 29.802





3C446 2026/04/10 0.08UT TOYOKAWA-KISO


K20260410090259




BLK: 3, SNR1: 11.271 , SNR2: 28.006



F20260410090304




BLK: 3,SNR1: 10.460 ,SNR2: 26.040





3C446 2026/04/10 0.08UT FUJI -KISO



K20260410090259




BLK: 3,SNR1: 10.627 ,SNR2: 26.475





T20260410090945




BLK:17,SNR1: 2.2878 ,SNR2: 4.4938




F20260410090947





BLK:17,SNR1: 1.3969 ,SNR2: 3.6810




2229-093 2026/04/10 0.19UT TOYOKAWA-FUJI



T20260410090945





BLK:10,SNR1: 2.1598 ,SNR2: 4.3100





2229-093 2026/04/10 0.19UT TOYOKAWA-KISO


K20260410090942




BLK:10,SNR1: 2.3648 ,SNR2: 7.5941





F20260410090947




BLK:15,SNR1: 5.5987 ,SNR2: 11.910




K20260410090942





BLK:15,SNR1: 2.3625 ,SNR2: 7.5866




2229-093 2026/04/10 0.19UT FUJI -KISO



T20260410091812




BLK:16,SNR1: 3.6630 ,SNR2: 10.192




Frequency (Hz)

2238-113 2026/04/10 0.33UT TOYOKAWA-FUJI


F20260410091814





BLK:16,SNR1: 0.67752 ,SNR2: 2.6693




Frequency (Hz)



T20260410091812





BLK:18,SNR1: 3.3530 ,SNR2: 6.1832





2238-113 2026/04/10 0.33UT TOYOKAWA-KISO


K20260410091809




BLK:18,SNR1: 2.5390 ,SNR2: 5.6843





F20260410091814




BLK:10,SNR1: 1.5995 ,SNR2: 5.7039




K20260410091809





BLK:10,SNR1: 3.0134 ,SNR2: 5.9936




2238-113 2026/04/10 0.33UT FUJI -KISO



T20260410093101





BLK:24,SNR1: 2.2543 ,SNR2: 7.1579




Frequency (Hz)

3C454.3 2026/04/10 0.55UT TOYOKAWA-FUJI


F20260410093103





BLK:24,SNR1: 0.31486 ,SNR2: 1.4955




Frequency (Hz)



T20260410093101





BLK:16,SNR1: 3.1152 ,SNR2: 9.5571




Frequency (Hz)

3C454.3 2026/04/10 0.55UT TOYOKAWA-KISO


K20260410093058




BLK:16,SNR1: 1.0207 ,SNR2: 3.4593




Frequency (Hz)




F20260410093103




BLK:13,SNR1: 1.3259 ,SNR2: 5.7893




K20260410093058





BLK:13,SNR1: 1.0481 ,SNR2: 3.8164




3C454.3 2026/04/10 0.55UT FUJI -KISO



T20260410093843





BLK:14,SNR1: 7.1039 ,SNR2: 12.779





2259+481 2026/04/10 0.67UT TOYOKAWA-FUJI



F20260410093845




BLK:14,SNR1: 1.6045 ,SNR2: 3.8063





T20260410093843




BLK:18,SNR1: 1.5658 ,SNR2: 5.4053




K20260410093840




BLK:18,SNR1: 3.9672 ,SNR2: 5.9871




2259+481 2026/04/10 0.67UT TOYOKAWA-KISO




F20260410093845




BLK:16,SNR1: 1.5605 ,SNR2: 3.7174




K20260410093840





BLK:16,SNR1: 1.9058 ,SNR2: 4.6521




2259+481 2026/04/10 0.67UT FUJI -KISO



T20260410095337





BLK:16,SNR1: 3.5037 ,SNR2: 13.195





3C459 2026/04/10 0.92UT TOYOKAWA-FUJI



F20260410095339




BLK:16,SNR1: 7.9242 ,SNR2: 13.283



T20260410095337





BLK:17,SNR1: 3.5148 ,SNR2: 13.227





3C459 2026/04/10 0.92UT TOYOKAWA-KISO


K20260410095334




BLK:17,SNR1: 2.6756 ,SNR2: 6.9151



F20260410095339





BLK:20,SNR1: 0.76222 ,SNR2: 4.5153





3C459 2026/04/10 0.92UT FUJI -KISO



K20260410095334




BLK:20,SNR1: 4.3777 ,SNR2: 11.264



T20260410102722





BLK:13,SNR1: 21.186 ,SNR2: 27.570





2347-02 2026/04/10 1.48UT TOYOKAWA-FUJI



F20260410102724




BLK:13,SNR1: 2.6382 ,SNR2: 4.3562



T20260410102722




BLK:14,SNR1: 0.16154 ,SNR2: 2.2101





2347-02 2026/04/10 1.48UT TOYOKAWA-KISO



K20260410102719




BLK:14,SNR1: 1.8075 ,SNR2: 2.8230



F20260410102724





BLK: 6,SNR1: 3.3837 ,SNR2: 4.4327





2347-02 2026/04/10 1.48UT FUJI -KISO


K20260410102719




BLK: 6,SNR1: 1.8412 ,SNR2: 4.1657



T20260410103416




BLK:14,SNR1: 3.5458 ,SNR2: 8.6442





2354+14 2026/04/10 1.60UT TOYOKAWA-FUJI



F20260410103418




BLK:14,SNR1: 3.1177 ,SNR2: 3.8417



T20260410103416




BLK: 2, SNR1: 9.6377 ,SNR2: 24.787





2354+14 2026/04/10 1.60UT TOYOKAWA-KISO


K20260410103413




BLK: 2, SNR1: 11.026 ,SNR2: 26.274




F20260410103418




BLK: 3,SNR1: 8.4091 ,SNR2: 21.724




K20260410103413




BLK: 3,SNR1: 6.4447 ,SNR2: 16.996




2354+14 2026/04/10 1.60UT FUJI -KISO




T20260410104319




BLK: 6,SNR1: 0.72521 ,SNR2: 4.7326




F20260410104321




BLK: 6,SNR1: 4.0871 ,SNR2: 14.009




3C2 2026/04/10 1.75UT TOYOKAWA-FUJI



T20260410104319




BLK: 6,SNR1: 4.9514 ,SNR2: 16.673









3C2 2026/04/10 1.75UT TOYOKAWA-KISO

K20260410104316








BLK: 6,SNR1: 13.062 ,SNR2: 31.345










3C2 2026/04/10 1.75UT FUJI -KISO






0011+344 2026/04/10 1.87UT TOYOKAWA-FUJI








0011+344 2026/04/10 1.87UT TOYOKAWA-KISO





F20260410105042




BLK: 8,SNR1: 1.3927 ,SNR2: 4.7161




K20260410105038





BLK: 8,SNR1: 1.4996 ,SNR2: 2.2599




0011+344 2026/04/10 1.87UT FUJI -KISO




T20260410105917




BLK: 8,SNR1: 11.044 ,SNR2: 19.775




F20260410105919





BLK: 8,SNR1: -0.72210E-01,SNR2: 1.8989




0019-00 2026/04/10 2.02UT TOYOKAWA-FUJI



T20260410105917




BLK: 7,SNR1: 10.355 ,SNR2: 13.474




0019-00 2026/04/10 2.02UT TOYOKAWA-KISO


K20260410105915




BLK: 7,SNR1: 3.5540 ,SNR2: 8.4746




Frequency (Hz)




F20260410105919




BLK: 3,SNR1:-0.16117E-02,SNR2: 2.3733




K20260410105915





BLK: 3,SNR1: 2.1975 ,SNR2: 6.3783




0019-00 2026/04/10 2.02UT FUJI -KISO



T20260410110931




BLK:17,SNR1: 0.40954 ,SNR2: 2.7378





3C12 2026/04/10 2.19UT TOYOKAWA-FUJI



F20260410110933




BLK:17,SNR1: 9.7807 ,SNR2: 10.680



T20260410110931





BLK: 8, SNR1: 13.924 ,SNR2: 20.493





3C12 2026/04/10 2.19UT TOYOKAWA-KISO


K20260410110929




BLK: 8, SNR1: 5.4568 ,SNR2: 13.892



F20260410110933





BLK: 3,SNR1: 1.9693 ,SNR2: 5.1794





3C12 2026/04/10 2.19UT FUJI -KISO



K20260410110929




BLK: 3,SNR1: 6.9256 ,SNR2: 18.591




T20260410112333




BLK:14,SNR1: 1.7371 ,SNR2: 2.4107




F20260410112335





BLK:14,SNR1: 1.2901 ,SNR2: 6.3899




0044-056 2026/04/10 2.42UT TOYOKAWA-FUJI



T20260410112333




BLK:10,SNR1:-0.23189 ,SNR2: 0.87305





0044-056 2026/04/10 2.42UT TOYOKAWA-KISO


K20260410112331




BLK:10,SNR1: 2.2760 ,SNR2: 8.8568




F20260410112335




BLK: 4,SNR1: 6.7808 ,SNR2: 16.990




K20260410112331




BLK: 4,SNR1: 2.0328 ,SNR2: 8.5917




0044-056 2026/04/10 2.42UT FUJI -KISO



T20260410113054




BLK: 9,SNR1: 1.7047 ,SNR2: 5.1967





3C26 2026/04/10 2.54UT TOYOKAWA-FUJI


F20260410113056




BLK: 9,SNR1: 6.7433 ,SNR2: 12.309




T20260410113054




BLK: 9,SNR1: 5.9817 ,SNR2: 12.781




K20260410113052




BLK: 9,SNR1: 9.5312 ,SNR2: 17.098




3C26 2026/04/10 2.54UT TOYOKAWA-KISO



F20260410113056




BLK: 1,SNR1: 2.2836 ,SNR2: 8.8651




3C26 2026/04/10 2.54UT FUJI -KISO


K20260410113052




BLK: 1,SNR1: 4.2497 ,SNR2: 10.752




Frequency (Hz)





T20260410113553




BLK:13,SNR1: 3.4591 ,SNR2: 4.4748




F20260410113555




BLK:13,SNR1: 9.3155 ,SNR2: 13.647




0056-00 2026/04/10 2.63UT TOYOKAWA-FUJI




T20260410113553




BLK:12,SNR1: 4.3460 ,SNR2: 5.5909




K20260410113551



BLK:12,SNR1: 4.1382 ,SNR2: 12.226




0056-00 2026/04/10 2.63UT TOYOKAWA-KISO




F20260410113555




BLK: 2,SNR1: 7.9333 ,SNR2: 13.134




K20260410113551




BLK: 2,SNR1: 5.1145 ,SNR2: 9.2387




0056-00 2026/04/10 2.63UT FUJI -KISO



T20260410114535




BLK: 9,SNR1: 5.4019 ,SNR2: 13.779





0106+01 2026/04/10 2.79UT TOYOKAWA-FUJI



F20260410114537




BLK: 9,SNR1: 5.5417 ,SNR2: 12.184



T20260410114535




BLK: 4,SNR1: 4.5618 ,SNR2: 11.564





0106+01 2026/04/10 2.79UT TOYOKAWA-KISO


K20260410114532




BLK: 4,SNR1: 1.8052 ,SNR2: 8.7921



F20260410114537




BLK: 5,SNR1:-0.48353E-01,SNR2: 0.97095





0106+01 2026/04/10 2.79UT FUJI -KISO



K20260410114532




BLK: 5,SNR1: 5.2037 ,SNR2: 13.195



T20260410115458





BLK: 7,SNR1: 7.9343 ,SNR2: 8.6570





0115-01 2026/04/10 2.94UT TOYOKAWA-FUJI


F20260410115500




BLK: 7,SNR1: 10.011 ,SNR2: 17.994



T20260410115458





No. Good Data




Frequency (Hz)

K20260410115456




No. Good Data





Frequency (Hz)


0115-01 2026/04/10 2.94UT TOYOKAWA-KISO





F20260410115500




BLK: 1,SNR1: 2.1570 ,SNR2: 10.677




K20260410115456





BLK: 1,SNR1: 2.2912 ,SNR2: 11.209




0115-01 2026/04/10 2.94UT FUJI -KISO




T20260410120757




BLK: 2,SNR1: 27.603 ,SNR2: 48.639




F20260410120759





BLK: 2,SNR1: 22.346 ,SNR2: 43.508




0128+03 2026/04/10 3.16UT TOYOKAWA-FUJI





T20260410120757




No.Good Data




K20260410120754




No.Good Data




0128+03 2026/04/10 3.16UT TOYOKAWA-KISO





F20260410120759




BLK: 1,SNR1: 2.2207 ,SNR2: 9.3241




K20260410120754





BLK: 1,SNR1: 2.5107 ,SNR2: 12.630




0128+03 2026/04/10 3.16UT FUJI -KISO



T20260410121432





BLK:17,SNR1: 0.81105 ,SNR2: 3.2085





3C48 2026/04/10 3.27UT TOYOKAWA-FUJI



F20260410121434




BLK:17,SNR1: 14.411 ,SNR2: 13.892



T20260410121432





BLK:19,SNR1: 2.2743 ,SNR2: 7.0967





3C48 2026/04/10 3.27UT TOYOKAWA-KISO



K20260410121429




BLK:19,SNR1: 10.721 ,SNR2: 25.764



F20260410121434





BLK: 2,SNR1: 5.1935 ,SNR2: 15.349





3C48 2026/04/10 3.27UT FUJI -KISO



K20260410121429




BLK: 2,SNR1: 9.6087 ,SNR2: 26.987



T20260410123416





BLK: 8,SNR1: 3.3896 ,SNR2: 14.306





0155-109 2026/04/10 3.60UT TOYOKAWA-FUJI



F20260410123418




BLK: 8,SNR1: 0.17174 ,SNR2: 1.7836





T20260410123416




BLK: 2,SNR1: 0.71634 ,SNR2: 4.3864




K20260410123414





BLK: 2,SNR1: 5.4822 ,SNR2: 13.579




0155-109 2026/04/10 3.60UT TOYOKAWA-KISO





F20260410123418




No. Good Data




K20260410123414




No. Good Data




0155-109 2026/04/10 3.60UT FUJI -KISO




T20260410124123




BLK: 3,SNR1: 17.077 ,SNR2: 30.436




F20260410124125





BLK: 3,SNR1: 8.8212 ,SNR2: 22.256




0202+15 2026/04/10 3.72UT TOYOKAWA-FUJI





T20260410124123




BLK: 4,SNR1: 16.744 ,SNR2: 29.539




K20260410124120




BLK: 4,SNR1: 20.820 ,SNR2: 36.290




0202+15 2026/04/10 3.72UT TOYOKAWA-KISO




F20260410124125




BLK: 5,SNR1: 7.8284 ,SNR2: 19.378




K20260410124120





BLK: 5,SNR1: 9.9252 ,SNR2: 24.101




0202+15 2026/04/10 3.72UT FUJI -KISO





T20260410125314




BLK:14,SNR1: 33.855 ,SNR2: 59.435




F20260410125316





BLK:14,SNR1: 91.315 ,SNR2: 105.32




0213+178 2026/04/10 3.92UT TOYOKAWA-FUJI





T20260410125314




BLK: 9,SNR1: 81.340 ,SNR2: 89.282




K20260410125311





BLK: 9,SNR1: 17.890 ,SNR2: 31.728




0213+178 2026/04/10 3.92UT TOYOKAWA-KISO





F20260410125316




BLK: 9,SNR1: 77.893 ,SNR2: 95.844




K20260410125311




BLK: 9,SNR1: 7.5293 ,SNR2: 18.884




0213+178 2026/04/10 3.92UT FUJI -KISO



T20260410130056




BLK: 9,SNR1: 7.2773 ,SNR2: 17.696





3C67 2026/04/10 4.04UT TOYOKAWA-FUJI



F20260410130058




BLK: 9,SNR1: 10.654 ,SNR2: 32.668



T20260410130056




BLK: 9,SNR1: 6.5693 ,SNR2: 16.426





3C67 2026/04/10 4.04UT TOYOKAWA-KISO


K20260410130054




BLK: 9,SNR1: 6.9408 ,SNR2: 16.978



F20260410130058




BLK:10,SNR1: 8.1467 ,SNR2: 19.756





3C67 2026/04/10 4.04UT FUJI -KISO



K20260410130054




BLK:10,SNR1: 6.4677 ,SNR2: 15.861



T20260410131911





BLK: 2,SNR1: 0.18808 ,SNR2: 1.6078





3C71 2026/04/10 4.35UT TOYOKAWA-FUJI



F20260410131913




BLK: 2,SNR1: 2.3800 ,SNR2: 6.2309





T20260410131911




BLK: 3,SNR1: 0.27633 ,SNR2: 1.5859




K20260410131909





BLK: 3,SNR1: 6.5347 ,SNR2: 11.046




3C71 2026/04/10 4.35UT TOYOKAWA-KISO



F20260410131913





BLK: 6,SNR1: 9.9046 ,SNR2: 21.649





3C71 2026/04/10 4.35UT FUJI -KISO


K20260410131909




BLK: 6,SNR1: 3.0577 ,SNR2: 9.4015




T20260410133827




BLK: 2,SNR1: 18.912 ,SNR2: 30.950




F20260410133829





BLK: 2,SNR1: 10.454 ,SNR2: 24.194




0258+350 2026/04/10 4.67UT TOYOKAWA-FUJI



T20260410133827





No.Good Data




Frequency (Hz)

K20260410133824




No.Good Data





Frequency (Hz)


0258+350 2026/04/10 4.67UT TOYOKAWA-KISO



F20260410133829





BLK: 1,SNR1: 5.5696 ,SNR2: 17.362




Frequency (Hz)

K20260410133824




BLK: 1,SNR1: 12.121 ,SNR2: 26.477




Frequency (Hz)


0258+350 2026/04/10 4.67UT FUJI -KISO




T20260410134816




BLK: 1,SNR1: 2.8522 ,SNR2: 13.769




F20260410134818





BLK: 1,SNR1: 12.067 ,SNR2: 29.621




0308+305 2026/04/10 4.83UT TOYOKAWA-FUJI





T20260410134816




BLK: 1,SNR1: 1.6810 ,SNR2: 11.255




K20260410134813





BLK: 1,SNR1: 2.9468 ,SNR2: 13.183




0308+305 2026/04/10 4.83UT TOYOKAWA-KISO





F20260410134818




No.Good Data




K20260410134813




No.Good Data




0308+305 2026/04/10 4.83UT FUJI -KISO





T20260410135947




No. Good Data




F20260410135949




No. Good Data




0320+05 2026/04/10 5.02UT TOYOKAWA-FUJI




T20260410135947




No.Good Data




K20260410135944





No.Good Data




0320+05 2026/04/10 5.02UT TOYOKAWA-KISO



F20260410135949




BLK: 1,SNR1: 14.252 ,SNR2: 31.896




Frequency (Hz)

K20260410135944




BLK: 1,SNR1: 10.998 ,SNR2: 24.023





Frequency (Hz)


0320+05 2026/04/10 5.02UT FUJI -KISO





T20260410141309




BLK: 1,SNR1: 0.10321 ,SNR2: 0.81653




F20260410141311





BLK: 1,SNR1: 0.31278 ,SNR2: 2.8286




0333+32 2026/04/10 5.25UT TOYOKAWA-FUJI





T20260410141309




BLK: 6,SNR1: 9.2697 ,SNR2: 19.831




K20260410141306




BLK: 6,SNR1: 8.8550 ,SNR2: 15.643





0333+32 2026/04/10 5.25UT TOYOKAWA-KISO







BLK: 1,SNR1: 13.611 ,SNR2: 25.149





BLK: 1,SNR1: 10.590 ,SNR2: 18.698




0333+32 2026/04/10 5.25UT FUJI -KISO




T20260410142610




BLK: 2,SNR1: 0.30505 ,SNR2: 1.0322




F20260410142612





BLK: 2,SNR1: 1.5067 ,SNR2: 3.6997




0347+05 2026/04/10 5.46UT TOYOKAWA-FUJI





T20260410142610




No.Good Data




K20260410142607




No.Good Data




0347+05 2026/04/10 5.46UT TOYOKAWA-KISO





F20260410142612




BLK: 1,SNR1:-0.40734E-01,SNR2: 1.8558




K20260410142607





BLK: 1,SNR1: 10.722 ,SNR2: 28.327




0347+05 2026/04/10 5.46UT FUJI -KISO




T20260410144143




BLK: 4,SNR1: 9.6591 ,SNR2: 24.857




F20260410144145





BLK: 4,SNR1: 3.8872 ,SNR2: 10.855




0403-132 2026/04/10 5.72UT TOYOKAWA-FUJI




T20260410144143




BLK: 4,SNR1: 11.134 ,SNR2: 26.389




K20260410144140




BLK: 4,SNR1: 5.6894 ,SNR2: 14.299




0403-132 2026/04/10 5.72UT TOYOKAWA-KISO




F20260410144145




No.Good Data




K20260410144140




No.Good Data




0403-132 2026/04/10 5.72UT FUJI -KISO





T20260410145055




BLK: 2,SNR1: 15.380 ,SNR2: 21.727




F20260410145057





BLK: 2,SNR1: 0.88289 ,SNR2: 3.9887




0411+05 2026/04/10 5.88UT TOYOKAWA-FUJI





T20260410145055




BLK: 1,SNR1: 5.7403 ,SNR2: 21.442




K20260410145052





BLK: 1,SNR1: 8.3889 ,SNR2: 20.678




0411+05 2026/04/10 5.88UT TOYOKAWA-KISO



F20260410145057





No.Good Data




Frequency (Hz)

K20260410145052




No.Good Data





Frequency (Hz)


0411+05 2026/04/10 5.88UT FUJI -KISO




T20260410150148




BLK: 7,SNR1: 3.1716 ,SNR2: 9.9737




F20260410150150





BLK: 7,SNR1: 2.3581 ,SNR2: 8.4882




0422+178 2026/04/10 6.06UT TOYOKAWA-FUJI





T20260410150148




BLK: 4,SNR1: 2.0746 ,SNR2: 13.833




K20260410150145





BLK: 4,SNR1: 1.2824 ,SNR2: 4.5260




0422+178 2026/04/10 6.06UT TOYOKAWA-KISO



F20260410150150





BLK: 1,SNR1: 0.41916E-02,SNR2: 0.98443




Frequency (Hz)

K20260410150145








BLK: 1,SNR1: 3.9064 ,SNR2: 9.8143




Frequency (Hz)


0422+178 2026/04/10 6.06UT FUJI -KISO







3C119 2026/04/10 6.18UT TOYOKAWA-FUJI







BLK: 9,SNR1: 1.3196 ,SNR2: 3.5329





BLK: 9,SNR1: 5.6622 ,SNR2: 21.458




3C119 2026/04/10 6.18UT TOYOKAWA-KISO








BLK: 5,SNR1: 2.4085 ,SNR2: 5.9772



Frequency (Hz)




BLK: 5,SNR1: 1.2254 ,SNR2: 3.6860





Frequency (Hz)


3C119 2026/04/10 6.18UT FUJI -KISO





T20260410155724




BLK: 3,SNR1: 0.26257 ,SNR2: 1.5876




F20260410155726





BLK: 3,SNR1: 0.39511 ,SNR2: 2.9440




3C138 2026/04/10 6.98UT TOYOKAWA-FUJI





T20260410155724




BLK: 1,SNR1: 0.10835 ,SNR2: 1.6733




K20260410155721





BLK: 1,SNR1: 3.2468 ,SNR2: 17.704




3C138 2026/04/10 6.98UT TOYOKAWA-KISO



F20260410155726





BLK: 1,SNR1: 1.8353 ,SNR2: 5.4971




Frequency (Hz)

K20260410155721




BLK: 1,SNR1: 0.39224 ,SNR2: 5.9873




Frequency (Hz)


3C138 2026/04/10 6.98UT FUJI -KISO




T20260410161057




BLK:13,SNR1: 8.3678 ,SNR2: 19.616




F20260410161059




BLK:13,SNR1: 8.6073 ,SNR2: 19.380




0531+194 2026/04/10 7.21UT TOYOKAWA-FUJI





T20260410161057




BLK:14,SNR1: 6.3925 ,SNR2: 15.346




K20260410161054




BLK:14,SNR1: 11.832 ,SNR2: 29.204




0531+194 2026/04/10 7.21UT TOYOKAWA-KISO





F20260410161059




BLK:13,SNR1: 11.222 ,SNR2: 25.480




K20260410161054





BLK:13,SNR1: 11.168 ,SNR2: 27.605




0531+194 2026/04/10 7.21UT FUJI -KISO





T20260410161919




BLK:28,SNR1: 103.80 ,SNR2: 105.89




F20260410161921





BLK:28,SNR1: 45.182 ,SNR2: 59.196




3C147 2026/04/10 7.35UT TOYOKAWA-FUJI





T20260410161919




BLK:22,SNR1: 104.16 ,SNR2: 106.26




K20260410161916




BLK:22,SNR1: 113.49 ,SNR2: 112.39





3C147 2026/04/10 7.35UT TOYOKAWA-KISO







BLK:20,SNR1: 54.646 ,SNR2: 72.059





BLK:20,SNR1: 102.22 ,SNR2: 117.22




3C147 2026/04/10 7.35UT FUJI -KISO



T20260410162728




BLK: 1,SNR1: 0.19691 ,SNR2: 1.9267




Frequency (Hz)

F20260410162730




BLK: 1,SNR1: 3.5221 ,SNR2: 13.506





Frequency (Hz)


0548+16 2026/04/10 7.49UT TOYOKAWA-FUJI




T20260410162728




BLK: 7,SNR1: 0.23758E-01,SNR2: 1.1442




K20260410162725




BLK: 7,SNR1: 3.2486 ,SNR2: 12.205




0548+16 2026/04/10 7.49UT TOYOKAWA-KISO





F20260410162730




No.Good Data




K20260410162725





No.Good Data




0548+16 2026/04/10 7.49UT FUJI -KISO



T20260410163139





BLK: 6,SNR1: 36.794 ,SNR2: 196.64




Frequency (Hz)

F20260410163141




BLK: 6,SNR1: 1.8050 ,SNR2: 3.0862




Frequency (Hz)


0552+12 2026/04/10 7.56UT TOYOKAWA-FUJI



T20260410163139





BLK:11,SNR1: 17.178 ,SNR2: 31.154




Frequency (Hz)

K20260410163136




BLK:11,SNR1: 6.4664 ,SNR2: 11.219





Frequency (Hz)


0552+12 2026/04/10 7.56UT TOYOKAWA-KISO



F20260410163141





BLK:10,SNR1: 1.1540 ,SNR2: 2.7884




Frequency (Hz)

K20260410163136




BLK:10,SNR1: 5.6443 ,SNR2: 10.483





Frequency (Hz)


0552+12 2026/04/10 7.56UT FUJI -KISO



T20260410163606





BLK: 4,SNR1: 10.689 ,SNR2: 25.908




Frequency (Hz)

F20260410163608




BLK: 4,SNR1: 10.648 ,SNR2: 19.028





Frequency (Hz)


0556+191 2026/04/10 7.63UT TOYOKAWA-FUJI



T20260410163606





BLK: 7,SNR1: 9.4971 ,SNR2: 23.696




Frequency (Hz)

K20260410163603




BLK: 7,SNR1: 9.2344 ,SNR2: 24.028





Frequency (Hz)


0556+191 2026/04/10 7.63UT TOYOKAWA-KISO



F20260410163608





BLK: 2,SNR1: 12.903 ,SNR2: 30.040




Frequency (Hz)

K20260410163603




BLK: 2,SNR1: 11.217 ,SNR2: 27.733





Frequency (Hz)


0556+191 2026/04/10 7.63UT FUJI -KISO



T20260410164039




BLK: 8,SNR1: 11.874 ,SNR2: 25.340




Frequency (Hz)

F20260410164041




BLK: 8,SNR1: 7.7085 ,SNR2: 18.844





Frequency (Hz)


3C152 2026/04/10 7.71UT TOYOKAWA-FUJI



T20260410164039





BLK:10,SNR1: 0.37416E-02,SNR2: 3.2688




Frequency (Hz)

K20260410164036




BLK:10,SNR1: 2.3586 ,SNR2: 11.581




Frequency (Hz)


3C152 2026/04/10 7.71UT TOYOKAWA-KISO



F20260410164041





BLK: 8,SNR1: 6.5032 ,SNR2: 15.905




Frequency (Hz)

K20260410164036




BLK: 8,SNR1: 8.1267 ,SNR2: 19.045





Frequency (Hz)


3C152 2026/04/10 7.71UT FUJI -KISO



T20260410170259





BLK: 6,SNR1: 3.7364 ,SNR2: 7.9841




Frequency (Hz)

F20260410170301




BLK: 6,SNR1: 12.843 ,SNR2: 31.007





Frequency (Hz)


3C161 2026/04/10 8.08UT TOYOKAWA-FUJI



T20260410170259





BLK:12,SNR1: 4.1681 ,SNR2: 8.1683




Frequency (Hz)

3C161 2026/04/10 8.08UT TOYOKAWA-KISO


K20260410170256





BLK:12,SNR1: 13.749 ,SNR2: 33.017




Frequency (Hz)



F20260410170301





BLK: 4,SNR1: 12.848 ,SNR2: 31.018




Frequency (Hz)

K20260410170256



BLK: 4,SNR1: 13.874 ,SNR2: 33.311



Frequency (Hz)

3C161 2026/04/10 8.08UT FUJI -KISO

