




T20260519053240





BLK: 6,SNR1: 33.108 ,SNR2: 79.281




Frequency (Hz)

F20260519053240




BLK: 6,SNR1: 10.024 ,SNR2: 24.949





Frequency (Hz)


2127+456 2026/05/18 20.57UT TOYOKAWA-FUJI



T20260519053240





BLK:12,SNR1: 16.494 ,SNR2: 41.176




Frequency (Hz)

K20260519053238




BLK:12,SNR1: 17.674 ,SNR2: 31.869





Frequency (Hz)


2127+456 2026/05/18 20.57UT TOYOKAWA-KISO



F20260519053240





BLK: 2,SNR1: 20.242 ,SNR2: 35.915




Frequency (Hz)

K20260519053238




BLK: 2,SNR1: 20.430 ,SNR2: 36.893





Frequency (Hz)


2127+456 2026/05/18 20.57UT FUJI -KISO



T20260519055757





BLK: 4,SNR1: 22.168 ,SNR2: 54.091




Frequency (Hz)

F20260519055757




BLK: 4,SNR1: 18.164 ,SNR2: 32.033





Frequency (Hz)


2152+450 2026/05/18 20.99UT TOYOKAWA-FUJI



T20260519055757





BLK: 7,SNR1: 28.950 ,SNR2: 49.198




Frequency (Hz)

K20260519055754




BLK: 7,SNR1: 11.713 ,SNR2: 20.425




Frequency (Hz)


2152+450 2026/05/18 20.99UT TOYOKAWA-KISO



F20260519055757




BLK: 3,SNR1: 9.9286 ,SNR2: 17.259




Frequency (Hz)

K20260519055754




BLK: 3,SNR1: 16.809 ,SNR2: 29.844





Frequency (Hz)


2152+450 2026/05/18 20.99UT FUJI -KISO



T20260519060525





BLK: 5, SNR1: 2.1077 ,SNR2: 10.558




Frequency (Hz)

F20260519060525




BLK: 5, SNR1: 1.8744 ,SNR2: 6.7057





Frequency (Hz)


2159+408 2026/05/18 21.12UT TOYOKAWA-FUJI



T20260519060525





No.Good Data




Frequency (Hz)

K20260519060522




No.Good Data





Frequency (Hz)


2159+408 2026/05/18 21.12UT TOYOKAWA-KISO



F20260519060525





BLK: 1,SNR1: 10.145 ,SNR2: 24.223




Frequency (Hz)

K20260519060522




BLK: 1,SNR1: 2.0973 ,SNR2: 7.6047





Frequency (Hz)


2159+408 2026/05/18 21.12UT FUJI -KISO



T20260519061304





BLK: 1,SNR1:-0.10049E-01,SNR2: 0.35200




Frequency (Hz)

F20260519061304




BLK: 1,SNR1: 2.0351 ,SNR2: 16.165





Frequency (Hz)


2207+374 2026/05/18 21.25UT TOYOKAWA-FUJI



T20260519061304





BLK: 4,SNR1: 0.38346 ,SNR2: 2.3156




Frequency (Hz)

K20260519061301




BLK: 4,SNR1: 2.1933 ,SNR2: 9.1347





Frequency (Hz)


2207+374 2026/05/18 21.25UT TOYOKAWA-KISO





F20260519061304




No.Good Data




K20260519061301





No.Good Data




2207+374 2026/05/18 21.25UT FUJI -KISO



T20260519062355





BLK: 1,SNR1: 0.92731 ,SNR2: 9.0525




Frequency (Hz)

F20260519062355




BLK: 1,SNR1: 0.79188 ,SNR2: 4.6346





Frequency (Hz)


2217+128 2026/05/18 21.43UT TOYOKAWA-FUJI





T20260519062355




No.Good Data




K20260519062353





No.Good Data




2217+128 2026/05/18 21.43UT TOYOKAWA-KISO



F20260519062355





BLK: 2,SNR1: 7.7352 ,SNR2: 18.537





2217+128 2026/05/18 21.43UT FUJI -KISO



K20260519062353




BLK: 2,SNR1: 19.415 ,SNR2: 44.278



T20260519064927





BLK: 2,SNR1: 2.4507 ,SNR2: 10.216




Frequency (Hz)

2243+394 2026/05/18 21.85UT TOYOKAWA-FUJI


F20260519064927





BLK: 2,SNR1: 14.463 ,SNR2: 33.624




Frequency (Hz)



T20260519064927





BLK: 4,SNR1: 4.4372 ,SNR2: 11.515




Frequency (Hz)

2243+394 2026/05/18 21.85UT TOYOKAWA-KISO


K20260519064925





BLK: 4,SNR1: 9.2912 ,SNR2: 23.001




Frequency (Hz)



F20260519064927





BLK: 1,SNR1: 27.104 ,SNR2: 91.520




Frequency (Hz)

K20260519064925




BLK: 1,SNR1: 10.221 ,SNR2: 25.045





Frequency (Hz)


2243+394 2026/05/18 21.85UT FUJI -KISO



T20260519065741





BLK: 1,SNR1: 9.9304 ,SNR2: 24.839




Frequency (Hz)

3C454.3 2026/05/18 21.99UT TOYOKAWA-FUJI


F20260519065741





BLK: 1,SNR1: 8.7103 ,SNR2: 21.620




Frequency (Hz)



T20260519065741





BLK: 1,SNR1: 2.2163 ,SNR2: 10.887




Frequency (Hz)

3C454.3 2026/05/18 21.99UT TOYOKAWA-KISO


K20260519065738





BLK: 1,SNR1: 2.5956 ,SNR2: 11.788




Frequency (Hz)



F20260519065741




BLK: 1,SNR1: 18.022 ,SNR2: 39.075




Frequency (Hz)

K20260519065738




BLK: 1,SNR1: 3.0924 ,SNR2: 13.671





Frequency (Hz)


3C454.3 2026/05/18 21.99UT FUJI -KISO



T20260519070523





BLK: 2,SNR1: 2.6274 ,SNR2: 8.5269




Frequency (Hz)

F20260519070524





BLK: 2,SNR1: 2.8859 ,SNR2: 7.9943





Frequency (Hz)

2259+481 2026/05/18 22.12UT TOYOKAWA-FUJI







BLK: 5, SNR1: 6.8342 ,SNR2: 19.704




BLK: 5, SNR1: 9.1754 ,SNR2: 22.798




2259+481 2026/05/18 22.12UT TOYOKAWA-KISO



F20260519070524




BLK: 5,SNR1: 3.4134 ,SNR2: 8.8385




Frequency (Hz)

K20260519070520




BLK: 5,SNR1: 9.0406 ,SNR2: 22.475




Frequency (Hz)


2259+481 2026/05/18 22.12UT FUJI -KISO



T20260519072017




BLK: 1,SNR1: 0.36851 ,SNR2: 2.5258




Frequency (Hz)

3C459 2026/05/18 22.37UT TOYOKAWA-FUJI


F20260519072017




BLK: 1,SNR1:-0.11636 ,SNR2: 0.84574




Frequency (Hz)



T20260519072017




BLK: 5,SNR1: 9.7084 ,SNR2: 55.161




Frequency (Hz)

3C459 2026/05/18 22.37UT TOYOKAWA-KISO


K20260519072014





BLK: 5,SNR1: 2.0167 ,SNR2: 3.9698




Frequency (Hz)



F20260519072017





BLK: 5,SNR1:-0.13464 ,SNR2: 1.7594




Frequency (Hz)

3C459 2026/05/18 22.37UT FUJI -KISO


K20260519072014





BLK: 5,SNR1: 7.5760 ,SNR2: 13.624




Frequency (Hz)



T20260519075402





BLK: 5,SNR1: 3.0475 ,SNR2: 6.2140




Frequency (Hz)

F20260519075402




BLK: 5,SNR1: 5.2381 ,SNR2: 15.330





Frequency (Hz)


2347-02 2026/05/18 22.93UT TOYOKAWA-FUJI



T20260519075402





BLK: 3,SNR1: 1.5968 ,SNR2: 4.4748




Frequency (Hz)

2347-02 2026/05/18 22.93UT TOYOKAWA-KISO


K20260519075400





BLK: 3,SNR1: 13.033 ,SNR2: 31.283




Frequency (Hz)



F20260519075402





BLK: 5,SNR1: 4.1986 ,SNR2: 12.554




Frequency (Hz)

K20260519075400




BLK: 5,SNR1: 8.7605 ,SNR2: 22.041





Frequency (Hz)


2347-02 2026/05/18 22.93UT FUJI -KISO



T20260519080055





BLK: 1,SNR1: 9.8404 ,SNR2: 24.502




Frequency (Hz)

2354+14 2026/05/18 23.04UT TOYOKAWA-FUJI


F20260519080055





BLK: 1,SNR1: 2.3173 ,SNR2: 5.9468




Frequency (Hz)





T20260519080055




No. Good Data




K20260519080052





No. Good Data




2354+14 2026/05/18 23.04UT TOYOKAWA-KISO





F20260519080055




No.Good Data




K20260519080052





No.Good Data




2354+14 2026/05/18 23.04UT FWJ -KISO



T20260519080958





BLK:21,SNR1: 12.333 ,SNR2: 21.185




Frequency (Hz)

3C2 2026/05/18 23.19UT TOYOKAWA-FUJI


F20260519080958





BLK:21,SNR1: 12.121 ,SNR2: 27.952




Frequency (Hz)



T20260519080958



BLK:29,SNR1: 7.1253 ,SNR2: 20.613





Frequency (Hz)


3C2

2026/05/18 23.19UT TOYOKAWA-KISO


K20260519080955





BLK:29,SNR1: 15.497 ,SNR2: 35.822




Frequency (Hz)



F20260519080958





BLK:25,SNR1: 11.035 ,SNR2: 25.877




Frequency (Hz)

3C2 2026/05/18 23.19UT FUJI -KISO


K20260519080955




BLK:25,SNR1: 16.078 ,SNR2: 37.126





Frequency (Hz)







BLK: 3,SNR1: 0.18862E-01,SNR2: 0.90515




BLK: 3,SNR1: 0.65040 ,SNR2: 2.0336




0011+344 2026/05/18 23.32UT TOYOKAWA-FUJI





T20260519081720




BLK: 3,SNR1:-0.67593E-01,SNR2: 0.72472




K20260519081717




BLK: 3,SNR1: 1.7523 ,SNR2: 6.1407




0011+344 2026/05/18 23.32UT TOYOKAWA-KISO



F20260519081720




BLK: 2,SNR1: 10.652 ,SNR2: 19.810





0011+344 2026/05/18 23.32UT FUJI -KISO



K20260519081717




BLK: 2,SNR1: 9.8969 ,SNR2: 17.664



T20260519082557





BLK: 4,SNR1: 0.20823 ,SNR2: 1.2654




Frequency (Hz)

F20260519082557




BLK: 4,SNR1: 4.1464 ,SNR2: 20.861





Frequency (Hz)


0019-00 2026/05/18 23.46UT TOYOKAWA-FUJI



T20260519082557




BLK: 3,SNR1: 0.46252E-01,SNR2: 1.1542





0019-00 2026/05/18 23.46UT TOYOKAWA-KISO



K20260519082554




BLK: 3,SNR1: 3.3269 ,SNR2: 11.365



F20260519082557





BLK: 4,SNR1: 1.4501 ,SNR2: 15.774




Frequency (Hz)

K20260519082554




BLK: 4,SNR1: 0.67256 ,SNR2: 2.3500




Frequency (Hz)


0019-00 2026/05/18 23.46UT FUJI -KISO



T20260519083611





BLK: 1,SNR1: 0.10952 ,SNR2: 1.4931




Frequency (Hz)

3C12 2026/05/18 23.63UT TOYOKAWA-FUJI


F20260519083611




BLK: 1,SNR1: 0.45786 ,SNR2: 2.7950




Frequency (Hz)



T20260519083611




BLK: 1,SNR1:-0.11726 ,SNR2: 1.6510





3C12 2026/05/18 23.63UT TOYOKAWA-KISO



K20260519083608




BLK: 1,SNR1: 0.43404 ,SNR2: 2.9995





F20260519083611




No. Good Data




K20260519083608





No. Good Data




3C12 2026/05/18 23.63UT FUJI -KISO



T20260519085013




BLK: 4,SNR1: 5.6257 ,SNR2: 22.585





0044-056 2026/05/18 23.87UT TOYOKAWA-FUJI



F20260519085013




BLK: 4,SNR1:-0.28792 ,SNR2: 0.98964



T20260519085013





BLK: 2,SNR1: 0.49825 ,SNR2: 1.2497




Frequency (Hz)

K20260519085010




BLK: 2,SNR1: 0.31920 ,SNR2: 2.2955





Frequency (Hz)


0044-056 2026/05/18 23.87UT TOYOKAWA-KISO





F20260519085013




No.Good Data




K20260519085010




No.Good Data




0044-056 2026/05/18 23.87UT FUJI -KISO



T20260519090233





BLK: 5, SNR1: 10.422 ,SNR2: 26.220





0056-00 2026/05/19 0.07UT TOYOKAWA-FUJI



F20260519090233




BLK: 5, SNR1: 10.355 ,SNR2: 26.148



T20260519090233





BLK: 3,SNR1: 7.5826 ,SNR2: 19.693




Frequency (Hz)

0056-00 2026/05/19 0.07UT TOYOKAWA-KISO


K20260519090230





BLK: 3,SNR1: 12.185 ,SNR2: 30.067




Frequency (Hz)





F20260519090233




BLK: 9,SNR1: 9.8144 ,SNR2: 24.802




K20260519090230





BLK: 9,SNR1: 8.6852 ,SNR2: 22.305




0056-00 2026/05/19 0.07UT FUJI -KISO



T20260519091215




BLK: 1, SNR1: 1.4973 ,SNR2: 4.4731





0106+01 2026/05/19 0.23UT TOYOKAWA-FUJI



F20260519091215




BLK: 1, SNR1: 1.2851 ,SNR2: 5.6147



T20260519091215




BLK: 6,SNR1: 6.2228 ,SNR2: 16.958





0106+01 2026/05/19 0.23UT TOYOKAWA-KISO


K20260519091212




BLK: 6,SNR1: 13.924 ,SNR2: 34.157




F20260519091215




BLK: 1,SNR1: 8.5286 ,SNR2: 21.816




K20260519091212





BLK: 1,SNR1: 8.0159 ,SNR2: 20.637




0106+01 2026/05/19 0.23UT FUJI -KISO



T20260519092305





BLK: 5, SNR1: 6.6421 ,SNR2: 17.201





0116+31 2026/05/19 0.41UT TOYOKAWA-FUJI



F20260519092305




BLK: 5, SNR1: 5.5269 ,SNR2: 16.523



T20260519092305





BLK: 2, SNR1: 0.23399 , SNR2: 3.1805




Frequency (Hz)

K20260519092302




BLK: 2, SNR1: 2.0285 , SNR2: 6.2688




Frequency (Hz)


0116+31 2026/05/19 0.41UT TOYOKAWA-KISO





F20260519092305




BLK: 6,SNR1: 12.368 ,SNR2: 17.429




K20260519092302




BLK: 6,SNR1: 2.3221 ,SNR2: 8.8737




0116+31 2026/05/19 0.41UT FUJI -KISO



T20260519093437




BLK: 4,SNR1: 3.0188 ,SNR2: 8.5517





0128+03 2026/05/19 0.61UT TOYOKAWA-FUJI


F20260519093437




BLK: 4,SNR1: 0.15927E-01,SNR2: 3.4663



T20260519093437




BLK:18,SNR1: 1.8054 ,SNR2: 4.4532





0128+03 2026/05/19 0.61UT TOYOKAWA-KISO


K20260519093434




BLK:18,SNR1: 6.0483 ,SNR2: 14.419




F20260519093437




BLK:10,SNR1:-0.22272 ,SNR2: 1.6659




K20260519093434




BLK:10,SNR1: 1.7415 ,SNR2: 5.8744




0128+03 2026/05/19 0.61UT FUJI -KISO



T20260519094112





BLK:29,SNR1: 30.100 ,SNR2: 73.550





3C48 2026/05/19 0.71UT TOYOKAWA-FUJI


F20260519094112




BLK:29,SNR1: 3.4895 ,SNR2: 8.7613



T20260519094112




BLK:32,SNR1: 30.283 ,SNR2: 74.864





3C48 2026/05/19 0.71UT TOYOKAWA-KISO


K20260519094109




BLK:32,SNR1: 6.1117 ,SNR2: 19.149



F20260519094112




BLK:17,SNR1: 3.7853 ,SNR2: 9.1217





3C48 2026/05/19 0.71UT FUJI -KISO


K20260519094109




BLK:17,SNR1: 4.1014 ,SNR2: 13.812



T20260519100056




BLK:10,SNR1: 5.8297 ,SNR2: 16.801





0155-109 2026/05/19 1.04UT TOYOKAWA-FUJI



F20260519100056




BLK:10,SNR1: 13.637 ,SNR2: 31.709



T20260519100056





BLK: 2,SNR1: 2.0468 ,SNR2: 5.6733




Frequency (Hz)

0155-109 2026/05/19 1.04UT TOYOKAWA-KISO


K20260519100053




BLK: 2,SNR1: 10.507 ,SNR2: 25.312




Frequency (Hz)



F20260519100056




BLK: 7,SNR1: 12.826 ,SNR2: 30.510





0155-109 2026/05/19 1.04UT FUJI -KISO



K20260519100053




BLK: 7,SNR1: 8.0193 ,SNR2: 22.942



T20260519100803





BLK: 8,SNR1: 0.33519 ,SNR2: 2.4125




Frequency (Hz)

F20260519100803




BLK: 8,SNR1: 0.84491E-02,SNR2: 1.4001





Frequency (Hz)


0202+15 2026/05/19 1.16UT TOYOKAWA-FUJI



T20260519100803





BLK: 9,SNR1: 0.40896 ,SNR2: 1.2477




Frequency (Hz)

K20260519100800




BLK: 9,SNR1: 0.61444 ,SNR2: 2.5924




Frequency (Hz)


0202+15 2026/05/19 1.16UT TOYOKAWA-KISO





F20260519100803




BLK:11,SNR1: 0.25246 ,SNR2: 1.7449




K20260519100800





BLK:11,SNR1: 0.69481 ,SNR2: 2.4607




0202+15 2026/05/19 1.16UT FUJI -KISO





T20260519101954




BLK: 1,SNR1: 0.32668 ,SNR2: 1.4827




F20260519101954





BLK: 1,SNR1: 0.43865 ,SNR2: 4.3058




0213+178 2026/05/19 1.36UT TOYOKAWA-FUJI



T20260519101954




BLK: 2,SNR1: 0.30215 ,SNR2: 1.3433





0213+178 2026/05/19 1.36UT TOYOKAWA-KISO



K20260519101951




BLK: 2,SNR1: 0.51463 ,SNR2: 2.3435



F20260519101954




No. Good Data




Frequency (Hz)

K20260519101951




No. Good Data





Frequency (Hz)


0213+178 2026/05/19 1.36UT FUJI -KISO



T20260519102736




BLK:13,SNR1: 0.18908 ,SNR2: 3.1697





3C67 2026/05/19 1.49UT TOYOKAWA-FUJI



F20260519102736




BLK:13,SNR1: 1.1272 ,SNR2: 3.2906



T20260519102736





BLK:15,SNR1: 2.1333 ,SNR2: 5.6826





3C67 2026/05/19 1.49UT TOYOKAWA-KISO



K20260519102733




BLK:15,SNR1: 5.4849 ,SNR2: 14.266



F20260519102736





BLK:10,SNR1: 10.733 ,SNR2: 26.126





3C67 2026/05/19 1.49UT FUJI -KISO



K20260519102733




BLK:10,SNR1: 6.9168 ,SNR2: 17.958




T20260519104551




BLK: 5,SNR1: 0.15996 ,SNR2: 0.78392




F20260519104551





BLK: 5,SNR1:-0.10300 ,SNR2: 1.4256




3C71 2026/05/19 1.79UT TOYOKAWA-FUJI





T20260519104551




BLK: 4,SNR1:-0.10164E-01,SNR2: 0.84473




K20260519104548




BLK: 4,SNR1: 97.027 ,SNR2: 95.154




3C71 2026/05/19 1.79UT TOYOKAWA-KISO



F20260519104551





BLK: 7,SNR1: 5.7613 ,SNR2: 16.953





3C71 2026/05/19 1.79UT FUJI -KISO


K20260519104548




BLK: 7,SNR1: 113.29 ,SNR2: 117.93




T20260519110507




No. Good Data




F20260519110507




No. Good Data




0258+350 2026/05/19 2.11UT TOYOKAWA-FUJI



T20260519110507





BLK: 1,SNR1: 10.171 ,SNR2: 24.808





0258+350 2026/05/19 2.11UT TOYOKAWA-KISO


K20260519110504




BLK: 1,SNR1: 9.4789 ,SNR2: 23.067



F20260519110507





BLK: 1,SNR1: 6.8759 ,SNR2: 20.131





0258+350 2026/05/19 2.11UT FUJI -KISO



K20260519110504




BLK: 1,SNR1: 27.484 ,SNR2: 40.469





T20260519111456




BLK:13,SNR1: 13.942 ,SNR2: 32.941




F20260519111456




BLK:13,SNR1: 0.11774 ,SNR2: 1.0160




0308+305 2026/05/19 2.28UT TOYOKAWA-FUJI





T20260519111456




BLK:23,SNR1: 3.9911 ,SNR2: 18.936




K20260519111453




BLK:23,SNR1: 1.0258 ,SNR2: 3.5032




0308+305 2026/05/19 2.28UT TOYOKAWA-KISO





F20260519111456




BLK:12,SNR1: 0.10203 ,SNR2: 0.97088




K20260519111453





BLK:12,SNR1: 1.3165 ,SNR2: 4.5461




0308+305 2026/05/19 2.28UT FUJI -KISO



T20260519112627




BLK:10,SNR1: 7.8159 ,SNR2: 13.971





0320+05 2026/05/19 2.47UT TOYOKAWA-FUJI



F20260519112627






BLK:10,SNR1: 8.3980 ,SNR2: 19.404




T20260519112627




K20260519112624




0320+05 2026/05/19 2.47UT TOYOKAWA-KISO





F20260519112627




BLK: 9,SNR1: 8.6898 ,SNR2: 20.087




K20260519112624




BLK: 9,SNR1: 2.2970 ,SNR2: 7.6442




0320+05 2026/05/19 2.47UT FUJI -KISO




T20260519113949




BLK:13,SNR1: 0.33402 ,SNR2: 3.4064




F20260519113949




BLK:13,SNR1:-0.22812E-01,SNR2: 2.8651




0333+32 2026/05/19 2.69UT TOYOKAWA-FUJI





T20260519113949




BLK:13,SNR1: 0.32830 ,SNR2: 3.0869




K20260519113946




BLK:13,SNR1: 0.69934 ,SNR2: 2.5460




0333+32 2026/05/19 2.69UT TOYOKAWA-KISO



F20260519113949




BLK:12,SNR1:-0.15107 ,SNR2: 1.0233





0333+32 2026/05/19 2.69UT FUJI -KISO



K20260519113946




BLK:12,SNR1: 0.45497 ,SNR2: 1.5315



T20260519115250





BLK: 3,SNR1: 0.64485 ,SNR2: 2.2965




Frequency (Hz)

F20260519115250




BLK: 3,SNR1: 2.8428 ,SNR2: 7.7904





Frequency (Hz)


0347+05 2026/05/19 2.91UT TOYOKAWA-FUJI





T20260519115250




BLK:10,SNR1: 0.86458 ,SNR2: 3.3737




K20260519115247




BLK:10,SNR1: 1.4031 ,SNR2: 5.4493




0347+05 2026/05/19 2.91UT TOYOKAWA-KISO



F20260519115250




BLK: 6,SNR1: 3.4316 ,SNR2: 8.4475





0347+05 2026/05/19 2.91UT FUJI -KISO



K20260519115247




BLK: 6,SNR1: 8.4732 ,SNR2: 14.787





T20260519120823




BLK:12,SNR1: 8.1122 ,SNR2: 14.466




F20260519120823





BLK:12,SNR1: 10.033 ,SNR2: 20.804




0403-132 2026/05/19 3.17UT TOYOKAWA-FUJI



T20260519120823





BLK:25,SNR1: 7.9057 ,SNR2: 13.999





0403-132 2026/05/19 3.17UT TOYOKAWA-KISO



K20260519120820




BLK:25,SNR1: 2.2018 ,SNR2: 7.1892



F20260519120823





BLK:12,SNR1: 10.047 ,SNR2: 20.832





0403-132 2026/05/19 3.17UT FUJI -KISO



K20260519120820




BLK:12,SNR1: 2.2076 ,SNR2: 7.2055




T20260519121735




BLK: 8,SNR1: 11.740 ,SNR2: 21.383




F20260519121735





BLK: 8,SNR1: 2.0542 ,SNR2: 6.9913




0411+05 2026/05/19 3.32UT TOYOKAWA-FUJI



T20260519121735





BLK:12,SNR1: 11.853 ,SNR2: 21.400





0411+05 2026/05/19 3.32UT TOYOKAWA-KISO


K20260519121732




BLK:12,SNR1: 8.6478 ,SNR2: 15.421





F20260519121735




BLK:14,SNR1: 2.2140 ,SNR2: 7.4221




K20260519121732





BLK:14,SNR1: 8.4050 ,SNR2: 14.777




0411+05 2026/05/19 3.32UT FUJI -KISO




T20260519122828




BLK: 8,SNR1: 0.36952 ,SNR2: 1.7554




F20260519122828





BLK: 8,SNR1: 0.23955 ,SNR2: 3.8590




0422+178 2026/05/19 3.5OUT TOYOKAWA-FUJI



T20260519122828





BLK:14,SNR1: 0.34479 ,SNR2: 2.4649





0422+178 2026/05/19 3.50UT TOYOKAWA-KISO


K20260519122825




BLK:14,SNR1: 0.86647 ,SNR2: 4.1023



F20260519122828




BLK: 8,SNR1: 4.6513 ,SNR2: 11.717





0422+178 2026/05/19 3.50UT FUJI -KISO



K20260519122825




BLK: 8,SNR1: 0.82945 ,SNR2: 2.7411




T20260519123558




BLK: 9,SNR1: 4.1510 ,SNR2: 14.537




F20260519123558





BLK: 9,SNR1: 7.1307 ,SNR2: 17.650




3C119 2026/05/19 3.63UT TOYOKAWA-FUJI




T20260519123558




BLK:13,SNR1: 5.4535 ,SNR2: 18.563




K20260519123556




BLK:13,SNR1: 4.5115 ,SNR2: 9.0676




3C119 2026/05/19 3.63UT TOYOKAWA-KISO




F20260519123558




BLK: 7,SNR1: 7.9258 ,SNR2: 19.311




K20260519123556





BLK: 7,SNR1: 4.6508 ,SNR2: 9.2191




3C119 2026/05/19 3.63UT FUJI -KISO




T20260519132404




BLK:16,SNR1: 4.5870 ,SNR2: 16.811




F20260519132404





BLK:16,SNR1: 2.0965 ,SNR2: 7.5449




3C138 2026/05/19 4.43UT TOYOKAWA-FUJI





T20260519132404




BLK:12,SNR1: 11.943 ,SNR2: 45.947




K20260519132401




BLK:12,SNR1: 6.1318 ,SNR2: 15.417




3C138 2026/05/19 4.43UT TOYOKAWA-KISO



F20260519132404





BLK: 2,SNR1:-0.13908 ,SNR2: 1.0192





3C138 2026/05/19 4.43UT FUJI -KISO


K20260519132401




BLK: 2,SNR1: 1.0838 ,SNR2: 4.3453




T20260519133737




BLK:19,SNR1: 2.1766 ,SNR2: 16.578




F20260519133737




BLK:19,SNR1:-0.12990 ,SNR2: 1.3671




0531+194 2026/05/19 4.66UT TOYOKAWA-FUJI




T20260519133737




BLK:25,SNR1: 2.1736 ,SNR2: 17.528




K20260519133734




BLK:25,SNR1: 1.3118 ,SNR2: 5.2007




0531+194 2026/05/19 4.66UT TOYOKAWA-KISO





F20260519133737




BLK:11,SNR1:-0.10516 ,SNR2: 1.8726




K20260519133734





BLK:11,SNR1: 0.75530 ,SNR2: 3.1193




0531+194 2026/05/19 4.66UT FUJI -KISO



T20260519134559




BLK: 3,SNR1: 9.1852 ,SNR2: 22.678





3C147 2026/05/19 4.79UT TOYOKAWA-FUJI



F20260519134559




BLK: 3,SNR1: 9.8604 ,SNR2: 24.534




T20260519134559




BLK: 3,SNR1: 10.152 ,SNR2: 24.955




K20260519134556




BLK: 3,SNR1: 9.8761 ,SNR2: 24.302




3C147 2026/05/19 4.79UT TOYOKAWA-KISO




F20260519134559




BLK: 2,SNR1: 9.6955 ,SNR2: 23.856




K20260519134556





BLK: 2,SNR1: 8.2624 ,SNR2: 20.702




3C147 2026/05/19 4.79UT FUJI -KISO




T20260519135408




BLK:12,SNR1: 0.30967 ,SNR2: 1.4905




F20260519135408





BLK:12,SNR1: 1.4184 ,SNR2: 4.5377




0548+16 2026/05/19 4.93UT TOYOKAWA-FUJI





T20260519135408




BLK:15,SNR1: 0.26780 ,SNR2: 4.5497




K20260519135405




BLK:15,SNR1: 0.66531 ,SNR2: 3.6773




0548+16 2026/05/19 4.93UT TOYOKAWA-KISO





F20260519135408




BLK: 6,SNR1: 0.45549E-02,SNR2: 1.4172




K20260519135405





BLK: 6,SNR1: 0.79293 ,SNR2: 3.8696




0548+16 2026/05/19 4.93UT FUJI -KISO





T20260519135819




BLK:16,SNR1: 7.4229 ,SNR2: 21.165




F20260519135819




BLK:16,SNR1: 8.4687 ,SNR2: 18.121




0552+12 2026/05/19 5.00UT TOYOKAWA-FUJI




T20260519135819




BLK:18,SNR1: 9.3830 ,SNR2: 26.120




K20260519135816





BLK:18,SNR1: 8.0574 ,SNR2: 14.489




0552+12 2026/05/19 5.00UT TOYOKAWA-KISO



F20260519135819





BLK:15,SNR1: 0.36522 ,SNR2: 1.7238





0552+12 2026/05/19 5.00UT FUJI -KISO



K20260519135816




BLK:15,SNR1: 8.1072 ,SNR2: 14.576





T20260519140246




BLK: 3,SNR1:-0.10713E-01,SNR2: 0.64309




F20260519140246





BLK: 3,SNR1: 0.54036 ,SNR2: 2.1912




0556+191 2026/05/19 5.07UT TOYOKAWA-FUJI





T20260519140246




BLK: 7,SNR1: 0.27279 ,SNR2: 1.5383




K20260519140243




BLK: 7,SNR1: 1.1879 ,SNR2: 4.0122




0556+191 2026/05/19 5.07UT TOYOKAWA-KISO





F20260519140246




BLK: 2,SNR1:-0.95285E-01,SNR2: 1.5374




K20260519140243





BLK: 2,SNR1: 1.9691 ,SNR2: 6.4697




0556+191 2026/05/19 5.07UT FUJI -KISO




T20260519141031




BLK: 6,SNR1: 0.55494 ,SNR2: 1.2173




F20260519141031




BLK: 6,SNR1: 1.2431 ,SNR2: 4.2878




0605-08 2026/05/19 5.20UT TOYOKAWA-FUJI




T20260519141031




BLK: 7,SNR1: 0.27902 ,SNR2: 1.3640




K20260519141028




BLK: 7,SNR1: 10.446 ,SNR2: 26.362




0605-08 2026/05/19 5.20UT TOYOKAWA-KISO





F20260519141031




BLK: 5,SNR1: 0.65352E-01,SNR2: 2.0982




K20260519141028





BLK: 5,SNR1: 0.78393 ,SNR2: 3.2213




0605-08 2026/05/19 5.20UT FUJI -KISO



T20260519142939





BLK: 7,SNR1: 7.6908 ,SNR2: 19.442





3C161 2026/05/19 5.52UT TOYOKAWA-FUJI



F20260519142939




BLK: 7,SNR1: 17.032 ,SNR2: 41.940





T20260519142939




BLK: 8,SNR1: 8.2491 ,SNR2: 20.859




K20260519142936





BLK: 8,SNR1: 8.6351 ,SNR2: 25.039




3C161 2026/05/19 5.52UT TOYOKAWA-KISO



F20260519142939





BLK: 9,SNR1: 8.9737 ,SNR2: 21.973









3C161 2026/05/19 5.52UT FUJI -KISO

K20260519142936








BLK: 9,SNR1: 14.721 ,SNR2: 35.670






0652-130 2026/05/19 5.98UT TOYOKAWA-FUJI








0652-130 2026/05/19 5.98UT TOYOKAWA-KISO





F20260519145711




BLK: 3,SNR1: 0.15736 ,SNR2: 4.7761




K20260519145708





BLK: 3,SNR1: 8.6878 ,SNR2: 17.069




0652-130 2026/05/19 5.98UT FUJI -KISO





T20260519150849




No.Good Data




F20260519150849





No.Good Data




0703+138 2026/05/19 6.18UT TOYOKAWA-FUJI





T20260519150849




No.Good Data




K20260519150846






No.Good Data






0703+138 2026/05/19 6.18UT TOYOKAWA-KISO




F20260519150849





K20260519150846




0703+138 2026/05/19 6.18UT FUJI -KISO



T20260519151811





BLK: 7,SNR1: 88.468 ,SNR2: 161.82




Frequency (Hz)

F20260519151811




BLK: 7,SNR1: 7.0695 ,SNR2: 20.381





Frequency (Hz)


0713-024 2026/05/19 6.33UT TOYOKAWA-FUJI



T20260519151811





BLK: 8,SNR1: 62.679 ,SNR2: 72.704




Frequency (Hz)

K20260519151808




BLK: 8,SNR1: 7.1410 ,SNR2: 20.336





Frequency (Hz)


0713-024 2026/05/19 6.33UT TOYOKAWA-KISO





F20260519151811




BLK: 8,SNR1: 7.3378 ,SNR2: 18.684




K20260519151808





BLK: 8,SNR1: 8.7481 ,SNR2: 21.310




0713-024 2026/05/19 6.33UT FUJI -KISO





T20260519152823




BLK: 4,SNR1: 11.393 ,SNR2: 28.735




F20260519152823





BLK: 4,SNR1: 11.647 ,SNR2: 28.871




0723+10 2026/05/19 6.50UT TOYOKAWA-FUJI





T20260519152823




BLK: 2,SNR1: 8.8882 ,SNR2: 22.467




K20260519152820





BLK: 2,SNR1: 14.216 ,SNR2: 35.117




0723+10 2026/05/19 6.50UT TOYOKAWA-KISO





F20260519152823




BLK: 2,SNR1: 11.958 ,SNR2: 29.629




K20260519152820





BLK: 2,SNR1: 14.216 ,SNR2: 35.117




0723+10 2026/05/19 6.50UT FUJI -KISO



T20260519153839





BLK: 3,SNR1: 0.99968E-01,SNR2: 0.34896




Frequency (Hz)

F20260519153839




BLK: 3,SNR1: 0.82005 ,SNR2: 2.2428





Frequency (Hz)


0732+33 2026/05/19 6.67UT TOYOKAWA-FUJI




T20260519153839




BLK: 2,SNR1: 0.16596 ,SNR2: 0.43354




K20260519153836




BLK: 2,SNR1: 0.10951 ,SNR2: 1.0046




0732+33 2026/05/19 6.67UT TOYOKAWA-KISO



F20260519153839




BLK: 5,SNR1: 0.33233 ,SNR2: 3.0174




Frequency (Hz)

K20260519153836




BLK: 5,SNR1: 0.17777 ,SNR2: 0.75010





Frequency (Hz)


0732+33 2026/05/19 6.67UT FUJI -KISO



T20260519154639




BLK: 4,SNR1: 10.504 ,SNR2: 26.131




Frequency (Hz)

F20260519154639




BLK: 4,SNR1: 17.640 ,SNR2: 30.555





Frequency (Hz)


0741-06 2026/05/19 6.81UT TOYOKAWA-FUJI



T20260519154639




BLK: 7,SNR1: 12.666 ,SNR2: 30.544




Frequency (Hz)

K20260519154636




BLK: 7,SNR1: 15.910 ,SNR2: 28.818




Frequency (Hz)


0741-06 2026/05/19 6.81UT TOYOKAWA-KISO



F20260519154639





BLK: 6,SNR1: 9.7746 ,SNR2: 24.094




Frequency (Hz)

K20260519154636




BLK: 6,SNR1: 8.2060 ,SNR2: 26.297





Frequency (Hz)


0741-06 2026/05/19 6.81UT FUJI -KISO



T20260519155623





BLK: 3,SNR1: 18.519 ,SNR2: 33.276




Frequency (Hz)

F20260519155623




BLK: 3,SNR1: 3.8277 ,SNR2: 11.229





Frequency (Hz)


0752-200 2026/05/19 6.97UT TOYOKAWA-FUJI



T20260519155623





BLK: 2,SNR1: 14.077 ,SNR2: 24.652




Frequency (Hz)

K20260519155620




BLK: 2,SNR1: 10.890 ,SNR2: 23.003





Frequency (Hz)


0752-200 2026/05/19 6.97UT TOYOKAWA-KISO





F20260519155623




BLK: 4,SNR1: 3.7977 ,SNR2: 11.151




K20260519155620





BLK: 4,SNR1: 11.113 ,SNR2: 23.465




0752-200 2026/05/19 6.97UT FUJI -KISO



T20260519160359





BLK: 3,SNR1: 10.562 ,SNR2: 29.052




Frequency (Hz)

F20260519160359




BLK: 3,SNR1: 8.1899 ,SNR2: 20.348





Frequency (Hz)


3C190 2026/05/19 7.09UT TOYOKAWA-FUJI





T20260519160359




BLK: 5,SNR1: 12.655 ,SNR2: 31.484




K20260519160356





BLK: 5,SNR1: 8.6636 ,SNR2: 22.128




3C190 2026/05/19 7.09UT TOYOKAWA-KISO



F20260519160359




BLK: 8,SNR1: 11.044 ,SNR2: 28.559




Frequency (Hz)

K20260519160356




BLK: 8,SNR1: 8.9024 ,SNR2: 22.301




Frequency (Hz)


3C190 2026/05/19 7.09UT FUJI -KISO



T20260519161625





No.Good Data




Frequency (Hz)

F20260519161625




No.Good Data




Frequency (Hz)


3C196 2026/05/19 7.30UT TOYOKAWA-FUJI



T20260519161625




No.Good Data




Frequency (Hz)

K20260519161622




No.Good Data





Frequency (Hz)


3C196 2026/05/19 7.30UT TOYOKAWA-KISO




F20260519161625




No.Good Data




K20260519161622





No.Good Data




3C196 2026/05/19 7.30UT FUJI -KISO



T20260519162734




BLK: 1,SNR1: 7.8651 ,SNR2: 22.590




Frequency (Hz)

F20260519162734




BLK: 1,SNR1: 4.4494 ,SNR2: 10.087





Frequency (Hz)


0821+394 2026/05/19 7.49UT TOYOKAWA-FUJI



T20260519162734




BLK: 1,SNR1: 10.029 ,SNR2: 24.968




Frequency (Hz)

K20260519162731








BLK: 1,SNR1: 19.963 ,SNR2: 35.463




Frequency (Hz)

0821+394 2026/05/19 7.49UT TOYOKAWA-KISO








0821+394 2026/05/19 7.49UT FUJI -KISO



T20260519164418





BLK: 3,SNR1: 0.56402 ,SNR2: 2.6850




Frequency (Hz)

F20260519164418




BLK: 3,SNR1: 0.23552 ,SNR2: 1.6717





Frequency (Hz)


0839-071 2026/05/19 7.77UT TOYOKAWA-FUJI



T20260519164418





BLK: 2,SNR1: 0.24890 ,SNR2: 1.3452




Frequency (Hz)

K20260519164415




BLK: 2,SNR1: 1.6514 ,SNR2: 9.0367





Frequency (Hz)


0839-071 2026/05/19 7.77UT TOYOKAWA-KISO



F20260519164418





BLK: 5, SNR1: 5.6916 , SNR2: 22.191




Frequency (Hz)

K20260519164415




BLK: 5, SNR1: 16.227 , SNR2: 35.639





Frequency (Hz)


0839-071 2026/05/19 7.77UT FUJI -KISO



T20260519165520





No.Good Data




Frequency (Hz)

F20260519165520




No.Good Data





Frequency (Hz)


3C208 2026/05/19 7.95UT TOYOKAWA-FUJI



T20260519165520





BLK: 1,SNR1: 18.262 ,SNR2: 32.209




Frequency (Hz)

K20260519165517




BLK: 1,SNR1: 2.3003 ,SNR2: 10.863




Frequency (Hz)


3C208 2026/05/19 7.95UT TOYOKAWA-KISO



F20260519165520





BLK: 1,SNR1: 8.5685 ,SNR2: 27.616




Frequency (Hz)

K20260519165517




BLK: 1,SNR1: 15.962 ,SNR2: 31.134




Frequency (Hz)


3C208 2026/05/19 7.95UT FUJI -KISO



T20260519171202




BLK: 4,SNR1: 3.2761 ,SNR2: 10.033




Frequency (Hz)

F20260519171202




BLK: 4,SNR1: 2.8900 ,SNR2: 8.2042




Frequency (Hz)


3C216 2026/05/19 8.23UT TOYOKAWA-FUJI





T20260519171202




BLK: 5,SNR1: 3.2715 ,SNR2: 10.003




K20260519171159




BLK: 5,SNR1: 8.9781 ,SNR2: 23.469




3C216 2026/05/19 8.23UT TOYOKAWA-KISO



F20260519171202





BLK: 8,SNR1: 2.1630 ,SNR2: 6.1707




Frequency (Hz)

K20260519171159




BLK: 8,SNR1: 8.6926 ,SNR2: 22.722





Frequency (Hz)


3C216 2026/05/19 8.23UT FUJI -KISO



T20260519173727





BLK: 2,SNR1: 1.7148 ,SNR2: 9.4279




Frequency (Hz)

F20260519173727





BLK: 2,SNR1: 0.39582 ,SNR2: 1.5188





Frequency (Hz)

0931+399 2026/05/19 8.65UT TOYOKAWA-FUJI







BLK:11,SNR1: 3.2364 ,SNR2: 9.9158




BLK:11,SNR1: 7.2390 ,SNR2: 16.941




0931+399 2026/05/19 8.65UT TOYOKAWA-KISO



F20260519173727





BLK:10,SNR1: 1.1717 ,SNR2: 3.5718




Frequency (Hz)

K20260519173724



BLK:10,SNR1: 7.7911 ,SNR2: 18.019



Frequency (Hz)

0931+399 2026/05/19 8.65UT FUJI -KISO

