




T20260601053305





BLK: 2,SNR1: 0.35677 ,SNR2: 10.084




Frequency (Hz)

F20260601053305




BLK: 2,SNR1:-0.11226 ,SNR2: 0.51788





Frequency (Hz)


2218+395 2026/05/31 20.58UT TOYOKAWA-FUJI



T20260601053305





BLK: 4,SNR1: 4.2370 ,SNR2: 10.636




Frequency (Hz)

K20260601053303




BLK: 4,SNR1:-0.16881E-01,SNR2: 0.71833





Frequency (Hz)


2218+395 2026/05/31 20.58UT TOYOKAWA-KISO



F20260601053305




BLK: 6,SNR1:-0.95188E-01,SNR2: 1.5695




Frequency (Hz)

K20260601053303




BLK: 6,SNR1: 0.45907E-01,SNR2: 0.97086





Frequency (Hz)


2218+395 2026/05/31 20.58UT FUJI -KISO



T20260601054154





BLK: 5,SNR1: 16.705 ,SNR2: 38.588




Frequency (Hz)

F20260601054154




BLK: 5,SNR1: 22.475 ,SNR2: 34.238





Frequency (Hz)


2227+444 2026/05/31 20.73UT TOYOKAWA-FUJI



T20260601054154





BLK:10,SNR1: 12.818 ,SNR2: 23.620





2227+444 2026/05/31 20.73UT TOYOKAWA-KISO



K20260601054152




BLK:10,SNR1: 0.62804E-01,SNR2: 3.2205



F20260601054154




BLK:10,SNR1: 9.5867 ,SNR2: 16.923




Frequency (Hz)

K20260601054152




BLK:10,SNR1: 0.89583E-01,SNR2: 3.3515




Frequency (Hz)


2227+444 2026/05/31 20.73UT FUJI -KISO



T20260601055403





BLK: 6,SNR1: 0.33260 ,SNR2: 1.7565




Frequency (Hz)

F20260601055403




BLK: 6,SNR1: 4.7660 ,SNR2: 12.592





Frequency (Hz)


2239+333 2026/05/31 20.93UT TOYOKAWA-FUJI



T20260601055403





BLK: 7, SNR1: 0.31483 , SNR2: 1.5894




Frequency (Hz)

K20260601055400




BLK: 7, SNR1: 4.3530 , SNR2: 10.790





Frequency (Hz)


2239+333 2026/05/31 20.93UT TOYOKAWA-KISO



F20260601055403





BLK: 8,SNR1: 4.1537 ,SNR2: 10.069




Frequency (Hz)

K20260601055400




BLK: 8,SNR1: 0.89797 ,SNR2: 2.5551





Frequency (Hz)


2239+333 2026/05/31 20.93UT FUJI -KISO



T20260601055820





BLK: 8,SNR1: 1.5068 ,SNR2: 9.8510




Frequency (Hz)

F20260601055821




BLK: 8,SNR1: 9.8616 ,SNR2: 17.534





Frequency (Hz)


2243+394 2026/05/31 21.00UT TOYOKAWA-FUJI



T20260601055820




BLK: 4, SNR1: 0.33087E-01, SNR2: 0.28741





2243+394 2026/05/31 21.00UT TOYOKAWA-KISO



K20260601055817




BLK: 4, SNR1: 10.540, SNR2: 18.625





F20260601055821




BLK: 9,SNR1: 4.5651 ,SNR2: 8.2323




K20260601055817





BLK: 9,SNR1: 3.3824 ,SNR2: 6.0923




2243+394 2026/05/31 21.00UT FUJI -KISO



T20260601061416





BLK:10,SNR1: 9.4052 ,SNR2: 61.914




Frequency (Hz)

F20260601061416




BLK:10,SNR1: 9.3730 ,SNR2: 20.103




Frequency (Hz)


2259+481 2026/05/31 21.27UT TOYOKAWA-FUJI



T20260601061416





BLK:14,SNR1: 6.6448 ,SNR2: 26.138




Frequency (Hz)

2259+481 2026/05/31 21.27UT TOYOKAWA-KISO


K20260601061413





BLK:14,SNR1: 2.0668 ,SNR2: 7.1698




Frequency (Hz)



F20260601061416





BLK: 9,SNR1: 10.413 ,SNR2: 25.986




Frequency (Hz)

2259+481 2026/05/31 21.27UT FUJI -KISO


K20260601061413




BLK: 9,SNR1: 1.6580 ,SNR2: 8.2427




Frequency (Hz)





T20260601062910




BLK: 1,SNR1: 21.364 ,SNR2: 38.251




F20260601062910





BLK: 1,SNR1: 23.792 ,SNR2: 53.121




3C459 2026/05/31 21.51UT TOYOKAWA-FUJI



T20260601062910





No.Good Data




Frequency (Hz)

K20260601062907




No.Good Data





Frequency (Hz)


3C459 2026/05/31 21.51UT TOYOKAWA-KISO





F20260601062910




No.Good Data




K20260601062907





No.Good Data




3C459 2026/05/31 21.51UT FUJI -KISO



T20260601064031





No.Good Data




Frequency (Hz)

F20260601064031




No.Good Data





Frequency (Hz)


2325+269 2026/05/31 21.70UT TOYOKAWA-FUJI



T20260601064031





BLK: 6,SNR1:-0.43220E-01,SNR2: 0.81242




Frequency (Hz)

K20260601064029




BLK: 6,SNR1: 1.5232 ,SNR2: 4.8637




Frequency (Hz)


2325+269 2026/05/31 21.70UT TOYOKAWA-KISO



F20260601064031




BLK: 6,SNR1:-0.68491E-01,SNR2: 0.53806




Frequency (Hz)

K20260601064029




BLK: 6,SNR1: 0.61193 ,SNR2: 2.2934





Frequency (Hz)


2325+269 2026/05/31 21.70UT FUJI -KISO



T20260601064913





BLK: 9,SNR1: 8.9619 ,SNR2: 32.588




Frequency (Hz)

F20260601064913




BLK: 9,SNR1: 8.5347 ,SNR2: 21.259





Frequency (Hz)


2334+085 2026/05/31 21.85UT TOYOKAWA-FUJI



T20260601064913





BLK: 8,SNR1: 14.163 ,SNR2: 52.362




Frequency (Hz)

K20260601064910




BLK: 8,SNR1: 6.6644 ,SNR2: 16.898




Frequency (Hz)


2334+085 2026/05/31 21.85UT TOYOKAWA-KISO



F20260601064913




BLK: 4,SNR1: 1.1228 ,SNR2: 4.8205




Frequency (Hz)

K20260601064910




BLK: 4,SNR1: 1.8800 ,SNR2: 6.1318





Frequency (Hz)


2334+085 2026/05/31 21.85UT FUJI -KISO



T20260601070255





BLK:11,SNR1: 1.2190 ,SNR2: 3.9245




Frequency (Hz)

F20260601070255




BLK:11,SNR1: 7.9422 ,SNR2: 14.248





Frequency (Hz)


2347-02 2026/05/31 22.08UT TOYOKAWA-FUJI



T20260601070255





BLK:14,SNR1: 8.9874 ,SNR2: 16.091




Frequency (Hz)

2347-02 2026/05/31 22.08UT TOYOKAWA-KISO


K20260601070252





BLK:14,SNR1: 5.7658 ,SNR2: 14.808




Frequency (Hz)



F20260601070255





BLK:16,SNR1: 8.1400 ,SNR2: 14.583




Frequency (Hz)

K20260601070252




BLK:16,SNR1: 7.5909 ,SNR2: 17.344





Frequency (Hz)


2347-02 2026/05/31 22.08UT FUJI -KISO



T20260601070949





BLK: 2,SNR1: 0.25270 ,SNR2: 0.64591




Frequency (Hz)

2354+14 2026/05/31 22.19UT TOYOKAWA-FUJI


F20260601070949




BLK: 2,SNR1: 0.55005 ,SNR2: 2.1482




Frequency (Hz)



T20260601070949





BLK: 2,SNR1: 0.13233 ,SNR2: 1.2467




Frequency (Hz)

2354+14 2026/05/31 22.19UT TOYOKAWA-KISO


K20260601070947




BLK: 2,SNR1: 4.6666 ,SNR2: 17.011




Frequency (Hz)



F20260601070949




BLK: 5,SNR1: 12.078 ,SNR2: 21.136




Frequency (Hz)

2354+14 2026/05/31 22.19UT FUJI -KISO


K20260601070947





BLK: 5,SNR1: 2.4714 ,SNR2: 9.0560




Frequency (Hz)



T20260601071852





BLK: 5,SNR1: 0.19846 ,SNR2: 0.76639




Frequency (Hz)

F20260601071852




BLK: 5,SNR1: 0.34911 ,SNR2: 2.0514





Frequency (Hz)


3C2 2026/05/31 22.34UT TOYOKAWA-FUJI





T20260601071852




BLK:10,SNR1: 0.45223E-01,SNR2: 0.72932




K20260601071849




BLK:10,SNR1: 0.53232 ,SNR2: 2.4731




3C2 2026/05/31 22.34UT TOYOKAWA-KISO




F20260601071852




BLK: 5,SNR1:-0.72690E-01,SNR2: 1.0240




K20260601071849





BLK: 5,SNR1: 0.83679 ,SNR2: 4.4050




3C2 2026/05/31 22.34UT FUJI -KISO



T20260601072613





BLK: 5,SNR1: 9.5900 ,SNR2: 17.430




Frequency (Hz)

0011+344 2026/05/31 22.47UT TOYOKAWA-FUJI


F20260601072613





BLK: 5,SNR1: 2.4021 ,SNR2: 7.9576




Frequency (Hz)



T20260601072613





BLK: 9,SNR1: 7.9608 ,SNR2: 14.706




Frequency (Hz)

K20260601072610




BLK: 9,SNR1: 9.3620 ,SNR2: 16.538





Frequency (Hz)


0011+344 2026/05/31 22.47UT TOYOKAWA-KISO



F20260601072613





BLK:19,SNR1: 2.4004 ,SNR2: 7.9523




Frequency (Hz)

K20260601072610




BLK:19,SNR1: 8.1677 ,SNR2: 14.427





Frequency (Hz)


0011+344 2026/05/31 22.47UT FUJI -KISO



T20260601073450





BLK: 3,SNR1: 0.18227 ,SNR2: 2.0687




Frequency (Hz)

F20260601073450




BLK: 3,SNR1: 1.9551 ,SNR2: 14.290




Frequency (Hz)


0019-00 2026/05/31 22.61UT TOYOKAWA-FUJI



T20260601073450




BLK: 3,SNR1:-0.37691E-02,SNR2: 0.69839





0019-00 2026/05/31 22.61UT TOYOKAWA-KISO



K20260601073448




BLK: 3,SNR1: 1.7892 ,SNR2: 6.9491



F20260601073450





BLK: 5,SNR1: 1.9073 ,SNR2: 13.604




Frequency (Hz)

K20260601073448




BLK: 5,SNR1: 0.99066 ,SNR2: 3.9518




Frequency (Hz)


0019-00 2026/05/31 22.61UT FUJI -KISO




T20260601074504




BLK: 6,SNR1: 0.51420 ,SNR2: 2.3264




F20260601074504




BLK: 6,SNR1: 5.2583 ,SNR2: 12.404




3C12 2026/05/31 22.78UT TOYOKAWA-FUJI




T20260601074504




BLK: 3,SNR1: 0.79057 ,SNR2: 2.1049




K20260601074501




BLK: 3,SNR1: 1.5497 ,SNR2: 5.4603




3C12 2026/05/31 22.78UT TOYOKAWA-KISO



F20260601074504




BLK: 3,SNR1: 2.1308 ,SNR2: 6.2692





3C12 2026/05/31 22.78UT FUJI -KISO



K20260601074501




BLK: 3,SNR1: 5.6859 ,SNR2: 15.371



T20260601075906





BLK: 4,SNR1: 4.6516 ,SNR2: 52.903




Frequency (Hz)

F20260601075906




BLK: 4,SNR1: 3.3496 ,SNR2: 11.588





Frequency (Hz)


0044-056 2026/05/31 23.01UT TOYOKAWA-FUJI



T20260601075906





BLK: 4,SNR1: 0.44646 ,SNR2: 6.1276





0044-056 2026/05/31 23.01UT TOYOKAWA-KISO



K20260601075903




BLK: 4,SNR1: 1.4661 ,SNR2: 7.3540





F20260601075906




BLK: 5, SNR1: 8.3369 ,SNR2: 20.443




K20260601075903





BLK: 5, SNR1: 7.0187 ,SNR2: 21.628




0044-056 2026/05/31 23.01UT FUJI -KISO



T20260601080627




BLK: 4,SNR1: 0.50552 ,SNR2: 2.1423




Frequency (Hz)

3C26 2026/05/31 23.14UT TOYOKAWA-FUJI


F20260601080627





BLK: 4,SNR1: 0.16495 ,SNR2: 1.8457




Frequency (Hz)




T20260601080627




BLK: 5,SNR1: 0.49209 ,SNR2: 1.4171




K20260601080624




BLK: 5,SNR1: 0.39795 ,SNR2: 1.8651




3C26 2026/05/31 23.14UT TOYOKAWA-KISO




F20260601080627




BLK: 8,SNR1: 0.56782 ,SNR2: 2.6142




K20260601080624




BLK: 8,SNR1: 2.3275 ,SNR2: 6.8676




3C26 2026/05/31 23.14UT FUJI -KISO



T20260601081126





BLK: 3,SNR1: 3.1894 ,SNR2: 9.9637





0056-00 2026/05/31 23.22UT TOYOKAWA-FUJI


F20260601081126




BLK: 3,SNR1: 6.9285 ,SNR2: 12.808



T20260601081126





BLK: 3,SNR1: 3.1894 ,SNR2: 9.9637





0056-00 2026/05/31 23.22UT TOYOKAWA-KISO


K20260601081123




BLK: 3,SNR1: 10.924 ,SNR2: 19.374



F20260601081126





No. Good Data




Frequency (Hz)

K20260601081123




No. Good Data




Frequency (Hz)


0056-00 2026/05/31 23.22UT FUJI -KISO



T20260601082108




BLK: 2,SNR1:-0.16910 ,SNR2: 0.26919




Frequency (Hz)

0106+01 2026/05/31 23.38UT TOYOKAWA-FUJI


F20260601082108





BLK: 2,SNR1:-0.24307 ,SNR2: 0.0000




Frequency (Hz)



T20260601082108





BLK: 4,SNR1: 0.11176E-01,SNR2: 0.85889





0106+01 2026/05/31 23.38UT TOYOKAWA-KISO


K20260601082106




BLK: 4,SNR1: 1.4245 ,SNR2: 6.1920




F20260601082108




BLK: 6,SNR1: 0.16198 ,SNR2: 1.3354




K20260601082106





BLK: 6,SNR1: 0.28176 ,SNR2: 1.9214




0106+01 2026/05/31 23.38UT FUJI -KISO



T20260601083031





BLK: 3,SNR1: 15.900 ,SNR2: 28.379




Frequency (Hz)

F20260601083031




BLK: 3,SNR1: 12.208 ,SNR2: 29.799




Frequency (Hz)


0115-01 2026/05/31 23.54UT TOYOKAWA-FUJI



T20260601083031




BLK: 3,SNR1: 6.4838 ,SNR2: 15.987





0115-01 2026/05/31 23.54UT TOYOKAWA-KISO



K20260601083028




BLK: 3,SNR1: 15.213 ,SNR2: 26.844





F20260601083031




No.Good Data




K20260601083028




No.Good Data




0115-01 2026/05/31 23.54UT FUJI -KISO



T20260601084331




BLK:11,SNR1: 10.926 ,SNR2: 20.255





0128+03 2026/05/31 23.75UT TOYOKAWA-FUJI


F20260601084331




BLK:11,SNR1: 3.4365 ,SNR2: 10.355



T20260601084331




BLK:17,SNR1: 10.863 ,SNR2: 20.134





0128+03 2026/05/31 23.75UT TOYOKAWA-KISO


K20260601084328




BLK:17,SNR1: 10.434 ,SNR2: 26.791



F20260601084331




BLK:11,SNR1: 3.4285 ,SNR2: 10.230





0128+03 2026/05/31 23.75UT FUJI -KISO



K20260601084328




BLK:11,SNR1: 11.272 ,SNR2: 28.889



T20260601085005




BLK: 7,SNR1: 2.2274 ,SNR2: 10.599





3C48 2026/05/31 23.86UT TOYOKAWA-FUJI



F20260601085006




BLK: 7,SNR1: 9.6526 ,SNR2: 23.737



T20260601085005




BLK: 5, SNR1: 10.004 , SNR2: 24.583





3C48 2026/05/31 23.86UT TOYOKAWA-KISO


K20260601085002




BLK: 5, SNR1: 11.294 , SNR2: 27.364



F20260601085006




BLK: 3,SNR1: 10.533 ,SNR2: 25.817





3C48 2026/05/31 23.86UT FUJI -KISO



K20260601085002




BLK: 3,SNR1: 19.326 ,SNR2: 34.693



T20260601090949




BLK: 2,SNR1: 0.67861E-02,SNR2: 1.2439





0155-109 2026/06/01 0.19UT TOYOKAWA-FUJI



F20260601090949




BLK: 2,SNR1:-0.18755 ,SNR2: 1.1955



T20260601090949





BLK: 6,SNR1: 0.35023 ,SNR2: 1.1839





0155-109 2026/06/01 0.19UT TOYOKAWA-KISO


K20260601090946




BLK: 6,SNR1: 1.3330 ,SNR2: 4.2853





F20260601090949




BLK: 5,SNR1: 0.92620 ,SNR2: 2.8630




K20260601090946





BLK: 5,SNR1: 0.99117 ,SNR2: 3.2572




0155-109 2026/06/01 0.19UT FUJI -KISO



T20260601091657





BLK: 2,SNR1: 0.28858 ,SNR2: 1.3010




Frequency (Hz)

0202+15 2026/06/01 0.31UT TOYOKAWA-FUJI


F20260601091657





BLK: 2,SNR1: 1.9839 ,SNR2: 5.3016




Frequency (Hz)



T20260601091657




BLK: 4,SNR1: 0.40026 ,SNR2: 1.2631





0202+15 2026/06/01 0.31UT TOYOKAWA-KISO


K20260601091654




BLK: 4,SNR1: 0.94138 ,SNR2: 4.0960




F20260601091657




BLK: 1,SNR1: 0.67867 ,SNR2: 2.0880




K20260601091654





BLK: 1,SNR1: 0.15894 ,SNR2: 1.1452




0202+15 2026/06/01 0.31UT FUJI -KISO





T20260601092847




No.Good Data




F20260601092848





No.Good Data




0213+178 2026/06/01 0.51UT TOYOKAWA-FUJI



T20260601092847




BLK: 5,SNR1: 0.20607 ,SNR2: 0.62153




0213+178 2026/06/01 0.51UT TOYOKAWA-KISO


K20260601092844




BLK: 5,SNR1: 1.9337 ,SNR2: 8.2834




Frequency (Hz)




F20260601092848




BLK: 6,SNR1: 0.88431 ,SNR2: 3.2565




K20260601092844





BLK: 6,SNR1: 1.0073 ,SNR2: 3.9503




0213+178 2026/06/01 0.51UT FUJI -KISO



T20260601093821





BLK: 4, SNR1: 12.083 , SNR2: 29.532




Frequency (Hz)

0223+341 2026/06/01 0.67UT TOYOKAWA-FUJI


F20260601093821





BLK: 4, SNR1: 10.697 , SNR2: 26.208




Frequency (Hz)



T20260601093821





BLK: 5, SNR1: 14.910 , SNR2: 36.305




Frequency (Hz)

0223+341 2026/06/01 0.67UT TOYOKAWA-KISO


K20260601093819




BLK: 5, SNR1: 10.805 , SNR2: 26.836




Frequency (Hz)




F20260601093821




BLK: 6,SNR1: 9.9513 ,SNR2: 24.439




K20260601093819




BLK: 6,SNR1: 13.341 ,SNR2: 31.306




0223+341 2026/06/01 0.67UT FUJI -KISO




T20260601095444




BLK: 2,SNR1: 10.552 ,SNR2: 25.857




F20260601095444




BLK: 2,SNR1: 10.214 ,SNR2: 23.302




3C71 2026/06/01 0.94UT TOYOKAWA-FUJI



T20260601095444




BLK: 3,SNR1: 17.936 ,SNR2: 32.171





3C71 2026/06/01 0.94UT TOYOKAWA-KISO



K20260601095441




BLK: 3,SNR1: 12.782 ,SNR2: 29.717





F20260601095444




No. Good Data




K20260601095441





No. Good Data




3C71 2026/06/01 0.94UT FUJI -KISO





T20260601101400




BLK: 2,SNR1: 13.767 ,SNR2: 33.979




F20260601101400





BLK: 2,SNR1: 10.186 ,SNR2: 24.533




0258+350 2026/06/01 1.26UT TOYOKAWA-FUJI



T20260601101400




BLK: 1, SNR1: 0.41128 , SNR2: 2.1815





0258+350 2026/06/01 1.26UT TOYOKAWA-KISO



K20260601101358




BLK: 1, SNR1: 0.87004 , SNR2: 2.8350



F20260601101400





BLK: 3,SNR1: 18.251 ,SNR2: 44.702





0258+350 2026/06/01 1.26UT FUJI -KISO


K20260601101358




BLK: 3,SNR1: 13.696 ,SNR2: 33.396




T20260601102349




BLK: 3,SNR1: 9.5706 ,SNR2: 27.710




F20260601102349




BLK: 3,SNR1: 12.298 ,SNR2: 30.523




0308+305 2026/06/01 1.43UT TOYOKAWA-FUJI




T20260601102349




BLK: 3,SNR1: 9.5947 ,SNR2: 27.775




K20260601102346




BLK: 3,SNR1: 11.443 ,SNR2: 29.478




0308+305 2026/06/01 1.43UT TOYOKAWA-KISO





F20260601102349




BLK: 2,SNR1: 8.4545 ,SNR2: 20.990




K20260601102346




BLK: 2,SNR1: 11.432 ,SNR2: 29.454




0308+305 2026/06/01 1.43UT FUJI -KISO



T20260601103210




BLK: 2,SNR1: 1.5975 ,SNR2: 8.2078





3C84 2026/06/01 1.56UT TOYOKAWA-FUJI



F20260601103210




BLK: 2,SNR1: 10.914 ,SNR2: 23.537



T20260601103210




BLK: 5,SNR1: 7.5885 ,SNR2: 18.742





3C84 2026/06/01 1.56UT TOYOKAWA-KISO


K20260601103208




BLK: 5,SNR1: 6.3966 ,SNR2: 13.400



F20260601103210




BLK: 6,SNR1: 5.5531 ,SNR2: 12.403





3C84 2026/06/01 1.56UT FUJI -KISO



K20260601103208




BLK: 6,SNR1: 4.6804 ,SNR2: 9.5146



T20260601103925




BLK: 2,SNR1: 0.77202E-01,SNR2: 1.3792





0324+119 2026/06/01 1.69UT TOYOKAWA-FUJI



F20260601103925




BLK: 2,SNR1: 0.34706 ,SNR2: 1.7427



T20260601103925





BLK: 3,SNR1:-0.74155E-02,SNR2: 0.15107





0324+119 2026/06/01 1.69UT TOYOKAWA-KISO


K20260601103923




BLK: 3,SNR1: 2.5831 ,SNR2: 8.0029





F20260601103925




BLK: 5,SNR1: 0.37262 ,SNR2: 2.2414




K20260601103923




BLK: 5,SNR1: 0.66319 ,SNR2: 2.6806




0324+119 2026/06/01 1.69UT FUJI -KISO





T20260601104842




BLK: 3,SNR1: 0.47105 ,SNR2: 1.0212




F20260601104842





BLK: 3,SNR1: 0.25755 ,SNR2: 1.1473




0333+32 2026/06/01 1.84UT TOYOKAWA-FUJI



T20260601104842





BLK: 5,SNR1: 0.17344 ,SNR2: 1.0880





0333+32 2026/06/01 1.84UT TOYOKAWA-KISO



K20260601104840




BLK: 5,SNR1: 0.48237 ,SNR2: 2.2907





F20260601104842




BLK: 3,SNR1: 9.6744 ,SNR2: 24.487




K20260601104840





BLK: 3,SNR1: 9.0358 ,SNR2: 22.701




0333+32 2026/06/01 1.84UT FUJI -KISO



T20260601110143




BLK: 6,SNR1: 8.5891 ,SNR2: 25.023





0347+05 2026/06/01 2.06UT TOYOKAWA-FUJI



F20260601110143




BLK: 6,SNR1: 1.9439 ,SNR2: 5.3447



T20260601110143




BLK: 9,SNR1: 9.1875 ,SNR2: 23.477





0347+05 2026/06/01 2.06UT TOYOKAWA-KISO


K20260601110140




BLK: 9,SNR1: 1.0548 ,SNR2: 3.6334




F20260601110143




BLK: 8,SNR1: 1.3262 ,SNR2: 4.8521




K20260601110140




BLK: 8,SNR1: 1.6938 ,SNR2: 7.3949




0347+05 2026/06/01 2.06UT FUJI -KISO





T20260601111717




No.Good Data




F20260601111717




No.Good Data




0403-132 2026/06/01 2.32UT TOYOKAWA-FUJI




T20260601111717




BLK: 1,SNR1: 0.69132 ,SNR2: 3.6120




K20260601111714




BLK: 1,SNR1: 0.76438 ,SNR2: 3.6580




0403-132 2026/06/01 2.32UT TOYOKAWA-KISO




F20260601111717




BLK: 1,SNR1: 0.10413 ,SNR2: 0.89730




K20260601111714





BLK: 1,SNR1: 1.6540 ,SNR2: 6.8918




0403-132 2026/06/01 2.32UT FUJI -KISO



T20260601112628





BLK: 1,SNR1: 5.5124 ,SNR2: 12.393





0411+05 2026/06/01 2.47UT TOYOKAWA-FUJI


F20260601112628




BLK: 1,SNR1: 3.6453 ,SNR2: 8.9657



T20260601112628





BLK: 1,SNR1: 0.40962 ,SNR2: 1.1103





0411+05 2026/06/01 2.47UT TOYOKAWA-KISO


K20260601112625




BLK: 1,SNR1: 8.6464 ,SNR2: 21.129





F20260601112628




BLK: 1,SNR1: 6.0139 ,SNR2: 13.536




K20260601112625





BLK: 1,SNR1: 1.0274 ,SNR2: 4.8609




0411+05 2026/06/01 2.47UT FUJI -KISO



T20260601113721





BLK:14,SNR1: 0.32136 ,SNR2: 2.3751





0422+178 2026/06/01 2.65UT TOYOKAWA-FUJI



F20260601113721




BLK:14,SNR1: 0.40912 ,SNR2: 3.1739



T20260601113721





BLK:13,SNR1: 0.33431 ,SNR2: 1.8113





0422+178 2026/06/01 2.65UT TOYOKAWA-KISO


K20260601113718




BLK:13,SNR1: 2.9209 ,SNR2: 8.8458





F20260601113721




BLK:15,SNR1: 3.2050 ,SNR2: 9.6085




K20260601113718





BLK:15,SNR1: 3.4118 ,SNR2: 10.350




0422+178 2026/06/01 2.65UT FUJI -KISO



T20260601114451





BLK: 9,SNR1: 8.2310 ,SNR2: 20.044





3C119 2026/06/01 2.78UT TOYOKAWA-FUJI



F20260601114451




BLK: 9,SNR1: 7.3246 ,SNR2: 10.894



T20260601114451





BLK:20,SNR1: 7.3146 ,SNR2: 18.733





3C119 2026/06/01 2.78UT TOYOKAWA-KISO



K20260601114448




BLK:20,SNR1: 13.890 ,SNR2: 18.434





F20260601114451




BLK: 9,SNR1: 5.4632 ,SNR2: 15.458




K20260601114448





BLK: 9,SNR1: 19.790 ,SNR2: 27.318




3C119 2026/06/01 2.78UT FUJI -KISO




T20260601123257




BLK:14,SNR1: 6.7573 ,SNR2: 19.537




F20260601123257





BLK:14,SNR1: 0.13448 ,SNR2: 2.6571




3C138 2026/06/01 3.58UT TOYOKAWA-FUJI





T20260601123257




BLK:16,SNR1: 7.1306 ,SNR2: 30.119




K20260601123254




BLK:16,SNR1: 21.822 ,SNR2: 44.062




3C138 2026/06/01 3.58UT TOYOKAWA-KISO



F20260601123257





BLK:14,SNR1: 0.12839 ,SNR2: 2.6566





3C138 2026/06/01 3.58UT FUJI -KISO



K20260601123254




BLK:14,SNR1: 94.853 ,SNR2: 90.836





T20260601124631




BLK:20,SNR1: 3.5432 ,SNR2: 10.850




F20260601124631





BLK:20,SNR1: 2.6063 ,SNR2: 10.289




0531+194 2026/06/01 3.80UT TOYOKAWA-FUJI





T20260601124631




BLK:20,SNR1: 3.3311 ,SNR2: 9.5303




K20260601124628




BLK:20,SNR1: 0.92040 ,SNR2: 3.4736




0531+194 2026/06/01 3.80UT TOYOKAWA-KISO





F20260601124631




BLK:19,SNR1: 2.5343 ,SNR2: 12.015




K20260601124628





BLK:19,SNR1: 1.0128 ,SNR2: 3.9350




0531+194 2026/06/01 3.80UT FUJI -KISO



T20260601125452





BLK:20,SNR1: 12.918 ,SNR2: 61.025





3C147 2026/06/01 3.94UT TOYOKAWA-FUJI



F20260601125452




BLK:20,SNR1: 3.2741 ,SNR2: 9.3921





T20260601125452




BLK:29,SNR1: 12.405 ,SNR2: 30.760




K20260601125449




BLK:29,SNR1: 1.5052 ,SNR2: 5.9664




3C147 2026/06/01 3.94UT TOYOKAWA-KISO



F20260601125452





BLK:21,SNR1: 4.4927 ,SNR2: 13.249





3C147 2026/06/01 3.94UT FUJI -KISO


K20260601125449




BLK:21,SNR1: 1.4466 ,SNR2: 6.3313





T20260601130302




BLK: 8,SNR1: 0.66770 ,SNR2: 4.2632




F20260601130302





BLK: 8,SNR1: 1.8039 ,SNR2: 8.3616




0548+16 2026/06/01 4.08UT TOYOKAWA-FUJI





T20260601130302




BLK: 9,SNR1: 0.88397 ,SNR2: 6.2251




K20260601130259





BLK: 9,SNR1: 1.5372 ,SNR2: 6.3745




0548+16 2026/06/01 4.08UT TOYOKAWA-KISO




F20260601130302




BLK: 7,SNR1: 7.8509 ,SNR2: 19.168




K20260601130259




BLK: 7,SNR1: 2.0749 ,SNR2: 8.9665




0548+16 2026/06/01 4.08UT FUJI -KISO





T20260601130712




BLK:13,SNR1: 21.248 ,SNR2: 72.231




F20260601130712





BLK:13,SNR1: 2.0712 ,SNR2: 6.1411




0552+12 2026/06/01 4.15UT TOYOKAWA-FUJI




T20260601130712




BLK: 9,SNR1: 47.949 ,SNR2: 154.65




K20260601130709




BLK: 9,SNR1: 1.1233 ,SNR2: 4.7279




0552+12 2026/06/01 4.15UT TOYOKAWA-KISO




F20260601130712




BLK: 7,SNR1: 6.4147 ,SNR2: 14.433




K20260601130709





BLK: 7,SNR1: 5.7724 ,SNR2: 13.239




0552+12 2026/06/01 4.15UT FUJI -KISO




T20260601131139




BLK:13,SNR1: 19.141 ,SNR2: 46.920




F20260601131139





BLK:13,SNR1: 1.6215 ,SNR2: 4.6165




0556+191 2026/06/01 4.22UT TOYOKAWA-FUJI





T20260601131139




BLK:14,SNR1: 0.79342 ,SNR2: 1.9430




K20260601131136




BLK:14,SNR1: 1.5385 ,SNR2: 6.6091




0556+191 2026/06/01 4.22UT TOYOKAWA-KISO





F20260601131139




BLK: 6,SNR1: 0.81849 ,SNR2: 4.2057




K20260601131136





BLK: 6,SNR1: 1.2627 ,SNR2: 5.2298




0556+191 2026/06/01 4.22UT FUJI -KISO





T20260601131924




BLK: 5,SNR1: 48.525 ,SNR2: 177.28




F20260601131924





BLK: 5,SNR1: 0.98865 ,SNR2: 2.3884




0605-08 2026/06/01 4.35UT TOYOKAWA-FUJI





T20260601131924




BLK: 7,SNR1: 46.374 ,SNR2: 169.36




K20260601131921





BLK: 7,SNR1: 3.7737 ,SNR2: 7.5689




0605-08 2026/06/01 4.35UT TOYOKAWA-KISO



F20260601131924





BLK: 4,SNR1: 0.67686 ,SNR2: 1.6890





0605-08 2026/06/01 4.35UT FUJI -KISO



K20260601131921




BLK: 4,SNR1: 11.141 ,SNR2: 32.691



T20260601133832





BLK: 8,SNR1: 0.53695 ,SNR2: 5.3869




Frequency (Hz)

F20260601133832




BLK: 8,SNR1: 2.9841 ,SNR2: 10.587





Frequency (Hz)


3C161 2026/06/01 4.67UT TOYOKAWA-FUJI




T20260601133832




BLK:17,SNR1: 0.53967 ,SNR2: 3.1627




K20260601133829





BLK:17,SNR1: 0.96079 ,SNR2: 3.0906




3C161 2026/06/01 4.67UT TOYOKAWA-KISO





F20260601133832




BLK: 8,SNR1: 4.7460 ,SNR2: 24.795




K20260601133829





BLK: 8,SNR1: 1.3879 ,SNR2: 4.8931




3C161 2026/06/01 4.67UT FUJI -KISO



T20260601140605





BLK:11,SNR1: 12.563 ,SNR2: 30.436




Frequency (Hz)

F20260601140605




BLK:11,SNR1: 7.2203 ,SNR2: 20.842





Frequency (Hz)


0652-130 2026/06/01 5.13UT TOYOKAWA-FUJI




T20260601140605




BLK: 8,SNR1: 12.594 ,SNR2: 31.603




K20260601140602





BLK: 8,SNR1: 11.751 ,SNR2: 28.424




0652-130 2026/06/01 5.13UT TOYOKAWA-KISO





F20260601140605




BLK: 8,SNR1: 7.8947 ,SNR2: 20.188




K20260601140602





BLK: 8,SNR1: 9.5231 ,SNR2: 23.502




0652-130 2026/06/01 5.13UT FUJI -KISO





T20260601141742




BLK: 5,SNR1: 10.290 ,SNR2: 25.436




F20260601141742





BLK: 5,SNR1: 1.5425 ,SNR2: 8.1183




0703+138 2026/06/01 5.32UT TOYOKAWA-FUJI





T20260601141742




BLK: 6,SNR1: 10.399 ,SNR2: 25.693




K20260601141739





BLK: 6,SNR1: 19.153 ,SNR2: 28.701




0703+138 2026/06/01 5.32UT TOYOKAWA-KISO





F20260601141742




BLK: 4,SNR1: 9.1163 ,SNR2: 22.754




K20260601141739




BLK: 4,SNR1: 19.283 ,SNR2: 28.896




0703+138 2026/06/01 5.32UT FUJI -KISO





T20260601142704




BLK: 8,SNR1: 8.3470 ,SNR2: 19.536




F20260601142704




BLK: 8,SNR1: 6.7837 ,SNR2: 19.613




0713-024 2026/06/01 5.48UT TOYOKAWA-FUJI





T20260601142704




BLK: 6,SNR1: 9.0273 ,SNR2: 21.246




K20260601142701




BLK: 6,SNR1: 16.741 ,SNR2: 31.897




0713-024 2026/06/01 5.48UT TOYOKAWA-KISO





F20260601142704




BLK: 7,SNR1: 5.4058 ,SNR2: 15.795




K20260601142701





BLK: 7,SNR1: 11.635 ,SNR2: 28.183




0713-024 2026/06/01 5.48UT FUJI -KISO



T20260601143716




BLK:10,SNR1: 10.225 ,SNR2: 17.962




Frequency (Hz)

F20260601143716




BLK:10,SNR1: 3.1975 ,SNR2: 9.4743





Frequency (Hz)


0723+10 2026/06/01 5.65UT TOYOKAWA-FUJI





T20260601143716




BLK:19,SNR1: 10.206 ,SNR2: 17.926




K20260601143713




BLK:19,SNR1: 16.636 ,SNR2: 18.208




0723+10 2026/06/01 5.65UT TOYOKAWA-KISO




F20260601143716




BLK:14,SNR1: 2.6633 ,SNR2: 8.0070




K20260601143713





BLK:14,SNR1: 16.865 ,SNR2: 19.608




0723+10 2026/06/01 5.65UT FUJI -KISO





T20260601144732




BLK: 3,SNR1: 7.9768 ,SNR2: 16.718




F20260601144732





BLK: 3,SNR1: 2.3291 ,SNR2: 5.2441




0732+33 2026/06/01 5.82UT TOYOKAWA-FUJI





T20260601144732




BLK: 8,SNR1: 4.9540 ,SNR2: 10.368




K20260601144729




BLK: 8,SNR1: 9.1452 ,SNR2: 20.925




0732+33 2026/06/01 5.82UT TOYOKAWA-KISO



F20260601144732





BLK:12,SNR1: 7.3013 ,SNR2: 20.931




Frequency (Hz)

K20260601144729




BLK:12,SNR1: 9.1091 ,SNR2: 20.620





Frequency (Hz)


0732+33 2026/06/01 5.82UT FUJI -KISO



T20260601145532




BLK:12,SNR1: 0.26241 ,SNR2: 3.4769




Frequency (Hz)

F20260601145532




BLK:12,SNR1: 2.2124 ,SNR2: 5.3922





Frequency (Hz)


0741-06 2026/06/01 5.95UT TOYOKAWA-FUJI



T20260601145532





BLK:13,SNR1: 0.23024 ,SNR2: 1.7498




Frequency (Hz)

K20260601145529




BLK:13,SNR1: 0.86923 ,SNR2: 4.0799





Frequency (Hz)


0741-06 2026/06/01 5.95UT TOYOKAWA-KISO




F20260601145532




BLK:14,SNR1: 2.9045 ,SNR2: 11.074




K20260601145529







BLK:14,SNR1: 0.81092 ,SNR2: 3.3194




0741-06 2026/06/01 5.95UT FUJI -KISO








0752-200 2026/06/01 6.12UT TOYOKAWA-FUJI



T20260601150516




BLK: 5,SNR1: 2.9802 ,SNR2: 9.2158




Frequency (Hz)

K20260601150513








BLK: 5,SNR1: 8.1797 ,SNR2: 14.417




Frequency (Hz)

0752-200 2026/06/01 6.12UT TOYOKAWA-KISO







0752-200 2026/06/01 6.12UT FUJI -KISO



T20260601151252




BLK: 3,SNR1: 1.9162 ,SNR2: 6.6846




Frequency (Hz)

F20260601151252




BLK: 3,SNR1: 4.1040 ,SNR2: 9.3546




Frequency (Hz)


3C190 2026/06/01 6.24UT TOYOKAWA-FUJI



T20260601151252




BLK:11,SNR1: 0.63544 ,SNR2: 2.5708




Frequency (Hz)

K20260601151249




BLK:11,SNR1: 7.1491 ,SNR2: 16.561




Frequency (Hz)


3C190 2026/06/01 6.24UT TOYOKAWA-KISO



F20260601151252




BLK: 4,SNR1: 1.3371 ,SNR2: 3.2098




Frequency (Hz)

K20260601151249




BLK: 4,SNR1: 1.8815 ,SNR2: 5.8553





Frequency (Hz)


3C190 2026/06/01 6.24UT FUJI -KISO



T20260601152518





BLK: 4,SNR1: 7.0019 ,SNR2: 12.572




Frequency (Hz)

F20260601152518




BLK: 4,SNR1: 5.6556 ,SNR2: 12.519





Frequency (Hz)


3C196 2026/06/01 6.45UT TOYOKAWA-FUJI



T20260601152518





BLK: 4,SNR1: 6.8323 ,SNR2: 12.184




Frequency (Hz)

K20260601152515




BLK: 4,SNR1: 1.5660 ,SNR2: 6.2662




Frequency (Hz)


3C196 2026/06/01 6.45UT TOYOKAWA-KISO




F20260601152518




BLK: 4,SNR1: 6.1841 ,SNR2: 13.430




K20260601152515





BLK: 4,SNR1: 2.0758 ,SNR2: 8.9998




3C196 2026/06/01 6.45UT FUJI -KISO



T20260601153628





BLK: 1,SNR1: 0.47551 ,SNR2: 1.2495




Frequency (Hz)

F20260601153628




BLK: 1,SNR1: 1.6365 ,SNR2: 4.2526




Frequency (Hz)


0821+394 2026/06/01 6.64UT TOYOKAWA-FUJI



T20260601153628




BLK: 1,SNR1: 0.59374E-01,SNR2: 0.68303




Frequency (Hz)

K20260601153625




BLK: 1,SNR1: 4.4520 ,SNR2: 11.667





Frequency (Hz)


0821+394 2026/06/01 6.64UT TOYOKAWA-KISO





F20260601153628




No.Good Data




K20260601153625





No.Good Data




0821+394 2026/06/01 6.64UT FUJI -KISO



T20260601154805




BLK:10,SNR1: 2.7407 ,SNR2: 4.9073




Frequency (Hz)

F20260601154805




BLK:10,SNR1: 2.4712 ,SNR2: 7.1198





Frequency (Hz)


0834-19 2026/06/01 6.83UT TOYOKAWA-FUJI



T20260601154805





BLK:12,SNR1: 2.4649 ,SNR2: 4.3492




Frequency (Hz)

K20260601154802




BLK:12,SNR1: 6.0149 ,SNR2: 16.245




Frequency (Hz)


0834-19 2026/06/01 6.83UT TOYOKAWA-KISO



F20260601154805





BLK:10,SNR1: 3.3811 ,SNR2: 8.2425




Frequency (Hz)

K20260601154802




BLK:10,SNR1: 7.3866 ,SNR2: 19.065





Frequency (Hz)


0834-19 2026/06/01 6.83UT FUJI -KISO



T20260601155311




BLK:10,SNR1: 5.6504 ,SNR2: 13.546




Frequency (Hz)

F20260601155311




BLK:10,SNR1: 6.8707 ,SNR2: 17.212





Frequency (Hz)


0839-071 2026/06/01 6.91UT TOYOKAWA-FUJI



T20260601155311




BLK: 8,SNR1: 13.095 ,SNR2: 31.260




Frequency (Hz)

K20260601155308




BLK: 8,SNR1: 9.2200 ,SNR2: 22.621




Frequency (Hz)


0839-071 2026/06/01 6.91UT TOYOKAWA-KISO



F20260601155311




BLK: 2,SNR1: 8.3707 ,SNR2: 20.910




Frequency (Hz)

K20260601155308




BLK: 2,SNR1: 7.5110 ,SNR2: 18.199





Frequency (Hz)


0839-071 2026/06/01 6.91UT FUJI -KISO



T20260601160413




BLK: 5,SNR1: 0.21032 ,SNR2: 2.0722




Frequency (Hz)

F20260601160413




BLK: 5,SNR1: 0.98737 ,SNR2: 3.6410





Frequency (Hz)


3C208 2026/06/01 7.10UT TOYOKAWA-FUJI



T20260601160413




BLK: 5,SNR1: 0.10791 ,SNR2: 0.41013




Frequency (Hz)

K20260601160410




BLK: 5,SNR1: 1.8277 ,SNR2: 6.5405




Frequency (Hz)


3C208 2026/06/01 7.10UT TOYOKAWA-KISO



F20260601160413




BLK: 1,SNR1: 0.33684 ,SNR2: 2.7759




Frequency (Hz)

K20260601160410




BLK: 1,SNR1: 0.89194 ,SNR2: 3.6559




Frequency (Hz)


3C208 2026/06/01 7.10UT FUJI -KISO



T20260601162055




BLK: 2,SNR1: 9.3629 ,SNR2: 23.311




Frequency (Hz)

F20260601162055




BLK: 2,SNR1: 9.8146 ,SNR2: 24.138





Frequency (Hz)


3C216 2026/06/01 7.38UT TOYOKAWA-FUJI



T20260601162055




BLK: 1, SNR1: 11.522 , SNR2: 26.930




Frequency (Hz)

K20260601162052




BLK: 1, SNR1: 4.5306 , SNR2: 14.372




Frequency (Hz)


3C216 2026/06/01 7.38UT TOYOKAWA-KISO



F20260601162055





BLK: 1,SNR1: 18.092 ,SNR2: 31.824




Frequency (Hz)

K20260601162052




BLK: 1,SNR1: 12.710 ,SNR2: 19.569





Frequency (Hz)


3C216 2026/06/01 7.38UT FUJI -KISO



T20260601163944




BLK:10,SNR1: 2.1009 ,SNR2: 7.1318




Frequency (Hz)

F20260601163944




BLK:10,SNR1: 6.0683 ,SNR2: 15.077





Frequency (Hz)


0926+117 2026/06/01 7.69UT TOYOKAWA-FUJI



T20260601163944




BLK: 7, SNR1: 2.1050 , SNR2: 7.1461




Frequency (Hz)

K20260601163942




BLK: 7, SNR1: 3.1028 , SNR2: 9.0951




Frequency (Hz)


0926+117 2026/06/01 7.69UT TOYOKAWA-KISO



F20260601163944




BLK: 7,SNR1: 8.8739 ,SNR2: 21.407




Frequency (Hz)

K20260601163942




BLK: 7,SNR1: 5.4084 ,SNR2: 17.039




Frequency (Hz)


0926+117 2026/06/01 7.69UT FUJI -KISO



T20260601164729




BLK: 1,SNR1: 19.929 ,SNR2: 34.491




Frequency (Hz)

F20260601164729




BLK: 1,SNR1: 8.6880 ,SNR2: 21.736




Frequency (Hz)


3C222 2026/06/01 7.82UT TOYOKAWA-FUJI



T20260601164729





BLK: 2,SNR1: 9.0228 ,SNR2: 22.357




Frequency (Hz)

K20260601164726




BLK: 2,SNR1: 25.593 ,SNR2: 46.054




Frequency (Hz)


3C222 2026/06/01 7.82UT TOYOKAWA-KISO



F20260601164729





BLK: 3,SNR1: 7.5727 ,SNR2: 18.688




Frequency (Hz)

3C222 2026/06/01 7.82UT FUJI -KISO


K20260601164726




BLK: 3,SNR1: 21.264 ,SNR2: 37.829




Frequency (Hz)



T20260601174809




BLK: 2,SNR1: 6.7980 ,SNR2: 16.836




Frequency (Hz)

F20260601174809




BLK: 2,SNR1: 9.6769 ,SNR2: 33.648




Frequency (Hz)


1034+404 2026/06/01 8.83UT TOYOKAWA-FUJI



T20260601174809




BLK: 3, SNR1: 10.304 , SNR2: 25.286




Frequency (Hz)

K20260601174806




BLK: 3, SNR1: 6.0514 , SNR2: 21.611




Frequency (Hz)


1034+404 2026/06/01 8.83UT TOYOKAWA-KISO



F20260601174809




BLK: 6,SNR1: 2.6794 ,SNR2: 12.402




Frequency (Hz)

K20260601174806



BLK: 6,SNR1: 33.948 ,SNR2: 44.223



Frequency (Hz)

1034+404 2026/06/01 8.83UT FWJ -KISO

