




T20260614052309





BLK: 5,SNR1: 14.284 ,SNR2: 44.229




Frequency (Hz)

F20260614052309




BLK: 5,SNR1: 6.3987 ,SNR2: 13.796




Frequency (Hz)


2259+481 2026/06/13 20.41UT TOYOKAWA-FUJI



T20260614052309




BLK: 4,SNR1: 13.067 ,SNR2: 32.142




Frequency (Hz)

K20260614052306




BLK: 4,SNR1: 15.580 ,SNR2: 27.534





Frequency (Hz)


2259+481 2026/06/13 20.41UT TOYOKAWA-KISO



F20260614052309





BLK: 4,SNR1: 13.672 ,SNR2: 24.928




Frequency (Hz)

K20260614052306




BLK: 4,SNR1: 13.355 ,SNR2: 24.079





Frequency (Hz)


2259+481 2026/06/13 20.41UT FUJI -KISO





T20260614053913




No.Good Data




F20260614053913





No.Good Data




2315+396 2026/06/13 20.68UT TOYOKAWA-FUJI



T20260614053913





BLK: 2,SNR1: 0.21113 ,SNR2: 1.1722




Frequency (Hz)

K20260614053910




BLK: 2,SNR1: 7.7046 ,SNR2: 21.354





Frequency (Hz)


2315+396 2026/06/13 20.68UT TOYOKAWA-KISO



F20260614053913





BLK: 5,SNR1: 9.9794 ,SNR2: 25.468




Frequency (Hz)

K20260614053910




BLK: 5,SNR1: 14.503 ,SNR2: 34.092





Frequency (Hz)


2315+396 2026/06/13 20.68UT FUJI -KISO



T20260614061842





No.Good Data




Frequency (Hz)

F20260614061842




No.Good Data





Frequency (Hz)


2354+14 2026/06/13 21.34UT TOYOKAWA-FUJI



T20260614061842





BLK: 3,SNR1: 6.1399 ,SNR2: 14.978




Frequency (Hz)

2354+14 2026/06/13 21.34UT TOYOKAWA-KISO


K20260614061839





BLK: 3,SNR1: 12.379 ,SNR2: 30.602




Frequency (Hz)



F20260614061842





BLK: 1,SNR1:-0.14046 ,SNR2: 0.89923




Frequency (Hz)

2354+14 2026/06/13 21.34UT FUJI -KISO


K20260614061839





BLK: 1,SNR1: 0.32652 ,SNR2: 5.9525




Frequency (Hz)



T20260614063507





BLK: 6,SNR1: 6.6922 ,SNR2: 15.214




Frequency (Hz)

F20260614063507




BLK: 6,SNR1: 7.0510 ,SNR2: 20.353





Frequency (Hz)


0011+344 2026/06/13 21.61UT TOYOKAWA-FUJI



T20260614063507





BLK: 8,SNR1: 9.6559 ,SNR2: 24.090




Frequency (Hz)

K20260614063504




BLK: 8,SNR1: 7.3965 ,SNR2: 19.052





Frequency (Hz)


0011+344 2026/06/13 21.61UT TOYOKAWA-KISO



F20260614063507





BLK: 4,SNR1: 6.5341 ,SNR2: 18.329




Frequency (Hz)

K20260614063504




BLK: 4,SNR1: 7.4208 ,SNR2: 18.918





Frequency (Hz)


0011+344 2026/06/13 21.61UT FUJI -KISO



T20260614064343





BLK: 1,SNR1: 2.5871 ,SNR2: 14.638




Frequency (Hz)

F20260614064343




BLK: 1,SNR1: 2.8212 ,SNR2: 8.8389





Frequency (Hz)


0019-00 2026/06/13 21.76UT TOYOKAWA-FUJI



T20260614064343





BLK: 7,SNR1: 7.5636 ,SNR2: 19.024




Frequency (Hz)

0019-00 2026/06/13 21.76UT TOYOKAWA-KISO


K20260614064340





BLK: 7,SNR1: 13.303 ,SNR2: 24.628




Frequency (Hz)



F20260614064343





BLK: 3,SNR1: 10.943 ,SNR2: 23.394




Frequency (Hz)

0019-00 2026/06/13 21.76UT FUJI -KISO


K20260614064340





BLK: 3,SNR1: 8.2881 ,SNR2: 20.836




Frequency (Hz)



T20260614065358





BLK: 3,SNR1: 15.561 ,SNR2: 27.733




Frequency (Hz)

F20260614065358




BLK: 3,SNR1: 8.2506 ,SNR2: 20.396





Frequency (Hz)


3C12 2026/06/13 21.93UT TOYOKAWA-FUJI



T20260614065358





BLK: 2,SNR1: 5.9469 ,SNR2: 14.966




Frequency (Hz)

3C12 2026/06/13 21.93UT TOYOKAWA-KISO


K20260614065355




BLK: 2,SNR1: 9.1537 ,SNR2: 23.498




Frequency (Hz)



F20260614065358




BLK: 2,SNR1: 15.921 ,SNR2: 28.895




Frequency (Hz)

3C12 2026/06/13 21.93UT FUJI -KISO


K20260614065355





BLK: 2,SNR1: 1.9432 ,SNR2: 9.8666




Frequency (Hz)



T20260614070216





BLK: 1,SNR1: 0.50287 ,SNR2: 2.5195




Frequency (Hz)

F20260614070216




BLK: 1,SNR1: 0.17724 ,SNR2: 1.1524






Frequency (Hz)




0038+328 2026/06/13 22.07UT TOYOKAWA-FUJI




T20260614070216





K20260614070213




0038+328 2026/06/13 22.07UT TOYOKAWA-KISO



F20260614070216




BLK: 4,SNR1:-0.68569E-02,SNR2: 0.86379




Frequency (Hz)

K20260614070213




BLK: 4,SNR1: 1.5202 ,SNR2: 5.9834





Frequency (Hz)


0038+328 2026/06/13 22.07UT FUJI -KISO



T20260614071521





BLK: 5,SNR1: 3.2925 ,SNR2: 10.017




Frequency (Hz)

3C26 2026/06/13 22.28UT TOYOKAWA-FUJI


F20260614071521





BLK: 5,SNR1: 6.0664 ,SNR2: 12.999




Frequency (Hz)



T20260614071521





BLK: 4,SNR1: 1.3630 ,SNR2: 3.3736




Frequency (Hz)

3C26 2026/06/13 22.28UT TOYOKAWA-KISO


K20260614071518





BLK: 4,SNR1: 9.3558 ,SNR2: 20.935




Frequency (Hz)



F20260614071521





BLK: 8,SNR1: 1.1354 ,SNR2: 3.8620




Frequency (Hz)

3C26 2026/06/13 22.28UT FUJI -KISO


K20260614071518





BLK: 8,SNR1: 9.3958 ,SNR2: 20.784




Frequency (Hz)





T20260614072019




No.Good Data




F20260614072019




No.Good Data




0056-00 2026/06/13 22.37UT TOYOKAWA-FUJI





T20260614072019




No.Good Data




K20260614072016





No.Good Data




0056-00 2026/06/13 22.37UT TOYOKAWA-KISO



F20260614072019





BLK: 2,SNR1: 7.9303 ,SNR2: 19.418




Frequency (Hz)

0056-00 2026/06/13 22.37UT FUJI -KISO


K20260614072016






BLK: 2,SNR1: 10.636 ,SNR2: 25.808







Frequency (Hz)





T20260614073001




F20260614073001



T20260614073001





BLK: 7,SNR1: 7.7577 ,SNR2: 20.041





0106+01 2026/06/13 22.53UT TOYOKAWA-KISO



K20260614072958




BLK: 7,SNR1: 8.5390 ,SNR2: 22.061



F20260614073001





BLK: 8,SNR1: 7.0903 ,SNR2: 17.900





0106+01 2026/06/13 22.53UT FUJI -KISO



K20260614072958




BLK: 8,SNR1: 7.9682 ,SNR2: 22.838



T20260614073924





BLK: 2,SNR1: 2.1688 ,SNR2: 6.5177




Frequency (Hz)

0115-01 2026/06/13 22.68UT TOYOKAWA-FUJI


F20260614073924






BLK: 2,SNR1: 0.84702 ,SNR2: 5.3374






Frequency (Hz)




T20260614073924





K20260614073921




0115-01 2026/06/13 22.68UT TOYOKAWA-KISO



F20260614073924





BLK: 4,SNR1: 0.99097 ,SNR2: 6.3079




Frequency (Hz)

K20260614073921




BLK: 4,SNR1: 2.8936 ,SNR2: 9.0119





Frequency (Hz)


0115-01 2026/06/13 22.68UT FWJ -KISO



T20260614075224





BLK: 1,SNR1: 0.26106 ,SNR2: 0.36651




Frequency (Hz)

0128+03 2026/06/13 22.90UT TOYOKAWA-FUJI


F20260614075224





BLK: 1,SNR1: 4.5166 ,SNR2: 11.445




Frequency (Hz)



T20260614075224





BLK: 1,SNR1:-0.65636E-01,SNR2: 0.96376




Frequency (Hz)

0128+03 2026/06/13 22.90UT TOYOKAWA-KISO


K20260614075221





BLK: 1,SNR1: 1.8354 ,SNR2: 9.2355




Frequency (Hz)



F20260614075224





BLK: 4,SNR1: 5.1708 ,SNR2: 12.337




Frequency (Hz)

K20260614075221




BLK: 4,SNR1: 6.3575 ,SNR2: 15.833





Frequency (Hz)


0128+03 2026/06/13 22.90UT FUJI -KISO



T20260614075858




BLK:17,SNR1: 8.1389 ,SNR2: 18.478





3C48 2026/06/13 23.01UT TOYOKAWA-FUJI



F20260614075858




BLK:17,SNR1: 7.2890 ,SNR2: 21.213



T20260614075858




BLK:16,SNR1: 1.2519 ,SNR2: 4.7019




Frequency (Hz)

3C48 2026/06/13 23.01UT TOYOKAWA-KISO


K20260614075855




BLK:16,SNR1: 3.2634 ,SNR2: 8.6529




Frequency (Hz)



F20260614075858




BLK:13,SNR1: 7.8689 ,SNR2: 22.876




Frequency (Hz)

3C48 2026/06/13 23.01UT FUJI -KISO


K20260614075855




BLK:13,SNR1: 2.1628 ,SNR2: 6.3982




Frequency (Hz)



T20260614081842





BLK: 4, SNR1: 0.21038 , SNR2: 2.8066




Frequency (Hz)

F20260614081842




BLK: 4, SNR1: 3.7273 , SNR2: 10.007




Frequency (Hz)


0155-109 2026/06/13 23.34UT TOYOKAWA-FUJI




T20260614081842




BLK: 6,SNR1: 0.35901 ,SNR2: 1.4078




K20260614081839





BLK: 6,SNR1: 8.8959 ,SNR2: 22.862




0155-109 2026/06/13 23.34UT TOYOKAWA-KISO



F20260614081842





BLK: 5,SNR1: 3.5458 ,SNR2: 9.6790




Frequency (Hz)

K20260614081839




BLK: 5,SNR1: 8.6949 ,SNR2: 16.651




Frequency (Hz)


0155-109 2026/06/13 23.34UT FUJI -KISO





T20260614082550




BLK: 8,SNR1: 0.32247 ,SNR2: 2.0822




F20260614082550





BLK: 8,SNR1: 6.6378 ,SNR2: 19.725




0202+15 2026/06/13 23.46UT TOYOKAWA-FUJI



T20260614082550




BLK:12,SNR1: 1.8255 ,SNR2: 3.2142





0202+15 2026/06/13 23.46UT TOYOKAWA-KISO


K20260614082547




BLK:12,SNR1: 3.5367 ,SNR2: 10.491




F20260614082550




BLK: 7,SNR1: 7.0711 ,SNR2: 12.658




K20260614082547




BLK: 7,SNR1: 6.8943 ,SNR2: 13.687




0202+15 2026/06/13 23.46UT FUJI -KISO




T20260614083740




BLK: 3,SNR1: 0.57439E-01,SNR2: 0.34394




F20260614083740





BLK: 3,SNR1: 0.38776 ,SNR2: 3.9675




0213+178 2026/06/13 23.66UT TOYOKAWA-FUJI




T20260614083740




BLK: 2,SNR1: 0.82251E-01,SNR2: 0.54816




K20260614083737





BLK: 2,SNR1: 0.49115 ,SNR2: 1.5516




0213+178 2026/06/13 23.66UT TOYOKAWA-KISO



F20260614083740





BLK: 3,SNR1: 4.0126 ,SNR2: 10.619




Frequency (Hz)

K20260614083737




BLK: 3,SNR1: 5.3024 ,SNR2: 13.723





Frequency (Hz)


0213+178 2026/06/13 23.66UT FUJI -KISO



T20260614084523





BLK: 4,SNR1: 6.5426 ,SNR2: 17.815




Frequency (Hz)

3C67 2026/06/13 23.78UT TOYOKAWA-FUJI


F20260614084523





BLK: 4,SNR1: 11.603 ,SNR2: 29.090




Frequency (Hz)



T20260614084523





BLK: 2, SNR1: 4.3579 ,SNR2: 12.382




Frequency (Hz)

3C67 2026/06/13 23.78UT TOYOKAWA-KISO


K20260614084520





BLK: 2, SNR1: 3.3682 ,SNR2: 5.9252




Frequency (Hz)



F20260614084523





BLK: 3,SNR1: 10.275 ,SNR2: 24.592




Frequency (Hz)

3C67 2026/06/13 23.78UT FUJI -KISO


K20260614084520




BLK: 3,SNR1: 7.0916 ,SNR2: 19.559




Frequency (Hz)



T20260614085416




BLK: 9,SNR1: 6.1865 ,SNR2: 16.569





0230-035 2026/06/13 23.93UT TOYOKAWA-FUJI


F20260614085416




BLK: 9,SNR1: 1.6749 ,SNR2: 8.1071



T20260614085416




BLK:14,SNR1: 4.7075 ,SNR2: 12.370





0230-035 2026/06/13 23.93UT TOYOKAWA-KISO


K20260614085413




BLK:14,SNR1: 6.2895 ,SNR2: 16.570




F20260614085416




BLK:18,SNR1: 1.1621 ,SNR2: 5.7032




K20260614085413





BLK:18,SNR1: 6.4423 ,SNR2: 15.490




0230-035 2026/06/13 23.93UT FUJI -KISO




T20260614090337




BLK: 6,SNR1: 0.49177 ,SNR2: 2.9177




F20260614090337





BLK: 6,SNR1: 3.3554 ,SNR2: 6.0374




3C71 2026/06/14 0.09UT TOYOKAWA-FUJI



T20260614090337




BLK:10,SNR1: 0.90333 ,SNR2: 2.7413





3C71 2026/06/14 0.09UT TOYOKAWA-KISO



K20260614090334




BLK:10,SNR1: 7.7876 ,SNR2: 17.409



F20260614090337





BLK: 5,SNR1: 3.9647 ,SNR2: 6.8938




Frequency (Hz)

3C71 2026/06/14 0.09UT FUJI -KISO


K20260614090334





BLK: 5,SNR1: 6.9667 ,SNR2: 18.030




Frequency (Hz)





T20260614092253




BLK: 9,SNR1: 8.9935 ,SNR2: 22.439




F20260614092253





BLK: 9,SNR1: 8.4355 ,SNR2: 14.711




0258+350 2026/06/14 0.41UT TOYOKAWA-FUJI



T20260614092253





BLK:16,SNR1: 7.3224 ,SNR2: 18.527




Frequency (Hz)

0258+350 2026/06/14 0.41UT TOYOKAWA-KISO


K20260614092250




BLK:16,SNR1: 9.0144 ,SNR2: 23.569




Frequency (Hz)




F20260614092253




BLK:13,SNR1: 13.818 ,SNR2: 32.529




K20260614092250





BLK:13,SNR1: 10.636 ,SNR2: 19.741




0258+350 2026/06/14 0.41UT FUJI -KISO



T20260614093242




BLK: 5, SNR1: 5.7389 , SNR2: 17.264





0308+305 2026/06/14 0.57UT TOYOKAWA-FUJI



F20260614093242




BLK: 5, SNR1: 8.7229 , SNR2: 21.560



T20260614093242





BLK: 4, SNR1: 5.4767 , SNR2: 16.340





0308+305 2026/06/14 0.57UT TOYOKAWA-KISO


K20260614093239




BLK: 4, SNR1: 6.9980 , SNR2: 18.223





F20260614093242




BLK: 7, SNR1: 7.5927 ,SNR2: 18.586




K20260614093239





BLK: 7, SNR1: 6.8531 ,SNR2: 19.833




0308+305 2026/06/14 0.57UT FUJI -KISO



T20260614094103





BLK: 4, SNR1: 10.046 , SNR2: 24.549





3C84 2026/06/14 0.71UT TOYOKAWA-FUJI



F20260614094103




BLK: 4, SNR1: 11.533 , SNR2: 30.309



T20260614094103





BLK: 4, SNR1: 8.4761 , SNR2: 21.705





3C84 2026/06/14 0.71UT TOYOKAWA-KISO



K20260614094100




BLK: 4, SNR1: 8.1034 , SNR2: 21.409



F20260614094103





BLK: 6,SNR1: 6.8353 ,SNR2: 19.801





3C84 2026/06/14 0.71UT FUJI -KISO


K20260614094100




BLK: 6,SNR1: 9.2575 ,SNR2: 24.466



T20260614094818




BLK:22,SNR1: 2.5128 ,SNR2: 7.7631





0324+119 2026/06/14 0.83UT TOYOKAWA-FUJI


F20260614094818




BLK:22,SNR1: 5.4392 ,SNR2: 13.491



T20260614094818





BLK:26,SNR1: 2.5026 ,SNR2: 7.7971





0324+119 2026/06/14 0.83UT TOYOKAWA-KISO


K20260614094815




BLK:26,SNR1: 16.592 ,SNR2: 19.291




F20260614094818




BLK:25,SNR1: 5.2527 ,SNR2: 9.3493




K20260614094815




BLK:25,SNR1: 16.536 ,SNR2: 19.226




0324+119 2026/06/14 0.83UT FUJI -KISO



T20260614095735





BLK: 5,SNR1: 0.50426 ,SNR2: 1.3603





0333+32 2026/06/14 0.99UT TOYOKAWA-FUJI


F20260614095735




BLK: 5,SNR1: 5.6434 ,SNR2: 10.052





T20260614095735




BLK: 7,SNR1: 0.53526 ,SNR2: 1.5224




K20260614095732





BLK: 7,SNR1: 10.453 ,SNR2: 20.304




0333+32 2026/06/14 0.99UT TOYOKAWA-KISO




F20260614095735




BLK: 6,SNR1: 5.5501 ,SNR2: 13.313




K20260614095732





BLK: 6,SNR1: 1.9856 ,SNR2: 7.3775




0333+32 2026/06/14 0.99UT FUJI -KISO



T20260614101036




BLK: 2,SNR1:-0.42690E-02,SNR2: 0.38651





0347+05 2026/06/14 1.20UT TOYOKAWA-FUJI



F20260614101036




BLK: 2,SNR1: 1.0435 ,SNR2: 3.8606



T20260614101036





BLK: 1,SNR1: 0.26600E-01,SNR2: 0.47375




0347+05 2026/06/14 1.20UT TOYOKAWA-KISO


K20260614101033




BLK: 1,SNR1: 0.47084 ,SNR2: 3.5190




Frequency (Hz)




F20260614101036




BLK: 4,SNR1: 2.2887 ,SNR2: 7.6782




K20260614101033





BLK: 4,SNR1: 0.51935 ,SNR2: 2.7461




0347+05 2026/06/14 1.20UT FUJI -KISO




T20260614102610




BLK: 3,SNR1:-0.82275E-01,SNR2: 1.0732




F20260614102610





BLK: 3,SNR1: 2.7644 ,SNR2: 7.8880




0403-132 2026/06/14 1.46UT TOYOKAWA-FUJI



T20260614102610





BLK: 2,SNR1:-0.26497E-01,SNR2: 0.88641





0403-132 2026/06/14 1.46UT TOYOKAWA-KISO


K20260614102607




BLK: 2,SNR1: 1.7315 ,SNR2: 7.8627





F20260614102610




BLK: 4,SNR1: 2.8576 ,SNR2: 14.410




K20260614102607




BLK: 4,SNR1: 0.62419 ,SNR2: 3.1627




0403-132 2026/06/14 1.46UT FUJI -KISO




T20260614103521




BLK: 3,SNR1: 0.34631 ,SNR2: 0.70743




F20260614103521





BLK: 3,SNR1: 0.25739 ,SNR2: 3.9675




0411+05 2026/06/14 1.62UT TOYOKAWA-FUJI




T20260614103521




BLK: 4,SNR1: 0.24639 ,SNR2: 1.7169




K20260614103518




BLK: 4,SNR1: 0.19490 ,SNR2: 0.87483




0411+05 2026/06/14 1.62UT TOYOKAWA-KISO




F20260614103521




BLK: 2,SNR1: 1.1312 ,SNR2: 3.6777




K20260614103518





BLK: 2,SNR1: 0.18356 ,SNR2: 2.2359




0411+05 2026/06/14 1.62UT FUJI -KISO




T20260614104216




BLK: 8,SNR1: 2.4578 ,SNR2: 7.3742




F20260614104216




BLK: 8,SNR1: 10.682 ,SNR2: 25.548




0418+236 2026/06/14 1.73UT TOYOKAWA-FUJI




T20260614104216




BLK:14,SNR1: 2.0321 ,SNR2: 6.0680




K20260614104213




BLK:14,SNR1: 2.8546 ,SNR2: 8.8000




0418+236 2026/06/14 1.73UT TOYOKAWA-KISO




F20260614104216




BLK:21,SNR1: 12.630 ,SNR2: 22.612




K20260614104213




BLK:21,SNR1: 2.9602 ,SNR2: 9.0616




0418+236 2026/06/14 1.73UT FUJI -KISO





T20260614105344




BLK:11,SNR1: 3.2186 ,SNR2: 11.788




F20260614105344




BLK:11,SNR1: 5.3483 ,SNR2: 18.909




3C119 2026/06/14 1.92UT TOYOKAWA-FUJI




T20260614105344




BLK:20,SNR1: 3.2478 ,SNR2: 11.806




K20260614105342





BLK:20,SNR1: 5.3754 ,SNR2: 13.459




3C119 2026/06/14 1.92UT TOYOKAWA-KISO



F20260614105344




BLK: 1,SNR1: 3.5085 ,SNR2: 8.2443





3C119 2026/06/14 1.92UT FUJI -KISO



K20260614105342




BLK: 1,SNR1: 0.87375 ,SNR2: 4.7232





T20260614114150




BLK:15,SNR1: 44.170 ,SNR2: 96.513




F20260614114150





BLK:15,SNR1: 7.4368 ,SNR2: 18.125




3C138 2026/06/14 2.73UT TOYOKAWA-FUJI





T20260614114150




BLK:22,SNR1: 46.114 ,SNR2: 99.678




K20260614114147





BLK:22,SNR1: 10.668 ,SNR2: 23.612




3C138 2026/06/14 2.73UT TOYOKAWA-KISO





F20260614114150




BLK: 1,SNR1: 0.61951 ,SNR2: 4.7720




K20260614114147





BLK: 1,SNR1: 9.2598 ,SNR2: 29.122




3C138 2026/06/14 2.73UT FUJI -KISO





T20260614115524




BLK:15,SNR1: 11.536 ,SNR2: 27.206




F20260614115524





BLK:15,SNR1: 8.5964 ,SNR2: 21.479




0531+194 2026/06/14 2.95UT TOYOKAWA-FUJI



T20260614115524





BLK: 7,SNR1: 6.4597 ,SNR2: 11.724





0531+194 2026/06/14 2.95UT TOYOKAWA-KISO



K20260614115521




BLK: 7,SNR1: 10.232 ,SNR2: 19.060





F20260614115524




BLK: 8,SNR1: 17.284 ,SNR2: 30.218




K20260614115521





BLK: 8,SNR1: 16.141 ,SNR2: 29.193




0531+194 2026/06/14 2.95UT FUJI -KISO




T20260614120345




BLK:26,SNR1: 16.746 ,SNR2: 34.379




F20260614120345





BLK:26,SNR1: 3.7321 ,SNR2: 6.1273




3C147 2026/06/14 3.09UT TOYOKAWA-FUJI




T20260614120345




BLK:29,SNR1: 15.687 ,SNR2: 30.671




K20260614120342




BLK:29,SNR1: 5.2454 ,SNR2: 18.229




3C147 2026/06/14 3.09UT TOYOKAWA-KISO




F20260614120345




BLK:23,SNR1: 2.8805 ,SNR2: 7.0014




K20260614120342





BLK:23,SNR1: 3.7488 ,SNR2: 14.912




3C147 2026/06/14 3.09UT FUJI -KISO



T20260614121155





BLK: 1,SNR1: 2.5389 ,SNR2: 14.603





0548+16 2026/06/14 3.23UT TOYOKAWA-FUJI



F20260614121155




BLK: 1,SNR1: 7.9632 ,SNR2: 19.723



T20260614121155





BLK: 1,SNR1: 3.5985 ,SNR2: 9.0745





0548+16 2026/06/14 3.23UT TOYOKAWA-KISO



K20260614121152




BLK: 1,SNR1: 13.187 ,SNR2: 31.150





F20260614121155




No.Good Data




K20260614121152




No.Good Data




0548+16 2026/06/14 3.23UT FUJI -KISO




T20260614121605




BLK: 7,SNR1: 16.092 ,SNR2: 33.287




F20260614121605




BLK: 7,SNR1: 5.1673 ,SNR2: 12.432




0552+12 2026/06/14 3.30UT TOYOKAWA-FUJI



T20260614121605





BLK: 9,SNR1: 41.108 ,SNR2: 99.611





0552+12 2026/06/14 3.30UT TOYOKAWA-KISO



K20260614121602




BLK: 9,SNR1: 7.2180 ,SNR2: 18.189





F20260614121605




No. Good Data




K20260614121602




No. Good Data




0552+12 2026/06/14 3.30UT FUJI -KISO




T20260614122032




BLK: 2,SNR1: 10.450 ,SNR2: 25.635




F20260614122032





BLK: 2,SNR1: 15.370 ,SNR2: 35.734




0556+191 2026/06/14 3.37UT TOYOKAWA-FUJI



T20260614122032





No.Good Data




Frequency (Hz)

K20260614122029




No.Good Data




Frequency (Hz)


0556+191 2026/06/14 3.37UT TOYOKAWA-KISO





F20260614122032




BLK: 3,SNR1: 18.470 ,SNR2: 33.095




K20260614122029





BLK: 3,SNR1: 22.026 ,SNR2: 39.103




0556+191 2026/06/14 3.37UT FUJI -KISO





T20260614122817




BLK: 2,SNR1: 5.1482 ,SNR2: 12.894




F20260614122817





BLK: 2,SNR1: 16.342 ,SNR2: 28.903




0605-08 2026/06/14 3.50UT TOYOKAWA-FUJI





T20260614122817




No.Good Data




K20260614122814





No.Good Data




0605-08 2026/06/14 3.50UT TOYOKAWA-KISO





F20260614122817




No.Good Data




K20260614122814




No.Good Data




0605-08 2026/06/14 3.50UT FUJI -KISO



T20260614124725





BLK: 2,SNR1: 10.371 ,SNR2: 25.567





3C161 2026/06/14 3.82UT TOYOKAWA-FUJI


F20260614124725




BLK: 2,SNR1: 9.3898 ,SNR2: 23.195





T20260614124725




BLK: 4,SNR1: 11.943 ,SNR2: 21.049




K20260614124722





BLK: 4,SNR1: 11.582 ,SNR2: 20.827




3C161 2026/06/14 3.82UT TOYOKAWA-KISO





F20260614124725




BLK: 3,SNR1: 7.8904 ,SNR2: 19.825




K20260614124722





BLK: 3,SNR1: 14.617 ,SNR2: 35.610




3C161 2026/06/14 3.82UT FUJI -KISO





T20260614131458




No.Good Data




F20260614131458




No.Good Data




0652-130 2026/06/14 4.28UT TOYOKAWA-FUJI





T20260614131458




BLK: 1,SNR1: 10.594 ,SNR2: 18.131




K20260614131455




BLK: 1,SNR1: 9.4641 ,SNR2: 22.013




0652-130 2026/06/14 4.28UT TOYOKAWA-KISO



F20260614131458





BLK: 1,SNR1: 6.3420 ,SNR2: 8.9103





0652-130 2026/06/14 4.28UT FUJI -KISO


K20260614131455




BLK: 1,SNR1: 11.196 ,SNR2: 24.196



T20260614132635




BLK: 3,SNR1: 5.8254 ,SNR2: 27.361





0703+138 2026/06/14 4.47UT TOYOKAWA-FUJI


F20260614132635




BLK: 3,SNR1: 18.787 ,SNR2: 40.007



T20260614132635




BLK: 2,SNR1: 5.6447 ,SNR2: 26.532





0703+138 2026/06/14 4.47UT TOYOKAWA-KISO



K20260614132632




BLK: 2,SNR1: 12.332 ,SNR2: 26.973





F20260614132635




No.Good Data




K20260614132632





No.Good Data




0703+138 2026/06/14 4.47UT FUJI -KISO





T20260614133557




BLK: 1,SNR1: 8.2393 ,SNR2: 20.395




F20260614133557





BLK: 1,SNR1: 7.5751 ,SNR2: 19.024




0713-024 2026/06/14 4.63UT TOYOKAWA-FUJI





T20260614133557




No.Good Data




K20260614133554





No.Good Data




0713-024 2026/06/14 4.63UT TOYOKAWA-KISO




F20260614133557




No.Good Data




K20260614133554





No.Good Data




0713-024 2026/06/14 4.63UT FUJI -KISO





T20260614134610




BLK: 1,SNR1: 26.926 ,SNR2: 51.833




F20260614134610





BLK: 1,SNR1: 13.531 ,SNR2: 32.992




0723+10 2026/06/14 4.80UT TOYOKAWA-FUJI





T20260614134610




No.Good Data




K20260614134607





No.Good Data




0723+10 2026/06/14 4.80UT TOYOKAWA-KISO



F20260614134610





BLK: 1,SNR1: 0.25293 ,SNR2: 4.4301





0723+10 2026/06/14 4.80UT FUJI -KISO


K20260614134607




BLK: 1,SNR1: 0.34448 ,SNR2: 0.91422




T20260614135625




BLK: 1,SNR1: 10.790 ,SNR2: 20.056




F20260614135625





BLK: 1,SNR1: 10.009 ,SNR2: 24.047




0732+33 2026/06/14 4.97UT TOYOKAWA-FUJI





T20260614135625




No.Good Data




K20260614135622




No.Good Data




0732+33 2026/06/14 4.97UT TOYOKAWA-KISO




F20260614135625




BLK: 6,SNR1: 13.869 ,SNR2: 21.271




K20260614135622





BLK: 6,SNR1: 3.0865 ,SNR2: 9.3453




0732+33 2026/06/14 4.97UT FUJI -KISO





T20260614140426




No.Good Data




F20260614140426





No.Good Data




0741-06 2026/06/14 5.10UT TOYOKAWA-FUJI





T20260614140426




No.Good Data




K20260614140423





No.Good Data




0741-06 2026/06/14 5.10UT TOYOKAWA-KISO





F20260614140426




No.Good Data




K20260614140423





No.Good Data




0741-06 2026/06/14 5.10UT FUJI -KISO





T20260614141409




No.Good Data




F20260614141409





No.Good Data




0752-200 2026/06/14 5.26UT TOYOKAWA-FUJI





T20260614141409




No.Good Data




K20260614141406





No.Good Data




0752-200 2026/06/14 5.26UT TOYOKAWA-KISO





F20260614141409




No.Good Data




K20260614141406





No.Good Data




0752-200 2026/06/14 5.26UT FUJI -KISO





T20260614142146




BLK: 9,SNR1: 1.3493 ,SNR2: 4.3122




F20260614142146





BLK: 9,SNR1: 3.1349 ,SNR2: 7.8327




3C190 2026/06/14 5.39UT TOYOKAWA-FUJI





T20260614142146




BLK: 4,SNR1: 0.93680E-01,SNR2: 2.0020




K20260614142143





BLK: 4,SNR1: 1.1507 ,SNR2: 7.7652




3C190 2026/06/14 5.39UT TOYOKAWA-KISO





F20260614142146




BLK: 3,SNR1: 2.3242 ,SNR2: 6.1775




K20260614142143





BLK: 3,SNR1: 1.5058 ,SNR2: 6.1023




3C190 2026/06/14 5.39UT FUJI -KISO





T20260614143412




BLK: 7,SNR1: 0.91699 ,SNR2: 3.0262




F20260614143412





BLK: 7,SNR1: 3.3837 ,SNR2: 8.1332




3C196 2026/06/14 5.60UT TOYOKAWA-FUJI





T20260614143412




BLK:11,SNR1: 0.78409 ,SNR2: 3.8862




K20260614143409




BLK:11,SNR1: 1.6133 ,SNR2: 7.4900




3C196 2026/06/14 5.60UT TOYOKAWA-KISO




F20260614143412




BLK: 9,SNR1: 2.6674 ,SNR2: 6.8048




K20260614143409





BLK: 9,SNR1: 1.7169 ,SNR2: 5.7997




3C196 2026/06/14 5.60UT FUJI -KISO



T20260614144521




BLK: 2,SNR1: 0.26659 ,SNR2: 1.7806




Frequency (Hz)

F20260614144521




BLK: 2,SNR1: 0.97286E-01,SNR2: 2.3381





Frequency (Hz)


0821+394 2026/06/14 5.78UT TOYOKAWA-FUJI



T20260614144521




BLK: 6,SNR1: 0.69780 ,SNR2: 2.4493




Frequency (Hz)

K20260614144518




BLK: 6,SNR1: 6.3002 ,SNR2: 8.1689




Frequency (Hz)


0821+394 2026/06/14 5.78UT TOYOKAWA-KISO




F20260614144521




BLK: 4,SNR1: 0.12954 ,SNR2: 2.4522




K20260614144518





BLK: 4,SNR1: 4.7564 ,SNR2: 8.1793




0821+394 2026/06/14 5.78UT FUJI -KISO



T20260614145659





BLK: 4,SNR1: 1.9750 ,SNR2: 5.4943




Frequency (Hz)

F20260614145659




BLK: 4,SNR1: 3.3516 ,SNR2: 10.042





Frequency (Hz)


0834-19 2026/06/14 5.98UT TOYOKAWA-FUJI





T20260614145659




BLK: 3,SNR1: 3.5597 ,SNR2: 10.770




K20260614145656





BLK: 3,SNR1: 2.6307 ,SNR2: 8.3377




0834-19 2026/06/14 5.98UT TOYOKAWA-KISO



F20260614145659





BLK: 6,SNR1: 3.2204 ,SNR2: 9.6505




Frequency (Hz)

K20260614145656




BLK: 6,SNR1: 2.3274 ,SNR2: 7.5302





Frequency (Hz)


0834-19 2026/06/14 5.98UT FUJI -KISO



T20260614150205




BLK:13,SNR1: 15.828 ,SNR2: 40.298




Frequency (Hz)

F20260614150205




BLK:13,SNR1: 4.4256 ,SNR2: 11.163





Frequency (Hz)


0839-071 2026/06/14 6.06UT TOYOKAWA-FUJI




T20260614150205




BLK:16,SNR1: 15.630 ,SNR2: 27.673




K20260614150202




BLK:16,SNR1: 8.1043 ,SNR2: 14.153





0839-071 2026/06/14 6.06UT TOYOKAWA-KISO







BLK: 5,SNR1: 5.9930 ,SNR2: 13.971





BLK: 5,SNR1: 6.8300 ,SNR2: 13.248




0839-071 2026/06/14 6.06UT FUJI -KISO





T20260614151306




BLK: 4,SNR1: 0.17316 ,SNR2: 0.78679




F20260614151306





BLK: 4,SNR1: 0.84784E-01,SNR2: 1.5475




3C208 2026/06/14 6.25UT TOYOKAWA-FUJI




T20260614151306




BLK: 4,SNR1: 0.30999 ,SNR2: 0.80321




K20260614151303





BLK: 4,SNR1: 2.1415 ,SNR2: 8.3491




3C208 2026/06/14 6.25UT TOYOKAWA-KISO





F20260614151306




BLK: 4,SNR1: 2.0821 ,SNR2: 3.8187




K20260614151303





BLK: 4,SNR1: 2.3322 ,SNR2: 9.0076




3C208 2026/06/14 6.25UT FUJI -KISO



T20260614152948





BLK: 7,SNR1: 0.35767 ,SNR2: 2.8629




Frequency (Hz)

F20260614152948




BLK: 7,SNR1: 2.5454 ,SNR2: 6.3958





Frequency (Hz)


3C216 2026/06/14 6.53UT TOYOKAWA-FUJI



T20260614152948





BLK: 3,SNR1: 0.87821 ,SNR2: 3.1269




Frequency (Hz)

K20260614152945




BLK: 3,SNR1: 2.6512 ,SNR2: 5.2658




Frequency (Hz)


3C216 2026/06/14 6.53UT TOYOKAWA-KISO





F20260614152948




BLK: 3,SNR1: 20.377 ,SNR2: 36.302




K20260614152945





BLK: 3,SNR1: 11.187 ,SNR2: 27.382




3C216 2026/06/14 6.53UT FUJI -KISO




T20260614154158




BLK:10,SNR1: 7.0084 ,SNR2: 16.802




F20260614154158





BLK:10,SNR1: 2.9668 ,SNR2: 7.1855




0919-142 2026/06/14 6.73UT TOYOKAWA-FUJI





T20260614154158




BLK:11,SNR1: 6.8587 ,SNR2: 16.614




K20260614154155




BLK:11,SNR1: 5.0138 ,SNR2: 9.8871




0919-142 2026/06/14 6.73UT TOYOKAWA-KISO



F20260614154158





BLK: 9,SNR1: 1.2517 ,SNR2: 4.4515




Frequency (Hz)

K20260614154155




BLK: 9,SNR1: 7.0008 ,SNR2: 12.832




Frequency (Hz)


0919-142 2026/06/14 6.73UT FUJI -KISO



T20260614154838





BLK: 2,SNR1: 14.026 ,SNR2: 27.265




Frequency (Hz)

F20260614154838




BLK: 2,SNR1: 14.025 ,SNR2: 35.410




Frequency (Hz)


0926+117 2026/06/14 6.84UT TOYOKAWA-FUJI



T20260614154838




BLK: 2,SNR1: 13.871 ,SNR2: 26.334




Frequency (Hz)

K20260614154835




BLK: 2,SNR1: 10.814 ,SNR2: 29.060





Frequency (Hz)


0926+117 2026/06/14 6.84UT TOYOKAWA-KISO




F20260614154838




BLK: 2,SNR1: 5.4551 ,SNR2: 19.802




K20260614154835





BLK: 2,SNR1: 26.669 ,SNR2: 31.015




0926+117 2026/06/14 6.84UT FUJI -KISO



T20260614155622





BLK: 5,SNR1: 9.1239 ,SNR2: 22.502




Frequency (Hz)

F20260614155622




BLK: 5,SNR1: 11.981 ,SNR2: 27.417





Frequency (Hz)


3C222 2026/06/14 6.97UT TOYOKAWA-FUJI



T20260614155622




BLK: 8,SNR1: 13.064 ,SNR2: 30.518




Frequency (Hz)

K20260614155619




BLK: 8,SNR1: 8.6576 ,SNR2: 22.077





Frequency (Hz)


3C222 2026/06/14 6.97UT TOYOKAWA-KISO



F20260614155622




BLK: 4, SNR1: 64.301 , SNR2: 66.283




Frequency (Hz)

K20260614155619




BLK: 4, SNR1: 11.469 , SNR2: 28.844





Frequency (Hz)


3C222 2026/06/14 6.97UT FUJI -KISO





T20260614160322




BLK: 1, SNR1: 2.2388 , SNR2: 30.678




F20260614160322





BLK: 1, SNR1: 5.5538 , SNR2: 19.744




0941-08 2026/06/14 7.08UT TOYOKAWA-FUJI



T20260614160322





BLK: 1,SNR1: 2.2387 ,SNR2: 30.677




Frequency (Hz)

K20260614160319




BLK: 1,SNR1: 8.7751 ,SNR2: 22.472





Frequency (Hz)


0941-08 2026/06/14 7.08UT TOYOKAWA-KISO





F20260614160322




No.Good Data




K20260614160319





No.Good Data




0941-08 2026/06/14 7.08UT FUJI -KISO



T20260614161144




BLK: 7,SNR1: 11.261 ,SNR2: 26.315




Frequency (Hz)

F20260614161144




BLK: 7,SNR1: 19.279 ,SNR2: 47.940





Frequency (Hz)


3C230 2026/06/14 7.22UT TOYOKAWA-FUJI



T20260614161144





BLK: 5,SNR1: 13.370 ,SNR2: 32.519




Frequency (Hz)

K20260614161141




BLK: 5,SNR1: 7.9691 ,SNR2: 20.784




Frequency (Hz)


3C230 2026/06/14 7.22UT TOYOKAWA-KISO




F20260614161144




BLK: 8,SNR1: 83.778 ,SNR2: 101.83




K20260614161141




BLK: 8,SNR1: 14.854 ,SNR2: 35.311




3C230 2026/06/14 7.22UT FUJI -KISO



T20260614162745




BLK: 2,SNR1: 18.634 ,SNR2: 63.764




Frequency (Hz)

F20260614162745




BLK: 2,SNR1: 4.6204 ,SNR2: 11.222




Frequency (Hz)


3C237 2026/06/14 7.49UT TOYOKAWA-FUJI



T20260614162745




BLK: 1,SNR1: 1.4705 ,SNR2: 3.2685




Frequency (Hz)

K20260614162742




BLK: 1,SNR1: 0.75598 ,SNR2: 4.0404




Frequency (Hz)


3C237 2026/06/14 7.49UT TOYOKAWA-KISO



F20260614162745




BLK: 1,SNR1: 0.55491 ,SNR2: 2.5262




Frequency (Hz)

K20260614162742




BLK: 1,SNR1: 6.0246 ,SNR2: 15.945





Frequency (Hz)


3C237 2026/06/14 7.49UT FUJI -KISO



T20260614163401





BLK: 3,SNR1: 9.1477 ,SNR2: 22.467




Frequency (Hz)

F20260614163401




BLK: 3,SNR1: 13.527 ,SNR2: 33.548





Frequency (Hz)


1011+110 2026/06/14 7.60UT TOYOKAWA-FUJI



T20260614163401





BLK: 1,SNR1: 6.6495 ,SNR2: 18.861




Frequency (Hz)

K20260614163358




BLK: 1,SNR1: 9.6737 ,SNR2: 24.110





Frequency (Hz)


1011+110 2026/06/14 7.60UT TOYOKAWA-KISO



F20260614163401





BLK: 3,SNR1: 13.619 ,SNR2: 33.789




Frequency (Hz)

K20260614163358




BLK: 3,SNR1: 7.3274 ,SNR2: 20.025





Frequency (Hz)


1011+110 2026/06/14 7.60UT FUJI -KISO



T20260614164142





BLK:17,SNR1: 3.0554 ,SNR2: 14.120




Frequency (Hz)

F20260614164142




BLK:17,SNR1: 14.902 ,SNR2: 26.413





Frequency (Hz)


3C241 2026/06/14 7.72UT TOYOKAWA-FUJI



T20260614164142





BLK:19,SNR1: 10.032 ,SNR2: 18.669




Frequency (Hz)

K20260614164139




BLK:19,SNR1: 7.1002 ,SNR2: 20.530





Frequency (Hz)


3C241 2026/06/14 7.72UT TOYOKAWA-KISO



F20260614164142





BLK:17,SNR1: 14.862 ,SNR2: 26.345




Frequency (Hz)

3C241 2026/06/14 7.72UT FUJI -KISO


K20260614164139




BLK:17,SNR1: 7.0974 ,SNR2: 20.524




Frequency (Hz)



T20260614175304




BLK: 4,SNR1: 2.5543 ,SNR2: 7.8479




Frequency (Hz)

F20260614175304




BLK: 4,SNR1: 3.1188 ,SNR2: 11.285




Frequency (Hz)


1130+335 2026/06/14 8.91UT TOYOKAWA-FUJI



T20260614175304




BLK: 4,SNR1:-0.65308E-01,SNR2: 0.33361




Frequency (Hz)

K20260614175302




BLK: 4,SNR1: 1.5508 ,SNR2: 6.3211




Frequency (Hz)


1130+335 2026/06/14 8.91UT TOYOKAWA-KISO



F20260614175304





BLK: 3,SNR1: 1.3238 ,SNR2: 3.6620




Frequency (Hz)

K20260614175302




BLK: 3,SNR1: 2.1310 ,SNR2: 7.9081





Frequency (Hz)


1130+335 2026/06/14 8.91UT FUJI -KISO



T20260614180721





BLK: 1,SNR1: 0.26598E-01,SNR2: 1.4409




Frequency (Hz)

F20260614180721




BLK: 1,SNR1: 18.522 ,SNR2: 42.975





Frequency (Hz)


1145+485 2026/06/14 9.15UT TOYOKAWA-FUJI



T20260614180721





BLK: 3,SNR1: 1.7624 ,SNR2: 18.413




Frequency (Hz)

K20260614180718




BLK: 3,SNR1: 1.3336 ,SNR2: 5.1113




Frequency (Hz)


1145+485 2026/06/14 9.15UT TOYOKAWA-KISO



F20260614180721




No.Good Data




Frequency (Hz)

K20260614180718



No.Good Data



Frequency (Hz)

1145+485 2026/06/14 9.15UT FWJ -KISO

