




T20260620055009




BLK: 7,SNR1: 0.16416 ,SNR2: 0.62542




Frequency (Hz)

F20260620055011




BLK: 7,SNR1: 1.1310 ,SNR2: 3.3075





Frequency (Hz)


2349+327 2026/06/19 20.86UT TOYOKAWA-FUJI



T20260620055009





BLK:11,SNR1: 0.75392E-01,SNR2: 0.50457




Frequency (Hz)

K20260620055006




BLK:11,SNR1: 4.4961 ,SNR2: 11.447





Frequency (Hz)


2349+327 2026/06/19 20.86UT TOYOKAWA-KISO



F20260620055011





BLK:12,SNR1: 1.6305 ,SNR2: 5.3596




Frequency (Hz)

K20260620055006




BLK:12,SNR1: 1.7360 ,SNR2: 5.5085





Frequency (Hz)


2349+327 2026/06/19 20.86UT FUJI -KISO



T20260620060343





BLK: 2,SNR1: 0.59378 ,SNR2: 3.3080




Frequency (Hz)

F20260620060345




BLK: 2,SNR1: 0.18273 ,SNR2: 1.7511




Frequency (Hz)


0003+313 2026/06/19 21.09UT TOYOKAWA-FUJI



T20260620060343





BLK: 3,SNR1: 0.46972 ,SNR2: 4.0751




Frequency (Hz)

K20260620060340




BLK: 3,SNR1: 0.45410 ,SNR2: 4.1030





Frequency (Hz)


0003+313 2026/06/19 21.09UT TOYOKAWA-KISO



F20260620060345





BLK: 2,SNR1: 0.49815 ,SNR2: 1.7219




Frequency (Hz)

K20260620060340




BLK: 2,SNR1: 0.92460 ,SNR2: 4.3478





Frequency (Hz)


0003+313 2026/06/19 21.09UT FUJI -KISO



T20260620061131





BLK: 8,SNR1: 18.622 ,SNR2: 23.945




Frequency (Hz)

F20260620061133




BLK: 8,SNR1: 5.0470 ,SNR2: 12.050





Frequency (Hz)


0011+344 2026/06/19 21.22UT TOYOKAWA-FUJI



T20260620061131





BLK:10,SNR1: 5.4471 ,SNR2: 18.830





0011+344 2026/06/19 21.22UT TOYOKAWA-KISO



K20260620061128




BLK:10,SNR1: 15.068 ,SNR2: 27.098



F20260620061133





BLK: 3,SNR1: 1.8176 ,SNR2: 6.1154




Frequency (Hz)

K20260620061128




BLK: 3,SNR1: 2.7780 ,SNR2: 8.3801





Frequency (Hz)


0011+344 2026/06/19 21.22UT FUJI -KISO



T20260620062457





BLK: 5,SNR1: 16.306 ,SNR2: 54.421




Frequency (Hz)

F20260620062459




BLK: 5,SNR1: 0.27579E-01,SNR2: 1.3435





Frequency (Hz)


0024+125 2026/06/19 21.44UT TOYOKAWA-FUJI



T20260620062457





BLK: 6,SNR1: 40.232 ,SNR2: 240.48




Frequency (Hz)

K20260620062454




BLK: 6,SNR1: 0.63986 ,SNR2: 1.9042





Frequency (Hz)


0024+125 2026/06/19 21.44UT TOYOKAWA-KISO



F20260620062459





BLK: 8,SNR1: 0.67024 ,SNR2: 1.9733




Frequency (Hz)

K20260620062454




BLK: 8,SNR1: 0.67736 ,SNR2: 2.3188




Frequency (Hz)


0024+125 2026/06/19 21.44UT FUJI -KISO



T20260620063022





BLK:25,SNR1: 6.0789 ,SNR2: 17.310




Frequency (Hz)

3C12 2026/06/19 21.53UT TOYOKAWA-FUJI


F20260620063024





BLK:25,SNR1: 2.7723 ,SNR2: 13.252




Frequency (Hz)



T20260620063022





BLK:28,SNR1: 6.0170 ,SNR2: 16.696




Frequency (Hz)

3C12 2026/06/19 21.53UT TOYOKAWA-KISO


K20260620063019





BLK:28,SNR1: 7.6258 ,SNR2: 18.922




Frequency (Hz)



F20260620063024





BLK:22,SNR1: 2.7288 ,SNR2: 13.079




Frequency (Hz)

3C12 2026/06/19 21.53UT FUJI -KISO


K20260620063019





BLK:22,SNR1: 8.1505 ,SNR2: 20.197




Frequency (Hz)



T20260620063841





BLK: 7,SNR1: 0.46191 ,SNR2: 1.6294




Frequency (Hz)

F20260620063843




BLK: 7,SNR1: 7.2811 ,SNR2: 15.963





Frequency (Hz)


0038+328 2026/06/19 21.67UT TOYOKAWA-FUJI



T20260620063841





BLK:12,SNR1: 0.25029 ,SNR2: 1.0719




Frequency (Hz)

K20260620063838




BLK:12,SNR1: 6.3752 ,SNR2: 14.048





Frequency (Hz)


0038+328 2026/06/19 21.67UT TOYOKAWA-KISO



F20260620063843





BLK: 3,SNR1: 4.0336 ,SNR2: 9.1651




Frequency (Hz)

K20260620063838




BLK: 3,SNR1: 1.5942 ,SNR2: 5.3883





Frequency (Hz)


0038+328 2026/06/19 21.67UT FUJI -KISO



T20260620065145





BLK:21,SNR1: 7.2074 ,SNR2: 18.211




Frequency (Hz)

3C26 2026/06/19 21.89UT TOYOKAWA-FUJI


F20260620065147





BLK:21,SNR1: 8.7502 ,SNR2: 21.969




Frequency (Hz)



T20260620065145





BLK:26,SNR1: 7.4072 ,SNR2: 18.908




Frequency (Hz)

K20260620065142




BLK:26,SNR1: 7.4416 ,SNR2: 18.764





Frequency (Hz)


3C26 2026/06/19 21.89UT TOYOKAWA-KISO



F20260620065147





BLK:18,SNR1: 8.7879 ,SNR2: 22.062




Frequency (Hz)

3C26 2026/06/19 21.89UT FUJI -KISO


K20260620065142




BLK:18,SNR1: 7.4630 ,SNR2: 18.818




Frequency (Hz)



T20260620065644




BLK:11,SNR1: 4.2920 ,SNR2: 10.783




Frequency (Hz)

F20260620065646




BLK:11,SNR1: 2.8971 ,SNR2: 7.1841




Frequency (Hz)


0056-00 2026/06/19 21.97UT TOYOKAWA-FUJI



T20260620065644




BLK:11,SNR1: 4.3746 ,SNR2: 10.976




Frequency (Hz)

K20260620065641




BLK:11,SNR1: 4.5351 ,SNR2: 8.9717





Frequency (Hz)


0056-00 2026/06/19 21.97UT TOYOKAWA-KISO



F20260620065646





BLK:10,SNR1: 0.67780 ,SNR2: 5.1854




Frequency (Hz)

K20260620065641




BLK:10,SNR1: 4.7174 ,SNR2: 15.381





Frequency (Hz)


0056-00 2026/06/19 21.97UT FUJI -KISO



T20260620070626




BLK: 7,SNR1: 18.536 ,SNR2: 43.917





0106+01 2026/06/19 22.14UT TOYOKAWA-FUJI



F20260620070628




BLK: 7,SNR1: 9.8897 ,SNR2: 24.655



T20260620070626





BLK:10,SNR1: 10.506 ,SNR2: 24.840




Frequency (Hz)

0106+01 2026/06/19 22.14UT TOYOKAWA-KISO


K20260620070623





BLK:10,SNR1: 11.782 ,SNR2: 28.129




Frequency (Hz)



F20260620070628





BLK: 5,SNR1: 10.497 ,SNR2: 26.195




Frequency (Hz)

0106+01 2026/06/19 22.14UT FUJI -KISO


K20260620070623





BLK: 5,SNR1: 15.102 ,SNR2: 35.380




Frequency (Hz)



T20260620071549





BLK: 9,SNR1: 11.042 ,SNR2: 26.370




Frequency (Hz)

F20260620071551




BLK: 9,SNR1: 10.776 ,SNR2: 27.714





Frequency (Hz)


0115-01 2026/06/19 22.29UT TOYOKAWA-FUJI



T20260620071549





BLK: 9,SNR1: 14.651 ,SNR2: 33.916




Frequency (Hz)

K20260620071546




BLK: 9,SNR1: 11.975 ,SNR2: 28.492





Frequency (Hz)


0115-01 2026/06/19 22.29UT TOYOKAWA-KISO



F20260620071551





BLK: 8,SNR1: 9.3548 ,SNR2: 22.982





0115-01 2026/06/19 22.29UT FUJI -KISO



K20260620071546




BLK: 8,SNR1: 7.5711 ,SNR2: 21.858



T20260620072849





BLK: 6,SNR1: 12.199 ,SNR2: 27.470




Frequency (Hz)

F20260620072851




BLK: 6,SNR1: 9.9329 ,SNR2: 26.395





Frequency (Hz)


0128+03 2026/06/19 22.51UT TOYOKAWA-FUJI



T20260620072849





BLK:10,SNR1: 9.4389 ,SNR2: 24.612




Frequency (Hz)

0128+03 2026/06/19 22.51UT TOYOKAWA-KISO


K20260620072846




BLK:10,SNR1: 12.908 ,SNR2: 28.575




Frequency (Hz)



F20260620072851




BLK: 9,SNR1: 10.655 ,SNR2: 27.860





0128+03 2026/06/19 22.51UT FWJ -KISO



K20260620072846




BLK: 9,SNR1: 13.800 ,SNR2: 30.764



T20260620073523





BLK:12,SNR1: 3.3209 ,SNR2: 10.117





3C48 2026/06/19 22.62UT TOYOKAWA-FUJI



F20260620073525




BLK:12,SNR1: 3.3388 ,SNR2: 10.063



T20260620073523





BLK:19,SNR1: 3.3199 ,SNR2: 10.068





3C48 2026/06/19 22.62UT TOYOKAWA-KISO


K20260620073520




BLK:19,SNR1: 3.0163 ,SNR2: 9.2302



F20260620073525





BLK:22,SNR1: 9.9852 ,SNR2: 17.481





3C48 2026/06/19 22.62UT FUJI -KISO



K20260620073520




BLK:22,SNR1: 3.0098 ,SNR2: 9.2134



T20260620075507





BLK: 4,SNR1: 0.15673 ,SNR2: 2.4002




Frequency (Hz)

F20260620075509




BLK: 4,SNR1: 0.62430 ,SNR2: 4.6656




Frequency (Hz)


0155-109 2026/06/19 22.95UT TOYOKAWA-FUJI



T20260620075507





BLK: 3,SNR1: 0.15145 ,SNR2: 1.1516




Frequency (Hz)

K20260620075504




BLK: 3,SNR1: 0.56834E-01,SNR2: 0.95655





Frequency (Hz)


0155-109 2026/06/19 22.95UT TOYOKAWA-KISO



F20260620075509





BLK: 6,SNR1: 0.22376 ,SNR2: 2.4056




Frequency (Hz)

K20260620075504




BLK: 6,SNR1: 0.88905 ,SNR2: 5.3197




Frequency (Hz)


0155-109 2026/06/19 22.95UT FUJI -KISO



T20260620080214





BLK: 9,SNR1: 9.1139 ,SNR2: 20.606




Frequency (Hz)

0202+15 2026/06/19 23.07UT TOYOKAWA-FUJI


F20260620080216





BLK: 9,SNR1: 9.4833 ,SNR2: 16.695




Frequency (Hz)



T20260620080214





BLK:14,SNR1: 3.3642 ,SNR2: 10.114




Frequency (Hz)

K20260620080211




BLK:14,SNR1: 9.7897 ,SNR2: 20.934





Frequency (Hz)


0202+15 2026/06/19 23.07UT TOYOKAWA-KISO



F20260620080216





BLK:13,SNR1: 8.7088 ,SNR2: 22.587




Frequency (Hz)

K20260620080211




BLK:13,SNR1: 5.9372 ,SNR2: 16.080




Frequency (Hz)


0202+15 2026/06/19 23.07UT FUJI -KISO



T20260620081405





BLK:11,SNR1: 1.9044 ,SNR2: 9.0349




Frequency (Hz)

F20260620081407




BLK:11,SNR1: 4.8428 ,SNR2: 8.7395




Frequency (Hz)


0213+178 2026/06/19 23.26UT TOYOKAWA-FUJI



T20260620081405





BLK:15,SNR1: 3.5540 ,SNR2: 8.3482





0213+178 2026/06/19 23.26UT TOYOKAWA-KISO



K20260620081402




BLK:15,SNR1: 8.4743 ,SNR2: 20.993





F20260620081407




BLK:12,SNR1: 2.5994 ,SNR2: 9.0133




K20260620081402





BLK:12,SNR1: 7.8874 ,SNR2: 19.596




0213+178 2026/06/19 23.26UT FUJI -KISO



T20260620082147





BLK: 5,SNR1: 0.60474 ,SNR2: 1.6305




Frequency (Hz)

3C67 2026/06/19 23.39UT TOYOKAWA-FUJI


F20260620082149





BLK: 5,SNR1: 4.9951 ,SNR2: 11.379




Frequency (Hz)





T20260620082147




BLK: 9,SNR1: 0.98510E-01,SNR2: 0.61804




K20260620082144




BLK: 9,SNR1: 5.3381 ,SNR2: 8.4558




3C67 2026/06/19 23.39UT TOYOKAWA-KISO



F20260620082149




BLK: 7,SNR1: 6.1650 ,SNR2: 13.575





3C67 2026/06/19 23.39UT FUJI -KISO



K20260620082144




BLK: 7,SNR1: 4.7055 ,SNR2: 7.8093



T20260620084002




BLK: 1,SNR1: 8.3704 ,SNR2: 20.964





3C71 2026/06/19 23.70UT TOYOKAWA-FUJI


F20260620084004




BLK: 1,SNR1: 2.2504 ,SNR2: 5.8607



T20260620084002




BLK: 2,SNR1: 10.103 ,SNR2: 24.823





3C71 2026/06/19 23.70UT TOYOKAWA-KISO


K20260620083959




BLK: 2,SNR1: 1.5565 ,SNR2: 6.5939



F20260620084004




BLK: 2,SNR1: 1.3030 ,SNR2: 3.6306





3C71 2026/06/19 23.70UT FUJI -KISO



K20260620083959




BLK: 2,SNR1: 1.3134 ,SNR2: 4.7550



T20260620090907





BLK: 7,SNR1: 9.2201 ,SNR2: 21.968





0308+305 2026/06/20 0.18UT TOYOKAWA-FUJI



F20260620090909




BLK: 7,SNR1: 6.9828 ,SNR2: 16.844





T20260620090907




BLK: 7,SNR1: 12.072 ,SNR2: 28.798




K20260620090904





BLK: 7,SNR1: 7.4658 ,SNR2: 18.457




0308+305 2026/06/20 0.18UT TOYOKAWA-KISO





F20260620090909




BLK: 7,SNR1: 6.6638 ,SNR2: 16.190




K20260620090904





BLK: 7,SNR1: 6.5793 ,SNR2: 16.000




0308+305 2026/06/20 0.18UT FUJI -KISO



T20260620091728





BLK:10,SNR1: 6.3946 ,SNR2: 11.345





3C84 2026/06/20 0.32UT TOYOKAWA-FUJI



F20260620091730




BLK:10,SNR1: 1.2719 ,SNR2: 4.5214



T20260620091728





BLK: 8,SNR1: 4.5944 ,SNR2: 8.5725





3C84 2026/06/20 0.32UT TOYOKAWA-KISO



K20260620091725




BLK: 8,SNR1: 0.89614 ,SNR2: 4.2752



F20260620091730





BLK: 5,SNR1: 1.0715 ,SNR2: 3.7133





3C84 2026/06/20 0.32UT FUJI -KISO



K20260620091725




BLK: 5,SNR1: 1.5608 ,SNR2: 4.8620



T20260620092443




BLK: 4,SNR1: 8.4113 ,SNR2: 20.810




0324+119 2026/06/20 0.44UT TOYOKAWA-FUJI


F20260620092445





BLK: 4,SNR1: 9.2283 ,SNR2: 23.003




Frequency (Hz)





T20260620092443




BLK: 4, SNR1: 10.315 ,SNR2: 25.626




K20260620092440





BLK: 4, SNR1: 9.4712 ,SNR2: 23.323




0324+119 2026/06/20 0.44UT TOYOKAWA-KISO





F20260620092445




BLK: 1, SNR1: 10.405 , SNR2: 25.632




K20260620092440





BLK: 1, SNR1: 9.1464 , SNR2: 22.589




0324+119 2026/06/20 0.44UT FUJI -KISO



T20260620093400





No. Good Data




Frequency (Hz)

F20260620093402




No. Good Data





Frequency (Hz)


0333+32 2026/06/20 0.59UT TOYOKAWA-FUJI



T20260620093400





No. Good Data




Frequency (Hz)

K20260620093357




No. Good Data





Frequency (Hz)


0333+32 2026/06/20 0.59UT TOYOKAWA-KISO





F20260620093402




BLK: 2, SNR1: 12.500 ,SNR2: 29.860




K20260620093357





BLK: 2, SNR1: 14.973 ,SNR2: 35.630




0333+32 2026/06/20 0.59UT FUJI -KISO



T20260620094701





BLK: 5, SNR1: 6.4525 , SNR2: 22.876




Frequency (Hz)

0347+05 2026/06/20 0.81UT TOYOKAWA-FUJI


F20260620094703





BLK: 5, SNR1: 8.0241 , SNR2: 20.099




Frequency (Hz)



T20260620094701





BLK: 5, SNR1: 6.7151 , SNR2: 23.803




Frequency (Hz)

0347+05 2026/06/20 0.81UT TOYOKAWA-KISO


K20260620094658





BLK: 5, SNR1: 1.8531 , SNR2: 9.3672




Frequency (Hz)



F20260620094703





BLK: 5, SNR1: 6.7330 ,SNR2: 17.213




Frequency (Hz)

0347+05 2026/06/20 0.81UT FUJI -KISO


K20260620094658




BLK: 5, SNR1: 6.9648 ,SNR2: 17.576




Frequency (Hz)



T20260620100234




BLK: 3, SNR1: 5.3940 , SNR2: 12.388





0403-132 2026/06/20 1.07UT TOYOKAWA-FUJI


F20260620100236




BLK: 3, SNR1: 7.7738 , SNR2: 16.946



T20260620100234





BLK: 8, SNR1: 10.332 ,SNR2: 18.676





0403-132 2026/06/20 1.07UT TOYOKAWA-KISO



K20260620100231




BLK: 8, SNR1: 7.2690 ,SNR2: 21.402



F20260620100236




BLK:12,SNR1: 7.1379 ,SNR2: 15.675





0403-132 2026/06/20 1.07UT FUJI -KISO



K20260620100231




BLK:12,SNR1: 6.0755 ,SNR2: 13.473



T20260620101146




BLK: 1,SNR1: 10.258 ,SNR2: 26.506




0411+05 2026/06/20 1.22UT TOYOKAWA-FUJI


F20260620101148





BLK: 1,SNR1: 11.163 ,SNR2: 27.367




Frequency (Hz)





T20260620101146




BLK: 3, SNR1: 5.9505 , SNR2: 22.023




K20260620101143




BLK: 3, SNR1: 15.021 , SNR2: 36.968




0411+05 2026/06/20 1.22UT TOYOKAWA-KISO




F20260620101148




BLK: 1,SNR1: 11.546 ,SNR2: 28.376




K20260620101143





BLK: 1,SNR1: 12.297 ,SNR2: 30.435




0411+05 2026/06/20 1.22UT FUJI -KISO




T20260620101841




BLK: 7, SNR1: 3.5172 , SNR2: 8.4530




F20260620101843





BLK: 7, SNR1: 7.4601 , SNR2: 17.845




0418+236 2026/06/20 1.34UT TOYOKAWA-FUJI




T20260620101841




BLK: 3,SNR1: 0.52059 ,SNR2: 1.9073




K20260620101838




BLK: 3,SNR1: 16.310 ,SNR2: 30.084




0418+236 2026/06/20 1.34UT TOYOKAWA-KISO




F20260620101843




BLK: 6,SNR1: 7.6231 ,SNR2: 18.674




K20260620101838





BLK: 6,SNR1: 20.676 ,SNR2: 36.776




0418+236 2026/06/20 1.34UT FUJI -KISO





T20260620103009




BLK: 5, SNR1: 8.9465 ,SNR2: 49.333




F20260620103011





BLK: 5, SNR1: 6.1004 ,SNR2: 15.087




3C119 2026/06/20 1.53UT TOYOKAWA-FUJI



T20260620103009





BLK:11,SNR1: 13.625 ,SNR2: 28.719





3C119 2026/06/20 1.53UT TOYOKAWA-KISO



K20260620103006




BLK:11,SNR1: 11.829 ,SNR2: 28.971





F20260620103011




BLK: 2,SNR1: 12.614 ,SNR2: 30.523




K20260620103006





BLK: 2,SNR1: 11.901 ,SNR2: 29.146




3C119 2026/06/20 1.53UT FUJI -KISO



T20260620111815





BLK: 4, SNR1: 17.701 ,SNR2: 42.512





3C138 2026/06/20 2.33UT TOYOKAWA-FUJI



F20260620111817




BLK: 4, SNR1: 9.3498 ,SNR2: 23.180



T20260620111815




BLK: 5, SNR1: 5.7720 ,SNR2: 22.821





3C138 2026/06/20 2.33UT TOYOKAWA-KISO



K20260620111812




BLK: 5, SNR1: 9.4219 ,SNR2: 23.234



F20260620111817





BLK: 2, SNR1: 24.995 , SNR2: 44.805





3C138 2026/06/20 2.33UT FUJI -KISO


K20260620111812




BLK: 2, SNR1: 23.890 , SNR2: 42.852





T20260620113149




BLK: 4,SNR1: 0.80618 ,SNR2: 3.3391




F20260620113151




BLK: 4,SNR1: 5.6357 ,SNR2: 14.342




0531+194 2026/06/20 2.56UT TOYOKAWA-FUJI





T20260620113149




BLK: 4,SNR1: 0.53655 ,SNR2: 4.1521




K20260620113146





BLK: 4,SNR1: 4.3702 ,SNR2: 7.9620




0531+194 2026/06/20 2.56UT TOYOKAWA-KISO



F20260620113151





BLK: 4,SNR1: 1.8793 ,SNR2: 9.2367




0531+194 2026/06/20 2.56UT FUJI -KISO


K20260620113146





BLK: 4,SNR1: 1.5533 ,SNR2: 8.0071




Frequency (Hz)





T20260620114010




BLK: 7,SNR1: 23.197 ,SNR2: 41.088




F20260620114012





BLK: 7,SNR1: 14.683 ,SNR2: 26.117




3C147 2026/06/20 2.70UT TOYOKAWA-FUJI



T20260620114010





BLK: 6, SNR1: 20.288 ,SNR2: 35.634




Frequency (Hz)

3C147 2026/06/20 2.70UT TOYOKAWA-KISO


K20260620114007





BLK: 6, SNR1: 7.8598 ,SNR2: 20.118




Frequency (Hz)



F20260620114012





BLK: 5,SNR1: 13.021 ,SNR2: 23.311




Frequency (Hz)

3C147 2026/06/20 2.70UT FUJI -KISO


K20260620114007




BLK: 5,SNR1: 10.242 ,SNR2: 24.823




Frequency (Hz)



T20260620114819





BLK:13,SNR1: 3.8539 ,SNR2: 11.442





0548+16 2026/06/20 2.83UT TOYOKAWA-FUJI


F20260620114821




BLK:13,SNR1: 3.7553 ,SNR2: 10.986



T20260620114819





BLK:17,SNR1: 3.9022 ,SNR2: 11.558





0548+16 2026/06/20 2.83UT TOYOKAWA-KISO



K20260620114816




BLK:17,SNR1: 8.1747 ,SNR2: 21.140




F20260620114821




BLK:13,SNR1: 10.086 ,SNR2: 17.674




K20260620114816




BLK:13,SNR1: 8.1791 ,SNR2: 21.151




0548+16 2026/06/20 2.83UT FUJI -KISO



T20260620115230




BLK: 4,SNR1: 7.8912 ,SNR2: 19.611





0552+12 2026/06/20 2.90UT TOYOKAWA-FUJI



F20260620115232




BLK: 4,SNR1: 33.258 ,SNR2: 45.931




T20260620115230




BLK: 2,SNR1: 16.945 ,SNR2: 63.081




K20260620115227




BLK: 2,SNR1: 17.321 ,SNR2: 42.601




0552+12 2026/06/20 2.90UT TOYOKAWA-KISO





F20260620115232




BLK: 2,SNR1: 10.667 ,SNR2: 25.532




K20260620115227




BLK: 2,SNR1: 10.598 ,SNR2: 26.084




0552+12 2026/06/20 2.90UT FUJI -KISO




T20260620115657




BLK: 7,SNR1: 0.67161 ,SNR2: 6.2326




F20260620115659





BLK: 7,SNR1: 21.551 ,SNR2: 37.829




0556+191 2026/06/20 2.98UT TOYOKAWA-FUJI




T20260620115657




BLK: 4, SNR1: 0.78466 , SNR2: 2.3406




K20260620115655




BLK: 4, SNR1: 13.329 , SNR2: 23.789




0556+191 2026/06/20 2.98UT TOYOKAWA-KISO



F20260620115659




BLK: 2,SNR1: 3.3794 ,SNR2: 16.786





0556+191 2026/06/20 2.98UT FUJI -KISO



K20260620115655




BLK: 2,SNR1: 5.6625 ,SNR2: 20.135




T20260620120130




BLK: 1,SNR1: 3.1493 ,SNR2: 10.467




F20260620120132




BLK: 1,SNR1: 1.2942 ,SNR2: 5.6398




3C152 2026/06/20 3.05UT TOYOKAWA-FUJI




T20260620120130




BLK: 1,SNR1: 5.1529 ,SNR2: 12.095




K20260620120128





BLK: 1,SNR1: 6.4198 ,SNR2: 12.726




3C152 2026/06/20 3.05UT TOYOKAWA-KISO



F20260620120132




BLK: 3,SNR1: 5.0685 ,SNR2: 12.801





3C152 2026/06/20 3.05UT FUJI -KISO


K20260620120128




BLK: 3,SNR1: 15.579 ,SNR2: 27.812





T20260620122350




BLK: 6,SNR1: 8.0437 ,SNR2: 17.449




F20260620122352





BLK: 6,SNR1: 4.5208 ,SNR2: 13.509




3C161 2026/06/20 3.43UT TOYOKAWA-FUJI




T20260620122350




BLK: 6,SNR1: 4.4011 ,SNR2: 10.744




K20260620122347





BLK: 6,SNR1: 8.9730 ,SNR2: 21.733




3C161 2026/06/20 3.43UT TOYOKAWA-KISO




F20260620122352




BLK: 2,SNR1: 9.7463 ,SNR2: 21.549




K20260620122347




BLK: 2,SNR1: 11.335 ,SNR2: 26.681




3C161 2026/06/20 3.43UT FUJI -KISO



T20260620125122





No. Good Data




Frequency (Hz)

F20260620125124




No. Good Data




Frequency (Hz)


0652-130 2026/06/20 3.88UT TOYOKAWA-FUJI



T20260620125122





BLK: 3,SNR1: 7.7501 ,SNR2: 19.316





0652-130 2026/06/20 3.88UT TOYOKAWA-KISO



K20260620125119




BLK: 3,SNR1: 11.230 ,SNR2: 20.199





F20260620125124




No.Good Data




K20260620125119





No.Good Data




0652-130 2026/06/20 3.88UT FUJI -KISO




T20260620130300




BLK: 1,SNR1: 18.885 ,SNR2: 33.559




F20260620130302





BLK: 1,SNR1: 6.0663 ,SNR2: 16.155




0703+138 2026/06/20 4.08UT TOYOKAWA-FUJI





T20260620130300




BLK: 1,SNR1: 0.37266 ,SNR2: 1.4486




K20260620130257





BLK: 1,SNR1: 1.8632 ,SNR2: 10.960




0703+138 2026/06/20 4.08UT TOYOKAWA-KISO





F20260620130302




No.Good Data




K20260620130257





No.Good Data




0703+138 2026/06/20 4.08UT FUJI -KISO





T20260620131222




BLK: 6,SNR1: 0.88051 ,SNR2: 4.2363




F20260620131224




BLK: 6,SNR1: 3.3406 ,SNR2: 8.6515




0713-024 2026/06/20 4.23UT TOYOKAWA-FUJI





T20260620131222




BLK:13,SNR1: 0.75901 ,SNR2: 5.2424




K20260620131219





BLK:13,SNR1: 4.2038 ,SNR2: 13.749




0713-024 2026/06/20 4.23UT TOYOKAWA-KISO





F20260620131224




BLK: 6,SNR1: 5.2352 ,SNR2: 13.397




K20260620131219





BLK: 6,SNR1: 2.6651 ,SNR2: 5.2587




0713-024 2026/06/20 4.23UT FUJI -KISO





T20260620132234




BLK:19,SNR1: 1.6011 ,SNR2: 5.4723




F20260620132236





BLK:19,SNR1: 12.170 ,SNR2: 21.448




0723+10 2026/06/20 4.40UT TOYOKAWA-FUJI





T20260620132234




BLK:18,SNR1: 1.6879 ,SNR2: 4.8013




K20260620132231




BLK:18,SNR1: 7.2357 ,SNR2: 9.4267




0723+10 2026/06/20 4.40UT TOYOKAWA-KISO



F20260620132236




BLK: 9,SNR1: 15.557 ,SNR2: 27.380





0723+10 2026/06/20 4.40UT FUJI -KISO


K20260620132231




BLK: 9,SNR1: 7.1463 ,SNR2: 17.304




T20260620133250




BLK:11,SNR1: 0.38151 ,SNR2: 2.1863




F20260620133252




BLK:11,SNR1: 3.2438 ,SNR2: 8.0421




0732+33 2026/06/20 4.58UT TOYOKAWA-FUJI





T20260620133250




BLK:17,SNR1: 0.34805 ,SNR2: 2.9446




K20260620133247




BLK:17,SNR1: 0.38438 ,SNR2: 1.4066




0732+33 2026/06/20 4.58UT TOYOKAWA-KISO





F20260620133252




BLK: 6,SNR1: 3.0097 ,SNR2: 7.4971




K20260620133247







BLK: 6,SNR1: 0.23472 ,SNR2: 2.1342








0732+33 2026/06/20 4.58UT FUJI -KISO










0741-06 2026/06/20 4.71UT TOYOKAWA-FUJI






0741-06 2026/06/20 4.71UT TOYOKAWA-KISO








0741-06 2026/06/20 4.71UT FUJI -KISO




T20260620135034




BLK:16,SNR1: 12.334 ,SNR2: 28.315




F20260620135036





BLK:16,SNR1: 10.641 ,SNR2: 25.607




0752-200 2026/06/20 4.87UT TOYOKAWA-FUJI




T20260620135034




BLK:17,SNR1: 11.753 ,SNR2: 27.238




K20260620135031







BLK:17,SNR1: 12.317 ,SNR2: 28.374




0752-200 2026/06/20 4.87UT TOYOKAWA-KISO







0752-200 2026/06/20 4.87UT FUJI -KISO





T20260620135810




BLK: 3,SNR1: 10.366 ,SNR2: 26.370




F20260620135812




BLK: 3,SNR1: 3.9293 ,SNR2: 10.322





3C190 2026/06/20 5.00UT TOYOKAWA-FUJI







BLK: 2,SNR1: 7.9324 ,SNR2: 24.113





BLK: 2,SNR1: 7.6500 ,SNR2: 14.997




3C190 2026/06/20 5.00UT TOYOKAWA-KISO



F20260620135812





BLK: 4,SNR1: 10.181 ,SNR2: 25.198





3C190 2026/06/20 5.00UT FUJI -KISO


K20260620135807




BLK: 4,SNR1: 11.229 ,SNR2: 27.524





T20260620141036




BLK: 6,SNR1: 4.4954 ,SNR2: 9.6019




F20260620141038




BLK: 6,SNR1: 6.7497 ,SNR2: 16.574




3C196 2026/06/20 5.20UT TOYOKAWA-FUJI



T20260620141036





BLK: 5,SNR1: 5.0126 ,SNR2: 10.495





3C196 2026/06/20 5.20UT TOYOKAWA-KISO


K20260620141033




BLK: 5,SNR1: 0.65964 ,SNR2: 7.0516



F20260620141038





BLK: 2,SNR1: 2.1246 ,SNR2: 5.6857





3C196 2026/06/20 5.20UT FUJI -KISO



K20260620141033




BLK: 2,SNR1: 1.9049 ,SNR2: 5.3436




T20260620142145




No.Good Data




F20260620142147





No.Good Data




0821+394 2026/06/20 5.39UT TOYOKAWA-FUJI





T20260620142145




BLK: 1,SNR1:-0.15788 ,SNR2: 0.28811




K20260620142142




BLK: 1,SNR1: 1.4905 ,SNR2: 8.6709




0821+394 2026/06/20 5.39UT TOYOKAWA-KISO




F20260620142147




BLK: 1,SNR1: 2.9118 ,SNR2: 7.3355




K20260620142142





BLK: 1,SNR1: 1.4905 ,SNR2: 8.6709




0821+394 2026/06/20 5.39UT FUJI -KISO





T20260620143323




No.Good Data




F20260620143325




No.Good Data




0834-19 2026/06/20 5.58UT TOYOKAWA-FUJI




T20260620143323




BLK: 1,SNR1: 1.9099 ,SNR2: 8.5880




K20260620143320




BLK: 1,SNR1: 3.6339 ,SNR2: 12.157




0834-19 2026/06/20 5.58UT TOYOKAWA-KISO



F20260620143325





No.Good Data




Frequency (Hz)

K20260620143320




No.Good Data





Frequency (Hz)


0834-19 2026/06/20 5.58UT FUJI -KISO





T20260620143829




BLK: 4,SNR1: 5.7904 ,SNR2: 15.333




F20260620143831





BLK: 4,SNR1: 4.9548 ,SNR2: 13.539




0839-071 2026/06/20 5.67UT TOYOKAWA-FUJI





T20260620143829




BLK: 5,SNR1: 50.077 ,SNR2: 67.772




K20260620143826





BLK: 5,SNR1: 4.3442 ,SNR2: 14.079




0839-071 2026/06/20 5.67UT TOYOKAWA-KISO





F20260620143831




BLK: 2,SNR1: 4.4858 ,SNR2: 14.598




K20260620143826





BLK: 2,SNR1: 4.8703 ,SNR2: 15.101




0839-071 2026/06/20 5.67UT FUJI -KISO




T20260620144931




BLK: 1,SNR1: 8.3425 ,SNR2: 23.307




F20260620144933





BLK: 1,SNR1: 15.119 ,SNR2: 44.176




3C208 2026/06/20 5.85UT TOYOKAWA-FUJI




T20260620144931




BLK: 3,SNR1: 12.619 ,SNR2: 23.895




K20260620144928






BLK: 3,SNR1: 9.1965 ,SNR2: 16.360







3C208 2026/06/20 5.85UT TOYOKAWA-KISO







F20260620144933








K20260620144928






3C216 2026/06/20 6.13UT TOYOKAWA-FUJI







3C216 2026/06/20 6.13UT TOYOKAWA-KISO





F20260620150615




BLK: 8,SNR1: 21.258 ,SNR2: 33.299




K20260620150610





BLK: 8,SNR1: 2.0319 ,SNR2: 6.8348




3C216 2026/06/20 6.13UT FUJI -KISO





T20260620151823




No.Good Data




F20260620151825





No.Good Data




0919-142 2026/06/20 6.33UT TOYOKAWA-FUJI



T20260620151823





No.Good Data




Frequency (Hz)

K20260620151820




No.Good Data




Frequency (Hz)


0919-142 2026/06/20 6.33UT TOYOKAWA-KISO





F20260620151825




BLK: 2,SNR1: 12.732 ,SNR2: 22.766




K20260620151820





BLK: 2,SNR1: 2.2824 ,SNR2: 12.856




0919-142 2026/06/20 6.33UT FUJI -KISO



T20260620152502





BLK: 3,SNR1: 18.806 ,SNR2: 35.262




Frequency (Hz)

F20260620152504




BLK: 3,SNR1: 1.5347 ,SNR2: 12.255





Frequency (Hz)


0926+117 2026/06/20 6.45UT TOYOKAWA-FUJI





T20260620152502




BLK: 3,SNR1: 15.131 ,SNR2: 32.062




K20260620152459





BLK: 3,SNR1: 23.636 ,SNR2: 48.831




0926+117 2026/06/20 6.45UT TOYOKAWA-KISO



F20260620152504





No.Good Data




Frequency (Hz)

K20260620152459




No.Good Data




Frequency (Hz)


0926+117 2026/06/20 6.45UT FUJI -KISO



T20260620153247




BLK: 8,SNR1: 0.43062 ,SNR2: 1.0187




Frequency (Hz)

F20260620153249




BLK: 8,SNR1: 2.8324 ,SNR2: 5.0592




Frequency (Hz)


3C222 2026/06/20 6.57UT TOYOKAWA-FUJI



T20260620153247




BLK:12,SNR1: 0.29283 ,SNR2: 1.3962




Frequency (Hz)

K20260620153244




BLK:12,SNR1: 3.9333 ,SNR2: 7.6788




Frequency (Hz)


3C222 2026/06/20 6.57UT TOYOKAWA-KISO



F20260620153249




BLK:17,SNR1: 2.1217 ,SNR2: 5.3342




Frequency (Hz)

K20260620153244




BLK:17,SNR1: 4.2382 ,SNR2: 8.3421





Frequency (Hz)


3C222 2026/06/20 6.57UT FUJI -KISO





T20260620153947




No.Good Data




F20260620153949





No.Good Data




0941-08 2026/06/20 6.69UT TOYOKAWA-FUJI



T20260620153947




BLK: 1,SNR1: 1.1829 ,SNR2: 4.5456




Frequency (Hz)

K20260620153944




BLK: 1,SNR1: 10.057 ,SNR2: 25.048




Frequency (Hz)


0941-08 2026/06/20 6.69UT TOYOKAWA-KISO



F20260620153949




BLK: 5,SNR1: 13.598 ,SNR2: 24.034




Frequency (Hz)

K20260620153944




BLK: 5,SNR1: 9.7063 ,SNR2: 17.245






Frequency (Hz)




0941-08 2026/06/20 6.69UT FUJI -KISO




T20260620154809





F20260620154811




3C230 2026/06/20 6.83UT TOYOKAWA-FUJI



T20260620154809




BLK: 1,SNR1: 7.4069 ,SNR2: 18.386





3C230 2026/06/20 6.83UT TOYOKAWA-KISO


K20260620154806




BLK: 1,SNR1: 10.058 ,SNR2: 24.867



F20260620154811




BLK: 2,SNR1: 10.440 ,SNR2: 25.993




Frequency (Hz)

K20260620154806




BLK: 2,SNR1: 16.300 ,SNR2: 38.835






Frequency (Hz)



3C230 2026/06/20 6.83UT FUJI -KISO




T20260620160409





F20260620160411




3C237 2026/06/20 7.10UT TOYOKAWA-FUJI




T20260620160409




BLK: 5, SNR1: 13.533 ,SNR2: 23.725




K20260620160406





BLK: 5, SNR1: 14.859 ,SNR2: 25.073




3C237 2026/06/20 7.10UT TOYOKAWA-KISO



F20260620160411




BLK: 2,SNR1: 11.215 ,SNR2: 27.501




Frequency (Hz)

K20260620160406




BLK: 2,SNR1: 10.246 ,SNR2: 25.059





Frequency (Hz)


3C237 2026/06/20 7.10UT FUJI -KISO



T20260620161026





BLK: 1,SNR1: 14.389 ,SNR2: 25.291




Frequency (Hz)

F20260620161028




BLK: 1,SNR1: 9.4767 ,SNR2: 22.210





Frequency (Hz)


1011+110 2026/06/20 7.20UT TOYOKAWA-FUJI



T20260620161026





BLK: 5, SNR1: 10.764 , SNR2: 26.769




Frequency (Hz)

K20260620161023




BLK: 5, SNR1: 11.195 , SNR2: 27.774




Frequency (Hz)


1011+110 2026/06/20 7.20UT TOYOKAWA-KISO



F20260620161028




BLK: 4,SNR1: 18.626 ,SNR2: 32.879




Frequency (Hz)

K20260620161023




BLK: 4,SNR1: 16.313 ,SNR2: 28.447




Frequency (Hz)


1011+110 2026/06/20 7.20UT FUJI -KISO



T20260620161807




BLK: 5,SNR1: 1.4995 ,SNR2: 4.4564




Frequency (Hz)

F20260620161809




BLK: 5,SNR1: 2.1223 ,SNR2: 5.2757




Frequency (Hz)


3C241 2026/06/20 7.33UT TOYOKAWA-FUJI



T20260620161807




BLK: 8,SNR1: 4.2527 ,SNR2: 11.043




Frequency (Hz)

K20260620161804




BLK: 8,SNR1: 6.4806 ,SNR2: 14.786




Frequency (Hz)


3C241 2026/06/20 7.33UT TOYOKAWA-KISO



F20260620161809





BLK: 3,SNR1: 1.8130 ,SNR2: 4.0755




Frequency (Hz)

K20260620161804




BLK: 3,SNR1: 4.1576 ,SNR2: 11.517






Frequency (Hz)




3C241 2026/06/20 7.33UT FUJI -KISO




T20260620162936




F20260620162938





1031-11 2026/06/20 7.52UT TOYOKAWA-FUJI







BLK: 9, SNR1: 7.9495 , SNR2: 13.853




BLK: 9, SNR1: 8.2392 , SNR2: 14.771




1031-11 2026/06/20 7.52UT TOYOKAWA-KISO



F20260620162938




BLK:15,SNR1: 9.1546 ,SNR2: 20.000




Frequency (Hz)

K20260620162933




BLK:15,SNR1: 9.1745 ,SNR2: 15.928




Frequency (Hz)


1031-11 2026/06/20 7.52UT FUJI -KISO



T20260620163409




BLK: 7,SNR1: 7.5536 ,SNR2: 19.934




Frequency (Hz)

F20260620163411




BLK: 7,SNR1: 2.8599 ,SNR2: 9.5078




Frequency (Hz)


1035-058 2026/06/20 7.60UT TOYOKAWA-FUJI



T20260620163409




BLK: 9,SNR1: 15.533 ,SNR2: 107.42




Frequency (Hz)

K20260620163406




BLK: 9,SNR1: 4.3453 ,SNR2: 11.201




Frequency (Hz)


1035-058 2026/06/20 7.60UT TOYOKAWA-KISO



F20260620163411




BLK: 2,SNR1: 2.4231 ,SNR2: 6.4445




Frequency (Hz)

K20260620163406




BLK: 2,SNR1: 5.6828 ,SNR2: 21.076





Frequency (Hz)


1035-058 2026/06/20 7.60UT FUJI -KISO



T20260620164322





BLK:11,SNR1: 0.27549 ,SNR2: 3.4486




Frequency (Hz)

F20260620164324




BLK:11,SNR1: 9.3365 ,SNR2: 16.718





Frequency (Hz)


1044-008 2026/06/20 7.75UT TOYOKAWA-FUJI



T20260620164322





BLK:22,SNR1: 6.0577 ,SNR2: 10.851




Frequency (Hz)

K20260620164319




BLK:22,SNR1: 8.5877 ,SNR2: 15.487





Frequency (Hz)


1044-008 2026/06/20 7.75UT TOYOKAWA-KISO



F20260620164324





BLK:15,SNR1: 9.4196 ,SNR2: 16.857




Frequency (Hz)

K20260620164319




BLK:15,SNR1: 8.5897 ,SNR2: 15.491




Frequency (Hz)


1044-008 2026/06/20 7.75UT FUJI -KISO



T20260620165427




BLK: 5,SNR1: 0.25004 ,SNR2: 1.8270




Frequency (Hz)

F20260620165429




BLK: 5,SNR1: 0.80143 ,SNR2: 3.9232





Frequency (Hz)


1055+01 2026/06/20 7.94UT TOYOKAWA-FUJI



T20260620165427





BLK: 3,SNR1:-0.86990E-01,SNR2: 0.87647




Frequency (Hz)

K20260620165424




BLK: 3,SNR1: 3.1839 ,SNR2: 8.1283




Frequency (Hz)


1055+01 2026/06/20 7.94UT TOYOKAWA-KISO



F20260620165429





BLK: 7,SNR1: 1.5051 ,SNR2: 4.2479




Frequency (Hz)

K20260620165424




BLK: 7,SNR1: 1.0872 ,SNR2: 3.6214





Frequency (Hz)


1055+01 2026/06/20 7.94UT FUJI -KISO



T20260620170544




BLK: 1,SNR1: 0.89243 ,SNR2: 3.2394




Frequency (Hz)

F20260620170546




BLK: 1,SNR1: 24.019 ,SNR2: 52.234





Frequency (Hz)


1107+109 2026/06/20 8.12UT TOYOKAWA-FUJI



T20260620170544





BLK: 1,SNR1: 1.0674 ,SNR2: 5.8002




Frequency (Hz)

K20260620170541




BLK: 1,SNR1: 17.645 ,SNR2: 30.768




Frequency (Hz)


1107+109 2026/06/20 8.12UT TOYOKAWA-KISO



F20260620170546




No.Good Data




Frequency (Hz)

K20260620170541




No.Good Data





Frequency (Hz)


1107+109 2026/06/20 8.12UT FWJ -KISO



T20260620172929




BLK: 1,SNR1: 0.79885E-01,SNR2: 1.2190




Frequency (Hz)

F20260620172931




BLK: 1,SNR1: 12.413 ,SNR2: 22.130





Frequency (Hz)


1130+335 2026/06/20 8.52UT TOYOKAWA-FUJI



T20260620172929





No.Good Data




Frequency (Hz)

K20260620172926




No.Good Data




Frequency (Hz)


1130+335 2026/06/20 8.52UT TOYOKAWA-KISO



F20260620172931





BLK: 1,SNR1: 8.8578 ,SNR2: 22.076




Frequency (Hz)

K20260620172926




BLK: 1,SNR1: 1.6636 ,SNR2: 7.8601




Frequency (Hz)


1130+335 2026/06/20 8.52UT FWJ -KISO



T20260620180500




BLK: 1,SNR1: 8.3036 ,SNR2: 20.381




Frequency (Hz)

F20260620180502




BLK: 1,SNR1:-0.10514 ,SNR2: 0.58683





Frequency (Hz)


1206+439 2026/06/20 9.11UT TOYOKAWA-FUJI



T20260620180500





BLK: 2,SNR1: 6.3017 ,SNR2: 15.640




Frequency (Hz)

K20260620180457




BLK: 2,SNR1: 12.555 ,SNR2: 28.423




Frequency (Hz)


1206+439 2026/06/20 9.11UT TOYOKAWA-KISO



F20260620180502





BLK: 3,SNR1: 5.0609 ,SNR2: 9.4347




Frequency (Hz)

K20260620180457



BLK: 3,SNR1: 2.8083 ,SNR2: 7.0157



Frequency (Hz)

1206+439 2026/06/20 9.11UT FUJI -KISO

